
CAPABILITIES OF THE OPERATIONALLY OUTSTANDING SUMMARIZED

How to do work



improve

work

C1 - PROCESS DESIGN

Abnormality
Sensitivity

Visualization

- -Prespecification(Documentation of the specification)
- → -Embedded Tests

(Makes a problem to the specification visible / known)

-Escalation

(Assigning pathways to respond to embedded tests)

- FOUR Levels of Process Design
 - > PROCESS OUTPUT (Output of Boundary Area)
 - > PATHWAY (Who is Responsible)
 - > CONNECTION (Handoffs between people)
 - > ACTIVITY (Methods How to do work)

C2 - PROBLEM SOLVING

Swarm Problems / Stop and Communicate Abnormalities

Two Types of Problems

1. Abnormality from prespecification

- 2. Improve prespecification toward TRUE NORTH
- Actual Product, Process, Place, People and Time
- Use the Scientific Method (logical thinking)
- Rapid / Low Cost Experiments (Hold, Tape, Clamp, Bolt, Weld)

C3 – SHARE KNOWLEDGE

- All people do their work using the enterprises collective knowledge and experience.
- Prespecification of (O, P, C, A) includes the enterprises global knowledge.

C4 – <u>LEADERS DEVELOP PEOPLE</u>

- Sustain process outputs by countermeasuring abnormalities
- Relentlessly improve prespecifications (O, P, C, A) toward True North
- Diagnose the organizations capabilities around C1 C4
- Develop countermeasures to build C1 C4 skills in people

Work elements Sequence

- 3. Timing
- 4. Location
- 5. Result