

1 FRANK M. PITRE (SBN 100077)
 fpitre@cpmlegal.com
 2 CHRISTOPHER LAVORATO (SBN 221034)
 clavorato@cpmlegal.com
 3 ALEXANDRA A. HAMILTON (SBN 280834)
 ahamilton@cpmlegal.com
 4 **COTCHETT, PITRE & McCARTHY, LLP**
 San Francisco Airport Office Center
 5 840 Malcolm Road, Suite 200
 Burlingame, CA 94010
 6 Telephone: (650) 697-6000
 Facsimile: (650) 697-0577

7 *Liaison Counsel for Plaintiffs*

8 **UNITED STATES DISTRICT COURT FOR THE**
9 **NORTHERN DISTRICT OF CALIFORNIA**

10 **IN RE: AIR CRASH AT SAN**
11 **FRANCISCO, CALIFORNIA ON**
12 **JULY 6, 2013**

MDL No. 2497

MASTER CONSOLIDATED COMPLAINT
FOR:

- 13 1. **PASSENGER LIABILITY**
(ASIANA AIRLINES)
- 14 2. **NEGLIGENCE**
(ASIANA AIRLINES)
- 15 3. **NEGLIGENCE**
(THE BOEING COMPANY)
- 16 4. **BREACH OF WARRANTY**
(THE BOEING COMPANY)
- 17 5. **STRICT LIABILITY**
(THE BOEING COMPANY)
- 18 6. **NEGLIGENCE**
(AIR CRUISERS/ZODIAC
19 **AEROSPACE)**
- 20 7. **BREACH OF WARRANTY**
(AIR CRUISERS/ZODIAC
21 **AEROSPACE)**
- 22 8. **STRICT LIABILITY**
(AIR CRUISERS/ZODIAC
23 **AEROSPACE)**
- 24 9. **LOSS OF CONSORTIUM**

25 **JURY TRIAL DEMANDED**

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

TABLE OF CONTENTS

PAGE NO.

- I. INTRODUCTION..... 1
- II. JURISDICTION AND VENUE 2
- III. PARTIES..... 3
 - A. Plaintiff..... 3
 - B. Defendants..... 3
 - C. Agency and Concert of Action..... 4
- IV. FACTUAL BACKGROUND FOR THE CLAIMS ASSERTED 5
 - A. History of the Aircraft that Crashed..... 5
 - 1. Boeing Designed, Manufactured, Promoted and Sold the Boeing 777As Safe For Air Travel 5
 - 2. Asiana Purchased the Ill-Fated Aircraft in 2006..... 6
 - B. Both Asiana Airlines and Boeing 777 Aircraft Have Been Involved in a Number of Prior Incidents Which Raised Safety Concerns 6
 - 1. Boeing 777 Incidents and Crashes Prior to July 6, 2013 7
 - 2. In 2009 A Turkish Airlines Boeing 737 Crashed Under Very Similar Circumstances as Flight 214 Placing Boeing on Notice of Design Defects in the Low Speed Warning System on Its Aircraft 7
 - 3. Asiana Incidents and Crashes Prior to July 6, 2013..... 8
 - C. The Horrific and Fatal July 6, 2013 Crash 9
 - D. Boeing Installed a Faulty and/or Defective Auto-Throttle Control System with Latent Dangerous Shortcomings 22
 - E. Boeing Failed to Install an Adequate Low Airspeed Warning System..... 24
 - F. Boeing and Asiana Failed to Properly Train Its Pilots..... 25
 - G. Boeing and/or Asiana Designed and Installed Lap Only Seat Belts In Sections Of The Boeing 777 That Crashed..... 26

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

V. CAUSES OF ACTION 29

FIRST CAUSE OF ACTION - PASSENGER LIABILITY / STRICT LIABILITY
(Against Defendant Asiana Airlines Inc.) 29

SECOND CAUSE OF ACTION - NEGLIGENCE
(Against Defendant Asiana Airlines Inc.) 30

THIRD CAUSE OF ACTION - NEGLIGENCE
(Against Defendant The Boeing Company) 32

FOURTH CAUSE OF ACTION - BREACH OF WARRANTY
(Against Defendant The Boeing Company) 35

FIFTH CAUSE OF ACTION - STRICT LIABILITY
(Against Defendant The Boeing Company) 36

SIXTH CAUSE OF ACTION - NEGLIGENCE
(Against Defendant Air Cruisers Company, LLC d/b/a Zodiac Aero Evacuation Systems,
a subsidiary of Defendant Zodiac Aerospace, S.A.) 37

SEVENTH CAUSE OF ACTION - BREACH OF WARRANTY
(Against Defendant Air Cruisers Company, LLC d/b/a Zodiac Aero Evacuation Systems,
a subsidiary of Defendant Zodiac Aerospace, S.A.) 38

EIGHTH CAUSE OF ACTION - STRICT LIABILITY
(Against Defendant Air Cruisers Company, LLC d/b/a Zodiac Aero Evacuation Systems,
a subsidiary of Defendant Zodiac Aerospace, S.A.) 40

NINTH CAUSE OF ACTION - LOSS OF CONSORTIUM
(Against All Defendants) 42

VI PRAYER FOR RELIEF 42

VII. JURY DEMAND 43

1 Plaintiff brings this action for damages and complains of the Defendant ASIANA
2 AIRLINES, INC. (“ASIANA”), Defendant THE BOEING COMPANY (“BOEING”), and
3 Defendant AIR CRUISERS COMPANY, LLC d/b/a ZODIAC AERO EVACTUATION
4 SYSTEMS, a subsidiary of ZODIAC AEROSPACE, S.A. as follows:

5 **I. INTRODUCTION**

6 1. On July 6, 2013 at approximately 11:27 a.m. PDT, the main landing gear and
7 fuselage of a Boeing 777-200ER, registration HL7742 (“subject aircraft”) operating as ASIANA
8 Flight 214 (“subject flight”) impacted the airport perimeter sea wall just short of runway 28L at
9 SFO while attempting to land following a perilously low altitude flight-path, low air-speed
10 approach. This landing accident and impact violently slammed, jerked, tossed, and bounced the
11 passengers, ejecting some passengers and flight attendants through the gaping cavity created by
12 the separation of the aircraft’s empennage from the fuselage. Once the aircraft came to a
13 standstill, passengers had to jump from the plane and hobble from the twisted wreckage.
14 Emergency responders rushed to extricate the remaining injured and trapped passengers before
15 smoke and/or flames engulfed the plane and fatally injured the passengers. This horrific,
16 unforgettable nightmare resulted in the death of three teenage passengers and injuries to 288
17 passengers and 16 crew onboard the aircraft.

18 2. In a matter of seconds, what should have been a routine landing turned into a
19 chamber of horrors for the unsuspecting passengers. This landing was the result of a
20 combination of factors caused by the negligence and failures of the named defendants. First,
21 BOEING inadequately designed, manufactured, distributed and/or sold the aircraft that crashed
22 on July 6, 2013 with a number of defects, including a faulty auto-throttle control system,
23 inadequate auto-throttle warnings, ineffective low-speed warnings, and/or lap-only seat belts in
24 sections of its aircraft. Second, BOEING failed to adequately train, notify, monitor, supervise
25 and/or update pilots to fly the BOEING 777-200ER; and/or warn ASIANA of concerns BOEING
26 knew or should have known about the unfitness of ASIANA pilots to fly the BOEING aircraft.
27 Third, ASIANA negligently operated, maintained, controlled, equipped, and/or piloted the
28 fateful aircraft, including failing to provide passengers in Economy Class with the same robust

1 seat restraint systems as those in Business Class. Fourth, ASIANA failed to properly hire, train,
2 and/or monitor its pilots to assure they had the required skill and experience to safely land their
3 aircraft at all airports in which ASIANA did business. Fifth, AIR CRUISERS COMPANY, LLC
4 d/b/a ZODIAC AERO EVACTUATION SYSTEMS, a subsidiary of ZODIAC AEROSPACE,
5 S.A. caused further injuries to the passengers by providing emergency evacuation slides which
6 opened in the cabin injuring passengers and crew or failed to operate or open forcing many
7 passengers and others to jump and fall into wreckage and onto the tarmac. This crash and its
8 aftermath should never have occurred. It was a by-product of reckless inattention and errors by
9 the inadequately trained ASIANA flight crew in combination with dangerous design defects and
10 shortcomings with auto flight modes and low airspeed warning systems incorporated into the
11 BOEING aircraft.

12 **II. JURISDICTION AND VENUE**

13 3. This Court has subject matter jurisdiction of this case pursuant to 28 U.S.C. §
14 1331(a) in that this matter arises under the laws and treaties ratified by the United States,
15 including but not limited to the Convention for the Unification of Certain Rules for International
16 Carriage by Air (“Montreal Convention”). Defendant ASIANA is a signatory to the Montreal
17 Convention via the International Air Carrier Transportation Association (“IATA”) Intercarrier
18 Agreement on Passenger Liability which specifically removes limitations on damages.

19 4. The Court also has subject matter jurisdiction of this dispute pursuant to 28
20 U.S.C. § 1332, as this case involves a dispute between Plaintiff, a United States citizen, a
21 California resident, a passenger with a destination of California, and/or a passenger who entered
22 into the contract of carriage in the United States, and Defendants, corporations based in South
23 Korea, France, the State of Illinois, and the State of New Jersey and the amount in controversy
24 exceeds the jurisdictional minimum of this Court.

25 5. Venue is also proper in this District pursuant to 28 U.S.C. § 1391 because a
26 substantial part of the events or omissions giving rise to the claim occurred in the Northern
27 District of California and because Defendants are subject to personal jurisdiction in the Northern
28

1 District of California and because Defendants have sufficient contacts because they do business
2 and/or commerce in California.

3 **III. PARTIES**

4 **A. Plaintiff**

5 6. Plaintiff has suffered physical, emotional, and/or economic injuries as a result of
6 the ASIANA Flight 214 crash at SFO on July 6, 2013.

7 **B. Defendants**

8 7. Defendant **THE BOEING COMPANY** is a Delaware corporation with its
9 principal place of business in the State of Illinois. Boeing is, and at all relevant times was,
10 registered with the California Secretary of State as doing business in California, and it does
11 business in California and in this Judicial District.

12 8. Defendant **ASIANA AIRLINES, INC.** is a foreign corporation domiciled in and
13 existing under the laws of South Korea. Defendant ASIANA AIRLINES is, and at all relevant
14 times was, registered with the California Secretary of State as doing business in California, and it
15 does business in California and in this Judicial District.

16 9. Defendant **ASIANA AIRLINES, INC.** is, and at all times relevant was, a
17 common carrier for hire in the business of soliciting and/or transporting passengers for regularly
18 scheduled flights in and out of San Francisco International Airport to destinations in South Korea
19 and throughout the world.

20 10. Defendant **ASIANA AIRLINES, INC.** is, and at all times relevant was, a carrier
21 within the meaning of the Montreal Convention, operating round-trip flights between San
22 Francisco, California, to Seoul, South Korea and throughout the world.

23 11. Defendant **AIR CRUISERS COMPANY, LLC** is a Delaware limited liability
24 company with its principal place of business in Wall Township in the State of New Jersey. AIR
25 CRUISERS COMPANY, LLC has been a subsidiary of ZODIAC AEROSPACE, S.A. since
26 1987, and in 2013, AIR CRUISERS COMPANY, LLC began doing business as ZODIAC AERO
27 EVACUATION SYSTEMS to establish its presence as a member of the ZODIAC
28 AEROSPACE, S.A. group. Defendant ZODIAC AEROSPACE, S.A., is a French société

1 anonyme with a Management Board and Supervisory Board with its principal place of business
2 in Plaisir, France.

3 12. Defendant **ZODIAC AEROSPACE**, through its subsidiary AIR CRUISERS
4 COMPANY, LLC d/b/a ZODIAC AERO EVACUATION SYSTEMS, routinely engages in
5 continuous and systematic business in this District. The evacuation slides/rafts on ASIANA
6 Flight 214 were manufactured by AIR CRUISERS COMPANY, LLC. According to the 2012-
7 13 Annual Report of ZODIAC AEROSPACE, 55% of commercial aircraft including the subject
8 aircraft are equipped with “Zodiac Aerosafety evacuation slides,” and AIR CRUISERS
9 COMPANY, LLC d/b/a ZODIAC AERO EVACUATION SYSTEMS, is the sole producer of
10 such items for ZODIAC AEROSPACE.

11 **C. Agency and Concert of Action**

12 13. At all times herein mentioned, Defendants, and each of them, were the agents,
13 servants, alter egos, employees, partners, aiders and abettors, co-conspirators and/or joint
14 venturers of each of the remaining Defendants named herein and were at all times operating and
15 acting within the purpose and scope of said agency, service, employment, partnership, enterprise
16 conspiracy, alter ego and/or joint venture, and each Defendant has ratified and approved the acts
17 of each of the remaining Defendants. Each Defendant aided and abetted, encouraged, and
18 rendered substantial assistance to the other Defendants in breaching their obligations to Plaintiff,
19 as alleged herein. In taking action to aid and abet and substantially assist the commission of
20 these wrongful acts and other wrongdoings complained of herein, each of the Defendants acted
21 with an awareness of his/her/its primary wrongdoing and realized that his/her/its conduct would
22 substantially assist the accomplishment of the wrongful conduct, wrongful goals, and
23 wrongdoing.

24 ///

25 ///

26 ///

27 ///

28 ///

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

IV. FACTUAL BACKGROUND FOR THE CLAIMS ASSERTED

A. History of the Aircraft that Crashed

1. Boeing Designed, Manufactured, Promoted and Sold the Boeing 777As Safe For Air Travel

14. Defendant THE BOEING COMPANY (“BOEING”) designs, manufactures, inspects, assembles, markets and sells large commercial jet aircraft, including the BOEING 777, and provides product-related instructions, manuals, maintenance and training to airline customers worldwide. BOEING’s main commercial products are the 737, 747, 757, 767, 777, and 787 families of airplanes and the BOEING Business Jet.

15. The BOEING 777 is a long-range wide-body twin-engine jet airliner designed, manufactured, marketed, and sold by BOEING. BOEING claims to offer a family of “technologically advanced” airplanes and services. BOEING touts that “ensuring safe travels for all passengers and crew” is its primary focus. According to BOEING, the BOEING 777 was the first entirely new airplane manufactured by BOEING in more than a decade and was the first jetliner to be 100 percent digitally designed using three-dimensional computer graphics. Throughout the design process, the airplane was “preassembled” on the computer, eliminating the need for a full-scale mock-up.

16. **BOEING designed, manufactured, assembled, tested, serviced, and/or sold the BOEING 777-200ER aircraft that crashed on July 6, 2013, incorporating various components of the subject aircraft including, but not limited to, the auto-throttle, autopilot, flight control computers, warning systems, primary flights displays, overhead compartments, evacuation slides/rafts, seats, and/or seatbelts.**

17. In addition, BOEING wrote and/or approved instructions and warnings for the subject aircraft, including training manuals, flight manuals, operation manuals, maintenance manuals, maintenance instructions, inspection schedules, and service life schedules to be followed by owners and operators, including ASIANA, for the continued airworthiness and safe flight of the BOEING 777-200ER aircraft, including the subject aircraft.

1 18. BOEING also provided customer support and post-sale services to ASIANA, as it
2 related to the subject aircraft and other 777-200ER aircraft in its possession, including Alert
3 Service Bulletins, Service Bulletins, Service Letters, Technical Advisors, aircraft parts,
4 engineering and training personnel, and other similar customer support services.

5 19. BOEING offers airlines, including Asiana, “a complete training solution for
6 operators of BOEING airplanes.” BOEING’s North America flight training facility in Miami,
7 Florida is one of the largest in the world and offers training on the BOEING’s 737, 757, 767,
8 and 777 aircrafts, as well as the Airbus 320 (“A320”). BOEING also maintains, operates, runs,
9 supports, advertises, and/or promotes twenty training campuses with more than 80 full-flight
10 simulators around the world. At these facilities, BOEING provides training instructors and
11 training products (e.g., training courses and manuals) and services (e.g., simulator training
12 courses and web managed courses) to train and qualify pilots and flight crew to safely fly
13 BOEING aircraft.

14 20. **In 2002, BOEING entered into contract with ASIANA to train all of**
15 **ASIANA’s pilots. In addition, BOEING operates a training campus for ASIANA near the**
16 **Gimpo International Airport in South Korea. The Gimpo facility, which opened in 2006,**
17 **specializes in flight training for the 777.**

18 21. The flight crew (Flying Pilot, Supervising Pilot, First Officer) were trained by
19 BOEING to fly the BOEING 777.

20 **2. Asiana Purchased the Ill-Fated Aircraft in 2006**

21 22. Defendant ASIANA currently maintains and operates a fleet of seventy-nine
22 aircraft, including twelve BOEING 777-200ERs. The subject aircraft was a BOEING 777-
23 200ER built by BOEING and delivered to ASIANA in March 2006.

24 **B. Both Asiana Airlines and Boeing 777 Aircraft Have Been Involved in a**
25 **Number of Prior Incidents Which Raised Safety Concerns**

26 23. Since the BOEING 777 was first delivered, BOEING aircraft have been involved
27 in numerous incidents and several crashes.

28 ///

1 **1. Boeing 777 Incidents and Crashes Prior to July 6, 2013**

2 24. On **September 5, 2001**, a British Airways BOEING 777 suffered fire damage to
3 the lower wing panels and engine housing compartment during a refueling fire at Denver
4 International Airport, causing fatal burns to one person.

5 25. On **January 17, 2008**, British Airways Flight 38, a BOEING 777-200ER (the
6 same model of aircraft involved in the ASIANA July 6, 2013 incident) with Rolls-Royce Trent
7 895 engines flying from Beijing to London, crash-landed approximately 1,000 feet short of
8 London Heathrow Airport's runway 27L. The aircraft slid onto the runway's threshold, injuring
9 forty-seven people and damaging the aircraft's landing gear, wing roots, and engines. Upon
10 investigation, it was determined that the accident was caused by ice crystals from the fuel system
11 clogging the fuel-oil heat exchanger. In 2009, in response to the 2008 incident, air accident
12 investigators called for a redesign of this fuel-oil heat exchanger on the Trent 800 series engine.
13 Redesigned fuel oil heat exchangers were installed on British Airways' BOEING 777s by
14 October 2009.

15 26. In **February and November 2008**, two other Trent 895 engines on BOEING 777
16 aircraft suffered loss of thrust. The National Transportation Safety Board ("NTSB")
17 investigators concluded that, just as on January 17, 2008, the loss of power was caused by ice in
18 the fuel system, clogging the fuel-oil heat exchanger.

19 27. On **July 29, 2011**, an Egypt Air BOEING 777-200ER suffered a cockpit fire
20 while parked at a gate at Cairo International Airport, causing structural, heat, and smoke damage
21 to the aircraft. The plane was successfully evacuated with no injuries to personnel, and airport
22 fire teams extinguished the fire. Investigators focused on a possible electrical fault with a supply
23 hose in the cockpit crew oxygen system.

24 **2. In 2009 A Turkish Airlines Boeing 737 Crashed Under Very Similar**
25 **Circumstances as Flight 214 Placing Boeing on Notice of Design**
26 **Defects in the Low Speed Warning System on Its Aircraft**

27 28. On February 25, 2009, a Turkish Airlines owned and operated a BOEING 737-
28 800 crashed during landing at Amsterdam Schiphol Airport, Netherlands. The tragedy resulted

1 in the deaths of nine passengers and crew including all three pilots, and scores of injured
2 passengers.

3 29. An investigation by the Dutch Safety Board revealed that the left radio altimeter
4 had malfunctioned, causing the auto-throttle to disregard the pilots' selected speed setting,
5 whereby reducing the throttle level position to flight-idle and allowing the airspeed of the
6 BOEING 737 to decrease 40 knots below the selected airspeed. This flight condition went
7 unnoticed by the pilots, who were relying on the auto-throttle to maintain the approach speed,
8 until it was too late. The pilots did not recognize the reduction in speed and excessively high
9 pitch attitude of the aircraft until the stall warning went off at an altitude of 460 feet. As a result
10 of the perilous loss of airspeed and the delayed warning, the BOEING 737 lost control and
11 crashed before reaching the runway. Because the aircraft's nose was pitched up, the tail struck
12 the ground first before the rest of the aircraft slammed down on the tarmac. The impact
13 separated the horizontal stabilizer, both main landing gear legs, and the left and right engines
14 from the aircraft.

15 30. **The Dutch Safety Board considered the dangers of inadequate low speed**
16 **warning to the flight crew and recommended to BOEING that it evaluate the benefits of**
17 **installing an aural command low-speed warning in the aircraft. Since then, BOEING has**
18 **retrofitted 400 of the world's 3,900 BOEING 737 models with an aural command warning**
19 **of "LOW AIRSPEED, LOW AIRSPEED." However, the vast majority of BOEING 737**
20 **aircrafts – let alone its other models – was not updated with this aural command warning**
21 **and instead, incorporates an aural tone warning.**

22 3. Asiana Incidents and Crashes Prior to July 6, 2013

23 31. On **July 26, 1993**, a BOEING 737-500 passenger aircraft owned, operated,
24 maintained, and flown by ASIANA crashed during landing. On the pilot's third attempt to land
25 at South Korea's Mokpo Airport in poor weather, the aircraft collided into Mount Ungeo, eight
26 hundred feet above ground. Of the 116 occupants, sixty-six passengers and two crew members,
27 including the pilot, died.

1 32. On **November 30, 1998**, an ASIANA BOEING 747 struck a crane next to the
2 taxiway at JFK International Airport, injuring at one person. Despite the close proximity
3 between the airplane and the crane, the crew continued taxiing the airplane, failed to
4 communicate, and misjudged the clearance between the right wing and the crane.

5 33. On **November 11, 2000**, an ASIANA BOEING 747 taxiing at Ted Stevens
6 Anchorage International Airport in Anchorage, Alaska, collided with a parked Aeroflot Ilyushin
7 Il-62 and injuring several personnel on board the ASIANA aircraft. According to NTSB reports,
8 excessive taxi speed and inadequate maneuvering by the flight crew caused the collision.

9 34. On **October 28, 2009**, the tail of an ASIANA Airbus A321-200 carrying 147
10 occupants struck the runway on landing at Kansai International Airport in Japan. According to a
11 Japan Transport Safety Board report, the first officer misjudged and miscalculated the landing
12 profile by allowing the aircraft pitch angle to become excessively high during the landing,
13 resulting in a tail strike and causing damage to the aircraft.

14 35. On July 28, 2011, an ASIANA BOEING 747 cargo plane crashed into the East
15 China Sea, killing the only two crew on board. The crash occurred after the crew reported a fire
16 in the cargo compartment and attempted to divert to Jeju International Airport.

17 36. Accidents and incidents involving ASIANA-owned BOEING airplanes put
18 BOEING on notice of ASIANA flight crew deficiencies and other ASIANA deficiencies that
19 threatened passenger safety.

20 **C. The Horrific and Fatal July 6, 2013 Crash**

21 37. On July 6, 2013, Boeing 777-200ER Registration HL 7742 owned, operated, and
22 flown by ASIANA and designated as Flight 214 departed from Seoul, South Korea for the
23 regularly scheduled passenger flight to SFO, operating under the provisions of 14 Code of
24 Federal Regulations Part 129. On that day, Flight 214 carried 291 passengers and sixteen crew
25 members. Three captains and a first officer were among the crew members.

26 ///

27 ///

28 ///

1 38. Although the “flying pilot” (“FP”)¹ had flown into SFO twenty-nine (29) times as
2 a first officer on a BOEING 747, including handling four landings, this was the “flying pilot’s”
3 first time landing a BOEING 777 at SFO. From 2005 to 2013, the “flying pilot” was a captain
4 on the Airbus A320 and was also a ground school instructor and flight simulator instructor for
5 A320 and A321 aircraft. On July 6, 2013, the “flying pilot” was in the process of completing his
6 Initial Operating Experience (“IOE”), required to certify and/or qualify him to fly the BOEING
7 777 as pilot in command. ASIANA requires that pilots complete twenty flights and sixty hours
8 of flight time during the IOE for an aircraft. As of July 6, 2013, the “flying pilot” was about half
9 way through his required IOE BOEING 777 training, having completed ten legs and about thirty-
10 five hours of flight time.


11 39. The supervising captain, sitting in the right seat of the cockpit next to the “flying
12 pilot,” was on his first flight as a BOEING instructor in which his role was to supervise or
13 instruct another pilot. Flight 214 was the first time he had flown with the “flying pilot.”

14 40. During landing, the relief first officer was sitting in the observer’s seat in the
15 cockpit while the relief captain was sitting in the cabin, outside the cockpit. These relief pilots
16 had flown the plane for a five hour period.

17 41. During the flight, the relief captain programed the plane’s flight management
18 computer (“FMC”) with the Golden Gate 6 arrival and the localizer 28 approach into SFO. Prior
19 to the approach at SFO, the “flying pilot” obtained the appropriate terminal information and
20 stated that he conducted a thorough approach briefing.

21 42. Flight 214 approached SFO on Saturday, July 6, 2013 at approximately 11 a.m.
22 on a seventeen-mile straight-in visual approach, heading to San Francisco. Inside the airplane,
23 passengers had placed their seat backs in the upright position, locked their tray tables in place,
24 and stowed away their electronics and carry-on luggage in preparation for landing, as instructed.
25 None of 291 passengers had any knowledge or reason to intuit that the landing would turn into a
26 violent, unforgettable catastrophe.

27 _____
28 ¹ “Flying pilot” in the context of this complaint refers to the pilot who was sitting in the left seat of the Boeing 777-
200ER and was in training to become a Captain of the Boeing 777-200 aircraft.



45. When the plane was approximately 17 miles from SFO, the pilots informed TRACON that they saw the airfield.

46. At 11:23 a.m. and 4,500 feet, TRACON instructed the pilots to fly 180 knots until 5 miles from SFO


47. The “flying pilot” intercepted the 28L localizer, set the last approach fix crossing altitude at 1,800 feet in the mode control panel (“MCP”) altitude window, and began using the AFDS vertical speed (“VS”) mode to descend the subject aircraft. The “flying pilot” also adjusted the airspeed hold setting to 172 knots and acknowledged when the relief first officer comments that this speed was below the 180 knots that TRACON instructed the crew to maintain.

48. At 11:25 a.m. and at 2,400 feet, TRACON instructed the pilots to contact SFO control tower and shortly thereafter the pilots first attempted to contact the control tower.

///

///

///




49. During the approach, the “flying pilot” ordered that the plane’s flaps be extended and requested the supervising pilot reset the mode control panel altitude from 1,800 feet to 3,000 feet, which was the missed approach altitude.

50. At an altitude of 1,600 feet, the aircraft’s Digital Flight Data Recorder (“DFDR”) shows that the autopilot flight director system (“AFDS”) pitch mode changed to flight level change (“FLCH”) mode. This change commanded the autopilot to climb to the missed approach altitude of 3,000 feet which had been set per standard operating procedures in the mode control panel. To cancel this unexpected climb the flying pilot disconnected the autopilot, called out manual flight and, because the speed and altitude were higher than desired, reduced the throttle levers to the idle position.

51. Shortly thereafter the “flying pilot” requested that the supervising pilot set the command airspeed to 137 knots, the target speed for the approach. Unbeknownst to the flight crew, the movement of the throttle levers to the idle position while in FLCH mode resulted in an automatic (un-commanded) change of the autothrottle mode from THRUST to HOLD, thereby turning off airspeed protection and disabling the autothrottle wake up function (when in HOLD

1 mode the autothrottle will not engage or add thrust to support stall protection even if there are
2 large deviations in airspeed).

3 52. At 11:26 a.m. and at an altitude of 1,000 feet, the pilots made their second attempt
4 to contact the control tower.



16 53. At 11:27 a.m. and at 600 feet, the control tower cleared Flight 214 for landing.

17 54. At approximately 500 feet, the flight crew was attempting to maneuver the
18 aircraft so it was properly aligned with the runway to achieve a safe landing and were unaware
19 that the plane had slowed below the target airspeed of 137 knots they had selected for the
20 approach airspeed.

21 55. At approximately 200 feet, the aircraft's airspeed had dropped to 118 knots. At
22 that time, the supervising pilot noticed that all four Precision Approach Path Indicators
23 ("PAPI")² lights were red and that the auto-throttle control system was not maintaining speed. In
24

25
26 ² PAPI is a light array system consisting of four light units located near the runway and visible from up to five miles
27 away. PAPI provides a visual descent path to the runway touchdown zone. When the four light units are white, the
28 plane's flight path is too high and, if maintained, will cause the aircraft to land beyond the touchdown zone. When
the four light units are red, the plane is too low and, if maintained, will cause the aircraft to land below touchdown
zone. When the array displays two red and two white light units, the plane is at the proper three degree angle
descent path.

1 an interview with the NTSB, the “flying pilot” stated that he believed that the auto-throttle
2 system would prevent the aircraft from going below the minimum speed by bringing the
3 aircraft’s throttles out of the idle position.

4 56. Seconds before impact, the supervising pilot pushed the throttles forward and
5 called out “go around.” The “flying pilot” pitched the aircraft’s nose up more than ten degrees
6 and moments later the pilots received a stall warning consisting of an aural warning tone,
7 accompanied by a tactile vibration warning on the throttle (also known as “stick shaker”).³ A few
8 seconds later, the subject aircraft struck the airport seawall.

9 57. At no time prior to impact with the seawall in this landing accident did the crew
10 warn or notify the passengers of the impending disaster. The impact of the wheels with the rock
11 seawall immediately before SFO’s Runway 28L when the plane was moving at a speed of over
12 120 miles per hour was the passengers first awareness of the harm that would come to them
13 moments later. The subject aircraft suffered separation of the empennage⁴ and landing gear from
14 the fuselage, leaving a gaping cavity in the rear portion of the aircraft. Flung about in their seats
15 and against the seatbelts and aircraft interior,, passengers heard the searing scrape of metal
16 against stone and asphalt as the aircraft struck the sea wall and slid across the tarmac before
17 spinning counterclockwise and resting on its belly, creating a path of debris and ejecting some
18 aircraft occupants onto the runway from the gaping hole where the empennage was once
19 attached.

20 ///

21 ///

22 ///

23 ///

24
25 _____
26 ³ A low-speed aerodynamic stall occurs when the airspeed slows, altering the angle-of-attack of the aircraft’s wing
27 relative to airflow under and over the wing. This disrupts the airflow to the point that the wing can no longer
28 generate the lift required to fly safely.

⁴ The empennage is the aircraft’s tail assembly and includes the vertical fin and horizontal stabilizers.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28





1
2
3
4
5
6
7
8
9
10
11 58. The powerful impact with the seawall and runway caused the passengers to be
12 violently thrown against their seatbelts and about the cabin and sustain numerous injuries.
13 Passengers in Flight 214's economy class were thrown over their lap-only seat belts, causing
14 some passengers to hit their heads on the cabin walls, armrests and/or on the seatbacks in front of
15 them, some of which collapsed due to the impact. The aircraft's cabin interior suffered heavy
16 damage with overhead compartments opening from the multiple aircraft impacts, tossing luggage
17 and debris onto the passengers and blocking aisles. The crash uprooted, dislodged, or collapsed
18 seats, causing further injuries to passengers and blocking routes of egress.



1 59. The subject aircraft lost its tail section, including its vertical and horizontal
2 stabilizers, leaving a ragged hole and flinging occupants out of the aircraft onto the runway. The
3 subject aircraft's right engine detached from the wing and lodged against the right side of the
4 fuselage. The left engine detached and landed to the right of runway 28L. Oil spewed from the
5 aircraft, providing a dangerous source for ignition.

6 60. Despite the policy that planes must be manufactured for all passengers to be
7 evacuated within ninety seconds⁵, the subject aircraft was not evacuated within ninety seconds.
8 **The emergency doors and chutes were not opened until approximately ninety seconds after**
9 **the plane came to a full stop** on the side of the runway. After the crash, a flight attendant asked
10 the pilots in the cockpit whether or not to evacuate the passengers and was told not to evacuate
11 the plane while the pilots talked to the SFO tower. Another flight attendant made an
12 announcement over the aircraft's PA system instructing passengers to stay in their seats and not
13 to evacuate. However, a flight attendant seated just forward of the wing saw fire and smoke
14 outside the window and notified the pilots. Only then did the pilots order evacuation.

15 61. The emergency evacuation process was hindered by the malfunction of the
16 evacuation slides manufactured by AIR CRUISERS COMPANY, LLC, d/b/a ZODIAC AERO
17 EVACUATION SYSTEMS, a subsidiary of ZODIAC AEROSPACE, S.A.

18 62. Two of the evacuation slides, 1R and 2R, deployed inside the cabin pinning two
19 flight attendants in their jump seats and blocking those exits for passengers seeking to evacuate
20 from the plane.

21 63. The release mechanism on some of the slides suffered catastrophic failure and
22 was overwhelmed by the forces experienced during the accident, which failure caused the slide
23 to release inboard and then inflate.

24
25
26 ⁵ The Federal Aviation Administration ("FAA") is focused on increasing the probability of occupant survival and
27 decreasing the probability of death or injury in an aircraft accident. Research conducted by FAA on commercial
28 aircraft exposed to an external fuel fire illustrated that the time available for passenger evacuation before flash over
occurred in the cabin was approximately ninety seconds. In response, the FAA established a regulation that
commercial aircraft must be able to demonstrate that a full load of passengers can be evacuated within ninety
seconds to prevent death or injury from flash over.

1 64. The evacuation slides were not properly tested for circumstances of a crash such
2 as that of Flight 214 thus resulting in a failure to properly operate. The slide defects caused the
3 evacuation to be delayed as those evacuating the plane were required to find alternate means of
4 exiting the plane if doors 1R and 2R were their closest emergency exits.

5 65. In addition to the two slides that deployed inside the cabin, multiple additional
6 evacuation slides either failed to deploy at all or did not deploy fully. These included Doors 3L
7 (did not deploy), 3R (partially deployed), and Door 4L (did not deploy). Passengers who had to
8 use these emergency exits with malfunctioning slides had to jump from the aircraft and into
9 wreckage and fall to the ground.

10 66. On September 30, 2010, AIR CRUISERS issued a Service Bulletin (No. 107-25-
11 30) to replace the housing assemblies for evacuations slides/rafts manufactured by AIR
12 CRUISERS because “[h]ousing assemblies supplied with ‘unsealed’ anodize may exhibit
13 excessive levels of corrosion, which can affect release assembly functionality.” This Service
14 Bulletin was revised twice prior to the crash of Flight 214 – first on November 11, 2011 and then
15 on July 27, 2012. The FAA issued Airworthiness Directive 2013-05-010 on March 29, 2013
16 related to this issue and required an inspection and corrective action be performed within 42
17 months.

18 67. In its teardown inspections the various evacuation slides/rafts from Flight 214,
19 1R, 2R, 3L, 3R, and 4L all had blue housing indicating that they had been changed pursuant to
20 the directive, but six of the eight slides still malfunctioned.

21 68. Only two of the eight slides on board Flight 214 deployed correctly requiring that
22 the nearly 300 passengers on board the aircraft had to evacuate the aircraft either via those two
23 deployed slides, out the rear of the plane where the tail end was missing, or jumping from one of
24 the other doors where the slides did not deploy, causing further injury to Plaintiffs and others in
25 the evacuation,

26 69. By manufacturing the evacuation slides in such a defective manner that the
27 majority of them either malfunctioned or did not deploy at all, AIR CRUISERS COMPANY,
28 LLC, d/b/a ZODIAC AERO EVACUATION SYSTEMS, a subsidiary of ZODIAC

1 AEROSPACE, S.A., created an unnecessarily dangerous situation which imperiled the lives of
2 those passengers seeking to evacuate Flight 214 after its crash on July 6, 2013.

3 70. Once evacuation began, dazed and panicked passengers scrambled to leave the
4 aircraft before it erupted in flames. However, injuries, uprooted seats, scattered luggage, seat-
5 belts and faulty evacuation slides complicated the evacuation process. Emergency responders
6 ran up one of the aircraft's inflated escape chutes to get to those trapped inside, clearing a
7 passage by tossing out luggage and wrecked overhead bins that were blocking the escape route
8 and/or pinning passengers as the flames spread. A black plume of smoke rose into the sky as
9 flames engulfed the aircraft and burned away the top of the fuselage. Passengers, trapped by
10 uprooted seats, luggage, escape slides, and/or seatbelts, were surrounded by thick, black smoke
11 as rescuers lifted them to safety.



12
13
14
15
16
17
18
19
20
21
22
23
24 ///
25 ///
26 ///
27 ///
28 ///

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28



1 71. What should have been a safe and smooth landing, turned into a chaotic disaster,
2 resulting in the death of three teenage girls and various injuries to the other passengers and crew.
3 Emergency responders at the scene triaged the aircraft’s occupants. The injured passengers and
4 flight attendants were transferred to eleven different Bay Area hospitals. As hospitals fought to
5 save lives and provide emergency care to these poor passengers, the NTSB initiated an
6 investigation into the causes of this fateful crash.

7 **D. Boeing Installed a Faulty and/or Defective Auto-Throttle Control System**
8 **with Latent Dangerous Shortcomings**

9 72. The crash of Flight 214 occurred after the aircraft’s speed dropped below the
10 minimum speed needed to safely approach the runway, and land the aircraft. During the landing
11 process, the ASIANA Flight 214 “flying pilot” set the airspeed for 137 knots and assumed that
12 the auto-throttle control system was maintaining the aircraft’s airspeed. However, due to
13 BOEING’s design, manufacture and/or installation of inadequate and/or defective auto-throttle
14 control systems, autopilot control systems, and/or low airspeed warning systems in the aircraft,
15 the pilots were not timely and adequately warned of the disengaged auto-throttle and/or fatefully
16 low airspeed.

17 73. The automatic flight control system in the B777 consists of an automatic flight
18 director system (“AFSD”) and an auto-throttle control system. Each of these systems is
19 controlled by and/or through the mode control panel (“MCP”) in the cockpit and the flight
20 management computers. Through these systems, pilots can use various levels of automation to
21 assist them in all phases of flight and many combinations of automation, each with different
22 characteristics and considerations.

23 ///
24 ///
25 ///
26 ///
27 ///
28 ///



12
13
14
15
16
17
18

74. The auto-throttle control system can regulate engine power in all flight profiles including take-off, climb, cruise, descent, approach, landing, and go-around. A pilot can program the appropriate landing requirements into the aircraft's autopilot and/or auto-throttle control system; thereby automating the process to properly maintain airspeed and glide path. While the autopilot automates pitch and roll, the auto-throttle automates the engine power requirements to maintain aircraft airspeed or vertical speed.

19
20
21
22
23

75. In order for the automatic throttle control system to be operating and maintaining a desired airspeed, it first must be armed and then engaged. To arm the auto-throttle control on a B777-200ER, the pilots actuate two switches, one for the left and one for the right engine. Once armed, the pilot can then engage the automatic throttle control by pressing another switch – which then turns green.

24
25
26
27
28

76. In most modes, the auto-throttle control system helps pilots prevent their airspeeds from becoming too slow by sensing the slow speed and automatically adding power to correct the situation. However, when the autopilot pitch mode is set to FLCH SPD and the engines are set at or near idle, the auto-throttle control system often moves automatically into HOLD mode. When the autopilot is in FLCH SPD and autothrottle is in HOLD mode, no speed

1 protection is provided. In other words, the auto-throttle control system will not automatically
2 reactivate or “wake up” to prevent an aircraft from slowing down towards a stall.

3 77. The Boeing 777 Operator’s manual does not adequately, clearly, and concisely
4 warn or instruct pilots about this dangerous condition and how to avoid, mitigate, and/or respond
5 to it. BOEING has stated that the mode change from engaged to HOLD is displayed on the
6 Flight Mode Annunciator (“FMA”) and highlighted for 10 seconds with a green box.

7 78. As a result of the lack of warning, instructions, and training on these systems, the
8 pilots did not realize that the autopilot and/or auto-throttle control system was not maintaining
9 the aircraft’s airspeed during the approach.

10 79. BOEING failed to design, manufacture and/or install an effective warning system
11 to notify pilots whether or not the auto-throttle control system is armed and/or engaged, and/or
12 the consequent danger of disengagement known in some circles as the “Flight Level Change
13 Trap”. BOEING also failed to warn, train and/or notify pilots to recognize auto-throttle control
14 system warnings and/or to constantly monitor airspeed when the auto-throttle control system is
15 armed and/or engaged, especially during landing.

16 **E. Boeing Failed to Install an Adequate Low Airspeed Warning System**

17 80. BOEING installed an ineffective and inadequate low airspeed warning system in
18 its 777 models. The BOEING 777 has a low airspeed warning system which detects low
19 airspeed and alerts the crew with a standard warning tone followed by a text message on a
20 display screen, “AIRSPEED LOW.” The standard warning tone requires the crew divert
21 attention to the display screen to determine the cause of the alert. The screen also contains other
22 alerts, such as “OIL PRESSURE LOW,” “FUEL PRESSURE LOW,” and other system status
23 indicators. The inadequate tonal warning poses the greatest danger during approach and landing
24 conditions when low airspeed situations are more likely to occur in addition to a number of
25 different situations requiring the pilots’ attention.

26 81. Because the ASIANA pilots’ primary attention was on aligning the aircraft’s
27 course to center on Runway 28L, the pilots did not realize that the auto-throttle control system
28 was not maintaining the aircraft’s airspeed during the approach and that the aircraft had slowed

1 to a dangerously low airspeed. Had an aural command warning of “AIRSPEED LOW” been
2 installed in the aircraft, as it is in the BOEING 737s and all Airbus models, the pilots would have
3 realized that the aircraft was at a dangerously low airspeed and could have taken immediate
4 action to rectify the problem by increasing airspeed and/or initiate a go around.

5 82. BOEING knew or should have known that its standard warning tone was
6 inadequate and/or ineffective and should have updated its aircraft.

7 83. In response to the February 25, 2009 Turkish Airlines Flight 1951 crash, where
8 the pilots flying a BOEING 737 were unaware that the auto-throttle was not maintaining
9 airspeed, the Dutch Safety Board recommended that BOEING evaluate the benefits of installing
10 an aural low-air-speed warning system in the aircraft. BOEING responded by retrofitting 400 of
11 the world’s 3,900 BOEING 737 models with an aural command warning of ‘LOW AIRSPEED,
12 LOW AIRSPEED.’”

13 84. Airbus SAS, the other leading manufacturer of commercial aircraft, has installed
14 an aural command warning of “SPEED-SPEED-SPEED” every five seconds between 2,000 and
15 100 feet when aircraft airspeed drops to an unsafe level. The aural command warning has been
16 installed on the A320 family of aircraft since 1995 and on all A330, 340, 350 and 380 aircraft.

17 85. Despite being fully aware of the NTSB recommendations, the Dutch Safety
18 Board’s recommendations, and Airbus’ practice of implementing the systems, BOEING failed to
19 retrofit or reprogram its BOEING 777 with a continuous and/or aural command warning that is
20 the most effective method to alert the pilots to the critical and imminent danger of low airspeed.

21 **F. Boeing and Asiana Failed to Properly Train Its Pilots**

22 86. Despite ASIANA’s reported practice of “put[ting] safety first,” ASIANA failed to
23 properly train and supervise its pilots to ensure the safety of its passengers. ASIANA pilots are
24 required to complete classroom and flight simulator training. ASIANA trains its pilots at
25 BOEING’s training facilities. In 2002, BOEING entered into contract with ASIANA to train all
26 of ASIANA’s pilots. In 2006, when ASIANA received the subject aircraft, BOEING opened a
27 BOEING 777 training facility near the Gimpo International Airport in South Korea.


28

1 87. BOEING’s training programs promise to help airlines “meet increasing demands
2 for qualified pilots by producing flight-ready officers quickly and efficiently.” BOEING’s full-
3 flight simulator training for its pilots is intended to allow ASIANA to economically enhance its
4 quality flight training services and gain efficiencies in pilot training for ASIANA’s fleet of
5 BOEING 737-400/-500s, 747-400s, 767-300s, 777-200s and Airbus 321s.

6 88. ASIANA also requires its pilots to complete an Initial Operating Experience
7 (“IOE”), which pairs pilots who are new to an aircraft model with more experienced supervising
8 or training pilots. The IOE requires twenty familiarization flights with sixty hours of flight time
9 under the supervision of pilots who are experienced with the particular aircraft model.
10 ASIANA’s IOE, along with ASIANA’s initial pilot training, calls for significantly less flying
11 hours than what international standards require in order to be considered qualified. BOEING, as
12 the pilot training provider for ASIANA, knew or should have known that ASIANA pilots
13 proficiency for safely piloting its aircraft were significantly below international standards.


14 **G. Boeing and/or Asiana Designed and Installed Lap Only Seat Belts In Sections**
15 **Of The Boeing 777 That Crashed**

16 89. The Asiana Flight 214 BOEING 777-200 had multiple types of seat belt systems.
17 In Economy Class, passengers were provided with lap-only seat belts. Business class
18 passengers, flight attendants, and pilots were provided with multipoint harnesses, restraining
19 those occupants by lap and shoulder straps.




1 90. Generally, airplane seatbelts must be designed so that a person making proper use
2 of the equipment will not suffer serious injury as a result of inertia forces during an emergency
3 landing or in flight turbulence.

4 91. Although lap-only safety belts are standard in many commercial airliners, studies
5 have consistently found significant benefits, in terms of injury reduction, through shoulder
6 harness use. A 1985 NTSB study found that shoulder harness were the most effective method of
7 reducing fatal and serious injuries in general aviation airplane accidents. According to the
8 NTSB, shoulder harness use could have prevented 75% of the fatalities and 79% of the serious
9 injuries considered in its study. In a 2011 analysis of over 37,000 general aviation accidents, the
10 NTSB found that the risk of fatal or serious injury with a lap-only safety belt was nearly 50%
11 higher than the lap and shoulder harness combination. The benefits rendered by the lap/shoulder
12 harness combination were even greater in accidents that occurred during take-off and landing.



13
14
15
16
17
18
19
20
21
22
23
24
25 ///
26 ///
27 ///
28 ///



92. Shoulder harnesses are common throughout the aviation industry. Shoulder harnesses are required for all seats in general aviation aircraft. Under 14 C.F.R. § 91.521, all flight crew stations (e.g. pilots and flight attendants) must have a restraint system consisting of a combined safety belt and shoulder harness. Pilots usually have a five-point seat restraint system while flight attendants are provided four-point seat belts. Additionally, many private jets and first class cabins have lap and shoulder harness seat belt systems.

93. Unlike passengers in ASIANA Flight 214's Economy Class, passengers sitting in Business Class were more safely and robustly secured to their seats using lap and shoulder harnesses, protecting those particular passengers from jerking in their seats and striking their head and body against the aircraft. Eugene Rah, a passenger sitting in business class of Flight 214, stated. "Luckily the seat I was sitting, it has [sic] one more strap coming across my chest here [indicating] in addition to the one that goes around the waist cause it was a sleeper seat. If I did not have that, I'd have hit the ceiling. That's how hard the impact was." See July 7, 2013 interview of Eugene Rah, located at <http://www.cnn.com/video/data/2.0/video/us/2013/07/07/nr-sf-plane-crash-survivor-eugene-rah.cnn.html>.

94. Passengers not equipped with multipoint harnesses suffered injuries, including but not limited to abdominal, spinal, and head injuries, when they were violently jerked in their seats

1 from the impact. In describing the role of lap-only seat belts in causing a Flight 214 passenger's
 2 unstable fracture of his cervical spine, St. Mary's Medical Center surgeon Dimitriy Kondashov
 3 stated, "Because there was no shoulder component to his seat belt, that allowed [the passenger]
 4 to violently slam [his] forehead into the seat in front of him, and then this resulted in some head
 5 trauma." See William Harless, "Seat-Belt Design Played Role in Asiana Crash Injuries" Wall
 6 Street Journal, July 10, 2013. Had passengers in Economy Class safely been restrained by lap
 7 and shoulder harnesses, many injuries would have been prevented and/or mitigated.

8 **V. CAUSES OF ACTION**

9 **FIRST CAUSE OF ACTION**
 10 **PASSENGER LIABILITY / STRICT LIABILITY**
 11 **(Against Defendant Asiana Airlines Inc.)**

12 95. Plaintiff incorporates and re-alleges each of the allegations set forth above as
 13 though fully set forth herein.

14 96. At all relevant times, ASIANA was a common carrier engaged in the business of
 15 providing air transporting fare-paying passengers on international flights to the United States.

16 97. Under Articles 17 and 21(a) of the Montreal Convention, Defendant ASIANA is
 17 strictly liable to Plaintiff for provable damages of up to 113,100 SDRs (which equates to
 18 approximately U.S. Dollar \$170,000).

19 98. In addition, under Article 21(2) of the Montreal Convention, due to the
 20 negligence, carelessness, gross negligence, and/or recklessness hereinabove set forth and the
 21 injuries and damages attendant thereto Plaintiff seeks damages in excess of 113,100 SDRs,
 22 according to proof at the time of trial.

23 99. As a direct and legal result of the negligence, carelessness, gross negligence,
 24 recklessness and/or otherwise wrongful acts and/or omissions hereinabove set forth, Plaintiff has
 25 suffered the injuries and damages hereafter set forth.

26 100. As a legal result of the wrongful conduct of ASIANA set forth above, Plaintiff
 27 was injured in Plaintiff's health, strength, and activity, and has sustained injuries to Plaintiff's
 28 body and/or mind, all of which have caused Plaintiff great physical, mental, emotional, and
 nervous pain and suffering.

1 101. By reason of the wrongful conduct of ASIANA set forth above, Plaintiff was
2 required to and continues to employ physicians and other health care providers to examine, treat,
3 and care for Plaintiff’s injuries, and has incurred, and will continue to incur, medical and
4 incidental expenses for such examination, treatment, rehabilitation, and care in an amount
5 according to proof.

6 102. By reason of the incident, Plaintiff has suffered a loss of income, and/or a loss of
7 earning capacity, in an amount according to proof.

8 103. By further reason of the premises, Plaintiff suffered the loss of Plaintiff’s personal
9 property, including but not limited to personal effects and items in checked in luggage and carry-
10 on items, in an amount according to proof at trial.

11 WHEREFORE, Plaintiff prays for relief as set forth below.

12 **SECOND CAUSE OF ACTION**
13 **NEGLIGENCE**
(Against Defendant Asiana Airlines Inc.)

14 104. Plaintiff incorporates and re-alleges each of the allegations set forth above as
15 though fully set forth herein.

16 105. At all relevant times, ASIANA was a common carrier engaged in the business of
17 providing air transportation for fare-paying passengers on international flights to the United
18 States. As a common carrier, ASIANA owed Plaintiff as passengers of Flight 214 a duty of
19 utmost care and the vigilance for the safe transport of passengers. As the holder of an Air
20 Carrier Operating Certificate authorized to serve as a common carrier in air transportation in the
21 United States pursuant to the provisions of Part 121 of the Federal Aviation Regulations [14
22 C.F.R. 121.1 et seq.], ASIANA owed a duty of care to Plaintiff consistent with the requirement
23 that it operate and maintain its aircraft in the safest manner. ASIANA also had a common law
24 duty to operate and maintain ASIANA Flight 214 to a standard equal to the highest possible
25 degree of safety.

26 106. At all times hereinabove set forth, ASIANA breached its duty of care to Plaintiff
27 as passengers aboard ASIANA Flight 214 with respect to its failure to safely operate, maintain,
28

1 manage, control, equip, handle, and/or pilot Flight 214 and/or adequately and appropriately train
2 its pilots and crew to operate a passenger aircraft, including but not limited to the following:

- 3 ● failure to train its pilots and flight crew to constantly monitor aircraft
4 airspeed;
- 5 ● failure to train its pilots to safely operate the auto-throttle control system
6 aboard the aircraft;
- 7 ● failure to train its pilots to safely operate the autopilot system aboard the
8 aircraft;
- 9 ● failure to train its pilots to safely operate the flight director aboard the
10 aircraft;
- 11 ● failure to train its pilots to communicate with one another in order to
12 safely operate and monitor flight systems aboard the aircraft;
- 13 ● failure to train its pilots to prevent their aircraft from entering into unsafe
14 airspeeds given the flight condition/s;
- 15 ● failure to train its pilots to timely recognize and safely respond to low
16 airspeeds given the flight condition/s;
- 17 ● failure to train its pilots to timely and safely evacuate the aircraft.

18 107. As a direct and legal result of the negligence, carelessness, gross negligence,
19 recklessness and/or otherwise wrongful acts and/or omissions hereinabove set forth, Plaintiff has
20 suffered the injuries and damages hereafter set forth.

21 108. As a legal result of the wrongful conduct of ASIANA set forth above, Plaintiff
22 was injured in Plaintiff's health, strength, and activity, and has sustained injuries to Plaintiff's
23 body and/or mind, all of which have caused Plaintiff great physical, mental, emotional, and
24 nervous pain and suffering.

25 109. By reason of the wrongful conduct of ASIANA set forth above, Plaintiff was
26 required to and continues to employ physicians and other health care providers to examine, treat,
27 and care for Plaintiff's injuries, and has incurred, and will continue to incur, medical and
28

1 incidental expenses for such examination, treatment, rehabilitation, and care in an amount
2 according to proof.

3 110. By reason of the incident, Plaintiff has suffered a loss of income, and/or a loss of
4 earning capacity, in an amount according to proof.

5 111. By further reason of the premises, Plaintiff suffered the loss of Plaintiff's personal
6 property, including but not limited to personal effects and items in checked in luggage and carry-
7 on items, in an amount according to proof at trial.

8 112. The Montreal Convention, formally entitled the Convention for the Unification of
9 Certain Rules for International Carriage by Air, sets forth the liability and compensation owed by
10 airlines for the injury and death of a passenger. Under Article 21(2), Plaintiff is entitled to
11 provable damages in excess of 113,100 Special Drawing Rights ("SDR") due to the negligence,
12 carelessness, gross negligence and/or recklessness of Defendant ASIANA, its agents and/or its
13 servants, as hereinabove set forth.

14 WHEREFORE, Plaintiff prays for relief as set forth below.

15 **THIRD CAUSE OF ACTION**
16 **NEGLIGENCE**
(Against Defendant The Boeing Company)

17 113. Plaintiff incorporates and re-alleges each of the allegations set forth above as
18 though fully set forth herein.

19 114. At all relevant times hereinabove set forth, Defendant BOEING was the designer,
20 manufacturer, distributor and/or seller of the BOEING 777 aircraft and its subsequent variants,
21 including the subject BOEING 777-200ER. Defendant BOEING was, at all times relevant, in
22 the business of designing, testing, manufacturing, selling, assembling, building, distributing,
23 marketing, and/or inspecting aircraft as suitable and safe for passenger air transportation,
24 including the subject BOEING 777-200ER that crashed at SFO on July 6, 2013.

25 115. At all relevant times hereinabove set forth, Defendant BOEING operated,
26 supervised, managed and/or oversaw the training facility that trained ASIANA's pilots to fly the
27 BOEING 777, and knew or should have known of the unfitness of ASIANA pilots to safely
28 operate the BOEING 777-200ER for passenger air travel.

1 116. At all times hereinabove set forth, BOEING breached its duty of care to Plaintiff
2 as passenger aboard ASIANA flight 214 with respect to the design, manufacture, inspection,
3 testing, assembly, distribution, and/or sale of a safe, airworthy aircraft; including the failure to
4 train, instruct, and/or issue advisory warnings necessary to assure the safe operation, control,
5 management and/or maintenance of the aircraft. BOEING acts and/or omissions include, but are
6 not limited to the following:

- 7 ● failure to manufacture and provide a safe and effective auto-throttle
8 control system on their aircraft, including the subject aircraft;
- 9 ● failure to provide adequate warnings with regard to the use of the auto
10 throttle control system on their aircraft including the subject aircraft;
- 11 ● failure to manufacture and provide a safe and adequate low airspeed
12 warning device on their aircraft, including the subject aircraft;
- 13 ● failure to provide adequate warnings with regard to the use of the flight
14 control systems on their aircraft including the subject aircraft;
- 15 ● failure to manufacture and provide safe and effective flight director
16 systems, EICAS, flight control computers and/or primary flight displays
17 on their aircraft, including the subject aircraft.
- 18 ● failure to manufacture and provide safe and effective evacuation
19 slides/rafts for its passengers.
- 20 ● failure to manufacture and provide safe and effective seating for its
21 passengers, which included improper seatbelts, particularly for Plaintiff
22 and those passengers of ASIANA Flight 214 who were seated in economy
23 class who had lap-only seatbelts.
- 24 ● failure to properly train pilots to constantly monitor aircraft airspeed;
- 25 ● failure to properly train pilots to safely operate the auto-throttle control
26 system aboard their aircraft;
- 27 ● failure to properly train pilots to safely operate the autopilot system
28 aboard their aircraft;

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

- failure to properly train pilots to safely operate and safely respond to the flight director aboard their aircraft;
- failure to properly train pilots to safely operate, monitor and respond to the flight systems aboard their aircraft;
- failure to properly train pilots to prevent their aircraft from entering into unsafe airspeeds given the flight condition/s;
- failure to properly train pilots to timely recognize and safely respond to low airspeeds given the flight condition/s.
- failure to properly train pilots to safely operate their aircraft in both Visual Meteorological Conditions (“VMC”) and Instrument Meteorological Conditions (“IMC”) conditions.

117. As a direct and legal result of Defendant BOEING’s negligence, carelessness, gross negligence, recklessness and/or otherwise wrongful acts and/or omissions hereinabove set forth, Plaintiff has suffered the injuries and damages hereafter set forth.

118. As a legal result of the wrongful conduct of BOEING set forth above, Plaintiff was injured in Plaintiff’s health, strength, and activity, and has sustained injuries to Plaintiff’s body and/or mind, all of which has caused Plaintiff great physical, mental, emotional, and nervous pain and suffering.

119. By reason of the wrongful conduct of BOEING set forth above, Plaintiff was required to and continues to employ physicians and other health care providers to examine, treat, and care for Plaintiff’s injuries, and has incurred, and will continue to incur, medical and incidental expenses for such examination, treatment, rehabilitation, and care in an amount according to proof.

120. By reason of the incident, Plaintiff has suffered a loss of income and/or a loss of earning capacity, in an amount according to proof.

121. By further reason of the premises, Plaintiff suffered the loss of Plaintiff’s personal property, including but not limited to personal effects and items in checked in luggage and carry-on items, in an amount according to proof at trial.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

WHEREFORE, Plaintiff prays for relief as set forth below.

FOURTH CAUSE OF ACTION
BREACH OF WARRANTY
(Against Defendant The Boeing Company)

122. Plaintiff incorporates and re-alleges each of the allegations set forth above as though fully set forth herein.

123. Defendant BOEING was the designer, manufacturer, distributor and/or seller of the Boeing 777 and its subsequent variants, including the BOEING 777-200ER.

124. Prior to the crash of ASIANA Flight 214, Defendant BOEING expressly and/or impliedly warranted and represented that the subject aircraft (the BOEING 777-200ER), including its component parts and instruments, and in conjunction with the instructions and warnings given by BOEING, was airworthy, of merchantable quality, both fit and safe for the purpose of commercial air travel for which it was designed, intended and used. Additionally, Defendant BOEING further warranted that the subject aircraft and/or its component parts were free from all defects.

125. Defendant BOEING breached said warranties in that the subject aircraft was not airworthy, of merchantable quality, or fit and safe for the purposes for which it was designed, intended and used, and free from all defects as set forth above.

126. Plaintiff, as passenger of ASIANA Flight 214, was intended third-party beneficiary of Defendant BOEING's warranties that ASIANA Flight 214 (the BOEING 777-200ER) was airworthy, of merchantable quality, both fit and safe for the purposes for which it was designed, intended and used, and free from all defects.

127. As a direct and legal result of Defendant BOEING's negligence, carelessness, gross negligence, recklessness and/or otherwise wrongful acts and/or omissions hereinabove set forth, Plaintiff has suffered the injuries and damages hereafter set forth.

128. As a legal result of the wrongful conduct of BOEING set forth above, Plaintiff was injured in Plaintiff's health, strength, and activity, and has sustained injuries to Plaintiff's body and/or mind, all of which has caused Plaintiff great physical, mental, emotional, and nervous pain and suffering.

1 129. By reason of the wrongful conduct of BOEING set forth above, Plaintiff was
2 required to and continues to employ physicians and other health care providers to examine, treat,
3 and care for Plaintiff's injuries, and has incurred, and will continue to incur, medical and
4 incidental expenses for such examination, treatment, rehabilitation, and care in an amount
5 according to proof.

6 130. By reason of the incident, Plaintiff has suffered a loss of income and/or a loss of
7 earning capacity, in an amount according to proof.

8 131. By further reason of the premises, Plaintiff suffered the loss of Plaintiff's personal
9 property, including but not limited to personal effects and items in checked in luggage and carry-
10 on items, in an amount according to proof at trial.

11 WHEREFORE, Plaintiff prays for relief as set forth below.

12 **FIFTH CAUSE OF ACTION**
13 **STRICT LIABILITY**
(Against Defendant The Boeing Company)

14 132. Plaintiff incorporates and re-alleges each of the allegations set forth above as
15 though fully set forth herein.

16 133. Defendant BOEING designed, manufactured, distributed and/or sold BOEING
17 777 and its subsequent variants, including the BOEING 777-200ER involved in the incident.
18 Defendant BOEING was in the business of designing, testing, manufacturing, selling,
19 assembling, building, distributing, marketing and/or inspecting aircraft as suitable for passenger
20 air transportation, including the subject BOEING 777-200ER that crashed at SFO on July 6,
21 2013.

22 134. At all times relevant hereinabove set forth, the subject BOEING 777-200ER
23 aircraft was being operated by ASIANA and used for the purposes of which it was manufactured,
24 designed, inspected, sold and intended to be used, in a manner reasonably foreseeable to
25 Defendant BOEING.

26 135. At all times relevant hereinabove set forth, the subject BOEING 777-200ER was
27 defective, dangerous, unsafe, and not airworthy by reason of Defendant BOEING's defective
28

1 manufacture, design, warning systems, inspections, testing, service, and/or maintenance of the
2 subject aircraft as set forth above.

3 136. As a direct and legal result of Defendant BOEING's negligence, carelessness,
4 gross negligence, recklessness and/or otherwise wrongful acts and/or omissions hereinabove set
5 forth, Plaintiff has suffered the injuries and damages hereafter set forth.

6 137. As a legal result of the wrongful conduct of BOEING set forth above, Plaintiff
7 was injured in Plaintiff's health, strength, and activity, and has sustained injuries to Plaintiff's
8 body and/or mind, all of which has caused Plaintiff great physical, mental, emotional, and
9 nervous pain and suffering.

10 138. By reason of the wrongful conduct of BOEING set forth above, Plaintiff was
11 required to and continues to employ physicians and other health care providers to examine, treat,
12 and care for Plaintiff's injuries, and has incurred, and will continue to incur, medical and
13 incidental expenses for such examination, treatment, rehabilitation, and care in an amount
14 according to proof.

15 139. By reason of the incident, Plaintiff has suffered a loss of income and/or a loss of
16 earning capacity, in an amount according to proof.

17 140. By further reason of the premises, Plaintiff suffered the loss of Plaintiff's personal
18 property, including but not limited to personal effects and items in checked in luggage and carry-
19 on items, in an amount according to proof at trial.

20 WHEREFORE, Plaintiff prays for relief as set forth below.

21 **SIXTH CAUSE OF ACTION**
22 **NEGLIGENCE**

23 **(Against Defendant Air Cruisers Company, LLC d/b/a Zodiac Aero**
24 **Evacuation Systems, a subsidiary of Defendant Zodiac Aerospace, S.A.)**

25 141. Plaintiff incorporates and re-alleges each of the allegations set forth above as
26 though fully set forth herein.

27 142. Defendant AIR CRUISERS COMPANY, LLC d/b/a ZODIAC AERO
28 EVACUATION SYSTEMS, a subsidiary of Defendant ZODIAC AEROSPACE, S.A., was the

1 designer, manufacturer, and/or seller of the evacuation slide/raft assemblies that were installed
2 on the Subject Aircraft.

3 143. Defendant AIR CRUISERS COMPANY, LLC d/b/a ZODIAC AERO
4 EVACUATION SYSTEMS, a subsidiary of Defendant ZODIAC AEROSPACE, S.A., knew or
5 should have known that the evacuation slide/raft assemblies would be susceptible to corrosion
6 and/or would not be able to withstand a crash such as the one that occurred on July 6, 2013
7 aboard the Subject Aircraft. Five of the eight evacuation slides/rafts that were available to be
8 used for disembarkation aboard the Subject Aircraft following the crash either failed to deploy at
9 all or deployed inside the cabin of the Subject Aircraft creating additional risks of delay and
10 injury in Plaintiff's disembarkation from the Subject Aircraft.

11 144. Defendant AIR CRUISERS COMPANY, LLC d/b/a ZODIAC AERO
12 EVACUATION SYSTEMS, a subsidiary of Defendant ZODIAC AEROSPACE, S.A., owed a
13 duty to the passengers of ASIANA Flight 214 to provide a safe means of disembarkation from
14 the Subject Aircraft in the event of a crash.

15 145. As a direct and legal result of Defendant AIR CRUISERS COMPANY, LLC's
16 d/b/a ZODIAC AERO EVACUATION SYSTEMS, a subsidiary of Defendant ZODIAC
17 AEROSPACE, S.A., negligence, carelessness, gross negligence, recklessness and/or otherwise
18 wrongful act and/or omissions, Plaintiff was forced to jump from the Subject Aircraft without the
19 benefit of an evacuating slide thus creating significantly dangerous situation and risking further
20 injury to Plaintiff.

21 WHEREFORE, Plaintiff prays for relief as set forth herein.

22 **SEVENTH CAUSE OF ACTION**
23 **BREACH OF WARRANTY**

24 **(Against Defendant Air Cruisers Company, LLC d/b/a Zodiac Aero
Evacuation Systems, a subsidiary of Defendant Zodiac Aerospace, S.A.)**

25 146. Plaintiff incorporates and re-alleges each of the allegations set forth above as
26 though fully set forth herein.

27 147. Defendant AIR CRUISERS/ZODIAC AEROSPACE was the designer,
28 manufacturer, supplier evacuation slides/raft assemblies that were installed on the subject aircraft

1 148. Prior to the crash of ASIANA Flight 214, Defendant AIR CRUISERS/ZODIAC
2 AEROSPACE expressly and/or impliedly warranted and represented that the evacuation
3 slides/raft assemblies, including their component parts and instruments, and in conjunction with
4 the instructions and warnings given by AIR CRUISERS/ZODIAC AEROSPACE, were
5 airworthy, of merchantable quality, both fit and safe for the purpose of commercial air travel for
6 which they were designed, intended and used. Additionally, Defendant AIR
7 CRUISERS/ZODIAC AEROSPACE further warranted that the evacuation slides/rafts
8 assemblies and/or their component parts were free from all defects.

9 149. Defendant AIR CRUISERS/ZODIAC AEROSPACE breached said warranties in
10 that the evacuation slides/rafts assemblies were not airworthy, of merchantable quality, or fit and
11 safe for the purposes for which they were designed, intended and used, and free from all defects
12 as set forth above.

13 150. Plaintiff, as passenger of ASIANA Flight 214, was an intended third-party
14 beneficiary of Defendant AIR CRUISERS/ZODIAC AEROSPACE 's warranties that the
15 evacuation slides/raft assemblies on ASIANA Flight 214 were airworthy, of merchantable
16 quality, both fit and safe for the purposes for which they were designed, intended and used, and
17 free from all defects.

18 151. As a direct and legal result of Defendant AIR CRUISERS/ZODIAC
19 AEROSPACE's negligence, carelessness, gross negligence, recklessness and/or otherwise
20 wrongful acts and/or omissions hereinabove set forth, Plaintiff has suffered the injuries and
21 damages hereafter set forth.

22 152. As a legal result of the wrongful conduct of AIR CRUISERS/ZODIAC
23 AEROSPACE set forth above, Plaintiff was injured in Plaintiff's health, strength, and activity,
24 and has sustained injuries to Plaintiff's body and/or mind, all of which has caused Plaintiff great
25 physical, mental, emotional, and nervous pain and suffering.

26 153. By reason of the wrongful conduct of AIR CRUISERS/ZODIAC AEROSPACE
27 set forth above, Plaintiff was required to and continues to employ physicians and other health
28 care providers to examine, treat, and care for Plaintiff's injuries, and has incurred, and will

1 continue to incur, medical and incidental expenses for such examination, treatment,
2 rehabilitation, and care in an amount according to proof.

3 154. By reason of the incident, Plaintiff has suffered a loss of income and/or a loss of
4 earning capacity, in an amount according to proof.

5 155. By further reason of the premises, Plaintiff suffered the loss of Plaintiff's personal
6 property, including but not limited to personal effects and items in checked in luggage and carry-
7 on items, in an amount according to proof at trial.

8 WHEREFORE, Plaintiff prays for relief as set forth below.

9 **EIGHTH CAUSE OF ACTION**
10 **STRICT LIABILITY**

11 **(Against Defendant Air Cruisers Company, LLC d/b/a Zodiac Aero
Evacuation Systems, a subsidiary of Defendant Zodiac Aerospace, S.A.)**

12 156. Plaintiff incorporates and re-alleges each of the allegations set forth above as
13 though fully set forth herein.

14 157. Defendant AIR CRUISERS COMPANY, LLC d/b/a ZODIAC AERO
15 EVACUATION SYSTEMS, a subsidiary of Defendant ZODIAC AEROSPACE, S.A., designed,
16 manufactured, inspected and/or sold the evacuation slide/raft assemblies that were installed on
17 the Subject Aircraft.

18 158. At all relevant times, ASIANA used the evacuation slide/raft assemblies for the
19 purposes for which they were manufactured, designed, inspected, sold, and intended to be used,
20 in a manner reasonably foreseeable to Defendant AIR CRUISERS COMPANY, LLC d/b/a
21 ZODIAC AERO EVACUATION SYSTEMS, a subsidiary of Defendant ZODIAC
22 AEROSPACE, S.A..

23 159. The evacuation slide/raft assemblies were defective, dangerous, unsafe and/or not
24 airworthy or crashworthy as a result of Defendant AIR CRUISERS COMPANY, LLC's d/b/a
25 ZODIAC AERO EVACUATION SYSTEMS, a subsidiary of Defendant ZODIAC
26 AEROSPACE, S.A., defective design, manufacture, testing, maintenance, service, warnings,
27 directives and/or inspection of evacuation slide/raft assemblies on the Subject Aircraft.

1 160. By manufacturing the evacuation slides/rafts in such a defective manner that the
2 majority of them either malfunctioned or did not deploy at all, AIR CRUISERS COMPANY,
3 LLC d/b/a ZODIAC AERO EVACUATION SYSTEMS, a subsidiary of ZODIAC
4 AEROSPACE, S.A., created an unnecessarily dangerous situation which imperiled the lives of
5 those passengers seeking to evacuate Flight 214 after its crash on July 6, 2013.

6 161. As a direct and legal result of Defendant AIR CRUISERS/ZODIAC
7 AEROSPACE negligence, carelessness, gross negligence, recklessness and/or otherwise
8 wrongful acts and/or omissions hereinabove set forth, Plaintiff has suffered the injuries and
9 damages hereafter set forth.

10 162. As a legal result of the wrongful conduct of AIR CRUISERS/ZODIAC
11 AEROSPACE set forth above, Plaintiff was injured in Plaintiff’s health, strength, and activity,
12 and has sustained injuries to Plaintiff’s body and/or mind, all of which has caused Plaintiff great
13 physical, mental, emotional, and nervous pain and suffering.

14 163. By reason of the wrongful conduct of AIR CRUISERS/ZODIAC AEROSPACE
15 set forth above, Plaintiff was required to and continues to employ physicians and other health
16 care providers to examine, treat, and care for Plaintiff’s injuries, and has incurred, and will
17 continue to incur, medical and incidental expenses for such examination, treatment,
18 rehabilitation, and care in an amount according to proof.

19 164. By reason of the air crash, Plaintiff has suffered a loss of income and/or a loss of
20 earning capacity, in an amount according to proof.

21 165. By further reason of the premises, Plaintiff suffered the loss of Plaintiff’s personal
22 property, including but not limited to personal effects and items in checked in luggage and carry-
23 on items, in an amount according to proof at trial.

24 WHEREFORE, Plaintiff prays for relief as set forth below.

25 ///
26 ///
27 ///
28 ///

NINTH CAUSE OF ACTION
LOSS OF CONSORTIUM
(Against All Defendants)

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

166. Plaintiff incorporates and re-alleges each of the allegations set forth above as though fully set forth herein.

167. Plaintiff is, and at all times herein mentioned was, spouse to a passenger on Flight 214 on July 6, 2013.

168. Plaintiff has been harmed by the acts and/or omissions of Defendants that have resulted in the injuries suffered by Plaintiff’s spouse, described herein above.

169. Prior to Defendants’ negligence, carelessness, gross negligence, recklessness and/or otherwise wrongful acts and/or omissions hereinabove set forth, Plaintiff’s spouse was able to and did perform all the duties of a spouse, including assisting in maintaining the home, caring for the child, working to help support the family, and providing the support and comfort to the spouse.

170. As a direct and legal result of the wrongful conduct of Defendants hereinabove set forth, Plaintiff has been deprived and will be deprived of the consortium of Plaintiff’s spouse, including the loss of the enjoyment of sexual relations and/or the loss of love, companionship, comfort, care, assistance, protection, affection, society, sexual relations, and/or moral support, all to the detriment of Plaintiff’s marriage.

WHEREFORE, Plaintiff prays for relief as set forth below.

VI. PRAYER FOR RELIEF

WHEREFORE, Plaintiff prays judgment against Defendants, and each of them, as hereinafter set forth below.

- 1. For compensatory and general damages according to proof;
- 2. For past and future medical expenses and incidental expenses according to proof;
- 3. For past and future loss of earnings and earning capacity according to proof;
- 4. For loss of personal property and personal effects according to proof;
- 5. For loss of consortium according to proof;
- 6. For pre- and post-judgment interest on all damages as allowed by the law;

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

- 7. For attorneys and expert/consultant fees under existing law;
- 8. For injunctive relief mandating that all Asiana pilots receive comprehensive training and demonstrate minimum proficiency in landing procedures and basic safety protocols.
- 9. For costs of suit incurred herein; and
- 10. For such other and further relief as the Court may deem just and proper.

Dated: May 12, 2014

COTCHETT PITRE & McCARTHY, LLP

By: /s/ Frank M. Pitre
FRANK M. PITRE
Liaison Counsel for Plaintiffs

VII. JURY DEMAND

Plaintiff demands trial by jury on all issues so triable.

Dated: May 12, 2014

COTCHETT PITRE & McCARTHY, LLP

By: /s/ Frank M. Pitre
FRANK M. PITRE
Liaison Counsel for Plaintiffs