

MCR10092

Fix test_cpu Test 51

Revision 1.1

Eric Swenson

July 22, 2021

1 Problem Description

When running `test_cpu` test 51 fails with a `fault_tag_1` exception. This occurs due to a bug in the test program, `sreg_no_write`, which attempts to load a pointer into a pointer register, but the data loaded is not guaranteed to contain a valid ITS pointer.

The messages emitted by `test_cpu` are:

```
Test 51 <sreg_no_write>
test_cpu: Test sreg_no_write encountered an unexpected fault_tag_1.
          *** HARDWARE FAILING ***
          The function under test does not normally exhibit this failure.
```

MACHINE CONDITIONS AT 234|6500:

```
fault_tag_1 by sreg_no_write$|1774
(>system_library_tools>bound_cpu_tests_|105004)
referencing stack_4|40040 (in process dir)
Ascii data where pointer expected.
  Cannot get line number in sreg_no_write
105004 600024351520  epp1  pr6|24,*
```

Machine registers at time of fault

pr0 (ap) 234 4376	stack_4 4376
pr1 (ab) 234 6620	stack_4 6620
pr2 (bp) 234 6300	stack_4 6300
pr3 (bb) 234 6340	stack_4 6340 (-> "tempseg_1")
pr4 (lp) 247 25050	!BBBKQGFJKbFLp.area.linker 25050 (internal static 0 for
ci_mod_case_2)	
pr5 (lb) 247 25050	!BBBKQGFJKbFLp.area.linker 25050 (internal static 0 for
ci_mod_case_2)	
pr6 (sp) 234 6220	stack_4 6220
pr7 (sb) 234 0	stack_4 0

x0 37324 x1 4376 x2 3320 x3 3164
 x4 0 x5 3357 x6 10 x7 1
 a 000376000004 q 107006000000 e 0
 Timer reg - 117701, Ring alarm reg - 0

SCU Data:

6530 400376250011 000000000007 400234000000 000000000000
 105004102200 040040000000 040040351440 200036251500

Fault Tag 1 Fault (7)

By: 376|105004 sreg_no_write|1774 (bound_cpu_tests_|105004)

Referencing: 234|40040 stack_4|40040

On: cpu a (#0)

Indicators: cary, tro, ^bar

APU Status: xsf, sd-on, pt-on, fabs

Instructions:

6536 040040 3514 40 epp1 40040,f
 6537 2 00036 2515 00 spr11 pr2|36

Time stored: 07/22/21 1451.8 pdt Thu (154101741012027323)

Ring: 4

EIS Pointers and Lengths:

6550 000400000101 000000000000 000000000000 000000000000
 000000000000 000000000000 000000000000 000000000000

CPU HISTORY REGISTERS AT TIME OF FAULT

DPS8 History Register Analysis

HR	IC or	c	Memory
id	Seg# [tpr.ca]	opcode tag y	Address mc flags
CU		scpr n* ?	242204 0 inh its
CU		n* ?	242204 0 inh its
CU		n* ?	242260 0 inh its
CU		cmpx3 du d	0 0 inh
CU		tze *	0 0 inh
CU		eax3 x3 ?	3 0 inh
CU		xec ?	127155 0 inh its
CU		scpr n* ?	242204 0 inh its
CU		n* ?	242204 0 inh its
CU		n* ?	242204 0 inh its
CU		n* ?	242260 0 inh its
CU		cmpx3 du d	0 0 inh
CU		tze *	0 0 inh
CU		eax3 x3 ?	3 0 inh
CU		xec ?	127155 0 inh its
CU		scpr n* ?	242204 0 inh its

Test 52 <tnz>
r 14:55 1.263 83

The following ticket describes this issue:

<https://multics-trac.swenson.org/ticket/229>

2 Analysis

The offending instructions in `sreg_no_write.alm` are:

epp1	pr6 20,*	return ptr
spri1	pr2 30	save return ptr in new frame

The first `epp1` instruction, which loads an ITS pointer into PR1, references an effective address of `pr6|20`. PR6 points to the current stack frame, and offset 20 refers to the `return_ptr` – the address to be returned to when the current call returns. In order to not get a fault during an `epp1` instruction, the 72-bit value referenced by the effective address must be a valid ITS pointer. If it isn't, a `fault_tag_1` fault will be raised by the hardware.

In a new stack frame, the `return_ptr` this pointer will be undefined. It will remain undefined until the procedure makes an external call. In the case of `sreg_no_write`, at this point in the instruction stream, no external call has been made, and therefore this value will be undefined. Since stack frames are allocated and deallocated based on the call history of the process, the values that exist in a new stack frame will be arbitrary, and quite likely not a valid ITS pointer.

The beginning of `sreg_no_write.alm` looks like this;

entry	sreg_no_write
name	sreg_no_write

sreg_no_write:

push	
tra	START
org	1014

START:

epp2	pr6 18,*	next frame ptr
epbp7	pr6 0	stack base
epp3	pr2 32	next frame area
nop	0,du	
inhibit	on	
spri3	pr6 18	NEW next frame ptr
spri3	pr7 20	NEW stack end ptr
inhibit	off	
epp1	pr6 20,*	return ptr
spri1	pr2 30	save return ptr in new frame

The `push` instruction directly after the entrypoint, pushes a new stack frame, and doesn't initialize the `return_ptr` field. As a result of the `push` instruction, PR6 is set to point to the new frame. Since there are no additional writes to `pr6|20`, the value there will be arbitrary.

None of the code that follows the above references `pr6|20`, and with the exception of the last instruction in the above code fragment, no code would use this value or the value stored by the `spri1` instruction. Consequently, the last two instructions in the above block are not actually needed. It seems that the code for `sreg_no_write` was created by disassembling other code which original exhibited the problem being tested by this test, and then extracting a fragment. Some of the lines of code have been commented out, suggesting that after the code was created, it was shortened. However, the two bad instructions were left in.

Simply removing these two instructions, while preventing the `fault_tag_1` fault, could well invalidate the test because the following comment appears in the code:

```
" The following instruction will fail with a access violation
" no_write_permission, because it asks for PR2's segment number
" and gets THIS segment number instead.
" The placement of this instruction is also very important. It must
" be two locations prior to the page boundary in the inst. segment.
    sreg    pr2|16    save regs in new frame
    sti     pr2|26    save indicators in new frame
    spri5   pr2|28    save pr5 in new frame
```

If the two instructions are removed, two new instructions must be inserted in order to ensure that the actual instruction that the test is attempting to validate remains at an offset 2 locations prior to the page boundary of the segment.

The instruction that is being tested is:

```
sreg    pr2|16    save regs in new frame
```

3 Proposed Changes

Although an alternative proposal was explored, it was rejected by the MCRB. See the section "Alternative Proposed Change" for details.

The proposed change is to simply comment out the invocation of the `cpu_tests.$sreg_no_write` call (and the loop that calls it) so that Test 51 appears to run and pass. The reason for choosing this alternative is that the test has several coding issues and it was felt that the simple fix proposed in "Alternative Proposed Change" would still leave bad code that doesn't follow Multics coding guidelines. Furthermore, it is very unlikely that this test would ever again be useful since no Multics hardware is likely to be found and placed in service, and in the unlikely event that hardware is resurrected, it is unlikely to not have had the FCO installed that corrected the issue with the `sreg` instruction.

The DPS8M simulator does not have the same issue, which only occurred when the `sreg` instruction was 2 locations from the end of a page boundary.

As the test is no longer useful and applicable, and fixing the bad code would perhaps render the test


```

Inserted in B:
B2142    */
Preceding:
A2117
A2118    exclude51:

```

Comparison finished: 3 differences, 26 lines.

4 Alternative Proposed Change

This proposed change was rejected by the MCRB. For documentation purposes, it is described below.

The fix involves commenting out these two instructions:

epp1	pr6 20,* return ptr
spri1	pr2 30 save return ptr in new frame

and two NOP instructions will be inserted, preserving the offset of the `sreg` instruction.

A comparison of the old and new versions, excluding history comments, follows:

```

mbuild: cmp

----- sreg_no_write.alm

compare_ascii >ldd>tools>source>bound_cpu_tests_.s.archive::sreg_no_write.alm ==

A24          epp1      pr6|20,* return ptr
A25          spri1     pr2|30  save return ptr in new frame
Changed by B to:
B24          "         epp1      pr6|20,* return ptr
B25          "         spri1     pr2|30  save return ptr in new frame
B26          nop
B27          nop

```

Comparison finished: 1 difference, 6 lines.

The `mbuild` description of the change looks like this:

Segments found by read request:

```

Build_script:      cpu_tests.mb;

bound_cpu_tests_.s.archive:

```

```
source:          sreg_no_write.alm          IN: tools.source REPLACE compiler:
    alm;

mbuild:
```

5 Documentation

There are no documentation changes for this change.

6 Testing

Testing involves running the `test_cpu` program repeatedly, with different `-fm` values that ensure that test 51 is executed, but with different prior tests (to generate different stack garbage).

7 Version History

2021-07-22	1.0	Initial version of the MCR.
2021-07-22	1.1	Update to change proposed fix.