



This document is scheduled to be published in the Federal Register on 03/20/2019 and available online at <https://federalregister.gov/d/2019-05199>, and on [govinfo.gov](http://govinfo.gov)

[4910-13-P]

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2019-0121; Product Identifier 2019-NM-025-AD;

Amendment 39-19591; AD 2019-05-09]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Airbus SAS Model A320-251N and -271N airplanes, and Model A321-253N airplanes. This AD was prompted by reports of low clearance between the electrical harness and nearby hydraulic pipes in the inboard trailing edge of the wing. This AD requires repetitive detailed inspections of certain electrical harnesses for discrepancies and corrective actions, if necessary, as specified in an European Aviation Safety Agency (EASA) AD, which is incorporated by reference. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD becomes effective [INSERT DATE 15 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of [INSERT DATE 15 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

We must receive comments on this AD by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: 202-493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
  - Hand Delivery: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For the incorporation by reference (IBR) material described in the “Related IBR Material Under 1 CFR part 51” section in SUPPLEMENTARY INFORMATION, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 1000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); Internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this

IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the Internet at <http://www.regulations.gov>.

### **Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0121; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (telephone 800-647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223.

### **SUPPLEMENTARY INFORMATION:**

#### **Discussion**

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019-0035, dated February 15, 2019 (“EASA AD 2019-0035”) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Airbus SAS Model A320-251N and -271N airplanes, and Model A321-253N airplanes. The MCAI states:

Low clearance between electrical harness and nearby hydraulic pipes has been detected in the inboard trailing edge of some aeroplanes.

This condition, if not detected and corrected, could lead to chafing of electrical harnesses on hydraulic pipes, eventually creating an ignition source in the flammable fluid leakage zone area, possibly resulting in fire or an explosion and loss of the aeroplane.

To address this potential unsafe condition, Airbus issued the AOT [alert operators transmission], providing instructions to accomplish a detailed inspection (DET) for clearance and damage, and published the modification SB [Service Bulletin A320-29-1176], providing instructions to modify the electrical harness routing, increasing the clearance between electrical harness and hydraulic pipes.

For the reasons described above, this [EASA] AD requires repetitive DET of the electrical harness and modification of the aeroplane.

### **Related IBR Material under 1 CFR part 51**

EASA AD 2019-0035 describes procedures for repetitive detailed inspections of certain electrical harnesses for discrepancies (clearance and damage) and corrective actions, if necessary. Corrective actions include repairing the electrical harness or replacing the electrical harness sleeve, and increasing the clearance between the affected electrical harness and hydraulic pipe. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section, and it is publicly available through the EASA website.

## **FAA's Determination**

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI referenced above. We are issuing this AD because we evaluated all pertinent information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

## **Requirements of this AD**

This AD requires accomplishing the actions specified in EASA AD 2019-0035 described previously through the incorporated by reference of EASA AD 2019-0035, except for any differences identified as exceptions in the regulatory text of this AD and except as discussed under "Differences Between this AD and the MCAI."

## **Explanation of Required Compliance Information**

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. As a result, EASA AD 2019-0035 is incorporated by reference in the FAA final rule. This AD, therefore, requires compliance with the provisions specified in EASA AD 2019-0035, except for any differences identified as exceptions in the regulatory text of this AD. Service information specified in EASA AD 2019-0035 that is required for compliance with EASA AD 2019-0035 is available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0121.

## **Differences Between this AD and the MCAI**

EASA AD 2019-0035 specifies to modify the airplane (modification of the adaptation damper bulkhead fitting for left hand and right hand wings). For this AD, the modification, which would terminate the repetitive inspections required by this AD, is optional. However, we are considering further rulemaking to require this modification. The planned compliance time for the modification would allow enough time to provide notice and opportunity for prior public comment on the merits of the modification. This difference has been coordinated with EASA.

## **FAA's Justification and Determination of the Effective Date**

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because failure to detect and correct chafing of electrical harnesses in the vicinity of hydraulic pipes could result in a potential source of ignition in the flammable fluid leakage zone, and possibly result in a fire or explosion and loss of the airplane. Therefore, we find good cause that notice and opportunity for prior public comment are impracticable. In addition, for the reasons stated above, we find that good cause exists for making this amendment effective in less than 30 days.

## **Comments Invited**

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an

address listed under the ADDRESSES section. Include “Docket No. FAA-2019-0121; Product Identifier 2019-NM-025-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

### **Costs of Compliance**

We estimate that this AD affects 14 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

#### **Estimated costs for required actions**

<b>Labor cost</b>	<b>Parts cost</b>	<b>Cost per product</b>	<b>Cost on U.S. operators</b>
6 work-hours X \$85 per hour = \$510	\$0	\$510	\$7,140

#### **Estimated costs for optional actions**

<b>Labor cost</b>	<b>Parts cost</b>	<b>Cost per product</b>
16 work-hours X \$85 per hour = \$1,360	\$8,900	\$10,260

We estimate the following costs for the necessary on-condition action that would be required based on the results of any required actions. We have no way of determining the number of aircraft that might need this on-condition action:

### **Estimated costs of on-condition actions**

<b>Labor cost</b>	<b>Parts cost</b>	<b>Cost per product</b>
Up to 8 work-hours X \$85 per hour = \$680	\$0*	Up to \$680

\*We have received no definitive data that would enable us to provide parts cost estimates.

According to the manufacturer, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all known costs in our cost estimate.

#### **Authority for this Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In

accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

### **Regulatory Findings**

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### **List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### **Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

## **PART 39 - AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

### **§ 39.13 [Amended]**

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2019-05-09 Airbus SAS:** Amendment 39-19591; Docket No. FAA-2019-0121; Product Identifier 2019-NM-025-AD.

#### **(a) Effective Date**

This AD becomes effective [INSERT DATE 15 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

#### **(b) Affected ADs**

None.

#### **(c) Applicability**

This AD applies to Airbus SAS Model A320-251N and -271N airplanes, and Model A321-253N airplanes, certificated in any category, as identified in European Aviation Safety Agency (EASA) AD 2019-0035, dated February 15, 2019 (“EASA AD 2019-0035”).

#### **(d) Subject**

Air Transport Association (ATA) of America Code 92, Electric and electronic common installation.

**(e) Reason**

This AD was prompted by reports of low clearance between the electrical harness and nearby hydraulic pipes in the inboard trailing edge of the wing. We are issuing this AD to address this condition, which, if not detected and corrected, could lead to chafing of electrical harnesses in the vicinity of hydraulic pipes and could result in a potential source of ignition in the flammable fluid leakage zone, and possibly result in a fire or explosion and loss of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2019-0035.

**(h) Exceptions to EASA AD 2019-0035**

- (1) For purposes of determining compliance with the requirements of this AD: Where EASA AD 2019-0035 refers to its effective date, this AD requires using the effective date of this AD.
- (2) The “Remarks” section of EASA AD 2019-0035 does not apply to this AD.
- (3) Where paragraph (4) of EASA AD 2019-0035 specifies to modify the airplane in accordance with Airbus Service Bulletin A320-29-1176, this AD does not require modification of the airplane, but this AD allows that modification as an optional terminating action for the required repetitive inspections.

(4) The provisions of paragraph (6) of EASA AD 2019-0035 are allowed in the optional modification specified in paragraph (h)(3) of this AD.

**(i) No Reporting Requirement**

Although certain service information referenced in EASA AD 2019-0035 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

**(j) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or

EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: For any service information referenced in EASA AD 2019-0035 that contains RC procedures and tests: Except as required by paragraph (j)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

**(k) Related Information**

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223.

**(l) Material Incorporated by Reference**

- (1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) AD 2019-0035, dated February 15, 2019.

(ii) [Reserved]

(3) For EASA AD 2019-0035, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); Internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this EASA AD at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. EASA AD 2019-0035 may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0121.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on March 11, 2019.

Dionne Palermo,  
Acting Director,  
System Oversight Division,  
Aircraft Certification Service.

[FR Doc. 2019-05199 Filed: 3/19/2019 8:45 am; Publication Date: 3/20/2019]