



Chimney Clean Co, Inc.

State License #678096

1538 San Joaquin Ave. San Jose, CA 95118

(650) 941-1412

(408) 265-1010

(510) 324-2020

Name:

Date:

9/8/2005

Address: 1704 HILLSDALE AVE.

Serviced By: JC

SAN JOSE, CA 95124

Prefabricated: Yes [ ] No [X]

The following hazards were noted while servicing this system:

1.) Follow-up: Repaired flashing, misc cracks in outside brick wall, and crown.

\* Mail payment to above address \*

CUSTOMER VERIFICATION: I have received a copy of this notification.

Signed: Shirley Torridge

Bill

Note: This notification is intended to alert to the presence of hazards that were noted while servicing this system, and is not intended as a certification of fire worthiness or safety. There are areas in every system which cannot be accessed. We make no warranty of the safety or function of any appliance, and none is to be implied or inferred. In any event, the liability of Chimney Clean Co, Inc. is limited to the amount paid for the service rendered.

Repair	160
Repair	100
Repair	290
Total:	\$450

All PSC



Chimney Clean Co, Inc.  
1538 San Joaquin Ave, San Jose, CA 95118  
voice (408)265-1010 voice (650)941-1412  
voice (510)324-2020 fax (408)265-3252  
state contractor's license number 678096

Page 1 of 2

Date: 20 Aug 2005

Address: 1704 HILLSDALE AVE.  
SAN JOSE, CA 95124

Serviced by: JC

Fireplaces are composed of the following areas (if applicable):

- 1 - Chimney Cap / Spark Arrestor
- 2 - Crown / Exterior of chimney above roof line
- 3 - Flashing and Counterflashing
- 4 - Exterior of chimney above ground
- 5 - Flue lining / Flue tiles
- 6 - Bottom flue tile joint
- 7 - Inside chimney above damper
- 8 - Damper / Damper frame
- 9 - Firebox rear wall
- 10 - Firebox side walls
- 11 - Firebox floor
- 12 - Ash dump door (interior and exterior)

The following hazards were noted while servicing this system:

1. Cement crown and top area of chimney have many cracks and missing mortar between bricks. This will allow water to enter the structure of the chimney. These should be repaired by replacing the crown and remortaring the spaces between the bricks.

Cost \$290

2. Counterflashing area at the roof line has missing mortar and is not fully sealed. This will allow water to enter the space between the chimney and the house. This should be resealed with silicone.

Cost \$60

*Handwritten signature/initials*

Page 2 of 2

No other hazards were noted.

Note: Chimney has some movement when pushed above the roof line, but does not appear to have a structural break.

Note: Near the base area there is a brick wall against the house that has some cracking between the bricks. This is not associated with the chimney per se, and is only cosmetic. However, this could be repaired if desired.

Cost \$100

Note: This notification is intended to alert to the presence of hazards that were noted while servicing this system, and is not intended as a certification of fire worthiness or safety. There are areas in every system which cannot be accessed. We make no warranty of the safety or function of any appliance, and none is to be implied or inferred. In any event, the liability of Chimney Clean Co, Inc. is limited to the amount paid for the service rendered.



Chimney Clean Co, Inc.  
 1538 San Joaquin Ave, San Jose, CA 95118  
 voice (408)265-1010 voice (650)941-1412  
 voice (510)324-2020 fax (408)265-3252  
 state contractor's license number 678096

**RECEIPT AND COMPLETION NOTICE**

**Date: 20 Aug 2005**

**Address: 1704 HILLSDALE AVE.  
SAN JOSE, CA 95124**

Description -----	Amount -----
Service chimney	\$119.00
<b>TOTAL</b>	<b>\$119.00</b>

**PAID IN FULL CHECK #2405 - THANK YOU!**