


Makita DXT 12" Miter Saw Parts Manual LS1219L 01-18

When the saw was dissassembled, it was found that the guide bushing assembly was missing parts and also included an additional washer that is not on the parts diagram. It is suspected the e-clip was lost some time ago and the incorrect parts were used to make the guide functional.



Missing Parts:

- 048 – PN 961018-5 Stop Ring E-5, looks like a common e-clip
- 053 – PN 257163-5 Ring 6, looks like a bushing, might be able to match it from existing item 041 as it has the same PM and description.

Flat washer (part 54) was installed on the wrong side link plate (part 52)

043	687042-7	STRAIN RELIEF	1 PC.
044	266034-5	TAPPING SCREW CT 4X16	1 PC.
045	251554-2	THUMB SCREW M6X40	1
046	922332-4	HEX. SOCKET HEAD BOLT M6X20	1 PC.
047	458146-0	LOGO PLATE	1
<u>048</u>	<u>961018-5</u>	<u>STOP RING E-5</u>	1 PC.
049	251547-9	HEX.SOCKET HEAD BOLT M8X25	1
050	922251-4	HEX. SOCKET HEAD BOLT M5X30	1 PC.
051	266034-5	TAPPING SCREW CT 4X16	3 PC.
052	144929-1	LINK PLATE COMPLETE	1
<u>053</u>	<u>257163-5</u>	<u>RING 6</u>	1 PC.
054	253804-1	FLAT WASHER 6	1 PC.
055	262001-8	URETHANE RING 5	1 PC.
056	942151-2	SPRING WASHER 6	1 PC.
057	257449-7	SLEEVE 6	1
058	266321-2	H.S.SET SCREW(FLAT POINT)M6X16	1 PC.