



# FIRMWARE RELEASE NOTES

Version 7.1.81

BrightSign XTx44, XDx34, XTx43, XDx33, HDx23, HO523, LS423, 4Kx42, XDx32, HDx22

## Changes Since 7.1.72

### End User

#### Improvements

- BP200/BP900 button panels no longer drop button-press events.

#### Bug Fixes

- 30732: Mosaic mode video windows can now be placed in front of a standard video window.
- 20545: Scrolling tickers now respect the Safe text region in Ticker zones.
- 29476: The Background bitmap for Ticker zones now works with scrolling tickers.
- 31491: Players now correctly display upscaled 4K video input.
- 31138: (XTx44, XTx43, XDx34, XDx33) HDCP 1.4 input once again works when the HDMI input cable is hotplugged.
- 31280: (XDx32, HDx22) The BrightSign splash screen no longer appears in the upper-left quadrant of 4K displays.

### Developer

#### Improvements

- The `SetViewMode()` and `SetLoopMode()` methods on the *roVideoPlayer* object now accept string arguments.

## Bug Fixes

- 31222: (XTx44, XDx34) Performance issues with the slick.js animation library have been fixed.
- 31542: The *roNetworkConfiguration.GetCurrentConfig()* method now returns the correct information for USB modems.