

BrightSign®

OS8 RELEASE NOTES

Version 8.0.11

HDx24, LS424

Changes Since 8.0.6.6

End User

Improvements

- BP200/BP900 configurations now persist after transient disconnects (less than 10 seconds). Longer disconnects will still cause reinitialization.

Bug Fixes

- 32167: USB audio from video files is no longer distorted.
- 31966: YouTube playlists have been fixed.

Developer

New Features

- (LS423) Support for IR input via USB Type-C connector

Improvements

- The *roSyncManager*/*BSSyncManager* objects now support packet encryption using the `SetEncryptionEnable()` method.
- HTML graphics rendering speeds have been improved.

Bug Fixes

- 32202: Modifying the HTML `volume` property works again.
- 32134: The *roHtmlWidget* object once again claims the input focus when initialized.