

January 30, 1979

ENGINEERING MEMO #399

TO: MEMO DISTRIBUTION

FROM: R. E. Orwig & C. Bland

SUBJECT: RELOCATION OF HORN RELAY TO INTERIOR OF THE VEHICLE.

At the request of management and New York Cab operators, the Horn Relay will be installed inside the vehicle directly below the fuse block, instead of the present location in the engine compartment on the inner fender.

This change will be made with a minimum of obsolescence, but must be incorporated in the next release of New York City Taxis, (Approximately March 1, 1979.) Rework of the present wiring will be required if vendors are unable to make the necessary changes in time to meet our schedule.

This revision will effect service in that the component parts (except #705732 Forward Lamp Harness) are not interchangeable.

The following is a list of parts affected.

REVISIONS			
DATE	ITEM REV & PAGE NO.	DATE	ITEM REV & PAGE NO.
2-8-79	(4,5) Added P.2		
3-26-79	(6) Added P.2		

