

**AEROSTAR INTERNATIONAL, INC.**  
**SERVICE LETTER 109**

November 9, 1994

**SUBJECT:** CLARIFICATION OF SERVICE BULLETIN 122 ISSUED  
JANUARY 15, 1987

**PROBLEM:** There have been reports that the cable backup system  
utilized on this service bulletin are not being installed on TW  
baskets that have stainless steel superstructures and lower  
frames.

**DISCUSSION:** It has been determined that the aluminum interface pins on  
these baskets will bend or break when flown at gross lift  
conditions in wind or restraint circumstances creating  
abnormal stresses or torquing of the superstructures.

**APPLICABILITY:** All Classic IX and X baskets with serial number prefixes  
starting with TW.

**CORRECTIVE  
ACTION:** Compliance with Service Bulletin 122, the installation of a  
cable back-up system.

**PROCEDURE:** Follow procedures on Service Bulletin 122. Cable back-up  
system furnished by Aerostar International, Inc.

If you have any questions contact:

Dee M. Rose  
Customer Service Manager  
AEROSTAR INTERNATIONAL, INC.  
P.O. BOX 5057  
SIOUX FALLS, SOUTH DAKOTA 57117  
PHONE: 605-331-3500  
FAX: 605-331-3500