

Globe Oct 2, 1908 Mimico

One man killed, two are injured. Mimico.

Fast passenger engine of the CPR crashes into a doubleheader yard engine.

The alleged carelessness of an operator in leaving open a switch that it was his duty to see was closed caused the death of one man and serious injury to two others.

While running at a speed of between forty and fifty miles an hour CPR passenger train No 811 westbound ran into an open switch about 75 yards west of Mimico crossing and smashed into a heavy doubleheader yard engine that was standing on a siding. William Quinn, engineer of the passenger [train] was killed.