

TABLE OF CONTENTS

	<u>PAGE</u>
SECTION 1 SPECIAL FEATURES OF OSP5000/500 SERIES	1
SECTION 2 SUMMARY OF OPERATION	2
SECTION 3 STRUCTURE OF OSP5020L/OSP5000L-G/OSP500L-G	3
1. CPU and Power Supply Unit	3
2. Servo Drive Unit	3
3. Relay and Magnet Switch Circuits	3
4. Spindle Drive Motor Control	4
5. Control Enclosure	4
6. Operation Panel	4
7. Absolute Position Feedback Encoders	4
8. Cooling Unit	4
SECTION 4 MAINTENANCE AND INSPECTION	5
1. Inspection during Installation	5
1-1. Installation Site	5
1-2. Environmental Requirements	5
1-3. Power Supply Voltage Inspection	6
2. Periodical Inspection	6
3. Operation and Structure of the NC	7
3-1. Example of Operation	7
3-2. Description on Each Major NC Unit	8
4. Self-Diagnostics	10
4-1. Alarm Display and Error Display	10
4-2. Check Data Display	10
SECTION 5 TROUBLE AND TROUBLESHOOTING	29
1. Analysis of Trouble	30
2. Machine-Mounted Electricals	31
2-1. Inspection of Limit Switches (Check Method by Multi-Meter)	31
2-2. Inspection of Limit Switches or Rotary Switches for Turret Indexing (Testing by Self-Diagnostic Function)	33
3. Inspection of Position Encoder	36

	<u>PAGE</u>
4. Check Panel (For LB15)	37
5. CPU	37
5-1. Operation and Structure of the CPU	37
5-2. Checking CPU Operations	39
5-3. Loading Control Software through Floppy Disk	40
5-4. CPU Power Supply	43
6. Relay and Magnet Switch Circuits	45
6-1. Operation and Structure of a Relay and Magnet Switch Circuit	45
6-2. Inspection of Relays and Magnet Contactors	46
SECTION 6 COOLING UNIT	49
1. Maintenance and Inspection	49
SECTION 7 C-AXIS OF MULTIPLE-MACHINING MODEL	50
1. C-Axis Joint Mechanism	50
2. C-Axis Joint Methods	51
2-1. Checking C-axis Joint Method	51
2-2. Spindle Driven by C-axis During C-axis Joint	52
2-3. High Speed C-axis Joint A	54
2-4. High Speed C-axis Joint B	55
2-5. Supplements to Joint Method Explanations	57
3. C-Axis Joint Parameters	58
3-1. Spindle Orientation Position Parameter	58
3-2. Zero Position in Spindle Orientation for C-axis Joint	59
3-3. How to Set Zero Position of Spindle Orientation for C-axis Joint	60
4. Trouble and Troubleshooting for C-Axis Joint Operation	61
4-1. Machine Condition Checking Procedure	61
4-2. Troubles and Troubleshooting	64
SECTION 8 ELECTRICAL SPARE PARTS LIST	66
SECTION 9 POWER REQUIREMENTS	76

	<u>PAGE</u>
APPENDED FIGURES	
Layout Diagrams of Machine-mounted Electricals	82
Operation Panel	82
Internal Layouts of CNC Unit	82
SUPPLEMENT 1 BRUSHLESS SERVOMOTOR DRIVE UNIT (BL-D**A Series)	98
1. Configuration of BL-D**A	98
2. Construction	99
3. Protection and Alarm Monitoring Function	101
4. Trouble and Troubleshooting	103
5. Checking Power Transistor	108
SUPPLEMENT 2 AC SPINDLE SERVO UNIT - MODEL 3 - 8 (FANUC MAKE)	109
1. Construction	109
2. Daily Maintenance and Maintenance Tools	110
2-1. AC Spindle Motor	110
2-2. AC Spindle Servo Unit	110
2-3. Maintenance Tools	110
3. Troubleshooting	111
3-1. Power Voltage Check	112
3-2. Power ON Indicator Lamp LED1 does not Light	113
3-3. Alarm Lamp Lights on PCB	114
3-4. Motor Does Not Rotate, Motor Does Not Rotate at the Specified Revolutions	129
3-5. Vibrations or Noises Are Noticeable During Rotation	130
3-6. Abnormal Noise Is Produced from Motor During Deceleration	130
3-7. Speed Overshooting or Hunting Occurs	130
3-8. Cutting Power Is Low	131
3-9. Orientation Is Not Correct	131
3-10. Acceleration/Deceleration Time Is Long	132
5. Component Layout on Servo Unit	134
6. Component Layout on Printed Circuit Board	138

	<u>PAGE</u>
SUPPLEMENT 3 SPINDLE DRIVE UNIT FOR VAC MOTOR (OKUMA MAKE)	139
1. Outline	139
2. VAC Drive Unit Construction	139
3. Operation Status Indication	144
3-1. Control PCB Operation Status Indicating Lamps	144
3-2. Operation Status Indicating Lamps	145
4. Troubleshooting	156
4-1. Confirmation of Power Supply, Connectors and Signals	156
4-2. Trouble and Troubleshooting	157
4-3. Recovery from Failure Status	165
5. Fuse Replacement	166
6. Inspection and Maintenance	170
7. Input/Output Signal Table	172
SUPPLEMENT 4 PCB TYPE RELAY BOARD PARTS ARRANGEMENT DIAGRAMS	174