

Gauge all individual adjusters for better control and settings

Flat and side pressures

Chain all bottom rollers to the motor

Add one or two more rollers accordingly.

Note: because of the nature of the shape (hexagonal) you may need to run all three flat sides to accomplish your bar flatness.

