





The main level of Madrasa is formed by a courtyard enclosed by four iwans




Entry facade of Madrasa. Access to apartments behind monument is through a vaulted passage (lower right)



South wing of Madrasa before restoration




South wing during restoration




The main "iwan" and paryer niche before restoration



The main "iwan" after restoration.
Note the reintroduction of parapets.



Detail of prayer niche's decoration



Courtyard paving and main "iwan" after restoration




The north “iwan” with the old Mahrabiya
before restoration



Detail of restored mahrabiya




Darb Qirmiz Quarter, Cairo, Egypt



Entrance on north "iwān" with
suspended lighting system

Restoration work
ot the fine
chiselled ceilings



Darb Qirmiz Quarter, Cairo, Egypt Egypt Saudi Arabia



Darb Qirmiz Quarter, Cairo, Egypt Egypt Saudi Arabia



Darb Qirmiz Quarter, Cairo, Egypt Egypt Saudi Arabia



Darb Qirmiz Quarter, Cairo, Egypt Egypt Saudi Arabia



Darb Qirmiz Quarter, Cairo, Egypt Egypt Saudi Arabia




Madrasa Tatr al-Higaziya: rebuilding of Mirhab




Madrasa Tatar al-Higaziya:
prayer niche frieze before restoration



Madrasa Tatar al-Higaziya: repair and stucco




Courtyard and southeast "iwan" during restoration



Stucco decoration before restoration




Stucco decoration after restoration



Wooden ceiling after restoration



Exterior of Fountainhouse





Sabil Kuttab: first floor before restoration



View from Teahouse gallery on surroundings



View on Fountainhouse during restoration of the roof



The first floor of Fountainhouse after rebuilding and consolidation



Fountainhouse construction details: super imposed roofs



Sabil Kuttab: entrance ceiling



Sabil Kuttab: decorated lower ceiling before cleaning



Sabil Kuttab: repair of roofing