


Above: View from the balcony of a guest room wing past lush tropical rainforest.


Right: The integration of the buildings into the natural landscape and the choice of materials which will weather and encourage the regrowth of disturbed vegetation were carefully considered.






Above: View of the pool deck (left) and pavilion restaurant (right); the grand stair in the centre leads to down the terraced site.


Below: The palm-roof beach club as seen from the pool terrace.






Above: Two-storey, stone and timber lounge and restaurant.

Below: Tree trunk columns, felled during the construction of the resort, support the restaurant in the beach club.






Above: View from the forecourt to the entrance lobby past the water garden .

Below: View from the entrance lobby; the lack of surrounding walls allows for natural ventilation and unobstructed views of the site.





Above: View from the timber verandah of the guest wing toward the presidential suite.



Right: Guest rooms are accessed through a series of detached, open-sided, covered walkways which permit cooling breezes.



Above: Interior view of a typical villa bedroom open to a private verandah.

Below: Interior view of a typical freestanding villa.

