

SCHOOL INSPECTION PROGRESS REPORT

School: Donagh Regional School, Eastern School District

Date: August 25, 2011

Room # / Description	Observations	Level of Remediation	Status
Custodian Room 150	Visual water damage to drywall ceiling.	Have area repaired. Further investigation required.	Area scraped and repainted. Area being monitored.
Fan Room	Visible mould on duct insulation.	Have area cleaned and decontaminated using Level 1 precautions by custodial staff.	Mould remediation complete.

Conclusion and Recommendations:

New school within last ten years, school in very good shape.

Faculty and staff are asked to report any signs of water infiltration and/or mould to their Property Services Manager so that water infiltration is repaired and any mould which may have developed is remediated right away.

For more information on the School Inspection program, please visit:

www.gov.pe.ca/eed/schoolinspections