

# SCHOOL INSPECTION PROGRESS REPORT

**School:** Montague Regional High School, Eastern School District

**Date:** August 25, 2011

Room # / Description	Observations	Level of Remediation	Status
Room 143, 01 Lobby, 19, 31, 42, 49, 102, 104, 113, 121, 136, 140A, Room 21 Music Room Washroom	Stained ceiling tiles.	Removal of stained ceiling tiles to further investigate for potential hidden mould above ceiling. Replace with new tiles to detect new water leaks.	Tiles replaced by contractor, water infiltration issues are currently being addressed.
Room 111, 10, 65, 87, 104, 113, 114, 119, 210, 211, 213, 221, 223, 226, 229, 249	Elevated moisture detected and visible water staining.	Further investigation required.	Water infiltration issues are currently being addressed.

## Conclusion and Recommendations:

School under construction warranty. Contractor looking into all water infiltration issues.

Faculty and staff are asked to report any signs of water infiltration and/or mould to their Property Services Manager so that water infiltration is repaired and any mould which may have developed is remediated right away.

**For more information on the School Inspection program, please visit:**

[www.gov.pe.ca/eecd/schoolinspections](http://www.gov.pe.ca/eecd/schoolinspections)