

# SCHOOL INSPECTION PROGRESS REPORT

**School:** Parkdale Elementary, Eastern School District  
**Date:** August 25, 2011

Room # / Description	Observations	Level of Remediation	Status
Room 010 Basement Level	Deteriorated concrete dust from perimeter wall from moisture/water.	Further investigation required.	Area scraped and repainted. Further monitoring required.
Room 004 Basement	Water stained ceiling tile. Visible mould identified on perimeter concrete wall.	Removal of stained ceiling tiles to further investigate for potential hidden mould above ceiling. Replace with new tiles to detect new water leaks.	Tiles replaced March/'11, monitoring for any signs of water infiltration. Mould remediated.

## Conclusion and Recommendations:

Faculty and staff are asked to report any signs of water infiltration and/or mould to their Property Services Manager so that water infiltration is repaired and any mould which may have developed is remediated right away.

**For more information on the School Inspection program, please visit:**

[www.gov.pe.ca/eed/schoolinspections](http://www.gov.pe.ca/eed/schoolinspections)