

SCHOOL INSPECTION PROGRESS REPORT

School: Amherst Cove Consolidated School, Western School Board

Date: August 23, 2011

Room # / Description	Observations	Level of Remediation	Status
Room 170, 137, 140, 162, 180, 196	Stained ceiling tiles observed and reported in notes areas. See Appendix 1 for location markings.	Removal of stained ceiling tiles to further investigate for potential hidden mould above ceiling. Replace with new to detect new water leaks.	Tiles replaced, currently monitoring for any signs of water infiltration.
Room 189 & 134	Visible moisture damage to drywall ceiling. No elevated moisture detected at time of inspection. No visible mould observed.	Have area repaired and monitor for potential water infiltration.	Area has been repaired and currently monitoring for any signs of water infiltration.
Corridor 113	Visible mould (minor) on ceiling tile. Leak from roof drain directly above stain as contributor.	Removal of stained ceiling tiles to further investigate for potential hidden mould above ceiling. Replace with new to detect new water leaks.	Tile replaced, currently monitoring for any signs of water infiltration.

Conclusion and Recommendations:

Faculty and staff are asked to report any signs of water infiltration and/or mould to their Property Services Manager so that water infiltration is repaired and any mould which may have developed is remediated right away.

For more information on the School Inspection program, please visit:

www.gov.pe.ca/eed/schoolinspections