

## SCHOOL INSPECTION PROGRESS REPORT

**School:** Elm Street Elementary School, Western School Board

**Date:** August 24, 2011

Room # / Description	Observations	Level of Remediation	Status
Room 306	Visible surface damage to plaster wall. No elevated moisture detected at the time of assessment.	Further investigation required.	Moisture damage was prior to window repair. Monitoring area for any potential moisture issues.

### Conclusion and Recommendations:

Faculty and staff are asked to report any signs of water infiltration and/or mould to their Property Services Manager so that water infiltration is repaired and any mould which may have developed is remediated right away.

For more information on the School Inspection program, please visit:

[www.gov.pe.ca/eed/schoolinspections](http://www.gov.pe.ca/eed/schoolinspections)