

# SCHOOL INSPECTION PROGRESS REPORT

**School:** Greenfield Elementary School, Western School Board

**Date:** August 24, 2011

Room # / Description	Observations	Level of Remediation	Status
Corridor 100, also noted in rooms 137, 145, Corridor 200A, 203, 209, 215, 216	Stained ceiling tiles observed and reported.	Removal of stained ceiling tiles to further investigate for potential hidden mould above ceiling. Replace with new to detect new water leaks.	Tiles replaced, currently monitoring for any signs of water infiltration.
Room 215	Minor amount of visible mold on top of ceiling tile.	Removal of stained ceiling tile to further investigate for potential hidden mould above ceiling. Replace with new to detect new water leaks.	Tiles replaced, currently monitoring for any signs of water infiltration.
Room 213, 105, 113, 141, 201, 203,	Visible water damage to window frame. Elevated moisture detected.	Have area repaired. Further investigation required.	Monitoring for any signs of water infiltration.

## Conclusion and Recommendations:

Faculty and staff are asked to report any signs of water infiltration and/or mould to their Property Services Manager so that water infiltration is repaired and any mould which may have developed is remediated right away.

**For more information on the School Inspection program, please visit:**

[www.gov.pe.ca/eecd/schoolinspections](http://www.gov.pe.ca/eecd/schoolinspections)