

# SCHOOL INSPECTION PROGRESS REPORT

**School:** Kinkora Regional High School, Western School Board  
**Date:** August 24, 2011

Room # / Description	Observations	Level of Remediation	Status
Room 128, 107 Corridor, 125 Entry, 206B, 218	Stained ceiling tiles observed and reported throughout in noted locations.	Removal of stained ceiling tiles to further investigate for potential hidden mould above ceiling. Replace with new to detect new water leaks.	Tiles replaced, currently monitoring for any signs of water infiltration.
Room 130, 132	Visible moisture damage to drywall/plaster wall surfaces. No leaks or moisture detected at time of inspection.	Have area repaired and further investigation required.	Cracks in plaster from equipment stored in rooms, no moisture detected at time of inspection.
Room 129	Visible moisture damage to drywall ceiling surfaces. No leaks or moisture detected at time of inspection.	Have area repaired and further investigation required.	No moisture detected at time of inspection, currently monitoring for any signs of water infiltration.
Room 106	Visible mould on mechanical pipe insulation and porcelain tank cover.	Have area cleaned and decontaminated using Level 1 precautions by custodial staff.	Mould remediation complete.

## Conclusion and Recommendations:

Faculty and staff are asked to report any signs of water infiltration and/or mould to their Property Services Manager so that water infiltration is repaired and any mould which may have developed is remediated right away.

**For more information on the School Inspection program, please visit:**

[www.gov.pe.ca/eed/schoolinspections](http://www.gov.pe.ca/eed/schoolinspections)