

SCHOOL INSPECTION PROGRESS REPORT

School: Tignish Consolidated School, Western School Board

Date: August 24, 2011

Room # / Description	Observations	Level of Remediation	Status
Room 102, 130, 131, 132, 142, 144, 145, 148, Corridor 154, 159, 164, 166, 170, 176, 177	Stained ceiling tiles observed and reported throughout the building.	Removal of stained ceiling tiles to further investigate for potential hidden mould above ceiling. Replace with new to detect new water leaks.	Tiles replaced, currently monitoring for any signs of water infiltration.
Room 102, 164	Release valves above ceiling causing water staining on ceiling tiles.	Have valve repaired and ceiling tile replaced.	Valve repaired, ceiling tile replaced
Above room 148 2 nd Level	Water damage on canvas insulation above ceiling tiles in three separate areas.	Have leak and insulation repaired and ceiling tile replaced.	Leak repaired, insulation replaced and ceiling tile replaced
Room 145	Visible mould (minor) on underside of ceiling tile	Removal of stained ceiling tiles Replace with new to detect new water leaks.	Tiles replaced, currently monitoring for any signs of water infiltration.

Conclusion and Recommendations:

Stained tiles in Hallway are from an old leak which was repaired. Custodial staff will require maintenance to assist in changing out the fixed tiles with new.

Faculty and staff are asked to report any signs of water infiltration and/or mould to their Property Services Manager so that water infiltration is repaired and any mould which may have developed is remediated right away.

For more information on the School Inspection program, please visit:

www.gov.pe.ca/eed/schoolinspections