

SCHOOL INSPECTION PROGRESS REPORT

School: Stratford Elementary, Eastern School District

Date: July 22, 2011

| Room # / Description | Observations | Level of Remediation | Status |
|----------------------|------------------------|--|---|
| Room 108, 141, 154 | Stained ceiling tiles. | Removal of stained ceiling tiles to further investigate for potential hidden mould above ceiling. Replace with new tiles to detect new water leaks. | Tiles replaced March/'11, monitoring for any signs of water infiltration. |

Conclusion and Recommendations:

Faculty and staff are asked to report any signs of water infiltration and/or mould to their Property Services Manager so that water infiltration is repaired and any mould which may have developed is remediated right away.

For more information on the School Inspection program, please visit:

www.gov.pe.ca/eed/schoolinspections