




Remove Skin From Inside Face Of Panel Until The Next End Post Or Stinger Extension Is Exposed.

**Warning:** Take care When Removing Old Skin To Not Cut Into Supporting Tubes.




Step 2:

Install The Collar And Blocking (Blocking When Necessary)
To Manufacturer
Recommended Dimensions.

Weld 100% At Every Point Possible.

19-Nov-2010




Step 3:

Cover All Exposed Area With Skin Made From Manufacture Materials.

Weld 100% At Every Point Possible.

Collar To A Trench Shield



By. C Stevens