

Scoundrel contact had already occurred at forward end of Sprig's jib tracks. See other pages. Sprig advancing.



This photo is after Scoundrel contact and just before or at the Arunga time of contact. Arunga change in position from previous photo gives indicate of time between photos.



Sprig damage from Scoundrel at forward end of Jib tracks



Sprig damage from Scoundrel at forward end of Jib tracks Page 4 of 5



Sprig damage from Scoundrel at forward end of Jib tracks

Page 5 of 5