


PROPERTY ADDRESS: 23 Chester Street - Somerville

#### PROPOSED WORK

#### **Work Description:**

- Replace 2 rubber sections -- front porch and rear low-slope
- Install tapered ISO board on edge of porch roof to drain water back onto roof toward roof drains.
- Replace rotted 8' wood gutter section on right side above porch roof section







## Existing Conditions













### MATERIALS

- EPDM Black 0.60-millimeter thickness rubber membrane covering the entire surface. – Genflex
- Wood Gutter replacement 8' section on right side, above porch roof.

# THANK YOU!

FRS ROOFING TEAM