

Aisin AW TF-80SC*

*Fits Volvo (AM6), Opel (AF40), Peugeot (TF80), Saab (AF40/6) & Land Rover (TF80). Most of these kits also fit TF-81SC.

sonnax®

TIME TESTED • INDUSTRY TRUSTED®

1 Automatic Drive • P.O. Box 440 • Bellows Falls, VT 05101-0440 USA
(800) 843-2600 • (802) 463-9722 • F: (802) 463-4059 • www.sonnax.com

1 15741-29K Oversized Lockup Clutch Control Valve Kit

Helps cure:

- Converter remains applied causing harsh downshifts
- RPM surge on coast
- Fluid overheat

Note: Requires tool kits F-15741-TL29 & F-15741-TL29PL & the VB-FIX reaming fixture.

2 39741-01K Oversized Main Pressure Regulator & Boost Kit

Helps cure:

- Excess pressure in reverse
- Fluid & converter overheat
- Bushing failure

Note: Requires tool kit F-39741-TL & the VB-FIX reaming fixture.

3 39741-11K Oversized Secondary Regulator Valve Kit

Helps cure:

- High/Low SLT pressure
- Overheating bushings & converter
- Harsh reverse

Note: Requires tool kit F-39741-TL11 & the VB-FIX reaming fixture.

4 39741-18K Oversized Solenoid Modulator Valve Kit

Fits either of 2 locations

Helps cure:

- Codes P0734, P0735 or P0729
- Slippage/Shock on kickdown
- Slip in steady driving 4th, 5th or 6th

Note: Requires tool kit F-39741-TL18 & the VB-FIX reaming fixture.

Item 10 is an alternative option, based on wear, for the same five locations as item 9.



5 15741-25K Oversized C1 Clutch Control Valve Kit

6 39741-05K Oversized C2 Clutch Control Valve Kit

7 39741-08K Oversized C3 Clutch Control Valve Kit

C1, C2 & C3 kits... Help cure:

- Flare upshifts
- Coast downshift bumps
- Delayed engagement

Note: 15741-25K requires tool kit F-15741-TL25, and 39741-05K & 39741-08K require tool kit F-39741-TL5; all require the VB-FIX reaming fixture.

8 39741-22K Oversized B1 Band Control Valve Kit

Helps cure:

- Harsh downshifts
- Flare on 1-2, 2-3 or 5-6
- B-1 band distress

Note: Requires tool kit F-39741-TL22 & the VB-FIX reaming fixture.

9 15741-14K Accumulator Piston Kit.

Fits any of 5 locations

10 39741-42K Accumulator Piston & Sleeve Kit

Fits any of 5 locations

Helps cure:

- Delayed engagements
- Slipping forward gears
- Burnt clutches/bands

Note: This kit does not fit TF-81SC units.

15741-35K 15741-36K O-Ringed End Plug Kits

5 Small, 9mm

5 Large, 11mm

Helps cure:

- Various shift complaints

Note: These kits fit multiple locations.

12 15741-48K Spring Adjuster Kit

Fits 4 locations

Helps cure:

- Slip, soft or long extended shifts
- Shift quality gets worse as temperature increases

