




SensorConnect Changelog

v16.6.2

(2026-08-04)

Features

- Updated CV7, GV7, and CX7 devices to use HBK branding

Bug Fixes

- Fixed removing custom buttons throwing due to button map typos
- Fixed '±' symbol not displaying correctly in drop-downs
- Changed 'Documentation' link to 'Changelog' and fixed pointing to wrong changelog
- Fixed license link showing blank page