



Custom Track Service
Summary

MUSTANG SALES &
SERVICE CO., LLC. (E300)

TEXAS MUNICIPAL PWR AGENCY

Prepared By: Ben Schexnayder

Model	D10R	Job Site	gibbons creek reservoir		Inspection Date	05May21
Manufacturer	Caterpillar		Left	Right	Next Inspection Date	--
Serial Number	3KR01792	Track Sag (5.7 in - 6.5 in)	5.80 "	5.80 "	Next Inspection Hours	--
Reference Number	--	Frame Ext (max 7.6 in)	--	--	Underfoot Conditions	
Hour Meter Reading	--	Dry Joints	0	0	Impact	--
Hours Per Week	--	Track Shoe Width	30.90 "	30.90 "	Abrasion	--
Total Odometer Reading	--				Moisture	--
Forward Odometer	--				Packing	--
Reverse Odometer	--				Bushing Allowable Wear	Greater
					Link Allowable Wear	Greater

GROUP	RECOMMENDATION	% WORN		PROJECTED SMU AT 100%		PROJECTED SMU AT 120%		PROJECTED DATE AT 100%		PROJECTED DATE AT 120%	
TRACK LINK	Good	6% (2.33 in)	6% (2.33 in)	--	--	--	--	--	--	--	--
BUSHING (EXT)	Good	16% (0.68 in)	12% (0.69 in)	--	--	--	--	--	--	--	--
TRACK SHOE	Good	13% (4.24 in)	12% (4.25 in)	--	--	--	--	--	--	--	--
FRONT IDLER	Good	16% (0.86 in)	16% (0.86 in)	--	--	--	--	--	--	--	--
REAR IDLER	Good	14% (0.85 in)	14% (0.85 in)	--	--	--	--	--	--	--	--
TRACK ROLLER FRONT	Good	13% (2.72 in)	12% (2.73 in)	--	--	--	--	--	--	--	--
2	Good	11% (2.74 in)	10% (2.75 in)	--	--	--	--	--	--	--	--
3	Good	10% (2.55 in)	10% (2.55 in)	--	--	--	--	--	--	--	--
4	Good	8% (2.57 in)	8% (2.57 in)	--	--	--	--	--	--	--	--
5	Good	6% (2.59 in)	7% (2.58 in)	--	--	--	--	--	--	--	--
6	Good	11% (2.54 in)	11% (2.54 in)	--	--	--	--	--	--	--	--
7	Good	9% (2.76 in)	9% (2.76 in)	--	--	--	--	--	--	--	--
8	Good	14% (2.71 in)	13% (2.72 in)	--	--	--	--	--	--	--	--
SPROCKET	Good	2% (11.20 in)	2% (11.20 in)	--	--	--	--	--	--	--	--

CONDITION: Good

CONDITION: Good

NOTES: Slightly Worn

General Recommendations

--