



Custom Track Service
Summary

MUSTANG SALES &
SERVICE CO., LLC. (E300)

TEXAS MUNICIPAL PWR AGENCY

Prepared By: Ben Schexnayder

Model	D8LSA	Job Site	gibbons creek reservoir		Inspection Date	06May21
Manufacturer	Caterpillar		Left	Right	Next Inspection Date	--
Serial Number	53Y00891	Track Sag (5.1 in - 5.9 in)	--	--	Next Inspection Hours	--
Reference Number	--	Frame Ext (max 6.5 in)	4.00 "	4.20 "	Underfoot Conditions	
Hour Meter Reading	--	Dry Joints	0	0	Impact	--
Hours Per Week	--	Track Shoe Width	22.00 "	22.00 "	Abrasion	--
Total Odometer Reading	--				Moisture	--
Forward Odometer	--				Packing	--
Reverse Odometer	--				Bushing Allowable Wear	Greater
					Link Allowable Wear	Greater

GROUP	RECOMMENDATION	% WORN		PROJECTED SMU AT 100%		PROJECTED SMU AT 120%		PROJECTED DATE AT 100%		PROJECTED DATE AT 120%	
TRACK LINK	Good	16% (1.80 in)	18% (1.79 in)	--	--	--	--	--	--	--	--
BUSHING (EXT)	Good	8% (0.58 in)	12% (0.57 in)	--	--	--	--	--	--	--	--
TRACK SHOE	Good	29% (3.34 in)	29% (3.33 in)	--	--	--	--	--	--	--	--
FRONT IDLER	Good	26% (0.91 in)	26% (0.91 in)	--	--	--	--	--	--	--	--
REAR IDLER	Good	24% (0.90 in)	20% (0.88 in)	--	--	--	--	--	--	--	--
TRACK ROLLER FRONT	Good	20% (2.28 in)	20% (2.28 in)	--	--	--	--	--	--	--	--
2	Good	9% (2.39 in)	10% (2.38 in)	--	--	--	--	--	--	--	--
3	Good	11% (2.28 in)	8% (2.30 in)	--	--	--	--	--	--	--	--
4	Good	8% (2.30 in)	10% (2.29 in)	--	--	--	--	--	--	--	--
5	Good	8% (2.30 in)	8% (2.30 in)	--	--	--	--	--	--	--	--
6	Good	11% (2.28 in)	11% (2.28 in)	--	--	--	--	--	--	--	--
7	Good	9% (2.39 in)	8% (2.40 in)	--	--	--	--	--	--	--	--
8	Good	9% (2.39 in)	10% (2.38 in)	--	--	--	--	--	--	--	--
SPROCKET	Good	6% (9.21 in)	8% (9.20 in)	--	--	--	--	--	--	--	--

CONDITION: Good

NOTES: Rusted

NOTES: Rusted

General Recommendations

--