PRESSURE VESSEL & COLUMN INSPECTION REPORT
Date: Mar. 4, 2016 Report #: IF

| Plant | Jackfish Creek | Op Unit EC- | -NO | System / LSD: | 04-26-065-0 | 5w4 | |
|------------|----------------------|---------------|-------------------|----------------|-------------|-------|----|
| Asset # | 66041478 | Equipment ID | | Asset Type | Separato | or | |
| Descripti | on 2 Phase Separato | r | Prov. Insp. # A | 2792929 | Serial # | 2079 | |
| Manufact | curer RJV Gasfield S | ervice | CRN H3897 | 2 | Year Built | 1992 | |
| MAWP | 4965 | KPag | @ 38 ⁰ | | MDMT | -29 | °C |
| Code | ASME VIII | Fluid Service | Natural Gas | Sweet | PWHT | No | |
| Internal A | Access No | Insulated | No | | Internal Co | ating | No |
| Operating | g Pressure - | | KPag | Operating Temp | - | _ | °C |

Report #: IR160304GENj

PSV DATA

| Separator | | | Fuel Gas Scrubber | | | |
|-----------------------|------|------------------------------|-------------------|------|--------------------------------------|--|
| Serial Number: | | 011110-102 | Serial Number: | | 011110-79 | |
| Manufacturer: | | Taylor | Manufacturer: | | Taylor | |
| Model: | | T-8200-1 | Model: | | T-8200-1 | |
| Set Pressure | Кра | 4965 | Set Pressure | Кра | 1035 | |
| Capacity | SCFM | 2614 | Capacity | SCFM | 582 | |
| Inlet Size | mm | 25 | Inlet Size | mm | 25 | |
| Outlet Size | mm | 25 | Outlet Size | mm | 25 | |
| Service Date: mm/yyyy | | 06/2011 | Service Date: | | 06/2011 | |
| Location: | | On the Side of the Separator | Location: | | On the Side of the Fuel Gas Scrubber | |

INSPECTION SUMMARY

External:

A visual external inspection performed to the applicable standards did not identify any concerns with the pressure boundary of this equipment, there were no significant deficiencies noted.

This equipment was in service at the time of inspection.

A thorough inspection to verify the equipment's integrity was done by VE and UT.

The nameplate is intact and legible.

There are no recommendations to be made at this time.

No NCR's were issued at this time.

The Fuel Gas Scrubber with CRN OH-0102.23 is in fair condition, the UT performed was within acceptable limits.

Internal:

There was no internal inspection or NDE performed at this time, the scope of work was for an external inspection only.

NDE

The UT readings are within acceptable limits and within the corrosion allowance: see the UT readings below.

| | RECOMMENDA | TIONS | |
|-------|--------------------|--------------------|--|
| | | | |
| | | | |
| NONCO | NFORMANCES / INSPE | CTION DEFICIENCIES | |
| | | | |
| | | | |
| | | | |

Inspection Strategy Availability Inspection Interval 10 yrs Inspection Date 03/2016 Date of Last Inspection Date of Next Inspection 03/2026

REPORT CERTIFICATION

| The signatures below certify that in the specified equipment is consider | • | | | fied inspection strategy and that |
|---|--------------|----------------|------------------------|-----------------------------------|
| VE Inspected by / Certification # | Guy Normand | API 510# 23041 | All of the second | Date Mar. 4, 2016 |
| VI Inspected by / Certification # | | | 4 | Date |
| Reviewed and Approved by | Roman Wynnyk | | How hand | Date Mr. ////. |
| Criticality Assessment Rerun | | | Inspection Planning Re | erun |
| Assessed Next Inspection Date | | | | |

PRESSURE VESSEL & COLUMN INSPECTION REPORT

Date: Mar. 4, 2016

Report #: IR160304GENj

DETAILED INSPECTION VISUAL EXTERNAL

| ID | Description | Condition | Location | NCR / IDR | Comments |
|-----|---------------------------------|-------------|----------|--------------|--|
| V1 | General Other (Explain) | Good | | 1 | This equipment was found to be acceptable for continued service. |
| | | 7 4 4 4 4 4 | | | Any deficiencies are noted below. |
| | III | | | | The nameplate is intact and legible. Covered in duct tape. |
| V2 | General Corrosion | Good | | | There is no corrosion present in the areas that were visibly |
| | | | | | accessible. |
| V3 | General Leaks | Good | | | No leaks were noted. |
| V4 | Vibration | N/A | | | |
| V5 | Dissimilar Flange Rating | Good | | | There are no dissimilar flange ratings noted on the components that are visible. |
| V6 | Ladder/Stairway | N/A | | | |
| V7 | Heads | Good | | | The heads are in good mechanical condition. |
| V8 | Guy Wires | N/A | | | |
| V9 | Electrical Ground | Good | | | The equipment is grounded through the skid package. |
| V10 | Painted Inactive Corrosion | N/A | | | |
| V11 | Coating/Painting | Good | | | The paint is in fair condition. |
| V12 | Expansion Joint or Bellows | N/A | | | |
| V13 | Gauge/Site Glass | Good | | | The gauges are legible and appear to be functioning properly. |
| V14 | Shell | Good | | | The shell is in good mechanical condition. |
| V15 | Jacket | N/A | | | |
| V21 | Support Other (Explain) | N/A | | | |
| V22 | Foundation | N/A | | | |
| V23 | Anchor Bolts | N/A | | | |
| V24 | Saddle/Skirt | Good | | | The skirt is in good mechanical condition. |
| V25 | Davit | N/A | | | |
| V26 | Fireproofing | N/A | | | |
| V31 | Connections Other (Explain) | Good | | | All piping connections to the vessel are secure. |
| V32 | Small Branches | Good | | la la | The instrumentation tubing is acceptable, no signs of leakage noted. |
| V33 | Nozzles | Good | | | All visible nozzles are straight with no mechanical deficiencies noted. |
| V34 | Manways | N/A | | W. | |
| V35 | Reinforcing Pads | N/A | | | |
| V36 | Inadequate Thread Engagement | Good | | | The thread engagement is adequate. |
| V37 | Bolting | Good | | | The studs / nuts are secure. |
| V38 | Flanges | Good | | | All flanges are intact with no defects noted. |
| V39 | Leak Clamps | N/A | | | g and a second a second and a second and a second and a second and a second a second and a second a second and a second and a second a second a second a second and a second a |
| V41 | Insulation Other (Explain) | N/A | | - | |
| V42 | Damage | N/A | 0. | | |
| V43 | Penetrations | N/A | | 1 | |
| V44 | Insulation Jacket | N/A | 1 | + | |
| V45 | Banding | N/A | + | | |
| V46 | Seals/Joints | N/A | | | |
| V51 | Relief Devices Other | Good | + | | The PSV is set to the proper pop pressure and has been serviced |
| | (Explain) | | | | within an acceptable time frame. |
| V52 | Relief Devices Corrosion | N/A | - | | |
| V53 | Relief Devices Leaks | N/A | 1 | | |
| V54 | Restricted Inlet/Outlet | N/A | | | |
| V55 | Manual Operation Lever | N/A | | | |

PRESSURE VESSEL & COLUMN INSPECTION REPORT

Date: Mar. 4, 2016

Report #: IR160304GENj

DETAILED INSPECTION VISUAL INTERNAL

| | | | | ISOAL III | ILKITAL |
|-----|----------------------------------|-----------|----------|--------------|----------|
| ID | Description | Condition | Location | NCR / IDR | Comments |
| 1/4 | O | | 1 | 1 | |
| V1 | General Other (Explain) | | | | |
| V2 | Corrosion (depth, length, width) | | | | |
| V3 | Erosion | | | | |
| V4 | Distortion | | | | |
| V5 | Blisters | | | | |
| V6 | Deposits | | | | |
| V7 | Heads | | | | |
| V8 | Welds | | | | |
| V9 | Nozzles | | | | |
| V10 | Shell | | | | |
| V11 | Gasket Surfaces | | | | |
| V21 | Internals Other(Explain) | | | | |
| V22 | Demister | | | | |
| V23 | Baffle/Weir | | | | |
| V24 | Sparger | | | | |
| V25 | Thermowells | | | | |
| V26 | Metallic Linings | | | - | |
| V27 | Nonmetallic Linings | | | | |
| V28 | Trays | | | | |
| V29 | Tray Rings | | | | |
| V30 | Other: Welded Attachments | | | | |

DETAILED INSPECTION OTHER TECHNIQUES

| ID | Location | Observation/Measurement | Acceptance Criteria | NCR / IDR | Comments | |
|----|----------|-------------------------|---------------------|--------------|----------|--|
| 1 | | | | | | |
| 2 | | | | | | |
| 3 | | | | | | |
| 4 | | | | | | |
| 5 | | | | | | |

DETAILED INSPECTION UT THICKNESS

| CML | Nom. Thk | Current Reading | Short Term Corr Rate | Long Term Corr Rate | Remaining Life | Comments |
|-----|-------------|--------------------|-------------------------|------------------------|-------------------|-----------------------------|
| 005 | 11.1 | 11.1 | | | | 3" Inlet nozzle |
| 010 | 11.1 | 12.7 | - | | | Top Head |
| 015 | 12.7 | 12.8 | | | | Upper Shell |
| 020 | 12.7 | 12.7 | | | | Lower shell at liquid level |
| 025 | 11.1 | 12.8 | | | | Bottom Head |
| 030 | 11.1 | 12.5 | | | | Bottom Head Scan |
| 035 | 11.1 | 12.1 | | | | 2" Drain nozzle 90° elbow |
| 040 | 11.1 | 11.2 | | | | 3" Outlet nozzle |
| | | | | | | |
| | | - | | | | |

PRESSURE VESSEL & COLUMN INSPECTION REPORT

Date: Mar. 4, 2016

Report #: IR160304GENj

PHOTOS





Nameplate





Fuel Gas Scrubber