

MDTools 790 Hotfix 02

Applicability: MDTools 790 with MDTools 790 Service Pack 02 installed

Issues Resolved:

1. Rotation of Undercut gave an error when running Machining Chart.
2. When inserting a Cavity with a mandatory Undercut, the placement of the Undercut was incorrect.

Date: Oct 07, 2024