

MDTools® 985 Hotfix 05

Applicability: MDTools 985 with Service Pack 2 and with or without Hotfix 04 Installed.

Issues Resolved:

1. MDTools Resize Block was unable to correctly position footprints when their parent cavity was suppressed within the manifold block.

Date: Oct 01, 2026

MDTools® 985 Hotfix 04

Applicability: MDTools 985 with Service Pack 2 Installed.

Issues Resolved:

1. MDTools Conformance to Schematic check was unable to detect incorrect net names and port types for flanges.
2. Cavities without Step12 incorrectly updated the depth of the bottom step when stretching the block.

Date: Apr 29, 2026