

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 3400

<p>SHEET 15 LTPP TRAFFIC DATA</p> <p>LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM</p>	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{5022}

LOCATION ON I 65 0.7 MI S OF SOUTHPORT ROAD
MP# 102.5

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
02-10-10	2:30PM	Site inspection loops 2,5,6,9,10,11,12 need respliced.	Mike Hemelgarn	317-502-3012	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 3400

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{5022}

LOCATION ON I 65 0.7 MI S OF SOUTHPORT ROAD
MP# 102.5

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
05-12-10	11:45am	Bypassed and removed bad UPS	Richard Martin	317-695-4773	N/A

revised November 11, 1999