

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P10]
	*STATE CODE	[53]
	*SHRP SECTION ID	[1005]

LOCATION SR 90 TYPE EQUIP. Piezo (Class 1)

MP # 218.3 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
10/10/01		<p>Site quit collecting at 0800-0900 on 9-24-01, grinding and paving in area (Tom)</p> <p>I stopped at Ritzville #1 on Thursday 10/11. EB is striped and they were working on striping the WB. I don't know if they got that far by end of day, someone will have to check.</p> <p>Steve</p>	Steve Schindler		
10/22-24/01		<p>Ritzville 1 P10.</p> <p>Start recut of site. Eastbound is complete, still have one lane (drive) to finish westbound. The grinding/paving crew damaged our conduit westbound. Talked with the engineers about possible replacement. Kevin will check into it and get back with me. Will complete this site next week. (KL)</p>	Ken Lakey		

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P10]
	*STATE CODE	[53]
	*SHRP SECTION ID	[1005]

LOCATION SR 90 TYPE EQUIP. Piezo (Class 1)

MP # 218.3 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
02/20/01		Ritzville 1, P10, road is bad around our site location. If no overlay or road work is coming soon we could relocate this site east or west of current location. – Ken Lakey	KEN LAKEY		