

**BrightSign**<sup>®</sup>

# **BRIGHTAUTHOR RELEASE NOTES**

Version 4.7.1.22

## BrightAuthor Requirements

- PC with Windows Vista, Windows 7, Windows 8, or Windows 10—plus Microsoft .Net Framework 4.6 or later
- XTx44, XTx43: **Minimum Required Firmware: 7.1.49**
- XTx34, XDx33, HDx23, LS423, HO523, HS123: **Minimum Required Firmware: 6.2.39**
- 4Kx42, XDx32, XDx30, HDx22, HDx20, LSx22, AU320: **Minimum Required Firmware: 5.1.33**

## Changes Since 4.7.1.14

### New Features

- Support for the following video modes: 800x1280x60p, 1200x1920x60p, 1280x720x25p, 1440x1080x60p, 1920x1200x50p, 3840x2160x23.976p
- **Enable camera access for web browser** checkbox for HTML5 states

### Improvements

- The 1920x1080x23.976p video mode is now available for 4Kx42 models.
- If a player encounters a media file in a Media RSS Feed state that is still being downloaded, it will now skip to the next downloaded file in the MRSS playlist rather than waiting for the download to complete.
- The BrightAuthor EULA contains updated language.
- The BrightAuthor autorun now automatically creates an application cache for HTML pages.

## Bug Fixes

- 31690: The player setup process now works with players running firmware versions 6.2.63 or earlier.
- 31356: The pixel value of the presentation area is now correctly represented when the **Full resolution graphics** option is enabled for 4096x2160 and 3840x2160x60/59.94/50p video modes,.
- 31538: Publishing to an HDx20, LSx22, or AU320 player running 6.1.76 or earlier no longer causes the player to crash.
- 31285: The **Audio Configuration** panel in the **Presentation Properties > Audio** window has been disabled for XDx30, HDx20, LSx22, and AU320 players.
- 31400: Issues related to Remote Snapshot on slow networks have been fixed.
- 31605: Players that have Remote Snapshot enabled (and are not set up for BSN networking) no longer crash after a Timeout event from an HTML5 state referencing a nonexistent URL.