Edit
Canister-Gouging (002).jpg
MPC 72 QUADRANT 2
3/23/2019 11:07 AM
BETWEEN SEISMIC RESTRAINTS 3 & 4
786 x 599
306 KB
100%


Edit
SCE Recent Results from Inspection on 72 (002).jpg
2019 (left) vs. 2024 (right) Depth Measurements
• Original characterization in 2019. Notice the red dot on left image and vertical straight line, which indicates a possible erroneous reading.
• Remeasurement in 2024.
Conclusions
• Scratches are still bright and shiny, no evidence of corrosion or chloride-induced stress corrosion cracking precursor activity.
713 x 614
142.6 KB
100%

Edit
Canister-Corrosion (002).jpg
MPC 72 INSPECTION
3/23/2019 10:01 AM
BETWEEN SEISMIC RESTRAINTS 1 & 2
787 x 600
298.3 KB
100%