

SERVICE PARTS LIST FOR MITSUBISHI ELECTRIC REFRIGERATION SYSTEMS:CHILLING UNIT

Series : EACV-P•YBL(-N)(-BS)

REVISED

Dec. 2023


BWE02022A

INDEX
EACV-P040YBL
EACV-P040YBL-BS
EACV-P040YBL-N
EACV-P040YBL-N-BS
EACV-P050YBL
EACV-P050YBL-BS
EACV-P050YBL-N
EACV-P050YBL-N-BS

Part information update day : **2023/12/15**

Please change the old catalog (issued Jan. 2021, No.BWE020220) to this new catalog.
Content of revision : Some of parts are changed.






No.	Part No.	Part Name	Spec.	EACV-P040YBL	EACV-P040YBL-BS	EACV-P050YBL	EACV-P050YBL-BS	Dwg. No.	Notes for the models	Revision info.
101	R15 015 626	Pillar		4	4			KC02P407G01		
102	R15 016 626	Pillar	BS		4	4		KC02P407G02		
103	R15 083 661	Panel UL		2	2			KC02J353G03		
104	R15 084 661	Panel UL	BS		2	2		KC02J353G04		
105	R15 085 661	Panel UR		2	2			KC02J354G03		
106	R15 086 661	Panel UR	BS		2	2		KC02J354G04		
107	R15 116 661	Panel ML		2	2			KC02R976G11		
108	R15 117 661	Panel ML	BS		2	2		KC02R976G12		
109	R15 118 661	Panel MR		2	2			KC02R985G11		
110	R15 119 661	Panel MR	BS		2	2		KC02R985G12		
111	R15 091 661	Panel assy SRL		2	2			KC00T296G01		
112	R15 092 661	Panel assy SRL	BS		2	2		KC00T296G02		
113	R15 144 661	Panel assy SR1		1	1			KC00S920G02		
114	R15 145 661	Panel assy SR1	BS		1	1		KC00S920G01		
115	R15 146 661	Panel assy SR2		1	1			KC00S921G02		
116	R15 147 661	Panel assy SR2	BS		1	1		KC00S921G01		
117	R15 148 661	Panel assy SL		2	2			KC00S919G02		
118	R15 149 661	Panel assy SL	BS		2	2		KC00S919G01		
119	R15 093 661	Panel assy TF		2	2			KC00P703G07		
120	R15 094 661	Panel assy TF	BS		2	2		KC00P703G08		
121	R15 095 661	Panel assy F		1	1			KC00T298G01		
122	R15 096 661	Panel assy F	BS		1	1		KC00T298G02		
123	R15 097 661	Panel assy BT		1	1			KC00P685G07		Chg.
124	R15 098 661	Panel assy BT	BS		1	1		KC00P685G08		Chg.
125	R15 150 661	Panel assy BR		1	1			KC00S984G01		
126	R15 151 661	Panel assy BR	BS		1	1		KC00S984G02		
127	R15 152 661	Panel assy BL		1	1			KC00S982G01		
128	R15 153 661	Panel assy BL	BS		1	1		KC00S982G02		
129	R15 103 661	Panel assy SF		2	2			KC00P860G03		
130	R15 104 661	Panel assy SF	BS		2	2		KC00P860G04		
131	R61 004 119	Bell mouth		4	4	4	4	KB25A368H04		Chg.
132	R61 009 669	Plate fan guard		16	16	16	16	KD02D205H03		Chg.
133	R11 003 009	Fan guard		4	4	4	4	KB25V019H04		Chg.
134	R15 007 318	Base fan		8	8			KW02C337H01		
135	R15 008 318	Base fan	BS		8	8		KW02C337G02		
136	R15 010 941	Motor	920W T 415V	4	4	4	4	KC61A231G01		
137	R61 047 114	Fan		4	4	4	4	KB25A993H02		
138	R63 4H6 122	Box nut	M12 CH	4	4	4	4	P552000X01		
139	R63 014 087	Upset screw	M6×10	16	16	16	16	P516047X01		
140	R63 009 087	PTT screw	5×10(30pcs)	9	9	9	9	KB00H418G04	242pcs/unit	
141	R15 001 383	Stopper assy		8	8			KC00M962G03		
142	R15 002 383	Stopper assy	BS		8	8		KC00M962G04		
143	R15 001 215	Frame TF		2	2			KC00R955G03		
144	R15 002 215	Frame TF	BS		2	2		KC00R955G04		
145	R15 001 119	Bell mouth support		8	8			KC02R625H02		

EACV-P040YBL(-BS)
EACV-P050YBL(-BS)

EXTERNAL PARTS & BLOWER PARTS (1)

[illegible]






No.	Part No.	Part Name	Spec.	EACV-P040YBL-N	EACV-P040YBL-N-BS	EACV-P050YBL-N	EACV-P050YBL-N-BS	Dwg. No.	Notes for the models	Revision info.
201	R15 015 626	Pillar		4	4			KC02P407G01		
202	R15 016 626	Pillar	BS		4	4		KC02P407G02		
203	R15 083 661	Panel UL		2	2			KC02J353G03		
204	R15 084 661	Panel UL	BS		2	2		KC02J353G04		
205	R15 085 661	Panel UR		2	2			KC02J354G03		
206	R15 086 661	Panel UR	BS		2	2		KC02J354G04		
207	R15 116 661	Panel ML		2	2			KC02R976G11		
208	R15 117 661	Panel ML	BS		2	2		KC02R976G12		
209	R15 118 661	Panel MR		2	2			KC02R985G11		
210	R15 119 661	Panel MR	BS		2	2		KC02R985G12		
211	R15 091 661	Panel assy SRL		2	2			KC00T296G01		
212	R15 092 661	Panel assy SRL	BS		2	2		KC00T296G02		
213	R15 144 661	Panel assy SR1		1	1			KC00S920G02		
214	R15 145 661	Panel assy SR1	BS		1	1		KC00S920G01		
215	R15 148 661	Panel assy SL1		1	1			KC00S919G02		
216	R15 149 661	Panel assy SL1	BS		1	1		KC00S919G01		
217	R15 093 661	Panel assy TF		2	2			KC00P703G07		
218	R15 094 661	Panel assy TF	BS		2	2		KC00P703G08		
219	R15 095 661	Panel assy F		2	2			KC00T298G01		
220	R15 096 661	Panel assy F	BS		2	2		KC00T298G02		
221	R15 097 661	Panel assy BT		1	1			KC00P685G07		Chg.
222	R15 098 661	Panel assy BT	BS		1	1		KC00P685G08		Chg.
223	R15 170 661	Panel assy B		1	1			KC00S986G01		
224	R15 171 661	Panel assy B	BS		1	1		KC00S986G02		
225	R15 172 661	Panel assy SR2		1	1			KC00S990G01		
226	R15 173 661	Panel assy SR2	BS		1	1		KC00S990G02		
227	R15 174 661	Panel assy SL2		1	1			KC00S988G01		
228	R15 175 661	Panel assy SL2	BS		1	1		KC00S988G02		
229	R15 103 661	Panel assy SF		2	2			KC00P860G03		
230	R15 104 661	Panel assy SF	BS		2	2		KC00P860G04		
231	R61 004 119	Bell mouth		4	4	4	4	KB25A368H04		Chg.
232	R61 009 669	Plate fan guard		16	16	16	16	KD02D205H03		Chg.
233	R11 003 009	Fan guard		4	4	4	4	KB25V019H04		Chg.
234	R15 007 318	Base fan		8	8			KW02C337H01		
235	R15 008 318	Base fan	BS		8	8		KW02C337G02		
236	R15 010 941	Motor	920W T 415V	4	4	4	4	KC61A231G01		
237	R61 047 114	Fan		4	4	4	4	KB25A993H02		
238	R63 4H6 122	Box nut	M12 CH	4	4	4	4	P552000X01		
239	R63 014 087	Upset screw	M6×10	16	16	16	16	P516047X01		
240	R63 009 087	PTT screw	5×10(30pcs)	9	9	9	9	KB00H418G04	234pcs/unit	
241	R15 001 383	Stopper assy		8	8			KC00M962G03		
242	R15 002 383	Stopper assy	BS		8	8		KC00M962G04		
243	R15 001 215	Frame TF		2	2			KC00R955G03		
244	R15 002 215	Frame TF	BS		2	2		KC00R955G04		
245	R15 001 119	Bell mouth support		8	8			KC02R625H02		




EACV-P040YBL-N(-BS)
EACV-P050YBL-N(-BS)

EXTERNAL PARTS & BLOWER PARTS (2)

[illegible]



Detail of sensor assy




*1 Prepare the band assy (parts No.320)
before replacing the compressor (parts No.301).

EACV-P040YBL(-N)(-BS)
EACV-P050YBL(-N)(-BS)




FUNCTIONAL PARTS

[illegible]

[illegible]





[illegible]



[illegible]

Attention

Parts differ for 1A, 1B, 2A, and 2B,
so be sure to check the parts numbers
to ensure that the correct parts are used
for each control box.




[illegible]

[illegible]

Attention

Parts differ for 1A, 1B, 2A, and 2B,
so be sure to check the parts numbers
to ensure that the correct parts are used
for each control box.





[illegible]

[illegible]

Attention

Parts differ for 1A, 1B, 2A, and 2B,
so be sure to check the parts numbers
to ensure that the correct parts are used
for each control box.




[illegible]

[illegible]


Attention

Parts differ for 1A, 1B, 2A, and 2B,
so be sure to check the parts numbers
to ensure that the correct parts are used
for each control box.



[illegible]

[illegible]



[illegible]

[illegible]

mitsubishi electric corporation

BWE02022A (20231231)