Designer r32.4.23 Release Notes

Download r32.4.23 Full (Pro)

Full (Pro) build: *273273*
Starter build: *273274*
Released: *November 4th 2026*

Items marked with a ● are also included in r34.2.3.

Improvements

- **DSOF - 26636** - Project diagnostics will now include OmniCal Plan settings, calibration results and alignment data, so we have more information when we help you with OmniCal issues. Captured images are still not included, so diagnostics for OmniCal projects will only be slightly larger.
- **DSOF - 34121** - Designer now uses CodeMeter v9.10a, and the installer includes CodeMeter Runtime v9.10a.

Fixes

- **DSOF - 34050** - PreComps will no longer fade faster than other content when the transport brightness is lowered.
- **DSOF - 32446** - HDMI video capture will no longer occasionally look pixelated at some input resolutions when the source sends RGB.
- **DSOF - 26895** - The active OmniCal Plan will no longer stay greyed out after startup when another Plan's name is the active Plan's name followed by a "." suffix, for example `Plan` and `Plan.v2`.
- **DSOF - 24524** - Designer will no longer repeatedly log "Network settings changed" when nothing has changed on a machine with a wireless network adapter.
- **DSOF - 34382** - On a machine with two Rivermax network cards on different networks, RenderStream Uncompressed streams will now be received on the card on the render node's network, instead of occasionally showing "No frames received yet".