

Designer r34.1.2 Release Notes

[Download r34.1.2 Full \(Pro\)](#)

Full (Pro) build: 263189

Starter build: 263190

Released: September 23rd 2026

Items marked with a ● are also included in [r32.4.18](#).

Fixes

- **DSOF - 30108** - Designer will no longer lose performance while it has a DMX device that cannot be reached on the network.
- **DSOF - 33652** - Designer will now interpret timecode correctly when a timeline's frame rate differs from the project clock's native rate, such as a 30 fps timeline in a 59.94 fps project.
- **DSOF - 33793** - Video inputs will no longer go black when GPU compute is unavailable. This typically would only happen on X Series machines.
- **DSOF - 33703** - Designer will no longer log excessively when an SDI input's geometry is not supported by the installed Deltacast hardware.
- **DSOF - 33643** - Designer will now discover RenderStream shortcut (.lnk) assets when an Unreal project is also present in the RenderStream Projects folder.
- **DSOF - 33204** - The RenderStream RTC license now correctly removes the RenderStream watermark on X Series machines running RenderStream Local.
- **DSOF - 33810** - Designer will no longer crash to desktop intermittently in rare circumstances.