



ECHLIN®

WEATHERLY # 512

NAUP-13

APRIL 2013

Supersedes Catalog NAUP-05

Unit Parts Guide For Electrical Systems

Distributor Parts


Electronic Ignition

Contact Controlled Ignition

Alternator Parts

Generator Parts

Starter Parts



NAPA ECHLIN IGNITION & FUEL SYSTEMS LIMITED WARRANTY

Your new NAPA Echlin product is warranted to you, the original customer to be free of defects in material and workmanship (as determined solely by NAPA Echlin) for one (1) year from the date of installation, subject to the limitations below. NAPA Echlin will repair or replace the NAPA Echlin product if it is proven defective under normal use and service. The NAPA Echlin product must be shipped prepaid or delivered to a participating NAPA store in the United States. Proof of the date of sale to the original customer may be required. NAPA Echlin modules have a 5 year/50,000 mile warranty.

This warranty does not include labor or cover the cost of any other components or labor required to restore the motor vehicle to its proper operating condition.

This warranty does not apply to NAPA Echlin products that have been: 1) altered; 2) improperly installed, maintained or repaired or installed on another engine or motor vehicle; 3) damaged by accident, negligence or misuse; or 4) used in commercial, fleet, heavy duty, off road, public or governmental vehicles.

ALL IMPLIED WARRANTIES, INCLUDING WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE EXCLUDED AFTER ONE (1) YEAR. NAPA ECHLIN IS NOT RESPONSIBLE FOR INJURY, PROPERTY DAMAGE OR OTHER INCIDENTAL OR CONSEQUENTIAL DAMAGES ARISING DIRECTLY OR INDIRECTLY OUT OF THE USE OF THIS PRODUCT, NOTWITHSTANDING THE FACT THAT SAID INJURY, PROPERTY DAMAGE OR OTHER INCIDENTAL OR CONSEQUENTIAL DAMAGES AROSE DIRECTLY OR INDIRECTLY FROM AN ACTUAL ALLEGED DEFECT IN MATERIAL AND/OR WORKMANSHIP.

Some states do not allow limitations on how long an implied warranty lasts, or the exclusion of limitation of incidental or consequential damages, so the above limitations or exclusions may not apply to you. This warranty gives you specific legal rights. You may also have other rights that vary from state to state.

For further information regarding this Limited Warranty, contact your local NAPA Auto Parts Store; NAPA Distribution Center; or NAPA Echlin, 37-18 Northern Boulevard, Long Island City, N.Y. 11101-1616, Attention Product Assistance Group, 1-800-732-4832.

SYSTÈMES D'ALLUMAGE ET D'ALIMENTATION EN CARBURANT NAPA ECHLIN GARANTIE LIMITÉE

Ce produit neuf NAPA Echlin est garanti à l'acheteur d'origine contre tout défaut de matériaux et de fabrication (comme déterminé à la seule discrétion de NAPA Echlin) durant un (1) an à compter de la date d'installation, sous réserve des limitations figurant ci-dessous. NAPA Echlin réparera ou remplacera le produit NAPA Echlin s'il s'avère défectueux après avoir été soumis à des conditions normales d'utilisation et de service. Le produit NAPA Echlin doit être expédié port payé ou livré à un magasin NAPA participant aux États-Unis. Une preuve de la date de vente à l'acheteur d'origine peut être exigée. Les modules NAPA Echlin sont protégés par une garantie de 5 ans/80 000 kilomètres.

Cette garantie ne couvre pas les frais de main-d'œuvre ni le coût de tout autre composant nécessaire, pas plus que les coûts de la main-d'œuvre nécessaire pour rétablir le bon état de fonctionnement du véhicule.

Cette garantie ne couvre pas les produits NAPA Echlin qui ont été : 1) modifiés; 2) installés, entretenus ou réparés de manière incorrecte; 3) endommagés en raison d'un accident, d'une négligence ou d'une utilisation abusive; ou 4) utilisés sur des véhicules lourds, commerciaux, de parcs, tout-terrain, de transport en commun ou gouvernementaux.

TOUTES LES GARANTIES IMPLICITES, NOTAMMENT LES GARANTIES DE QUALITÉ MARCHANDE ET D'ADAPTABILITÉ À UN USAGE PARTICULIER, SONT EXCLUES APRÈS UN (1) AN. NAPA ECHLIN N'EST PAS RESPONSABLE DES BLESSURES, DES DOMMAGES MATÉRIELS ET D'AUTRES DOMMAGES-INTÉRÊTS INDIRECTS OU CONSÉCUTIFS DÉCOULANT DIRECTEMENT OU INDIRECTEMENT DE L'UTILISATION DE CE PRODUIT, MALGRÉ LE FAIT QUE LESDITES BLESSURES, LESDITS DOMMAGES OU TOUS LES AUTRES DOMMAGES-INTÉRÊTS INDIRECTS OU CONSÉCUTIFS PUISSENT DÉCOULER DIRECTEMENT OU INDIRECTEMENT D'UN DÉFAUT RÉEL PRÉSUMÉ DE MATÉRIAUX OU DE FABRICATION.

Certaines provinces interdisent la limitation de la durée d'une garantie implicite ou l'exclusion de la limitation des dommages indirects ou consécutifs; par conséquent, il est possible que les limitations ou les exclusions susmentionnées ne s'appliquent pas au titulaire de cette garantie. Cette garantie confère des droits particuliers à son titulaire, mais il est possible que ce dernier ait d'autres droits pouvant varier d'une province à l'autre.

Pour obtenir de plus amples renseignements sur cette garantie limitée, contactez le magasin NAPA Pièce d'auto ou le Centre de distribution NAPA de votre localité, ou communiquez avec le Groupe d'assistance sur les produits NAPA Echlin, 37-18 Northern Boulevard, Long Island City, NY 11101-1616, 1 800 732-4832.

SISTEMAS DE ENCENDIDO Y COMBUSTIBLE NAPA ECHLIN GARANTÍA LIMITADA

Su producto nuevo NAPA Echlin tiene una garantía extendida a usted, el cliente original, que certifica que el producto está libre de defectos de material y mano de obra (según lo determinado exclusivamente por NAPA Echlin) por un (1) año a partir de la fecha de instalación, sujeto a las limitaciones indicadas a continuación. NAPA Echlin reparará o reemplazará el producto NAPA Echlin si se comprueba la presencia de un defecto bajo uso y servicio normal. El producto NAPA Echlin deberá enviarse con porte de correo prepago o entregarse a una tienda NAPA participante en los Estados Unidos. Es posible que se requiera el comprobante fechado de venta al cliente original. Los módulos NAPA Echlin tienen una garantía de 5 años/80 000 km.

Esta garantía no incluye la mano de obra ni cubre el costo de ningún otro componente o mano de obra que se requieran para restaurar el vehículo motorizado a su condición de operación apropiada.

Esta garantía no se aplica a los productos NAPA Echlin que hayan sido: 1) alterados; 2) instalados incorrectamente, mantenidos o reparados o instalados en otro motor o vehículo motorizado; 3) dañados por accidente, negligencia o uso incorrecto; o 4) utilizados en vehículos comerciales, de flota, de servicio pesado, de todo terreno, de uso público o gubernamental.

TODAS LAS GARANTÍAS IMPLÍCITAS, INCLUSIVE LAS GARANTÍAS DE COMERCIABILIDAD E IDONEIDAD PARA PROPÓSITOS PARTICULARES, QUEDAN EXCLUIDAS DESPUÉS DE UN (1) AÑO. NAPA ECHLIN NO SERÁ RESPONSABLE POR LESIONES PERSONALES, DAÑOS MATERIALES NI DAÑOS INCIDENTALES O CONSECUENTES QUE SURJAN DIRECTA O INDIRECTAMENTE DEL USO DE ESTE PRODUCTO, INDEPENDIENTEMENTE DEL HECHO DE QUE DICHAS LESIONES, DAÑOS MATERIALES U OTROS DAÑOS INCIDENTALES O CONSECUENTES PROVENGAN DIRECTA O INDIRECTAMENTE DE UN DEFECTO DE MATERIAL Y/O MANO DE OBRA REAL O PRESUNTO.

Algunos estados no permiten limitaciones referentes a la duración de una garantía implícita, o referentes a la exclusión de limitación de daños incidentales o consecuentes, por lo tanto, las limitaciones o exclusiones indicadas anteriormente pueden no aplicarse en su caso. Esta garantía le otorga derechos legales específicos. Usted también puede tener otros derechos que varían de un estado a otro.

Para obtener más información respecto a esta Garantía Limitada, comuníquese con la sucursal local de NAPA Auto Parts Store o NAPA Distribution Center, o con NAPA Echlin, 37-18 Northern Boulevard, Long Island City, N.Y. 11101-1616, Attention Product Assistance Group, 1-800-732-4832.

**FOR CATALOG ASSISTANCE DIAL — 1-800-732-4832
POUR L'ASSISTANCE CATALOGUE, COMPOSER LE — 1 800 732-4832
PARA AYUDA CON EL CATÁLOGO MARQUE EL — 1-800-732-4832**



INDEX

Weatherly #512
NAUP-13
May 2013
Supersedes Catalog NAUP-05

ELECTRONIC DISTRIBUTORS

AMERICAN MOTORS	1
AUDI-VOLKSWAGEN	1
AUTOLITE-PRESTOLITE	2-3
BOSCH	3-7
CHRYSLER (ALSO SEE MITSUBISHI)	7-11
DAIHATSU	11
DELCO REMY	11-30
DUCELLIER	30
FIAT	30
FORD-MOTORCRAFT	30-44
HITACHI	44-45
HONDA	46-48
HYUNDAI	48
I.H.C.	49
ISUZU	50
LUCAS	50
MARELLI	50
MAZDA	51-53
MITSUBISHI	53-57
NIPPONDENSO	57
NISSAN-DATSUN	57-64
PEUGEOT	64
PORSCHE	64
STERLING	64
SUZUKI	64
TEC	64-65
TOYOTA	65-66
VOLVO	66
YUGO	67

CONTACT CONTROLLED DISTRIBUTORS

AMERICAN MOTORS	68
AUDI-VOLKSWAGEN	68
AUTOLITE-PRESTOLITE	68-87
BOSCH	88-94
CHRYSLER (ALSO SEE MITSUBISHI)	94-103
DELCO REMY	103-130
DUCELLIER	130
FIAT	130-131
FORD-MOTORCRAFT	131-150
HOLLEY	150-157
HONDA	157
I.H.C.	157-159
LUCAS	160-168
MALLORY	168-174
MARELLI	174-175
MAZDA	175-176
MITSUBISHI	176-177
NISSAN-DATSUN	177-179
OMC (OUTBOARD MARINE CORP.)	179
PORSCHE	179
RENAULT	180
SAAB	180
SEVELIER	180
SIMCA	181

(continued on next column)

CONTACT CONTROLLED DISTRIBUTORS (Cont'd)

SUBARU	181
TOYOTA	181-182
VOLVO	183

ALTERNATORS

AMERICAN MOTORS	184
AUDI-VOLKSWAGEN	184-185
AUTOLITE-PRESTOLITE	185-190
BMW	190
BOSCH	191-193
CHRYSLER (ALSO SEE MITSUBISHI)	193-196
DAIHATSU	196
DELCO REMY	196-219
FORD-MOTORCRAFT	219-229
HITACHI	229
HONDA	229
ISUZU	230
LUCAS	230
MAZDA	230-231
MITSUBISHI	231-233
MOTOROLA	234-235
NISSAN-DATSUN	235-236
PARIS-RHONE	236
RENAULT	237
SAAB	237
SUBARU	237
SUZUKI	237
TOYOTA	237-239
VOLVO	239

GENERATORS

AMERICAN MOTORS	240
AUTOLITE-PRESTOLITE	240-255
BOSCH	256
CHRYSLER	256-260
DELCO REMY	260-287
FORD-MOTORCRAFT	287-290
LUCAS	291

STARTERS

AMERICAN MOTORS	292
AUDI-VOLKSWAGEN	292-293
AUTOLITE-PRESTOLITE	293-308
BMW	308
BOSCH	308-310
CHRYSLER (ALSO SEE MITSUBISHI)	310-312
DELCO REMY	312-378
FORD-MOTORCRAFT	378-384
HITACHI	384
HONDA	384
I.H.C.	385
ISUZU	385
LUCAS	385-386
MAZDA	386-387
MITSUBA	387

(continued on next page)



STARTERS (Cont'd)

MITSUBISHI	387-389
NIPPONDENSO	389
NISSAN-DATSUN	389-391
OMC (OUTBOARD MARINE CORP.)	391
SAAB	391
SUBARU	391
SUZUKI	391
TOYOTA	392
VOLVO	392
YUGO	392

AMERICAN MOTORS

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor
3230443	TP40	MP700	FA157	FA102	IC21	—	—
3231915	TP40	MP712	FA158	FA104	IC21	—	—
3232434	TP40	MP712	FA158	FA104	IC21	—	—
3233959	TP40	MP700	FA157	FA102	IC21	—	—
3234693	TP40	MP700	FA157	FA102	IC21	—	—
3235141	TP40	MP712	FA158	FA104	IC21	—	—
3237200	TP40	MP712	FA158	FA104	IC21	—	—
3241334	TP40	MP712	FA158	FA104	IC21	—	—
3242409	TP28	MP712	FA158	FA104	IC21	VC2042	MO36
3242410	TP28	MP712	FA158	FA104	IC21	—	MO36
3242700	TP28	MP840	FA155	FA135	IC21	—	MO36
8130961	TP45	MP107	RR173	RR197	IC19	—	RR233
8130962	TP45	MP107	RR173	RR197	IC19	—	RR233
8133514	TP45	MP107	RR173	RR197	IC19	—	RR233

AUDI-VOLKSWAGEN

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
021905205AE	—	—	—	EP326	EP319
023905205B	—	—	—	EP572	EP578
025905205AC	—	—	—	EP572	EP327
025905205D	TP140	MP306	—	EP765	EP274
025905205K	TP140	MP306	—	EP765	EP852
025905205M	—	—	—	EP572	EP852
026905205AH	TP140	—	—	EP765	EP852
026905205D	TP140	MP306	—	EP765	EP274
026905205F	TP140	—	—	EP765	EP852
026905205L	TP140	MP306	—	EP765	EP274
026905205S	TP140 ¹⁰	—	—	EP572	EP852
026905206B	TP140	—	—	EP765	EP852
027905205	TP140	—	—	EP572	EP852
027905205A	TP140	—	—	EP572	EP852
027905205F	TP140	—	—	EP572	EP852
027905205P	TP140	—	—	EP572 ⁷	EP852
027905205Q	—	—	—	EP765	EP852
034905205E	TP140	—	—	—	EP578
034905205F	—	—	—	EP765	EP578
034905205H	TP140	—	—	EP765	EP578
034905205J	TP140	—	—	EP765	EP578
035905205AE	TP140	—	—	EP765	EP534
035905205AJ	TP140	—	—	EP765	EP534
035905205AM	TP140	—	—	EP765	EP534
035905205AZ	TP140	—	—	EP765	EP534
035905205B	—	MP300	—	—	EP534
035905205E	—	MP300	—	—	EP534
035905205G	—	MP300	—	—	EP534
035905205H	—	MP306	—	EP765	EP534
035905205J	TP140	MP306	—	EP765	EP534
035905205L	TP140	MP306	—	EP765	EP534
035905206A	TP140	MP306	—	EP765	EP534
035905206AF	—	—	—	—	EP578
035905206D	TP140	MP306	—	EP765	EP534
035905206J	—	MP306	—	EP765	EP534
035905206L	TP140	—	—	EP765	EP534
035905206R	TP140	MP306	—	EP765	EP534
037905205	TP140	—	—	EP572	EP852
037905205F	—	—	—	EP572	EP327
037905205G	—	—	—	EP572	EP327
037905205K	—	—	—	EP572	EP327
037905205L	—	—	—	EP572	EP327
039905205C	TP140	MP306	—	EP765	EP274
049905205D	TP140	MP306	—	EP765	EP274
049905205Q	TP140	MP306	—	EP765	EP274
049905205R	TP140	MP306	—	EP765	EP274
049905206B	TP140	MP306	—	EP765	EP274
049905206D	TP140	MP306	—	EP765	EP274
049905206F	TP140	MP306	—	EP765	EP274
049905206G	TP140	MP306	—	EP765	EP274
051905205A	—	—	—	EP572	EP852
051905205B	—	—	EP572	—	—
053905205A	—	—	—	EP572	EP852
055905205AA	TP140	MP306	—	EP765	EP274
055905206B	TP140	MP306	—	EP765	EP274
077905206E	—	—	—	—	EP882
175905205B	TP140	—	—	EP765	EP274
175905206A	TP140	—	—	EP765	EP274

(continued on next column)

⁷ Glued on rotor ¹⁰ Physical comparison is necessary or check application guide

AUTOLITE-PRESTOLITE

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
IDD4101A	—	—	—	AL150	AL149	—
IDD4102	—	—	—	AL134	AL133	—
IDD4103	—	—	—	AL134	AL133	—
IDD4104	—	—	—	AL150	AL165	—
IDD4105	—	—	—	AL150	AL155	—
IDD4106	—	—	—	AL134	AL133	—
IDD4107	—	—	—	AL150	—	—
IDD4201	—	—	—	AL62	AL63	—
IDD7001	—	—	—	AL125	AL168	—
IDH7001	—	MP804	MP800	AL125	—	—
IDH7001S	—	MP804	MP800	AL125	—	—
IDH7002	—	MP804	MP800	AL125	—	—
IDH7002S	—	MP804	MP800	AL125	—	—
IDH7003	—	MP804	MP800	AL125	—	—
IDH7003A	—	MP804	MP800	—	—	—
IDH7003AS	—	MP804	MP800	AL125	—	—
IDH7003S	—	MP804	MP800	AL125	—	—
IDJ4001	—	—	—	AL125	AL129	—
IDJ4001A	TP75	—	—	AL125	AL129	—
IDJ4001B	TP75	—	—	AL125	AL129	—
IDJ4001C	TP75	—	—	AL125	AL129	—
IDJ4001E	TP75	—	—	AL125	AL129	—
IDJ4001F	TP75	—	—	AL125	AL129	—
IDJ4001G	TP75	—	—	AL125	AL129	—
IDJ4001H	TP75	—	—	AL125	AL129	—
IDJ4001J	TP75	—	—	AL125	AL129	—
IDJ4001K	TP75	—	—	AL125	AL129	—
IDJ4001N	TP75	—	—	AL125	AL129	—
IDJ4002B	TP75	—	TW100	AL125	MO40	—
IDJ4002C	TP75	—	TW100	AL125	MO40	—
IDJ4002E	TP75	—	TW100	AL125	MO40	—
IDJ4002F	TP75	—	TW100	AL125	MO40	—
IDJ4002G	TP75	—	TW100	AL160	MO40	—
IDJ4005	TP85	—	—	AL150	AL165	—
IDJ4005A	TP85	—	—	AL150	AL165	—
IDJ4005B	TP85	—	—	AL150	AL165	—
IDJ4006	TP85	—	—	AL150	AL165	—
IDJ4007	TP85	—	—	AL150	AL165	—
IDJ4008	TP85	—	—	AL150	AL165	—
IDJ4010	TP85	—	—	AL150	AL165	—
IDJ4011	TP85	—	—	AL160	MO40	—
IDJ4012	TP85	—	—	AL150	AL149	—
IDJ4013	TP85	—	—	AL150	—	—
IDJ4014	TP85	—	—	AL150	AL142	—
IDJ4015	TP85	—	—	AL150	AL165	—
IDN400A	—	—	—	AL163	AL162	—
IDN400B	—	—	—	AL163	AL162	—
IDN4001	—	—	—	AL163	AL161	—

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
IDN4001A	—	—	—	AL163	AL161	—
IDN4001B	—	—	—	AL163	AL161	—
IDN4001C	—	—	—	AL163	AL161	—
IDN4002	—	—	—	AL163	AL162	—
IDN4002A	—	—	—	AL163	AL162	—
IDN4002AB	—	—	—	AL163	AL162	—
IDN4002B	—	—	—	AL163	AL162	—
IDN4002G	—	—	—	AL163	AL162	—
IDN4002L	—	—	—	AL163	AL162	—
IDN4002R	—	—	—	AL163	AL162	—
IDN4002U	—	—	—	AL163	AL162	—
IDN4002W	—	—	—	AL163	AL162	—
IDN4002XS	—	—	—	AL163	AL162	—
IDN4003	—	—	—	AL163	AL162	—
IDN4003A	—	—	—	AL163	AL162	—
IDN4003B	—	—	—	AL163	AL162	—
IDN4006	—	—	—	AL163	AL162	—
IDN4007	—	—	—	AL163	AL162	—
IDN4009	—	—	—	AL163	AL161	—
IDN4009A	—	—	—	AL163	AL161	—
IDN4010	—	—	—	AL163	AL161	—
IDN4011	—	—	—	AL163	AL162	—
IDN4012	—	—	—	AL163	AL161	—
IDN4201	TP85	—	—	AL163	AL161	—
IDN4201A	TP85	—	—	AL163	AL161	—
IDN4202	TP85	—	—	AL163	AL162	—
IDN4202A	TP85	—	—	AL163	AL162	—
IDN4202B	TP85	—	—	AL163	AL162	—
IDN4202C	TP85	—	—	AL163	AL162	—
IDN4202D	TP85	—	—	AL163	AL162	—
IDN4202E	TP85	—	—	AL163	AL162	—
IDN4202G	TP85	—	—	AL163	AL162	—
IDN4202H	TP85	—	—	AL163	AL162	—
IDN4202J	TP85	—	—	AL163	AL162	—
IDN4203	TP85	—	—	AL163	AL162	—
IDU4403	—	—	—	—	AL165	—
IDU4403A	—	—	—	—	AL165	—
IDU4403B	—	—	—	AL150	AL165	—
IDU4404	—	—	—	AL150	AL165	—
IDU4404A	—	—	—	AL150	AL165	—
IDU4406	—	—	—	AL150	AL165	—
IDU4406A	—	—	—	AL150	AL165	—
IDU4407	—	—	—	—	AL165	—
IDU4408	—	—	—	AL150	AL165	—
IDU4409	—	—	—	—	AL165	—
IDU4602	—	—	—	AL150	AL142	—
IDU4605	—	—	—	—	AL142	—
IDU7801	—	—	—	AL182	AL171	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
IDU7801A		—	—	AL182	AL171	—

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
IDU7801B		—	—	AL182	AL171	—

(continued on next column)

BOSCH

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Ign Coil	Vac Control
021905205AF		—	—	—	EP123	EP319	—
025905205AG		TP140	—	—	EP572	EP327	—
050905205AH		—	—	—	EP572	EP327	—
077905205E		—	—	—	EP412	EP882	—
0001208036		—	MP712	—	—	—	—
0231170284		—	—	—	EP278	—	—
0231176024		—	—	—	EP278	—	—
0231178087		—	—	—	EP278	—	—
0231402001		—	—	—	—	EP442	—
0231522009		—	—	—	EP765	EP578	—
0231522015		—	—	—	EP765	EP578	—
0237002002		TP140	MP300	—	EP278	EP274	—
0237002003		TP140	MP300	—	EP278	EP274	—
0237002007		TP140	MP300	—	EP278	EP274	—
0237002008		TP140	MP300	—	EP278	EP274	—
0237002009		TP140	MP300	—	EP278	EP274	—
0237002020		—	MP300	—	EP278	EP471	—
0237002021		—	MP300	—	EP278	EP274	—
0237002023		—	MP307	—	EP278	EP274	—
0237002024		—	—	—	EP541	EP850	—
0237002026		—	MP307	—	EP541	EP274	—
0237002035		—	MP300	—	EP278	EP274	—
0237002038		TP140	MP300	—	EP278	EP274	—
0237002039		TP140	MP300	—	EP278	EP274	—
0237002041		—	MP300	—	EP278	EP471	—
0237002049		TP140	MP307	—	—	EP850	—
0237002050		—	MP300	—	EP278	EP471	—
0237002064		TP45	—	—	EP143	EP274	—
0237002080		TP140	MP307	—	EP541	EP850	—
0237002094		TP104	—	MP320	EP541	EP735	—
0237002096		TP140	MP307	—	EP541	EP274	—
0237002098		TP104	—	MP320	EP541	EP735	—
0237002113		—	MP300	—	—	EP274	—
0237003001		—	MP300	—	EP541	EP274	—
0237003003		TP140	MP300	—	EP278	EP274	—
0237003008		—	MP300	—	EP278	EP274	—
0237003009		—	MP300	—	EP541	EP274	—
0237003013		—	—	—	EP278	EP274	—
0237003014		—	MP307	—	EP278	EP274	—
0237003018		—	MP300	—	EP278	EP274	—
0237003024		TP140	MP300	—	EP278	EP274	—

(continued on next page)

BOSCH (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Ign Coil	Vac Control
0237004001	—	MP300	—	EP278	EP534	—	—
0237004005	—	MP300	—	EP278	EP534	—	—
0237009001	—	MP307	—	EP477	EP480	—	—
0237009002	—	MP307	—	EP477	EP480	—	—
0237009004	—	MP307	—	EP477	EP480	—	—
0237009008	—	MP307	—	EP477	EP274	—	—
0237009052	—	—	—	EP477	EP274	—	—
0237012001	—	MP300	—	EP278	EP534	—	—
0237013001	—	MP307	—	EP541	EP274	—	—
0237020067	TP140	—	—	EP541	EP274	—	—
0237020068	—	—	—	EP541	EP274	—	—
0237020071	TP140	—	—	EP541	EP274	—	—
0237020087	TP140	—	—	EP541	EP274	—	—
0237020089	TP140	MP328	—	EP541	EP274	—	—
0237020105	TP140	—	—	EP541	EP274	—	—
0237020109	TP140	MP328	—	EP541	EP850	—	—
0237020111	TP140	—	—	EP541	EP850	—	—
0237020146	TP140	—	—	EP541	EP850	—	—
0237020148	TP140	—	—	EP541	EP850	—	—
0237021014	—	MP310 ²⁹	MP310 ²⁹	—	EP274	—	—
0237021045	TP198	MP322	—	EP571	EP274	—	—
0237021051	TP198	—	—	EP571	EP274	—	—
0237022009	TP140	MP306	—	EP278	EP274	—	—
0237022013	TP140	—	—	EP278	EP274	—	—
0237022015	TP140	MP306	—	EP541	EP274	—	—
0237022017	TP140	—	—	—	EP274	—	—
0237022018	—	—	—	—	EP274	—	—
0237022019	TP140	—	—	EP541	EP274	—	—
0237022021	TP140	—	—	EP541	EP274	—	—
0237022025	TP140	—	—	EP541	EP274	—	—
0237022035	TP140	—	—	EP541	EP274	—	—
0237022045	TP140	—	—	EP541	EP850	—	—
0237026003	—	MP310 ²⁹	MP310 ²⁹	—	EP274	—	—
0237026006	—	MP310 ²⁹	MP310 ²⁹	—	EP274	—	—
0237027001	TP140	MP306	—	—	EP534	—	—
0237027002	—	—	—	—	EP534	—	—
0237027003	TP140	MP306	—	EP541	EP534	—	—
0237027004	TP140	MP306	—	EP765	EP534	—	—
0237027007	—	—	—	EP541	EP534	—	—
0237027009	TP140	MP306	—	EP541	EP534	—	—
0237027011	TP140	MP306	—	EP541	EP534	—	—
0237027015	—	—	—	EP541	EP534	—	—
0237027017	—	—	—	EP541	EP534	—	—
0237028003	—	—	—	EP541	EP534	—	—
0237028005	TP140	—	—	EP541	EP534	—	—
0237028007	TP140	—	—	EP541	EP534	—	—
0237030001	TP140	MP306	—	EP541	EP534	—	—
0237030003	TP140	MP328	—	EP541	EP534	—	—
0237030005	TP140	MP328	—	EP541	EP534	—	—

(continued on next page)

²⁹ Magnetic pick-up & reluctor set

BOSCH (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Ign Coil	Vac Control
0237030009	TP140	MP328	—	—	—	—	—
0237030020	TP140	MP328	—	EP541	EP578	—	—
0237030021	—	MP328	—	EP541	EP578	—	—
0237031028	—	—	—	EP278	EP850	—	—
0237032001	—	—	—	EP541	EP274	—	—
0237300001	—	MP304	—	EP407	EP406	—	—
0237301001	—	MP304	—	EP278	EP406	—	—
0237301002	—	—	—	—	EP406	—	—
0237301005	—	MP304	—	—	EP406	—	—
0237301008	—	—	—	—	EP406	—	—
0237302009	—	MP304	—	—	EP406	—	—
0237302034	—	—	—	EP407	EP406	—	—
0237302045	—	—	—	EP407	EP406	—	—
0237304001	—	MP304	—	—	EP438	—	—
0237304002	TP199	MP304	—	EP407	EP406	—	—
0237304003	—	MP304	—	EP407	EP438	—	—
0237304005	—	MP304	—	EP407	EP406	—	—
0237304006	TP199	MP304	—	EP407	EP406	—	—
0237304015	TP199	MP304	—	EP407	EP406	—	—
0237304016	—	MP304	—	EP407	EP406	—	—
0237304018	—	MP304	MP320	—	EP580	—	—
0237304302	—	—	—	EP407	EP406	—	—
0237306001	—	MP304	—	EP407	EP406	—	—
0237306011	—	MP304	—	EP407	EP406	—	—
0237306016	—	MP304	—	EP407	EP406	—	—
0237322001	—	—	—	EP407	EP406	—	—
0237332001	—	MP314	MP314	EP407	EP406	—	—
0237401006	—	MP304	MP320	EP548	EP739	—	—
0237401007	—	MP304	MP320	EP548	EP739	—	—
0237401010	—	MP304	MP320	EP760	EP739	—	—
0237401012	—	MP304	MP320	EP760	EP739	—	—
0237401018	—	—	MP320	EP548	EP739	—	—
0237401019	—	MP304	—	EP548	EP739	—	—
0237402004	—	MP304	—	EP548	EP530	—	—
0237402008	—	MP304	—	EP548	EP530	—	—
0237402009	—	MP304	—	EP548	EP530	—	—
0237402013	—	—	—	EP548	EP530	—	—
0237402015	—	MP304	—	EP548	EP530	—	—
0237402016	—	MP304	—	EP548	EP530	—	—
0237402017	—	MP304	—	EP548	EP530	—	—
0237402018	—	MP304	—	EP760	EP530	—	—
0237402019	—	MP304	MP320	EP760	EP530	—	—
0237402020	—	MP304	—	EP760	EP530	—	—
0237402023	—	MP304	—	EP548	EP530	—	—
0237404004	—	—	—	—	EP739	—	—
0237405001	—	MP304	MP320	EP548	EP739	—	—
0237405002	—	MP304	MP320	EP548	EP739	—	—
0237405010	—	MP304	MP320	EP548	EP739	—	—
0237405011	—	MP304	—	EP548	EP739	—	—

(continued on next page)

BOSCH (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Ign Coil	Vac Control
0237405012	—	—	—	EP548	EP739	—	—
0237405020	—	MP304	MP320	EP548	EP739	—	—
0237405021	—	MP304	MP320	EP548	EP739	—	—
0237405022	—	MP304	—	EP548	EP739	—	—
0237405023	—	MP304	MP320	EP548	EP739	—	—
0237406001	—	MP304	—	EP548	EP530	—	—
0237406004	—	MP304	—	EP548	EP530	—	—
0237406011	—	—	—	EP548	EP530	—	—
0237500001	—	—	—	EP541	EP274	—	—
0237500002	—	—	—	EP541	EP274	—	—
0237500004	—	—	—	EP585	EP584	—	—
0237500006	TP109	—	—	—	—	—	—
0237501001	—	—	—	EP143	EP274	—	—
0237501002	—	—	—	—	EP274	—	—
0237501006	—	—	—	EP572	EP274	—	—
0237501010	TP109	—	—	EP572 ⁷	EP274	—	—
0237502001	TP109	—	—	EP763	EP754	—	—
0237502002	—	—	—	EP763	EP553	—	—
0237502003	TP109	MP315	—	EP572	EP274	—	—
0237503003	—	MP336	—	—	EP274	—	—
0237503004	TP109	—	—	EP372	EP329	—	—
0237503010	—	—	—	EP372	EP580	—	—
0237505001	—	—	—	EP407	EP329	—	—
0237505003	—	—	—	EP788	EP789	—	—
0237505009	—	—	—	EP788	EP789	—	—
0237505011	—	—	—	EP372	EP580	—	—
0237506003	—	—	—	—	EP274	—	—
0237506004	—	MP309 ²⁹	MP309 ²⁹	EP541	EP274	—	—
0237506006	TP198	MP310	—	EP572	EP274	—	—
0237506009	—	—	—	—	EP274	—	—
0237506011	—	—	—	—	EP274	—	—
0237506013	TP109	—	—	—	EP274	—	—
0237507001	—	—	—	EP541	EP274	—	—
0237507006	TP198	—	—	EP572 ⁷	EP274	—	—
0237507007	—	—	—	—	EP274	—	—
0237507008	—	—	—	EP572 ⁷	EP274	—	—
0237520004	—	—	—	EP765	EP850	—	—
0237520005	—	—	—	EP765	EP850	—	—
0237520007	—	—	—	EP765	EP850	—	—
0237520010	TP140	MP316	—	EP572	EP852	—	—
0237520011	—	—	—	EP765	EP578	—	—
0237520013	TP140	—	—	EP572	EP852	—	—
0237520015	—	—	—	EP765	EP578	—	—
0237520024	TP140	—	—	EP572	EP327	—	—
0237520026	TP140	—	—	EP572	EP852	—	—
0237520027	—	—	—	EP572 ⁷	EP852	—	—
0237520034	—	—	—	EP326	EP319	—	—
0237520038	—	—	—	EP572	EP327	—	—
0237520044	TP140	—	—	EP572	EP327	—	—

(continued on next page)

⁷ Glued on rotor ²⁹ Magnetic pick-up & reluctor set

BOSCH (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Ign Coil	Vac Control
0237520046	—	—	—	EP572 ⁷	EP327	—	—
0237520050	TP140	—	—	EP572	EP327	—	—
0237520052	—	—	—	EP123	EP319	—	—
0237520054	—	—	—	EP572	EP508	—	—
0237520065	—	—	—	EP572	EP327	—	—
0237520146	TP140	MP311 ²⁹	MP311 ²⁹	EP765	EP852	—	—
0237521006	—	—	—	EP412	EP882	—	—
0237521010	TP140	MP316	—	EP572 ⁷	EP852	—	—
0237521016	—	—	—	—	EP882	—	—
0237521026	TP140	—	—	EP572 ⁷	EP852	—	—
0237521027	TP140	MP316	—	EP572	EP850	—	—
0237521033	—	—	—	EP572 ⁷	EP327	—	—
0237521046	—	—	—	EP572 ⁷	EP327	—	—
0237522009	—	—	—	EP572	EP578	—	—
0237522011	—	—	—	EP765	EP578	—	—
0237522013	—	—	—	EP572 ⁷	EP578	—	—
0237522015	—	—	—	EP572	EP578	—	—
0237522019	—	—	—	EP572 ⁷	EP578	—	—
0237522021	—	—	—	EP765	EP578	—	—
0237523001	—	—	—	EP765	EP835	—	—
0237523003	TP109	—	—	EP572	EP274	—	—
0237523004	—	—	—	EP572	EP835	—	—
0237523006	—	—	—	EP412	EP882	—	—
0237523016	—	—	—	—	EP882	—	—

CHRYSLER (ALSO SEE MITSUBISHI)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
MD001116	—	—	—	EP342	EP706	—
MD009152	—	—	—	EP342	EP706	—
MD012145	—	—	—	EP658	EP675	—
MD013792	MP818	—	—	EP658	EP675	—
MD013793	MP818	—	—	EP658	EP675	—
MD013880	—	—	—	EP342	EP706	—
MD018450	—	—	—	EP658	EP675	—
MD027696	—	—	—	EP658	EP675	—
MD027697	—	—	—	EP658	EP675	—
MD034140	—	—	—	EP658	EP675	—
MD041682	—	—	—	EP658	EP675	—
MD060263	—	—	—	EP342	EP706	—
MD060264	—	—	—	EP658	EP675	—
MD060265	—	—	—	EP658	EP675	—
MD060266	—	—	—	EP342	EP706	—
MD060269	—	—	—	EP658	EP675	—
MD061593	—	—	—	EP658	EP675	—
MD066251	MP818	—	—	EP658	EP675	—
MD067134	MP818	—	—	EP658	EP675	—
MD070472	—	—	—	EP342	EP706	—
MD073071	—	—	—	EP342	EP706	—
MD073072	—	—	—	EP342	EP706	—
MD073073	—	—	—	EP342	EP706	—
MD073074	—	—	—	EP342	EP706	—
MD073075	—	—	—	EP342	EP706	—
MD073445	—	—	—	EP342	EP706	—
MD073485	—	—	—	EP342	EP706	—
MD073496	—	—	—	EP342	EP706	—
MD073527	—	—	—	EP342	EP706	—
MD073529	—	—	—	EP342	EP706	—
MD074647	—	—	—	EP342	EP706	—
MD074649	—	—	—	EP342	EP706	—
MD075631	—	—	—	EP342	EP706	—
MD084036	—	—	—	—	EP706	—
MD084039	—	—	—	EP342	EP706	—
MD084042	—	—	—	—	EP706	—
MD088687	—	—	—	EP342	EP706	—
MD088688	—	—	—	EP342	EP706	—
MD091163	—	—	—	EP342	EP706	—
MD093766	—	—	—	EP658	EP675	—

(continued on next column)

(continued on next page)

⁷ Glued on rotor ²⁹ Magnetic pick-up & reluctor set

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
MD094026	—	—	—	—	EP706	—
MD098230	—	MP818	—	EP658	EP675	—
MD098383	—	—	—	EP342	EP706	—
MD098384	—	—	—	EP342	EP706	—
3374868	TP51 ⁴	MP804	—	MO13	MO20	VC3032
3656278	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656279	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656335	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656336	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656338	TP51 ⁴	MP804	MP800	MO13	MO20	VC3028
3656339	TP51 ⁴	MP804	MP800	MO13	MO20	VC3028
3656341	TP51 ⁴	MP804	MP800	MO13	MO20	VC3028
3656342	TP51 ⁴	MP804	MP800	MO13	MO20	VC3028
3656347	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656348	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656353	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656354	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656429	TP51 ⁴	MP804	MP800	MO13	MO20	VC3027
3656430	TP51 ⁴	MP804	MP800	MO13	MO20	VC3027
3656435	TP51 ⁴	MP804	MP800	MO13	MO20	VC3027
3656436	TP51 ⁴	MP804	MP800	MO13	MO20	VC3027
3656587	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656588	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656596	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656597	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656667	TP51 ⁴	MP804	MP800	MO13	MO20	VC3027
3656668	TP51 ⁴	MP804	MP800	MO13	MO20	VC3027
3656672	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656673	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656678	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656679	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656685	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656686	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656763	TP51 ⁴	MP804	MP800	MO13	MO20	VC3031
3656764	TP51 ⁴	MP804	MP800	MO13	MO20	VC3031
3656771	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656772	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656780	—	MP804	—	—	—	VC3031
3656781	TP51 ⁴	MP804	MP800	MO13	MO20	VC3031
3656791	TP51 ⁴	MP804	MP800	MO13	MO20	VC3028
3656792	TP51 ⁴	MP804	MP800	MO13	MO20	VC3028
3656802	TP51 ⁴	MP804	MP800	MO13	MO20	VC3028
3656803	TP51 ⁴	MP804	MP800	MO13	MO20	VC3028
3656830	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656831	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656839	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656840	TP51 ⁴	MP804	MP800	MO13	MO20	—
3656859	—	MP805	MP802	MO13	MO40	—

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
3656861	—	MP805	MP802	MO13	MO40	—
3656872	—	—	MP800	FA8000	FA98	—
3656874	—	—	MP800	FA8000	FA98	—
3656876	—	—	MP800	FA8000	FA98	—
3656877	—	—	MP800	FA8000	FA98	—
3656878	—	—	MP800	FA8000	FA98	—
3656879	—	—	MP800	FA8000	FA98	—
3656881	—	—	MP800	FA8000	FA98	—
3656882	—	—	MP800	FA8000	FA98	—
3755037	—	MP805	MP802	MO13	MO40	—
3755038	—	MP805	MP802	MO13	MO40	—
3755042	—	MP805	MP802	MO13	MO40	VC3029
3755043	—	MP805	MP802	MO13	MO40	VC3029
3755044	—	MP805	MP802	MO13	MO40	—
3755045	—	MP805	MP802	MO13	MO40	—
3755053	—	MP805	MP802	MO13	MO40	—
3755054	—	MP805	MP802	MO13	MO40	—
3755056	—	MP805	MP802	MO13	MO40	—
3755057	—	MP805	MP802	MO13	MO40	—
3755062	—	MP805	MP802	MO13	MO40	—
3755063	—	MP805	MP802	MO13	MO40	—
3755071	—	MP805	MP802	MO13	MO40	—
3755072	—	MP805	MP802	MO13	MO40	—
3755075	—	MP805	MP802	MO13	MO40	—
3755076	—	MP805	MP802	MO13	MO40	—
3755149	TP51 ⁴	MP804	MP800	MO13	MO20	—
3755150	TP51 ⁴	MP804	MP800	MO13	MO20	—
3755157	TP51 ⁴	MP804	MP800	MO13	MO20	VC3028
3755158	TP51 ⁴	MP804	MP800	MO13	MO20	VC3028
3755160	TP51 ⁴	MP804	MP800	MO13	MO20	VC3027
3755161	TP51 ⁴	MP804	MP800	MO13	MO20	VC3027
3755201	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3755202	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3755308	TP51 ⁴	MP804	MP800	MO13	MO20	—
3755310	TP51 ⁴	MP804	MP800	MO13	MO20	—
3755336	TP51 ⁴	MP804	MP800	MO13	MO20	VC3031
3755337	TP51 ⁴	MP804	MP800	MO13	MO20	VC3031
3755365	TP51 ⁴	MP804	MP800	MO13	MO20	VC3031
3755366	TP51 ⁴	MP804	MP800	MO13	MO20	VC3031
3755467	—	MP805	MP802	MO13	MO40	VC3030
3755468	—	MP805	MP802	MO13	MO40	VC3030
3755470	—	MP805	MP802	MO13	MO40	VC3029
3755471	—	MP805	MP802	MO13	MO40	VC3029
3755472	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3755473	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3755475	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3755476	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3755486	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032

(continued on next page)

⁴Fender mounted module (4 pin)

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
3755487	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3755508	TP51 ⁴	MP804	MP800	MO13	MO20	—
3755509	TP51 ⁴	MP804	MP800	MO13	MO20	—
3755512	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3755513	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3755518	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3755519	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3755520	—	—	MP800	FA8000	FA98	—
3755521	—	—	MP800	FA8000	FA98	—
3755522	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3755523	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3755681	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3755682	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3755686	TP51 ⁴	MP804	MP800	MO13	MO20	—
3755818	TP51 ⁴	MP804	MP800	MO13	MO20	—
3755820	TP51 ⁴	MP804	MP800	MO13	MO20	—
3755821	TP51 ⁴	MP804	MP800	MO13	MO20	VC3031
3755822	TP51 ⁴	MP804	MP800	MO13	MO20	VC3031
3755825	—	MP805	MP802	MO13	MO40	VC3030
3755826	—	MP805	MP802	MO13	MO40	VC3030
3755841	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3755842	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3775520	—	—	MP800	FA98	FA98	—
3775521	—	—	MP800	FA98	FA98	—
3843173	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3843174	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3874082	—	MP805	MP802	MO13	MO40	VC3029
3874083	—	MP805	MP802	MO13	MO40	VC3029
3874085	TP51 ⁴	MP805	MP802	MO13	MO40	VC3029
3874086	TP51 ⁴	MP805	MP802	MO13	MO40	VC3029
3874090	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3874091	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3874097	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3874098	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3874101	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3874102	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3874110	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3874111	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3874115	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3874116	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3874119	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3874120	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3874145	TP51 ⁴	MP804	—	MO13	MO20	VC3032
3874146	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3874173	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3874174	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3874201	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3874202	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
3874231	TP51 ⁴	MP805	MP802	MO13	MO40	—
3874232	TP51 ⁴	MP805	MP802	MO13	MO40	—
3874238	TP51 ⁴	MP804	MP800	MO13	MO20	—
3874239	TP51 ⁴	MP804	MP800	MO13	MO20	—
3874298	TP51 ⁴	MP804	MP800	MO13	MO20	—
3874299	TP51 ⁴	MP804	MP800	MO13	MO20	—
3874302	TP51 ⁴	MP804	MP800	—	MO20	VC3031
3874303	TP51 ⁴	MP804	MP800	—	MO20	VC3031
3874596	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3874597	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
3874598	—	MP805	MP802	MO13	MO40	VC3029
3874599	—	MP805	MP802	MO13	MO40	VC3029
3874714	—	MP805	MP802	MO13	MO40	VC3029
3874719	—	MP805	MP802	MO13	MO40	VC3029
3874754	TP51 ⁴	MP804	MP800	MO13	MO20	—
3874755	TP51 ⁴	MP804	MP800	MO13	MO20	—
3874786	—	—	MP800	MO13	MO20	—
3874795	—	MP805	MP802	MO13	MO40	VC3035
3874796	—	MP805	MP802	MO13	MO40	VC3035
3874848	—	—	MP800	MO13	MO20	—
3874849	—	—	MP800	MO13	MO20	—
3874858	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3874859	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3874867	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3874868	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
3874876	—	MP805	MP802	MO13	MO40	VC3034
3874877	—	MP805	MP802	MO13	MO40	VC3034
3874887	TP51 ⁴	MP804	MP800	MO13	MO20	—
3874888	TP51 ⁴	MP804	MP800	MO13	MO20	—
3874909	TP51 ⁴	MP804	MP800	MO14	MO20	VC3035
3874910	TP51 ⁴	MP804	MP800	MO14	MO20	VC3035
3874913	TP51 ⁴	MP804	MP800	MO13	MO20	—
3874914	TP51 ⁴	MP804	MP800	MO13	MO20	—
3874917	TP51 ⁴	MP804	MP800	MO13	MO20	—
3874918	TP51 ⁴	MP804	MP800	MO13	MO20	—
3874927	TP51 ⁴	MP804	MP800	MO13	MO20	—
3874929	—	MP805	—	MO13	MO40	VC3029
3874930	—	MP805	—	MO13	MO40	VC3029
3874940	—	—	MP800	MO13	MO20	—
3874941	—	—	MP800	MO13	MO20	—
4091015	—	—	MP800	MO13	MO20	—
4091017	—	—	MP800	MO13	MO20	—
4091018	—	—	MP800	MO13	MO20	—
4091019	—	—	—	MO13	MO20	—
4091020	—	—	—	MO13	MO20	—
4091021	—	—	MP800	MO13	MO20	—
4091088	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033
4091089	TP51 ⁴	MP804	MP800	MO13	MO20	VC3033

(continued on next page)

⁴Fender mounted module (4 pin)

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
4091101	—	MP805	MP802	MO13	MO40	—
4091102	—	MP805	MP802	MO13	MO40	—
4091140	—	MP811	MP800	MO13	MO20	—
4091142	—	MP811	MP800	MO13	MO20	—
4091282	TP51 ⁴	MP804	MP800	MO13	MO20	—
4091283	TP51 ⁴	MP804	MP800	MO13	MO20	—
4091490	—	MP805	MP802	MO13	MO40	—
4091491	—	MP805	MP802	MO13	MO40	—
4091549	TP51 ⁴	MP804	MP800	MO13	MO20	—
4091550	TP51 ⁴	MP804	MP800	MO13	MO20	—
4091661	TP51 ⁴	MP804	MP800	MO13	MO20	—
4091662	TP51 ⁴	MP804	MP800	MO13	MO20	—
4091709	—	MP810	MP800	MO13	MO20	—
4091710	—	MP810	MP800	MO13	MO20	—
4091711	—	MP810	MP800	MO13	MO20	—
4091712	—	MP810	MP800	MO13	MO20	—
4091821	TP51 ⁴	MP804	MP800	MO13	MO20	VC3028
4091822	TP51 ⁴	MP804	MP800	MO13	MO20	VC3028
4091902	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
4091903	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
4109140	—	MP811	MP800	MO13	MO20	—
4109142	—	MP811	MP800	MO13	MO20	—
4111487	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
4111488	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
4111501	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
4111502	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
4111782	—	MP811	MP800	MO13	MO20	—
4111783	TP51 ⁴	MP804	MP800	MO13	MO40	—
4111784	—	MP811	MP800	MO13	MO20	—
4111948	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
4111950	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
4111955	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
4145239	—	MP816	MP800	MO13	MO20	—
4145519	TP51 ⁴	MP804	MP800	MO13	MO20	—
4145602	—	—	MP800	MO13	MO20	—
4145603	—	—	MP800	MO13	MO20	—
4145604	TP51 ⁴	MP804	MP800	MO13	MO20	VC3032
4145605	—	—	MP800	MO13	MO20	VC3032
4145612	—	MP816	MP802	MO13	MO40	—
4145613	—	MP817	MP802	MO13	MO40	—
4145717	—	—	MP802	MO13	MO40	—
4145718	—	—	MP802	MO13	MO40	—
4145751	—	MP817	MP802	MO13	MO40	—
4145752	—	MP817	MP802	MO13	MO40	—
4145753	—	MP817	MP800	MO13	MO20	—
4145754	TP50	MP817	MP800	MO13	MO20	—
4145845	—	—	MP802	MO13	MO40	—
4145848	—	—	MP802	MO13	MO40	—

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
4145849	—	—	MP802	MO13	MO40	—
4145859	—	—	MP802	MO13	MO40	—
4145954	—	MP816	MP802	MO13	MO40	—
4145955	—	MP816	MP802	MO13	MO40	—
4240470	—	—	—	MO15	MO16	—
4243134	—	MP818	—	EP658	EP675	—
4243230	—	MP818	—	EP658	EP675	—
4243251	—	MP818	—	EP658	EP675	—
4243694	—	MP818	—	EP658	EP675	—
4243707	—	MP818	—	EP658	EP675	—
4243708	—	MP818	—	EP658	EP675	—
4243968	—	MP818	—	EP658	EP675	—
4289657	TP51 ⁴	MP804	MP800	MO13	MO20	—
4289658	TP51 ⁴	MP804	MP800	MO13	MO20	—
4289800	—	MP805	MP802	MO13	MO40	—
4289839	—	—	MP800	MO13	MO20	—
4289950	—	MP805	MP802	MO13	MO40	—
4289980	TP50	MP804	MP800	—	MO20	VC3032
4379070	—	MP816	MP800	MO13	MO20	VC3029
4379071	—	MP816	MP800	MO13	MO20	VC3029
4379229	—	—	—	—	MO40	—
4379230	—	—	—	—	MO40	—
4379233	—	—	MP800	—	MO20	VC3032
4723067	—	MP831	—	MO31	MO30	—
4740338	—	MP846	—	MO26	MO28	—
4740339	—	MP846	—	MO26	MO29	—
4762312	—	MP831	—	MO35	FA141	—
5206275	—	MP812	—	MO15	MO14	—
5206276	—	MP812	—	MO15	MO14	—
5206842	—	MP815	—	MO18	MO17	—
5206843	—	MP815	—	MO18	MO17	—
5206925	—	MP815	—	MO18	MO17	—
5206935	—	MP815	—	MO18	MO17	—
5206975	—	—	—	MO15	MO16	—
5213366	—	—	—	MO15	MO16	—
5213525	—	—	—	MO15	MO16	—
5213575	—	MP812	—	MO15	MO16	—
5226525	—	—	—	MO22	MO21	—
5226575	—	MP833	—	MO22	MO21	—
5227255	—	—	—	MO22	MO21	—
5227273	—	—	—	MO22	MO21	—
5227274	—	—	—	MO22	MO21	—
5227275	—	MP825	—	MO22	MO21	—
53006150	—	MP831	—	MO35	FA141	—
56027027	—	MP833	—	MO31	MO27	—
56027027AB	—	MP847	—	MO31	MO27	—
56027028	—	MP846	—	MO31	MO30	—
56027088	TP28	—	—	—	—	—

(continued on next page)

⁴Fender mounted module (4 pin)

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
56041033		—	MP847	—	MO31	MO27

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
56041034		—	MP847	—	MO31	MO30

DAIHATSU

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
1906087107000	—	—	—	EP843	EP881
1906087115000	—	—	—	EP843	EP881
1906087118000	—	—	—	EP843	EP301
1906087119000	—	—	—	EP843	EP881

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
1910087119000	—	—	—	EP843	EP881
1910087120000	—	—	—	EP843	EP881
1910087744000	—	TP210	—	RR246	EP808

DELCO REMY

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1103065	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1103073	TP45	MP102	RR173	RR171	IC18	VC1846	RR170	RR195	RR231	RR204
1103200	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103201	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103202	TP45	MP100	RR173	RR171	IC19	VC1841	—	RR195	RR233	RR204
1103203	TP45	MP100	RR173	RR171	IC19	VC1853	RR170	RR195	RR231	RR204
1103204	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1103205	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103206	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103207	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103208	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1103209	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103210	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1103211	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1103212	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1103214	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103216	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103217	TP45	MP100	RR173	RR171	IC19	VC1845	RR170	RR195	—	RR204
1103218	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1103219	TP45	MP100	RR173	RR171	IC19	VC1845	—	RR195	RR233	RR204
1103220	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR233	RR204
1103221	TP45	MP101	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103222	TP45	MP101	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103223	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103228	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1103229	TP45	MP107	RR173	RR197	IC19	—	RR170	RR195	—	RR204
1103230	TP45	MP107	RR173	RR197	IC19	—	RR170	RR195	—	RR204
1103231	TP45	MP107	RR173	RR197	IC19	—	RR170	RR195	—	RR204
1103232	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103233	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103235	TP45	MP101	RR173	RR171	IC18	VC1828	RR170	RR195	—	RR204
1103236	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103237	TP45	MP100	RR173	RR171	IC19	VC1852	RR170	RR195	RR231	RR204

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1103238	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103239	TP45	MP100	RR173	RR171	IC19	VC1843	RR170	RR195	RR231	RR204
1103240	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103241	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103242	TP45	MP100	RR173	RR171	IC19	VC1843	RR170	RR195	RR231	RR204
1103244	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103245	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1103246	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103248	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103249	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103250	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103251	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103252	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103253	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103254	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103255	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103256	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103257	TP45	MP100	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103258	TP45	MP102	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103259	TP45	MP100	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1103260	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1103262	TP45	MP101	RR173	RR171	IC18	VC1855	RR170	RR195	RR231	RR204
1103263	TP45	MP107	RR173	RR197	IC19	—	RR170	RR195	—	RR204
1103264	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1103265	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR230	RR204
1103266	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1103267	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1103268	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1103269	TP45	MP102	RR173	RR171	IC18	VC1850	RR170	RR195	—	RR204
1103271	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103272	TP45	MP102	RR173	RR171	IC18	VC1846	RR170	RR195	—	RR204
1103273	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103274	TP45	MP100	RR173	RR171	IC19	VC1853	RR170	RR195	—	RR204
1103275	TP45	MP101	RR173	RR171	IC18	VC1851	RR170	RR195	—	RR204
1103276	TP45	MP102	RR173	RR171	IC18	VC1850	RR170	RR195	—	RR204
1103277	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1103278	TP45	MP102	RR173	RR171	IC18	VC1850	RR170	RR195	—	RR204
1103279	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103281	TP45	MP100	RR173	RR171	IC19	VC1836	RR170	RR195	RR231	RR204
1103282	TP45	MP100	RR173	RR171	IC19	VC1859	RR170	RR195	RR231	RR204
1103284	TP45	MP100	RR173	RR171	IC19	VC1836	RR170	RR195	RR231	RR204
1103285	TP45	MP100	RR173	RR171	IC19	VC1703	RR170	RR195	RR231	RR204
1103286	TP45	MP100	RR173	RR171	IC19	VC1836	RR170	RR195	RR231	RR204
1103287	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103291	TP45	MP100	RR173	RR171	IC19	VC1703	RR170	RR195	RR231	RR204
1103297	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR233	RR204
1103298	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1103300	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1103301	TP45	MP100	RR173	RR171	IC19	VC1703	RR170	RR195	RR231	RR204

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1103302	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103303	TP45	MP107	RR173	RR197	IC19	—	RR170	RR195	—	RR204
1103304	TP20	MP108	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103305	TP45	MP107	RR173	RR197	IC19	—	RR170	RR195	—	RR204
1103306	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR233	RR204
1103307	TP20	MP108	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103308	TP45	MP107	RR173	RR197	IC19	—	RR170	RR195	RR231	RR204
1103309	TP45	MP107	RR173	RR197	IC18	—	RR170	RR195	—	RR204
1103310	TP45	MP102	RR173	RR197	IC18	VC1861	RR170	RR195	—	RR204
1103311	TP45	MP102	RR173	RR197	IC19	VC1861	RR170	RR195	—	RR204
1103312	TP45	MP107	RR173	RR197	IC19	—	RR170	RR195	—	RR204
1103313	TP46	MP112	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103314	TP45	MP102	RR173	RR171	IC18	VC1861	RR170	RR195	—	RR204
1103315	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103316	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103320	TP45	MP102	RR173	RR171	IC18	VC1855	RR170	RR195	RR231	RR204
1103321	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1103322	TP45	MP101	RR173	RR171	IC18	VC1847	RR170	RR195	RR231	RR204
1103323	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1103324	TP45	MP101	RR173	RR171	IC18	VC1847	RR170	RR195	RR231	RR204
1103325	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1103326	TP45	MP107	RR173	RR197	IC19	—	RR170	RR195	—	—
1103328	TP45	MP107	RR173	RR197	IC19	—	RR170	RR195	—	RR204
1103329	TP45	MP107	RR173	RR197	IC19	—	RR170	RR195	—	RR204
1103330	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103331	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1103332	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1103333	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1103334	TP45	MP100	RR173	RR171	IC19	VC1845	—	RR195	RR233	RR204
1103335	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR233	RR204
1103336	TP45	MP101	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103337	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1103338	TP45	MP100	RR173	RR171	IC19	VC1864	RR170	RR195	RR231	RR204
1103339	TP45	MP100	RR173	RR171	IC19	VC1703	RR170	RR195	RR231	RR204
1103340	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1103341	TP20	MP108	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103342	TP45	MP101	RR173	RR171	IC18	VC1851	RR170	RR195	—	RR204
1103343	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103345	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1103346	TP45	MP101	RR173	RR171	IC18	VC1847	—	RR195	RR231	RR204
1103347	TP45	MP101	RR173	RR171	IC18	VC1847	—	RR195	RR231	RR204
1103348	TP20	MP108	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103349	TP20	MP108	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103350	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103351	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR233	RR204
1103352	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1103353	TP45	MP100	RR173	RR171	IC19	VC1859	—	RR195	RR231	RR204
1103354	TP45	MP107	RR173	RR197	IC19	—	RR170	RR195	—	RR204
1103355	TP45	MP101	RR173	RR171	IC18	—	—	RR195	RR231	RR204

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1103356	TP45	MP100	RR173	RR171	IC19	VC945	—	RR195	RR231	RR204
1103357	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103358	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103359	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1103360	TP45	MP107	RR173	RR197	IC19	—	RR170	RR195	—	RR204
1103361	TP45	MP104	RR173	RR203	IC19	VC1703	—	RR205	RR234	RR204
1103362	TP45	MP104	RR173	RR203	IC19	VC1862	—	RR205	RR234	RR204
1103363	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1103364	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1103365	TP45	MP107	RR173	RR197	IC19	—	RR170	RR195	—	RR204
1103368	TP45	MP100	RR173	RR171	IC19	VC1703	—	RR195	RR231	RR204
1103369	TP45	MP100	RR173	RR171	IC19	VC1862	—	RR195	RR231	RR204
1103370	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103371	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103372	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103373	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103374	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103375	TP45	MP100	RR173	RR171	IC19	VC1703	—	RR195	RR231	RR204
1103376	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103377	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103378	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103379	TP45	MP100	RR173	RR171	IC19	VC1868	—	RR195	RR231	RR204
1103380	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103381	TP45	MP100	RR173	RR171	IC19	VC1868	—	RR195	RR231	RR204
1103382	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103383	TP45	MP100	RR173	RR171	IC19	VC1862	—	RR195	RR231	RR204
1103384	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103385	TP45	MP103	RR198	RR191	IC29	—	—	—	RR232	—
1103386	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103387	TP45	MP100	RR173	RR171	IC19	VC1703	—	RR195	RR231	RR204
1103389	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1103392	TP20	—	RR173	RR171	IC19	—	—	RR195	RR233	RR204
1103393	TP20	MP108	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103394	TP20	MP108	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103395	TP20	—	RR173	RR171	IC19	—	—	RR195	RR233	RR204
1103396	TP45	MP101	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103398	TP21	MP101	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103399	TP21	MP102	RR173	RR171	IC18	VC1861	—	RR195	RR233	RR204
1103400	TP21	MP102	RR173	RR171	IC18	—	—	RR195	RR233	RR204
1103401	TP47	MP119	RR173	RR214	IC19	—	—	RR195	RR231	RR204
1103402	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1103403	TP20	MP127	RR173	RR171	IC18	—	—	RR195	RR233	RR204
1103404	TP20	MP147	RR173	RR171	IC19	VC1859	—	RR195	RR231	RR204
1103405	TP20	MP108	RR173	RR214	IC18	—	—	RR195	RR231	RR204
1103406	TP47	MP117	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103407	TP20	MP127	RR173	RR171	IC18	—	—	RR195	RR233	RR204
1103408	TP45	MP102	RR173	RR171	IC18	VC1859	—	RR195	RR233	RR204
1103412	TP21	MP101	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103413	TP21	MP101	RR173	RR171	IC18	—	—	RR195	RR231	RR204

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1103414	TP21	MP101	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103415	TP20	MP112	RR173	RR171	IC19	—	—	RR195	RR233	RR204
1103416	TP20	MP112	RR173	RR171	IC19	—	—	RR195	RR233	RR204
1103417	TP45	MP101	RR173	RR171	IC18	—	—	RR195	RR230	RR204
1103418	TP20	MP112	RR173	RR171	IC19	—	—	RR195	RR233	RR204
1103419	TP21	MP112	RR173	RR171	IC18	VC1855	—	RR195	RR231	RR204
1103420	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103421	TP45	MP100	RR173	RR171	IC19	VC1836	—	RR195	RR231	RR204
1103423	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103425	TP45	MP102	RR173	RR171	IC18	—	—	RR195	RR233	RR204
1103426	TP45	MP102	RR173	RR171	IC18	—	—	RR195	RR233	RR204
1103431	TP45	MP103	RR198	RR191	IC22	—	—	—	—	—
1103432	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103433	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103434	TP21	MP113	RR173	RR203	IC19	VC1868	—	RR205	RR231	RR204
1103435	TP45	MP100	RR173	RR171	IC19	VC1862	—	RR195	RR231	RR204
1103436	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103439	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103440	TP417	MP115	RR210	RR209	IC22	—	—	—	—	—
1103441	TP48	MP122	RR210	RR209	IC22	VC1720	—	—	—	—
1103443	TP47	MP119	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103444	TP20	MP127	RR173	RR171	IC18	—	—	RR195	RR233	RR204
1103445	TP48	MP123	RR210	RR211	IC22	—	—	—	—	—
1103446	TP48	MP123	RR210	RR211	IC22	—	—	—	—	—
1103447	TP45	MP101	RR173	RR171	IC18	—	—	RR195	RR230	RR204
1103449	TP45	MP102	RR173	RR171	IC18	—	—	RR195	RR233	RR204
1103450	TP45	MP102	RR173	RR171	IC18	—	—	RR195	RR233	RR204
1103451	TP47	MP117	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103452	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR233	RR204
1103453	TP47	MP117	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103455	TP47	MP119	RR173	RR214	IC19	—	—	RR195	RR231	RR204
1103457	TP47	MP117	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103458	TP21	MP101	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103460	TP47	MP119	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103461	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103462	TP47	MP117	RR173	RR214	IC18	—	—	RR195	RR231	RR204
1103464	TP20	MP147	RR173	RR171	IC19	VC1703	—	RR195	RR231	RR204
1103465	TP20	MP147	RR173	RR171	IC19	VC1868	—	RR195	RR231	RR204
1103466	TP47	MP117	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103467	TP21	MP101	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103468	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1103469	TP48	MP122	RR188	RR244	IC29	—	—	—	—	—
1103470	TP47	MP118	RR173	RR203	IC18	—	—	RR205	RR231	RR204
1103471	TP48	MP122	RR210	RR209	IC22	—	—	—	—	—
1103472	TP47	MP119	RR173	RR214	IC19	—	—	RR195	RR231	RR204
1103475	TP48	MP122	—	—	—	—	—	—	—	—
1103477	TP48	MP122	—	—	—	—	—	—	—	—
1103478	TP48	MP122	RR188	RR244	IC29	—	—	—	—	—
1103479	TP47	MP117	RR173	RR171	IC18	—	—	RR195	RR231	RR204

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1103480	TP47	MP116	RR173	RR203	IC19	—	—	RR205	RR231	RR204
1103481	TP45	MP104	RR173	RR203	IC19	VC1862	—	RR205	RR234	RR204
1103482	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1103483	TP45	MP104	RR173	RR203	IC19	VC1868	—	RR205	RR234	RR204
1103484	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1103485	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1103486	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1103487	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103488	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1103489	TP48	MP115	RR210	RR209	IC29	—	—	—	—	—
1103490	TP45	MP101	RR173	RR171	IC18	VC945	—	RR195	RR231	RR204
1103491	TP48	MP122	RR210	RR209	IC29	—	—	—	—	—
1103492	TP48	MP122	RR210	RR209	IC29	—	—	—	—	—
1103494	TP47	MP119	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103496	TP48	MP122	RR210	RR209	IC29	VC1720	—	—	—	—
1103497	TP45	MP103	RR198	RR191	IC22	—	—	—	—	—
1103498	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1103499	TP48	MP122	RR210	RR209	IC29	—	—	—	—	—
1103500	TP417	MP115	RR210	RR209	IC29	—	—	—	—	—
1103501	TP45	MP103	RR198	RR191	IC22	—	—	—	RR232	—
1103504	TP45	MP103	RR198	RR191	IC22	VC1868	—	—	—	—
1103505	TP45	MP103	RR198	RR191	IC22	—	—	—	—	—
1103506	TP45	MP103	RR198	RR191	IC22	—	—	—	—	—
1103510	TP45	MP103	RR198	RR191	IC22	—	—	—	RR232	—
1103511	TP45	MP103	RR198	RR191	IC22	—	—	—	—	—
1103513	TP417	MP124	RR212	RR209	IC22	—	—	—	—	—
1103514	TP417	MP115	RR212	RR237	IC22	—	—	—	—	—
1103515	TP417	MP115	RR210	RR209	IC22	—	—	—	—	—
1103516	TP48	MP122	RR188	RR244	IC29	—	—	—	—	—
1103518	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1103519	TP417	MP121	RR210	RR211	IC22	—	—	—	—	—
1103520	TP48	MP123	RR210	RR211	IC22	VC1706	—	—	—	—
1103521	TP48	MP123	RR210	RR211	IC22	VC1720	—	—	—	—
1103522	TP48	MP123	RR210	RR211	IC22	—	—	—	—	—
1103523	TP48	MP123	RR210	RR211	IC22	—	—	—	—	—
1103525	TP48	MP123	RR210	RR211	IC22	—	—	—	—	—
1103527	TP48	MP122	RR210	RR209	IC29	—	—	—	—	—
1103528	TP48	MP122	RR210	RR209	IC22	VC1709	—	—	—	—
1103530	TP20	MP146	RR173	RR203	IC19	VC1703	—	RR205	RR234	RR204
1103532	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1103535	TP48	MP122	RR210	RR209	IC22	—	—	—	—	—
1103536	TP48	MP122	RR210	RR209	IC22	VC1720	—	—	—	—
1103538	TP47	MP117	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103539	TP47	MP119	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103540	TP47	MP117	RR173	RR214	IC18	—	—	RR195	RR231	RR204
1103541	TP47	MP119	RR173	RR214	IC19	—	—	RR195	RR231	RR204
1103543	TP417	MP115	RR210	RR244	IC22	—	—	—	—	—
1103544	TP20	MP147	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103545	TP48	MP122	RR210	RR209	IC22	VC1709	—	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1103546	TP48	MP122	RR210	RR209	IC22	VC1720	—	—	—	—
1103547	TP48	MP122	RR210	RR209	IC22	VC1720	—	—	—	—
1103548	TP48	MP122	RR210	RR209	IC22	—	—	—	—	—
1103549	—	MP122	RR188	RR244	IC29	—	—	—	—	—
1103551	TP417	MP115	RR212	RR209	IC22	—	—	—	—	—
1103553	TP417	MP115	RR212	RR237	IC29	—	—	—	—	—
1103554	TP48	MP123	RR210	RR211	IC22	—	—	—	—	—
1103561	TP417	MP115	RR212	RR237	IC22	—	—	—	—	—
1103562	TP417	MP121	RR210	RR211	IC22	—	—	—	—	—
1103563	TP47	MP119	RR173	RR214	IC19	—	—	RR195	RR231	RR204
1103565	TP45	MP103	RR198	RR191	IC22	—	—	—	—	—
1103566	TP45	MP103	RR198	RR191	IC22	—	—	—	—	—
1103567	TP25	MP131	RR240	RR239	IC29	—	—	—	—	—
1103568	—	MP131	RR242	RR241	IC29	—	—	—	—	—
1103569	TP417	MP121	RR210	RR211	IC22	—	—	—	—	—
1103570	TP417	MP121	RR210	RR211	IC22	—	—	—	—	—
1103571	TP45	MP103	RR198	RR191	IC22	—	—	—	—	—
1103572	TP20	MP146	RR173	RR203	IC19	VC1868	—	RR205	RR231	RR204
1103573	TP47	MP116	RR173	RR203	IC19	—	—	RR205	RR231	RR204
1103574	TP25	MP131	RR242	RR241	IC29	—	—	—	—	—
1103579	TP417	MP115	RR210	RR209	IC22	—	—	—	—	—
1103585	TP417	MP115	RR212	RR237	IC22	—	—	—	—	—
1103586	TP48	MP147	RR210	RR211	IC29	VC1700	—	—	—	—
1103587	TP48	MP147	RR210	RR211	IC22	—	—	—	—	—
1103588	TP47	MP118	RR173	RR238	IC18	—	—	RR195	—	RR204
1103589	TP417	MP115	RR212	RR237	IC22	—	—	—	—	—
1103591	TP25	MP131	RR242	RR241	IC29	—	—	—	—	—
1103592	TP48	MP122	RR210	RR209	IC22	—	—	—	—	—
1103595	TP47	MP117	RR173	RR214	—	—	—	RR195	RR231	RR204
1103596	TP47	MP119	RR173	RR214	—	—	—	RR195	RR231	RR204
1103598	TP47	MP119	RR173	RR171	—	—	—	RR195	RR231	RR204
1103600	—	MP115	RR212	RR244	IC29	—	—	—	—	—
1103601	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103602	TP47	MP117	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103603	TP47	MP117	RR173	RR171	—	—	—	RR195	RR231	RR204
1103604	TP20	MP147	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103605	TP417	MP115	RR212	RR209	IC22	—	—	—	—	—
1103606	TP45	MP100	RR173	RR171	IC19	VC1703	—	RR195	RR231	RR204
1103607	TP45	MP101	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103609	TP417	MP115	RR212	RR237	IC29	—	—	—	—	—
1103610	TP417	MP115	RR212	RR237	IC29	—	—	—	—	—
1103611	TP48	MP122	RR188	RR244	IC29	—	—	—	—	—
1103612	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1103613	TP45	MP103	RR198	RR191	IC29	—	—	—	—	—
1103614	TP45	MP103	RR198	RR191	IC29	—	—	—	—	—
1103615	TP45	MP103	RR198	RR191	IC29	—	—	—	—	—
1103616	TP45	MP103	RR198	RR191	IC29	VC1868	—	—	—	—
1103617	TP48	MP123	RR210	RR210	IC29	—	—	—	—	—
1103618	TP48	MP123	RR210	RR210	IC29	—	—	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1103619	TP48	MP123	RR210	RR210	IC29	VC1700	—	—	—	—
1103620	TP48	MP123	RR210	RR210	IC29	VC1706	—	—	—	—
1103621	TP48	MP123	RR210	RR210	IC29	VC1706	—	—	—	—
1103623	TP48	MP122	RR188	RR244	IC29	—	—	—	—	—
1103625	TP417	MP124	RR212	RR209	IC29	—	—	—	—	—
1103628	TP48	MP122	RR188	RR244	IC29	—	—	—	—	—
1103630	TP48	MP123	RR210	RR210	IC29	—	—	—	—	—
1103631	TP20	—	RR173	RR203	IC19	VC1862	—	RR195	RR231	RR204
1103632	TP24	MP131	RR240	RR239	IC29	—	—	—	—	—
1103633	—	MP131	RR242	RR241	IC29	—	—	—	—	—
1103634	TP24	MP131	RR240	RR239	IC29	—	—	—	—	—
1103635	TP48	MP123	RR210	RR210	IC29	VC1700	—	—	—	—
1103636	TP45	MP104	RR173	RR203	IC19	—	—	RR195	RR234	RR204
1103637	TP47	MP117	RR173	RR214	IC18	—	—	RR195	RR231	RR204
1103638	TP47	MP119	RR173	RR214	IC19	—	—	RR195	RR231	RR204
1103641	TP20	MP147	RR173	RR171	IC19	VC1862	—	RR195	RR231	RR204
1103643	TP417	MP121	RR210	RR210	IC29	—	—	—	—	—
1103644	TP417	MP121	RR210	RR210	IC29	—	—	—	—	—
1103647	TP417	MP115	RR212	RR209	IC29	—	—	—	—	—
1103649	TP25	MP131	RR240	EP828	IC29	—	—	—	—	—
1103650	—	MP131	RR240	RR239	IC29	—	—	—	—	—
1103651	—	MP131	RR240	RR239	IC29	—	—	—	—	—
1103652	TP25	MP131	RR242	RR241	IC29	—	—	—	—	—
1103653	TP25	MP131	RR240	RR239	IC29	—	—	—	—	—
1103655	TP25	MP131	RR242	RR241	IC29	—	—	—	—	—
1103658	—	MP122	RR212	RR244	IC29	—	—	—	—	—
1103659	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103660	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103664	TP47	MP117	RR173	RR214	IC18	—	—	RR195	RR231	RR204
1103665	TP45	—	RR173	RR203	IC19	—	—	RR195	RR231	RR204
1103667	TP417	MP115	RR212	RR244	IC29	—	—	—	—	—
1103674	TP25	MP131	RR240	EP828	IC29	—	—	—	—	—
1103675	TP47	MP139	RR173	RR214	IC19	—	—	RR195	—	RR204
1103676	TP47	MP119	RR173	RR214	IC19	—	—	RR195	RR231	RR204
1103677	TP47	MP117	RR173	RR171	IC18	—	—	RR195	RR231	RR204
1103678	TP24	—	RR240	EP828	IC29	—	—	—	—	—
1103679	TP47	MP119	RR173	RR214	IC19	—	—	RR195	RR231	RR204
1103680	TP47	MP117	RR173	RR214	IC18	—	—	RR195	RR231	RR204
1103683	TP47	MP119	RR173	RR214	IC19	—	—	RR195	RR231	RR204
1103684	TP48	MP122	RR188	RR244	IC29	—	—	—	—	—
1103685	TP48	MP122	RR188	RR244	IC29	—	—	—	—	—
1103686	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103687	TP47	MP117	RR173	RR214	IC18	—	—	RR195	RR231	RR204
1103690	TP25	MP131	RR242	RR241	IC29	—	—	—	—	—
1103694	—	MP131	RR242	RR241	IC29	—	—	—	—	—
1103696	TP48	MP122	RR188	RR244	IC29	—	—	—	—	—
1103698	TP25	MP131	RR250	RR249	IC29	—	—	—	—	—
1103704	TP25	MP131	RR242	RR241	IC29	—	—	—	—	—
1103705	TP25	MP131	RR242	RR241	IC29	—	—	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1103706	TP47	MP117	RR173	RR214	IC18	—	—	RR195	RR231	RR204
1103707	TP47	MP117	RR173	RR214	IC18	—	—	RR195	RR231	RR204
1103708	TP47	MP119	RR173	RR214	IC19	—	—	RR195	RR231	RR204
1103709	TP47	MP119	RR173	RR214	IC19	—	—	RR195	RR231	RR204
1103710	TP417	MP115	RR212	RR237	IC29	—	—	—	—	—
1103711	TP417	MP115	RR212	RR237	IC29	—	—	—	—	—
1103717	TP45	MP100	RR173	RR171	IC19	—	—	RR195	RR231	RR204
1103718	TP45	MP101	RR171	RR171	IC18	—	—	RR195	RR231	RR204
1103719	TP45	MP104	RR203	RR203	IC19	—	—	RR205	RR234	RR204
1103720	TP417	MP115	RR212	RR244	IC29	—	—	—	—	—
1103721	TP417	MP115	RR212	RR244	IC29	—	—	—	—	—
1103722	TP47	MP139	RR214	RR214	IC19	—	—	RR195	RR236	RR204
1103723	TP48	MP122	RR188	RR244	IC29	—	—	—	—	—
1103724	TP48	MP122	RR188	RR244	IC29	—	—	—	—	—
1103725	TP25	MP131	RR242	RR241	IC29	—	—	—	—	—
1103726	TP45	MP100	RR171	RR171	IC19	—	—	RR195	RR231	RR204
1103730	TP47	MP117	RR214	RR214	IC18	—	—	RR195	RR231	RR204
1103731	TP47	MP119	RR214	RR214	IC19	—	—	RR195	RR231	RR204
1103732	TP47	MP139	RR214	RR214	IC19	—	—	RR195	RR236	RR204
1103735	TP47	MP139	RR214	RR214	IC19	—	—	RR195	RR236	RR204
1103742	TP47	MP119	RR214	RR214	IC19	—	—	RR195	RR231	RR204
1103743	TP47	MP117	RR214	RR214	IC18	—	—	RR195	RR231	RR204
1103747	TP47	MP139	RR214	RR214	IC19	—	—	RR195	RR236	RR204
1103749	TP25	MP131	RR250	RR249	IC29	—	—	—	—	—
1103751	TP45	MP100	RR171	RR171	IC19	—	—	RR195	RR231	RR204
1103752	TP45	MP100	RR171	RR171	IC19	VC1703	—	RR195	RR231	RR204
1103754	TP25	MP131	RR240	EP828	IC29	—	—	—	—	—
1103755	TP47	MP119	RR214	RR214	IC19	VC1703	—	RR195	RR231	RR204
1103756	TP47	MP117	RR214	RR214	IC18	—	—	RR195	RR231	RR204
1103765	TP47	MP136	RR214	RR214	IC18	—	—	RR195	RR236	RR204
1103766	TP24	MP137	RR250	EP828	IC29	—	—	—	—	—
1103767	TP417	MP115	RR212	RR237	IC29	—	—	—	—	—
1103768	TP417	MP115	RR212	RR237	IC29	—	—	—	—	—
1103769	TP24	—	RR250	EP828	IC29	—	—	—	—	—
1103770	TP25	MP131	RR250	RR249	IC29	—	—	—	—	—
1103773	TP24	MP137	RR240	RR241	IC29	—	—	—	—	—
1103774	TP24	MP137	RR240	EP828	IC29	—	—	—	—	—
1103776	TP47	MP136	RR214	RR214	IC18	—	—	RR195	—	RR204
1103778	TP47	MP139	RR214	RR214	IC19	—	—	RR195	—	RR204
1103782	TP59	MP145	RR240	RR241	IC29	—	—	—	—	—
1103791	TP18	MP131	RR250	RR249	IC29	—	—	—	—	—
1103798	TP59	MP145	—	RR241	IC29	—	—	—	—	—
1103799	TP59	MP145	RR252	RR249	IC29	—	—	—	—	—
1103800	TP25	MP131	RR240	EP828	IC29	—	—	—	—	—
1103827	TP25	MP131	RR250	RR249	IC29	—	—	—	—	—
1103829	TP24	MP131	RR240	RR241	IC29	—	—	—	—	—
1103833	TP417	MP115	RR212	RR237	IC29	—	—	—	—	—
1103837	TP25	MP131	RR242	RR241	IC29	—	—	—	—	—
1103838	TP25	MP131	RR250	RR249	IC29	—	—	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1103839	TP18	MP131	RR250	RR249	IC29	—	—	—	—	—
1103843	TP24	MP131	RR242	RR241	IC29	—	—	—	—	—
1103847	TP47	MP139	RR173	RR214	IC19	—	—	RR195	—	RR204
1103848	TP47	MP136	RR173	RR214	IC18	—	—	RR195	—	RR204
1103849	TP47	MP136	RR173	RR214	IC18	—	—	RR195	—	RR204
1103852	TP25	MP131	RR250	RR249	IC29	—	—	—	—	—
1103857	TP47	MP136	RR173	RR214	IC18	—	—	RR195	—	RR204
1103863	TP417	MP115	RR212	RR237	IC29	—	—	—	—	—
1103864	TP49	MP121	RR188	RR211	IC29	—	—	—	—	—
1103874	TP48	MP122	RR188	RR244	IC29	—	—	—	—	—
1103879	TP47	MP117	RR173	RR214	IC18	—	—	—	—	—
1103880	TP25	MP131	RR250	RR249	IC29	—	—	—	—	—
1103881	TP25	MP131	RR242	RR241	IC29	—	—	—	—	—
1103883	TP25	—	RR240	EP828	IC29	—	—	—	—	—
1103900	TP25	—	RR240	RR241	IC29	—	—	—	—	—
1103911	TP414	—	—	—	IC39	—	—	—	—	—
1103916	TP12	ESC13M	—	RR218	IC29	—	—	—	—	—
1103920	TP18	MP131	RR250	RR249	IC29	—	—	—	—	—
1103927	TP18	MP145	RR252	RR249	IC29	—	—	—	—	—
1103933	TP59	MP145	—	RR241	IC29	—	—	—	—	—
1103934	TP25	MP145	RR252	RR249	IC29	—	—	—	—	—
1103935	—	—	—	—	IC29	—	—	—	—	—
1103936	TP414	—	—	—	IC39	—	—	—	—	—
1103951	TP25	MP131	RR242	RR241	IC29	—	—	—	—	—
1103952	TP25	MP131	RR250	RR249	IC29	—	—	—	—	—
1103953	TP25	MP131	RR250	RR249	IC29	—	—	—	—	—
1103992	TP18	MP145	RR199	RR249	IC29	—	—	—	—	—
1103993	TP59	MP145	—	RR241	IC29	—	—	—	—	—
1104035	TP49	MP121	RR188	RR211	IC29	—	—	—	—	—
1104048	TP18	MP145	RR199	RR249	IC29	—	—	—	—	—
1104050	TP58	MP143	—	RR253	IC58	—	—	—	—	—
1104052	TP418	—	RR256	RR253	IC46	—	—	—	—	—
1104057	TP58	MP143	RR256	RR253	IC58	—	—	—	—	—
1104058	TP58	—	RR256	RR207	IC58	—	—	—	—	—
1104059	TP58	—	RR256	RR207	IC58	—	—	—	—	—
1104060	TP59	MP145	RR199	RR249	IC29	—	—	—	—	—
1108048	TP18	MP145	RR250	RR249	IC29	—	—	—	—	—
1110325	—	—	RR182R	RR183	—	—	—	—	—	—
1110326	—	—	RR182R	RR183	—	—	—	—	—	—
1110327	—	—	RR182R	RR183	—	—	—	—	—	—
1110332	—	—	RR182R	RR183	—	—	—	—	—	—
1110333	—	—	RR182R	RR183	—	—	—	—	—	—
1110344	—	—	RR182R	RR183	—	—	—	—	—	—
1110380	—	—	RR182R	RR183	—	—	—	—	—	—
1110386	—	—	RR182R	RR183	—	—	—	—	—	—
1110400	—	—	RR182R	RR183	—	—	—	—	—	—
1110432	—	—	RR182R	RR183	—	—	—	—	—	—
1110450	—	—	RR182R	RR183	—	—	—	—	—	—
1110538	TP45	MP103	RR198	RR191	IC22	VC1848	RR170	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1110539	TP45	MP103	RR198	RR191	IC22	VC1848	RR170	—	—	—
1110548	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1110550	TP20	MP126	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110551	TP20	MP126	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110552	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110553	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110554	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110555	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110556	TP45	MP103	RR198	RR191	IC22	VC1862	—	—	RR232	—
1110558	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110559	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110560	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110561	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110565	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110566	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110567	TP417	MP115	RR210	RR209	—	—	—	—	—	—
1110568	TP45	MP111	RR173	RR203	IC19	VC1703	—	RR205	RR234	RR204
1110569	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110570	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110571	TP20	MP126	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110572	TP20	MP126	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110573	TP47	MP118	RR173	RR203	IC18	—	—	RR205	RR231	RR204
1110574	TP45	MP113	RR173	RR203	IC19	VC1868	—	RR205	RR231	RR204
1110575	TP417	MP115	RR210	RR209	—	—	—	—	—	—
1110576	TP20	MP126	RR173	RR203	IC18	—	—	RR205	—	—
1110577	TP48	—	RR210	RR209	—	—	—	—	—	—
1110578	TP48	—	RR210	RR209	—	—	—	—	—	—
1110579	TP47	MP116	RR173	RR203	IC19	—	—	RR205	RR231	RR204
1110580	TP47	MP120	RR198	RR191	—	—	—	—	RR232	—
1110581	TP48	MP123	RR210	RR211	—	—	—	—	—	—
1110582	TP48	MP123	RR210	RR211	—	—	—	—	—	—
1110583	TP417	MP121	RR210	RR211	—	—	—	—	—	—
1110584	TP47	MP125	RR173	RR203	IC19	—	—	RR205	RR236	RR204
1110585	TP47	MP120	RR198	RR191	—	—	—	—	RR232	—
1110589	TP45	MP104	RR173	RR203	IC19	VC1862	—	RR205	RR234	RR204
1110590	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1110592	TP47	MP118	RR173	RR203	IC18	—	—	RR205	RR231	RR204
1110593	TP47	MP116	RR173	RR203	IC19	—	—	RR205	RR231	RR204
1110594	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110595	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110596	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110597	TP417	MP124	RR212	RR209	IC29	—	—	—	—	—
1110598	TP48	MP122	RR210	RR209	—	—	—	—	—	—
1110599	TP417	MP115	RR210	RR244	IC29	—	—	—	—	—
1110600	TP45	MP103	—	RR191	—	—	—	—	RR232	—
1110602	—	—	RR99	RR100	—	—	—	—	—	—
1110649	TP45	MP103	RR198	RR191	IC22	—	RR170	—	—	—
1110650	TP45	MP104	RR198	RR192	IC22	—	RR170	—	—	—
1110651	TP45	MP105	RR173	RR194	IC18	VC1827	RR170	RR195	RR230	RR204

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1110652	TP45	MP104	RR198	RR192	IC22	VC1847	RR170	—	—	—
1110654	TP45	MP103	RR198	RR191	IC22	—	RR170	—	—	—
1110655	TP45	MP103	RR198	RR191	IC22	VC700	RR170	—	—	—
1110656	TP45	MP103	RR198	RR191	IC22	—	RR170	—	—	—
1110657	TP45	MP103	RR198	RR191	IC22	VC1839	RR170	—	—	—
1110658	TP45	MP103	RR198	RR191	IC22	VC1855	RR170	—	—	—
1110659	TP45	MP103	RR198	RR191	IC22	—	RR170	—	—	—
1110660	TP45	MP103	RR198	RR191	IC22	—	RR170	—	—	—
1110661	TP45	MP105	RR173	RR194	IC18	VC1827	RR170	RR195	RR230	RR204
1110662	TP45	MP104	RR198	RR192	IC22	VC1836	RR170	—	—	—
1110663	TP45	MP105	RR173	RR194	IC18	VC1827	RR170	RR195	RR230	RR204
1110664	TP45	MP104	RR198	RR192	IC22	—	RR170	—	—	—
1110665	TP45	MP104	RR198	RR192	IC22	—	RR170	—	—	—
1110666	TP45	MP104	RR198	RR192	IC22	—	RR170	—	—	—
1110667	TP45	MP104	RR198	RR192	IC22	—	RR170	—	—	—
1110668	TP45	MP105	RR173	RR194	IC18	VC1826	RR170	RR195	RR230	RR204
1110672	TP45	MP107	RR198	RR191	IC22	—	RR170	—	—	—
1110673	TP45	MP104	RR198	RR192	IC22	—	RR170	—	—	—
1110674	TP45	MP104	RR198	RR192	IC22	VC1836	RR170	—	—	—
1110676	TP45	MP104	RR198	RR192	IC22	—	RR170	—	—	—
1110677	TP45	MP105	RR173	RR194	IC18	VC1849	RR170	RR195	RR230	RR204
1110678	TP45	MP104	RR198	RR192	IC22	—	RR170	—	—	—
1110679	TP45	MP104	RR198	RR192	IC22	—	RR170	—	—	—
1110680	TP45	MP104	RR198	RR192	IC22	—	RR170	—	—	—
1110681	TP45	MP104	RR198	RR192	IC22	—	RR170	—	—	—
1110682	TP45	MP104	RR198	RR192	IC22	—	RR170	—	—	—
1110685	TP45	MP103	RR198	RR191	IC22	—	RR170	—	—	—
1110686	TP45	MP105	RR173	RR194	IC18	—	RR170	RR195	RR230	RR204
1110687	TP45	MP103	RR198	RR191	IC22	—	RR170	—	—	—
1110688	TP45	MP103	RR198	RR191	IC22	VC1863	RR170	—	—	—
1110692	TP45	MP104	RR198	RR192	IC22	VC1836	RR170	—	RR232	—
1110693	TP45	MP103	RR198	RR191	IC22	—	RR170	—	RR232	—
1110694	TP45	MP105	RR173	RR194	IC18	—	RR170	RR195	RR230	RR204
1110695	TP45	MP111	RR173	RR203	IC18	—	RR170	RR205	RR230	RR204
1110696	TP45	MP113	RR173	RR203	IC19	VC1862	RR170	RR205	RR231	RR204
1110700	TP45	MP104	RR198	RR192	IC22	—	RR170	—	RR232	—
1110702	TP45	MP103	RR198	RR191	IC22	VC945	RR170	—	RR232	—
1110703	TP45	MP103	RR198	RR191	IC22	VC945	RR170	—	RR232	—
1110705	TP45	MP103	RR198	RR191	IC22	VC945	RR170	—	RR232	—
1110706	TP45	MP103	RR198	RR191	IC22	—	RR170	—	RR232	—
1110707	TP45	MP103	RR198	RR191	IC22	—	RR170	—	RR232	—
1110708	TP45	MP103	RR198	RR191	IC22	VC945	RR170	—	RR232	—
1110711	TP45	MP103	RR198	RR191	IC22	—	RR170	—	RR232	—
1110712	TP45	MP103	RR198	RR191	IC22	—	RR170	—	RR232	—
1110713	TP45	MP103	RR198	RR191	IC22	VC945	RR170	—	RR232	—
1110715	TP45	MP104	RR173	RR203	IC19	VC1857	RR170	RR205	RR234	RR204
1110716	TP45	MP104	RR173	RR203	IC19	—	RR170	RR205	RR234	RR204
1110717	TP45	MP104	RR173	RR203	IC19	VC1836	RR170	RR205	RR234	RR204
1110718	TP45	MP104	RR173	RR203	IC19	VC1836	RR170	RR205	RR234	RR204

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1110719	TP45	MP104	RR173	RR203	IC19	VC1836	RR170	RR205	RR234	RR204
1110720	TP45	MP104	RR173	RR203	IC19	—	RR170	RR205	RR234	RR204
1110721	TP45	MP104	RR173	RR203	IC19	—	RR170	RR205	RR234	RR204
1110722	TP45	MP104	RR173	RR203	IC19	—	RR170	RR205	RR234	RR204
1110723	TP20	MP126	RR173	RR203	IC18	—	RR170	RR205	RR230	RR204
1110724	TP45	MP104	RR198	RR192	IC22	—	RR170	—	RR232	—
1110725	TP45	MP104	RR198	RR192	IC22	—	RR170	—	RR232	—
1110726	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110728	TP45	MP111	RR173	RR203	IC18	—	RR170	RR205	RR230	RR204
1110730	TP20	MP126	RR173	RR203	IC18	VC1849	RR170	RR205	RR230	RR204
1110731	TP45	MP111	RR173	RR203	IC18	—	RR170	RR205	RR230	RR204
1110732	TP45	MP111	RR173	RR203	IC18	—	RR170	RR205	RR230	RR204
1110733	TP45	MP107	RR173	RR197	IC19	—	RR170	RR195	—	RR204
1110735	TP20	MP126	RR173	RR203	IC18	VC1863	RR170	RR205	RR230	RR204
1110736	TP45	MP104	RR173	RR203	IC19	—	RR170	RR205	—	RR204
1110737	TP45	MP113	RR173	RR203	IC19	—	RR170	RR205	RR231	RR204
1110739	TP45	MP111	RR173	RR203	IC18	VC1863	RR170	RR205	RR230	RR204
1110740	TP45	MP103	RR198	RR191	IC22	VC1863	RR170	—	RR232	—
1110741	TP45	MP103	RR198	RR191	IC22	—	RR170	—	RR232	—
1110742	TP45	MP103	RR198	RR191	IC22	—	RR170	—	RR232	—
1110743	TP45	MP103	RR198	RR191	IC22	VC1863	RR170	—	RR232	—
1110744	TP45	MP103	RR198	RR191	IC22	VC1863	RR170	—	RR232	—
1110747	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1110748	TP45	MP104	RR173	RR203	IC19	VC1859	—	RR205	RR234	RR204
1110749	TP45	MP104	RR173	RR203	IC19	VC1703	—	RR205	RR234	RR204
1110750	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1110751	TP45	MP113	RR173	RR203	IC19	—	—	RR205	RR231	RR204
1110752	TP45	MP113	RR173	RR203	IC19	VC1862	—	RR205	RR231	RR204
1110753	TP45	MP104	RR173	RR203	IC19	VC1703	—	RR205	RR231	RR204
1110754	TP21	MP113	RR173	RR203	IC19	VC1862	—	RR205	RR231	RR204
1110755	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1110756	TP45	MP113	RR173	RR203	IC19	—	—	RR205	RR231	RR204
1110757	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110759	TP45	MP103	RR198	RR191	IC22	VC1836	RR170	—	RR232	—
1110760	TP45	MP103	RR198	RR191	IC22	—	RR170	—	RR232	—
1110763	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110764	TP20	MP126	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110765	TP20	MP126	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110766	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110767	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110768	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110769	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110770	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110771	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110772	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110773	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110774	TP20	MP126	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110775	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110776	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1110777	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110778	TP45	MP103	RR198	RR191	IC22	VC1864	RR170	—	RR232	—
1110779	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110780	TP45	MP113	RR173	RR203	IC19	—	—	RR205	RR231	RR204
1110782	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110783	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110784	TP47	MP118	RR173	RR203	IC18	—	—	RR205	RR231	RR204
1110785	TP45	MP111	RR173	RR203	IC18	—	—	RR205	RR230	RR204
1110786	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110787	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110788	TP45	MP103	RR198	RR191	IC22	—	RR170	—	RR232	—
1110789	TP45	MP103	RR198	RR191	IC29	VC1868	RR170	—	RR232	—
1110792	TP45	MP103	RR198	RR191	IC22	—	RR170	—	RR232	—
1110794	TP45	MP103	RR198	RR191	IC29	VC1862	RR170	—	RR232	—
1110795	TP45	MP103	RR198	RR191	IC22	—	RR170	—	RR232	—
1110796	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1110797	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1111017	—	—	RR169R	RR165	—	—	—	—	—	—
1111027	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111038	—	—	RR169R	RR165	—	—	—	—	—	—
1111040	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111041	—	—	RR169R	RR165	—	—	—	—	—	—
1111047	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111059	—	—	RR169R	RR165	—	VC1802	—	—	—	—
1111060	—	—	RR169R	RR165	—	—	—	—	—	—
1111064	—	—	RR169R	RR165	—	—	—	—	—	—
1111065	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111066	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111067	—	—	RR169R	RR165	—	VC1802	—	—	—	—
1111068	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111072	—	—	RR169R	RR165	—	—	—	—	—	—
1111074	—	—	RR169R	RR165	—	—	—	—	—	—
1111080	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111081	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111086	—	—	RR169R	RR165	—	—	—	—	—	—
1111093	—	—	RR169R	RR165	—	—	—	—	—	—
1111095	—	—	RR169R	RR165	—	—	—	—	—	—
1111097	—	—	RR169R	RR165	—	—	—	—	—	—
1111098	—	—	RR169R	RR165	—	VC1605	—	—	—	—
1111137	—	—	RR169R	RR165	—	VC700	—	—	—	—
1111139	—	—	RR169R	RR165	—	—	—	—	—	—
1111140	—	—	RR169R	RR165	—	VC1765	—	—	—	—
1111142	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111146	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111155	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111157	—	—	RR169R	RR165	—	—	—	—	—	—
1111166	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111179	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111180	—	—	RR169R	RR165	—	VC680	—	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1111188	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111189	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111197	—	—	RR169R	RR165	—	—	—	—	—	—
1111240	—	—	RR169R	RR165	—	—	—	—	—	—
1111245	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111246	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111248	—	—	RR169R	RR165	—	—	—	—	—	—
1111251	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111255	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111258	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111263	—	—	RR169R	RR165	—	—	—	—	—	—
1111267	—	—	RR169R	RR165	—	—	—	—	—	—
1111273	—	—	—	—	—	VC1755	—	—	—	—
1111277	—	—	RR169R	RR165	—	VC1802	—	—	—	—
1111278	—	—	RR169R	RR165	—	—	—	—	—	—
1111283	—	—	RR169R	RR165	—	—	—	—	—	—
1111290	—	—	RR169R	RR165	—	VC1755	—	—	—	—
1111291	—	—	RR169R	RR165	—	—	—	—	—	—
1111292	—	—	RR169R	RR165	—	VC1755	—	—	—	—
1111294	—	—	RR169R	RR165	—	—	—	—	—	—
1111295	—	—	RR169R	RR165	—	—	—	—	—	—
1111296	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111303	—	—	RR169R	RR165	—	—	—	—	—	—
1111307	—	—	RR169R	RR165	—	—	—	—	—	—
1111308	—	—	RR169R	RR165	—	—	—	—	—	—
1111312	—	—	RR169R	RR165	—	—	—	—	—	—
1111316	—	—	RR169R	RR165	—	—	—	—	—	—
1111317	—	—	RR169R	RR165	—	—	—	—	—	—
1111318	—	—	RR169R	RR165	—	—	—	—	—	—
1111320	—	—	RR169R	RR165	—	—	—	—	—	—
1111321	—	—	RR169R	RR165	—	—	—	—	—	—
1111322	—	—	RR169R	RR165	—	—	—	—	—	—
1111323	—	—	RR169R	RR165	—	—	—	—	—	—
1111324	—	—	RR169R	RR165	—	—	—	—	—	—
1111325	—	—	RR169R	RR165	—	—	—	—	—	—
1111328	—	—	RR169R	RR165	—	—	—	—	—	—
1111329	—	—	RR169R	RR165	—	—	—	—	—	—
1111332	—	—	RR169R	RR165	—	VC1765	—	—	—	—
1111333	—	—	RR169R	RR165	—	—	—	—	—	—
1111339	—	—	RR169R	RR165	—	VC1755	—	—	—	—
1111340	—	—	RR169R	RR165	—	—	—	—	—	—
1111341	—	—	RR169R	RR165	—	VC680	—	—	—	—
1111342	—	—	RR169R	RR165	—	VC1755	—	—	—	—
1111343	—	—	RR169R	RR165	—	VC1755	—	—	—	—
1111346	—	—	RR169R	RR165	—	—	—	—	—	—
1111347	—	—	RR182R	RR183	—	—	—	—	—	—
1111348	—	—	RR182R	RR183	—	—	—	—	—	—
1111349	—	—	RR182R	RR183	—	—	—	—	—	—
1111350	—	—	RR169R	RR165	—	—	—	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1111357	—	—	RR182R	RR183	—	—	—	—	—	—
1111358	—	—	RR169R	RR165	—	—	—	—	—	—
1111359	—	—	—	RR165	—	—	—	—	—	—
1111362	—	—	RR182R	RR183	—	—	—	—	—	—
1111363	—	—	RR182R	RR183	—	—	—	—	—	—
1111385	TP45	MP103	RR198	RR191	IC29	—	—	—	RR232	—
1111386	TP47	MP118	RR173	RR203	IC18	—	—	RR205	RR231	RR204
1111387	TP45	MP113	RR173	RR203	IC19	—	—	RR205	RR231	RR204
1111388	TP45	MP104	RR173	RR203	IC19	VC1868	—	RR205	RR234	RR204
1111391	TP45	MP107	RR173	RR197	IC19	VC1868	—	RR195	RR233	RR204
1111392	TP45	MP104	RR173	RR203	IC19	—	—	RR205	RR234	RR204
1111393	TP45	MP107	RR173	RR197	IC19	—	—	RR195	RR233	RR204
1111395	TP48	MP122	RR188	RR244	IC29	—	—	—	—	—
1111398	TP48	MP122	RR188	RR244	IC29	—	—	—	—	—
1111399	TP48	MP122	RR210	RR209	IC29	—	—	—	—	—
1111441	—	—	RR169R	RR165	—	VC1802	—	—	—	—
1111465	—	—	RR169R	RR165	—	—	—	—	—	—
1111470	—	—	RR169R	RR165	—	VC1765	—	—	—	—
1111471	—	—	RR169R	RR165	—	—	—	—	—	—
1111475	—	—	RR169R	RR165	—	VC1802	—	—	—	—
1111491	—	—	RR169R	RR165	—	VC1802	—	—	—	—
1111927	—	—	RR169R	RR165	—	—	—	—	—	—
1111928	—	—	RR169R	RR165	—	VC1802	—	—	—	—
1111954	—	—	RR169R	RR165	—	—	—	—	—	—
1111958	—	—	RR169R	RR165	—	—	—	—	—	—
1111967	—	—	RR169R	RR165	—	VC1802	—	—	—	—
1111968	—	—	RR169R	RR165	—	VC1605	—	—	—	—
1111971	—	—	RR169R	RR165	—	—	—	—	—	—
1111972	—	—	RR169R	RR165	—	VC1765	—	—	—	—
1111983	—	—	RR169R	RR165	—	VC1765	—	—	—	—
1112026	—	—	RR169R	RR165	—	VC1802	—	—	—	—
1112035	—	—	—	—	—	VC1765	—	—	—	—
1112038	—	—	RR169R	RR165	—	VC1802	—	—	—	—
1112053	—	—	RR169R	RR165	—	—	—	—	—	—
1112076	—	—	RR169R	RR165	—	—	—	—	—	—
1112210	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112212	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112213	TP45	MP102	RR173	RR171	IC18	VC1837	RR170	RR195	—	RR204
1112494	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1112495	TP45	MP102	RR173	RR171	IC18	VC1837	RR170	RR195	—	RR204
1112497	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112498	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112499	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112500	TP45	MP102	RR173	RR171	IC18	VC1837	RR170	RR195	—	RR204
1112506	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1112520	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR230	RR204
1112521	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR230	RR204
1112523	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR232	RR204
1112524	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR232	RR204

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1112527	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR232	RR204
1112528	TP45	MP100	RR173	RR171	IC19	VC1853	RR170	RR195	RR232	RR204
1112532	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR232	RR204
1112546	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112547	TP45	MP102	RR173	RR171	IC18	VC1837	RR170	RR195	—	RR204
1112675	—	—	RR182R	RR181	—	—	—	—	—	—
1112794	—	—	RR169R	RR165	—	—	—	—	—	—
1112798	—	—	RR169R	RR165	—	—	—	—	—	—
1112799	—	—	RR169R	RR165	—	—	—	—	—	—
1112800	—	—	RR169R	RR165	—	—	—	—	—	—
1112802	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1112803	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1112815	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR230	RR204
1112820	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1112829	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR230	RR204
1112830	TP45	MP100	RR173	RR171	IC19	VC1828	RR170	RR195	RR230	RR204
1112839	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1112840	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1112841	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1112842	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1112855	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1112862	TP45	MP103	—	RR191	IC22	—	RR170	—	—	—
1112863	TP45	MP104	—	RR192	IC22	—	RR170	—	—	—
1112864	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1112865	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1112866	TP45	MP100	RR173	RR171	IC19	VC1843	RR170	RR195	RR231	RR204
1112869	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1112871	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112876	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112878	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112880	TP45	MP100	RR173	RR171	IC19	VC1836	RR170	RR195	RR231	RR204
1112882	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1112883	TP45	MP100	RR173	RR171	IC19	VC1843	RR170	RR195	RR231	RR204
1112884	TP45	MP100	RR173	RR171	IC19	VC1852	RR170	RR195	RR231	RR204
1112885	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1112886	TP45	MP100	RR173	RR171	IC19	VC1825	RR170	RR195	RR231	RR204
1112887	TP45	MP104	—	RR192	IC22	—	RR170	—	—	—
1112888	TP45	MP100	RR173	RR171	IC18	VC1836	RR170	RR195	RR231	RR204
1112889	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1112890	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1112891	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1112892	TP45	MP100	RR173	RR171	IC19	VC1833	RR170	RR195	RR233	RR204
1112893	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR230	RR204
1112894	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR230	RR204
1112896	TP45	MP101	RR173	RR171	IC18	VC1838	RR170	RR195	RR230	RR204
1112897	TP45	MP100	RR173	RR171	IC19	VC1841	RR170	RR195	—	RR204
1112898	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112899	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112901	TP45	MP101	RR173	RR171	IC18	VC1835	RR170	RR195	RR231	RR204

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1112903	TP45	MP100	RR173	RR171	IC19	VC1835	RR170	RR195	RR230	RR204
1112905	TP45	MP100	RR173	RR171	IC19	VC1853	RR170	RR195	RR231	RR204
1112918	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112923	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112924	TP45	MP100	RR173	RR171	IC19	VC1833	RR170	RR195	RR233	RR204
1112927	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112928	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112929	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112930	TP45	MP102	RR173	RR171	IC18	VC1837	RR170	RR195	—	RR204
1112931	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1112932	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1112933	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1112934	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1112935	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1112936	TP45	MP101	RR173	RR171	IC18	VC1835	RR170	RR195	RR231	RR204
1112937	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1112938	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR230	RR204
1112939	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR230	RR204
1112940	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1112941	TP45	MP100	RR173	RR171	IC19	VC1852	RR170	RR195	RR231	RR204
1112943	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1112944	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1112945	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR230	RR204
1112946	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	RR230	RR204
1112947	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	RR230	RR204
1112948	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	RR230	RR204
1112949	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	RR230	RR204
1112950	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	RR230	RR204
1112951	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1112952	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR230	RR204
1112953	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1112954	TP45	MP100	RR173	RR171	IC19	VC1833	RR170	RR195	—	RR204
1112956	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1112957	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1112958	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112959	TP45	MP100	RR173	RR171	IC19	VC1853	RR170	RR195	RR231	RR204
1112960	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112962	TP45	MP101	RR173	RR171	IC18	VC1838	RR170	RR195	RR230	RR204
1112963	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR230	RR204
1112977	TP45	MP100	RR173	RR171	IC19	VC1836	RR170	RR195	RR231	RR204
1112979	TP45	MP100	RR173	RR171	IC19	VC1843	RR170	RR195	RR231	RR204
1112983	TP45	MP100	RR173	RR171	IC19	VC1843	RR170	RR195	RR231	RR204
1112984	TP45	MP101	RR173	RR171	IC18	VC1828	RR170	RR195	RR230	RR204
1112985	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR230	RR204
1112988	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	RR231	RR204
1112989	TP45	MP100	RR173	RR171	IC19	VC1841	RR170	RR195	RR233	RR204
1112990	TP45	—	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1112991	TP45	MP101	RR173	RR171	IC18	VC1828	RR170	RR195	RR231	RR204
1112992	TP45	MP101	RR173	RR171	IC18	VC1838	RR170	RR195	—	RR204

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
1112993	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	—	RR204
1112994	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112995	TP45	MP101	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112996	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR233	RR204
1112997	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112998	TP45	MP102	RR173	RR171	IC18	—	RR170	RR195	—	RR204
1112999	TP45	MP100	RR173	RR171	IC19	—	RR170	RR195	RR231	RR204
1113386	TP47	MP118	—	—	—	—	—	RR205	RR231	—
1990354	TP407	—	—	—	—	—	—	—	—	—
16132799	TP13	—	—	RR221	—	—	—	—	—	—
24503623	TP407	—	—	—	IC28	—	—	—	—	—
25521351	TP400	—	—	—	IC28	—	—	—	—	—
25523649	TP400	—	—	—	IC28	—	—	—	—	—
91172595	TP125	MP142	EP855	EP854	—	—	—	—	—	—
91172596	TP125	MP141	EP418	EP832	—	—	—	—	—	—
91172597	—	—	EP521	EP520	—	—	—	—	—	—
94109580	MP1400	TP135	EP324	EP724	—	—	—	—	—	—
94157468	—	TP135	EP324	EP724	—	—	—	—	—	—
94178219	TP189	MP207	RR246	RR248	IC175	—	—	—	—	—
94217242	—	MP129	EP674	EP705	IC88	—	—	—	—	—
94222671	—	MP129	EP674	EP705	IC88	—	—	—	—	—
94222672	—	MP129	EP674	EP705	IC88	—	—	—	—	—
94230979	—	—	EP312	EP718	—	—	—	—	—	—
94230990	—	—	EP312	EP718	—	—	—	—	—	—
94233533	—	MP129	EP674	EP705	IC88	—	—	—	—	—
94240905	—	—	EP312	EP718	—	—	—	—	—	—
94243344	—	—	EP312	EP718	—	—	—	—	—	—
94328367	TP135	MP1400	EP324	EP724	IC70	—	—	—	—	—
94328368	TP135	MP1400	EP324	EP724	IC70	—	—	—	—	—
94419559	TP189	MP207	RR246	RR248	IC175	—	—	—	—	—
94840105	TP187	MP207	EP484	EP707	IC104	—	—	—	—	—
94843955	TP187	MP207	EP484	EP707	IC104	—	—	—	—	—
94844318	TP187	MP207	EP484	EP707	IC104	—	—	—	—	—
94845172	—	—	EP484	EP756	IC88	—	—	—	—	—
94848893	—	—	RR246	—	IC104	—	—	—	—	—
94849768	TP206	—	EP484	EP863	IC131	—	—	—	—	—
94850028	—	—	RR246	—	IC104	—	—	—	—	—
94853694	TP193	—	RR246	EP355	—	—	—	—	—	—
94854206	TP193	—	EP395	EP355	IC175	—	—	—	—	—
94855714	TP211	—	RR246	EP355	IC176	—	—	—	—	—
94858868	TP193	—	RR246	EP355	IC175	—	—	—	—	—
96052001	TP138	MP1400	EP324	RR243	—	—	—	—	—	—
96053177	—	MP1400	EP324	RR243	—	—	—	—	—	—
96054065	TP138	MP1400	EP324	RR243	—	—	—	—	—	—
96054066	—	TP138	EP324	RR243	—	—	—	—	—	—
96055619	—	MP1400	EP324	RR243	—	—	—	—	—	—
96055620	—	MP1308	EP780	EP779	—	—	—	—	—	—
96056787	—	MP1400	EP324	RR243	—	—	—	—	—	—
96060339	TP133	MP1400	EP855	EP854	—	—	—	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Module	Pick-Up	Rotor	Cap	Coil	Vac Control	Capacitor	Cap Cover	Term Block	Ground Strap
96060340	TP125	MP142	EP855	EP854	—	—	—	—	—	—
96060341	TP133	MP1400	EP855	EP854	—	—	—	—	—	—
96062560	TP133	—	EP324	EP891	—	—	—	—	—	—
96065255	TP133	MP1400	EP855	EP854	—	—	—	—	—	—
96065256	TP133	—	EP855	EP854	—	—	—	—	—	—
96066461	TP125	MP141	EP418	EP832	—	—	—	—	—	—
96067243	TP125	—	EP349	EP599	—	—	—	—	—	—
96067332	TP133	MP1400	EP855	EP854	—	—	—	—	—	—
96067333	TP133	MP1400	EP855	EP854	—	—	—	—	—	—
96068685	TP125	—	EP349	EP599	—	—	—	—	—	—
96069521	—	—	EP324	EP891	—	—	—	—	—	—

DUCELLIER

Unit No	Module	Pick-Up	Rotor	Cap
525122A	TP45	—	EP173	—
525198A	TP45	—	EP173	EP163
525210A	—	—	EP173	—
525211A	—	—	EP173	—
525320A	—	—	EP481	EP783
525352A	—	—	—	EP783
525352C	—	—	EP810	EP783

(continued on next column)

Unit No	Module	Pick-Up	Rotor	Cap
525356A	—	—	EP481	EP783
525409A	—	—	—	EP483
525409B	—	—	EP753	EP483
525409C	—	—	EP753	EP483
525409D	—	—	EP753	EP483

FIAT

Unit No	Module	Pick-Up	Rotor	Cap
4387796	—	—	EP247	EP732
4392844	TP45	—	—	EP274
4406490	TP45	—	EP477	EP471
4419073	TP45	—	EP477	EP471
4430224	—	—	EP247	EP732
4430226	TP45	—	EP477	EP471
4430227	TP45	MP300	—	EP471

(continued on next column)

Unit No	Module	Pick-Up	Rotor	Cap
4443054	TP45	—	EP477	EP471
4443055	TP45	—	EP477	EP471
4452749	TP45	MP300	EP765	EP471
4452750	TP45	MP300	—	EP274
82350469	—	—	EP247	EP240

FORD-MOTORCRAFT

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
B6BF18200A . . .	—	—	EP546	EP501	—	—
B60118200B . . .	MP717	—	EP738	EP800	—	—
D0SZ12127C . . .	MP700	MP703	FA144	FA134	—	—
D0SZ12127D . . .	MP700	MP703	FA144	FA134	—	—
D0SZ12127E . . .	MP700	MP703	FA144	FA134	—	—
D3VY12127C . . .	MP700	MP703	FA157	FA79	—	—
D4AE12127AA . . .	MP700	MP703	FA157	FA79	—	—
D4AE12127CA . . .	MP700	MP703	FA157	FA102	VC2038	—
D4AE12127HA . . .	MP700	MP703	FA157	FA79	—	—
D4AE12127IA . . .	MP700	MP703	FA157	FA79	—	—

(continued on next column)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
D4AF12127CA . . .	MP700	MP703	FA157	FA102	VC2038	—
D4AZ12127A . . .	MP700	MP703	FA157	FA79	—	—
D4AZ12127C . . .	MP700	MP703	FA157	FA102	—	—
D4AZ12127H . . .	MP700	MP703	FA157	FA79	—	—
D4BE12127EA . . .	MP700	MP703	FA157	FA79	—	—
D4BE12127FA . . .	MP700	MP703	FA157	FA79	—	—
D4BZ12127E . . .	MP700	MP703	FA157	FA79	—	—
D4BZ12127F . . .	MP700	MP703	FA157	FA79	—	—
D4DE12127BA . . .	MP700	—	FA158	FA6900	—	—
D4DE12127CA . . .	MP700	MP703	FA157	FA79	—	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
D4DE12127FA .	MP700	—	FA158	FA6900	—	—
D4DE12127LA .	MP700	—	FA158	FA6900	—	—
D4DE12127MA .	MP700	MP703	FA157	FA79	—	—
D4DE12127RA .	MP700	—	FA157	FA79	—	—
D4DZ12127C . . .	MP700	MP703	FA157	FA79	—	—
D4DZ12127F . . .	MP700	—	FA158	FA6900	—	—
D4DZ12127L . . .	MP700	—	FA158	FA6900	—	—
D4DZ12127M . . .	MP700	MP703	FA157	FA79	—	—
D4DZ12127R . . .	MP700	—	FA158	FA6900	—	—
D4HE12127CA .	MP700	MP703	FA157	FA79	—	—
D4HE12127DA .	MP700	MP703	FA157	FA79	—	—
D4HE12127EA .	MP700	MP703	FA157	FA79	—	—
D4HE12127FA .	MP700	MP703	FA157	FA79	VC2038	—
D4HE12127LA .	MP700	MP703	FA157	FA79	—	—
D4HE12127NA .	MP700	MP703	FA157	FA79	—	—
D4HZ12127C . . .	MP700	MP703	FA157	FA79	—	—
D4HZ12127D . . .	MP700	MP703	FA157	FA79	—	—
D4HZ12127E . . .	MP700	MP703	FA157	FA79	—	—
D4HZ12127F . . .	MP700	MP703	FA157	FA79	—	—
D4HZ12127L . . .	MP700	MP703	FA157	FA79	—	—
D4HZ12127N . . .	MP700	MP703	FA157	FA79	—	—
D4OE12127CA .	MP700	MP703	FA157	FA79	VC2038	—
D4OE12127DA .	MP700	MP703	FA157	FA79	—	—
D4OE12127GA .	MP700	MP703	FA157	FA79	—	—
D4OE12127KA .	MP700	MP703	FA157	FA79	—	—
D4OE12127LA .	MP700	MP703	FA157	FA79	—	—
D4OZ12127C . . .	MP700	MP703	FA157	FA79	—	—
D4OZ12127D . . .	MP700	MP703	FA157	FA79	—	—
D4OZ12127G . . .	MP700	MP703	FA157	FA79	—	—
D4OZ12127K . . .	MP700	MP703	FA157	FA79	—	—
D4PZ12127A . . .	MP700	—	FA158	FA104	—	—
D4PZ12127B . . .	MP712	—	FA158	FA104	—	—
D4PZ12127C . . .	MP712	—	FA158	FA104	—	—
D4TE12127CA .	MP711	—	FA142	FA134	—	FA146
D4TE12127EA .	MP700	—	FA158	FA6900	—	—
D4TE12127HA .	MP700	MP703	FA157	FA79	VC2037	—
D4TE12127LA .	MP700	MP703	FA157	FA79	—	—
D4TE12127NA .	MP700	MP703	FA157	FA79	—	—
D4TE12127PA .	MP700	MP703	FA157	FA79	—	—
D4TE12127TA .	MP700	MP703	FA157	FA79	—	—
D4TE12127VA .	MP700	MP703	FA157	FA79	—	—
D4TE12127YA .	MP700	MP703	FA157	FA79	—	—
D4TZ12127H . . .	MP700	MP703	FA157	FA79	—	—
D4TZ12127L . . .	MP700	MP703	FA157	FA79	—	—
D4TZ12127N . . .	MP700	MP703	FA157	FA79	—	—
D4TZ12127P . . .	MP700	MP703	FA157	FA79	—	—
D4TZ12127T . . .	MP700	MP703	FA157	FA79	—	—
D4TZ12127V . . .	MP700	MP703	FA157	FA79	—	—

(continued on next column)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
D4TZ12127Y . . .	MP700	MP703	FA157	FA79	—	—
D4UE12127CA .	MP700	MP703	FA157	FA79	—	—
D4UE12127FA .	MP700	MP703	FA157	FA79	—	—
D4UE12127HA .	MP700	MP703	FA157	FA79	—	—
D4UE12127JA .	MP700	MP703	FA157	FA102	VC2039	—
D4UZ12127C . . .	MP700	MP703	FA157	FA79	—	—
D4UZ12127F . . .	MP700	MP703	FA157	FA79	—	—
D4UZ12127H . . .	MP700	MP703	FA157	FA79	—	—
D4VE12127AA .	MP700	MP703	FA157	FA79	—	—
D4VE12127CA .	MP700	MP703	FA157	FA79	VC2037	—
D4VY12127C . . .	MP700	MP703	FA157	FA79	VC2037	—
D5AE12127AA .	MP700	MP703	FA157	FA102	—	—
D5AE12127BA .	MP700	MP703	FA157	FA102	VC2041	—
D5AE12127DA .	MP700	MP703	FA157	FA102	VC2039	—
D5AE12127EA .	MP700	MP703	FA157	FA102	VC2041	—
D5AE12127KA .	MP700	MP703	FA157	FA102	VC2039	—
D5AZ12127B . . .	MP700	MP703	FA157	FA102	—	—
D5AZ12127D . . .	MP700	MP703	FA157	FA102	—	—
D5AZ12127E . . .	MP700	MP703	FA157	FA102	—	—
D5AZ12127K . . .	MP700	MP703	FA157	FA102	—	—
D5DE12127ACA	MP712	—	FA158	FA104	VC2042	—
D5DE12127AFA	MP700	MP703	FA157	FA102	VC2041	—
D5DE12127AGA	MP700	MP703	FA157	FA102	VC2039	—
D5DE12127BA .	MP700	MP703	FA157	FA102	—	—
D5DE12127DA .	MP712	—	FA158	FA104	—	—
D5DE12127FA .	MP712	—	FA158	FA104	VC2039	—
D5DE12127HA .	MP700	MP703	FA157	FA102	—	—
D5DE12127JA .	MP700	MP703	FA157	FA102	VC2039	—
D5DE12127KA .	MP700	MP703	FA157	FA102	VC2039	—
D5DE12127LA .	MP700	MP703	FA157	FA102	—	—
D5DE12127MA .	MP700	MP703	FA157	FA102	—	—
D5DE12127NA .	MP700	MP703	FA157	FA102	—	—
D5DE12127RA .	MP712	—	FA158	FA104	VC2050	—
D5DE12127SA .	MP700	MP703	FA157	FA102	VC2038	—
D5DE12127UA .	MP712	—	FA158	FA104	VC2039	—
D5DE12127VA .	MP712	—	FA158	FA104	VC2039	—
D5DE12127YA .	MP712	—	FA158	FA104	—	—
D5DE12127ZA .	MP700	MP703	FA157	FA102	VC2037	—
D5DZ12127A . . .	MP712	—	FA158	FA104	—	—
D5DZ12127B . . .	MP700	MP703	FA157	FA102	—	—
D5DZ12127D . . .	MP712	—	FA158	FA104	—	—
D5DZ12127H . . .	MP700	MP703	FA157	FA102	—	—
D5DZ12127J . . .	MP700	MP703	FA157	FA102	—	—
D5DZ12127K . . .	MP700	MP703	FA157	FA102	—	—
D5DZ12127L . . .	MP700	MP703	FA157	FA102	—	—
D5DZ12127M . . .	MP700	MP703	FA157	FA102	—	—
D5DZ12127N . . .	MP700	MP703	FA157	FA102	—	—
D5DZ12127R . . .	MP712	—	FA158	FA104	—	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
D5DZ12127S ...	MP700	MP703	FA157	FA102	—	—
D5DZ12127T ...	MP712	—	FA158	FA104	—	—
D5DZ12127U ...	MP712	—	FA158	FA104	—	—
D5DZ12127V ...	MP712	—	FA158	FA104	—	—
D5DZ12127W ...	MP700	MP703	FA157	FA102	—	—
D5DZ12127X ...	MP700	MP703	FA157	FA102	—	—
D5FZ12127E ...	MP712	MP706	FA108	FA107	—	—
D5FZ12127F ...	MP712	MP706	FA108	FA107	—	—
D5FZ12127G ...	MP712	MP706	FA108	FA107	—	—
D5OE12127FA ...	MP700	MP703	FA157	FA102	VC2038	—
D5OZ12127F ...	MP700	MP703	FA157	FA102	—	—
D5RY12127C ...	MP712	MP706	FA108	FA107	—	—
D5RY12127D ...	MP712	MP706	FA108	FA107	—	—
D5RY12127E ...	MP712	—	FA105	FA104	—	—
D5RY12127F ...	—	—	FA105	FA104	—	—
D5TE12127AA ...	MP712	—	FA158	FA104	—	—
D5TE12127AAA ...	MP712	—	FA158	FA104	—	—
D5TE12127ABA ...	MP700	MP703	FA157	FA102	—	—
D5TE12127ADA ...	—	MP703	—	—	—	—
D5TE12127AEA ...	MP700	MP703	FA157	FA102	—	—
D5TE12127AFA ...	MP700	MP703	FA157	FA102	—	—
D5TE12127AGA ...	MP700	MP703	FA157	FA102	—	—
D5TE12127AKA ...	MP700	MP703	FA157	FA102	—	—
D5TE12127ALA ...	MP700	MP703	FA157	FA102	—	—
D5TE12127ANA ...	MP712	—	FA158	FA104	—	—
D5TE12127ASA ...	MP700	MP703	FA157	FA102	VC2049	—
D5TE12127DA ...	MP700	MP703	FA157	FA102	—	—
D5TE12127EA ...	MP700	MP703	FA157	FA102	—	—
D5TE12127FA ...	MP712	—	FA158	FA104	VC2042	—
D5TE12127JA ...	MP700	MP703	FA157	FA102	—	—
D5TE12127LA ...	MP700	MP703	FA157	FA102	—	—
D5TE12127MA ...	MP712	—	FA158	FA104	VC2050	—
D5TE12127NA ...	MP712	—	FA158	FA104	—	—
D5TE12127PA ...	MP700	MP703	FA157	FA102	—	—
D5TE12127RA ...	MP700	MP703	FA157	FA102	—	—
D5TE12127SA ...	MP700	MP703	FA157	FA102	VC2049	—
D5TE12127TA ...	MP700	MP703	FA157	FA102	—	—
D5TE12127UA ...	MP712	—	FA158	FA104	VC2050	—
D5TE12127YA ...	MP700	MP703	FA157	FA102	—	—
D5TE12127ZA ...	MP700	MP703	FA157	FA102	—	—
D5TZ12127A ...	MP712	—	FA158	FA104	—	—
D5TZ12127AB ...	MP700	MP703	FA157	FA102	—	—
D5TZ12127AC ...	MP712	—	FA158	FA104	—	—
D5TZ12127C ...	MP700	MP703	FA157	FA102	—	—
D5TZ12127D ...	MP700	MP703	FA157	FA102	—	—
D5TZ12127E ...	MP700	MP703	FA157	FA102	—	—
D5TZ12127F ...	MP712	—	FA158	FA104	—	—
D5TZ12127FA ...	MP700	MP703	FA157	FA102	—	—

(continued on next column)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
D5TZ12127GA ...	MP700	MP703	FA157	FA102	—	—
D5TZ12127HA ...	MP700	MP703	FA157	FA102	—	—
D5TZ12127J ...	MP700	MP703	FA157	FA102	—	—
D5TZ12127JA ...	MP700	MP703	FA157	FA102	—	—
D5TZ12127L ...	MP700	MP703	FA157	FA102	—	—
D5TZ12127M ...	MP700	MP703	FA157	FA102	—	—
D5TZ12127N ...	MP712	—	FA158	FA104	—	—
D5TZ12127P ...	MP712	—	FA158	FA104	—	—
D5TZ12127R ...	MP700	MP703	FA157	FA102	—	—
D5TZ12127T ...	MP700	MP703	FA157	FA102	—	—
D5TZ12127U ...	MP712	—	FA158	FA104	—	—
D5TZ12127Z ...	MP700	MP703	FA157	FA102	—	—
D5UE12127BA ...	MP700	MP703	FA157	FA102	—	—
D5UE12127CA ...	MP700	MP703	FA157	FA102	—	—
D5UE12127DA ...	MP700	MP703	FA157	FA102	—	—
D5UE12127EA ...	MP700	MP703	FA157	FA102	VC2049	—
D5UE12127HA ...	MP700	MP703	FA157	FA102	—	—
D5UZ12127A ...	MP700	MP703	FA157	FA102	—	—
D5UZ12127B ...	MP700	MP703	FA157	FA102	—	—
D5UZ12127C ...	MP700	MP703	FA157	FA102	—	—
D5UZ12127D ...	MP700	MP703	FA157	FA102	—	—
D5VE12127BA ...	MP700	MP703	FA157	FA102	VC2038	—
D5VE12127CA ...	MP700	MP703	FA157	FA102	VC2038	—
D5VY12127A ...	MP700	MP703	FA157	FA102	—	—
D5VY12127B ...	MP700	MP703	FA157	FA102	—	—
D5ZE12127AA ...	MP712	MP706	FA108	FA107	—	—
D5ZE12127BA ...	MP700	MP703	FA157	FA102	—	—
D5ZE12127EA ...	MP712	MP706	FA108	FA107	VC2043	—
D5ZE12127FA ...	MP712	MP706	FA108	FA107	VC2043	—
D5ZE12127GA ...	MP712	MP706	FA108	FA107	—	—
D5ZE12127HA ...	MP712	MP706	FA108	FA107	—	—
D5ZY12127BA ...	MP700	MP703	FA157	FA102	—	—
D5ZY12127CA ...	MP712	MP706	FA108	FA107	—	—
D5ZY12127EA ...	MP712	MP706	FA108	FA107	—	—
D5ZY12127FA ...	MP712	MP706	FA108	FA107	VC2043	—
D5ZY12127GA ...	MP703	MP706	FA108	FA107	—	—
D5ZY12127HA ...	MP712	MP706	FA108	FA107	—	—
D5ZY12127NH ...	MP712	MP706	FA108	FA107	—	—
D5ZY12127PA ...	MP712	MP706	FA108	FA107	—	—
D5ZY12127RA ...	MP712	MP706	FA108	FA107	—	—
D5ZY12127SA ...	MP712	MP706	FA108	FA107	—	—
D5ZZ12127A ...	MP712	MP706	FA108	FA107	—	—
D5ZZ12127B ...	MP700	MP703	FA157	FA102	—	—
D5ZZ12127C ...	MP712	—	FA105	FA104	—	—
D5ZZ12127D ...	MP712	—	FA105	FA104	—	—
D5ZZ12127E ...	MP712	—	FA105	FA104	—	—
D5ZZ12127F ...	MP712	MP706	FA108	FA107	—	—
D5ZZ12127FG ...	MP712	MP706	FA108	FA107	VC2043	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
D5ZZ12127G . . .	MP712	MP706	FA108	FA107	—	—
D6AE12127AA . .	MP700	MP703	FA157	FA102	VC2039	—
D6AE12127BA . .	MP700	MP703	FA157	FA102	—	—
D6AE12127CA . .	MP700	MP703	FA157	FA102	VC2039	—
D6AE12127DA . .	MP700	MP703	FA157	FA102	VC2039	—
D6AZ12127A . . .	MP700	MP703	FA157	FA102	—	—
D6AZ12127B . . .	MP700	MP703	FA157	FA102	—	—
D6AZ12127C . . .	MP700	MP703	FA157	FA102	—	—
D6AZ12127D . . .	MP700	MP703	FA157	FA102	—	—
D6BE12127BA . .	MP712	—	FA158	FA104	—	—
D6DE12127AA . .	MP712	—	FA158	FA104	VC2044	—
D6DE12127BA . .	MP712	—	FA158	FA104	—	—
D6DE12127CA . .	MP700	MP703	FA157	FA102	VC2041	—
D6DE12127EA . .	MP700	MP703	FA157	FA102	VC2041	—
D6DE12127GA . .	MP712	—	FA158	FA104	VC2044	—
D6DE12127JA . .	MP700	MP703	FA157	FA102	VC2041	—
D6DE12127KA . .	MP712	—	FA158	FA104	—	—
D6DZ12127A . . .	MP712	—	FA158	FA104	—	—
D6DZ12127B . . .	MP712	—	FA158	FA104	—	—
D6DZ12127C . . .	MP700	MP703	FA157	FA102	—	—
D6DZ12127D . . .	MP712	—	FA158	FA104	—	—
D6DZ12127E . . .	MP700	MP703	FA157	FA102	—	—
D6DZ12127F . . .	MP700	MP703	FA157	FA102	—	—
D6DZ12127G . .	MP712	—	FA158	FA104	—	—
D6DZ12127J . . .	MP700	MP703	FA157	FA102	—	—
D6DZ12127K . . .	MP712	—	FA158	FA104	—	—
D6EE12127AA . .	MP712	MP706	FA108	FA107	VC2043	—
D6EE12127BA . .	MP712	MP706	FA108	FA107	—	—
D6EE12127DA . .	MP712	MP706	FA108	FA107	VC2043	—
D6FZ12127A . . .	MP712	MP706	FA108	FA107	—	—
D6FZ12127B . . .	MP712	MP706	FA108	FA107	—	—
D6FZ12127D . . .	MP712	MP706	FA108	FA107	—	—
D6HE12127FA . .	MP700	MP703	FA157	FA102	—	—
D6HE12127GA . .	MP700	MP703	FA157	FA102	—	—
D6HE12127HA . .	MP700	MP703	FA157	FA102	—	—
D6HZ12127D . . .	MP700	MP703	FA157	FA102	—	—
D6HZ12127E . . .	MP700	MP703	FA157	FA102	—	—
D6OE12127AA . .	MP700	MP703	FA157	FA102	VC2039	—
D6OZ12127A . .	MP700	MP703	FA157	FA102	—	—
D6RY12127A . .	MP712	—	FA159	FA136	—	—
D6RY12127B . .	MP712	—	FA159	FA136	—	—
D6TE12127AA . .	MP712	—	FA158	FA104	VC2050	—
D6TE12127CA . .	MP700	MP703	FA157	FA102	VC2049	—
D6TE12127DA . .	MP700	MP703	FA157	FA102	VC2039	—
D6TE12127EA . .	MP712	—	FA158	FA104	VC2043	—
D6TE12127FA . .	MP700	MP703	FA157	FA102	—	—
D6TE12127GA . .	MP712	—	FA158	FA104	—	—
D6TE12127HA . .	MP700	MP703	FA157	FA102	VC2039	—

(continued on next column)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
D6TE12127JA . .	MP700	MP703	FA157	FA102	VC2039	—
D6TE12127KA . .	MP700	MP703	FA157	FA102	—	—
D6TZ12127A . . .	MP712	—	FA158	FA104	—	—
D6TZ12127C . . .	MP700	MP703	FA157	FA102	—	—
D6TZ12127D . . .	MP700	MP703	FA157	FA102	—	—
D6TZ12127E . . .	MP700	MP703	FA157	FA102	—	—
D6TZ12127F . . .	MP700	MP703	FA157	FA102	—	—
D6TZ12127G . . .	MP712	—	FA158	FA104	—	—
D6TZ12127H . . .	MP700	MP703	FA157	FA102	—	—
D6TZ12127J . . .	MP712	—	FA158	FA104	—	—
D6TZ12127K . . .	MP700	MP703	FA157	FA102	—	—
D6TZ12127L . . .	MP700	MP703	FA157	FA102	—	—
D6TZ12127M . . .	MP700	MP703	FA157	FA102	—	—
D6UE12127AA . .	MP700	MP703	FA157	FA102	—	—
D6UE12127BA . .	MP700	MP703	FA157	FA102	VC2039	—
D6UE12127CA . .	MP700	MP703	FA157	FA102	VC2041	—
D6UE12127CV . .	MP700	MP703	FA157	FA102	—	—
D6UZ12127A . . .	MP700	MP703	FA157	FA102	—	—
D6UZ12127B . . .	MP700	MP703	FA157	FA102	—	—
D6UZ12127C . . .	MP700	MP703	FA157	FA102	—	—
D6UZ12127D . . .	MP700	MP703	FA157	FA102	—	—
D6VE12127AA . .	MP700	MP703	FA157	FA102	VC2041	—
D6VE12127BA . .	MP700	MP703	FA157	FA102	VC2041	—
D6VE12127CA . .	MP700	MP703	FA157	FA102	VC2041	—
D6VE12127DA . .	MP700	MP703	FA144	FA134	VC2038	—
D6VY12127A . . .	MP700	MP703	FA157	FA102	—	—
D6VY12127AA . .	MP700	MP703	FA157	FA102	VC2041	—
D6VY12127B . . .	MP700	MP703	FA157	FA102	—	—
D6VY12127C . . .	MP700	MP703	FA157	FA102	—	—
D6ZE12127AA . .	MP700	MP703	FA157	FA102	VC2041	—
D6ZZ12127A . . .	MP712	—	FA105	FA104	—	—
D6ZZ12127B . . .	MP712	—	FA105	FA104	—	—
D6ZZ12127C . . .	MP712	—	FA105	FA104	—	—
D6ZZ12127D . . .	MP712	—	FA105	FA104	—	—
D6ZZ12127F . . .	MP700	MP703	FA157	FA102	—	—
D7AE12127BA . .	MP700	MP703	FA144	FA134	VC2039	—
D7AE12127CA . .	MP700	MP703	FA144	FA134	—	FA151
D7AE12127DA . .	MP700	MP703	FA144	FA134	VC2041	—
D7AE12127GA . .	MP700	MP703	FA144	FA134	—	—
D7AE12127KA . .	MP700	MP703	FA144	FA134	VC2039	—
D7AE12127NA . .	MP700	MP703	FA144	FA134	VC2039	—
D7AE12127PA . .	MP700	MP703	FA144	FA134	VC2039	—
D7AE12127UA . .	MP700	MP703	FA144	FA134	VC2041	—
D7AE12127VA . .	MP700	MP703	FA144	FA134	VC2039	—
D7AZ12127A . . .	MP700	MP703	FA144	FA134	—	—
D7AZ12127C . . .	MP700	MP703	FA144	FA134	—	—
D7AZ12127D . . .	MP700	MP703	FA144	FA134	—	—
D7AZ12127F . . .	MP700	MP703	FA144	FA134	—	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
D7AZ12127H ...	MP700	MP703	FA144	FA134	—	—
D7AZ12127J ...	MP700	MP703	FA144	FA134	—	—
D7AZ12127K ...	MP700	MP703	FA144	FA134	—	—
D7AZ12127L ...	MP700	MP703	FA144	FA134	—	—
D7BE12127AA ...	MP700	MP703	FA144	FA134	VC2039	FA151
D7BE12127CA ...	MP712	—	FA159	FA136	—	—
D7BE12127DA ...	MP712	—	FA159	FA136	VC2044	—
D7BE12127EA ...	MP712	—	FA159	FA136	—	—
D7BE12127FA ...	MP712	—	FA159	FA136	—	FA139
D7BE12127GA ...	MP712	—	FA159	FA136	—	—
D7BE12127JA ...	MP700	MP703	FA144	FA134	VC2039	FA151
D7BZ12127A ...	MP700	MP703	FA144	FA134	VC2039	FA151
D7BZ12127C ...	MP712	—	FA159	FA136	—	FA139
D7BZ12127D ...	MP712	—	FA159	FA136	VC2044	FA139
D7BZ12127E ...	MP712	—	FA159	FA136	—	FA139
D7BZ12127G ...	MP700	MP703	FA144	FA134	VC2039	FA151
D7BZ12127H ...	MP700	MP703	FA144	FA134	—	FA151
D7BZ12127K ...	MP700	MP703	FA144	FA134	VC2039	FA151
D7BZ12127L ...	MP700	MP703	FA144	FA134	VC2039	FA151
D7BZ12127M ...	MP712	—	FA159	FA136	—	FA139
D7DE12127AA ...	MP700	MP703	FA144	FA134	VC2039	—
D7DE12127CA ...	MP700	MP703	FA144	FA134	VC2039	—
D7DE12127DA ...	MP700	MP703	FA144	FA134	VC2039	—
D7DE12127FA ...	MP700	MP703	FA144	FA134	VC2039	—
D7DE12127GA ...	MP700	MP703	FA144	FA134	—	—
D7DE12127HA ...	MP700	MP703	FA144	FA134	VC2039	—
D7DE12127JA ...	MP700	MP703	FA144	FA134	—	—
D7DZ12127A ...	MP700	MP703	FA144	FA134	—	—
D7DZ12127C ...	MP712	—	FA159	FA136	—	—
D7DZ12127D ...	MP712	—	FA159	FA136	—	—
D7DZ12127E ...	MP712	—	FA159	FA136	—	—
D7DZ12127G ...	MP700	MP703	FA144	FA134	—	—
D7DZ12127H ...	MP700	MP703	FA144	FA134	—	—
D7DZ12127K ...	MP700	MP703	FA144	FA134	—	—
D7DZ12127L ...	MP700	MP703	FA144	FA134	—	—
D7DZ12127M ...	MP712	—	FA159	FA136	—	—
D7EE12127BA ...	MP712	MP706	FA155	FA135	—	—
D7EE12127CA ...	MP712	MP706	FA155	FA135	—	—
D7EE12127DA ...	MP712	MP706	FA155	FA135	—	—
D7EE12127EA ...	MP712	MP706	FA155	FA135	—	—
D7EE12127FA ...	MP712	MP706	FA155	FA135	VC2043	—
D7EE12127GA ...	MP712	MP706	FA155	FA135	—	—
D7EE12127HA ...	MP712	MP706	FA155	FA135	—	—
D7FZ12127B ...	MP712	MP706	FA155	FA135	—	—
D7FZ12127C ...	MP712	MP706	FA155	FA135	—	—
D7FZ12127D ...	MP712	MP706	FA155	FA135	—	—
D7FZ12127E ...	MP712	MP706	FA155	FA135	—	—
D7FZ12127G ...	MP712	MP706	FA155	FA135	—	—

(continued on next column)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
D7FZ12127H ...	MP712	MP706	FA155	FA135	—	—
D7FZ12127J ...	MP712	MP706	FA155	FA135	—	—
D7HZ12127A ...	MP700	MP703	FA157	FA102	—	—
D7OE12127DA ...	MP700	MP703	FA144	FA134	VC2039	—
D7OZ12127B ...	MP700	MP703	FA144	FA134	—	—
D7TE12127ABA ...	MP700	MP703	FA144	FA134	—	—
D7TE12127ADA ...	MP700	MP703	FA144	FA134	—	—
D7TE12127AHA ...	MP700	MP703	FA144	FA134	—	—
D7TE12127AJA ...	MP712	—	FA159	FA136	—	—
D7TE12127AKA ...	MP712	—	FA159	FA136	—	—
D7TE12127ALA ...	MP700	MP703	FA144	FA134	—	—
D7TE12127AMA ...	MP700	MP703	FA144	FA134	—	—
D7TE12127APA ...	MP700	MP703	FA144	FA134	—	—
D7TE12127BA ...	MP700	MP703	FA144	FA134	VC2039	—
D7TE12127EA ...	MP700	MP703	FA144	FA134	VC2039	—
D7TE12127GA ...	MP712	—	FA159	FA136	—	—
D7TE12127JA ...	MP700	MP703	FA144	FA134	VC2039	—
D7TE12127LA ...	MP700	MP703	FA144	FA134	VC2041	—
D7TE12127MA ...	MP712	—	FA159	FA136	—	—
D7TE12127NA ...	MP700	MP703	FA144	FA134	VC2039	—
D7TE12127PA ...	MP700	MP703	FA144	FA134	VC2039	—
D7TE12127RA ...	MP700	MP703	FA144	FA134	—	—
D7TE12127TA ...	MP712	—	FA159	FA136	—	—
D7TE12127UA ...	MP712	—	FA159	FA136	—	—
D7TZ12127AA ...	MP700	MP703	FA144	FA134	—	—
D7TZ12127AB ...	MP700	MP703	FA144	FA134	—	—
D7TZ12127AC ...	MP700	MP703	FA144	FA134	—	—
D7TZ12127AD ...	MP712	—	FA159	FA136	—	—
D7TZ12127AE ...	MP712	—	FA159	FA136	—	—
D7TZ12127AF ...	MP700	MP703	FA144	FA134	—	—
D7TZ12127AL ...	MP700	MP703	FA144	FA134	—	—
D7TZ12127AM ...	MP700	MP703	FA144	FA134	—	—
D7TZ12127B ...	MP700	MP703	FA144	FA134	—	—
D7TZ12127E ...	MP700	MP703	FA144	FA134	—	—
D7TZ12127G ...	MP712	—	FA159	FA136	—	—
D7TZ12127J ...	MP700	MP703	FA144	FA134	—	—
D7TZ12127L ...	MP700	MP703	FA144	FA134	—	—
D7TZ12127M ...	MP712	—	FA159	FA136	—	—
D7TZ12127N ...	MP700	MP703	FA144	FA134	—	—
D7TZ12127P ...	MP700	MP703	FA144	FA134	—	—
D7TZ12127R ...	MP700	MP703	FA144	FA134	—	—
D7TZ12127T ...	MP712	—	FA159	FA136	—	—
D7TZ12127U ...	MP712	—	FA159	FA136	—	—
D7UE12127AA ...	MP700	MP703	FA144	FA134	—	—
D7UE12127BA ...	MP700	MP703	FA144	FA134	—	—
D7UE12127DA ...	MP700	MP703	FA144	FA134	—	—
D7UE12127EA ...	MP700	MP703	FA144	FA134	—	—
D7UE12127F ...	MP700	MP703	FA144	FA134	—	FA151

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
D7UE12127FA .	MP700	MP703	FA144	FA134	—	—
D7UE12127H .	MP700	MP703	FA144	FA134	—	FA151
D7UE12127J .	MP700	MP703	FA144	FA134	—	FA151
D7UE12127JA .	MP700	MP703	FA144	FA134	—	—
D7UE12127LA .	MP700	MP703	FA144	FA134	—	—
D7UZ12127A .	MP700	MP703	FA144	FA134	—	—
D7UZ12127B .	MP700	MP703	FA144	FA134	—	—
D7UZ12127E .	MP700	MP703	FA144	FA134	—	—
D7UZ12127F .	MP700	MP703	FA144	FA134	—	—
D7UZ12127H .	MP700	MP703	FA144	FA134	—	—
D7UZ12127J .	MP700	MP703	FA144	FA134	—	—
D7VE12127CA .	MP700	MP703	FA144	FA134	VC2041	—
D7VE12127DA .	MP700	MP703	FA144	FA134	—	—
D7VY12127A .	MP700	MP703	FA144	FA134	—	—
D7VY12127B .	MP700	MP703	FA144	FA134	—	—
D7VY12127C .	MP700	MP703	FA144	FA134	—	—
D7ZE12127BA .	MP700	MP703	FA144	FA134	VC2041	—
D7ZE12127CA .	MP700	MP703	FA144	FA134	VC2039	—
D7ZZ12127C .	MP712	—	FA159	FA136	—	—
D7ZZ12127D .	MP700	MP703	FA144	FA134	—	—
D7ZZ12127E .	MP700	MP703	FA144	FA134	—	—
D7ZZ12127F .	MP700	MP703	FA144	FA134	—	—
D8AE12127ABA .	MP712	—	FA159	FA136	—	—
D8AE12127BA .	MP700	MP703	FA144	FA134	VC2051	—
D8AE12127EA .	MP700	MP703	FA144	FA134	—	—
D8AE12127GA .	MP700	MP703	FA144	FA134	—	—
D8AE12127HA .	MP700	MP703	FA144	FA134	VC2051	—
D8AE12127JA .	MP700	MP703	FA144	FA134	VC2051	—
D8AE12127LA .	MP700	MP703	FA144	FA134	VC2051	—
D8AE12127MA .	MP700	MP703	FA144	FA134	VC2051	—
D8AE12127NA .	MP700	MP703	FA144	FA134	VC2025	—
D8AE12127RA .	MP700	MP703	FA144	FA134	—	—
D8AZ12127A .	MP700	MP703	FA144	FA134	—	—
D8AZ12127B .	MP700	MP703	FA144	FA134	—	—
D8AZ12127C .	MP700	MP703	FA144	FA134	—	—
D8AZ12127D .	MP700	MP703	FA144	FA134	—	—
D8AZ12127E .	MP700	MP703	FA144	FA134	—	—
D8AZ12127F .	MP700	MP703	FA144	FA134	—	—
D8AZ12127G .	MP700	MP703	FA144	FA134	—	—
D8BE12127BA .	MP712	—	FA159	FA136	—	FA139
D8BE12127CA .	MP712	—	FA159	FA136	VC2044	—
D8BE12127DA .	MP700	MP703	FA144	FA134	—	—
D8BE12127EA .	MP712	—	FA159	FA136	VC2044	—
D8BE12127FA .	MP712	—	FA159	FA136	—	—
D8BE12127HA .	MP712	—	FA159	FA136	—	—
D8BE12127JA .	MP712	—	FA159	FA136	—	—
D8BE12127KA .	MP712	—	FA159	FA136	VC2043	—
D8BE12127LA .	MP712	—	FA159	FA136	—	FA139

(continued on next column)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
D8BE12127MA .	MP712	—	FA159	FA136	—	FA139
D8BE12127NA .	MP712	—	FA159	FA136	—	FA139
D8BZ12127A .	MP712	—	FA159	FA136	—	—
D8BZ12127B .	MP700	MP703	FA144	FA134	—	—
D8BZ12127C .	MP712	—	FA159	FA136	—	—
D8BZ12127D .	MP712	—	FA159	FA136	—	—
D8BZ12127E .	MP712	—	FA159	FA136	—	—
D8DE12127AA .	—	—	FA126	FA124	—	—
D8DE12127CA .	MP712	—	FA159	FA136	—	—
D8DE12127DA .	MP700	MP703	FA144	FA134	—	—
D8DE12127EA .	MP700	MP703	FA144	FA134	—	—
D8DZ12127A .	MP712	—	FA159	FA136	—	—
D8DZ12127AA .	MP700	MP703	FA144	FA134	VC2039	FA151
D8DZ12127B .	MP700	MP703	FA144	FA134	—	—
D8DZ12127C .	MP712	—	FA159	FA136	—	—
D8DZ12127D .	MP700	MP703	FA144	FA134	—	—
D8DZ12127E .	MP712	—	FA159	FA136	—	—
D8DZ12127F .	MP700	MP703	FA144	FA134	—	—
D8OE12127AA .	MP700	MP703	FA144	FA134	VC2039	—
D8OZ12127A .	MP700	MP703	FA144	FA134	—	—
D8PE12127AA .	MP712	—	FA159	FA136	—	—
D8PZ12127A .	MP712	—	FA159	FA136	—	—
D8RZ12127A .	—	—	FA123	FA122	—	—
D8TE12127AAA .	MP712	—	FA159	FA136	—	—
D8TE12127AKA .	MP712	—	FA159	FA136	—	—
D8TE12127ALA .	MP712	—	FA159	FA136	—	—
D8TE12127AMA .	MP712	—	FA159	FA136	—	—
D8TE12127APA .	MP712	—	FA159	FA136	—	—
D8TE12127ARA .	MP712	—	FA159	FA136	—	—
D8TE12127ATA .	MP712	—	FA159	FA136	—	—
D8TE12127AZ .	MP712	—	FA158	FA104	—	—
D8TE12127BA .	MP700	MP703	FA144	FA134	—	—
D8TE12127DA .	MP700	MP703	FA144	FA134	—	—
D8TE12127FA .	MP700	MP703	FA144	FA134	VC2039	—
D8TE12127PA .	MP700	MP703	FA144	FA134	VC2039	—
D8TE12127RA .	MP700	MP703	FA144	FA134	—	—
D8TE12127UA .	MP700	MP703	FA144	FA134	—	—
D8TE12127YA .	MP712	—	FA159	FA136	—	—
D8TE12127ZA .	MP712	—	FA159	FA136	—	—
D8TZ12127A .	MP700	MP703	FA144	FA134	—	—
D8TZ12127AB .	MP712	—	FA159	FA136	—	—
D8TZ12127AC .	MP712	—	FA159	FA136	—	—
D8TZ12127AR .	MP712	—	FA159	FA136	—	—
D8TZ12127AT .	MP712	—	FA159	FA136	—	—
D8TZ12127B .	MP712	—	FA159	FA136	—	—
D8TZ12127C .	MP700	MP703	FA144	FA134	—	—
D8TZ12127F .	MP700	MP703	FA144	FA134	—	—
D8TZ12127P .	MP700	MP703	FA144	FA134	—	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
D8TZ12127R ...	MP700	MP703	FA144	FA134	—	—
D8TZ12127S ...	MP712	—	FA159	FA136	—	—
D8TZ12127U ...	MP700	MP703	FA144	FA134	—	—
D8TZ12127Z ...	MP712	—	FA159	FA136	—	—
D8UE12127AA ...	MP700	MP703	FA144	FA134	—	—
D8UE12127CA ...	MP700	MP703	FA144	FA134	—	—
D8UE12127DA ...	MP700	MP703	FA144	FA134	—	—
D8UE12127EA ...	MP712	—	FA159	FA136	—	—
D8UZ12127A ...	MP700	MP703	FA144	FA134	—	—
D8UZ12127C ...	MP700	MP703	FA144	FA134	—	—
D8UZ12127D ...	MP700	MP703	FA144	FA134	—	—
D8UZ12127E ...	MP712	—	FA159	FA136	—	—
D8ZE12127ADA ...	MP700	MP703	FA144	FA134	VC2051	FA151
D8ZE12127BA ...	MP700	MP703	FA144	FA134	VC2041	—
D8ZE12127CA ...	MP700	MP703	FA144	FA134	VC2051	—
D8ZE12127DA ...	MP700	MP703	FA144	FA134	VC2051	—
D8ZZ12127A ...	MP700	MP703	FA144	FA134	—	—
D8ZZ12127B ...	MP700	MP703	FA144	FA134	—	—
D8ZZ12127C ...	MP712	—	FA159	FA136	—	—
D8ZZ12127D ...	MP712	—	FA159	FA136	—	—
D9AE12127AAA ...	MP700	MP703	FA144	FA134	VC2039	—
D9AE12127ABA ...	MP700	MP703	FA144	FA134	—	—
D9AE12127ACA ...	MP700	MP703	FA144	FA134	—	—
D9AE12127AEA ...	MP700	MP703	FA144	FA134	—	—
D9AE12127AGA ...	MP700	MP703	FA144	FA134	—	—
D9AE12127BA ...	MP700	MP703	FA126	FA124	—	—
D9AE12127DA ...	MP700	MP703	FA127	FA156	—	—
D9AE12127PA ...	MP700	MP703	FA144	FA134	VC2051	—
D9AE12127TA ...	MP700	MP703	FA144	FA134	—	—
D9AE12127YA ...	MP700	MP703	FA144	FA134	—	—
D9AE12127ZA ...	MP700	MP703	FA144	FA134	VC2051	—
D9AZ12127A ...	MP700	MP703	FA144	FA134	—	—
D9AZ12127AA ...	MP700	MP703	FA144	FA134	—	—
D9AZ12127B ...	MP700	MP703	FA126	FA124	—	—
D9AZ12127BA ...	MP700	MP703	FA144	FA134	—	—
D9AZ12127C ...	MP700	MP703	FA126	FA124	—	—
D9AZ12127CA ...	MP700	MP703	FA144	FA134	—	FA151
D9AZ12127D ...	MP700	MP703	FA127	FA156	—	—
D9AZ12127DA ...	MP700	MP703	FA144	FA134	—	FA151
D9AZ12127H ...	MP700	MP703	FA144	FA134	—	—
D9AZ12127K ...	MP700	MP703	FA144	FA134	—	—
D9AZ12127TA ...	MP700	MP703	FA144	FA134	—	FA151
D9AZ12127Y ...	MP700	MP703	FA144	FA134	—	—
D9AZ12127Z ...	MP700	MP703	FA144	FA134	—	—
D9BE12127CA ...	MP700	MP703	FA144	FA134	VC2041	—
D9BE12127DA ...	MP712	—	FA159	FA136	—	—
D9BE12127EA ...	MP712	—	FA159	FA136	VC2043	—
D9BE12127FA ...	MP700	MP703	FA144	FA134	VC2051	—

(continued on next column)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
D9BZ12127C ...	MP712	—	FA159	FA136	—	—
D9BZ12127D ...	MP712	—	FA159	FA136	—	—
D9BZ12127F ...	MP700	MP703	FA144	FA134	—	—
D9DE12127CA ...	MP712	—	FA159	FA136	—	—
D9DZ12127C ...	MP712	—	FA159	FA136	—	—
D9EE12127AA ...	MP712	MP706	FA155	FA135	—	—
D9FZ12127A ...	MP712	MP706	FA155	FA135	—	—
D9HZ12127AS ...	MP700	—	FA144	FA102	—	—
D9HZ12127AU ...	MP700	—	FA144	FA102	—	—
D9HZ12127V ...	MP700	MP703	FA144	FA134	—	—
D9JE12127BA ...	—	MP706	—	—	—	—
D9OZ12127B ...	MP700	MP703	FA144	FA134	—	—
D9OZ12127C ...	MP700	MP703	FA144	FA134	—	—
D9PE12127BA ...	MP712	—	FA158	FA104	—	—
D9PE12127CA ...	MP712	—	FA158	FA104	—	—
D9PE12127EA ...	MP712	—	FA158	FA104	—	—
D9SE12127AA ...	MP700	MP703	FA144	FA134	—	—
D9SE12127BA ...	MP700	MP703	FA144	FA134	—	—
D9SZ12127A ...	MP700	MP703	FA144	FA134	—	—
D9TE12127AAA ...	MP712	—	FA159	FA136	—	—
D9TE12127ACA ...	MP712	—	FA159	FA136	—	—
D9TE12127ADA ...	MP712	—	FA159	FA136	—	—
D9TE12127AEA ...	MP712	—	FA159	FA136	—	—
D9TE12127AFA ...	MP712	—	FA159	FA136	—	—
D9TE12127AGA ...	MP700	MP703	FA144	FA134	—	—
D9TE12127AHA ...	MP700	MP703	FA144	FA134	—	—
D9TE12127AJA ...	MP700	MP703	FA144	FA134	—	—
D9TE12127AKA ...	MP700	MP703	FA144	FA134	—	—
D9TE12127AMA ...	MP700	MP703	FA144	FA134	—	—
D9TE12127ANA ...	MP700	MP703	FA144	FA134	—	—
D9TE12127APA ...	MP700	MP703	FA144	FA134	—	—
D9TE12127ASA ...	MP700	—	FA144	FA102	—	—
D9TE12127ATA ...	MP700	MP703	FA144	FA134	—	—
D9TE12127AUA ...	MP700	—	FA144	FA102	—	—
D9TE12127AVA ...	MP700	—	FA144	FA102	—	—
D9TE12127DA ...	MP700	MP703	FA144	FA134	—	—
D9TE12127EA ...	MP700	MP703	FA144	FA134	—	—
D9TE12127GA ...	MP700	MP703	FA144	FA134	—	—
D9TE12127NA ...	MP700	MP703	FA144	FA134	—	—
D9TE12127SA ...	MP712	—	FA159	FA136	—	—
D9TE12127TA ...	MP712	—	FA159	FA136	—	—
D9TE12127UA ...	MP712	—	FA159	FA136	—	—
D9TE12127VA ...	MP700	MP703	FA144	FA134	—	—
D9TE12127YA ...	MP712	—	FA159	FA136	—	—
D9TZ12127AD ...	MP712	—	FA159	FA136	—	—
D9TZ12127AE ...	MP712	—	FA159	FA136	—	—
D9TZ12127AF ...	MP712	—	FA159	FA136	—	—
D9TZ12127AH ...	MP700	MP703	FA144	FA134	—	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
D9TZ12127AJ	MP700	MP703	FA144	FA134	—	—
D9TZ12127AP	MP700	MP703	FA144	FA134	—	—
D9TZ12127AT	MP700	MP703	FA144	FA134	—	—
D9TZ12127AUA	MP700	MP703	FA144	FA134	—	FA151
D9TZ12127G	MP700	MP703	FA144	FA134	—	—
D9TZ12127H	MP700	MP703	FA144	FA134	—	—
D9TZ12127J	MP700	MP703	FA144	FA134	—	—
D9TZ12127L	MP700	MP703	FA144	FA134	—	—
D9UE12127BA	MP700	MP703	FA144	FA134	—	—
D9UE12127CA	MP700	MP703	FA144	FA134	—	—
D9UE12127DA	MP700	MP703	FA144	FA134	—	—
D9UE12127EA	MP712	—	FA159	FA136	—	—
D9UE12127FA	MP712	—	FA159	FA136	—	—
D9UE12127HA	MP700	MP703	FA144	FA134	—	—
D9UE12127JA	MP712	—	FA159	FA136	—	—
D9UE12127KA	MP712	—	FA159	FA136	—	—
D9UE12127LA	MP700	MP703	FA144	FA134	—	—
D9UE12127MA	MP712	—	FA159	FA136	—	—
D9UE12127NA	MP712	—	FA159	FA136	—	—
D9UE12127PA	MP700	MP703	FA144	FA134	—	—
D9UE12127RA	MP700	MP703	FA144	FA134	—	—
D9UE12127SA	MP700	MP703	FA144	FA134	—	—
D9UE12127UA	MP712	—	FA159	FA136	—	—
D9UZ12127A	MP712	—	FA159	FA136	—	—
D9UZ12127B	MP700	MP703	FA144	FA134	—	—
D9UZ12127K	MP712	—	FA159	FA136	—	—
D9UZ12127L	MP700	MP703	FA144	FA134	—	—
D9UZ12127M	MP712	—	FA159	FA136	—	—
D9UZ12127N	MP712	—	FA159	FA136	—	—
D9UZ12127P	MP700	MP703	FA144	FA134	—	—
D9UZ12127R	MP700	MP703	FA144	FA134	—	—
D9ZE12127CA	MP700	MP703	FA144	FA134	—	—
D9ZE12127EA	MP712	MP706	FA155	FA135	—	—
D9ZE12127FA	MP712	MP706	FA155	FA135	—	—
D9ZE12127GA	MP712	MP706	FA155	FA135	—	—
D9ZZ12127A	MP712	MP706	FA155	FA135	—	—
D9ZZ12127B	MP712	MP706	FA155	FA135	—	—
D9ZZ12127C	MP700	MP703	FA144	FA134	—	—
D9ZZ12127D	MP700	MP703	FA144	FA134	—	—
D9ZZ12127E	MP712	—	FA159	FA136	—	—
D9ZZ12127F	—	—	EP407	EP406	—	—
D9ZZ12127G	—	—	EP407	EP406	—	—
D9ZZ12127J	MP712	MP706	FA155	FA135	—	—
D52E12127CA	MP712	MP706	FA108	FA107	—	—
D52E12127EA	MP712	MP706	FA108	FA107	—	—
D52E12127FA	MP712	MP706	FA108	FA107	—	—
D52E12127NA	MP712	MP706	FA108	FA107	—	—
D52E12127PA	MP712	MP706	FA108	FA107	VC2044	—

(continued on next column)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
D52E12127RA	MP712	MP706	FA108	FA107	—	—
D52E12127SA	MP712	MP706	FA108	FA107	—	—
D58E12127FA	MP712	MP706	FA108	FA107	—	—
D58E12127GA	MP712	MP706	FA108	FA107	—	—
D77TF12100AA	—	—	EP407	EP406	—	—
D77TF12100CA	—	—	EP407	EP406	—	—
D84Y12127B	—	—	FA126	FA124	—	—
D94E12127AA	MP700	MP703	FA127	FA156	—	—
D94E12127BA	—	—	FA126	FA124	—	—
D94E12127DA	—	—	FA127	FA156	—	FA162
D94E12127TA	—	—	FA144	FA134	—	FA151
D94Y12127A	MP700	MP703	FA127	FA156	—	—
E0AE12127FA	MP700	MP703	FA144	FA134	—	—
E0AZ12127A	MP700	MP703	FA144	FA134	—	—
E0AZ12127F	MP700	MP703	FA144	FA134	—	—
E0BE12127AA	MP700	MP703	FA144	FA134	VC2041	FA151
E0BE12127BA	MP700	MP703	FA144	FA134	—	—
E0BE12127CA	MP712	—	FA159	FA136	—	—
E0EE12127BA	MP712	MP706	FA155	FA135	—	—
E0EE12127CA	MP712	MP706	FA155	FA135	—	—
E0EE12127DA	MP712	MP706	FA155	FA135	—	—
E0EE12127FA	MP712	MP706	FA155	FA135	—	—
E0FZ12127B	MP712	MP706	FA155	FA135	—	—
E0FZ12127C	MP712	MP706	FA155	FA135	—	—
E0FZ12127D	MP712	MP706	FA155	FA135	—	—
E0FZ12127F	MP712	MP706	FA155	FA135	—	—
E0HZ12127AV	MP700	—	FA144	FA136	—	—
E0PE12127AMA	MP700	MP703	FA144	FA134	—	—
E0PZ12127AM	MP700	MP703	FA144	FA134	—	—
E0SE12127CA	MP700	MP703	FA144	FA134	—	—
E0SE12127DA	MP700	MP703	FA144	FA134	—	—
E0SZ12127AM	MP700	MP703	FA144	FA134	—	—
E0SZ12127C	MP700	MP703	FA144	FA134	VC2041	FA151
E0SZ12127D	MP700	MP703	FA144	FA134	VC2041	FA151
E0SZ12127E	MP700	MP703	FA144	FA134	VC2041	FA151
E0TE12127AA	MP712	—	FA159	FA136	—	—
E0TE12127BA	MP700	MP703	FA144	FA134	—	—
E0TE12127DA	MP700	MP703	FA144	FA134	—	—
E0TE12127EA	MP712	—	FA159	FA136	—	—
E0TE12127FA	MP712	—	FA159	FA136	—	—
E0TE12127GA	MP712	—	FA159	FA136	—	—
E0TE12127HA	MP700	MP703	FA144	FA134	—	—
E0TE12127JA	MP700	MP703	FA144	FA134	—	—
E0TE12127KA	MP712	—	FA159	FA136	—	—
E0TE12127LA	MP700	MP703	FA144	FA134	—	—
E0TE12127MA	MP700	MP703	FA144	FA134	—	—
E0TE12127NA	MP700	MP703	FA144	FA134	—	—
E0TE12127PA	MP712	—	FA159	FA136	—	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
E0TE12127RA	MP700	MP703	FA144	FA134	—	—
E0TE12127SA	MP700	MP703	FA144	FA134	—	FA151
E0TZ12127B	MP700	MP703	FA144	FA134	—	—
E0TZ12127D	MP700	MP703	FA144	FA134	—	—
E0TZ12127E	MP712	—	FA159	FA136	—	—
E0TZ12127F	MP712	—	FA159	FA136	—	—
E0TZ12127G	MP712	—	FA159	FA136	—	—
E0TZ12127H	MP700	MP703	FA144	FA134	—	—
E0TZ12127J	MP700	MP703	FA144	FA134	—	—
E0TZ12127K	MP712	—	FA159	FA136	—	—
E0TZ12127L	MP700	MP703	FA144	FA134	—	—
E0TZ12127M	MP700	MP703	FA144	FA134	—	—
E0TZ12127N	MP700	MP703	FA144	FA134	—	—
E0TZ12127P	MP712	—	FA159	FA136	—	—
E0TZ12127R	MP700	MP703	FA144	FA134	—	—
E0TZ12127S	MP700	MP703	FA144	FA134	—	—
E0TZ12127SA	MP700	MP703	FA144	FA134	—	FA151
E0UE12127AA	MP712	—	FA159	FA136	—	—
E0UE12127BA	MP712	—	FA159	FA136	—	—
E0UE12127CA	—	MP703	FA144	FA134	—	—
E0UE12127DA	—	MP703	FA144	FA134	—	—
E0UZ12127A	MP712	—	FA159	FA136	—	—
E0UZ12127B	MP712	—	FA159	FA136	—	—
E0UZ12127C	MP700	MP703	FA144	FA134	—	—
E0UZ12127D	MP700	MP703	FA144	FA134	—	—
E0VE12127AA	MP700	MP703	FA144	FA134	—	—
E0VY12127A	MP700	MP703	FA144	FA134	—	—
E0ZE12127BA	MP712	MP706	FA155	FA135	—	—
E0ZE12127EA	MP700	MP703	FA144	FA134	—	—
E0ZE12127GA	MP712	MP706	FA155	FA135	—	—
E0ZE12127HA	MP712	MP706	FA155	FA135	—	—
E0ZZ12127B	MP712	MP706	FA155	FA135	—	—
E0ZZ12127G	MP712	MP706	FA155	FA135	—	—
E0ZZ12127H	MP712	MP706	FA155	FA135	—	—
E1AE12127EA	MP700	MP703	FA144	FA134	—	—
E1AE12127JA	MP700	MP703	FA144	FA134	—	—
E1AE12127KA	MP700	MP703	FA144	FA134	—	—
E1AE12127LA	MP700	MP703	FA127	FA156	—	—
E1AE12127LS	—	—	FA127	FA156	—	—
E1AE12127MA	MP700	MP703	FA127	FA156	—	—
E1AZ12127E	MP700	MP703	FA144	FA134	—	—
E1AZ12127J	MP700	MP703	FA144	FA134	—	—
E1AZ12127K	MP700	MP703	FA144	FA134	—	—
E1AZ12127L	MP700	MP703	FA127	FA156	—	—
E1AZ12127M	MP700	MP703	FA127	FA156	—	—
E1BE12127BA	MP700	MP703	FA144	FA134	—	—
E1BE12127DA	MP700	MP703	FA144	FA134	—	—
E1BE12127EA	MP712	—	—	FA136	—	—

(continued on next column)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
E1BZ12127A	MP712	—	—	FA136	—	—
E1BZ12127C	MP700	MP703	FA144	FA134	—	—
E1BZ12127E	MP700	MP703	FA144	FA134	—	—
E1BZ12127F	MP700	MP703	FA144	FA134	—	—
E1EE12127AC	MP710	—	FA142	FA137	—	—
E1EE12127AE	MP710	—	FA142	FA137	—	—
E1EE12127AF	MP710	—	FA142	FA137	—	—
E1EE12127JA	MP712	—	FA142	FA137	—	—
E1EE12127JB	MP709	—	FA142	FA137	—	—
E1EE12127JC	MP709	—	FA142	FA137	—	—
E1EE12127KA	MP709	—	FA142	FA137	—	—
E1EE12127KB	MP709	—	FA142	FA137	—	—
E1FZ12127A	MP710	—	FA142	FA137	—	—
E1FZ12127B	MP710	—	FA142	FA137	—	—
E1FZ12127C	MP709	—	FA142	FA137	—	—
E1FZ12127J	MP709	—	FA142	FA137	—	—
E1SE12127BA	MP700	MP703	FA144	FA134	—	—
E1SE12127CA	MP700	MP703	FA144	FA134	—	—
E1SE12127DA	MP700	MP703	FA144	FA134	—	—
E1SE12127EA	MP700	MP703	FA144	FA134	—	—
E1SE12127FA	MP700	MP703	FA144	FA134	—	—
E1SZ12127B	MP700	MP703	FA144	FA134	—	—
E1SZ12127C	MP700	MP703	FA144	FA134	—	—
E1SZ12127D	MP700	MP703	FA144	FA134	—	—
E1SZ12127E	MP700	MP703	FA144	FA134	—	—
E1SZ12127F	MP700	MP703	FA144	FA134	—	—
E1TE12127ABA	MP700	MP703	FA144	FA134	—	—
E1TE12127ACA	MP700	—	FA159	FA136	—	—
E1TE12127ADA	MP700	MP703	FA144	FA134	—	—
E1TE12127AEA	MP700	MP703	FA159	FA136	—	—
E1TE12127BA	MP700	MP703	FA144	FA134	—	—
E1TE12127EA	MP700	MP703	FA144	FA134	—	—
E1TE12127FA	MP712	—	FA159	FA136	—	—
E1TE12127GA	MP712	—	FA159	FA136	—	—
E1TE12127HA	MP712	—	FA159	FA136	—	—
E1TE12127JA	MP712	—	FA159	FA136	—	—
E1TE12127KA	MP700	MP703	FA144	FA134	—	—
E1TE12127MA	MP700	MP703	FA144	FA134	—	—
E1TE12127NA	MP700	MP703	FA144	FA134	—	—
E1TE12127PA	MP700	MP703	FA144	FA134	—	—
E1TE12127RA	MP712	—	FA159	FA136	—	—
E1TE12127SA	MP700	MP703	FA144	FA134	—	—
E1TE12127TA	MP700	MP703	FA144	FA134	—	—
E1TE12127UA	MP700	MP703	FA144	FA134	—	—
E1TE12127VA	MP712	—	FA159	FA136	—	—
E1TE12127YA	MP712	—	FA159	FA136	—	—
E1TE12127ZA	MP712	—	FA159	FA136	—	—
E1TZ12127AB	MP700	MP703	FA144	FA134	—	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
E1TZ12127AC . . .	MP700	—	FA159	FA136	—	—
E1TZ12127AD . . .	MP700	MP703	FA144	FA134	—	—
E1TZ12127AE . . .	MP700	MP703	FA159	FA136	—	—
E1TZ12127B . . .	MP700	MP703	FA144	FA134	—	—
E1TZ12127E . . .	MP700	MP703	FA144	FA134	—	—
E1TZ12127F . . .	MP712	—	FA159	FA136	—	—
E1TZ12127G . . .	MP712	—	FA159	FA136	—	—
E1TZ12127H . . .	MP712	—	FA159	FA136	—	—
E1TZ12127J . . .	MP712	—	FA159	FA136	—	—
E1TZ12127K . . .	MP700	MP703	FA144	FA134	—	—
E1TZ12127M . . .	MP700	MP703	FA144	FA134	—	—
E1TZ12127N . . .	MP700	MP703	FA144	FA134	—	—
E1TZ12127P . . .	MP700	MP703	FA144	FA134	—	FA151
E1TZ12127R . . .	MP712	—	FA159	FA136	—	—
E1TZ12127S . . .	MP700	MP703	FA144	FA134	—	—
E1TZ12127T . . .	MP700	MP703	FA144	FA134	—	—
E1TZ12127U . . .	MP700	MP703	FA144	FA134	—	—
E1TZ12127V . . .	MP712	—	FA159	FA136	—	—
E1TZ12127Y . . .	MP712	—	FA159	FA136	—	—
E1TZ12127Z . . .	MP712	—	FA159	FA136	—	—
E1UE12127AA . . .	MP700	MP703	FA144	FA134	—	—
E1UE12127BA . . .	MP700	MP703	FA144	FA134	—	—
E1UE12127CA . . .	MP700	MP703	FA144	FA134	—	—
E1UE12127DA . . .	MP700	MP703	FA144	FA134	—	—
E1UE12127EA . . .	MP700	MP703	FA144	FA134	—	—
E1UE12127FA . . .	MP700	MP703	FA144	FA134	—	—
E1UE12127GA . . .	MP700	MP703	FA144	FA134	—	—
E1UZ12127A . . .	MP700	MP703	FA144	FA134	—	—
E1UZ12127B . . .	MP700	MP703	FA144	FA134	—	—
E1UZ12127C . . .	MP700	MP703	FA144	FA134	—	—
E1UZ12127D . . .	MP700	MP703	FA144	FA134	—	—
E1UZ12127E . . .	MP700	MP703	FA144	FA134	—	—
E1UZ12127F . . .	MP700	MP703	FA157	FA134	—	FA151
E1UZ12127G . . .	MP700	MP703	FA144	FA134	—	FA151
E1ZE12127AA . . .	MP712	MP706	FA155	FA135	—	—
E1ZE12127CA . . .	MP712	MP706	FA155	FA135	—	—
E1ZZ12127A . . .	MP712	MP706	FA155	FA135	—	—
E1ZZ12127C . . .	MP712	MP706	FA155	FA135	—	—
E2AE12127EA . . .	MP700	MP703	FA144	FA134	—	—
E2AE12127FA . . .	MP700	MP703	FA144	FA134	—	—
E2AE12127GA . . .	MP700	MP703	FA144	FA134	—	—
E2AE12127HA . . .	MP700	MP703	FA127	FA156	—	—
E2AZ12127E . . .	MP700	MP703	FA144	FA134	—	—
E2AZ12127F . . .	MP700	MP703	FA144	FA134	—	—
E2BE12127BA . . .	MP700	MP703	FA144	FA134	—	—
E2BE12127CA . . .	MP712	—	FA159	FA136	—	—
E2BZ12127A . . .	MP712	—	FA159	FA136	—	—
E2BZ12127B . . .	MP700	MP703	FA144	FA134	—	—

(continued on next column)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
E2BZ12127C . . .	MP712	—	FA159	FA136	—	—
E2DE12127AA . . .	MP700	—	FA159	FA136	—	—
E2DX12127AB . . .	MP712	MP706	FA155	FA135	—	—
E2DZ12127A . . .	MP700	—	FA159	FA136	—	—
E2DZ12127B . . .	MP712	MP706	FA155	FA135	—	—
E2EE12127EA . . .	MP710	—	FA142	FA137	—	—
E2EE12127EB . . .	MP709	—	FA142	FA137	—	—
E2EE12127FA . . .	MP710	—	FA142	FA137	—	—
E2EE12127GA . . .	MP710	—	FA142	FA137	—	—
E2EE12127HA . . .	MP710	—	FA142	FA137	—	—
E2EE12127HB . . .	MP710	—	FA142	FA137	—	—
E2EE12127LA . . .	MP709	—	FA142	FA137	—	—
E2EE12127PA . . .	MP710	—	FA142	FA137	—	—
E2EE12127RA . . .	MP709	—	FA137	—	—	—
E2EE12A332EA . . .	MP710	—	FA142	FA137	—	—
E2EE12A332FA . . .	MP710	—	FA142	FA137	—	—
E2EE12A332GA . . .	MP709	—	FA142	FA137	—	—
E2EE12A332JA . . .	MP710	—	FA142	FA137	—	—
E2FZ12127C . . .	—	—	FA142	FA137	—	—
E2FZ12127E . . .	MP710	—	FA142	FA137	—	—
E2FZ12127F . . .	MP710	—	FA142	FA137	—	—
E2FZ12127G . . .	MP710	—	FA142	FA137	—	—
E2FZ12127H . . .	MP710	—	FA142	FA137	—	—
E2FZ12127L . . .	MP709	—	FA142	FA137	—	—
E2FZ12127P . . .	MP710	—	FA142	FA137	—	—
E2FZ12127R . . .	MP709	—	FA142	FA137	—	—
E2PE12127AA . . .	MP700	MP703	FA144	FA134	—	—
E2PE12127BA . . .	MP700	MP703	FA144	FA134	—	—
E2PZ12127A . . .	MP700	MP703	FA144	FA134	—	—
E2PZ12127B . . .	MP700	MP703	FA144	FA134	—	—
E2SE12127AA . . .	MP700	MP703	FA144	FA134	—	—
E2SE12127AC . . .	MP700	MP703	FA144	FA134	—	FA151
E2SE12127BA . . .	MP700	—	FA159	FA136	—	—
E2SE12127CA . . .	MP700	—	FA159	FA136	—	—
E2SE12127DA . . .	MP700	—	FA159	FA136	—	—
E2SE12127EA . . .	MP700	—	FA159	FA136	—	—
E2SZ12127A . . .	MP700	MP703	FA144	FA134	—	—
E2SZ12127B . . .	MP700	—	FA159	FA136	—	—
E2SZ12127C . . .	MP700	—	FA159	FA136	—	—
E2SZ12127D . . .	MP700	—	FA159	FA136	—	—
E2SZ12127E . . .	MP700	—	FA159	FA136	—	—
E2TE12127AA . . .	MP700	MP703	FA127	FA134	—	—
E2TE12127ACA . . .	MP700	MP703	FA144	FA134	—	—
E2TE12127BA . . .	MP700	MP703	FA144	FA134	—	—
E2TE12127CA . . .	MP700	MP703	FA144	FA134	—	—
E2TE12127DA . . .	MP700	—	FA159	FA136	—	—
E2TE12127EA . . .	MP712	—	FA159	FA136	—	—
E2TE12127FA . . .	MP712	—	FA159	FA136	—	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
E2TE12127GA .	MP700	MP703	FA127	FA134	—	—
E2TE12127HA .	MP700	MP703	FA127	FA134	—	—
E2TE12127JA .	MP700	—	FA159	FA136	—	—
E2TE12127KA .	MP700	MP703	FA144	FA134	—	—
E2TE12127LA .	MP700	MP703	FA144	FA134	—	—
E2TE12127MA .	MP700	MP703	FA144	FA134	—	—
E2TE12127NA .	MP700	—	FA159	FA136	—	—
E2TE12127RA .	MP712	—	FA159	FA136	—	—
E2TE12127SA .	MP700	MP703	FA144	FA134	—	—
E2TE12127TA .	MP700	MP703	FA144	FA134	—	—
E2TE12127UA .	MP700	MP703	FA144	FA134	—	—
E2TZ12127A .	MP700	MP703	FA127	FA134	—	—
E2TZ12127AC .	MP700	MP703	FA144	FA134	—	—
E2TZ12127B .	MP700	MP703	FA144	FA134	—	—
E2TZ12127C .	MP700	MP703	FA144	FA134	—	—
E2TZ12127D .	MP700	—	FA159	FA136	—	—
E2TZ12127E .	MP712	—	FA159	FA136	—	—
E2TZ12127F .	MP712	—	FA159	FA136	—	—
E2TZ12127G .	MP700	MP703	FA127	FA134	—	—
E2TZ12127H .	MP700	MP703	FA127	FA134	—	—
E2TZ12127J .	MP700	—	FA159	FA136	—	—
E2TZ12127K .	MP700	MP703	FA144	FA134	—	—
E2TZ12127L .	MP700	MP703	FA144	FA134	—	—
E2TZ12127M .	MP700	MP703	FA144	FA134	—	—
E2TZ12127N .	MP700	—	FA159	FA136	—	—
E2TZ12127R .	MP712	—	FA159	FA136	—	—
E2TZ12127S .	MP700	MP703	FA144	FA134	—	—
E2TZ12127T .	MP700	MP703	FA144	FA134	—	—
E2UE12127AA .	MP700	MP703	FA144	FA134	—	—
E2UE12127BA .	MP712	—	FA159	FA136	—	—
E2UE12127EA .	—	—	FA144	FA134	—	FA151
E2UZ12127A .	MP700	MP703	FA144	FA134	—	—
E2UZ12127B .	MP712	—	FA159	FA136	—	—
E2VE12127BA .	MP700	MP703	FA144	FA134	—	—
E2VY12127B .	MP700	MP703	FA144	FA134	—	—
E2ZE12127DA .	MP700	MP703	FA144	FA134	—	—
E2ZE12127EA .	MP700	MP703	FA144	FA134	—	—
E2ZZ12127D .	MP700	MP703	FA144	FA134	—	—
E2ZZ12127E .	MP700	MP703	FA144	FA134	—	—
E3AE12127CA .	MP712	—	FA159	FA136	—	—
E3AE12127DA .	MP700	—	FA159	FA136	—	—
E3AE12127EA .	MP712	—	FA159	FA136	—	—
E3AE12127FA .	MP700	MP703	FA127	FA156	—	—
E3AZ12127A .	MP700	MP703	FA144	FA134	—	—
E3AZ12127B .	MP700	MP703	FA127	FA156	—	—
E3AZ12127C .	MP712	—	FA159	FA136	—	—
E3AZ12127D .	MP700	—	FA159	FA136	—	—
E3AZ12127E .	MP712	—	FA159	FA136	—	—

(continued on next column)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
E3DX12127AA .	MP712	MP706	FA155	FA135	—	—
E3DZ12127A .	MP712	MP706	FA155	FA135	—	—
E3EE12127BA .	MP711	—	FA142	FA137	—	—
E3EE12127DA .	MP709	—	FA142	FA137	—	—
E3EE12127HA .	MP709	—	FA142	FA137	—	—
E3EE12127KA .	MP709	—	FA142	FA137	—	—
E3EE12127NA .	MP709	—	FA142	FA137	—	—
E3EE12127PA .	MP709	—	FA142	FA137	—	—
E3EE12127RA .	MP709	—	FA142	FA137	—	—
E3EE12127SA .	MP709	—	FA142	FA137	—	—
E3EE12127TA .	MP709	—	FA142	FA137	—	—
E3EE12127UA .	MP709	—	FA142	FA137	—	—
E3EE12127VA .	MP709	—	FA142	FA137	—	—
E3EE12127YA .	MP709	—	FA142	FA137	—	—
E3EE12127ZA .	MP709	—	FA142	FA137	—	—
E3EE12A332AA	MP711	—	FA142	FA137	—	—
E3EE12A332CA	MP709	—	FA142	FA137	—	—
E3EE12A332GA	MP709	—	FA142	FA137	—	—
E3EE12A332JA	MP709	—	FA142	FA137	—	—
E3EE12A332MA	MP709	—	FA142	FA137	—	—
E3EE12A332NA	MP709	—	FA142	FA137	—	—
E3EE12A332PA	MP709	—	FA142	FA137	—	—
E3EE12A332RA	MP709	—	FA142	FA137	—	—
E3EE12A332SA	MP709	—	FA142	FA137	—	—
E3EE12A332UA	MP709	—	FA142	FA137	—	—
E3EE12A332VA	MP709	—	FA142	FA137	—	—
E3EE12A332YA	MP709	—	FA142	FA137	—	—
E3EF12127AA .	—	—	FA142	FA137	—	—
E3EF12127PA .	—	—	FA142	FA137	—	—
E3FZ12127B .	MP711	—	FA142	FA137	—	—
E3FZ12127H .	MP709	—	FA142	FA137	—	—
E3FZ12127K .	MP709	—	FA142	FA137	—	—
E3FZ12127N .	MP709	—	FA142	FA137	—	—
E3FZ12127P .	MP709	—	FA142	FA137	—	—
E3FZ12127R .	MP709	—	FA142	FA137	—	—
E3FZ12127S .	MP709	—	FA142	FA137	—	—
E3FZ12127T .	MP709	—	FA142	FA137	—	—
E3FZ12127V .	MP709	—	FA142	FA137	—	—
E3FZ12127Y .	MP709	—	FA142	FA137	—	—
E3FZ12127Z .	MP709	—	FA142	FA137	—	—
E3HE12127BA .	MP700	MP703	FA144	FA134	—	—
E3SE12127AA .	MP700	—	FA159	FA136	—	—
E3SZ12127A .	MP700	—	FA159	FA136	—	—
E3TE12127AAA	MP700	MP703	FA144	FA134	VC2037	—
E3TE12127BA .	MP712	—	FA159	FA136	—	—
E3TE12127CA .	MP712	—	FA159	FA136	—	—
E3TE12127DA .	MP700	MP703	FA144	FA134	—	—
E3TE12127EA .	MP712	—	FA159	FA136	—	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
E3TE12127FA . .	MP712	—	FA159	FA136	—	—
E3TE12127HA . .	MP700	MP703	FA144	FA134	—	—
E3TE12127JA . .	MP700	MP703	FA144	FA134	—	—
E3TE12127KA . .	MP712	—	FA159	FA136	—	—
E3TE12127LA . .	MP700	—	FA159	FA136	—	—
E3TE12127MA . .	MP700	MP703	FA144	FA134	—	—
E3TE12127NA . .	MP712	—	FA159	FA136	—	—
E3TE12127PA . .	MP700	—	FA159	FA136	—	—
E3TE12127RA . .	MP712	—	FA159	FA136	—	—
E3TE12127SA . .	MP700	MP703	FA144	FA134	—	—
E3TE12127TA . .	MP712	—	FA159	FA136	—	—
E3TE12127UA . .	MP712	—	FA159	FA136	—	—
E3TE12127VA . .	MP712	—	FA159	FA136	—	—
E3TE12127YA . .	MP700	—	FA159	FA136	—	—
E3TE12127ZA . .	MP700	MP703	FA144	FA134	—	—
E3TZ12127A . . .	MP712	MP706	FA155	FA135	—	—
E3TZ12127AA . .	MP700	MP703	FA144	FA134	—	—
E3TZ12127B . . .	MP712	—	FA159	FA136	—	—
E3TZ12127BAA . .	MP700	MP703	FA144	FA134	—	—
E3TZ12127C . . .	MP712	—	FA159	FA136	—	—
E3TZ12127E . . .	MP712	—	FA159	FA136	—	—
E3TZ12127EA . .	MP711	—	FA153	FA145	—	—
E3TZ12127F . . .	MP712	—	FA159	FA136	—	—
E3TZ12127FA . .	MP712	MP706	FA155	FA135	—	—
E3TZ12127GA . .	MP712	MP706	FA155	FA135	—	—
E3TZ12127H . . .	MP700	MP703	FA144	FA134	—	—
E3TZ12127J . . .	MP700	MP703	FA144	FA134	—	—
E3TZ12127K . . .	MP712	—	FA159	FA136	—	—
E3TZ12127L . . .	MP700	—	FA159	FA136	—	—
E3TZ12127M . . .	MP700	MP703	FA144	FA134	—	—
E3TZ12127N . . .	MP712	—	FA159	FA136	—	—
E3TZ12127P . . .	MP700	—	FA159	FA136	—	—
E3TZ12127R . . .	MP712	—	FA159	FA136	—	—
E3TZ12127S . . .	MP700	MP703	FA144	FA134	—	—
E3TZ12127T . . .	MP712	—	FA159	FA136	—	—
E3TZ12127U . . .	MP712	—	FA159	FA136	—	—
E3TZ12127V . . .	MP712	—	FA159	FA136	—	—
E3TZ12127Y . . .	MP700	—	FA159	FA136	—	—
E3TZ12127Z . . .	MP700	MP703	FA144	FA134	—	—
E3UE12127AA . .	MP700	MP703	FA144	FA134	—	—
E3UE12127BA . .	MP712	—	FA159	FA136	—	—
E3UE12127CA . .	MP712	—	FA159	FA136	—	—
E3UE12127DA . .	MP700	MP703	FA144	FA134	—	—
E3UE12127EA . .	MP700	MP703	FA144	FA134	—	—
E3UE12127GA . .	MP712	—	FA159	FA136	—	—
E3UE12127HA . .	MP712	—	FA159	FA136	—	—
E3UE12127JA . .	MP712	—	FA159	FA136	—	—
E3UZ12127A . . .	MP700	MP703	FA144	FA134	—	—

(continued on next column)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
E3UZ12127C . . .	MP712	—	FA159	FA136	—	—
E3UZ12127D . . .	MP700	MP703	FA144	FA134	—	—
E3UZ12127E . . .	MP700	MP703	FA144	FA134	—	—
E3UZ12127G . . .	MP712	—	FA159	FA136	—	—
E3UZ12127H . . .	MP712	—	FA159	FA136	—	—
E3UZ12127J . . .	MP712	—	FA159	FA136	—	—
E3ZE12127BA . .	MP711	—	FA142	FA137	—	—
E3ZE12127CA . .	MP700	—	FA159	FA136	—	—
E3ZE12127DA . .	MP712	MP706	FA155	FA135	—	—
E3ZE12127EA . .	MP712	MP706	FA155	FA135	—	—
E3ZE12127FA . .	MP700	—	FA159	FA136	—	—
E3ZE12127HA . .	MP700	MP703	FA144	FA134	—	—
E3ZE12127JA . .	MP700	MP703	FA144	FA134	—	—
E3ZE12A332AA . .	MP711	—	FA142	FA137	—	—
E3ZZ12127B . . .	MP711	—	FA142	FA137	—	—
E3ZZ12127C . . .	MP700	—	FA159	FA136	—	—
E3ZZ12127D . . .	MP712	MP706	FA155	FA135	—	—
E3ZZ12127E . . .	MP712	MP706	FA155	FA135	—	—
E3ZZ12127F . . .	MP700	—	FA159	FA136	—	—
E3ZZ12127H . . .	MP700	MP703	FA144	FA134	—	—
E3ZZ12127J . . .	MP700	MP703	FA144	FA134	—	—
E4AE12127AA . .	MP700	—	FA159	FA136	—	—
E4AZ12127A . . .	MP700	—	FA159	FA136	—	—
E4EE12127AA . .	MP711	—	FA142	FA137	—	—
E4EE12127FA . .	MP709	—	FA142	FA137	—	—
E4EE12127GA . .	MP709	—	FA142	FA137	—	—
E4EE12127HA . .	MP711	—	FA142	FA137	—	—
E4EE12A332EA . .	MP709	—	FA142	FA137	—	—
E4EE12A332FA . .	MP709	—	FA142	FA137	—	—
E4EE12A332GA . .	MP711	—	FA142	FA137	—	—
E4FZ12127F . . .	MP709	—	FA142	FA137	—	—
E4FZ12127G . . .	MP709	—	FA142	FA137	—	—
E4HE12127AA . .	MP700	MP703	FA144	FA134	—	—
E4HE12127CA . .	MP700	MP703	FA144	FA134	—	—
E4HE12127DA . .	MP700	MP703	FA144	FA134	—	—
E4HZ12127D . . .	MP700	MP703	FA144	FA134	—	—
E4PZ12127A . . .	MP709	—	FA142	FA137	—	—
E4TE12127AA . .	MP711	—	FA142	FA141	—	—
E4TE12127BA . .	MP711	—	FA153	FA134	—	—
E4TE12127CA . .	MP711	—	FA153	FA134	—	—
E4TE12127EA . .	MP700	MP703	FA144	FA134	—	—
E4TE12A332AA . .	MP711	—	FA142	FA141	—	—
E4TE12A332BA . .	MP711	—	FA153	FA134	—	—
E4TE12A332CA . .	MP711	—	FA153	FA134	—	—
E4TZ12127A . . .	MP711	—	FA142	FA141	—	—
E4TZ12127AA . .	MP700	MP703	FA144	FA134	—	—
E4TZ12127AAA . .	MP711	—	FA142	FA141	—	—
E4TZ12127B . . .	MP711	—	FA153	FA134	—	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
E4TZ12127C ...	MP711	—	FA153	FA134	—	—
E4TZ12127E ...	MP703	—	FA144	FA134	—	—
E4ZE12127AA ...	MP711	—	FA153	FA141	—	—
E4ZE12127BA ...	MP712	MP706	FA155	FA135	—	—
E4ZE12127CA ...	MP712	MP706	FA155	FA135	—	—
E4ZE12127DA ...	MP700	MP703	FA144	FA134	—	—
E4ZE12127EA ...	MP700	MP703	FA144	FA134	—	—
E4ZE12127FA ...	MP711	—	FA142	FA137	—	—
E4ZE12A332AA ...	MP711	—	MO35	FA141	—	—
E4ZE12A332BA ...	MP711	—	FA153	FA141	—	—
E4ZZ12127A ...	MP711	—	FA153	FA141	—	—
E4ZZ12127B ...	MP712	MP706	FA155	FA135	—	—
E4ZZ12127C ...	MP712	MP706	FA155	FA135	—	—
E4ZZ12127D ...	MP700	MP703	FA144	FA134	—	—
E4ZZ12127E ...	MP700	MP703	FA144	FA134	—	—
E4ZZ12127F ...	MP711	—	FA153	FA141	—	—
E5AE12127BA ...	MP711	—	FA152	FA134	—	—
E5AE12A332AA ...	MP711	—	FA152	FA134	—	—
E5AZ12127B ...	MP711	—	FA152	FA134	—	—
E5EE12127CB ...	MP709	—	FA142	FA137	—	—
E5EE12127DB ...	—	—	FA142	FA137	—	—
E5EE12127EA ...	MP711	—	MO35	FA137	—	—
E5EE12127EB ...	MP711	—	MO35	FA137	—	—
E5EE12A332CB ...	MP711	—	FA142	FA137	—	—
E5EE12A332DB ...	MP711	—	FA142	FA137	—	—
E5EE12A332EB ...	MP711	—	FA142	FA137	—	—
E5HE12127AA ...	MP700	MP703	FA144	FA134	—	—
E5HE12127BA ...	MP700	MP703	FA144	FA134	—	—
E5HZ12127A ...	MP700	MP703	FA144	FA134	—	—
E5HZ12127B ...	MP700	MP703	FA144	FA134	—	—
E5TE12127AA ...	MP711	—	FA153	FA134	—	—
E5TE12127BA ...	MP711	—	FA152	FA134	—	—
E5TE12127CA ...	—	—	FA153	FA134	—	FA140
E5TE12127EA ...	MP711	—	FA153	FA134	—	—
E5TE12127FA ...	MP711	—	FA142	FA136	—	—
E5TE12127HA ...	MP711	—	FA153	FA134	—	—
E5TE12127LA ...	MP711	—	MO35	FA141	—	—
E5TE12127MA ...	MP712	—	FA142	FA136	—	—
E5TE12127NA ...	MP712	—	FA142	FA136	—	—
E5TE12127PA ...	MP711	—	FA153	FA134	—	—
E5TE12127RA ...	MP700	MP703	FA144	FA134	—	—
E5TE12127SA ...	MP711	—	FA144	FA134	—	—
E5TE12127UA ...	MP711	—	FA153	FA134	—	—
E5TE12A332AA ...	MP711	—	FA153	FA134	—	—
E5TE12A332BA ...	MP711	—	FA152	FA134	—	—
E5TE12A332CA ...	—	—	FA144	FA134	—	FA151
E5TE12A332EA ...	MP711	—	MO35	FA141	—	—
E5TE12A332FA ...	MP711	—	FA153	FA134	—	—

(continued on next column)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
E5TZ12127A ...	MP711	—	FA153	FA134	—	—
E5TZ12127B ...	MP711	—	FA152	FA134	—	—
E5TZ12127E ...	MP711	—	FA153	FA134	—	—
E5TZ12127FA ...	MP711	MP706	FA142	FA136	—	FA139
E5TZ12127H ...	MP711	—	FA153	FA134	—	—
E5TZ12127L ...	MP711	—	MO35	FA141	—	—
E5TZ12127M ...	MP712	—	FA142	FA136	—	—
E5TZ12127N ...	MP712	—	FA142	FA136	—	—
E5TZ12127P ...	MP711	—	FA153	FA134	—	—
E5TZ12127R ...	MP700	MP703	FA144	FA134	—	—
E5ZE12127BA ...	MP700	MP703	FA144	FA134	—	—
E5ZZ12127B ...	MP700	MP703	FA144	FA134	—	—
E6AE12127DA ...	MP711	—	FA152	FA134	—	—
E6AE12127EA ...	MP711	—	MO35	FA141	—	—
E6AE12A332DA ...	MP711	—	FA152	FA134	—	—
E6AE12A332EA ...	MP711	—	MO35	FA141	—	—
E6AE12A332FA ...	MP711	—	MO35	FA141	—	—
E6AE12A332GA ...	MP711	—	MO35	FA141	—	—
E6AZ12127C ...	MP711	—	MO35	FA141	—	—
E6AZ12127D ...	MP711	—	FA152	FA134	—	—
E6FZ12127C ...	MP711	—	FA142	FA137	—	—
E6FZ12127D ...	MP711	—	FA142	FA137	—	—
E6FZ12127E ...	MP711	—	MO35	FA137	—	—
E6RE12127FA ...	MP711	—	MO35	FA137	—	—
E6RE12A332FA ...	MP711	—	MO35	FA137	—	—
E6SE12127DA ...	MP711	—	MO35	FA141	—	—
E6SE12127EA ...	MP711	—	FA152	FA134	—	—
E6SE12A332EA ...	MP711	—	MO35	FA141	—	—
E6SE12A332FA ...	MP711	—	FA152	FA134	—	—
E6SZ12127C ...	MP711	—	MO35	FA141	—	—
E6SZ12127E ...	MP711	—	FA152	FA134	—	—
E6TE12127AA ...	MP712	—	FA159	FA136	—	—
E6TE12127BA ...	MP712	—	FA159	FA136	—	—
E6TZ12127A ...	MP711	—	—	—	—	—
E6TZ12127B ...	MP711	—	FA144	FA134	—	—
E6TZ12127C ...	MP712	—	FA159	FA136	—	—
E6TZ12127D ...	MP712	—	FA159	FA136	—	—
E6TZ12127E ...	MP711	—	FA144	FA134	—	—
E7AE12A332BA ...	MP711	—	FA152	FA134	—	—
E7EE12127EA ...	MP711	—	MO35	FA137	—	—
E7EE12127EB ...	MP711	—	MO35	FA137	—	—
E7EE12A332AA ...	MP711	—	MO35	FA137	—	—
E7EE12A332AB ...	MP711	—	MO35	FA137	—	—
E7EE12A332AC ...	MP711	—	MO35	FA137	—	—
E7FZ12127E ...	MP711	—	MO35	FA137	—	—
E7HE12127AA ...	MP700	MP703	FA144	FA134	—	—
E7HZ12127A ...	MP700	MP703	FA144	FA134	—	—
E7SE12A332BA ...	MP711	—	MO35	FA137	—	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
E7SE12A332CA	MP711	—	FA152	FA134	—	—
E7SZ12127A . . .	MP711	—	MO35	FA137	—	—
E7TE12127BC . . .	MP711	—	FA152	FA134	—	—
E7TE12127BD . . .	MP711	—	FA152	FA134	—	—
E7TE12127DA . . .	MP711	—	FA152	FA134	—	—
E7TE12127EA . . .	MP711	—	MO35	FA141	—	—
E7TE12127FA . . .	MP711	—	FA153	FA134	—	—
E7TE12A332AD	MP711	—	FA152	FA134	—	—
E7TE12A332BA	MP711	—	FA152	FA134	—	—
E7TE12A332EA	MP711	—	FA152	FA141	—	—
E7TE12A332GA	MP711	—	FA152	FA141	—	—
E7TZ12127BA . . .	MP711	—	FA155	FA135	—	—
E7TZ12127D . . .	MP711	—	FA152	FA134	—	—
E7TZ12127E . . .	MP711	—	MO35	FA141	—	—
E7TZ12127F . . .	MP711	—	FA153	FA134	—	—
E8DE12127AC . . .	MP711	—	MO35	FA141	—	—
E8DE12127EA . . .	MP711	—	MO35	FA141	—	—
E8DE12A332CA	MP711	—	MO35	FA141	—	—
E8DZ12127A . . .	MP711	—	MO35	FA141	—	—
E8EE12A332AA	MP711	—	MO35	FA137	—	—
E8EE12A332BA	MP711	—	MO35	FA137	—	—
E8PF12A199AB	MP703	—	FA152	FA134	—	—
E8SE12127A . . .	MP711	—	MO35	FA141	—	—
E8SE12127AA . . .	MP711	—	MO35	FA141	—	—
E8TE12127AA . . .	MP711	—	MO35	FA141	—	—
E8TE12127BA . . .	—	—	FA152	FA134	—	—
E8TE12127BC . . .	MP711	—	FA152	FA134	—	—
E8TE12127CA . . .	MP711	—	FA152	FA134	—	—
E8TE12A332BA	MP711	—	FA152	FA141	—	—
E8TE12A332CA	MP711	—	FA152	FA134	—	—
E9DE12A332AA	MP711	—	MO35	FA141	—	—
E9SE12127BA . . .	MP711	—	MO35	FA141	—	—
E9SE12127BB . . .	CSS405	—	MO35	FA141	—	—
E9SZ12127B . . .	MP711	—	MO35	FA141	—	—
E9TE12127CA . . .	MP711	—	FA152	FA134	—	—
E27E12127AA . . .	MP712	MP706	FA155	FA135	—	—
E27E12127BA . . .	MP712	MP706	FA155	FA135	—	—
E37E12127EA . . .	MP711	—	FA153	FA145	—	—
E37E12127FA . . .	MP712	MP706	FA155	FA135	—	—
E37E12127GA . . .	MP712	MP706	FA155	FA135	—	—
E37E12A332AA	MP711	—	FA153	FA145	—	—
E43E12127CA . . .	MP711	—	FA142	FA137	—	—
E43E12127DA . . .	MP712	MP706	FA155	FA135	—	—
E43E12127FA . . .	—	—	FA142	FA137	—	—
E43E12127GA . . .	MP712	MP706	FA155	FA135	—	—
E43E12127HA . . .	MP700	MP703	FA144	FA134	—	—
E43E12A332AA	MP711	—	FA159	FA137	—	—
E43Z12127C . . .	MP711	—	FA142	FA137	—	—

(continued on next column)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
E43Z12127D . . .	MP712	MP706	FA155	FA135	—	—
E43Z12127G . . .	MP712	MP706	FA155	FA135	—	—
E43Z12127H . . .	MP700	MP703	FA144	FA134	—	—
E47E12127AA . . .	MP711	—	FA142	FA141	—	—
E47E12A332AA	MP711	—	FA142	FA141	—	—
E59E12127CA . . .	MP711	—	MO35	FA137	—	—
E59E12A332BA	MP711	—	MO35	FA137	—	—
E59Z12127C . . .	MP711	—	MO35	FA137	—	—
E63E12127AA . . .	MP711	MP706	MO35	FA137	—	—
E63E12127BA . . .	MP711	—	MO35	FA137	—	—
E63E12127DA . . .	MP711	MP706	MO35	FA141	—	—
E63E12A332BA	MP711	—	MO35	FA137	—	—
E63F12A332BA	MP711	—	—	FA137	—	—
E63Z12127B . . .	MP711	—	MO35	FA137	—	—
E67E12127AA . . .	MP711	—	—	—	—	—
E67E12A332AA	MP711	—	MO35	FA141	—	—
E69E12127AA . . .	MP711	—	MO35	FA141	—	—
E69E12127BA . . .	MP711	—	FA142	FA141	—	—
E69E12127BD . . .	—	—	FA152	FA134	—	—
E69E12A332AA	MP711	—	MO35	FA141	—	—
E69Z12127A . . .	MP711	—	MO35	FA141	—	—
E73E12127BA . . .	MP711	—	FA155	FA137	—	—
E73Z12127B . . .	MP711	—	FA155	FA137	—	—
E77E12127BA . . .	MP711	—	FA155	FA135	—	—
E83E12127AA . . .	MP711	—	MO35	FA137	—	—
E83E12A332AA	MP711	—	MO35	FA137	—	—
E83Z12127A . . .	MP711	—	MO35	FA137	—	—
E87E12A332AA	MP711	—	FA142	FA141	—	—
F0SE12127CA . . .	—	—	FA152	FA134	—	—
F0TE12127JA . . .	MP711	—	FA152	FA134	—	—
F2DE12127BB . . .	MP711	—	MO35	FA141	—	—
F2TE12127AA . . .	MP711	—	FA152	FA134	—	—
F2TE12127BA . . .	MP711	—	FA152	FA134	—	—
F2TE12127DA . . .	MP711	—	MO35	FA141	—	—
F2XA12127AA . . .	—	—	EP834	EP866	—	—
F2XE12127BA . . .	—	—	EP834	EP866	—	—
F27E12127BB . . .	—	—	MO35	FA141	—	—
F22018200C . . .	—	—	EP816	EP827	—	—
FEH12127E	—	—	FA157	FA78	—	—
FEJ12127D	—	—	FA157	FA78	—	—
T3T607713874 . . .	MP713	—	—	—	—	—
T3T607723877 . . .	MP713	—	—	—	—	—
T3T607743874 . . .	MP713	—	—	—	—	—
T3T607758786 . . .	MP713	—	—	—	—	—
T3T607778495 . . .	MP713	—	—	—	—	—
T3T616748682 . . .	MP713	—	—	—	—	—
T4T611748678 . . .	MP820	—	—	EP660	—	—
75DE12127DA . . .	MP712	—	FA158	FA104	—	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
75TF12100BA ..	—	—	FA105	FA104	—	—
75TF12100EA ..	MP712	—	FA105	FA104	—	—
75TF12100HA ..	MP712	—	FA105	FA104	—	—
75TF12100JA ..	—	—	FA105	FA104	—	—
75TF12100MA ..	MP712	—	FA105	FA104	—	—
75TF12100NA ..	MP712	—	FA105	FA104	—	—
76TF12100EA ..	MP712	—	FA105	FA104	—	—
76TF12100FA ..	MP712	—	FA105	FA104	—	—
76TF12100GA ..	MP712	—	FA105	FA104	—	—
76TF12100KA ..	MP712	—	FA105	FA104	—	—
76TF12100LA ..	MP712	—	FA105	FA104	—	—

(continued on next column)

Unit No	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Adapter
77TF12100AA ..	MP712	—	FA159	FA136	—	—
77TF12100CA ..	MP712	—	FA159	FA136	—	—
77TF12100DA ..	MP712	—	FA159	FA136	—	—
77TF12100EA ..	MP712	—	FA159	FA136	—	—
77TF12100GA ..	MP712	—	FA159	FA136	—	FA139
77TF12100HA ..	MP712	—	FA159	FA136	—	—
79TF12100EA ..	—	—	FA159	FA136	—	—
79TF12100FA ..	MP712	—	FA159	FA136	—	—
771F12100AB ..	—	—	FA123	FA122	—	—
771F12127AB ..	—	—	FA123	FA122	—	—

HITACHI

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Ign Coil	Vac Control
D4M704	—	—	—	EP312	EP718	IC80	—
D4M705	—	—	—	EP312	EP718	IC80	—
D4P8303D	—	MP418	—	EP768	EP769	—	—
D4P8605	—	—	—	EP773	EP769	IC114	—
D4P8703	—	—	—	EP773	EP769	IC114	—
D4P8704	—	—	—	EP310	EP851	IC114	—
D4R802	—	TP120 ³	MP1104	EP312	EP692	IC12	—
D4R8020	—	TP120 ³	—	EP312	EP718	IC12	—
D4R8021	—	TP120 ³	—	EP312	EP718	IC12	—
D4R8022	—	TP120 ³	—	EP312	EP718	IC12	VC4099
D4R8023	—	TP120 ³	—	EP312	EP751	IC12	—
D4R8024	—	TP120 ³	—	EP312	EP718	IC12	—
D4R8026	—	TP120 ³	—	EP312	EP718	IC12	VC4097
D4R8027	—	TP120 ³	—	EP312	EP718	IC12	VC4098
D4R8029	—	TP120 ³	—	EP312	EP718	IC12	—
D4R803	—	TP120 ³	MP1104	EP312	EP692	IC12	—
D4R807	—	TP120 ³	—	EP312	EP718	IC12	—
D4R808	—	TP120 ³	MP1104	EP312	EP692	IC12	—
D4R809	—	TP120 ³	MP1104	EP312	EP692	IC12	—
D4R810	—	TP120 ³	—	EP312	EP718	IC12	VC4113
D4R8209	—	TP120 ³	MP1105	EP312	EP708	IC12	—
D4R822	—	TP120 ³	MP1104	EP312	EP751	IC12	—
D4R8223	—	TP120 ³	MP1105	EP312	EP708	IC12	—
D4R8226	—	TP120 ³	MP1105	EP312	EP708	IC12	—
D4R823	—	TP120 ³	MP1104	EP312	EP751	IC12	—
D4R8230	—	TP120 ³	—	EP312	EP717	—	—
D4R824	—	TP120 ³	MP1104	EP312	EP751	IC12	—
D4R8304	—	TP120 ³	MP1104	EP312	EP693	IC12	—
D4R8306	—	TP120 ³	MP1104	EP312	EP693	IC12	—
D4R8314	—	TP120 ³	MP1105	EP312	EP708	IC12	—
D4R8315	—	TP120 ³	MP1105	EP312	EP708	IC12	—

(continued on next page)

³ Control Module & Pickup Assembly

HITACHI (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Ign Coil	Vac Control
D4R832	—	TP120 ³	MP1104	EP312	EP692	IC12	—
D4R8332	—	TP120 ³	MP1105	EP312	EP708	IC12	—
D4R8339	—	TP120 ³	MP1104	EP312	EP693	IC12	—
D4R8418	—	TP120 ³	—	EP312	EP717	IC12	—
D4R8433	—	TP120 ³	—	EP312	EP717	IC12	—
D4R8440	—	TP120 ³	—	EP312	EP717	—	—
D4R8448	—	TP120 ³	—	EP312	EP797	IC12	—
D4R8455	—	TP120 ³	MP1106	EP312	EP708	IC115	—
D4R8456	—	—	MP1106	EP312	EP708	IC115	—
D4R8457	—	TP120 ³	MP1106	EP312	EP708	IC115	—
D4R8458	—	TP120 ³	MP1106	EP312	EP708	IC115	—
D4R8465	—	TP120 ³	MP1105	EP312	EP708	IC12	—
D4R8466	—	TP120 ³	—	EP312	EP797	IC12	—
D4R8467	—	TP120 ³	—	EP312	EP717	IC12	—
D4R8501	—	TP120 ³	—	EP312	EP797	IC12	—
D4R8510	—	—	EP738	—	—	—	—
D4R8522	—	TP120 ³	—	EP312	EP797	IC116	—
D4R8611	—	TP120 ³	MP1106	EP312	EP708	IC116	—
D4R8612	—	TP120 ³	MP1106	EP312	EP708	IC116	—
D4R8613	—	TP120 ³	MP1106	EP312	EP708	IC116	—
D4R8614	—	TP120 ³	MP1106	EP312	EP708	IC116	—
D4R8624	—	TP120 ³	—	EP312	EP797	IC116	—
D4R8628	—	TP120 ³	MP1106	EP312	EP709	IC115	—
D4R8668	—	TP120 ³	MP1106	EP312	EP709	IC115	—
D4R904	—	TP120 ³	—	EP312	EP718	IC12	VC4114
D4R906	—	TP120 ³	—	EP312	EP718	IC12	VC4112
D4R907	—	TP120 ³	—	EP312	EP718	IC12	—
D4R912	—	TP120 ³	—	EP312	EP718	IC12	VC4104
D4R913	—	TP120 ³	—	EP312	EP718	IC12	—
D4S803	—	—	—	EP312	EP718	IC80	—
D4S805	—	—	—	EP312	EP718	IC80	—
D4T9403	TP221	—	—	—	EP475	—	—
D4T9405	—	—	—	—	EP475	—	—
D4T9407	TP221	—	—	—	EP475	—	—
D4T9607	TP221	—	—	EP474	EP556	—	—
D4T9703	TP221	—	—	EP474	EP556	—	—
D5P9401	—	—	—	EP519	EP518	—	—
D6P8203	—	—	—	EP761	EP741	IC114	—
D6P8401	—	—	—	EP761	EP752	IC112	—
D6P9601	—	—	—	EP503	EP504	—	—
DR48227	—	TP120 ³	—	EP312	EP717	IC12	—
DR48228	—	TP120 ³	—	EP312	EP717	—	—
DR48231	—	TP120 ³	—	EP312	EP717	—	—
DR48443	—	TP120 ³	—	EP312	EP717	IC12	—
DR48447	—	TP120 ³	—	EP312	EP797	IC12	—
DR48611	—	TP120 ³	MP1106	EP312	EP708	IC116	VC4101
DR48612	—	TP120 ³	MP1106	EP312	EP708	IC116	—

³ Control Module & Pickup Assembly

HONDA

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
30100P06A02 ..	—	—	—	EP469	EP867	—
30100P08006 ..	—	—	—	EP469	EP867	—
30100P08A02 ..	—	—	—	EP469	EP867	—
30100P12A01 ..	—	—	—	EP469	EP478	—
30100P13A01 ..	TP379	—	—	—	EP478	—
30100P14A01 ..	—	—	—	EP469	EP478	—
30100P30006 ..	—	—	—	EP469	EP867	—
30100PA1733 ..	—	—	—	EP821	EP676	—
30100PA1734 ..	—	MP1102	—	EP312	EP718	—
30100PA1736 ..	—	—	—	EP821	EP676	—
30100PA1737 ..	—	—	—	EP821	EP676	—
30100PA1752 ..	—	—	—	EP821	—	—
30100PA1941 ..	—	MP1102	—	EP312	EP718	—
30100PA1942 ..	—	—	—	EP821	EP676	—
30100PA1944 ..	—	—	—	EP821	EP676	—
30100PA1945 ..	—	—	—	EP821	EP676	—
30100PA1949 ..	—	—	—	EP821	EP676	—
30100PA5005 ..	TP120	—	—	EP312	EP718	—
30100PA5015 ..	TP120	—	—	EP312	EP718	—
30100PA5661 ..	TP120	—	—	EP312	EP718	—
30100PA5681 ..	TP120	—	—	EP312	EP718	—
30100PA5682 ..	TP120	—	—	EP312	EP718	—
30100PA5684 ..	TP120	—	—	EP312	EP718	—
30100PA6015 ..	TP120	—	—	EP312	EP718	—
30100PA6025 ..	TP120	—	—	EP312	EP718	—
30100PA6035 ..	TP120	—	—	EP312	EP718	—
30100PA6662 ..	TP120	—	—	EP312	EP718	—
30100PA6663 ..	TP120	—	—	EP312	EP718	—
30100PA6671 ..	TP120	—	—	EP312	EP718	—
30100PA6673 ..	TP120	—	—	EP312	EP718	—
30100PA6681 ..	TP120	—	—	EP312	EP718	—
30100PA6683 ..	TP120	—	—	EP312	EP718	—
30100PA6692 ..	TP120	—	—	EP312	EP718	—
30100PA6693 ..	TP120	—	—	EP312	EP718	—
30100PA6731 ..	—	TP120 ³	—	EP312	EP718	—
30100PA6732 ..	—	—	—	EP821	EP676	—
30100PA6912 ..	TP120	—	—	EP312	EP718	—
30100PB2661 ..	TP120	—	—	EP312	EP718	—
30100PB2671 ..	TP120	—	—	EP312	EP718	—
30100PB2691 ..	TP120	—	—	EP312	EP718	—
30100PC2661 ..	TP120	—	—	EP312	EP718	—
30100PC2662 ..	—	MP1103	—	EP312	EP676	—
30100PC2663 ..	TP120	—	—	EP312	EP718	—
30100PC2664 ..	—	MP1103	—	EP312	EP676	—
30100PC2671 ..	TP120	—	—	EP312	EP718	—
30100PC2672 ..	—	MP1103	—	EP312	EP676	—
30100PC2673 ..	TP120	—	—	EP312	EP718	—
30100PC2674 ..	—	MP1103	—	EP312	EP676	—

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
30100PC2681 ..	TP120	—	—	EP312	EP718	—
30100PC2682 ..	—	MP1103	—	EP312	EP718	—
30100PC2683 ..	—	MP1103	—	EP312	EP676	—
30100PC2691 ..	TP120	—	—	EP312	EP718	—
30100PC2692 ..	—	MP1103	—	EP312	EP676	—
30100PC2693 ..	—	MP1103	—	EP312	EP676	—
30100PC3732 ..	—	—	—	EP821	EP676	—
30100PC3733 ..	—	—	—	EP821	EP676	—
30100PC3735 ..	—	—	—	EP821	—	—
30100PC3742 ..	—	—	—	EP821	EP676	—
30100PC3752 ..	—	—	—	EP821	EP676	—
30100PC3753 ..	—	—	—	EP821	EP676	—
30100PC6661 ..	TP120	—	—	EP312	EP708	—
30100PC6662 ..	—	—	—	EP312	EP709	—
30100PC6671 ..	TP120	—	—	EP312	EP708	—
30100PC6672 ..	—	—	—	EP312	EP709	—
30100PC6841 ..	TP120	—	—	EP312	EP708	—
30100PC6842 ..	—	—	—	EP312	EP709	—
30100PC7661 ..	TP120	—	—	EP312	EP708	—
30100PC7662 ..	—	—	—	EP312	EP758	—
30100PC7671 ..	TP120	—	—	EP312	EP708	—
30100PC7672 ..	—	—	—	EP312	EP758	—
30100PC7673 ..	TP120	—	—	EP312	EP708	—
30100PC7674 ..	—	—	—	EP312	EP758	—
30100PC7781 ..	—	TP120 ³	MP1105	EP312	EP708	—
30100PC7783 ..	—	TP120 ³	MP1105	EP312	EP708	—
30100PC7784 ..	—	—	—	EP821	EP758	—
30100PC7785 ..	—	TP120 ³	MP1105	EP312	EP708	—
30100PC7787 ..	—	—	—	EP821	EP709	—
30100PC7791 ..	—	TP120 ³	MP1105	EP312	EP708	—
30100PC7792 ..	—	—	—	EP821	EP709	—
30100PC7793 ..	—	—	—	EP821	EP758	—
30100PD2005 ..	TP120	—	—	EP312	EP692	—
30100PD2006 ..	—	—	—	EP312	EP693	—
30100PD2601 ..	TP120	—	—	EP312	EP692	—
30100PD2602 ..	—	—	—	EP312	EP692	—
30100PD2611 ..	TP120	—	—	EP312	EP692	—
30100PD2612 ..	—	—	—	EP312	EP693	—
30100PD2621 ..	TP120	—	—	EP312	EP692	—
30100PD2622 ..	—	—	—	EP312	EP693	—
30100PD2661 ..	TP120	—	—	EP312	EP692	—
30100PD2662 ..	—	—	—	EP312	EP693 ¹⁴	—
30100PD2662 ..	—	—	—	EP312	EP757 ¹³	—
30100PD2663 ..	TP120	—	—	EP312	EP751	—
30100PD2664 ..	—	MP1103	—	EP821	EP676	—
30100PD2665 ..	—	TP120 ³	—	EP312	EP718	—
30100PD2671 ..	TP120	—	—	EP312	EP692	—
30100PD2672 ..	—	—	—	EP312	EP693	—

(continued on next page)

³ Control Module & Pickup Assembly ¹³ With side outlets ¹⁴ With top outlets

HONDA (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
30100PD2673	TP120	—	—	EP312	EP692	—
30100PD2674	—	—	—	EP312	EP693 ¹⁴	—
30100PD2674	—	—	—	EP312	EP757 ¹³	—
30100PD2675	TP120	—	—	EP312	EP751	—
30100PD2681	TP120	—	—	EP312	EP692	—
30100PD2682	—	—	—	EP312	EP693	—
30100PD2683	TP120	—	—	EP312	EP692	—
30100PD2684	—	—	—	EP312	EP693 ¹⁴	—
30100PD2684	—	—	—	EP312	EP757 ¹³	—
30100PD2685	—	—	—	EP312	EP751	—
30100PD2693	—	MP1103	—	EP821	EP676	—
30100PD2694	—	TP120 ³	—	EP312	EP718	VC4099
30100PD3641	—	TP120 ³	MP1104	EP312	EP693	—
30100PD3642	—	—	—	EP821	EP693	—
30100PD5641	—	TP120 ³	MP1104	EP312	EP693	—
30100PD5642	—	—	—	EP821	EP693	—
30100PD5781	—	TP120 ³	MP1104	EP312	EP693	—
30100PD5782	—	—	—	EP821	EP693	—
30100PD6006	—	—	—	EP312	EP693	—
30100PD6A02	—	—	—	EP469	EP867	—
30100PE0673	TP120	—	—	EP312	EP717	—
30100PE0674	TP120	—	—	—	—	—
30100PE0675	TP120	—	—	—	—	—
30100PE0676	TP120	—	—	—	—	—
30100PE0713	TP120	—	—	EP312	EP717	—
30100PE0714	TP120	—	—	—	—	—
30100PE0715	TP120	—	—	—	—	—
30100PE0716	TP120	—	—	—	—	—
30100PE0717	—	TP120 ³	MP1107	EP312	EP797	—
30100PE1672	TP120	—	—	EP312	EP717	—
30100PE1673	TP120	—	—	EP312	EP717	—
30100PE1674	TP120	—	—	EP312	EP717	—
30100PE1675	TP120	—	—	—	—	—
30100PE1676	TP120	—	—	—	—	—
30100PE1677	TP120	—	—	—	—	—
30100PE1678	TP120	—	—	—	—	—
30100PE1691	TP120	—	—	EP312	EP717	—
30100PE1692	TP120	—	—	—	—	—
30100PE1693	TP120	—	—	—	—	—
30100PE1702	TP120	—	—	EP312	EP717	—
30100PE1703	TP120	—	—	EP312	EP717	—
30100PE1704	TP120	—	—	EP312	EP717	—
30100PE1705	TP120	—	—	—	—	—
30100PE1706	TP120	—	—	—	—	—
30100PE1707	TP120	—	—	—	—	—
30100PE1717	TP120	—	—	—	—	—
30100PE1721	TP120	—	—	EP312	EP717	—
30100PE1722	TP120	—	—	—	—	—

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
30100PE1731	TP120	—	—	—	—	—
30100PE1961	TP120	—	—	EP312	EP717	—
30100PE1962	TP120	—	—	—	—	—
30100PE1963	TP120	—	—	—	—	—
30100PE1964	TP120	—	—	—	—	—
30100PE1971	—	TP120 ³	—	EP312	EP797	—
30100PE3016	—	—	—	EP821	EP693	—
30100PE3026	—	—	—	EP821	EP693	—
30100PE4731	—	—	—	EP821	EP693	—
30100PE4732	—	—	—	EP821	EP693	—
30100PE7642	—	—	—	EP821	EP693	—
30100PE7661	—	—	—	EP312	EP693	—
30100PE7662	—	—	—	EP312	EP693	—
30100PE7671	—	—	—	EP312	EP693	—
30100PE7672	—	—	—	EP312	EP693	—
30100PG7662	—	—	—	EP821	EP693	—
30100PH4602	—	—	—	EP821	EP693	—
30100PH4612	—	—	—	EP821	EP693	—
30100PH4661	TP120	—	—	EP312	EP708	—
30100PH4662	—	—	—	EP312	EP758	—
30100PH4663	TP120	—	—	EP312	EP708	—
30100PH4664	—	—	—	EP312	EP758	—
30100PH4665	TP120	—	—	EP312	EP708	—
30100PH4666	—	—	—	EP312	EP758	—
30100PH4671	TP120	—	—	EP312	EP708	—
30100PH4672	—	—	—	EP312	EP758	—
30100PH4673	TP120	—	—	EP312	EP708	—
30100PH4674	—	—	—	EP312	EP758	—
30100PH4681	TP120	—	—	EP312	EP708	—
30100PH4682	—	—	—	EP312	EP758	—
30100PH4683	TP120	—	—	EP312	EP708	—
30100PH4684	—	—	—	EP312	EP758	—
30100PH7672	—	—	—	EP776	EP777	—
30100PH7902	—	—	—	EP776	EP777	—
30100PJ0662	—	—	—	EP312	—	—
30100PJ0663	—	—	—	EP312	—	—
30100PJ0732	—	—	—	EP821	EP799	—
30100PJ0A02	—	—	—	EP821	EP799	—
30100PJ0A03	—	—	—	EP312	—	—
30100PJ0A04	—	—	—	EP821	EP799	—
30100PJ0A12	—	—	—	EP821	EP799	—
30100PJ0A13	—	—	—	EP312	—	—
30100PJ0A14	—	—	—	EP821	EP799	—
30100PK1661	—	—	—	EP312	EP708	—
30100PK1662	—	—	—	EP312	—	—
30100PK1671	—	—	—	EP312	EP708	—
30100PK1672	—	—	—	EP312	—	—
30100PK1681	—	—	—	EP312	EP708	—

(continued on next page)

³ Control Module & Pickup Assembly ¹³ With side outlets ¹⁴ With top outlets

HONDA (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
30100PK1682 ..	—	—	—	EP312	—	—
30100PK1691 ..	—	—	—	EP312	EP708	—
30100PK1692 ..	—	—	—	EP312	—	—
30100PK1701 ..	—	TP120 ³	MP1106	EP312	EP708	VC4101
30100PK1702 ..	—	—	—	EP821	EP812	—
30100PK1711 ..	—	TP120 ³	MP1106	EP312	EP708	—
30100PK1712 ..	—	—	—	EP821	EP812	—
30100PK2006 ..	—	—	—	EP807	EP812	—
30100PK2016 ..	—	—	—	EP807	EP806	—
30100PK2026 ..	—	—	—	EP807	EP806	—
30100PK2602 ..	—	—	—	EP807	EP806	—
30100PL2006 ..	—	—	—	EP822	EP825	—
30100PM5016 ..	—	—	—	EP332	EP804	—
30100PM5026 ..	—	—	—	EP332	EP804	—
30100PM5702 ..	—	—	—	EP332	EP804	—
30100PM5A02 ..	—	—	—	EP332	EP804	—
30100PM5A03 ..	—	—	—	EP332	EP804	—
30100PM5A04 ..	—	—	—	EP332	EP804	—
30100PM5A05 ..	—	—	—	EP332	EP804	—
30100PM5A07 ..	—	—	—	EP332	EP804	—
30100PM6006 ..	—	—	—	EP332	EP804	—
30100PM6016 ..	—	—	—	EP332	EP804	—
30100PM6026 ..	—	—	—	EP332	EP804	—
30100PM6046 ..	—	—	—	EP332	EP804	—
30100PM6702 ..	—	—	—	EP332	EP804	—
30100PM6A02 ..	—	—	—	EP332	EP804	—
30100PM6A04 ..	—	—	—	EP332	EP804	—
30100PM7006 ..	—	—	—	EP332	EP804	—
30100PM7016 ..	—	—	—	EP332	EP804	—
30100PM7026 ..	—	—	—	EP332	EP804	—
30100PO6A02 ..	—	—	—	EP469	EP867	—
30100POJA01 ..	—	—	—	EP469	EP478	—
30100PR4A12 ..	—	—	—	EP469	EP867	—

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
30100PT2A01 ..	—	—	—	EP469	EP478	—
30100PT3A02 ..	—	—	—	EP479	EP867	—
30100PT3A11 ..	—	—	—	EP479	EP867	—
30100PT3A12 ..	—	—	—	EP479	EP478	—
30100PT3A72 ..	—	—	—	EP479	EP867	—
30100PT4A01 ..	—	—	—	EP469	EP478	—
30100PV1A03 ..	—	—	—	EP488	EP491	—
31200PA5025 ..	—	TP120 ³	—	EP312	EP718	—
31200PA5661 ..	—	TP120 ³	—	EP312	EP718	VC4112
31200PA5686 ..	—	TP120 ³	—	EP312	EP718	VC4097
31200PA6015 ..	—	TP120 ³	—	EP312	EP718	VC4114
31200PA6045 ..	—	TP120 ³	—	EP312	EP718	VC4098
31200PA6663 ..	—	TP120 ³	—	EP312	EP718	—
31200PA6675 ..	—	TP120 ³	—	EP312	EP718	—
31200PA6693 ..	—	TP120 ³	—	EP312	EP718	VC4113
30100663791 ..	—	—	—	—	EP718	VC4111
30100676641 ..	—	MP1102	—	EP312	EP718	—
30100676643 ..	—	MP1102	—	EP312	EP718	—
30100676645 ..	—	—	—	EP821	EP676	—
30100676743 ..	—	MP1102	—	EP312	EP718	—
30100676744 ..	—	MP1102	—	EP312	EP718	—
30100676745 ..	—	—	—	EP821	EP676	—
30100689661 ..	—	MP1100	—	EP312	EP718	—
30100689662 ..	—	MP1102	—	EP312	EP718	—
30100689771 ..	—	MP1100	—	EP312	EP718	—
30100689781 ..	—	MP1100	—	EP312	EP718	—
30100689782 ..	—	MP1102	—	EP312	EP718	—
30100689791 ..	—	MP1100	—	EP312	EP718	—
31200634775 ..	—	—	—	EP312	EP718	VC4109
31200657674 ..	—	—	—	EP312	EP718	—
31200657812 ..	—	—	—	EP312	EP718	—

HYUNDAI

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
2710011010 ...	—	—	—	EP342	EP513
2710021410 ...	TP160	—	MP835	EP342	EP513
2710021420 ...	TP160	—	MP835	EP342	EP513
2710024301 ...	TP160	—	MP835	EP342	EP513
2710024311 ...	TP160	MP835	—	EP342	EP831
2710024511 ...	TP125	—	—	EP785	EP513
2710032111 ...	TP160	—	—	EP342	EP513
2710032130 ...	TP160	—	—	EP342	EP513

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
2710032810 ...	TP125	—	—	EP785	EP513
2710032820 ...	TP125	—	—	—	EP513
2710035000 ...	TP125	—	—	MO24	EP831
2710035010 ...	TP125	—	—	MO24	EP831
2710035020 ...	TP125	—	—	MO24	EP831

³ Control Module & Pickup Assembly

I.H.C.

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control	
170105C91		—	—	AL163	AL162	VC145	
170261C91		—	—	AL163	AL162		
170343C91		—	—	AL163	AL161		
170344C91		—	—	AL163	AL162		
170345C91		—	—	AL163	AL162		
170571C92		—	—	AL163	AL162		
170770C92		—	—	AL163	AL162		
405751R91		—	—	RR182R	RR183		
405752R92		—	—	RR182R	RR183		
428095C91	 TP85	—	—	FA8000	FA98		
446916C91	 TP85	—	—	FA157	FA98	VC145	
446916C92	 TP85	—	—	FA157	FA98		
446917C91	 TP85	—	—	FA157	FA98		
446917C92	 TP85	—	—	FA157	FA98		
446918C91	 TP85	—	—	FA157	FA98		
446918C92	 TP85	—	—	FA157	FA98		
446920C91	 TP85	—	—	FA157	FA98		
446920C92	 TP85	—	—	FA157	FA98		
446921C91	 TP85	—	—	FA157	FA98		
446921C92	 TP85	—	—	FA157	FA98		
448195C91	 TP85	—	—	FA157	FA98	VC145	
448685C91	 TP85	—	—	FA157	FA98		
448686C91	 TP85	—	—	FA157	FA98		
448783C91	 TP85	—	—	AL163	AL162		
461270C91	 TP85	—	—	FA157	FA98		
461271C91	 TP85	—	—	FA157	FA98		
461272C91	 TP85	—	—	FA157	FA98		
461273C91	 TP85	—	—	FA8000	FA98		
463330C91	 TP85	—	—	FA157	FA98		
463331C91	 TP85	—	—	FA157	FA98		
463332C91	 TP85	—	—	FA157	FA98	VC145	
463333C91	 TP85	—	—	FA157	FA98		
463334C91	 TP85	—	—	FA157	FA98		
463335C91	 TP85	—	—	FA157	FA98		
463336C91	 TP85	—	—	FA157	FA98		
464359C91	 TP85	—	—	FA8000	FA86		
467034C91	 TP85	—	—	FA157	FA98		
467035C91	 TP85	—	—	FA157	FA98		
467073C91	 TP85	—	—	FA157	FA98		
469648C91	 TP85	—	—	FA8000	FA98		
469649C91	 TP85	—	—	FA8000	FA98	VC145	
469650C91	 TP85	—	—	FA8000	FA98		
469668C91	 TP85	—	—	FA8000	FA98		
471273C91	 TP85	—	—	FA157	FA98		
472203C91	 TP85	—	—	FA157	FA98		
472908C91	 TP85	—	—	FA8000	FA98		
476165C91	 TP85	—	—	FA8000	FA86		
480870C91	 TP85	—	—	FA157	FA98		VC145
481270C91	 TP85	—	—	FA157	FA98		
483423C91	 TP85	—	—	FA157	FA98		
483433C91	 TP85	—	—	FA8000	FA98		
483492C91	 TP85	—	—	FA157	FA98		
483493C91	 TP85	—	—	FA8000	FA98		
484685C91	 TP85	—	—	FA8000	FA98		
484776C91	 —	—	—	AL163	AL161		
484777C91	 —	—	—	AL163	AL161		
484778C91	 —	—	—	AL163	AL162		
484783C91	 —	—	—	AL163	AL162	VC145	
484785C91	 —	—	—	AL163	AL162		
484785C92	 —	—	—	AL163	AL162		
484786C91	 —	—	—	AL163	AL162		
484786C92	 —	—	—	AL163	AL162		
484788C91	 —	—	—	AL163	AL162		
484788C92	 —	—	—	AL163	AL162		
484790C91	 —	—	—	AL163	AL162		
484790C92	 —	—	—	AL163	AL162		
484792C91	 —	—	—	AL163	AL162		
484792C92	 —	—	—	AL163	AL162	VC145	
484794C91	 —	—	—	AL163	AL162		
484794C92	 —	—	—	AL163	AL162		
484797C91	 —	—	—	AL163	AL162		
484804C91	 —	—	—	AL163	AL162		
484804C92	 —	—	—	AL163	AL162		
491250C91	 —	—	—	AL163	AL162		
491344C91	 TP85	—	—	AL163	AL161		
491345C91	 TP85	—	—	AL163	AL161		
491346C91	 TP85	—	—	AL163	AL162		
491347C91	 TP85	—	—	AL163	AL162	VC145	
491348C91	 TP85	—	—	FA8000	FA98		
491349C91	 TP85	—	—	AL163	AL162		
491350C91	 —	—	—	AL163	AL162		
491351C91	 TP85	—	—	AL163	AL162		
491352C91	 TP85	—	—	AL163	AL162		
491353C91	 TP85	—	—	AL163	AL162		
491354C91	 TP85	—	—	AL163	AL162		
491355C91	 TP85	—	—	AL163	AL162		
491356C91	 TP85	—	—	AL163	AL162		
496003C91	 —	—	—	AL163	AL161	VC145	
496004C91	 —	—	—	AL163	AL162		
497600C91	 —	—	—	AL163	AL161		
519861C91	 TP85	—	—	FA8000	FA98		
497600091	 —	—	—	AL163	AL161		

(continued on next column)

ISUZU

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
0941764882 ...	TP189	MP207	—	RR246	RR248
0941782192 ...	TP189	MP207	—	RR246	RR248
8941095804 ...	—	—	—	EP324	EP724
8941367650 ...	TP120	—	—	—	—
8941476120 ...	—	—	—	EP784	EP796
8941574680 ...	—	—	—	EP324	EP724
8941619730 ...	TP120	—	—	—	—
8941672490 ...	TP120	—	—	—	—
8941723460 ...	—	—	—	—	EP346
8941782192 ...	TP189	MP207	—	—	RR248
8942172420 ...	—	MP129	—	EP674	EP705
8942226710 ...	—	MP129	—	EP674	EP705
8942226720 ...	—	MP129	—	EP674	EP705

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
8942305800 ...	—	MP129	—	EP674	EP705
8942335330 ...	—	MP129	—	EP674	EP705
8942537440 ...	—	—	—	EP324	EP724
8942537441 ...	—	—	—	EP324	EP724
8942537450 ...	—	MP1400	—	EP324	EP724
8942537451 ...	—	—	—	EP324	EP724
8942584390 ...	—	—	—	—	EP346
8944195591 ...	TP189	MP207	—	—	RR248
8944284110 ...	—	—	—	EP784	EP796
8970404540 ...	—	—	—	EP784	EP840
8971078520 ...	—	—	—	EP784	EP840

LUCAS

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
DAC4758	—	—	—	EP896	EP897
DBC2690	—	—	—	EP885	EP868
41383	—	—	—	EP71	EP78
41387	—	—	MP506	EP62	EP65
41593	—	—	—	EP62	EP61
41600	—	—	—	EP62	EP61
41601	—	—	—	EP62	EP61
41603	—	—	—	EP62	EP61
41643	—	—	—	EP62	EP61
41646	—	—	—	EP62	EP61
41649	—	—	—	EP62	EP63
41656	—	—	—	EP62	EP61
41693	—	—	EP67	EP62	EP61
41695	—	—	EP67	EP62	EP61
41697	—	—	EP67	EP62	EP61

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
41698	—	—	EP67	EP62	EP61
41700	—	—	EP67	EP62	EP61
41701	—	—	EP67	EP62	EP61
41711	—	—	—	EP62	EP63
41807	—	—	—	EP62	EP61
41808	—	—	—	EP62	EP61
41825	—	MP504	MP506	—	EP65
41837	—	—	MP506	—	—
41879H	—	—	—	EP62	EP740
41922	—	—	—	EP62	EP740
41922D	—	—	—	EP62	EP740
41990	—	—	—	EP885	EP868
42640	—	—	—	—	EP869

MARELLI

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
SM800AK	TP45	MP317	—	EP247	EP732
SM800AX	TP45	—	—	—	—
SM800BK	TP45	MP317	—	EP247	EP732
SM800BX	TP45	—	—	—	—
SM800CX	TP45	—	—	—	—
SM800E	TP45	MP317	—	EP247	EP732
SM800EX	TP45	—	—	—	—

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
SM801AX	TP45	—	—	—	—
SM801BX	TP45	—	—	—	—
SM807AX	TP45	—	—	—	EP732
SM807BX	TP45	—	—	—	EP732

MAZDA

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Ign Coil	Vac Control
AM1518200	—	—	MP835	EP342	EP513	—	—
B3F518200	—	—	—	—	EP827	—	—
B3F518200A	—	—	—	EP816	EP827	—	—
B6A718200C	—	MP719	—	—	EP826	—	—
B6B118200	—	TP180	—	EP738	EP800	—	—
B6B518200B	—	MP1308	—	—	EP815	—	—
B6D518200B	—	—	—	—	EP826	—	—
B6D518200B	—	—	—	EP729	EP826	—	—
B6S718300B	—	—	—	—	EP849	—	—
B6V518200	—	MP1308	—	EP729	EP826	—	VC4089
B6VD18200	—	—	—	EP780	EP826	—	—
B6VS18200	—	MP1308	—	EP729	EP826	—	VC4089
B61G18200A	—	MP1308	—	—	EP826	—	VC4089
B30318200D	—	—	—	EP780	FA137	—	—
B30318200E	—	—	—	EP780	FA137	—	—
B30718200	—	MP719	—	—	EP815	—	—
B30818200A	—	MP719	—	—	EP815	—	—
B35918200	—	—	—	EP780	FA137	—	—
B50118200A	—	MP1308	—	EP780	EP815	—	—
B60318200A	—	TP180	—	EP738	EP800	—	—
B66018200C	—	MP1308	—	—	EP826	—	VC4089
B67518200A	—	MP1308	—	—	EP815	—	—
B68518200	—	MP1308	—	EP729	EP826	—	VC4089
BJ0118200C	—	—	—	EP729	EP826	—	—
BP1A18200	—	—	—	EP546	EP501	—	—
BP0118200	—	—	—	EP895	EP827	—	—
BP0118200A	—	—	—	—	EP827	—	—
BP0218200	—	—	—	—	EP827	—	—
BP0218200A	—	—	—	—	EP827	—	—
BP0518200A	—	—	—	—	EP827	—	—
BP0518200B	—	—	—	—	EP827	—	—
BPO518200A	—	—	—	MO35	EP827	—	—
D30318200A	—	—	—	EP658	EP675	—	—
D53018200A	—	MP719	—	—	EP815	—	—
E5D618200	—	MP719	—	—	—	—	—
E35718200A	—	MP719	—	—	—	—	—
E50818200B	—	—	—	EP342	EP718	—	—
E56318200	—	—	—	EP342	EP718	—	—
F2C718200	—	—	—	—	EP827	—	—
F2G818100A	—	—	—	—	EP815	—	—
F2G818200B	—	—	—	—	EP849	—	—
F2G818200C	—	—	—	—	EP849	—	—
F8B118200D	—	MP1308	MP1317	—	EP728	—	—
F8B118200E	—	MP719	MP1317	—	EP728	—	—
F8B318200C	—	MP719	MP1317	—	EP728	—	—
F8B518200	—	MP1308	—	—	EP815	—	—
F8B518200A	—	—	—	—	EP815	—	—
F8E218200A	—	—	—	—	EP815	—	—
F8G318200	—	MP719	MP1317	EP729	EP728	—	—

(continued on next page)

MAZDA (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Ign Coil	Vac Control
F8G818200	—	MP719	—	EP729	EP728	—	—
F8H318200	—	—	—	EP816	—	—	—
F22018200C	—	—	—	EP816	EP827	—	—
F24018200	—	MP1308	—	EP780	EP815	—	—
F26218200	—	MP719	—	EP729	EP728	—	—
F28518200	—	MP719	—	EP729	EP728	—	—
F28718200	—	—	—	—	EP827	—	—
F80118200F	—	MP1310	—	EP658	EP675	—	—
F80718200D	—	MP1310	—	EP658	EP675	—	—
F82018200B	—	MP1310	—	EP658	EP675	—	—
F82218200B	—	MP1310	—	EP658	EP675	—	—
F82318200A	—	MP1310	—	EP658	EP675	—	—
F82918200C	—	MP719	—	—	EP815	—	—
F85018200J	—	—	—	EP658	EP675	—	—
FE1H18200	—	MP1308	—	EP780	EP815	—	—
FE2H18200D	—	MP1308	—	—	EP815	—	—
FE2J18200	—	MP1308	—	—	EP815	—	—
FE3N18200	—	—	—	—	EP827	—	—
FE3N18200A	—	—	—	—	EP827	—	—
FE4S18200A	—	MP1308	—	—	EP815	—	—
FE4S18200B	—	MP719	—	—	EP815	—	—
FE6L18200A	—	MP719	—	—	EP815	—	—
FE8N18200D	—	MP1308	—	—	EP815	—	—
FE0118200A	—	MP1310	—	EP658	EP675	—	—
FE0218200	—	MP1310	—	EP658	EP675	—	—
FE0318200	—	MP1310	—	EP658	EP675	—	—
FE0418200	—	MP1310	—	EP658	EP675	—	—
FE0518200C	—	MP1310	—	EP658	EP675	—	—
FE1418200E	—	MP1310	—	EP658	EP675	—	—
FE1518200D	—	MP1310	—	EP658	EP675	—	—
FE3018200E	—	—	—	EP658	EP675	—	—
FE5118200J	—	—	—	EP658	EP675	—	—
FE6518200E	—	MP1310	—	EP658	EP675	—	—
FE6818200F	—	MP1310	—	EP658	EP675	—	—
FE7918200F	—	—	—	EP658	EP675	—	—
FE8518200A	—	MP1310	—	EP658	EP726	—	—
FEAN18200	—	—	—	—	EP827	—	—
FEEG18200	—	—	—	EP780	EP815	—	—
FEEG18200B	—	MP719	—	EP780	EP815	—	—
FEEH18200	—	—	—	EP780	EP815	—	—
FEEH18200C	—	MP719	—	EP780	EP815	—	—
FEFB18200B	—	MP719	—	EP780	EP815	—	—
FEFC18200B	—	MP719	—	EP780	EP815	—	—
FEG718200C	—	—	—	EP658	EP675	—	—
FEH118200A	—	MP1310	—	EP658	EP675	—	—
FEH518200A	—	MP1308	—	EP729	EP736	—	—
FS0718200A	—	—	—	—	EP417	—	—
FS7818200	—	—	—	EP415	EP417	IC24	—
FS7818200A	—	—	—	EP415	EP417	IC24	—

(continued on next page)

MAZDA (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Ign Coil	Vac Control
FSB918200	—	—	—	EP415	EP417	IC24	—
G60118200B	—	—	—	—	EP849	—	—
G60718200A	—	—	—	—	EP849	—	—
G60918200A	—	—	—	—	EP849	—	—
G60918200B	—	—	—	—	EP849	—	—
H80618200B	—	MP1310	—	EP658	EP675	—	—
HE0118200	—	MP1310	—	EP658	EP675	—	—
HE8718200	—	MP1310	—	EP658	EP675	—	—
JE0118200B	—	—	—	EP846	EP889	—	—
JE1518200B	—	—	—	—	EP889	—	—
JE4818200	—	—	—	EP878	EP884	—	—
JF0118200C	—	—	—	EP684	EP813	—	—
JF0718100B	—	—	—	EP684	EP813	—	—
JF0718200B	—	—	—	EP878	EP884	—	—
JF0718200C	—	—	—	EP684	EP813	—	—
KF3412000A	—	—	—	EP567	EP499	—	—
N20118200	—	MP1303	—	EP691	EP690	—	—
N22518200B	—	MP1303	—	EP691	EP690	—	—
N23118200A	—	MP1303	—	EP691	EP690	—	—
N24518200A	—	MP1303	—	EP691	EP690	—	—
N24618200A	—	MP1303	—	EP691	EP690	—	—
N24918200	—	MP1303	—	EP691	EP690	—	—
N24918200A	—	MP1303	—	EP691	EP690	—	—
N30418200A	—	MP1303	—	EP691	EP690	—	—
N30418200B	—	MP1303	—	EP691	EP690	—	—
N30618200A	—	MP1303	—	EP691	EP690	—	—
TE2J18200A	—	MP1308	—	—	EP815	—	—
823918200	—	MP713	—	EP342	EP706	—	—
832518200	—	—	—	EP342	EP718	—	—
834118200	TP162	MP1303	—	EP691	EP690	—	—
834218200	TP162	MP1303	—	EP691	EP690	—	—
835618200	—	MP820	—	EP658	EP660	—	—
838718200	—	MP1310	—	EP658	EP675	—	—
867818200	—	MP820	—	EP658	EP660	—	—
868218200A	—	—	—	EP342	EP706	—	—
876818200	—	—	—	EP658	EP660	—	—

MITSUBISHI

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
MD013791	—	MP818	—	EP658	EP675	—
MD027695	—	—	—	—	EP675	—
MD027800	—	—	—	EP342	—	—
MD034142	—	—	—	EP658	EP675	—
MD060390	—	MP818	—	EP658	EP675	—
MD064228	—	—	—	EP342	—	—
MD066836	—	—	—	EP658	EP675	—
MD068602	—	—	—	EP658	EP675	—

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
MD073070	—	—	MP836	EP342	EP513	—
MD073446	—	MP821	MP821	EP342	EP513	—
MD073525	—	—	MP835	EP342	EP513	—
MD074646	—	MP821	MP838	EP342	EP513	—
MD074934	—	—	MP835	EP342	EP513	—
MD074996	—	—	MP835	EP342	EP513	—
MD074998	—	—	MP835	EP342	EP513	—
MD074999	—	—	MP835	EP342	EP513	—

(continued on next column)

(continued on next page)

MITSUBISHI (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
MD075009	—	—	MP835	EP342	EP513	—
MD075777	—	—	—	EP658	EP675	—
MD076765	—	MP821	MP838	EP342	EP513	—
MD078618	—	—	MP835	EP342	EP513	—
MD080151	—	—	MP835	EP342	EP513	—
MD082010	—	—	MP838	EP342	EP513	—
MD083743	—	MP821	MP838	EP342	EP513	—
MD084035	TP131	MP829	—	—	—	—
MD084038	—	MP829	—	—	—	—
MD084040	—	—	—	—	EP725	—
MD084041	—	—	—	—	EP725	—
MD084893	—	MP829	—	—	—	—
MD086077	—	—	MP838	EP342	EP513	—
MD088686	—	—	MP835	EP342	EP513	—
MD089285	—	—	MP835	EP342	EP513	—
MD090640	—	—	MP835	EP342	EP513	—
MD090641	—	—	MP835	EP342	EP513	—
MD094036	—	—	—	EP324	EP725	—
MD097968	—	MP818	—	EP658	EP675	—
MD098390	—	TP175	MP835	EP342	EP513	VC4107
MD099665	—	—	MP835	EP342	EP513	—
MD099666	—	—	MP835	EP342	EP513	—
MD100432	—	—	MP835	EP342	EP513	—
MD100433	—	—	MP835	EP342	EP513	—
MD100434	—	—	—	EP342	EP513	—
MD100435	—	—	—	EP342	EP513	—
MD103134	—	MP821	MP838	EP342	EP513	—
MD103419	—	—	MP835	EP342	EP513	—
MD104695	—	—	—	EP785	—	—
MD105440	—	—	MP835	—	—	—
MD106134	—	—	MP838	EP342	EP513	—
MD107637	—	—	MP835	EP342	EP513	—
MD107857	—	—	MP835	EP342	EP513	—
MD108019	—	—	—	EP342	EP513	—
MD109013	—	—	MP835	EP342	EP513	VC4105
MD109555	—	—	MP838	EP342	EP513	—
MD109556	—	MP821	MP838	EP342	EP513	—
MD109933	—	—	MP838	EP342	EP513	—
MD109934	—	—	—	EP658	EP675	—
MD109935	—	—	—	EP658	EP675	—
MD109936	—	—	—	EP658	EP675	—
MD109937	—	MP823	—	EP658	EP675	—
MD109938	—	MP823	—	EP658	EP675	VC4084
MD109949	—	TP175	MP835	EP342	EP513	VC4107
MD110264	—	—	MP835	EP342	EP513	VC4103
MD110418	—	—	—	EP324	EP725	—
MD110419	—	—	—	EP324	EP725	—
MD110440	—	—	—	EP324	EP725	—

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
MD111112	—	—	MP835	EP342	EP513	VC4085
MD111261	—	—	MP835	EP342	EP513	—
MD111738	—	—	MP835	EP342	EP513	VC4108
MD111795	—	—	—	EP342	EP513	—
MD111973	—	—	MP835	EP342	EP513	—
MD113955	—	—	MP835	EP342	EP513	—
MD114781	—	—	—	MO24	—	—
MD116211	—	—	—	MO24	MO23	—
MD118706	—	—	—	MO24	EP831	—
MD119306	—	—	—	EP886	EP857	—
MD119754	—	MP823	—	EP658	EP675	VC4084
MD120275	—	—	MP835	EP342	EP513	—
MD120728	—	—	MP835	EP342	EP513	—
MD125098	—	—	MP835	EP342	EP513	—
MD125099	—	—	MP835	EP342	EP513	—
MD125103	—	—	—	EP324	EP725	—
MD125264	—	—	—	—	EP831	—
MD125509	—	—	—	EP785	EP857	—
MD126680	—	—	MP835	MO24	MO23	—
MD127420	—	—	MP835	EP342	EP513	VC4085
MD129372	—	—	—	MO24	EP831	—
MD132020	—	—	MP835	EP342	EP513	—
MD134364	—	MP823	—	EP785	EP513	VC4084
MD137230	—	—	—	EP339	—	—
MD143571	—	—	—	EP785	MO23	—
MD145496	—	—	—	EP437	—	—
MD145751	—	—	—	EP785	—	—
MD147116	—	—	—	EP785	—	—
MD147874	—	—	—	MO24	EP831	—
MD147875	—	—	—	MO24	EP831	—
MD148008	—	—	—	MO24	MO23	—
MD149512	—	—	—	MO24	MO23	—
MD153199	—	—	—	EP886	EP309	—
MD155852	—	—	—	EP886	EP313	—
MD156252	—	—	—	EP339	EP335	—
MD156617	—	—	—	EP886	—	—
MD156722	—	TP125	—	EP339	EP335	—
MD161466	—	—	MP835	EP342	EP513	—
MD162108	—	—	MP835	EP342	EP513	—
MD162109	—	—	MP835	EP342	EP513	—
MD163989	—	—	—	MO24	EP802	—
MD171706	—	—	—	EP339	—	—
MD173072	—	—	MP835	EP342	EP513	—
MD180936	—	—	—	EP437	EP349	—
MD180938	—	—	—	EP437	—	—
MD181469	—	—	—	EP339	—	—
MD188610	—	—	—	EP437	—	—
MD190166	—	—	—	EP339	EP335	—

(continued on next page)

MITSUBISHI (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
MD190167	—	—	—	EP437	EP349	—
MD190168	—	—	—	EP437	EP349	—
MD198182	—	—	—	EP339	—	—
MD198219	—	—	—	EP901	EP349	—
MD305060	—	—	—	MO24	MO23	—
MD305080	—	—	—	MO24	MO23	—
MD313403	—	—	—	EP437	EP349	—
MD314904	—	—	—	MO33	MO32	—
MD316173	—	—	—	MO33	MO32	—
MD320732	TP125	—	—	MO24	EP802	—
MD322639	—	—	—	MO24	MO23	—
MD326587	—	—	—	EP544	EP352	—
MD326588	—	—	—	EP544	EP538	—
MD326834	—	—	—	EP544	EP333	—
MD327305	—	—	—	EP567	EP547	—
MD329094	—	—	—	EP544	EP352	—
MD331092	—	—	—	MO33	MO32	—
MD342884	—	—	—	EP498	EP575	—
MD343019	—	—	—	MO33	MO32	—
MD345492	—	—	—	MO33	MO32	—
MD375920	—	—	—	EP498	EP575	—
MD1982198	—	—	—	EP901	EP349	—
MM115552	—	—	MP835	EP342	EP513	—
T2T42071	TP233	—	—	EP786	EP778	—
T4T624718387	—	—	—	—	EP675	—
T000T60271	—	—	MP419	—	—	—
T000T60278	—	—	MP419	—	EP775	—
T000T60376	—	—	MP419	—	—	—
T000T60686	—	—	MP419	—	—	—
T000T60971	—	—	MP419	—	—	—
T000T61571	—	—	—	—	EP775	—
T000T62278	—	—	MP419	—	EP775	—
T000T62372	—	—	—	—	EP775	—
T000T62572	—	—	—	EP824	EP775	—
T000T71072	—	—	—	—	EP775	—
T000T71172	—	—	—	—	EP775	—
T000T71271	—	—	—	—	EP775	—
T000T71371	—	—	—	EP824	EP775	—
T000T75071	—	—	—	EP846	—	—
T000T80871	—	—	MP419	—	—	—
T000T80874	—	—	MP419	—	—	—
T001T12573	—	—	—	EP342	—	—
T001T42073	—	—	—	EP785	—	—
T001T42074	—	—	—	EP785	—	—
T002M52273	—	—	—	EP339	—	—
T002T45371	—	—	—	—	EP815	—
T002T52171	—	—	—	EP816	—	—
T002T52371	—	—	—	—	EP827	—

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
T002T52471	—	—	—	—	EP827	—
T002T52571	—	—	—	—	EP827	—
T002T52971	—	—	—	EP816	—	—
T002T53371	—	—	—	EP339	EP335	—
T002T53372	—	—	—	EP339	EP335	—
T002T55071	—	—	—	EP816	—	—
T002T72171	—	MP1308	—	—	EP815	—
T002T72172	—	MP1308	—	—	EP815	—
T002T72173	—	—	—	EP780	EP815	—
T002T72174	—	—	—	EP780	EP815	—
T002T72175	—	MP1308	—	—	EP815	—
T002T72176	—	MP1308	—	—	EP815	—
T002T72177	—	—	—	EP780	EP815	—
T002T72179	—	—	—	EP780	EP815	—
T002T72180	—	—	—	EP780	EP815	—
T002T72181	—	—	—	EP780	EP815	—
T002T73671	—	—	—	—	EP815	—
T002T75371	—	—	—	EP780	—	—
T003T05791	—	—	—	EP342	EP513	—
T003T05792	—	—	—	EP342	EP513	—
T003T05793	—	—	—	EP342	EP513	—
T003T05795	—	—	—	EP342	EP513	—
T003T06371	—	—	—	EP342	—	—
T003T07473	—	—	—	EP342	—	—
T003T07671	—	—	—	EP342	—	—
T003T61771	—	—	—	EP342	—	—
T003T61875	—	—	MP835	EP342	EP513	—
T003T61877	—	—	MP835	EP342	EP513	—
T003T61882	—	—	—	EP342	—	—
T003T61883	—	—	MP835	EP342	EP513	—
T003T61884	—	—	MP835	EP342	EP513	—
T003T61886	—	—	MP835	EP342	EP513	—
T003T61895	—	—	MP835	EP342	EP513	—
T003T61991	—	—	MP835	EP342	EP513	—
T003T62179	—	—	MP835	EP342	EP513	—
T003T62185	—	—	MP835	EP342	EP513	—
T003T62371	—	—	MP835	EP342	EP513	—
T003T62472	—	—	MP835	EP342	EP513	—
T003T62493	—	—	MP835	EP342	EP513	—
T003T62494	—	—	MP835	EP342	EP513	—
T003T62972	—	—	MP835	EP342	EP513	—
T003T62973	—	—	MP835	EP342	EP513	—
T003T62974	—	—	MP835	EP342	EP513	—
T003T62975	—	—	MP835	EP342	EP513	—
T003T62977	—	—	MP835	EP342	EP513	—
T003T62979	—	—	MP835	EP342	EP513	—
T003T62980	—	—	MP835	EP342	EP513	—
T003T62985	—	—	MP835	EP342	EP513	—

(continued on next page)

MITSUBISHI (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
T003T62988 ...	—	—	MP835	EP342	EP513	—
T003T62989 ...	—	—	MP835	EP342	EP513	—
T003T62993 ...	—	—	MP835	EP342	EP513	—
T003T62994 ...	—	—	MP835	EP342	EP513	—
T003T62997 ...	—	—	MP835	EP342	EP513	—
T003T63072 ...	—	MP821	MP838	EP342	EP513	—
T003T63172 ...	—	MP821	MP821	EP342	EP513	—
T003T63173 ...	—	MP821	MP838	EP342	EP513	—
T003T63175 ...	—	MP821	MP838	EP342	EP513	—
T003T63178 ...	—	MP821	MP838	EP342	EP513	—
T003T63179 ...	—	—	MP838	EP342	EP513	—
T003T63185 ...	—	—	MP838	EP342	EP513	—
T003T63187 ...	—	MP821	MP838	EP342	EP513	—
T003T64171 ...	—	—	—	EP785	—	—
T003T64172 ...	—	—	—	EP785	—	—
T003T64173 ...	—	—	—	EP785	—	—
T003T64271 ...	—	—	—	EP785	—	—
T003T64272 ...	—	—	—	EP785	—	—
T003T65175 ...	—	—	MP838	EP342	EP513	—
T003T65178 ...	—	—	MP838	EP342	EP513	—
T003T65187 ...	—	—	MP838	EP342	EP513	—
T003T65674 ...	—	—	MP835	EP342	EP513	—
T003T65676 ...	—	—	MP835	EP342	EP513	—
T004M72273 ...	—	—	—	EP729	EP826	—
T004M72274 ...	—	MP1308	—	—	EP826	VC4089
T004T62076 ...	—	—	—	EP658	EP675	—
T004T62177 ...	—	—	—	EP658	EP675	—
T004T62378 ...	—	—	—	EP658	EP675	—
T004T62379 ...	—	—	—	EP658	EP675	—
T004T62381 ...	—	—	—	EP658	EP675	—
T004T62474 ...	—	MP1310	—	EP658	EP675	—
T004T62971 ...	—	—	—	EP658	EP675	—
T004T63071 ...	—	MP1310	—	EP658	EP675	—
T004T63072 ...	—	MP1310	—	EP658	EP675	—
T004T63073 ...	—	MP1310	—	EP658	EP675	—
T004T63172 ...	—	MP1310	—	EP658	EP675	—
T004T63176 ...	—	MP1310	—	EP658	EP675	—
T004T63177 ...	—	MP1310	—	EP658	EP675	—
T004T63799 ...	—	MP1310	—	EP658	EP675	—
T004T63971 ...	—	—	—	EP658	EP675	—
T004T64071 ...	—	—	—	EP658	EP675	—
T004T64072 ...	—	—	—	EP658	EP675	—
T004T64073 ...	—	MP1310	—	EP658	EP675	—
T004T64273 ...	—	—	—	EP658	EP675	—
T004T64471 ...	—	MP1310	—	EP658	EP675	—
T004T65771 ...	—	—	—	EP658	EP815	—
T004T65972 ...	—	MP1310	—	EP658	EP675	—
T004T66071 ...	—	MP1310	—	EP658	EP675	—

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
T004T66075 ...	—	MP1310	—	EP658	EP675	—
T004T66171 ...	—	—	—	EP658	EP675	—
T004T67073 ...	—	—	—	EP658	EP675	VC4084
T004T67178 ...	—	—	—	EP658	EP675	—
T004T67179 ...	—	—	—	EP658	EP675	—
T004T67181 ...	—	—	—	EP658	EP675	—
T004T67271 ...	—	MP1308	—	—	EP815	—
T004T67272 ...	—	MP1308	—	—	EP815	—
T004T67273 ...	—	MP1308	—	—	EP815	—
T004T67274 ...	—	MP1308	—	—	EP815	—
T004T67275 ...	—	MP1308	—	—	EP815	—
T004T67671 ...	—	MP1308	—	—	EP815	—
T004T67673 ...	—	MP1308	—	—	EP815	—
T004T71171 ...	—	—	—	EP658	—	—
T004T71172 ...	—	—	—	EP658	—	—
T004T71271 ...	—	—	—	EP658	—	—
T004T71371 ...	—	—	—	EP658	—	—
T004T71479 ...	—	—	—	EP658	—	—
T004T72271 ...	—	MP1308	—	—	EP826	VC4089
T004T72273 ...	—	MP1308	—	—	EP826	VC4089
T004T72274 ...	—	MP1308	—	—	EP826	VC4089
T004T72373 ...	—	MP1308	—	—	EP815	—
T004T72571 ...	—	—	MP1317	EP729	EP728	—
T004T72572 ...	—	MP719	—	—	EP728	—
T004T72574 ...	—	MP719	—	EP729	EP728	—
T004T72671 ...	—	MP719	—	EP729	EP826	—
T004T72673 ...	—	MP1308	—	EP729	EP826	—
T004T72674 ...	—	MP1308	—	EP729	EP826	—
T004T73471 ...	—	—	—	—	EP827	—
T004T73472 ...	—	—	—	—	EP827	—
T004T73671 ...	—	MP1308	—	—	EP815	—
T004T73672 ...	—	MP1308	—	—	EP815	—
T004T73775 ...	—	MP1308	—	—	EP815	—
T004T73971 ...	—	—	MP1317	—	EP728	—
T004T74371 ...	—	—	—	—	EP827	—
T004T74571 ...	—	MP1308	—	—	EP815	—
T004T76971 ...	—	MP1308	MP1317	—	EP728	—
T004T84091 ...	—	—	—	—	EP778	—
T004T84092 ...	—	—	—	—	EP778	—
T005T42171 ...	—	—	—	MO24	MO23	—
T005T42371 ...	—	—	—	MO24	MO23	—
T005T42471 ...	—	—	—	MO24	MO23	—
T005T42571 ...	—	—	—	MO24	EP831	—
T005T42671 ...	—	—	—	MO24	EP831	—
T005T42771 ...	—	—	—	MO24	—	—
T005T60373 ...	—	MP1303	—	EP691	EP690	—
T005T60378 ...	—	MP1303	—	EP691	EP690	—
T005T60572 ...	—	MP1303	—	EP691	EP690	—

(continued on next page)

MITSUBISHI (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
T005T60573 ...	—	MP1303	—	EP691	EP690	—
T005T61171 ...	—	—	—	MO24	EP741	—
T005T61172 ...	—	—	—	MO24	EP741	—
T005T61173 ...	—	—	—	MO24	EP741	—
T005T61174 ...	—	—	—	MO24	EP741	—
T005T61971 ...	—	—	—	MO24	EP831	—
T005T61972 ...	—	—	—	MO24	EP831	—
T005T62171 ...	—	—	—	MO24	—	—
T005T62374 ...	—	—	—	MO24	EP741	—
T005T72071 ...	—	—	—	—	EP831	—
T006M57671 ...	—	—	—	EP437	EP349	—
T006M57771 ...	—	—	—	EP437	—	—

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
T006T57071 ...	—	—	—	EP886	EP857	—
T006T57171 ...	—	—	—	EP886	EP309	—
T006T57371 ...	—	—	—	EP886	EP313	—
T006T58071 ...	—	—	—	EP437	EP349	—
T006T58171 ...	—	—	—	EP437	EP349	—
T006T87071 ...	—	—	—	EP437	—	—
2710021350 ...	—	—	MP835	EP342	EP513	—
2710021360 ...	—	—	MP835	EP342	EP513	—
2710021430 ...	—	—	MP835	EP342	EP513	—
2710021440 ...	—	—	MP835	EP342	EP513	—
2710024511 ...	—	—	—	EP785	EP513	—

NIPPONDENSO

Unit No	Module	Pick-Up	Reluctor	Rotor
420857002 ...	—	MP1205	—	—

NISSAN-DATSUN

Unit No	Module	Pick-Up	Contact Assembly	Reluctor	Rotor	Cap	Vac Control
D4F401	—	MP403	MP408	—	EP345	EP346	—
D4F402	—	MP403	MP408	—	EP345	EP346	—
D4F403	—	MP401	MP408	—	EP345	EP346	—
D4F404	—	MP401	MP408	—	EP345	EP346	—
D4F501	—	MP403	MP408	—	EP345	EP346	—
D4F502	—	MP402	MP408	—	EP345	EP346	—
D4F503	—	MP403	MP408	—	EP345	EP346	—
D4F504	—	MP402	MP408	—	EP345	EP346	—
D4F505	—	MP403	MP408	—	EP345	EP346	—
D4F506	—	MP400	MP408	—	EP345	EP346	—
D4F507	—	MP400	MP408	—	EP345	EP346	—
D4F601	—	MP403	MP408	—	EP345	EP346	—
D4F603	—	MP403	MP408	—	EP345	EP346	—
D4F604	—	MP400	MP408	—	EP345	EP346	—
D4F608	—	MP400	MP408	—	EP345	EP346	—
D4F609	—	MP400	MP408	—	EP345	EP346	—
D4F701	—	MP403	MP408	—	EP345	EP346	—
D4K802	—	MP405	—	—	EP345	EP346	—
D4K803	—	—	—	—	EP345	EP346	—
D4K804	—	—	—	—	EP345	EP346	—
D4K805	—	—	—	—	EP345	EP346	—
D4K806	—	—	—	—	EP345	EP346	—
D4K807	—	—	—	—	EP345	EP346	—
D4K808	—	—	—	—	EP345	EP346	—
D4K809	—	—	—	—	EP345	EP346	—
D4K810	—	—	—	—	EP345	EP346	—

(continued on next page)

NISSAN-DATSUN (Cont'd)

Unit No	Module	Pick-Up	Contact Assembly	Reluctor	Rotor	Cap	Vac Control
D4K813	—	MP405	—	—	EP345	EP346	—
D4K815	—	MP405	—	—	EP345	EP346	—
D4K816	—	MP405	—	—	EP345	EP346	—
D4K817	—	MP405	—	—	EP345	EP346	—
D4K818	—	MP405	—	—	EP345	EP346	—
D4K819	—	MP405	—	—	EP345	EP346	—
D4K901	—	—	—	—	EP345	EP346	—
D4K902	—	—	—	—	EP345	EP346	—
D4K903	—	—	—	—	EP345	EP346	—
D4K904	—	MP405	—	—	EP345	EP346	—
D4K905	—	MP405	—	—	EP345	EP346	—
D4K906	—	MP405	—	—	EP345	EP346	—
D4K907	—	MP405	—	—	EP345	EP346	—
D4K909	—	MP404	—	—	EP345	EP346	—
D4K910	—	MP404	—	—	EP345	EP346	—
D4K912	—	MP405	—	—	EP345	EP346	—
D4K914	—	MP404	—	—	EP345	EP346	—
D6F301	—	—	—	—	EP345	EP347	—
D6F302	—	—	—	—	EP345	EP347	—
D6F401	—	—	MP408	MP406	EP345	EP347	—
D6F402	—	—	MP408	MP406	EP345	EP347	—
D6F403	—	MP403	MP408	MP406	EP345	EP347	—
D6F502	—	MP403	MP408	MP406	EP345	EP347	—
D6F503	—	MP403	MP408	MP406	EP345	EP347	—
D6F601	—	MP403	MP408	MP406	EP345	EP347	—
D6F606	—	MP403	MP408	MP406	EP345	EP347	—
D6F607	—	MP403	MP408	MP406	EP345	EP347	—
D6F801	—	MP403	MP408	MP406	EP345	EP347	—
D6F802	—	MP403	MP408	MP406	EP345	EP347	—
D6F803	—	MP403	MP408	MP406	EP345	EP347	—
D6F804	—	MP403	MP408	MP406	EP345	EP347	—
D6K802	—	MP404	—	MP407	EP664	EP663	—
D6K803	—	MP404	—	MP407	EP664	EP663	—
D6K805	—	MP404	—	MP407	EP664	EP663	—
D6K806	—	MP404	—	MP407	EP664	EP663	—
D6K80605	—	MP404	—	MP407	EP664	EP663	—
D6K807	—	MP404	—	MP407	—	EP663	—
D6K808	—	MP404	—	MP407	EP664	EP663	—
D6K822	—	MP404	—	MP407	EP664	EP663	—
D6K901	—	MP404	—	MP407	—	EP663	—
D6K902	—	MP404	—	MP407	—	EP663	—
D6K908	—	MP404	—	MP407	EP664	EP663	—
D6K909	—	MP404	—	MP407	EP664	EP663	—
D6K914	—	MP404	—	MP407	EP664	EP663	—
D6KA0105	—	MP404	—	MP407	EP664	EP663	—
22100B9800	—	MP400	MP408	—	EP345	EP346	—
22100B9802	—	—	—	—	EP345	EP346	—
22100B9805	—	MP400	MP408	—	EP345	EP346	—
22100B9807	—	—	—	—	EP345	EP346	—

(continued on next page)

NISSAN-DATSUN (Cont'd)

Unit No	Module	Pick-Up	Contact Assembly	Reluctor	Rotor	Cap	Vac Control
22100B9860	—	MP400	MP408	—	EP345	EP346	—
22100B9865	—	MP400	MP408	—	EP345	EP346	—
22100B9871	—	—	—	—	EP345	EP346	—
22100B9900	—	MP400	MP408	—	EP345	EP346	—
22100B9905	—	MP400	MP408	—	EP345	EP346	—
22100D1702	—	—	—	MP410	EP680	EP678	—
22100D1707	—	—	—	MP410	EP680	EP678	—
22100D1800	—	—	—	MP410	EP680	EP678	—
22100D2101	—	—	—	MP410	EP680	EP678	—
22100D2102	—	—	—	MP410	EP680	EP678	—
22100D2107	—	—	—	MP410	EP680	EP678	—
22100D2209	—	—	—	MP410	EP680	EP678	—
22100D3303	—	—	—	MP410	EP680	EP678	—
22100D3304	—	—	—	MP410	EP680	EP678	—
22100D3305	—	—	—	MP410	—	—	—
22100D3315	—	—	—	—	EP774	EP775	—
22100D3502	—	—	—	—	EP781	EP678	—
22100D3511	—	—	—	—	—	EP775	—
22100D3512	—	—	—	—	EP824	EP775	—
22100D8300	—	—	—	MP410	EP680	EP679	—
22100D8305	—	—	—	MP410	EP680	EP679	—
22100F6000	—	—	—	—	—	EP741	—
22100F6600	—	—	—	—	EP761	EP741	—
22100G5410	—	—	—	MP419	—	EP775	—
22100H6700	—	—	—	—	EP345	—	—
22100H7265	—	MP403	MP408	—	EP345	EP346	—
22100H7280	—	MP403	MP408	—	EP345	EP346	—
22100H7301	—	MP403	MP408	—	EP345	EP346	—
22100H7302	—	MP403	MP408	—	EP345	EP346	—
22100H7305	—	MP403	MP408	—	EP345	EP346	—
22100H7306	—	—	—	—	EP345	—	—
22100H7360	—	MP403	MP408	—	EP345	EP346	—
22100H7365	—	MP403	MP408	—	EP345	EP346	—
22100H7625	—	—	—	—	EP345	EP346	—
22100H7680	—	MP403	MP408	—	EP345	EP346	—
22100H7901	—	—	—	—	EP345	—	—
22100H7960	—	—	—	—	EP345	—	—
22100H8700	—	MP405	—	MP409	—	—	—
22100H8720	—	MP405	—	MP409	—	—	—
22100H9100	—	—	—	—	EP345	—	—
22100H9102	—	MP405	—	—	EP345	EP346	—
22100H9106	—	MP405	—	—	EP345	EP346	—
22100H9162	—	MP405	—	—	EP345	EP346	—
22100H9166	—	MP405	—	—	EP345	EP346	—
22100H9300	—	MP405	—	—	EP345	EP346	—
22100H9305	—	MP405	—	—	EP345	EP346	—
22100H9501	—	MP405	—	MP409	—	—	—
22100H9700	—	MP405	—	—	EP345	EP346	—
22100H9701	—	MP405	—	—	EP345	EP346	—

(continued on next page)

NISSAN-DATSUN (Cont'd)

Unit No	Module	Pick-Up	Contact Assembly	Reluctor	Rotor	Cap	Vac Control
22100H9760	—	MP405	—	—	EP345	EP346	—
22100H9801	—	MP405	—	MP409	—	—	—
22100H9806	—	MP405	—	MP409	—	—	—
22100H9900	—	MP405	—	—	EP345	EP346	—
22100H9905	—	MP405	—	MP409	—	—	—
22100H9960	—	MP405	—	—	EP345	EP346	—
22100M0701	—	—	—	—	—	EP663	—
22100M5900	—	MP402	MP408	—	EP345	EP346	—
22100M5906	—	—	—	—	EP345	EP346	—
22100M5960	—	MP402	MP408	—	EP345	EP346	—
22100M6700	—	MP405	—	—	EP345	EP346	—
22100M6860	—	MP405	—	MP409	—	—	—
22100M9162	—	MP405	—	—	EP345	EP346	—
22100M9701	—	MP405	—	—	EP345	EP346	—
22100N3602	—	—	—	—	EP345	EP347	—
22100N3607	—	—	—	—	EP345	EP347	—
22100N4201	—	—	MP408	MP406	EP345	EP347	—
22100N4206	—	—	MP408	MP406	EP345	EP347	—
22100N4301	—	MP403	MP408	MP406	EP345	EP347	—
22100N4700	—	MP403	MP408	MP406	EP345	EP347	—
22100N4703	—	MP403	MP408	MP406	EP345	EP347	—
22100N4705	—	MP403	MP408	MP406	EP345	EP347	—
22100N4708	—	MP403	MP408	MP406	EP345	EP347	—
22100N5800	—	MP400	MP408	—	EP345	EP346	—
22100N5801	—	—	—	—	EP345	—	—
22100N5805	—	MP400	MP408	—	EP345	EP346	—
22100N5807	—	—	—	—	EP345	—	—
22100N5907	—	MP400	MP408	—	EP345	EP346	—
22100N6001	—	—	—	—	EP345	—	—
22100N6002	—	—	—	—	EP345	—	—
22100N6101	—	MP401	MP408	—	EP345	EP346	—
22100N6102	—	MP401	MP408	—	EP345	EP346	—
22100N7700	—	MP403	MP408	MP406	EP345	EP347	—
22100N7705	—	MP403	MP408	MP406	EP345	EP347	—
22100N8502	—	MP404	—	—	EP345	EP346	—
22100N8561	—	—	—	MP410	EP694	EP695	—
22100N8566	—	—	—	MP410	EP694	EP695	—
22100N8602	—	MP404	—	—	EP345	EP346	—
22100N8603	—	MP404	—	—	EP345	EP346	—
22100N8702	—	—	—	MP410	EP694	EP695	—
22100N8705	—	—	—	MP410	EP694	EP695	—
22100N9600	—	—	—	MP410	EP680	EP679	—
22100P1000	—	MP404	—	MP407	EP664	EP663	—
22100P7101	—	MP404	—	MP407	EP664	EP663	—
22100P7106	—	MP404	—	MP407	EP664	EP663	—
22100P7201	—	MP404	—	MP407	EP664	EP663	—
22100P7202	—	MP404	—	MP407	EP664	EP663	—
22100P7205	—	MP404	—	MP407	EP664	EP663	—
22100P7301	—	MP404	—	MP407	—	EP663	—

(continued on next page)

NISSAN-DATSUN (Cont'd)

Unit No	Module	Pick-Up	Contact Assembly	Reluctor	Rotor	Cap	Vac Control
22100P7800	—	MP404	—	MP407	EP664	EP663	—
22100P7806	—	MP404	—	MP407	EP664	EP663	—
22100P7901	—	MP404	—	MP407	EP664	EP663	—
22100P8102	—	MP404	—	MP407	EP664	EP663	—
22100P8105	—	MP404	—	MP407	EP664	EP663	—
22100P8301	—	MP404	—	MP407	—	EP663	—
22100P8306	—	MP404	—	MP407	—	EP663	—
22100P9000	—	—	—	—	EP722	EP712	—
22100P9020	—	—	—	—	—	EP712	—
22100P9500	—	—	—	—	EP721	EP712	—
22100U8700	—	MP403	MP408	MP406	EP345	EP347	—
22100U8702	—	MP403	MP408	MP406	EP345	EP347	—
22100U8703	—	MP404	—	MP407	EP664	EP663	—
22100U8705	—	MP403	MP408	MP406	EP345	EP347	—
22100U8707	—	MP404	—	MP407	EP664	EP663	—
22100U8760	—	MP404	—	MP407	EP664	EP663	—
22100V5513	—	—	—	MP419	—	—	—
22100V5514	—	—	—	MP419	—	—	—
22100W0701	—	MP404	—	MP407	EP664	EP663	—
22100W0705	—	MP404	—	MP407	EP664	EP663	—
22100W2640	—	MP404	—	MP407	EP664	EP663	—
22100W3000	—	—	—	—	EP664	EP663	—
22100W3001	—	MP404	—	MP407	EP664	EP663	—
22100W3100	—	MP404	—	MP407	EP664	EP663	—
22100W4800	—	MP404	—	MP407	EP664	EP663	—
22100W5800	—	—	—	—	EP345	—	—
22100W5801	—	—	—	—	EP345	EP346	—
22100W5806	—	—	—	—	EP345	EP346	—
22100W5906	—	—	—	—	EP345	EP346	—
22100W6701	—	—	—	—	EP345	EP346	—
22100W6706	—	—	—	—	EP345	EP346	—
22100W8801	—	MP404	—	—	EP345	EP346	—
22100W8901	—	—	—	MP410	EP694	EP695	—
22100W8902	—	—	—	MP410	EP694	EP695	—
22100W8906	—	—	—	MP410	EP694	EP695	—
22100W8907	—	—	—	MP410	EP680	EP695	—
22100W9100	—	—	—	MP410	EP680	EP695	—
22100W9105	—	—	—	MP410	EP680	EP695	—
22101P7301	—	—	—	—	—	EP663	—
220200M220	—	—	—	—	EP545	EP539	—
221000B000	TP54	MP418	—	—	EP834	EP866	—
221000C810	—	—	—	—	EP890	—	—
221000M200	—	—	—	—	EP545	EP539	—
221000M220	—	—	—	—	EP545	EP539	—
221000M300	—	—	—	—	EP545	EP539	—
221000M810	—	—	—	—	EP544	EP540	—
221000M811	—	—	—	—	EP544	EP540	—
221000MB10	—	—	—	—	EP544	EP540	—
221000MB11	—	—	—	—	EP544	EP540	—

(continued on next page)

NISSAN-DATSUN (Cont'd)

Unit No	Module	Pick-Up	Contact Assembly	Reluctor	Rotor	Cap	Vac Control
221000P100	—	—	—	—	EP761	EP741	—
221000W001	—	—	—	—	EP899	EP453	—
221001E400	—	—	—	—	EP482	—	—
221001E420	—	—	—	—	EP482	—	—
221001S702	—	—	—	—	EP545	EP539	—
221003S500	—	—	—	—	EP545	—	—
2210001N10	—	—	—	MP419	—	—	—
2210002F12	—	—	—	MP419	—	—	—
2210003E11	—	—	—	—	—	EP775	—
2210004W00	—	—	—	—	EP345	EP346	—
2210004W60	—	—	—	—	EP345	EP346	—
2210004W65	—	—	—	—	EP345	EP346	—
2210005W00	—	—	—	—	EP345	EP346	—
2210006W02	—	—	—	MP410	EP694	EP695	—
2210006W03	—	—	—	MP410	EP680	EP679	—
2210006W22	—	—	—	MP410	EP694	EP695	—
2210006W23	—	—	—	MP410	EP680	EP679	—
2210006W62	—	—	—	MP410	EP680	EP695	—
2210006W82	—	—	—	MP410	EP680	EP695	—
2210007F02	—	—	—	MP410	EP680	EP679	—
2210007F03	—	—	—	MP410	EP680	EP679	—
2210007G01	—	—	—	—	EP781	EP679	—
2210007W02	—	—	—	MP410	EP694	EP695	—
2210007W03	—	—	—	MP410	EP680	EP679	—
2210008M10	—	—	—	—	EP544	EP540	—
2210008M11	—	—	—	—	EP544	EP540	—
2210010W20	—	—	—	MP410	EP680	EP679	—
2210010W24	—	—	—	MP410	EP680	EP679	—
2210011C10	—	—	—	—	—	EP775	—
2210012P11	—	—	—	—	MO24	EP741	—
2210015P10	—	—	—	—	MO24	EP741	—
2210016E00	—	—	—	—	EP761	EP752	—
2210016E01	—	—	—	—	EP761	—	—
2210016E02	—	—	—	—	EP761	EP752	—
2210016E03	—	—	—	—	EP761	EP752	—
2210016N10	—	—	—	MP419	—	—	—
2210017C00	—	—	—	—	EP781	EP679	—
2210018F01	—	—	—	—	EP781	EP679	—
2210018F02	—	—	—	—	EP781	EP679	—
2210018R00	—	—	—	MP410	EP680	EP678	—
2210018R01	—	—	—	MP410	EP680	EP678	VC4110
2210018R05	—	—	—	MP410	EP680	EP678	—
2210018R06	—	—	—	MP410	EP680	EP678	VC4110
2210018V11	—	—	—	MP419	—	—	—
2210020R01	—	—	—	—	EP781	—	—
2210020R11	—	—	—	—	—	EP775	—
2210020R12	—	—	—	—	EP824	EP775	—
2210020W20	—	—	—	MP410	EP680	EP679	—
2210020W24	—	—	—	MP410	EP680	EP679	—

(continued on next page)

NISSAN-DATSUN (Cont'd)

Unit No	Module	Pick-Up	Contact Assembly	Reluctor	Rotor	Cap	Vac Control
2210020W60	—	—	—	MP410	EP680	EP679	—
2210020W64	—	—	—	MP410	EP680	EP679	—
2210021M00	—	—	—	MP411	EP345	EP847	—
2210021P02	—	—	—	—	EP761	EP741	—
2210021P03	—	—	—	—	EP761	EP741	—
2210021P10	—	—	—	—	MO24	EP741	—
2210021P12	—	—	—	—	MO24	EP741	—
2210022M00	—	—	—	MP411	EP345	EP847	—
2210023M00	—	—	—	MP411	EP345	EP847	—
2210023M05	—	—	—	MP411	EP345	EP847	—
2210023M06	—	—	—	MP411	EP345	EP847	—
2210023M07	—	—	—	MP411	EP345	EP847	—
2210023M61	—	—	—	MP411	EP345	EP847	—
2210024M00	—	—	—	MP411	EP345	EP847	—
2210027M01	—	—	—	MP411	EP768	EP769	—
2210027M02	—	—	—	—	EP768	EP769	—
2210030R00	—	—	—	—	EP310	EP851	—
2210030R01	—	—	—	—	EP310	EP851	—
2210032F10	—	—	—	—	EP761	EP741	—
2210032M01	—	—	—	MP411	EP345	EP847	—
2210032M02	—	—	—	MP411	EP345	EP847	—
2210033M01	—	—	—	MP411	EP345	EP847	—
2210033M02	—	—	—	MP411	EP345	EP847	—
2210033M71	—	—	—	MP411	EP345	EP847	—
2210033M72	—	—	—	MP411	EP345	EP847	—
2210034M00	—	—	—	MP411	EP345	EP847	—
2210034M71	—	—	—	MP411	EP345	EP847	—
2210034M72	—	—	—	MP411	EP345	EP847	—
2210036A00	—	—	—	—	EP768	EP769	—
2210036A01	—	—	—	MP411	EP768	EP769	—
2210036A02	—	MP418	—	—	EP768	EP769	—
2210040F00	—	—	—	—	EP773	EP769	—
2210040F10	—	—	—	—	EP786	EP893	—
2210040W20	—	—	—	MP410	EP680	EP679	—
2210044W01	—	—	—	—	EP345	EP346	—
2210044W51	—	—	—	—	EP345	—	—
2210044W61	—	—	—	—	EP345	EP346	—
2210046W61	—	—	—	MP410	EP680	EP695	—
2210047W01	—	—	—	MP410	EP694	EP695	—
2210047W02	—	—	—	MP410	EP680	EP679	—
2210053F11	—	—	—	—	EP890	EP888	—
2210053J01	—	—	—	—	EP310	EP887	—
2210053J02	—	—	—	—	EP310	EP887	—
2210055J01	—	—	—	—	EP310	EP887	—
2210061W02	—	—	—	MP410	—	EP679	—
2210070F10	—	—	—	—	EP544	EP543	—
2210078A00	—	—	—	—	EP773	EP769	—
2210080W00	—	—	—	MP410	EP680	EP679	—
2210080W20	—	—	—	MP410	EP680	EP679	—

(continued on next page)

NISSAN-DATSUN (Cont'd)

Unit No	Module	Pick-Up	Contact Assembly	Reluctor	Rotor	Cap	Vac Control
2210081W00	—	—	—	MP410	EP680	EP679	—
2210082W00	—	—	—	MP410	EP680	EP679	—
2210083W00	—	—	—	MP410	EP680	EP679	—
2210083W20	—	—	—	MP410	EP680	EP679	—
2210085E01	TP228	MP418	—	—	EP834	EP841	—
2210088G00	—	—	—	—	EP834	EP866	—

PEUGEOT

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
525213A	—	—	—	EP472	EP783
525285	—	—	—	EP472	EP783
525534A	—	—	EP810	EP810	EP783

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
2525655A	TP140	—	—	—	—
2525709A	TP140	—	EP810	—	—

PORSCHE

Unit No	Module	Pick-Up	Rotor	Cap
93060201501 ..	TP109	—	EP372	EP329

(continued on next column)

Unit No	Module	Pick-Up	Rotor	Cap
96560202400 ..	—	—	EP372	EP580

STERLING

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
86386350022 ..	TP185	—	—	EP776	EP777

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
86386350044 ..	TP185	—	—	EP776	EP777

SUZUKI

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
3310056B10 ...	TP125	—	—	EP339	EP599
3310056B11 ...	TP125	—	—	EP339	EP599
3310058B10 ...	TP125	—	—	—	—
3310060G10 ...	TP125	MP141	—	EP418	EP832
3310063B10 ...	TP133	MP1500	—	—	EP832
3310063B11 ...	TP133	—	—	EP843	EP832
3310063B70 ...	TP133	—	—	EP843	EP832
3310063B71 ...	TP133	—	—	EP843	EP832

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
3310064B10 ...	TP125	—	—	EP842	EP778
3310071C30 ...	—	—	—	—	EP832
3310080C10 ...	—	—	—	EP864	EP883
3310063871 ...	TP133	MP1500	—	—	EP832
3310083032 ...	—	MP1503	—	—	—

TEC

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
TC01U	—	—	—	EP332	EP804
TC05A	TP166	—	—	EP332	EP804
TC05U	TP166	—	—	EP332	EP804
TD01K	TP185	—	—	EP821	EP693
TD01L	TP185	—	—	EP821	EP693
TD01N	TP185	—	—	EP821	EP799

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
TD01T	—	—	—	EP822	EP825
TD01U	TP166	—	—	EP332	EP804
TD02E	TP184	—	—	EP821	EP676
TD02K	TP185	—	—	EP821	EP693
TD02P	—	—	—	EP807	EP806
TD02U	TP166	—	—	—	—

(continued on next page)

TEC (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
TD02V	TP185	—	—	—	—	TD18K	TP185	—	—	EP821	EP757
TD03E	TP184	—	—	EP821	EP676	TD18U	—	—	—	EP332	EP804
TD03H	TP185	—	—	EP821	EP709	TD19K	TP185	—	—	EP821	EP693
TD03R	TP185	—	—	EP776	EP777	TD20K	TP185	—	—	EP821	EP693
TD03V	TP185	—	—	EP821	EP812	TD21K	TP185	—	—	EP821	EP693
TD04K	TP185	—	—	EP821	EP693	TD22K	TP185	—	—	EP821	EP758
TD04R	TP185	—	—	EP776	EP777	TD23U	TP222	—	—	EP332	EP804
TD04V	TP185	—	—	EP821	EP812	TD24C	TP185	MP1103	—	EP821	EP676
TD05J	TP185	—	—	EP821	EP693	TD24U	TP166	—	—	EP332	EP804
TD05V	TP185	—	—	EP821	EP812	TD31U	—	—	—	EP479	EP867
TD06H	TP185	—	—	EP821	EP709	TD34K	TP185	—	—	EP821	EP693
TD06J	TP185	—	—	EP821	EP693	TD34U	—	—	—	EP479	EP867
TD06K	TP185	—	—	EP821	EP693	TD35K	TP185	—	—	EP821	EP693
TD06N	TP185	—	—	EP821	EP799	TD41K	TP185	—	—	EP821	EP676
TD07H	TP185	—	—	EP821	EP709	TD41U	—	—	—	EP469	EP867
TD07K	TP185	MP1103	—	EP821	EP709	TD42K	TP185	—	—	EP821	EP799 ¹⁰
TD07N	TP185	—	—	EP821	EP799	TD42U	—	—	—	EP469	EP867
TD08H	TP185	—	—	EP821	EP709	TD43K	TP185	—	—	EP821	EP758 ¹⁰
TD08K	TP185	—	—	EP821	EP693	TD44K	TP185	—	—	EP821	EP799 ¹⁰
TD10I	TP185	—	—	EP821	EP693	TD44U	—	—	—	EP469	EP867
TD10M	TP185	—	—	EP821	EP693	TD52U	—	—	—	EP479	EP478
TD11T	—	—	—	EP488	EP491	TD59U	—	—	—	EP469	EP478
TD12C	TP185	MP1103	—	EP821	EP676	TD61U	—	—	—	EP469	EP478
TD13C	TP185	MP1103	—	EP821	EP676	TD76U	TP222	—	—	EP469	EP478
TD13K	TP185	—	—	EP821	EP758	TD77U	TP222	—	—	EP469	EP478
TD14C	TP185	MP1103	—	EP821	EP676	TD80U	TP222	—	—	EP469	EP867
TD14I	TP185	—	—	EP821	EP693	TD91U	TP222	—	—	EP469	EP867
TD15K	TP185	—	—	EP821	EP758	TD97U	TP222	—	—	EP469	EP867
TD16K	TP185	—	—	EP821	EP757	TD98U	TP222	—	—	EP469	EP867
TD17K	TP185	—	—	EP821	EP757						

(continued on next column)

TOYOTA

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control	Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
1900062020	—	—	—	EP805	EP803	—	1904073020	—	MP206	—	EP484	EP720	—
1902016250	—	—	—	RR246	EP355	—	1904074030	—	—	—	RR246	—	—
1903011010	—	MP207	—	RR246	—	—	1905011010	—	—	—	RR246	EP355	—
1903016082	—	MP207	—	EP687	EP707	—	1905016030	—	—	—	EP395	EP355	—
1903016120	—	MP207	MP211	RR246	—	VC4102	1905074010	—	—	—	RR246	EP341	—
1903016130	—	—	—	EP484	EP756	—	1905074020	—	—	—	RR246	EP374	—
1903016140	—	—	—	RR246	—	—	1905074030	TP211	—	—	—	EP374	—
1903074010	—	—	—	EP484	EP719	—	1905074050	—	—	—	—	EP374	—
1903074020	—	MP206	—	EP687	EP719	—	1905075020	TP211	—	—	EP395	EP549	—
1903074040	—	—	—	RR246	EP374	—	1910013090	—	—	—	—	EP685	—
1903074110	—	—	—	EP864	EP860	—	1910016130	—	—	—	EP484	EP756	—
1903074230	TP211	—	—	EP864	EP860	—	1910016180	TP206	—	—	EP484	EP830	—
1904073010	—	—	—	EP484	EP720	—	1910016210	—	—	—	EP484	EP756	—

(continued on next column)

(continued on next page)

¹⁰ Physical comparison is necessary or check application guide

TOYOTA (Cont'd)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
1910016260 ...	TP206	—	—	EP484	EP863	—
1910024200 ...	—	—	—	—	EP685	—
1910026231 ...	—	—	—	—	EP685	—
1910026232 ...	—	—	—	—	EP685	—
1910026241 ...	—	—	—	—	EP685	—
1910026260 ...	—	—	—	—	EP685	—
1910026261 ...	—	—	—	—	EP685	—
1910026270 ...	—	—	—	—	EP685	—
1910026271 ...	—	—	—	—	EP685	—
1910026280 ...	—	—	—	—	EP685	—
1910026290 ...	—	—	—	—	EP685	—
1910035180 ...	—	—	—	EP687	EP671	—
1910035240 ...	—	—	—	EP687	EP671	—
1910038011 ...	—	—	—	—	EP685	—
1910038040 ...	—	—	—	—	EP685	—
1910038080 ...	—	—	—	—	EP685	—
1910038081 ...	—	—	—	—	EP665	—
1910038090 ...	—	—	—	—	EP685	—
1910038091 ...	—	—	—	—	EP665	—
1910038140 ...	—	—	—	—	EP685	—
1910038150 ...	—	—	—	—	EP665	—
1910038160 ...	—	—	—	—	EP685	—
1910038180 ...	—	—	—	—	EP665	—
1910038190 ...	—	—	—	—	EP665	—
1910042040 ...	—	—	—	EP684	EP683	—
1910042050 ...	—	—	—	EP839	EP809	—

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap	Vac Control
1910043190 ...	—	—	—	EP684	EP795	—
1910046011 ...	TP213	—	—	EP396	EP399	—
1910061061 ...	—	—	—	EP376	—	—
1910061100 ...	—	—	—	EP376	—	—
1910061101 ...	—	—	—	EP376	—	—
1910061102 ...	—	MP208	—	EP684	EP689	—
1910061240 ...	—	—	—	EP801	EP689	—
1910062020 ...	TP205	—	—	EP805	EP803	—
1910062030 ...	TP205	—	—	EP805	EP803	—
1910062050 ...	TP213	—	—	EP397	EP402	—
1910065020 ...	TP208	—	—	EP839	EP403	—
1910074050 ...	TP212	—	—	EP864	EP859	—
1910074060 ...	TP212	—	—	EP864	EP860	—
1910074110 ...	TP211	—	—	EP864	EP860	—
1910075020 ...	TP211	—	—	EP395	EP549	—
1910076010 ...	TP212	—	—	EP864	EP858	—
1910079010 ...	—	—	—	EP864	EP858	—
1910088362 ...	TP293	—	—	EP687	EP811	—
1910088363 ...	TP212	—	—	EP864	EP861	—
1910088364 ...	—	—	—	EP864	EP392	—
1910088381 ...	—	—	—	EP687	EP811	—
2710024510 ...	TP125	—	—	—	—	—
2710035330 ...	—	—	—	MO24	EP831	—
2710035600 ...	—	—	—	MO24	EP831	—

VOLVO

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
1306059	—	—	—	EP767	EP737
2691343	—	—	—	EP548	EP530
2693233	—	—	—	EP548	EP530
2695658	—	—	—	EP548	EP530
2697332	—	—	—	EP548	EP530
2697392	—	—	—	EP548	EP530
2699957	—	—	—	EP548	EP530
4627626	—	—	—	EP143	EP274
4628962	—	—	—	EP143	EP274
4636940	—	—	—	EP143	EP274
4638326	—	—	—	EP143	EP274
12182135	—	—	—	EP573	EP413
12186714	—	—	—	EP143	EP274

(continued on next column)

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
12186722	—	—	—	EP143	EP274
12196622	—	—	—	EP143	EP274
12198487	—	—	—	EP143	EP274
12199576	—	—	—	EP143	EP274
13360870	—	—	—	EP763	EP553
13361324	TP227	—	—	EP763	EP553
13460712	—	—	—	EP573	EP413
13671979	—	—	—	EP763	EP553
13673827	—	MP318	—	—	EP274
13674684	—	MP318	—	—	EP274
13894258	—	—	—	—	EP274
136738277	—	—	—	EP765	—

YUGO

Unit No	Module	Pick-Up	Reluctor	Rotor	Cap
46620555	 —	—	—	EP143	EP274

AMERICAN MOTORS

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
923068	CS725A	MO5000	AL130	AL110	—
931852	CS729A	MO5000	AL107	AL128	—
947211	CS725A	MO5000	AL130	AL110	—
948163	CS719A	MO5000	AL141	AL142	—
991846	CS719A	MO5000	AL141	AL142	—
992360	CS725A	MO5000	AL130	AL110	—
3157209	CS729A	MO5000	AL107	AL128	—
3157218	CS729A	MO5000	AL125	AL124	—
3162150	CS729A	MO5000	AL125	AL124	—
3164149	CS729A	MO5000	AL107	AL128	—
3164150	CS729A	MO5000	AL125	AL124	—
3164204	CS763A	RR174	RR161	RR162	—
3167665	CS788P	RR176	RR182R	RR183	—
3167666	CS788P	RR176	RR182R	RR183	VC1420
3167667	CS786P	RR175	RR169R	RR165	VC1765
3169406	CS729A	MO5000	AL132	AL131	—
3169407	CS729A	MO5000	AL132	AL131	—
3173161	CS729A	MO5000	AL132	AL131	—
3173162	CS729A	MO5000	AL132	AL131	—
3173163	CS729A	MO5000	AL125	AL124	—
3179094	CS719A	MO5000	AL132	AL131	—
3180070	CS788P	RR176	RR182R	RR183	VC1420
3180286	CS719A	MO5000	AL132	AL131	—
3181865	CS786P	RR175	RR169R	RR165	—
3182701	CS786P	RR174	RR169R	RR165	VC1765
3182702	CS788P	RR176	RR182R	RR183	VC1420
3182862	CS723A	MO5000	AL125	AL124	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
3182863	CS723A	MO5000	AL125	AL124	—
3184797	CS786P	RR174	RR169R	RR165	—
3184859	CS788P	RR176	RR182R	RR183	VC1420
3187537	CS786P	RR174	RR169R	RR165	VC1765
3190890	CS788P	RR176	RR182R	RR183	VC1420
3193144	CS786P	RR174	RR169R	RR165	VC1765
3193199	CS786P	RR174	RR169R	RR165	—
3194669	CS786P	RR174	RR169R	RR165	VC1765
3197232	CS786P	RR174	RR169R	RR165	—
3197233	CS786P	RR174	RR169R	RR165	—
3197332	CS788P	RR176	RR182R	RR183	—
3210193	CS786P	RR174	RR169R	RR165	—
3211821	CS786P	RR174	RR169R	RR165	—
3215824	CS788P	RR176	RR182R	RR183	—
3215825	CS786P	RR174	RR169R	RR165	VC1765
3215826	CS786P	RR174	RR169R	RR165	VC1765
3217798	CS786P	RR174	RR169R	RR165	VC1765
3219196	CS786P	RR174	RR169R	RR165	—
3219197	CS786P	RR174	RR169R	RR165	—
3219198	CS788P	RR174	RR182R	RR183	—
3219199	CS788P	RR174	RR182R	RR183	—
3223014	CS788P	RR174	RR182R	RR183	—
3223015	CS788P	RR174	RR182R	RR183	—
3250163	CS313	EP387	EP143	EP274	—
3250497	CS313	EP387	EP143	EP274	—

AUDI-VOLKSWAGEN

Unit No	Contact Assembly	Condenser	Rotor	Cap
050905205AH	—	—	—	EP327

AUTOLITE-PRESTOLITE

Unit No	Contact Assembly	Condenser	Rotor	Cap
IAD404A	CS725A	AL869	AL69	AL70
IAD4001	CS725A	AL869	AL69	AL70
IAD4003	CS725A	AL869	AL62	AL63
IAD4005A	CS725A	AL869	AL62	AL63
IAD4006	CS725A	AL869	AL62	AL63
IAD4007	CS725A	AL869	AL62	AL63
IAD4008	CS725A	AL869	AL69	AL70
IAD4008A	CS725A	AL869	AL69	AL70
IAD4008T	CS725A	AL869	AL69	AL70
IAD4009	CS725A	AL869	AL62	AL63

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IAD4010A	CS725A	AL869	AL69	AL70
IAD4010C	CS725A	AL869	AL69	AL70
IAD4010D	CS725A	AL869	AL69	AL70
IAD4011A	CS725A	AL869	AL62	AL63
IAD4012A	CS725A	AL869	AL62	AL63
IAD4015	CS725A	AL869	AL62	AL63
IAD4016	CS725A	AL869	AL62	AL63
IAD4016A	CS725A	AL869	AL62	AL63
IAD4017A	CS725A	AL869	AL62	AL63
IAD4018	CS725A	AL869	AL69	AL70

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IAD4019A	CS725A	AL869	AL62	AL63
IAD4019A1	CS725A	AL869	AL62	AL63
IAD4020A	CS725A	AL869	AL69	AL70
IAD4020B	CS725A	AL869	AL69	AL70
IAD4023A	CS725A	AL869	AL69	AL70
IAD4024	CS725A	AL869	AL69	AL70
IAD4025	CS725A	AL869	AL62	AL63
IAD4025A	CS725A	AL869	AL62	AL63
IAD4026A	CS725A	AL869	AL62	AL63
IAD4026C	CS725A	AL869	AL62	AL63
IAD4027	CS725A	AL869	AL62	AL63
IAD4027A	CS725A	AL869	AL62	AL63
IAD4028A	CS725A	AL869	AL69	AL70
IAD4029	CS725A	AL869	AL69	AL70
IAD4029A	CS725A	AL869	AL69	AL70
IAD4029A1	CS725A	MO5000	AL69	AL70
IAD4029AA1	CS725A	AL869	AL69	AL70
IAD4029B	CS725A	AL869	AL69	AL70
IAD4030	CS725A	AL869	AL69	AL70
IAD4031	CS725A	AL869	AL69	AL70
IAD4032	CS725A	AL869	AL62	AL63
IAD4033	CS725A	AL869	AL62	AL63
IAD4033A	CS725A	AL869	AL62	AL63
IAD4034	CS725A	AL869	AL62	AL63
IAD4034A	CS725A	AL869	AL62	AL63
IAD4035	CS725A	AL869	AL62	AL63
IAD4036A	CS725A	AL869	AL302	AL70
IAD4037	CS725A	AL869	AL69	AL70
IAD4038	CS725A	AL869	AL69	AL70
IAD4040	CS725A	MO5000	AL62	AL63
IAD4041	CS725A	AL869	AL69	AL70
IAD4042	CS725A	AL869	AL69	—
IAD4043	CS725A	AL869	AL69	AL70
IAD4043A	CS725A	MO5000	AL69	AL70
IAD4044	CS725A	MO5000	AL62	AL63
IAD4046	CS725A	MO5000	AL69	AL128
IAD4101A	CS725A	AL869	AL69	AL70
IAD4201	CS725A	AL869	AL62	AL63
IAD4203	CS725A	AL869	AL62	AL63
IAD4204	CS725A	AL869	AL62	AL63
IAD4204A	CS725A	AL869	AL62	AL63
IAD4204B	CS725A	AL869	AL62	AL63
IAD4206	CS725A	AL869	AL69	AL70
IAD4207A	CS725A	AL869	AL69	AL70
IAD4302A	CS725A	AL869	AL62	AL63
IAD6001	CS725A	AL869	AL62	AL63
IAD6001B	CS725A	MO5000	AL62	AL63
IAD6001C	CS725A	AL869	AL62	AL63

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IAD6001D	CS725A	AL869	AL62	AL63
IAD6001E	CS725A	AL869	AL62	AL63
IAD6001F	CS725A	AL869	AL62	AL63
IAD6001G	CS725A	AL869	AL62	AL63
IAD6001N	CS725A	AL869	AL62	AL63
IAD6001R	CS725A	MO5000	AL62	AL63
IAD6003B	CS725A	AL869	AL69	AL70
IAD6003D	CS725A	AL869	AL69	AL70
IAD6004A	CS725A	MO5000	AL69	AL70
IAD6004B	CS725A	MO5000	AL69	AL70
IAD6004U	CS725A	—	AL69	AL70
IAD6012	CS725A	—	AL150	AL165
IAD6013	CS725A	AL869	AL69	AL70
IAD6013A	CS725A	AL869	AL69	AL70
IAD6013B	CS725A	AL869	AL302	AL70
IAD6013C	CS725A	AL869	—	AL70
IAD40291	CS725A	AL869	AL69	AL70
IAD40391	CS725A	AL869	AL62	AL63
IAD40401	CS725A	AL869	AL62	AL63
IAD41011	CS725A	AL869	AL69	AL70
IAD41091	CS725A	MO5000	AL62	AL63
IAD41091M	CS725A	MO5000	AL62	AL63
IAD42011	CS725A	AL869	AL62	AL63
IAD42031	CS725A	AL869	AL62	AL63
IAD60011A	CS725A	AL869	AL62	AL63
IAD60011F	CS725A	AL869	AL62	AL63
IAD60011G	CS725A	AL869	AL62	AL63
IAD60011K	CS725A	AL869	AL62	AL63
IAD60012B	CS725A	—	—	AL63
IAD60012F	CS725A	—	—	AL63
IAD60012R	CS725A	MO5000	AL62	AL63
IAD60021A	CS725A	AL869	AL62	AL63
IAD60021B	CS725A	AL869	AL62	AL63
IAD60021C	CS725A	AL869	AL62	AL63
IAD60021D	CS725A	AL869	AL62	AL63
IAD60021E	CS725A	AL869	AL62	AL63
IAD60021F	CS725A	AL869	AL62	AL63
IAD60021G	CS725A	AL869	AL62	AL63
IAD60021H	CS725A	AL869	AL62	AL63
IAD60021I	CS725A	AL869	AL62	AL63
IAD60021J	CS725A	AL869	AL62	AL63
IAD60021K	CS725A	AL869	AL62	AL63
IAD60021L	CS725A	AL869	AL62	AL63
IAD60021N	CS725A	AL869	AL62	AL63
IAD60021P	CS725A	AL869	AL62	AL63
IAD60031A	CS725A	AL869	AL69	AL70
IAD60031B	CS725A	MO5000	AL69	AL70
IAD60032A	CS725A	MO5000	AL69	AL70

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Unit No	Contact Assembly	Condenser	Rotor	Cap
IAD60032E	CS725A	AL869	AL69	AL70	IAO40021	CS725A	AL116	AL62	AL98
IAD60032F	CS725A	MO5000	AL69	AL70	IAO40031	CS725A	AL116	AL62	AL98
IAD60032G	CS725A	MO5000	AL69	AL70	IAO41011	CS725A	AL116	AL62	AL98
IAD60032H	CS725A	MO5000	AL69	AL70	IAO41021	CS725A	AL116	AL62	AL98
IAD60032J	CS725A	AL869	AL69	AL70	IAO41021M	CS725A	MO5000	AL62	AL98
IAD60032K	CS725A	MO5000	AL69	AL70	IAO41031	CS725A	AL116	AL62	AL98
IAD60032V	CS725A	MO5000	AL69	AL70	IAO41031F	CS725A	AL116	AL62	AL98
IAD60041A	CS725A	MO5000	AL69	AL70	IAO41031M	CS725A	MO5000	AL62	AL98
IAD60041B	CS725A	AL869	AL69	AL70	IAO41051M	CS725A	MO5000	AL62	AL98
IAD60041C	CS725A	AL869	AL69	AL70	IAO41061M	CS725A	MO5000	AL62	AL98
IAD60041D	CS725A	AL869	AL69	AL70	IAO41081M	CS725A	MO5000	AL62	AL98
IAD60041E	CS725A	MO5000	AL69	AL70	IAO41091M	CS725A	MO5000	AL62	AL98
IAD60041G	CS725A	MO5000	AL69	AL70	IAO41111M	CS725A	MO5000	AL62	AL98
IAD60041H	CS725A	MO5000	AL69	AL70	IAO41121M	CS725A	MO5000	AL62	AL98
IAD60041J	CS725A	AL869	AL69	AL70	IAO41131M	CS725A	MO5000	AL62	AL98
IAD60042D	CS725A	AL869	AL69	AL70	IAO41141M	CS725A	MO5000	AL62	AL98
IAD60042E	CS725A	AL869	AL69	AL70	IAO41161	CS725A	MO5000	AL62	AL98
IAD60042F	CS725A	AL869	AL69	AL70	IAP4001A1	CS725A	MO5000	—	AL98
IAD60042H	CS725A	AL869	AL69	AL70	IAP4002A1	CS725A	MO5000	AL62	AL98
IAD60042N	CS725A	MO5000	AL69	AL70	IAP4002B1	CS725A	MO5000	AL62	AL98
IAD60042P	CS725A	MO5000	AL69	AL70	IAP4102A1	CS725A	MO5000	AL62	AL98
IAD60042R	CS725A	AL869	AL69	AL70	IAP4102B1	CS725A	MO5000	AL62	AL98
IAD60061	CS725A	AL869	AL62	—	IAP4102C1	CS725A	MO5000	AL62	AL98
IAD60092A	CS725A	AL869	AL62	AL63	IAP4103A1	CS725A	MO5000	AL62	AL98
IAD60101	CS725A	MO5000	AL62	AL63	IAP40021	CS725A	MO5000	AL62	AL98
IAD60111A	CS725A	AL869	AL69	AL70	IAP41011	CS725A	MO5000	AL62	AL98
IAD60141E	CS725A	MO5000	AL69	AL70	IAP41021	CS725A	MO5000	AL62	AL98
IAK4101M	—	—	AL65	AL66	IAP41031	CS725A	MO5000	AL62	AL98
IAL4005M	CS725A	MO5000	AL62	AL63	IAPSERIES	CS725A	MO5000	AL62	AL98
IAL40011M	CS725A	MO5000	AL62	—	IAR4101A1	—	—	AL65	AL99
IAL40021M	CS725A	MO5000	AL62	—	IAR41011	—	—	AL65	AL99
IAL40031M	CS725A	MO5000	AL62	—	IAT401A	CS725A	AL869	AL107	AL106
IAL40041M	CS725A	MO5000	AL62	—	IAT4001	CS725A	AL869	AL104	AL105
IAM4001	CS725A	AL869	AL62	—	IAT4002	CS719A	AL869	AL104	AL105
IAO4001A1	CS725A	AL116	AL62	AL98	IAT4003	CS719A	AL869	AL107	AL106
IAO4001B1	CS725A	AL116	AL62	AL98	IAT4003A	CS719A	MO5000	AL107	AL128
IAO4101A1	CS725A	AL116	AL62	AL98	IAT4003B	CS719A	AL869	AL107	AL106
IAO4101M	CS725A	MO5000	AL62	AL98	IAT4004	CS719A	AL869	AL107	AL106
IAO4103A1	CS725A	AL116	AL62	AL98	IAT4004A	CS719A	AL869	AL107	AL106
IAO4103A1F	CS725A	AL116	AL62	AL98	IAT4004B	CS719A	AL869	AL107	AL106
IAO4104B1	CS725A	AL116	AL62	AL98	IAT4004C	CS719A	AL869	AL107	AL106
IAO41071M	CS725A	MO5000	AL62	AL98	IAT4005	CS725A	AL869	AL104	AL105
IAO41091M	CS725A	MO5000	AL62	AL98	IAT4006	CS719A	AL869	AL104	AL110
IAO41101M	CS725A	MO5000	AL62	AL98	IAT4007	CS725A	AL869	AL104	AL105
IAO4114A1M	CS725A	MO5000	AL62	AL98	IAT4007A	CS725A	AL869	AL104	AL105
IAO4114AIM	CS725A	MO5000	AL62	AL98	IAT4007B	CS725A	MO5000	AL104	AL105
IAO41151M	CS725A	MO5000	AL62	AL98	IAT4008	CS725A	AL869	AL104	AL110
IAO40011	CS725A	AL116	AL62	AL98	IAT4008A	CS725A	AL869	AL104	AL110

(continued on next column)

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IAT4008B	CS725A	AL869	AL104	AL110
IAT4009	CS719A	AL869	AL112	AL106
IAT4009A	CS719A	AL869	AL112	AL106
IAT4009B	CS719A	AL869	AL112	AL106
IAT4010	CS725A	AL869	AL107	AL106
IAT4011	CS719A	AL869	AL107	AL106
IAT4011A	CS719A	AL869	AL107	AL106
IAT4011B	CS719A	AL869	AL107	AL106
IAT4011C	CS719A	MO5000	AL107	AL128
IAT4012	CS719A	AL869	AL107	AL106
IAT4012A	CS719A	AL869	AL107	AL106
IAT4012B	CS719A	AL869	AL107	AL106
IAT4012C	CS719A	AL869	AL107	AL106
IAT4012D	CS719A	MO5000	AL107	AL106
IAT4013	CS725A	AL869	AL104	AL105
IAT4014	CS719A	AL869	AL107	AL106
IAT4015	CS725A	AL869	AL104	AL105
IAT4015A1	CS725A	MO5000	AL104	AL110
IAT4016	CS719A	AL869	AL112	AL106
IAT4017	CS725A	AL869	AL107	AL106
IAT4017A	CS725A	MO5000	AL107	AL128
IAT4018	CS719A	AL869	AL112	AL106
IAT4019	CS725A	AL869	AL112	AL106
IAT4020	CS725A	MO5000	AL104	AL110
IAT4021	—	—	AL104	AL105
IAT4101	CS719A	AL869	AL107	AL106
IAT4101A	CS719A	AL869	AL107	AL106
IAT4101B	CS719A	AL869	AL107	AL106
IAT4101C	CS725A	MO5000	AL107	AL106
IAT4101CS	CS719A	MO5000	—	—
IAT4101D	CS725A	MO5000	AL107	AL106
IAT4101DS	CS719A	MO5000	AL107	AL106
IAT4102	CS719A	AL869	AL107	AL106
IAT4102	CS719A	MO5000	AL107	AL106
IAT4102A	CS719A	MO5000	AL107	AL106
IAT4102AS	CS719A	MO5000	AL107	AL106
IAT4103	CS719A	MO5000	AL107	AL106
IAT4104	CS719A	MO5000	AL107	AL128
IAT4201	CS725A	MO5000	AL107	AL106
IAT4202	CS719A	MO5000	AL112	AL106
IAT4203	CS719A	MO5000	AL112	AL106
IAT4203A	CS719A	MO5000	AL112	AL106
IAT4203B	CS719A	MO5000	AL112	AL128
IAT4204	CS725A	MO5000	AL104	AL110
IAT4204A	CS725A	MO5000	AL104	AL110
IAT4204AT	CS725A	MO5000	AL104	AL110
IAT4205	CS725A	MO5000	AL107	AL106
IAT4205A	CS725A	MO5000	AL107	AL106

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IAT4206	CS725A	MO5000	AL112	AL106
IAT4206A	CS725A	MO5000	AL112	AL106
IAT4206B	CS725A	MO5000	AL112	AL106
IAT4207	CS725A	MO5000	AL107	AL106
IAT4207A	CS725A	MO5000	AL107	AL106
IAT4301	CS719A	MO5000	AL107	AL106
IAT4402	CS729A	MO5000	AL107	AL128
IAT4403	CS729A	MO5000	AL107	AL106
IAT4403A	CS729A	MO5000	AL107	AL106
IAT4403B	CS729A	MO5000	AL107	AL106
IAT4404	CS729A	MO5000	AL107	AL106
IAT4404A	CS729A	MO5000	AL107	AL106
IAT4404AT	CS729A	MO5000	AL107	AL106
IAT4405	CS729A	MO5000	AL130	AL110
IAT4406	CS729A	MO5000	AL130	AL105
IAT4407	CS729A	MO5000	AL107	AL128
IAT4408	CS729A	MO5000	AL107	AL128
IAT4411	CS729A	MO5000	AL107	AL128
IAT4414	CS729A	MO5000	AL132	—
IAT4414A	CS729A	MO5000	AL132	AL131
IAT4415	CS729A	MO5000	AL132	—
IAT4415A	CS729A	MO5000	AL132	—
IAT4416	CS729A	MO5000	AL107	AL128
IAT4417	CS729A	—	AL130	AL110
IAT4501	CS729A	MO5000	AL141	AL142
IAT4502	CS719A	MO5000	AL141	AL142
IAT4502A	CS719A	MO5000	AL141	AL142
IAT6002	CS719A	MO5000	AL104	AL105
IAT44021	CS729A	MO5000	AL107	AL128
IAT60042F	CS725A	MO5000	AL69	AL70
IAU4006AUT	CS725A	MO5000	—	—
IAU4006UT	CS725A	MO5000	—	—
IAU4007UT	CS725A	AL869	—	—
IAU4016UT	CS725A	AL869	—	—
IAU4017UT	CS725A	AL869	—	—
IAU4019UT	CS725A	AL869	—	—
IAU4020UT	CS725A	AL869	—	—
IAU4021UT	CS725A	—	—	—
IAX4001M	—	—	AL65	AL99
IAX40011M	CS720P	MO5000	AL65	AL99
IAX40021M	CS720P	MO5000	AL65	AL99
IAX40031M	CS720P	MO5000	AL65	AL99
IAX40041M	CS720P	MO5000	AL65	AL99
IAX40051M	CS720P	MO5000	AL65	AL99
IAY4001A1	CS725A	AL116	AL107	AL106
IAY4003	CS725A	—	AL107	AL106
IAY4003A1	CS725A	AL116	AL107	AL106
IAY4003B1	CS725A	AL116	AL107	AL106

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IAY4004	CS725A	AL116	AL107	AL128
IAY4004A1	CS725A	AL116	AL107	AL106
IAY4004B1	CS725A	AL116	AL107	AL106
IAY4004C1	CS725A	AL116	AL107	AL106
IAY4005A1	CS725A	AL116	AL104	AL110
IAY4005A1T	CS725A	AL116	AL104	AL110
IAY4007A1	CS725A	AL116	AL104	AL105
IAY4009	CS725A	AL116	AL104	AL105
IAY4009A	CS725A	AL116	AL104	AL105
IAY4009B	CS725A	AL116	AL104	AL105
IAY4010	CS725A	AL116	AL104	AL110
IAY4010A	CS725A	AL116	AL104	AL110
IAY4011	CS725A	AL116	AL104	AL105
IAY4011A1T	CS725A	AL116	AL104	AL105
IAY4012	CS725A	MO5000	AL104	AL110
IAY4013	CS725A	AL116	AL104	AL105
IAY4013A	CS725A	AL116	AL104	AL105
IAY4013C	CS725A	AL116	AL104	AL105
IAY4013D	CS725A	AL116	AL104	AL105
IAY4013S	CS725A	AL116	AL104	AL105
IAY4014	CS725A	AL116	AL104	AL110
IAY4014B	CS725A	AL116	AL104	AL110
IAY4014C	CS725A	AL116	AL104	AL110
IAY4014S	CS725A	AL116	AL104	AL110
IAY4015	CS725A	AL116	AL104	AL110
IAY4015A1	CS725A	AL116	AL104	AL110
IAY4015A1T	CS725A	AL116	AL104	AL110
IAY4102A1	CS725A	AL116	AL107	AL106
IAY4102A1S	CS725A	AL116	AL107	AL106
IAY4104	CS725A	MO5000	AL107	AL106
IAY4104A1	CS725A	MO5000	AL107	AL106
IAY4401	CS725A	AL116	AL130	AL110
IAY4401A	CS725A	MO5000	AL130	AL110
IAY4401B	CS725A	MO5000	AL130	AL110
IAY4401C	CS725A	MO5000	AL130	AL110
IAY4405	CS729A	—	AL125	AL124
IAY4405	CS729A	—	AL130	—
IAY4502A	CS719A	MO5000	AL141	AL142
IAY6001	CS725A	AL116	AL104	AL105
IAY6003	CS725A	AL116	AL104	AL110
IAY40011	CS725A	AL116	AL107	AL106
IAY40021	CS725A	AL116	AL107	AL106
IAY40031	CS725A	AL116	AL107	AL106
IAY40031B	CS725A	AL116	AL107	AL128
IAY40031F	CS725A	AL116	AL107	AL106
IAY40041	CS725A	AL116	AL107	AL106
IAY40041F	CS725A	AL116	AL107	AL106
IAY40061	CS725A	AL116	AL107	AL106

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IAY40081	CS725A	AL116	AL107	AL106
IAY40091	CS725A	AL116	AL104	AL105
IAY40091A	CS725A	AL116	AL104	AL105
IAY40121	CS725A	MO5000	AL107	AL128
IAY41011	CS725A	MO5000	AL107	AL106
IAY41021	CS725A	MO5000	AL107	AL106
IAY41031	CS725A	MO5000	AL107	AL128
IAY41041	CS725A	MO5000	AL107	AL106
IAZ4001	CS721A	MO5000	AL65	AL99
IAZ4001A	CS721A	MO5000	AL65	AL99
IAZ4001B	CS721A	MO5000	AL65	AL99
IAZ4001C	CS721A	MO5000	AL65	AL99
IAZ4001D	CS721A	MO5000	AL65	AL99
IAZ4001E	CS721A	MO5000	AL65	AL99
IAZ4001F	CS721A	MO5000	AL65	AL99
IAZ4001G	CS721A	MO5000	AL65	AL99
IAZ4002	CS721A	MO5000	AL65	AL99
IAZ4002A	CS721A	MO5000	AL65	AL99
IAZ4002B	CS721A	MO5000	AL65	AL99
IAZ4002C	CS721A	MO5000	AL65	AL99
IAZ4002D	CS721A	MO5000	AL65	AL99
IAZ4003	CS721A	AL869	AL65	AL99
IAZ4003A	CS721A	AL869	AL65	AL99
IAZ4003B	CS721A	AL869	AL65	AL99
IAZ4003C	CS721A	AL869	AL65	AL99
IAZ4003D	CS721A	AL869	AL65	AL99
IAZ4003E	CS721A	MO5000	AL65	AL99
IAZ4003F	CS721A	MO5000	AL65	AL99
IAZ4003G	CS721A	MO5000	AL65	AL99
IAZ4003H	CS721A	AL869	AL65	AL99
IAZ40013	CS721A	MO5000	AL65	AL99
IBB4001A	—	—	AL125	AL129
IBB4001AS	—	—	AL125	AL129
IBB4001S	—	—	AL125	AL129
IBB4002H	CS729A	MO5000	AL125	AL124
IBB4002J	CS729A	MO5000	AL125	AL124
IBB4013	CS720P	MO5000	AL65	AL99
IBB4013A	CS720P	MO5000	AL65	AL99
IBB4013B	CS720P	MO5000	AL65	AL99
IBB4013C	CS720P	MO5000	AL65	AL99
IBB4101A1	CS720P	AL869	AL65	AL99
IBB4101B	CS720P	MO5000	AL65	AL99
IBB4101B1	CS720P	AL869	AL65	AL99
IBB4102A1	CS720P	MO5000	AL65	AL99
IBB4102A1M	CS720P	MO5000	AL65	AL99
IBB4103	CS720P	MO5000	AL65	AL99
IBB4103A	CS720P	MO5000	AL65	AL99
IBB4103B	CS720P	MO5000	AL65	AL99

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IBB4103C	CS720P	MO5000	AL65	AL99
IBB4104	CS720P	MO5000	AL65	AL99
IBB4104A	CS720P	MO5000	AL65	AL99
IBB4104B	CS720P	MO5000	AL65	AL99
IBB4105	CS720P	MO5000	AL65	AL99
IBB4105A	CS720P	MO5000	AL65	AL99
IBB4105B	CS720P	MO5000	AL65	AL99
IBB4106A1	CS720P	MO5000	AL65	AL99
IBB4108	CS720P	MO5000	AL65	AL99
IBB4109A	CS720P	MO5000	AL65	AL99
IBB4110	CS720P	—	AL125	AL124
IBB4201A	CS720P	AL869	AL65	AL99
IBB4201B	CS720P	AL869	AL65	AL99
IBB4202	CS720P	MO5000	AL125	AL129
IBB4202A	—	—	AL125	AL129
IBB4202AS	—	—	AL125	AL129
IBB4202S	CS720P	MO5000	AL125	AL129
IBB4204	CS720P	MO5000	AL125	AL129
IBB4204S	CS720P	MO5000	AL125	AL129
IBB4205	CS720P	MO5000	AL125	AL129
IBB4205S	CS720P	MO5000	AL125	AL129
IBB4301A	CS720P	AL869	AL125	AL129
IBB4301B	CS720P	AL869	AL125	AL129
IBB4401	—	—	AL125	AL129
IBB4401A	—	—	AL125	AL129
IBB4401AS	—	—	AL125	AL129
IBB4401S	—	—	AL125	AL129
IBB7003	CS720P	MO5000	AL125	AL129
IBB7003S	CS720P	MO5000	AL125	AL129
IBB41011M	CS720P	AL869	AL65	AL99
IBB41021	CS720P	MO5000	AL65	AL99
IBB41021M	CS720P	MO5000	AL65	AL99
IBB41061	CS720P	MO5000	AL65	AL99
IBB41071	CS720P	MO5000	AL65	AL99
IBC4002UT	CS725A	MO5000	—	—
IBC4005UT	CS725A	AL869	—	—
IBC4006UT	CS725A	AL869	—	—
IBC4010UT	CS725A	AL869	—	—
IBC4012UT	CS725A	AL869	—	—
IBC4013AUT	CS725A	AL869	—	—
IBC4015UT	CS725A	AL869	—	—
IBC4016AUT	CS725A	AL869	—	—
IBC4016UT	CS725A	MO5000	—	—
IBC4018UT	CS725A	AL869	—	—
IBC4019UT	CS725A	AL869	—	—
IBC4020UT	CS725A	AL869	—	—
IBC4021UT	CS725A	AL869	—	—
IBC4022UT	CS725A	AL869	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IBC4023UT	CS725A	AL869	—	—
IBC4024UT	CS725A	AL869	—	—
IBD4002UT	CS725A	MO5000	—	—
IBD4006AUT	CS725A	AL869	—	—
IBD4008AUT	CS725A	AL869	—	—
IBD4008BUT	CS725A	AL869	—	—
IBD4008CUT	CS725A	AL869	—	—
IBD4008UT	CS725A	MO5000	—	—
IBD4009UT	CS725A	AL869	—	—
IBD4013UT	CS725A	AL869	—	—
IBD4014UT	CS725A	AL869	—	—
IBD4015UT	CS725A	AL869	—	—
IBD4016UT	CS725A	AL869	—	—
IBE40011M	CS725A	AL116	AL62	AL98
IBF4001AUT	CS721A	AL869	—	—
IBF4002AUT	CS721A	AL869	—	—
IBF4002BUT	CS721A	MO5000	—	—
IBF4002CUT	CS721A	MO5000	—	—
IBF4002UT	CS721A	MO5000	—	—
IBF4004UT	CS720P	AL869	—	—
IBG4001AUT	CS721A	MO5000	—	—
IBG4001UT	CS721A	MO5000	—	—
IBH4001AUT	CS721A	MO5000	—	—
IBH4001UT	CS721A	MO5000	—	—
IBJ4001	CS720P	MO5000	AL65	AL99
IBJ4001A	CS720P	MO5000	AL65	AL99
IBJ4001B	CS720P	MO5000	AL65	AL99
IBJ4001C	CS720P	MO5000	AL65	AL99
IBJ4001D	CS720P	MO5000	AL65	AL99
IBJ4001E	CS720P	MO5000	AL65	AL99
IBJ4301	CS721A	MO5000	AL125	AL124
IBJ4301A	CS721A	MO5000	AL125	AL124
IBJ4301B	CS721A	MO5000	AL125	AL124
IBJ4302	CS721A	MO5000	AL125	AL124
IBJ4302A	CS721A	MO5000	AL125	AL124
IBJ4302B	CS721A	MO5000	AL125	AL124
IBJ4302C	CS721A	MO5000	AL125	AL124
IBJ4302D	CS721A	MO5000	AL125	AL124
IBJ4303	CS721A	MO5000	AL125	AL124
IBJ4303A	CS721A	MO5000	AL125	AL124
IBJ4303B	CS721A	MO5000	AL125	AL124
IBJ4303C	CS721A	MO5000	AL125	AL124
IBK4001	CS720P	MO5000	AL65	AL99
IBK4001A	CS720P	MO5000	AL65	AL99
IBK4001B	CS720P	MO5000	AL65	AL99
IBK4301A	CS721A	MO5000	AL125	AL124
IBK4301C	CS721A	MO5000	AL125	AL124
IBK4302	CS721A	MO5000	AL125	AL124

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IBK4303	CS721A	MO5000	AL125	AL124
IBK4303A	CS721A	MO5000	AL125	AL124
IBK4304	CS721A	MO5000	AL125	AL124
IBL4001A	CS720P	MO5000	AL65	AL99
IBM4001	CS720P	MO5000	AL125	AL124
IBM4001A	CS720P	MO5000	AL125	AL124
IBM4001B	CS720P	MO5000	AL125	AL124
IBM4002	CS720P	MO5000	AL125	AL124
IBM4003	CS720P	MO5000	AL125	AL124
IBM4014	CS720P	MO5000	AL125	AL124
IBM4101	CS720P	MO5000	AL125	AL124
IBM4101A	CS720P	MO5000	AL125	AL124
IBM4101B	CS720P	MO5000	AL125	AL124
IBM4102	CS720P	MO5000	AL125	AL124
IBM4103	CS720P	MO5000	AL125	AL124
IBM4103A	CS720P	MO5000	AL125	AL124
IBM4104	CS720P	MO5000	AL125	AL124
IBM4106	CS720P	MO5000	AL125	AL124
IBM4106S	CS720P	MO5000	AL125	AL124
IBM4107	CS720P	AL869	AL125	AL129
IBM4107A	CS720P	AL869	AL125	AL129
IBM4108	CS720P	AL869	AL125	AL129
IBM4108A	CS720P	AL869	AL125	AL129
IBM4108B	CS720P	AL869	AL125	AL129
IBM4108BS	CS720P	AL869	AL125	AL129
IBM4108C	CS720P	AL869	AL125	AL129
IBM4108CS	CS720P	AL869	AL125	AL129
IBM4109	CS720P	AL869	AL125	AL129
IBM4109A	CS720P	AL869	AL125	AL129
IBM4109AS	CS720P	AL869	AL125	AL129
IBM4110	CS720P	AL869	AL139	—
IBM4112	CS720P	AL869	AL139	—
IBM4112A	CS720P	AL869	AL139	—
IBM4113A	—	—	AL139	—
IBM4113AS	—	—	AL139	—
IBM4113B	—	—	AL139	—
IBM4113BS	—	—	AL139	—
IBM4114	—	—	AL139	—
IBM4114S	—	—	AL139	—
IBM4115	CS720P	MO5000	AL139	—
IBM4116	CS720P	MO5000	AL139	—
IBM4117A	CS720P	AL869	AL125	AL124
IBM4117S	CS720P	AL869	AL125	AL124
IBM4118A	CS720P	AL869	AL139	—
IBM4119	CS720P	AL869	AL139	—
IBM4119A	CS720P	AL869	AL139	—
IBM4119S	CS720P	AL869	AL139	—
IBM4120	CS720P	MO5000	AL139	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IBM4120S	CS720P	MO5000	AL139	—
IBM4122	CS720P	MO5000	AL125	AL129
IBM4122S	CS720P	MO5000	AL125	AL129
IBM7001	—	—	AL125	AL124
IBM7003B	CS720P	AL869	AL125	AL168
IBM7003BS	CS720P	AL869	AL125	AL168
IBM7004A	CS720P	AL869	AL125	AL168
IBM7004AS	CS720P	AL869	AL125	AL168
IBM7004B	CS720P	AL869	AL125	AL168
IBM7004BS	CS720P	AL869	AL125	AL168
IBM7005A	CS720P	AL869	AL125	AL168
IBM7005AS	CS720P	AL869	AL125	AL168
IBM7007	CS720P	AL869	AL125	AL168
IBM7007A	CS720P	AL869	AL125	AL168
IBM7007AS	CS720P	AL869	AL125	AL168
IBM7007S	CS720P	AL869	AL125	AL168
IBM7008	CS720P	AL869	AL125	AL168
IBM7008A	CS720P	AL869	AL125	AL168
IBM7008AS	CS720P	AL869	AL125	AL168
IBM7008B	CS720P	AL869	AL125	AL168
IBM7008BS	CS720P	AL869	AL125	AL168
IBM7008C	CS720P	AL869	AL125	AL168
IBM7008CS	CS720P	AL869	AL125	AL168
IBM7008S	CS720P	AL869	AL125	AL168
IBM7010	CS729A	MO5000	AL125	AL168
IBM7011	CS720P	AL869	AL125	AL168
IBM7011A	CS720P	AL869	AL125	AL168
IBM7011B	—	—	AL125	AL168
IBM7011C	CS720P	AL869	AL125	AL168
IBM7011D	CS720P	AL869	AL125	AL168
IBM7012	CS720P	AL869	AL125	AL168
IBM7013	CS720P	AL869	—	AL171
IBM7013A	CS720P	AL869	AL160	AL171
IBM7013B	—	—	AL160	AL171
IBM7013C	CS720P	AL869	—	AL171
IBM7013D	CS720P	AL869	—	AL171
IBM7013E	CS720P	AL869	—	AL171
IBM7014	CS720P	MO5000	—	—
IBM7014A	CS720P	AL869	—	AL172
IBM7014A	CS720P	MO5000	—	—
IBM7014E	CS720P	AL869	—	AL172
IBM7016	CS720P	AL869	—	AL171
IBM7017	CS720P	AL869	—	AL171
IBM7018	CS720P	AL869	—	AL172
IBM7019	CS720P	AL869	—	AL171
IBM7019A	CS720P	AL869	—	AL171
IBM7019AS	CS720P	AL869	—	AL171
IBM7019S	CS720P	AL869	—	AL171

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IBM7020	CS720P	AL869	—	AL171
IBM7020A	CS720P	AL869	—	AL171
IBM7020AS	CS720P	AL869	—	AL171
IBM7020B	CS720P	AL869	—	AL171
IBM7020BS	CS720P	AL869	—	AL171
IBM7020C	CS720P	AL869	—	AL171
IBM7020CS	CS720P	AL869	—	AL171
IBM7021	CS720P	AL869	—	AL172
IBM7022	CS720P	AL869	—	—
IBM41051	CS720P	MO5000	AL125	AL124
IBO4001	CS720P	MO5000	AL125	AL124
IBO4001A1	CS720P	MO5000	AL125	AL124
IBO4003	CS720P	MO5000	AL125	AL124
IBO4101	CS720P	MO5000	AL125	AL124
IBO4102	CS720P	MO5000	AL125	AL124
IBO4103	CS720P	MO5000	AL125	AL124
IBO4103A	CS720P	MO5000	AL125	AL124
IBO4104	CS720P	MO5000	AL125	AL124
IBO40011	CS720P	MO5000	AL125	AL124
IBO40021	CS720P	MO5000	AL125	AL124
IBP4001	CS723A	MO5000	AL125	AL124
IBP4001A	CS723A	MO5000	AL125	AL124
IBP4001AS	CS719A	MO5000	—	—
IBP4002	CS723A	MO5000	AL125	AL124
IBP4002A	CS723A	MO5000	AL125	AL124
IBP4002B	CS723A	MO5000	AL125	AL124
IBP4002C	CS723A	MO5000	AL125	AL124
IBP4002D	CS723A	MO5000	AL125	AL124
IBP4002E	CS723A	MO5000	AL125	AL124
IBP4002F	CS723A	MO5000	AL125	AL124
IBP4002G	CS723A	MO5000	AL125	AL124
IBP4002H	CS723A	MO5000	AL125	AL124
IBP4002J	CS723A	MO5000	AL125	AL124
IBP4002P	CS723A	MO5000	AL125	AL124
IBP4003	CS723A	MO5000	AL125	AL124
IBP4003A	CS723A	MO5000	AL125	AL124
IBP4003AA	CS723A	MO5000	AL125	AL129
IBP4003AAS	CS723A	MO5000	AL125	AL129
IBP4003AB	CS723A	MO5000	AL125	AL129
IBP4003ABS	CS723A	MO5000	AL125	AL129
IBP4003AC	CS723A	MO5000	AL125	AL129
IBP4003ACS	CS723A	MO5000	AL125	AL129
IBP4003AD	CS723A	MO5000	AL125	AL129
IBP4003ADS	CS723A	MO5000	AL125	AL129
IBP4003AE	CS723A	MO5000	AL125	AL129
IBP4003AES	CS723A	MO5000	AL125	AL129
IBP4003AF	CS723A	MO5000	AL125	AL129
IBP4003AFS	CS723A	MO5000	AL125	AL129

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IBP4003AG	CS723A	MO5000	AL125	AL129
IBP4003AGS	CS723A	MO5000	AL125	AL129
IBP4003AS	CS723A	MO5000	AL125	AL129
IBP4003B	CS723A	MO5000	AL125	AL124
IBP4003C	CS723A	MO5000	AL125	AL124
IBP4003D	CS723A	MO5000	AL125	AL124
IBP4003E	CS723A	MO5000	AL125	AL124
IBP4003F	CS723A	MO5000	AL125	AL124
IBP4003H	CS723A	MO5000	AL125	AL124
IBP4003J	CS723A	MO5000	AL125	AL124
IBP4003K	CS723A	MO5000	AL125	AL124
IBP4003L	CS723A	MO5000	AL125	AL129
IBP4003LS	CS723A	MO5000	AL125	AL129
IBP4003N	CS723A	MO5000	AL125	AL129
IBP4003P	CS723A	MO5000	AL125	AL129
IBP4003PS	CS723A	MO5000	AL125	AL129
IBP4003R	CS723A	MO5000	AL125	AL129
IBP4003RS	CS723A	MO5000	AL125	AL129
IBP4003T	CS723A	MO5000	AL125	AL129
IBP4003U	CS723A	MO5000	AL125	AL129
IBP4003US	CS723A	MO5000	AL125	AL129
IBP4003V	CS723A	MO5000	AL125	AL129
IBP4003VS	CS723A	MO5000	AL125	AL129
IBP4003W	CS723A	MO5000	AL125	AL129
IBP4003WS	CS723A	MO5000	AL125	AL129
IBP4003X	CS723A	MO5000	AL125	AL129
IBP4003XS	CS723A	MO5000	AL125	AL129
IBP4003Y	CS723A	MO5000	AL125	AL129
IBP4003YS	CS723A	MO5000	AL125	AL129
IBP4003Z	CS723A	MO5000	AL125	AL129
IBP4003ZS	CS723A	MO5000	AL125	AL129
IBP4005	CS729A	MO5000	AL125	AL124
IBP4005B	CS729A	MO5000	AL125	AL124
IBP4005C	CS729A	MO5000	AL125	AL129
IBP4005D	CS729A	MO5000	AL125	AL129
IBP4005E	CS729A	MO5000	AL125	AL129
IBP4005E1	CS729A	—	AL125	AL124
IBP4005F	CS729A	MO5000	AL125	AL129
IBP4005FS	CS729A	MO5000	AL125	AL129
IBP4005G	CS729A	MO5000	AL125	AL129
IBP4005GS	CS729A	MO5000	AL125	AL129
IBP4005H	CS729A	MO5000	AL125	AL129
IBP4005HS	CS729A	MO5000	AL125	AL129
IBP4005J	CS729A	MO5000	AL125	AL129
IBP4005JS	CS729A	MO5000	AL125	AL129
IBP4006	CS729A	MO5000	AL125	AL124
IBP4006B	CS729A	MO5000	AL125	AL124
IBP4006C	CS729A	MO5000	AL125	AL129

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IBP4006D	CS729A	MO5000	AL125	AL129
IBP4006E	CS729A	MO5000	AL125	AL129
IBP4006F	CS729A	MO5000	AL125	AL129
IBP4006G	CS729A	MO5000	AL125	AL129
IBP4006GS	CS729A	MO5000	AL125	AL129
IBP4006H	CS729A	MO5000	AL125	AL129
IBP4006HS	CS729A	MO5000	AL125	AL129
IBP4006J	CS729A	MO5000	AL125	AL129
IBP4006JS	CS729A	MO5000	AL125	AL129
IBP4006K	CS729A	MO5000	AL125	AL129
IBP4006KS	CS729A	MO5000	AL125	AL129
IBP4008	CS729A	MO5000	AL125	AL129
IBP4008A	CS729A	MO5000	AL125	AL129
IBP4008AS	CS729A	MO5000	AL125	AL129
IBP4008B	CS729A	MO5000	AL125	AL129
IBP4008BS	CS729A	MO5000	AL125	AL129
IBP4008C	CS729A	MO5000	AL125	AL129
IBP4008CS	CS729A	MO5000	AL125	AL129
IBP4008D	CS729A	MO5000	AL125	AL129
IBP4008DS	CS729A	MO5000	AL125	AL129
IBP4008E	CS729A	MO5000	AL125	AL129
IBP4008ES	CS729A	MO5000	AL125	AL129
IBP4008F	CS729A	MO5000	AL125	AL129
IBP4008FS	CS729A	MO5000	AL125	AL129
IBP4008G	CS729A	MO5000	AL125	AL129
IBP4008GS	CS729A	MO5000	AL125	AL129
IBP4008S	CS729A	MO5000	AL125	AL129
IBP4009S1	CS851P	MO5000	MO13	MO20
IBP4010CS1	CS851P	MO5000	MO13	MO20
IBP4011LS1	CS851P	MO5000	MO13	MO20
IBP4104	CS729A	MO5000	AL125	AL124
IBP4104A	CS729A	MO5000	AL125	AL124
IBP4105	CS729A	MO5000	AL125	AL124
IBP4105A	CS729A	MO5000	AL125	AL124
IBP4107	CS729A	MO5000	AL125	AL129
IBP4108	CS729A	MO5000	AL125	AL124
IBP4109	CS729A	MO5000	AL125	AL124
IBP4109A	CS729A	MO5000	AL125	AL129
IBP4110	CS729A	MO5000	AL139	—
IBP4110A	CS729A	MO5000	AL139	—
IBP4110B	CS729A	MO5000	AL139	—
IBP4111A	CS729A	MO5000	AL125	AL129
IBP4111S	CS729A	MO5000	AL125	AL129
IBP4112A	CS729A	MO5000	AL139	—
IBP4112B	CS729A	MO5000	AL139	—
IBP4113	CS729A	MO5000	AL139	—
IBP4113A	CS729A	MO5000	AL139	—
IBP4113B	CS729A	MO5000	AL139	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IBP4113C	CS729A	MO5000	AL139	—
IBP4113S1	CS729A	MO5000	AL139	—
IBP4113S2	CS729A	MO5000	AL139	—
IBP4201	CS723A	MO5000	AL125	AL129
IBP4201A	CS723A	MO5000	AL125	AL129
IBP4201AS	CS723A	MO5000	AL125	AL129
IBP4201S	CS723A	MO5000	AL125	AL129
IBP4301	CS729A	MO5000	AL125	AL129
IBP4301A	CS729A	MO5000	AL125	AL129
IBP4301AS	CS729A	MO5000	AL125	AL129
IBP4301S	CS729A	MO5000	AL125	AL129
IBR4001	CS729A	MO5000	AL107	AL106
IBR4001A	CS719A	MO5000	AL107	AL128
IBR4001AS	CS719A	MO5000	AL107	AL128
IBR4002	CS719A	MO5000	AL107	AL106
IBR4002A	CS719A	MO5000	AL107	AL128
IBR4002AS	CS719A	MO5000	AL107	AL128
IBR4002B	CS719A	MO5000	AL107	AL128
IBR4002BS	CS719A	MO5000	AL107	AL128
IBR4003	CS719A	MO5000	AL107	AL106
IBR4201A	CS719A	MO5000	AL132	AL131
IBR4201B	CS719A	MO5000	AL132	AL131
IBR4201C	CS719A	MO5000	AL132	AL131
IBR4201CS	CS719A	MO5000	AL132	AL131
IBR4201D	CS719A	MO5000	AL132	AL131
IBR4201DS	CS719A	MO5000	AL132	AL131
IBR4201E	CS719A	MO5000	AL132	AL131
IBR4201ES	CS719A	MO5000	AL132	AL131
IBR4201F	CS719A	MO5000	AL132	AL131
IBR4201FS	CS719A	MO5000	AL132	AL131
IBR4201G	CS719A	MO5000	AL132	AL131
IBR4201GS	CS719A	MO5000	AL132	AL131
IBR4201H	CS719A	MO5000	AL132	AL131
IBR4201HS	CS719A	MO5000	AL132	AL131
IBR4201J	CS719A	MO5000	AL132	AL131
IBR4201JS	CS719A	MO5000	AL132	AL131
IBR4202	CS719A	MO5000	AL132	AL131
IBR4202S	CS719A	MO5000	AL132	AL131
IBR4203A	CS723A	AL869	—	MO40
IBR4203AD	CS723A	MO5000	AL160	MO40
IBR4203AS	CS723A	AL869	—	MO40
IBR4203B	CS723A	AL869	—	MO40
IBR4203BS	CS723A	AL869	—	MO40
IBR4203C	CS723A	AL869	—	MO40
IBR4203CS	CS723A	AL869	—	MO40
IBR4203D	CS723A	MO5000	—	—
IBR4203DS	CS723A	MO5000	—	—
IBR4203E	CS723A	MO5000	—	MO40

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IBR4203ES	CS723A	MO5000	—	MO40
IBR4203F	CS723A	MO5000	—	MO40
IBR4203FS	CS723A	MO5000	—	MO40
IBR4203G	CS723A	MO5000	—	MO40
IBR4203GS	CS723A	MO5000	—	MO40
IBR4203H	CS723A	MO5000	—	MO40
IBR4203HS	CS723A	MO5000	—	MO40
IBR4203J	CS723A	MO5000	—	MO40
IBR4203JS	CS723A	MO5000	—	MO40
IBR4205	CS851P	MO5000	MO13	MO40
IBR4205A	CS851P	MO5000	MO13	MO40
IBR4205S	CS851P	MO5000	MO13	MO40
IBR7002	CS725A	—	AL62	AL98
IBR7002A	CS725A	—	AL62	AL98
IBR7002AS	CS725A	—	AL62	AL98
IBR7002S	CS725A	—	AL62	AL98
IBS401A	CS720P	MO5000	AL125	AL129
IBS401B	CS720P	MO5000	AL125	AL129
IBS401C	CS720P	MO5000	AL125	AL129
IBS401D	CS720P	MO5000	AL125	AL129
IBS4001A	CS720P	MO5000	AL125	AL124
IBS4001B	CS720P	MO5000	AL125	AL124
IBS4003	CS721A	MO5000	AL125	AL124
IBS4004	CS721A	MO5000	AL125	AL124
IBS4005	CS721A	MO5000	AL125	AL124
IBS4005A	CS721A	MO5000	AL125	AL124
IBS4006B	CS720P	MO5000	AL125	AL124
IBS4006C	CS720P	MO5000	AL125	AL124
IBS4006D	CS720P	MO5000	AL125	AL129
IBS4006E	CS720P	MO5000	AL125	AL129
IBS4006F	CS720P	MO5000	AL125	AL129
IBS4006G	CS720P	MO5000	AL125	AL129
IBS4006J	CS720P	MO5000	AL125	AL129
IBS4006JS	CS720P	MO5000	AL125	AL129
IBS4006K	CS720P	MO5000	AL125	AL129
IBS4006KS	CS720P	MO5000	AL125	AL129
IBS4006L	CS720P	MO5000	AL125	AL129
IBS4006LS	CS720P	MO5000	AL125	AL129
IBS4006N	CS720P	MO5000	AL125	AL129
IBS4006NS	CS720P	MO5000	AL125	AL129
IBS4006P	CS720P	MO5000	AL125	AL129
IBS4006PS	CS720P	MO5000	AL125	AL129
IBS4006S	CS720P	MO5000	AL125	AL129
IBS4006T	CS720P	MO5000	AL125	AL129
IBS4006V	CS720P	MO5000	AL125	AL129
IBS4006W	CS720P	MO5000	AL125	AL129
IBS4006WS	CS720P	MO5000	AL125	AL129
IBS4006Y	CS720P	MO5000	AL125	AL129

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IBS4006YS	CS720P	MO5000	AL125	AL129
IBS4006Z	CS720P	MO5000	AL125	AL129
IBS4006ZS	CS720P	MO5000	AL125	AL129
IBS4007	CS721A	MO5000	AL125	AL124
IBS4007A	CS721A	MO5000	AL125	AL124
IBS4008	CS721A	MO5000	AL125	AL124
IBS4009	CS720P	MO5000	AL125	AL124
IBS4010	CS720P	MO5000	AL125	AL124
IBS4010A	CS720P	MO5000	AL125	AL124
IBS4010B	CS720P	MO5000	AL125	AL124
IBS4011	CS720P	MO5000	AL125	AL129
IBS4011A	CS720P	MO5000	AL125	AL124
IBS4011AS	CS720P	MO5000	AL125	AL124
IBS4011B	CS720P	MO5000	AL125	AL129
IBS4011BS	CS720P	MO5000	AL125	AL129
IBS4011C	CS720P	MO5000	AL125	AL129
IBS4011CS	CS720P	MO5000	AL125	AL129
IBS4011D	CS720P	MO5000	AL125	AL129
IBS4011DS	CS720P	MO5000	AL125	AL129
IBS4011E	CS720P	MO5000	AL125	AL129
IBS4011ES	CS720P	MO5000	AL125	AL129
IBS4012	CS720P	MO5000	AL125	AL124
IBS4012A	CS720P	MO5000	AL125	AL124
IBS4013	CS721A	MO5000	AL125	AL129
IBS4013A	CS721A	MO5000	AL125	AL129
IBS4013AS	CS721A	MO5000	AL125	AL129
IBS4013B	CS721A	MO5000	AL125	AL129
IBS4013BS	CS721A	MO5000	AL125	AL129
IBS4013S	CS721A	MO5000	AL125	AL129
IBS4014	CS720P	MO5000	AL125	AL129
IBS4014A	CS720P	MO5000	AL125	AL129
IBS4014AS	CS720P	MO5000	AL125	AL129
IBS4014B	CS720P	MO5000	AL125	AL129
IBS4014BS	CS720P	MO5000	AL125	AL129
IBS4014C	CS720P	MO5000	AL125	AL129
IBS4014CS	CS720P	MO5000	AL125	AL129
IBS4014D	CS720P	MO5000	AL125	AL129
IBS4014DS	CS720P	MO5000	AL125	AL129
IBS4014E	CS720P	MO5000	AL125	AL129
IBS4014ES	CS720P	MO5000	AL125	AL129
IBS4014F	CS720P	MO5000	AL125	AL129
IBS4014FS	CS720P	MO5000	AL125	AL129
IBS4014G	CS720P	MO5000	AL125	AL129
IBS4014GS	CS720P	MO5000	AL125	AL129
IBS4014S	CS720P	MO5000	AL125	AL129
IBS4015	CS721A	MO5000	AL125	AL129
IBS4015A	CS721A	MO5000	AL125	AL129
IBS4015AS	CS721A	MO5000	AL125	AL129

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IBS4015B	CS721A	MO5000	AL125	AL129
IBS4015BS	CS721A	MO5000	AL125	AL129
IBS4015C	CS721A	MO5000	AL125	AL129
IBS4015CS	CS721A	MO5000	AL125	AL129
IBS4015S	CS721A	MO5000	AL125	AL129
IBS4016	CS720P	MO5000	AL125	AL129
IBS4016A	CS720P	MO5000	AL125	AL129
IBS4016AS	CS720P	MO5000	AL125	AL129
IBS4016S	CS720P	MO5000	AL125	AL129
IBS4017	CS720P	MO5000	AL125	AL129
IBS4017A	CS720P	MO5000	AL125	AL129
IBS4017AS	CS720P	MO5000	AL125	AL129
IBS4017B	CS720P	MO5000	AL125	AL129
IBS4017BS	CS720P	MO5000	AL125	AL129
IBS4017C	CS720P	MO5000	AL125	AL129
IBS4017CS	CS720P	MO5000	AL125	AL129
IBS4017D	CS720P	MO5000	AL125	AL129
IBS4017DS	CS720P	MO5000	AL125	AL129
IBS4017E	CS720P	MO5000	AL125	AL129
IBS4017ES	CS720P	MO5000	AL125	AL129
IBS4017S	CS720P	MO5000	AL125	AL129
IBS4018	CS721A	MO5000	AL125	AL129
IBS4018A	CS721A	MO5000	AL125	AL129
IBS4018AS	CS721A	MO5000	AL125	AL129
IBS4018B	CS721A	MO5000	AL125	AL129
IBS4018BS	CS721A	MO5000	AL125	AL129
IBS4018C	CS721A	MO5000	AL125	AL129
IBS4018CS	CS721A	MO5000	AL125	AL129
IBS4018D	CS721A	MO5000	AL125	AL129
IBS4018DS	CS721A	MO5000	AL125	AL129
IBS4018E	CS721A	MO5000	AL125	AL129
IBS4018ES	CS721A	MO5000	AL125	AL129
IBS4018S	CS721A	MO5000	AL125	AL129
IBS4019	CS720P	MO5000	AL125	AL129
IBS4019A	CS720P	MO5000	AL125	AL129
IBS4019AS	CS720P	MO5000	AL125	AL129
IBS4019B	CS720P	MO5000	AL125	AL129
IBS4019BS	CS720P	MO5000	AL125	AL129
IBS4019S	CS720P	MO5000	AL125	AL129
IBT4001G	CS723A	MO5000	AL130	AL133
IBT4101A	CS720P	MO5000	AL125	AL124
IBT4101H	CS729A	MO5000	AL130	AL133
IBT4101L	CS729A	MO5000	AL134	AL133
IBT4101R	CS729A	MO5000	AL134	AL133
IBT4101S	CS729A	MO5000	AL134	AL133
IBT4101U	CS729A	MO5000	AL134	AL133
IBT4102	CS729A	AL869	—	—
IBT4102A	CS729A	AL869	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IBT4103	CS729A	AL869	AL134	—
IBT4105	CS723A	AL869	AL150	AL165
IBT4105A	CS723A	AL869	AL150	AL165
IBT4201	CS723A	AL869	AL141	—
IBT4301B	CS729A	MO5000	AL134	AL148
IBT4301C	CS729A	MO5000	AL134	AL148
IBT4301D	CS729A	MO5000	AL134	AL148
IBT4301E	CS729A	AL869	AL134	AL148
IBT4402	CS723A	MO5000	AL134	AL133
IBT4402A	CS723A	MO5000	AL134	AL133
IBT4403	CS723A	MO5000	AL134	AL133
IBT4403A	CS723A	MO5000	AL134	AL133
IBT4403B	CS723A	AL869	AL134	AL133
IBT4404	CS723A	MO5000	AL134	AL133
IBT4405	CS723A	AL869	AL134	AL133
IBT4406	CS729A	AL869	AL134	AL133
IBT4408	CS723A	AL869	AL134	—
IBT4501A	CS729A	MO5000	AL130	AL149
IBT4501B	CS729A	AL869	AL150	AL149
IBT4701A	CS729A	MO5000	AL130	AL149
IBT4701AT	CS729A	MO5000	AL130	AL149
IBT4701B	CS729A	MO5000	AL130	AL149
IBT4701BT	CS729A	AL869	AL150	AL149
IBT4701C	CS729A	AL869	AL150	AL149
IBT4701D	CS729A	AL869	AL150	AL149
IBT4702	CS729A	MO5000	AL130	AL133
IBT4705	CS729A	MO5000	AL130	AL133
IBT4706	CS729A	AL869	AL150	AL165
IBT4707	CS729A	AL869	AL150	AL165
IBT4708	—	—	AL150	—
IBT4801	CS723A	MO5000	AL134	AL133
IBT6101H	CS729A	MO5000	AL134	AL128
IBT6101J	—	—	AL130	AL128
IBT6101K	CS729A	MO5000	AL134	AL144
IBT6101L	CS729A	MO5000	AL134	AL128
IBT6101N	CS729A	MO5000	AL134	AL144
IBT6201	CS729A	AL869	AL150	AL142
IBT6201A	CS729A	AL869	AL150	AL142
IBT6403	CS723A	MO5000	AL134	AL128
IBT6404	CS723A	MO5000	AL134	AL144
IBT6404A	CS723A	MO5000	AL134	AL144
IBT6405	CS723A	MO5000	AL134	AL144
IBT6501A	CS729A	MO5000	AL150	—
IBT6501B	CS729A	MO5000	AL150	—
IBT6501C	CS729A	MO5000	AL150	—
IBT6501D	CS729A	AL869	AL150	—
IBT6501E	CS729A	AL869	AL150	—
IBT6501F	CS729A	AL869	AL150	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IBT6502	CS729A	AL869	AL130	AL144
IBT6701A	CS729A	MO5000	AL150	—
IBT6701B	CS729A	MO5000	AL150	—
IBT6701C	CS729A	MO5000	AL150	—
IBT6701D	CS729A	AL869	AL150	—
IBT6701E	CS729A	AL869	AL150	—
IBT6701F	CS729A	AL869	AL150	—
IBT6702	CS729A	MO5000	AL130	AL128
IBT6702A	CS729A	MO5000	AL130	AL144
IBT6703	CS729A	AL869	AL150	AL142
IBT6704	CS729A	AL869	AL150	AL142
IBT6705	—	—	AL150	—
IDA4401UT	CS725A	AL869	—	—
IDA4402UT	CS709	AL869	—	—
IDA4601UT	CS725A	AL869	—	—
IDA4602UT	CS725A	AL869	—	—
IDA4801UT	CS720P	AL869	—	—
IDA4802UT	CS720P	AL869	—	—
IDA4803UT	CS720P	AL869	—	—
IDA4804UT	CS720P	AL869	—	—
IDC460A	CS719A	MO5000	AL132	AL131
IDC460B	CS719A	MO5000	AL132	AL131
IDC4601	CS719A	MO5000	AL132	AL131
IDC4601A	CS719A	MO5000	AL132	AL131
IDC4601B	CS719A	MO5000	AL132	AL131
IDD4101A	—	—	AL150	—
IDD4102	—	—	AL134	AL133
IDD4103	—	—	AL134	AL133
IDD4104	—	—	AL150	AL165
IDD4105	—	—	AL150	—
IDD4106	—	—	AL134	AL133
IDD4107	—	—	AL150	—
IDD4108	—	—	AL134	AL133
IDD4201	—	—	AL62	AL63
IDD4301	—	—	—	MO40
IDD5103	—	—	AL150	—
IDD5103A	—	—	AL150	—
IDD5104	—	—	AL134	AL133
IDD5105	—	—	AL62	AL63
IDD5106	—	—	—	MO40
IDD5107	—	—	AL150	—
IDD5108	—	—	AL134	AL133
IDD5109	—	—	AL125	—
IDD5111	—	—	AL134	AL133
IDD5112	—	—	AL150	—
IDD5113	—	—	AL150	—
IDD7001	—	—	AL125	—
IDN4101	CS723A	MO5000	AL163	AL161

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IDN4102	CS723A	MO5000	AL163	AL162
IDN4102A	CS723A	MO5000	AL163	AL162
IDN4102B	CS723A	MO5000	AL163	AL162
IDN4102C	CS723A	MO5000	AL163	AL162
IDN4102D	CS723A	MO5000	AL163	AL162
IDN4102E	CS723A	MO5000	AL163	AL162
IDN4102G	CS723A	MO5000	AL163	AL162
IDN4102H	CS723A	MO5000	AL163	AL162
IDN4102J	CS723A	MO5000	AL163	AL162
IDN4102K	CS723A	MO5000	AL163	AL162
IDN4102L	CS723A	MO5000	AL163	AL162
IDN4102N	CS723A	MO5000	AL163	AL162
IDN4103G	CS723A	MO5000	AL163	AL162
IDN4109	CS723A	MO5000	AL163	AL162
IDN4109A	CS723A	MO5000	AL163	AL162
IDR4001	CS729A	AL869	AL130	—
IGB406A	CS709	AL38	AL32	—
IGB4005A	CS709	MO5000	AL32	—
IGB4005B	CS709	MO5000	AL32	—
IGB4005C	CS709	MO5000	AL32	—
IGB4005D	CS709	MO5000	AL32	—
IGB4005E	CS709	MO5000	AL32	—
IGB4005F	CS709	MO5000	AL32	—
IGB4005G	CS709	MO5000	AL32	—
IGB4005H	CS709	MO5000	AL32	—
IGB4005I	CS709	MO5000	AL32	—
IGB4005J	CS709	MO5000	AL32	—
IGB4019A	CS709	AL38	AL32	—
IGB4041A	CS709	AL38	AL32	—
IGB4041B	CS709	AL38	AL32	—
IGB4041C	CS709	AL38	AL32	—
IGB4041D	CS709	AL38	AL32	—
IGB4041E	CS709	AL38	AL32	—
IGB4041F	CS709	AL38	AL32	—
IGB4045	CS709	AL38	AL32	—
IGB4045A	CS709	AL38	AL32	—
IGB4057	CS709	AL38	AL32	—
IGB4057A	CS709	AL38	AL32	—
IGB4057B	CS709	AL38	AL32	—
IGB4057C	CS709	AL38	AL32	—
IGB4064	CS709	MO5000	AL32	—
IGB4065A	CS709	AL38	AL32	—
IGB4065B	CS709	AL38	AL32	—
IGB4065D	CS709	AL38	AL32	—
IGB4068	CS709	AL38	AL32	—
IGB4068A	CS709	AL38	AL32	AL31
IGB4080	CS709	MO5000	AL32	AL143
IGB4080A	CS709	MO5000	AL32	AL143

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IGB4080B	CS709	MO5000	AL32	AL143
IGB4080C	CS709	MO5000	AL32	AL143
IGB4082	CS709	AL38	AL32	—
IGB4095	CS709	MO5000	AL32	—
IGB4096	CS709	AL38	AL32	—
IGB4096A	CS709	AL38	AL32	—
IGB4096B	CS709	AL38	AL32	—
IGB4099	CS709	MO5000	AL32	—
IGB4100	CS709	AL38	AL32	AL143
IGB4101	CS709	AL38	AL32	—
IGB4102	CS709	AL38	AL32	—
IGB4105A	CS709	MO5000	AL132	AL143
IGB4106	CS709	AL38	AL32	—
IGB4201	CS709	AL38	—	—
IGB4201A	CS709	AL38	—	—
IGB4203	CS709	MO5000	AL32	AL352
IGB4204	CS709	MO5000	—	—
IGB4205	CS709	AL38	—	—
IGB4301A	CS709	MO5000	AL32	AL59
IGB4301B	CS709	MO5000	AL32	AL59
IGB4303D	CS709	AL38	AL32	AL59
IGB4303E	CS709	AL38	AL32	AL59
IGB4304A	CS709	AL38	AL32	AL59
IGB4304B	CS709	AL38	AL32	AL59
IGB4304C	CS709	AL38	AL32	AL59
IGB4304D	CS709	AL38	AL32	AL59
IGB4305A	CS709	MO5000	AL32	—
IGB4305B	CS709	MO5000	AL32	—
IGB4305C	CS709	MO5000	AL32	—
IGB4306	CS709	MO5000	AL32	AL59
IGB4307A	CS709	MO5000	AL32	AL59
IGB4307B	CS709	MO5000	AL32	AL59
IGB4307C	CS709	MO5000	AL32	AL59
IGB4307D	CS709	MO5000	AL32	AL59
IGB4307E	CS709	MO5000	AL32	AL59
IGB4307F	CS709	MO5000	AL32	AL59
IGB4307G	CS709	MO5000	AL32	AL59
IGB4307H	CS709	MO5000	AL32	AL59
IGB4307I	CS709	MO5000	AL32	AL59
IGB4307J	CS709	MO5000	AL32	AL59
IGB4307K	CS709	MO5000	AL32	AL59
IGB4307L	CS709	MO5000	AL32	AL59
IGB4307M	CS709	MO5000	AL32	AL59
IGB4309A	CS709	AL38	AL32	AL59
IGB4310	CS709	AL38	AL32	AL59
IGB4312	CS709	AL38	AL32	AL59
IGB4312A	CS709	AL38	AL32	AL59
IGB4312B	CS709	AL38	AL32	AL59

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IGB4315A	CS709	AL38	AL32	AL59
IGB4315B	CS709	AL38	AL32	AL59
IGB4317A	CS709	AL38	AL32	AL59
IGB4317B	CS709	AL38	AL32	AL59
IGB4320	CS709	AL38	AL32	AL59
IGB4322	CS709	AL38	AL32	AL59
IGB4322A	CS709	AL38	AL32	AL59
IGB4323	CS709	MO5000	AL32	AL59
IGB4325	CS709	AL38	AL32	AL59
IGB4327A	CS709	AL38	AL32	AL59
IGB4328	CS709	AL38	AL32	AL59
IGB4328A	CS709	AL38	AL32	AL59
IGB4328B	CS709	AL38	AL32	AL59
IGB4330	CS709	AL38	AL32	AL59
IGB4331	CS709	AL38	AL32	AL59
IGB4332	CS709	AL38	AL32	AL59
IGB4337A	CS709	AL38	AL32	AL59
IGB4337B	CS709	AL38	AL32	AL59
IGB4337C	CS709	AL38	AL32	AL59
IGB43261	CS709	AL38	AL32	AL59
IGC4005A	CS709	MO5000	—	—
IGC4005B	CS709	AL869	AL17	AL18
IGC4005C	CS709	MO5000	—	—
IGC4007	CS709	AL869	AL17	AL70
IGC4029	CS709	—	—	—
IGC4030	CS709	AL869	AL17	AL18
IGC4032C	CS709	MO5000	AL17	AL70
IGC4032E	CS709	MO5000	AL17	AL70
IGC4033A	CS709	AL869	AL17	AL70
IGC4033B	CS709	AL869	AL17	AL70
IGC4048B	CS709	AL869	AL17	AL18
IGC4048C	CS709	AL869	AL17	AL70
IGC4054B	CS709	AL869	AL17	AL18
IGC4054D	CS709	AL869	AL17	AL18
IGC4060A	CS709	AL869	AL17	AL70
IGC4060B	CS709	AL869	AL17	AL70
IGC4060C	CS709	AL869	AL17	AL70
IGC4061A	CS709	AL869	AL17	AL18
IGC4061B	CS709	AL869	AL17	AL18
IGC4061C	CS709	MO5000	—	—
IGC4062	CS709	AL869	AL17	AL18
IGC4062A	CS709	AL869	AL17	AL18
IGC4063	CS709	AL869	AL17	AL18
IGC4064	CS709	AL869	AL17	AL18
IGC4065	CS709	AL869	AL17	AL18
IGC4067	CS709	AL869	AL17	AL18
IGC4205	CS709	AL869	AL17	AL18
IGC4209B	CS709	AL869	AL17	AL70

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IGC4210A	CS709	AL869	AL17	AL18
IGC4214A	CS709	AL869	AL17	AL18
IGC4214B	CS709	AL869	AL17	AL18
IGC4216B	CS709	AL869	AL17	AL18
IGC4220A	CS709	AL869	AL17	AL18
IGC4225B	CS709	AL869	AL17	AL18
IGC4225D	CS709	AL869	AL17	AL18
IGC4225F	CS709	AL869	AL17	AL18
IGC4227A	CS709	AL869	AL17	AL18
IGC4227B	CS709	AL869	AL17	AL18
IGC4227C	CS709	AL869	AL17	AL18
IGC4227E	CS709	AL869	AL17	AL18
IGC4227F	CS709	AL869	AL17	AL18
IGC4228A	CS709	AL869	AL17	AL18
IGC4236A	CS709	AL869	AL17	AL18
IGC4236B	CS709	AL869	AL17	AL18
IGC4236C	CS709	AL869	AL17	AL18
IGC4238	CS709	AL869	AL17	AL18
IGC4240B	CS709	AL869	AL17	AL18
IGC4241	CS709	AL869	AL17	AL18
IGC4241A	CS709	AL869	AL17	AL18
IGC4246	CS709	AL869	AL17	AL18
IGC4246B	CS709	AL869	AL17	AL18
IGC4247	CS709	AL869	AL17	AL18
IGC4251	CS709	AL869	AL17	AL18
IGC4251B	CS709	AL869	AL17	AL18
IGC4253A	CS709	AL869	AL17	AL18
IGC4253B	CS709	AL869	AL17	AL18
IGC4259	CS709	AL869	AL17	AL18
IGC4262	CS709	AL869	AL17	AL18
IGC4264	CS709	AL869	AL17	AL70
IGC4272	CS709	AL869	AL17	AL18
IGC4272A	CS709	AL869	AL17	AL18
IGC4272A1	CS709	AL869	AL17	AL18
IGC4274	CS709	AL869	AL17	AL18
IGC4274A	CS709	AL869	AL17	AL18
IGC4275	CS709	AL869	AL17	AL18
IGC4276	CS709	AL869	AL17	AL18
IGC4277	CS709	AL869	AL17	AL18
IGC4279	CS709	AL869	AL17	AL18
IGC4279A	CS709	AL869	AL17	AL18
IGC4280A	CS709	AL869	AL17	AL18
IGC4281	CS709	AL869	AL17	AL18
IGC4281A	CS709	AL869	AL17	AL18
IGC4281B	CS709	AL869	AL17	AL18
IGC4284	CS709	—	—	—
IGC4284A	CS709	AL869	AL17	AL18
IGC4285	CS709	AL869	AL17	AL18

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IGC4285A	CS709	AL869	AL17	AL18
IGC4285B	CS709	AL869	AL17	AL18
IGC4286	CS709	AL869	AL17	AL18
IGC4287A	CS709	AL869	AL17	AL18
IGC4287B	CS709	AL869	AL17	AL18
IGC4288	CS709	AL869	AL17	AL18
IGC4294	CS709	AL869	AL17	AL18
IGC4296	CS709	AL869	AL17	AL70
IGC4401A	CS709	AL869	AL62	AL63
IGC4401C	CS709	AL869	AL62	AL63
IGC4401C1	CS709	AL869	AL62	AL63
IGC4402	CS709	AL869	AL62	AL63
IGC4402A	CS709	AL869	AL62	AL63
IGC4402A1	CS709	AL869	AL62	AL63
IGC4403	CS709	AL869	AL62	AL63
IGC4403A	CS709	AL869	AL62	AL63
IGC4403A1	CS709	AL869	AL62	AL63
IGC4404A	CS709	AL869	AL62	—
IGC4404A1	CS709	AL869	AL62	—
IGC4406	CS709	AL869	AL62	AL63
IGC4406A	CS709	AL869	AL62	AL63
IGC4406A1	CS709	AL869	AL62	AL63
IGC4407	CS709	AL869	AL62	AL63
IGC4407A	CS709	AL869	AL62	AL63
IGC4407A1	CS709	AL869	AL62	AL63
IGC4407B	CS709	AL869	AL62	AL63
IGC4407B1	CS709	AL869	AL62	AL63
IGC4407C	CS709	AL869	AL62	AL63
IGC4407C1	CS709	AL869	AL62	AL63
IGC4407D	CS709	AL869	AL62	AL63
IGC4407D1	CS709	AL869	AL62	AL63
IGC4407E	CS709	AL869	AL62	AL63
IGC4407E1	CS709	AL869	AL62	AL63
IGC4408	CS709	AL869	AL62	AL63
IGC4409A	CS709	AL869	AL62	—
IGC4410	CS709	AL869	AL62	—
IGC4411	CS709	AL869	AL62	—
IGC4413	CS709	AL869	AL62	AL63
IGC4414	CS709	AL869	AL62	—
IGC4415	CS709	AL869	AL62	—
IGC4417	CS709	AL869	AL62	AL63
IGC4418	CS709	AL869	AL62	AL63
IGC4501	CS725A	AL869	AL62	AL63
IGC4502A1	CS725A	AL869	AL62	AL63
IGC4503	CS725A	AL869	AL62	AL63
IGC4505	CS725A	AL869	AL62	AL63
IGC4506	CS725A	AL869	AL62	AL63
IGC4508A1	CS725A	AL869	AL62	AL63

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IGC4508B1	CS725A	AL869	AL62	AL63
IGC4512	CS725A	AL869	AL62	AL63
IGC4513	CS725A	AL869	AL62	AL63
IGC4514	CS725A	AL869	AL62	AL63
IGC4515A1	CS725A	AL869	AL62	AL63
IGC4517A1	CS725A	AL869	AL62	AL63
IGC4518A1	CS725A	AL869	AL62	AL63
IGC4601A	CS709	—	—	—
IGC4601A1	CS709	AL869	AL17	AL18
IGC4601A2	CS709	AL869	AL17	AL18
IGC4602	CS709	AL869	AL17	AL18
IGC4604	CS709	AL869	AL17	AL70
IGC4605	CS709	AL869	AL17	AL70
IGC4606	CS709	AL869	AL17	AL18
IGC4606A	CS709	AL869	AL17	AL18
IGC4607	CS709	AL869	AL17	AL18
IGC4608	CS709	AL869	AL17	AL18
IGC4701	CS725A	AL869	AL62	AL63
IGC4702A	CS725A	AL869	AL62	AL63
IGC4703A	CS725A	AL869	AL62	AL63
IGC4703A1	CS725A	AL869	AL62	AL63
IGC4705	CS725A	AL869	AL69	AL70
IGC4710A1	CS725A	AL869	AL62	AL63
IGC4711	CS725A	MO5000	AL62	—
IGC4713A	CS725A	MO5000	AL62	—
IGC4721	CS725A	AL869	AL62	AL63
IGC4723M	CS725A	AL869	AL62	AL63
IGC4724M	CS725A	AL869	AL62	AL63
IGC4801	CS725A	AL869	AL62	AL63
IGC4802	CS725A	AL869	AL62	AL63
IGC4805	CS725A	AL869	AL62	AL63
IGC4806	CS725A	AL869	AL62	—
IGC4807A	CS725A	AL869	AL62	AL131
IGC4808A	CS725A	AL869	AL62	AL63
IGC4810	CS725A	AL869	AL62	AL131
IGC4811	CS725A	MO5000	AL62	AL63
IGC4904	CS725A	AL869	AL62	AL63
IGC4905	CS725A	AL869	AL62	AL63
IGC4905A	CS725A	AL869	AL62	AL63
IGC4907	CS725A	AL869	AL62	AL63
IGC4908	CS725A	AL869	AL62	AL63
IGC4908A	CS725A	AL869	AL62	AL63
IGC4909A	CS725A	—	AL62	AL63
IGC4909A1	CS725A	AL869	AL62	AL63
IGC4912	CS725A	AL869	AL62	AL63
IGC4913	CS725A	AL869	AL62	AL63
IGC4914	CS725A	AL869	AL62	AL63
IGC4914A	CS725A	AL869	AL62	AL63

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IGC4914B	CS725A	AL869	AL62	AL63
IGC5001	CS725A	AL869	AL62	AL63
IGC5001A	CS725A	AL869	AL62	AL63
IGC5001B	CS725A	AL869	AL62	AL63
IGC5001C	CS725A	AL869	AL62	AL63
IGC5001D	CS725A	AL869	AL62	AL63
IGC5501A	CS725A	AL869	AL62	AL63
IGC6001A	CS725A	AL869	AL62	AL63
IGC6001B	CS725A	AL869	AL62	AL63
IGC6001C	CS725A	AL869	AL62	AL63
IGC6001E	CS725A	AL869	AL62	AL63
IGC6001G	CS725A	AL869	AL62	AL63
IGC6001S	CS725A	AL869	AL62	AL63
IGC6001SERIES	CS725A	MO5000	AL62	AL63
IGC6001W	CS725A	AL869	AL62	AL63
IGC6002SERIES	CS725A	MO5000	AL62	AL63
IGC6003B	CS725A	AL869	AL69	AL70
IGC6003C	CS725A	AL869	AL69	AL70
IGC6005B	CS725A	AL869	AL62	AL131
IGC42791	CS709	AL869	AL17	AL18
IGC44011	CS709	AL869	AL62	AL63
IGC44021	CS709	AL869	AL62	AL63
IGC44031	CS709	AL869	AL62	AL63
IGC44061	CS709	AL869	AL62	AL63
IGC44062	CS709	AL869	AL62	AL63
IGC44071	CS709	AL869	AL62	AL63
IGC44081	CS709	AL869	AL62	AL63
IGC44141	CS709	AL869	AL62	—
IGC45012	CS725A	AL869	AL62	AL63
IGC45021	CS725A	AL869	AL62	AL63
IGC45061	CS725A	AL869	AL62	AL63
IGC45081	CS725A	AL869	AL62	AL63
IGC45101M	CS725A	MO5000	AL62	—
IGC45111M	CS725A	MO5000	AL62	—
IGC45151	CS725A	AL869	AL62	AL63
IGC45161	CS725A	AL869	AL62	AL63
IGC45171	CS725A	AL869	AL62	AL63
IGC45181	CS725A	AL869	AL62	AL63
IGC46011	CS709	AL869	AL17	AL18
IGC46012	CS709	AL869	AL17	AL18
IGC47011	CS725A	AL869	AL62	AL63
IGC47041	CS725A	AL869	AL62	AL63
IGC47101	CS725A	AL869	AL62	AL63
IGC47102	CS725A	AL869	AL62	AL63
IGC47211	CS725A	AL869	AL62	AL63
IGC47231M	CS725A	AL869	AL62	AL63
IGC47241M	CS725A	AL869	AL62	AL63
IGC47251M	CS725A	AL869	AL62	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IGC60012L	CS725A	AL869	AL62	AL63
IGC60021AC ...	CS725A	AL869	AL62	AL63
IGC60021AE ...	CS725A	AL869	AL62	AL63
IGC60021AH ...	CS725A	AL869	AL62	AL63
IGC60021E	CS725A	AL869	AL62	AL63
IGC60021T	CS725A	—	AL62	AL63
IGC60021V	CS725A	AL869	AL62	AL63
IGC60041	CS725A	AL869	AL69	AL70
IGC60052A	CS725A	AL869	AL62	AL131
IGC60052B	CS725A	AL869	AL62	AL131
IGC60061	CS725A	AL869	AL62	—
IGC60101B	CS725A	AL869	AL62	AL63
IGC60101C	CS725A	AL869	AL62	AL63
IGC60101D	CS725A	AL869	AL62	AL63
IGC60101E	CS725A	AL869	AL62	AL63
IGC460121	CS709	MO5000	—	—
IGC600521AC ..	CS725A	—	AL62	AL63
IGE4003H1	CS725A	—	—	—
IGE4020	CS709	—	—	—
IGE4909A	CS725A	—	AL62	AL63
IGE60021S	CS725A	—	AL62	AL63
IGESERIES	CS709	AL869	—	AL66
IGH4016A	CS709	AL869	—	—
IGH4016B	CS709	AL869	—	—
IGK4101	CS709	AL869	—	—
IGK4101A	CS709	AL869	—	—
IGK4101B	CS709	AL869	—	—
IGK4102	CS709	AL869	—	—
IGP4001A	CS709	AL869	—	—
IGP4001B	CS709	AL869	—	—
IGP4002A	CS709	AL869	—	—
IGP4002B	CS709	AL869	—	—
IGP4003	CS709	AL869	—	—
IGP4006	CS709	AL869	—	—
IGP4007	CS709	AL869	AL65	AL66
IGP4007A	CS709	AL869	AL65	AL66
IGP4007B	CS709	MO5000	AL65	—
IGP4008	CS709	AL869	—	—
IGP4008B	CS709	AL869	—	—
IGP4009A	CS709	AL869	AL65	AL66
IGP4009B	CS709	AL869	AL65	AL66
IGP4401	CS709	MO5000	AL65	AL66
IGP4401A1	CS709	MO5000	AL65	AL66
IGP4402	CS709	MO5000	AL65	AL66
IGP4402A1	CS709	MO5000	AL65	AL66
IGP4402B	CS709	MO5000	AL65	AL66
IGP4402B1	CS709	MO5000	AL65	AL66
IGP4501	—	—	AL65	AL66

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IGP4501A	—	—	AL65	AL66
IGP4502	—	—	AL65	AL66
IGP4502A	—	—	AL65	AL66
IGP4502B	—	—	AL65	AL66
IGP4502C	—	—	AL65	AL66
IGP4502D	—	—	AL65	AL66
IGP4502E	—	—	AL65	AL66
IGP4504	—	—	AL65	AL66
IGP4504M	—	—	AL65	AL66
IGP44021A	CS709	MO5000	AL65	AL66
IGP45041M	—	—	AL65	AL66
IGS4001	CS709	MO5000	AL62	AL63
IGS4001A	CS709	MO5000	AL62	AL63
IGS4001A1	CS709	MO5000	AL62	AL63
IGS4002	CS709	MO5000	AL62	AL63
IGS4002A	CS709	MO5000	AL62	AL63
IGS4002A1	CS709	MO5000	AL62	AL63
IGS4003	CS709	MO5000	AL62	AL63
IGS4003A	CS709	MO5000	AL62	AL63
IGS4003B	CS709	MO5000	AL62	AL63
IGS4003C	CS709	MO5000	AL62	AL63
IGS4003C1	CS709	MO5000	AL62	AL63
IGS4006	CS709	MO5000	AL62	AL63
IGS4006A	CS709	MO5000	AL62	AL63
IGS4006A1	CS709	MO5000	AL62	AL63
IGS4007	CS709	MO5000	AL69	AL70
IGS4007A	CS709	MO5000	AL69	AL70
IGS4007B	CS709	MO5000	AL69	AL70
IGS4008	CS709	MO5000	AL62	AL63
IGS4008A	CS709	MO5000	AL62	AL63
IGS4010	CS709	MO5000	AL62	AL63
IGS4010A	CS709	MO5000	AL62	AL63
IGS4010A2	CS709	MO5000	AL62	AL63
IGS4010B	CS709	MO5000	AL62	AL63
IGS4010B2	CS709	MO5000	AL62	AL63
IGS4010C	CS709	MO5000	AL69	AL63
IGS4010C1	CS709	MO5000	AL69	AL63
IGS4011	CS709	MO5000	AL69	AL63
IGS4012	CS709	MO5000	AL62	AL63
IGS4013	CS709	MO5000	AL69	AL63
IGS4014	CS709	MO5000	AL62	AL63
IGS4015	CS709	MO5000	AL62	AL63
IGS4101A	CS725A	MO5000	AL62	AL63
IGS4101A1	CS725A	MO5000	AL62	AL63
IGS4101B	CS725A	MO5000	AL62	AL63
IGS4101B1	CS725A	MO5000	AL62	AL63
IGS4101C	CS725A	MO5000	AL62	AL63
IGS4101C1	CS725A	MO5000	AL62	AL63

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IGS4102	CS725A	MO5000	AL62	AL63
IGS4102A	CS725A	MO5000	AL62	AL63
IGS4102B	CS725A	MO5000	AL62	AL63
IGS4102C	CS725A	MO5000	AL62	AL63
IGS4102D	CS725A	MO5000	AL62	AL63
IGS4102E	CS725A	MO5000	AL62	AL63
IGS4103	CS725A	MO5000	AL62	AL63
IGS4103A	CS725A	MO5000	AL62	AL63
IGS4103B	CS725A	MO5000	AL62	AL63
IGS4103B1	CS725A	MO5000	AL62	AL63
IGS4104	CS725A	MO5000	AL62	AL63
IGS4104X	CS725A	MO5000	—	—
IGS4107	CS725A	MO5000	AL62	AL63
IGS4107A	CS725A	MO5000	AL62	AL63
IGS4107A1	CS725A	MO5000	AL62	AL63
IGS4108	CS725A	MO5000	AL62	AL63
IGS4108A	CS725A	MO5000	AL62	AL63
IGS4108B	CS725A	MO5000	AL62	AL63
IGS4108C	CS725A	MO5000	AL62	AL63
IGS4108D	CS725A	MO5000	AL62	AL63
IGS4109	CS725A	MO5000	AL62	AL63
IGS4110	CS725A	MO5000	AL62	AL63
IGS4111	CS725A	MO5000	AL62	AL63
IGS4112	CS725A	MO5000	AL62	AL63
IGS4113	CS725A	MO5000	AL62	AL63
IGS4114	CS725A	MO5000	AL62	AL63
IGS4115	CS725A	MO5000	AL62	AL63
IGS4116	—	—	AL62	AL63
IGS4117	CS725A	MO5000	AL62	AL63
IGS4201	—	—	AL62	AL63
IGS4202	CS725A	MO5000	AL62	AL63
IGS4202A	CS725A	MO5000	AL62	AL63
IGS4202B	CS725A	MO5000	AL62	AL63
IGS4202C1	CS725A	MO5000	AL62	AL63
IGS4203	CS725A	MO5000	AL62	AL63
IGS4203A	CS725A	MO5000	AL62	AL63
IGS4203B	CS725A	MO5000	AL62	AL63
IGS4203C	CS725A	MO5000	AL62	AL63
IGS4203C1	CS725A	MO5000	AL62	AL63
IGS4204	CS725A	MO5000	AL62	AL63
IGS4205	CS725A	MO5000	AL62	AL63
IGS4205A	CS725A	MO5000	AL62	AL63
IGS4205B	CS725A	MO5000	AL62	AL63
IGS4207A1	CS725A	MO5000	AL62	AL63
IGS4207B1	CS725A	MO5000	AL62	AL63
IGS4208A1	CS725A	MO5000	AL62	AL63
IGS4208B1	CS725A	MO5000	AL62	AL63
IGS4211	—	—	AL62	AL63

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IGS4213A1	CS725A	MO5000	AL62	AL63
IGS4214	—	—	AL62	AL63
IGS4703A1	CS725A	—	AL62	AL63
IGS40031	CS709	MO5000	AL62	AL63
IGS40061	CS709	MO5000	AL62	AL63
IGS40101	CS709	MO5000	AL62	AL63
IGS40141	CS709	MO5000	AL62	AL63
IGS40151	CS709	MO5000	AL62	AL63
IGS41021	CS725A	MO5000	AL62	AL63
IGS41022	CS725A	MO5000	AL62	AL63
IGS41081	CS725A	MO5000	AL62	AL63
IGS41091	CS725A	MO5000	AL62	AL63
IGS41101	CS725A	MO5000	AL62	AL63
IGS41111	CS725A	MO5000	AL62	AL63
IGS41121	CS725A	MO5000	AL62	AL63
IGS41131	CS725A	MO5000	AL62	AL63
IGS41141	CS725A	MO5000	AL62	AL63
IGS41171	CS725A	MO5000	AL62	AL63
IGS42011	—	—	AL62	AL63
IGS42041	CS725A	MO5000	AL62	AL63
IGS42071	CS725A	MO5000	AL62	AL63
IGS42081	CS725A	MO5000	AL62	AL63
IGS42131	CS725A	MO5000	AL62	AL63
IGS47171	CS725A	—	AL62	AL63
IGSW4129	CS709	AL38	—	AL59
IGSW4129	CS709	AL38	—	AL91
IGT4001	CS709	MO5000	AL65	AL66
IGT4001A	CS709	MO5000	AL65	AL66
IGT4001B	CS709	MO5000	AL65	AL66
IGT4001C	CS709	MO5000	AL65	AL66
IGT4001D	CS709	MO5000	AL65	AL66
IGT4001E	CS709	MO5000	AL65	AL66
IGT4001F	CS709	MO5000	AL65	AL66
IGT4001G	CS709	MO5000	AL65	AL66
IGT4001H	CS709	MO5000	AL65	AL66
IGT4001I	CS709	MO5000	AL65	AL66
IGT4001J	CS709	MO5000	AL65	AL66
IGT4001K	CS709	MO5000	AL65	AL66
IGT4003	CS709	MO5000	AL65	AL66
IGT4003A	CS709	MO5000	AL65	AL66
IGT4004	CS709	MO5000	AL65	AL66
IGT4005	CS709	MO5000	—	—
IGT4006	CS709	MO5000	AL65	—
IGT4006A	CS709	MO5000	AL65	—
IGT4007	CS709	MO5000	AL65	AL66
IGT4007A	CS709	MO5000	AL65	AL66
IGT4008	CS709	MO5000	—	—
IGT4101	—	—	AL65	AL66

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IGT4101A	—	—	AL65	AL66
IGT4101B	—	—	AL65	AL66
IGT4102	CS709	MO5000	AL65	AL66
IGT4103	—	—	AL65	AL66
IGT4103A	—	—	AL65	AL66
IGT4103A1	—	—	AL65	AL66
IGT4104	—	—	AL65	AL66
IGT4201	—	—	AL65	AL66
IGT4201A	—	—	AL65	AL66
IGT4201B	—	—	AL65	AL66
IGT4201GB	—	—	AL65	—
IGT4202	—	—	AL65	AL66
IGT4203	—	—	AL65	AL66
IGT4204A1	—	—	AL65	AL66
IGT4204B1	—	—	AL65	AL66
IGT40011	CS709	MO5000	AL65	AL66
IGT41011	—	—	AL65	AL66
IGT41012	—	—	AL65	AL66
IGT42011	—	—	AL65	AL66
IGT43021	—	—	AL65	AL66
IGW411A	CS709	AL38	AL32	AL59
IGW411A	CS709	AL38	AL32	AL91
IGW411B	CS709	AL38	AL32	AL59
IGW411B	CS709	AL38	AL32	AL91
IGW411C	CS709	AL38	AL32	AL59
IGW411C	CS709	AL38	AL32	AL91
IGW4001	CS709	AL38	AL32	AL59
IGW4005	CS709	AL38	AL32	AL59
IGW4005A	CS709	AL38	AL32	AL59
IGW4005H	—	AL38	AL58	AL59
IGW4006B	CS709	AL38	AL32	AL59
IGW4006C	CS709	AL38	AL32	AL59
IGW4007	CS709	AL38	AL32	AL59
IGW4008	CS709	AL38	AL32	AL59
IGW4009A	CS709	AL38	AL32	AL59
IGW4010	CS709	AL38	AL32	AL59
IGW4011	CS709	AL38	AL32	AL59
IGW4012A	CS709	MO5000	AL32	AL59
IGW4013A	CS709	MO5000	AL32	AL59
IGW4014	CS709	AL38	AL32	AL59
IGW4014A	CS709	AL38	AL58	AL59
IGW4015	CS709	AL38	AL32	AL59
IGW4015A	CS709	AL38	AL32	AL59
IGW4016	CS709	AL38	AL32	—
IGW4017	CS709	AL38	AL32	AL59
IGW4018	CS709	MO5000	AL32	AL59
IGW4019A	CS709	MO5000	AL32	—
IGW4020	CS709	AL38	AL32	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IGW4022	CS709	AL38	AL32	—
IGW4023	CS709	AL38	AL32	AL59
IGW4023A	CS709	AL38	AL32	AL59
IGW4024	CS709	AL38	AL32	AL59
IGW4025	CS709	AL38	AL32	—
IGW4025B	CS709	AL38	AL32	—
IGW4026	CS709	AL38	AL32	AL59
IGW4028	CS709	AL38	AL32	—
IGW4029	CS709	AL38	AL32	AL354
IGW4030	CS709	AL38	AL32	AL143
IGW4031A	CS709	AL38	AL32	AL59
IGW4032	CS709	AL38	AL32	AL59
IGW4032A	CS709	AL38	AL32	AL59
IGW4032B	CS709	AL38	AL32	AL59
IGW4033	CS709	AL38	AL32	AL59
IGW4034A	CS709	AL38	AL32	—
IGW4034B	CS709	AL38	AL32	—
IGW4034C	CS709	AL38	AL32	—
IGW4035	CS709	MO5000	AL32	—
IGW4036	CS709	MO5000	AL32	AL59
IGW4037	CS709	AL38	AL32	AL59
IGW4038	CS709	AL38	AL32	AL59
IGW4038A	CS709	AL38	AL32	AL59
IGW4040B	CS709	AL38	AL32	AL59
IGW4043A	CS709	AL38	AL32	—
IGW4044	CS709	AL38	AL32	—
IGW4044A	CS709	AL38	AL32	—
IGW4044B	CS709	AL38	AL32	—
IGW4045A	CS709	AL38	AL32	AL59
IGW4046	CS709	MO5000	AL32	AL143
IGW4047A	CS709	MO5000	AL32	—
IGW4047B	CS709	MO5000	AL32	—
IGW4048A	CS709	MO5000	AL32	AL143
IGW4049	CS709	MO5000	AL32	AL143
IGW4050	CS709	MO5000	AL32	—
IGW4051	CS709	MO5000	AL32	AL143
IGW4052	CS709	MO5000	AL32	—
IGW4053	CS709	MO5000	—	—
IGW4054A	CS709	MO5000	AL32	—
IGW4055	CS709	MO5000	AL32	—
IGW4056	CS709	AL38	AL32	AL91
IGW4056A	CS709	AL38	AL32	AL91
IGW4056B	CS709	AL38	AL32	AL91
IGW4056C	CS709	AL38	AL32	AL91
IGW4056D	CS709	AL38	AL32	AL91
IGW4101	CS709	AL38	AL32	AL59
IGW4103A	CS709	MO5000	AL32	AL59
IGW4104A	CS709	MO5000	AL32	AL59

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IGW4105A	CS709	AL38	AL32	—
IGW4105B	CS709	AL38	AL32	—
IGW4105C	CS709	AL38	AL32	—
IGW4107	CS709	AL38	AL32	AL59
IGW4107A	CS709	AL38	AL32	AL59
IGW4107B	CS709	AL38	AL58	AL59
IGW4107C	CS709	AL38	AL58	AL59
IGW4108	CS709	AL38	AL32	AL59
IGW4108A	CS709	AL38	AL32	AL59
IGW4108B	CS709	AL38	AL32	AL59
IGW4108C	CS709	AL38	AL32	AL59
IGW4108E	CS709	AL38	AL32	AL59
IGW4110	CS709	AL38	AL32	AL59
IGW4110A	CS709	AL38	AL32	AL59
IGW4110B	CS709	AL38	AL32	AL59
IGW4110C	CS709	AL38	AL32	AL59
IGW4111	CS709	AL38	AL32	AL59
IGW4112	CS709	AL38	AL32	AL354
IGW4112A	CS709	AL38	AL32	AL354
IGW4113	CS709	AL38	AL32	AL59
IGW4113A	CS709	AL38	AL32	AL59
IGW4113C	CS709	AL38	AL32	AL59
IGW4113D	CS709	AL38	AL32	AL59
IGW4113E	CS709	AL38	AL32	AL59
IGW4113M	CS709	AL38	AL32	AL59
IGW4114	CS709	AL38	AL32	AL59
IGW4114A	CS709	AL38	AL32	AL59
IGW4114B	CS709	AL38	AL32	AL59
IGW4114C	CS709	AL38	AL32	AL59
IGW4114D	CS709	AL38	AL32	AL59
IGW4114E	CS709	AL38	AL32	AL59
IGW4115	CS709	AL38	AL32	AL91
IGW4116	CS709	AL38	AL32	AL91
IGW4116A	CS709	AL38	AL58	AL91
IGW4116B	CS709	AL38	AL58	AL91
IGW4116C	CS709	AL38	AL58	AL91
IGW4117	CS709	AL38	AL32	AL91
IGW4118	CS709	AL38	AL32	AL91
IGW4118A	CS709	AL38	AL58	AL91
IGW4119	CS709	AL38	AL32	AL59
IGW4119A	CS709	AL38	AL58	AL59
IGW4119B	CS709	AL38	AL58	AL59
IGW4119C	CS709	AL38	AL58	AL59
IGW4120	CS709	AL38	AL32	AL91
IGW4120A	CS709	AL38	AL32	AL91
IGW4120B	CS709	AL38	AL32	AL91
IGW4120B2	CS709	AL38	AL32	AL91
IGW4120B2C	CS709	AL38	AL32	AL91

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
IGW4120C	CS709	AL38	AL32	AL91
IGW4120C2	CS709	AL38	AL32	AL91
IGW4120D	CS709	AL38	AL32	AL91
IGW4120E	CS709	AL38	AL32	AL91
IGW4120F	CS709	AL38	AL32	AL91
IGW4120G	CS709	AL38	AL32	AL91
IGW4120H	CS709	AL38	AL32	AL91
IGW4120I	CS709	AL38	AL32	AL91
IGW4120J	CS709	AL38	AL32	AL91
IGW4120K	CS709	AL38	AL32	AL91
IGW4120L	CS709	AL38	AL32	AL91
IGW4120M	CS709	AL38	AL32	AL91
IGW4120N	CS709	AL38	AL32	AL91
IGW4120O	CS709	AL38	AL32	AL91
IGW4120P	CS709	AL38	AL32	AL91
IGW4120Q	CS709	AL38	AL32	AL91
IGW4120R	CS709	AL38	AL32	AL91
IGW4120S	CS709	AL38	AL32	AL91
IGW4121	CS709	AL38	AL32	AL91
IGW4121A	CS709	AL38	AL32	AL91
IGW4122	CS709	AL38	AL32	—
IGW4123	CS709	AL38	AL32	AL59
IGW4123A	CS709	AL38	AL32	AL59
IGW4123B	CS709	AL38	AL32	AL59
IGW4124	CS709	AL38	AL32	AL59
IGW4125A	—	—	AL32	AL59
IGW4126A	—	—	AL59	AL59
IGW4127	CS709	AL38	AL32	AL91
IGW4129	CS709	AL38	AL32	AL91
IGW4129A	CS709	AL38	AL32	AL91
IGW4129A1	CS709	AL38	AL32	AL91
IGW4129A2	CS709	AL38	AL32	AL91
IGW4130A	CS709	AL38	AL32	AL91
IGW4130B	CS709	AL38	AL32	AL91
IGW4130C	CS709	AL38	AL32	AL91
IGW4130D	CS709	AL38	AL32	AL91
IGW4131	CS709	AL38	AL32	AL59
IGW4132	CS709	AL38	AL32	AL59
IGW4134	CS709	AL38	AL32	AL91
IGW4136	CS709	AL38	AL32	AL354
IGW4136A	CS709	AL38	AL32	AL354
IGW4137	CS709	AL38	AL32	AL91
IGW4138	CS709	AL38	AL32	AL91
IGW4139	CS709	AL38	AL32	AL354
IGW4139A	CS709	AL38	AL32	AL354
IGW4139B	CS709	AL38	AL32	AL354
IGW4139C	CS709	AL38	AL32	AL354
IGW4139D	CS709	AL38	AL32	AL354

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Unit No	Contact Assembly	Condenser	Rotor	Cap
IGW4140	CS709	AL38	AL32	AL91	IGW4189A	CS709	AL38	AL32	AL91
IGW4142	CS709	AL38	AL32	AL143	IGW4190	CS709	AL38	AL32	AL59
IGW4142A	CS709	AL38	AL32	AL143	IGW4191A	CS709	AL38	AL32	—
IGW4143	CS709	AL38	AL32	AL59	IGW4192	CS709	AL38	AL32	AL91
IGW4143A	CS709	AL38	AL32	AL59	IGW4194	CS709	AL38	AL32	AL59
IGW4146	CS709	AL38	AL32	AL143	IGW4195	CS709	AL38	AL32	AL354
IGW4147	CS709	—	AL32	AL59	IGW4196	CS709	AL38	AL32	AL59
IGW4149	CS709	AL38	AL32	AL59	IGW4198	CS709	AL38	AL32	AL354
IGW4149A	CS709	AL38	AL32	AL59	IGW4199A	CS709	AL38	AL32	AL143
IGW4152	CS709	AL38	AL32	AL91	IGW4199B	CS709	AL38	AL32	AL143
IGW4152A	CS709	AL38	AL32	AL91	IGW4199C	CS709	AL38	AL32	AL143
IGW4152B	CS709	AL38	AL32	AL91	IGW4201A	—	—	AL32	AL59
IGW4152C	CS709	AL38	AL32	AL91	IGW4202A	—	—	AL32	AL59
IGW4154	CS709	AL38	AL32	AL59	IGW4203	—	—	AL32	AL59
IGW4156	CS709	AL38	AL32	AL91	IGW4203A	—	—	AL32	AL59
IGW4156A	CS709	AL38	AL32	AL91	IGW4204	—	—	AL32	AL59
IGW4156B	CS709	AL38	AL32	AL91	IGW4301	CS709	AL38	AL32	—
IGW4156C	CS709	AL38	AL32	AL91	IGW4302	CS709	AL38	AL32	—
IGW4156D	CS709	AL38	AL32	AL91	IGW4303	CS709	AL38	AL32	—
IGW4157	CS709	AL38	AL32	AL91	IGW4401	CS709	AL38	AL32	AL91
IGW4157A	CS709	AL38	AL32	AL91	IGW4402	CS709	AL38	—	—
IGW4159A	CS709	AL38	AL32	AL352	IGW4403	CS709	AL38	AL32	—
IGW4159A1	CS709	AL38	AL32	AL352	IGW4403A	CS709	AL38	AL32	—
IGW4161	CS709	AL38	AL32	AL91	IGW4405	CS709	AL38	—	—
IGW4162A	CS709	AL38	AL32	AL59	IGW4406	CS709	AL38	AL32	—
IGW4163A	CS709	AL38	AL32	AL143	IGW4406A	CS709	AL38	AL32	—
IGW4163B	CS709	AL38	AL32	AL143	IGW4406E	CS709	AL38	AL32	—
IGW4164	CS709	AL38	AL32	AL354	IGW4407	CS709	AL38	AL62	—
IGW4167	CS709	AL38	—	—	IGW4408	CS709	AL38	AL62	—
IGW4168A	CS709	AL38	AL32	AL143	IGW4409	CS709	AL38	AL32	AL91
IGW4168B	CS709	AL38	AL32	AL143	IGW4409A	CS709	AL38	AL32	AL91
IGW4169A	CS709	AL38	AL32	AL59	IGW4409B	CS709	AL38	AL32	AL91
IGW4175A	CS709	AL38	AL32	AL91	IGW4410	CS709	MO5000	—	—
IGW4175B	CS709	AL38	AL32	AL91	IGW4411	CS709	AL38	AL62	—
IGW4176	CS709	AL38	AL32	—	IGW4412	CS709	AL38	AL32	AL157
IGW4176A	CS709	AL38	AL32	—	IGW4501	CS709	AL38	AL32	—
IGW4178	CS709	AL38	AL32	—	IGW4502	CS709	AL38	AL32	—
IGW4178A	CS709	AL38	AL32	—	IGW41201	CS709	AL38	AL32	AL91
IGW4179	CS709	AL38	—	—	IGW41641	CS709	AL38	AL32	AL354
IGW4181	CS709	AL38	AL32	AL91	IGW41671	CS709	AL38	—	—
IGW4181A	CS709	AL38	AL32	—	IGW41771	CS709	AL38	AL32	AL91
IGW4181B	CS709	AL38	AL32	—	IGW60012	CS709	AL38	AL32	AL59
IGW4181C	CS709	AL38	AL32	—	IGW60032	CS709	AL38	AL32	AL91
IGW4183	CS709	AL38	AL32	AL59	IGW60032A	CS709	AL38	AL32	AL91
IGW4184	CS709	MO5000	AL32	AL59	IGW60032D	CS709	AL38	AL32	AL91
IGW4184A	CS709	MO5000	AL32	AL59	IGW60032E	CS709	AL38	AL32	AL91
IGW4187A	CS709	AL38	AL32	AL354	IGW60033A	CS709	AL38	AL32	AL91
IGW4189	CS709	AL38	AL32	AL91	IGZSERIES	CS709	—	—	—
(continued on next column)					ITA4003A	CS719A	AL869	AL107	AL106

BOSCH

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
VE4CL402T	CS321	—	—	—	—
VJ2B1Z	CS301	EP147	—	—	—
VJ2BL15	CS321	EP147	—	—	—
VJ2BL3	CS321	EP147	—	—	—
VJ3BR1T	CS321	EP147	EP143	—	—
VJ3BR2	CS321	EP147	EP143	—	—
VJ3BR4	CS321	EP147	EP143	—	—
VJ4(R)BR17	CS321	EP147	—	—	—
VJ4BL15	CS321	EP147	—	EP131	—
VJ4BR16	CS321	EP147	—	—	—
VJ(R)4BR15	CS321	EP147	EP143	EP131	—
VJR4/2BR21	CS321	EP147	—	—	—
VJR4BL23	CS303	—	EP143	EP131	—
VJR4BL26	CS303	—	EP143	EP131	—
VJR6BR60	CS321	EP147	EP143	EP269	—
VJU4BR17	CS301	—	—	EP131	—
VJU4BR6	CS301	—	—	EP131	—
VJU6BR30MS	CS301	—	—	EP269	—
VJU(R)4BL10	CS303	—	—	EP131	—
VJU(R)4BL15	CS303	—	—	EP131	—
ZV/JCUR4L1	CS303	—	—	EP131	—
ZV/LBUR8R1	—	—	EP143	—	—
ZV/PAU4R2M.K . . .	CS305	EP147	EP142	EP133	—
ZV/PAU4R5	CS305	EP147	EP142	EP133	—
ZV/PAUR4R1M.K . .	CS305	EP147	EP142	EP133	—
ZV/PBR632	CS301	EP147	—	EP269	—
ZV/SUR4R1	—	—	—	EP131	—
2BL5	CS321	EP147	—	—	—
2BL7	CS321	EP147	—	—	—
3BR1	CS321	EP147	—	—	—
3BR1T	CS301	—	—	—	—
3BR2	CS321	EP147	—	—	—
3BR2T	CS301	—	—	—	—
3BR4	CS321	EP147	—	—	—
3BR8	CS321	EP147	—	—	—
4/BR13T	CS303	—	—	—	—
4BBS383	CS321	EP125	—	—	—
4BL10	—	—	—	EP131	—
4BL15	CS303	—	—	EP131	—
4BL23	CS321	—	—	EP131	—
4BL24	CS303	—	—	EP131	—
4BL26	CS321	—	—	EP131	—
4BL29	CS303	—	—	EP131	—
4BL31	CS303	—	—	EP131	—
4BL32T	CS321	EP147	—	—	—
4BL33	CS303	EP147	—	EP131	—
4BL33M.K	—	—	—	EP131	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
4BL34K	—	—	—	EP131	—
4BL34M	—	—	—	EP131	—
4BL34M.K.	—	—	—	EP131	—
4BL35	CS303	—	—	EP131	—
4BL36K	—	—	—	EP131	—
4BL36M	—	—	—	EP131	—
4BL36M.K.	—	—	—	EP131	—
4BR11K	CS321	EP148	—	EP131	—
4BR11M	CS321	EP148	—	EP131	—
4BR11M.K.	CS321	—	—	EP131	—
4BR13T	CS303	—	—	—	—
4BR15	CS321	EP147	—	EP131	—
4BR17	CS301	—	—	EP131	—
4BR17M.K	CS321	EP147	—	—	—
4BR18	CS301	—	—	EP131	—
4BR18M.K	CS321	EP147	—	EP131	—
4BR18M.S	CS301	EP148	—	EP131	—
4BR19	CS321	EP147	—	EP131	—
4BR1M.K	CS301	EP148	—	EP131	—
4BR1TM.K.	CS301	—	—	EP131	—
4BR20	CS301	—	—	EP131	—
4BR227M.K.	CS301	—	—	EP131	—
4BR227M.R.	CS301	—	—	EP131	—
4BR22K	CS321	EP147	—	EP131	—
4BR22M	CS321	EP147	—	EP131	—
4BR22M.K.	CS321	EP147	—	EP131	—
4BR24M.K	CS321	EP147	—	EP131	—
4BR25M.K	CS321	EP147	—	EP131	—
4BR26M.S	CS301	EP147	—	EP131	—
4BR27M.K	CS301	EP148	—	EP131	—
4BR27M.K.	CS321	EP147	—	EP131	—
4BR27M.R	CS301	EP148	—	EP131	—
4BR28M.K	CS301	EP147	—	EP131	—
4BR28T	CS301	EP147	—	EP131	—
4BR29T.K	—	—	—	EP131	—
4BR29TM.K.	—	—	—	EP131	—
4BR30	CS321	EP147	—	—	—
4BR37M.S	CS301	EP147	EP143	EP131	—
4BR41M.K	CS301	EP147	—	EP131	—
4BR44M.S	CS301	EP147	EP143	EP131	—
4BR46M.S	CS301	EP147	EP143	EP131	—
4BR48M.S	CS301	EP147	—	EP131	—
4BR50	CS301	EP147	—	EP131	—
4BR6	CS301	—	—	EP131	—
4BR8M.K	CS301	—	—	EP131	—
4BR8M.K.	CS321	EP125	—	EP131	—
4BR9	CS321	EP147	—	EP131	—
4BRS383	CS321	EP125	—	—	—

(continued on next page)

BOSCH (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control	Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
4CL402	CS321	—	—	—	—	0231112366	CS313	EP250	EP143	EP131	—
6BR21TM.K	CS301	EP147	—	EP131	—	0231115002	CS303	EP147	EP143	EP131	—
6BR24	CS301	—	—	—	—	0231115003	CS313P	EP250	EP143	EP131	—
6BR26M.K.T	CS301	—	—	—	—	0231115005	CS313P	EP446	—	EP131	—
6BR26TM.K	CS301	EP147	—	EP131	—	0231115006	CS301	—	—	EP131	—
6BR32TK	CS301	EP148	—	—	—	0231115009	CS301	—	—	EP131	—
6BR32TM	CS301	EP148	—	—	—	0231115017	CS301	—	—	EP131	—
6BR32TM.K	CS301	—	—	—	—	0231115022	CS303	—	—	EP131	—
6BR38M.K	CS301	EP147	—	—	—	0231115026	CS301	EP147	—	EP131	—
6BR45TM.K	CS301	EP147	—	—	—	0231115027	CS301	EP147	—	EP131	—
6BR47M.K	CS301	EP147	—	—	—	0231115028	CS301	EP147	—	EP131	—
6BR49M.K	CS301	EP147	—	—	—	0231115029	CS301	EP147	—	EP131	—
6BR49TM.K	CS301	EP147	—	EP131	—	0231115030	CS303	—	—	EP131	—
6BR49TM.S	CS301	EP147	—	—	—	0231115032	CS303	—	—	EP131	—
6BR62	CS321	EP147	—	—	—	0231115034	CS303	—	—	EP131	—
6BR6Z	CS321	EP147	—	—	—	0231115036	CS303	—	—	EP131	—
71HMACA	CS313P	—	—	EP274	—	0231115038	CS303	—	—	EP131	—
412CR404	CS321	—	—	—	—	0231115040	CS301	EP125	—	EP131	—
462657	CS314	EP284	—	EP274	—	0231115042	CS303	—	—	EP131	—
022905205S	CS313P	EP433	—	EP274	—	0231115043	CS303	EP147	—	EP131	—
047905205B	CS313P	—	—	EP274	—	0231115045	CS301	EP147	—	EP131	—
049905205A	CS313P	—	—	EP274	VC1309	0231115046	CS323	EP147	—	—	—
056905205C	CS313P	EP431	—	EP274	—	0231115048	CS301	EP147	—	EP131	—
0231110011	CS321	—	—	EP131	—	0231115049	CS301	EP147	—	EP145	—
0231110013	CS301	—	—	EP131	—	0231115051	CS303	EP147	EP278	EP131	—
0231110018	CS321	—	—	EP131	—	0231115052	CS301	EP147	—	EP131	—
0231110040	CS321	EP147	—	EP131	—	0231115056	CS313P	EP259	EP146	EP145	—
0231110041	CS321	EP147	—	EP131	—	0231115058	CS313P	—	EP146	EP145	—
0231110044	CS313P	EP446	EP143	EP131	—	0231115060	CS303	—	—	EP131	—
0231111034	CS321	EP147	—	EP269	—	0231115061	CS314	EP446	EP278	EP131	—
0231112003	CS313	EP250	EP143	EP269	—	0231115065	CS314	—	EP278	EP131	—
0231112006	CS313	EP250	EP143	EP131	—	0231115067	CS313	EP292	EP143	EP131	—
0231112024	CS301	—	—	EP131	—	0231115068	CS313	EP292	EP143	EP131	—
0231112031	CS301	—	—	EP131	—	0231115071	CS313	EP446	EP143	EP131	—
0231112043	CS301	EP147	EP143	EP131	—	0231115072	CS313	EP446	EP143	EP131	—
0231112046	CS303	EP147	—	EP131	—	0231115075	CS313	EP284	EP146	—	—
0231112053	CS301	EP147	—	EP131	—	0231115077	CS313	EP259	EP278	EP274	—
0231112054	CS301	EP147	EP143	EP131	—	0231115078	CS313	EP259	EP278	EP274	—
0231112056	CS301	EP147	EP143	EP131	—	0231115079	CS313	EP259	EP278	EP274	—
0231112059	CS323	EP147	—	EP131	—	0231115081	CS313	EP446	EP143	EP131	—
0231112060	CS323	EP147	—	EP131	—	0231115086	CS314	—	EP278	EP131	—
0231112062	CS301	EP147	EP143	EP131	—	0231115089	CS314	EP293	EP278	EP131	—
0231112064	CS301	EP147	—	EP131	—	0231115090	CS314	—	EP278	EP131	—
0231112065	CS301	EP147	—	EP131	—	0231115093	CS314	EP292	EP278	EP131	—
0231112066	CS313P	EP250	EP143	EP131	—	0231115096	CS313	EP291	EP146	EP145	—
0231112068	CS313P	EP446	EP143	EP131	—	0231116011	CS301	—	—	EP269	—
0231112069	CS313P	EP290	EP143	EP131	—	0231116013	CS301	—	—	EP269	—
0231112070	CS314	EP446	EP143	EP131	—	0231116019	CS301	—	—	EP269	—

(continued on next column)

(continued on next page)

BOSCH (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
0231116023 ...	CS301	—	—	EP269	—
0231116025 ...	CS301	EP147	EP278	EP269	—
0231116027 ...	CS301	—	—	EP269	—
0231116034 ...	CS301	EP147	—	EP269	—
0231116037 ...	CS301	EP147	—	EP269	—
0231116038 ...	CS301	EP147	—	EP269	—
0231116040 ...	CS301	EP147	—	EP269	—
0231116042 ...	CS301	EP147	—	EP269	—
0231116046 ...	CS301	EP147	—	EP269	—
0231116047 ...	CS303	EP147	—	EP269	—
0231116048 ...	CS301	EP147	—	EP269	—
0231116049 ...	CS301	EP147	—	EP269	—
0231116050 ...	CS301	EP147	—	EP269	—
0231116051 ...	CS303	EP147	EP278	EP269	—
0231116052 ...	CS301	EP147	EP278	EP269	—
0231116053 ...	CS313P	EP446	EP143	EP269	—
0231116060 ...	CS303	EP147	—	EP131	—
0231116061 ...	CS314	—	EP278	EP269	—
0231116062 ...	CS314	—	EP278	EP269	—
0231116066 ...	CS314	EP293	EP278	EP269	—
0231116067 ...	CS314	EP293	EP278	EP269	—
0231116068 ...	CS314	EP293	EP278	EP269	—
0231117007 ...	—	—	EP143	—	—
0231117009 ...	—	—	EP278	—	—
0231119002 ...	CS321	EP147	—	—	—
0231119003 ...	CS305 ⁹	EP147	—	—	—
0231119004 ...	CS305 ⁹	EP147	—	—	—
0231119008 ...	CS328	—	EP278	—	—
0231120001 ...	CS321	EP147	—	—	—
0231120003 ...	CS332	EP147	—	—	—
0231120007 ...	CS321	EP147	—	—	—
0231120014 ...	CS321	EP147	—	—	—
0231120016 ...	CS321	EP147	—	—	—
0231120018 ...	—	EP147	—	—	—
0231120020 ...	CS321	EP147	—	—	—
0231120022 ...	CS321	EP147	—	—	—
0231120023 ...	CS321	EP147	—	—	—
0231120046 ...	CS303	EP147	—	EP131	—
0231121004 ...	CS321	EP147	—	EP269	—
0231121006 ...	CS321	EP147	—	EP269	—
0231122002 ...	—	EP147	—	—	—
0231124001 ...	—	—	—	EP131	—
0231128003 ...	CS313P	—	—	—	—
0231129001 ...	CS321	EP147	—	EP131	—
0231129002 ...	CS321	EP147	—	EP131	—
0231129007 ...	CS321	—	—	EP131	—
0231129009 ...	CS321	EP147	—	EP131	—
0231129010 ...	CS321	EP147	—	EP131	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
0231129012 ...	CS321	EP147	—	EP131	—
0231129015 ...	—	—	—	EP131	—
0231129017 ...	CS321	EP147	—	EP131	—
0231129019 ...	CS321	EP125	—	EP131	—
0231129020 ...	CS321	EP125	—	EP131	—
0231129022 ...	CS321	EP147	—	EP131	—
0231129023 ...	CS321	EP147	—	EP131	—
0231129026 ...	CS313P	—	—	EP131	—
0231129028 ...	CS313P	—	EP143	—	—
0231129029 ...	CS313P	—	EP143	EP131	—
0231129031 ...	CS321	EP147	—	EP131	—
0231129032 ...	CS321	EP147	—	EP131	—
0231129033 ...	CS313P	—	—	EP131	—
0231129034 ...	CS321	EP446	—	EP131	—
0231129036 ...	CS313P	EP446	EP143	EP274	—
0231129037 ...	CS313P	EP446	EP143	EP131	—
0231130001 ...	—	—	—	EP142	—
0231137001 ...	—	—	—	EP131	—
0231137002 ...	CS315	—	EP146	—	—
0231137003 ...	CS315	—	EP146	—	—
0231137004 ...	CS315	—	EP146	—	—
0231137005 ...	CS307	EP148	EP146	EP145	—
0231137007 ...	CS307	EP147	EP146	EP145	—
0231137009 ...	CS307	EP148	EP146	EP145	—
0231137011 ...	CS307	EP148	EP146	EP145	—
0231137013 ...	CS307	EP147	EP146	EP145	—
0231137015 ...	CS305	EP147	EP142	EP133	—
0231137017 ...	CS307	EP259	EP146	EP145	—
0231137021 ...	CS312P	EP148	EP146	EP145	—
0231137035 ...	CS312P	EP148	EP278	EP274	—
0231137036 ...	CS312P	EP148	EP278	EP274	—
0231137056 ...	CS313P	EP259	EP146	EP145	—
0231138001 ...	CS305	EP147	EP142	EP133	—
0231138002 ...	CS305	EP147	EP142	EP133	—
0231139002 ...	—	—	EP142	EP133	—
0231139004 ...	CS305	EP147	EP142	EP133	—
0231139005 ...	CS305	EP147	EP142	EP133	—
0231139006 ...	CS305	EP147	EP142	EP133	—
0231141001 ...	CS305 ⁹	EP147	EP142	—	—
0231141002 ...	CS305 ⁹	EP147	EP142	EP269	—
0231141004 ...	CS305 ⁹	EP147	EP142	—	—
0231142001 ...	CS314	EP284	EP143	EP269	—
0231142002 ...	CS313P	EP446	EP143	EP269	—
0231142003 ...	CS313P	—	EP278	EP269	—
0231142004 ...	CS313P	—	EP278	EP269	—
0231142005 ...	CS313P	—	EP278	EP269	—
0231143001 ...	—	—	EP142	—	—
0231144001 ...	CS301	EP147	—	—	—

(continued on next page)

⁹ Two required

BOSCH (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
0231144002 ...	CS301	EP147	—	—	—
0231144003 ...	CS323	EP147	—	—	—
0231144004 ...	CS323	EP147	—	—	—
0231145049 ...	—	EP147	—	—	—
0231146001 ...	CS303	—	—	EP131	—
0231146003 ...	CS303	—	—	EP131	—
0231146004 ...	CS303	—	—	EP131	—
0231146007 ...	—	—	—	EP131	—
0231146008 ...	—	—	—	EP131	—
0231146009 ...	CS303	—	—	EP131	—
0231146010 ...	CS303	—	—	EP131	—
0231146011 ...	CS303	—	—	—	—
0231146012 ...	CS303	—	—	EP131	—
0231146021 ...	CS313	EP446	EP143	EP131	—
0231146022 ...	CS313	EP446	EP143	EP131	—
0231146024 ...	CS313	—	EP143	EP131	—
0231146025 ...	CS313	EP446	EP143	EP131	—
0231146026 ...	CS303	EP147	EP143	EP131	—
0231146027 ...	CS313	—	—	EP145	—
0231146031 ...	CS313	—	—	EP145	—
0231146032 ...	CS313P	EP446	EP143	EP131	—
0231146033 ...	CS313P	EP446	EP143	EP131	—
0231146034 ...	CS303	—	—	EP131	—
0231146035 ...	CS303	—	—	EP131	—
0231146036 ...	CS303	—	—	EP131	—
0231146037 ...	—	—	—	EP131	—
0231146038 ...	—	—	—	EP131	—
0231146039 ...	CS303	—	—	EP131	—
0231146041 ...	CS313	—	—	EP145	—
0231146042 ...	CS313	—	—	—	—
0231146044 ...	CS313	EP446	EP143	EP131	—
0231146049 ...	CS313P	EP446	EP143	—	—
0231146053 ...	CS313	EP446	EP143	EP131	—
0231146056 ...	CS313P	—	EP143	EP131	—
0231146069 ...	CS313P	—	—	—	—
0231146072 ...	CS313P	—	EP143	EP131	—
0231146073 ...	CS313P	—	EP143	EP274	—
0231146078 ...	CS313P	EP284	EP143	EP131	—
0231146080 ...	CS313P	—	EP143	EP274	—
0231146081 ...	CS313P	EP259	EP278	EP274	—
0231146082 ...	CS307	EP148	EP146	EP145	—
0231146084 ...	CS313P	—	EP143	EP274	—
0231146092 ...	CS313P	—	EP143	EP274	—
0231146099 ...	CS313P	EP284	EP143	EP131	—
0231146113 ...	CS313P	EP291	EP146	EP145	—
0231147001 ...	CS315	—	EP146	—	—
0231147002 ...	CS307	EP148	EP146	EP145	—
0231147003 ...	CS315	—	EP146	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
0231147004 ...	CS315	—	EP146	—	—
0231147005 ...	CS315	—	EP146	EP145	—
0231147006 ...	CS307	EP147	EP146	EP145	—
0231150001 ...	CS301	EP147	EP146	EP145	—
0231150002 ...	CS313P	—	EP143	EP131	—
0231150003 ...	CS313P	EP250	EP143	EP131	—
0231150004 ...	CS313P	—	EP143	EP131	—
0231150007 ...	CS313	EP250	EP143	EP269	—
0231150013 ...	CS313	EP290	EP143	EP274	—
0231150024 ...	CS313P	EP282	EP143	—	—
0231150025 ...	CS313P	EP282	EP143	—	—
0231151003 ...	CS313P	—	—	EP131	—
0231151005 ...	CS313P	EP446	—	EP131	—
0231151008 ...	CS313P	—	EP460	EP131	—
0231152001 ...	CS313P	EP446	EP143	EP269	—
0231152002 ...	CS313	EP446	EP143	EP269	—
0231153002 ...	CS321	EP147	EP143	EP131	—
0231153003 ...	CS321	EP147	EP143	—	—
0231153009 ...	CS321	EP147	EP143	EP131	—
0231153012 ...	CS313	—	EP143	EP131	—
0231153099 ...	CS321	EP147	—	EP131	—
0231154001 ...	CS321	EP147	EP143	EP131	—
0231154002 ...	CS321	EP147	EP143	EP131	—
0231159001 ...	CS321	EP147	—	EP269	—
0231159002 ...	CS321	EP147	—	EP269	—
0231159006 ...	CS313P	—	—	EP269	—
0231159007 ...	CS313P	—	—	EP269	—
0231159008 ...	CS313P	—	—	EP269	—
0231162001 ...	CS301	EP446	—	EP269	—
0231162002 ...	CS313P	EP446	EP460	EP269	—
0231163001 ...	CS313P	EP259	—	EP145	—
0231163003 ...	CS313P	EP259	EP146	EP145	—
0231163004 ...	CS313P	EP259	EP146	EP145	—
0231163006 ...	CS313P	EP446	EP143	EP131	—
0231163007 ...	CS313P	EP293	EP143	EP274	—
0231163008 ...	CS313P	EP259	EP146	EP145	—
0231163009 ...	CS313P	EP259	EP146	EP145	—
0231163010 ...	CS313P	EP446	EP143	EP131	—
0231163011 ...	CS313P	EP291	EP278	EP274	—
0231163012 ...	CS313P	EP291	EP278	EP274	—
0231163016 ...	CS313P	EP259	EP146	EP145	—
0231163017 ...	CS313P	EP259	EP146	EP145	—
0231163018 ...	CS313P	EP259	EP146	EP145	—
0231163019 ...	CS313P	EP259	EP146	EP145	—
0231163021 ...	CS313P	EP446	EP143	EP131	—
0231163024 ...	CS314	—	EP143	—	—
0231163025 ...	CS313P	EP293	EP143	EP274	—
0231163027 ...	CS313P	EP291	EP146	EP145	—

(continued on next page)

BOSCH (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
0231163029 ...	CS313P	EP291	EP146	EP145	—
0231163033 ...	CS313P	EP446	EP143	EP131	—
0231163037 ...	CS314	EP153	EP143	—	—
0231167001 ...	CS313P	EP261	EP143	EP131	—
0231167004 ...	CS313P	EP290	EP143	EP274	—
0231167005 ...	CS313P	EP289	EP143	EP131	—
0231167006 ...	CS313P	EP289	EP143	EP131	—
0231167007 ...	CS313P	EP293	EP143	EP274	—
0231167009 ...	CS313P	EP290	EP143	EP274	—
0231167010 ...	CS313P	EP292	EP278	EP131	—
0231167011 ...	CS313P	EP292	EP278	EP131	—
0231167012 ...	CS313P	EP291	EP278	EP274	—
0231167013 ...	CS313P	EP291	EP278	EP274	—
0231167014 ...	CS313P	EP291	EP146	EP145	—
0231167015 ...	CS313P	EP291	EP146	EP145	—
0231167017 ...	CS313	—	EP146	EP145	—
0231167023 ...	CS313P	EP290	EP143	EP274	—
0231167024 ...	CS313P	EP293	EP143	EP274	—
0231167029 ...	CS313	—	EP143	EP274	—
0231167032 ...	CS313P	EP290	EP143	EP274	—
0231167037 ...	CS313P	EP293	EP143	EP274	—
0231167038 ...	CS313P	EP293	EP143	EP274	—
0231167039 ...	CS313P	EP450	EP143	EP274	—
0231167043 ...	CS313P	—	EP143	—	—
0231167045 ...	CS313P	EP282	EP278	EP131	—
0231167046 ...	CS313P	EP282	EP143	—	—
0231167047 ...	CS313P	—	EP143	—	—
0231167049 ...	CS313P	EP291	EP278	EP274	—
0231167050 ...	CS313P	EP291	EP278	EP274	—
0231167051 ...	CS313	—	EP143	EP274	—
0231167053 ...	CS313P	EP291	EP278	EP274	—
0231167054 ...	CS313P	EP291	EP278	EP274	—
0231167055 ...	CS313P	EP291	—	EP274	—
0231167056 ...	CS313P	EP291	EP278	EP274	—
0231167070 ...	CS313P	EP291	EP278	EP274	—
0231167071 ...	CS313P	EP291	EP278	EP274	—
0231168005 ...	CS313P	EP433	EP517	EP274	—
0231168013 ...	CS313P	EP446	EP460	EP274	—
0231169001 ...	CS314	—	—	EP269	—
0231169003 ...	CS314	—	—	—	—
0231169004 ...	CS314	—	—	EP269	—
0231169005 ...	CS314	—	—	—	—
0231169009 ...	CS314	—	—	—	—
0231169010 ...	CS314	—	EP871	—	—
0231169011 ...	CS314	—	—	—	—
0231170010 ...	CS332	EP448	EP278	EP274	—
0231170033 ...	CS312P	—	EP143	EP274	—
0231170034 ...	CS313P	EP291	EP278	EP274	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
0231170036 ...	CS313P	EP291	EP278	EP274	—
0231170087 ...	CS314	EP284	EP278	EP274	—
0231170093 ...	CS313P	EP433	EP278	EP274	—
0231170099 ...	—	—	EP143	EP274	—
0231170107 ...	—	—	EP143	EP274	—
0231170115 ...	CS314	EP466	EP278	EP274	—
0231170118 ...	—	—	EP278	EP274	—
0231170119 ...	—	—	EP278	EP274	—
0231170122 ...	CS314	EP464	EP278	EP274	—
0231170131 ...	CS313	EP451	EP143	EP274	—
0231170137 ...	—	—	EP278	EP274	—
0231170140 ...	CS312P	—	EP143	EP274	—
0231170144 ...	CS314	EP464	EP278	EP274	—
0231170145 ...	CS314	EP464	EP278	EP274	—
0231170157 ...	CS312P	—	EP143	EP274	—
0231170158 ...	CS314	EP464	EP278	EP274	—
0231170164 ...	CS313P	EP446	EP278	EP274	—
0231170197 ...	CS314	EP464	EP278	EP274	—
0231170202 ...	CS313P	EP387	EP278	EP274	—
0231170214 ...	CS312P	EP446	EP278	EP274	—
0231170252 ...	CS313P	EP387	EP278	—	—
0231170284 ...	—	—	—	EP274	—
0231172005 ...	CS301	EP291	EP278	EP274	—
0231172006 ...	CS301	EP291	EP278	EP274	—
0231172007 ...	CS313P	EP291	EP278	EP274	—
0231172008 ...	CS301	EP291	EP278	EP274	—
0231172009 ...	CS313P	EP291	EP146	EP145	—
0231172010 ...	CS313P	—	EP146	EP145	—
0231172011 ...	CS313P	EP291	EP146	EP145	—
0231172012 ...	CS313P	—	EP146	EP145	—
0231172019 ...	CS313P	EP291	EP278	EP274	—
0231172021 ...	CS313P	EP291	EP278	EP274	—
0231173001 ...	CS313P	EP291	EP582	EP274	—
0231173002 ...	CS313P	EP291	—	EP274	—
0231173005 ...	CS313P	EP291	EP517	EP274	—
0231173007 ...	CS313P	EP291	EP517	EP274	—
0231173009 ...	CS313P	EP291	EP517	EP274	—
0231174001 ...	CS313P	EP291	—	EP274	—
0231174002 ...	CS313P	EP291	—	EP274	—
0231174005 ...	CS313	—	EP278	EP274	—
0231174007 ...	CS313P	EP291	—	EP274	—
0231174009 ...	CS313	—	EP278	EP274	—
0231174011 ...	CS313P	EP291	—	EP274	—
0231175065 ...	CS314	EP259	—	EP131	—
0231176004 ...	CS313P	EP282	EP143	—	—
0231176005 ...	CS313P	EP282	EP143	—	—
0231176010 ...	CS313	EP451	EP143	EP274	—
0231176011 ...	CS313P	EP293	EP143	EP274	—

(continued on next page)

BOSCH (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
0231176012 ...	CS313P	EP293	EP143	EP274	—
0231176014 ...	CS313P	EP292	EP278	EP274	—
0231176015 ...	CS313P	EP431	EP278	EP274	—
0231176016 ...	CS313P	EP293	EP278	EP274	—
0231176024 ...	CS313P	EP293	—	EP274	—
0231176028 ...	CS313P	EP291	EP278	EP274	—
0231176032 ...	CS313P	—	EP278	EP274	—
0231176033 ...	CS313	EP433	EP143	EP274	—
0231176035 ...	CS313P	—	EP143	EP274	—
0231176037 ...	CS313P	—	EP143	EP274	—
0231176040 ...	CS313P	EP431	EP278	EP274	—
0231176044 ...	CS313P	EP291	EP278	EP274	—
0231176046 ...	CS313P	EP431	EP278	EP274	—
0231176048 ...	CS313P	EP433	EP278	EP274	—
0231176053 ...	CS313P	EP291	EP278	EP274	—
0231176055 ...	CS313P	EP433	EP278	EP274	—
0231176057 ...	CS313P	EP387	EP278	EP274	VC1309
0231176059 ...	CS313P	EP446	EP278	EP274	—
0231176060 ...	CS313P	EP433	EP278	EP274	—
0231176064 ...	CS313P	EP387	EP278	EP274	—
0231176084 ...	CS313P	EP446	EP278	EP274	—
0231176104 ...	—	—	EP143	EP274	—
0231176105 ...	—	—	EP143	EP274	—
0231176106 ...	CS313P	EP507	EP278	EP274	—
0231176108 ...	CS313P	EP507	EP278	EP850	—
0231176110 ...	CS313P	EP451	EP278	EP274	—
0231176114 ...	CS313P	EP292	EP278	EP274	—
0231178003 ...	CS313P	EP378	EP278	EP274	—
0231178006 ...	CS313P	EP446	EP143	EP274	—
0231178007 ...	CS313P	EP446	EP143	EP274	—
0231178009 ...	CS321	EP466	EP143	EP274	—
0231178087 ...	CS314	EP284	—	EP274	—
0231179001 ...	CS314	EP466	EP278	EP274	—
0231180003 ...	CS313P	EP446	EP460	EP131	—
0231180008 ...	CS314	EP446	—	EP131	—
0231180013 ...	CS314	—	EP460	EP131	—
0231181003 ...	CS313	EP433	EP278	EP274	—
0231181005 ...	CS313P	EP433	EP517	EP274	—
0231181007 ...	CS313P	EP433	EP517	EP274	—
0231181009 ...	CS313P	EP433	—	EP274	—
0231181011 ...	CS313P	EP446	EP460	EP274	—
0231181012 ...	CS313P	EP433	EP517	EP274	—
0231181014 ...	CS313P	EP433	EP517	EP274	—
0231184001 ...	CS313P	—	—	—	—
0231184002 ...	CS313P	—	—	—	—
0231184003 ...	CS313P	—	—	—	—
0231184004 ...	CS313P	—	—	—	—
0231301001 ...	CS313P	—	—	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
0231301010 ...	CS329	EP445	EP407	EP274	—
0231301014 ...	CS329	EP445	EP407	EP274	—
0231302002 ...	CS301	EP423	EP548	EP882	—
0231302010 ...	—	—	EP407	EP274	—
0231303001 ...	CS313P	—	—	—	—
0231303002 ...	CS313P	—	—	—	—
0231304001 ...	CS313P	—	—	—	—
0231305050 ...	CS313	EP434	—	EP406	—
0231305052 ...	CS313P	EP434	EP407	EP274	—
0231305059 ...	CS332	EP455	EP407	EP274	—
0231305070 ...	CS332	EP455	EP407	EP274	—
0231305170 ...	CS312P	EP455	EP541	EP406	—
0231308001 ...	CS313	—	—	EP406	—
0231308002 ...	CS313	—	—	EP406	—
0231308005 ...	CS314	—	EP407	EP274	—
0231308006 ...	CS313	EP434	—	EP406	—
0231308008 ...	CS313	EP434	—	EP406	—
0231308010 ...	CS313P	EP434	EP407	EP274	—
0231308012 ...	CS313P	EP434	EP407	EP274	—
0231308103 ...	CS313P	EP434	EP407	—	—
0231308104 ...	CS313P	EP434	EP407	—	—
0231310002 ...	CS313P	—	EP509	—	—
0231310003 ...	CS312P	EP455	—	EP274	—
0231311001 ...	CS313P	—	EP407	—	—
0231401002 ...	CS301	—	EP548	EP882	—
0231401003 ...	CS328	—	—	EP442	—
0231402001 ...	CS313P	—	—	EP442	—
0231402002 ...	CS328	—	—	EP442	—
0231402005 ...	CS301	—	EP548	EP882	—
0231402007 ...	CS328	—	—	—	—
0231403006 ...	CS313P	—	—	EP442	—
0231403007 ...	CS313P	—	—	EP442	—
0231404002 ...	CS313P	—	—	EP442	—
0237002002 ...	—	—	EP278	EP274	—
0237002003 ...	—	—	EP278	EP274	—
0237002017 ...	—	—	—	EP274	—
0237002020 ...	—	—	EP278	—	—
0237002021 ...	—	—	EP278	—	—
0237002023 ...	—	—	EP278	EP274	—
0237002024 ...	—	—	EP278	—	—
0237002026 ...	—	—	EP278	EP274	—
0237002035 ...	—	—	EP278	—	—
0237002038 ...	—	—	EP278	EP274	—
0237002039 ...	—	—	EP278	EP274	—
0237002041 ...	—	—	EP278	—	—
0237002049 ...	—	—	—	EP850	—
0237002050 ...	—	—	EP278	—	—
0237003003 ...	—	—	EP278	EP274	—

(continued on next page)

BOSCH (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
0237003008	—	—	EP278	EP274	—
0237003013	—	—	EP278	EP274	—
0237003014	—	—	EP278	EP274	—
0237003018	—	—	EP278	EP274	—
0237004001	—	—	EP278	EP534	—
0237004005	—	—	EP278	EP534	—
0237009001	—	—	EP477	EP247	—
0237009002	—	—	EP477	EP247	—
0237009004	—	—	EP477	EP247	—
0237012001	—	—	EP278	EP534	—
0237022009	—	—	EP278	EP274	—
0237022013	—	—	EP278	EP274	—
0237022015	—	—	EP278	EP274	—
0237022018	—	—	EP278	EP274	—
0237022057	CS313	EP387	EP143	EP274	—
0237027001	—	—	—	EP534	—
0237027002	—	—	—	EP534	—
0237027003	—	—	EP278	EP534	—
0237300001	—	—	EP407	EP274	—
0237301001	—	—	—	EP274	—
0237301002	—	—	—	EP274	—
0237301005	—	—	—	EP274	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
0237302009	—	—	—	EP274	—
0237304002	—	—	EP407	EP274	—
0237304003	—	—	EP407	—	—
0237304005	—	—	EP407	EP274	—
0237304006	—	—	EP407	EP274	—
0237304015	—	—	EP407	EP274	—
0237304016	—	—	EP407	EP274	—
0237306001	—	—	EP407	EP274	—
0237402004	—	—	—	EP530	—
0237402008	—	—	—	EP530	—
0237402009	—	—	—	EP530	—
0237402013	—	—	—	EP530	—
0237402015	—	—	—	EP530	—
0237402017	—	—	—	EP530	—
0237406001	—	—	—	EP530	—
0237406004	—	—	—	EP530	—
7831176104	CS313	EP408	EP143	EP274	—
9230081094	CS321	EP466	EP143	EP274	—
02311115045	CS301	EP147	—	EP131	—
02311129026	CS313P	—	—	EP131	—

CHRYSLER (ALSO SEE MITSUBISHI)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
A98308	—	EP10	—	—	—
A3213094	CS751	—	—	—	—
MD001116	CS351	EP656	EP342	EP706	—
MD003616	CS359	EP367	EP342	EP706	—
MD003617	CS359	EP367	EP342	EP706	—
MD003642	CS359	EP367	EP342	EP706	—
MD003643	CS359	EP367	EP342	EP706	—
MD003646	CS359	EP367	EP342	EP706	—
MD005600	CS351	EP325	EP321	EP353	—
MD005601	CS351	EP325	EP321	EP353	—
MD005602	CS359	EP350	EP342	EP706	—
MD005603	CS359	EP350	EP342	—	—
MD007390	CS351	EP656	—	—	—
MD009101	CS351	EP656	EP342	EP706	—
MD009102	CS351	EP656	EP342	—	—
MD009112	CS359	EP656	EP342	EP706	—
MD009146	CS351	EP656	EP342	EP706	—
MD009152	CS351	—	EP342	EP706	—
MD009314	—	—	EP658	EP660	—
MD009319	CS351	—	—	EP706	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
MD021696	CS359	EP350	EP342	EP706	—
MD021825	CS359	EP368	EP342	EP706	—
MD021830	CS359	EP350	EP342	—	—
MD021831	CS359	EP350	EP342	—	—
MD021834	CS359	EP368	EP342	EP706	—
MD021835	CS359	EP368	EP342	EP706	—
MD021836	CS359	EP368	EP342	EP706	—
MD025751	CS351	EP657	EP342	—	—
MD025757	CS351	EP657	EP342	—	—
MD025759	CS351	EP657	EP342	—	—
MD025761	—	—	EP658	EP660	—
MD025762	—	—	EP658	EP660	—
MD025763	—	—	EP658	EP660	—
MD027695	—	—	EP658	—	—
MD027696	—	—	EP658	—	—
MD027697	—	—	EP658	—	—
MD027698	—	—	EP658	—	—
MD027704	—	—	EP658	—	—
MD034140	—	—	EP658	—	—
MD034141	—	—	EP658	—	—

(continued on next page)

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
MD0257679	CS351	EP657	EP342	—	—
268308	—	EP10	—	—	—
321788	CS725A	MO5000	AL62	AL98	—
540552	CS721A	MO5000	AL65	AL99	—
546755	CS719A	MO5000	AL107	AL128	—
930366	CS725A	MO5000	AL62	AL63	—
1071820	CS709	MO5000	AL65	AL66	—
1071821	CS709	MO5000	AL65	AL66	—
1109760	CS725A	MO5000	AL62	AL63	—
1119564	CS725A	MO5000	AL62	—	—
1123056	CS725A	MO5000	AL62	—	—
1124876	CS725A	MO5000	AL62	—	—
1126571	—	—	AL65	AL99	—
1193314	CS725A	MO5000	AL62	AL98	—
1193317	CS725A	MO5000	AL62	AL98	—
1233564	CS725A	MO5000	AL62	AL98	—
1261411	CS725A	MO5000	AL62	AL63	—
1266945	CS725A	MO5000	AL62	AL63	—
1271144	CS725A	MO5000	AL107	AL106	—
1274066	CS725A	MO5000	AL107	AL106	—
1274116	CS725A	MO5000	AL107	—	—
1321786	—	—	AL65	AL99	—
1321787	CS725A	MO5000	AL62	AL98	—
1321788	CS725A	MO5000	AL62	AL98	—
1321789	CS725A	MO5000	AL62	AL98	—
1323899	CS725A	MO5000	AL62	AL98	—
1323933	—	—	AL65	AL99	—
1326532	CS725A	MO5000	AL62	AL99	—
1326533	CS725A	MO5000	AL62	AL99	—
1343554	CS719A	MO5000	AL107	AL106	—
1345464	CS719A	MO5000	AL107	AL106	—
1383290	CS721A ⁹	MO5000	AL65	AL99	—
1383757	CS721A	MO5000	AL65	AL99	—
1402503	CS721A	MO5000	AL65	AL99	—
1402600	CS720P	MO5000	AL65	AL99	—
1405219	CS725A	MO5000	—	—	—
1407602	CS725A	MO5000	—	—	—
1407604	CS725A	MO5000	—	—	—
1466945	CS725A	MO5000	AL62	AL63	—
1479139	CS721A	MO5000	AL65	—	—
1479588	CS719A	MO5000	AL106	—	—
1479589	CS719A	MO5000	AL107	AL106	—
1486190	CS721A	MO5000	AL65	AL99	—
1501786	CS720P	MO5000	AL65	AL99	—
1507047	CS721A	MO5000	AL65	AL99	—
1507048	CS721A	MO5000	AL65	AL99	—
1507456	CS725A	MO5000	AL107	AL106	—
1507530	CS725A	MO5000	AL107	AL106	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1507547	CS720P	MO5000	AL65	AL99	—
1509668	CS725A	MO5000	AL62	AL63	—
1540552	CS721A	MO5000	AL65	AL99	—
1540809	CS721A	MO5000	AL65	AL99	—
1540810	CS721A	MO5000	AL65	AL99	—
1546755	CS719A	MO5000	AL107	AL106	—
1550584	CS725A	MO5000	—	—	—
1550585	CS725A	MO5000	—	—	—
1550590	CS725A	MO5000	—	—	—
1551878	CS725A	MO5000	—	—	—
1555284	CS721A	MO5000	AL65	AL99	—
1555288	CS721A	MO5000	—	—	—
1555289	CS721A	MO5000	—	—	—
1558149	CS721A	MO5000	—	—	—
1566545	CS721A	MO5000	AL65	AL99	—
1566565	CS720P	MO5000	AL65	AL99	—
1566658	CS721A	MO5000	AL65	AL99	—
1571756	CS719A	MO5000	AL107	AL106	—
1595305	CS719A	MO5000	AL65	AL99	—
1605148	CS721A	MO5000	AL65	AL99	—
1610349	CS721A	MO5000	—	—	—
1612723	CS721A ⁹	MO5000	—	—	—
1612742	CS721A	MO5000	AL65	AL99	—
1614217	CS721A ⁹	MO5000	—	—	—
1616631	CS721A	MO5000	AL65	AL99	—
1626656	CS721A	MO5000	AL65	AL99	—
1626657	—	—	AL65	AL99	—
1626658	CS721A	MO5000	AL65	AL99	—
1626659	CS721A	MO5000	AL65	AL99	—
1626660	—	—	AL65	AL99	—
1626661	CS721A	MO5000	AL65	AL99	—
1633140	CS725A	MO5000	—	—	—
1633141	CS725A	AL869	—	—	—
1633142	CS725A	MO5000	—	—	—
1633143	CS725A	MO5000	—	—	—
1633144	CS725A	MO5000	AL104	—	—
1633145	CS725A	MO5000	—	—	—
1633150	CS721A ⁹	MO5000	—	—	—
1633157	CS721A	MO5000	—	—	—
1634193	CS721A	MO5000	AL65	AL99	—
1634224	CS721A	MO5000	—	—	—
1641707	CS721A	MO5000	AL65	AL99	—
1641740	CS721A	MO5000	AL65	AL99	—
1641956	CS721A	MO5000	AL65	AL99	—
1642387	CS721A	MO5000	AL125	AL124	—
1642389	CS721A	MO5000	AL125	AL124	—
1642390	CS721A	MO5000	AL125	AL124	—
1642392	CS721A	MO5000	AL125	AL124	—

(continued on next page)

⁹ Two required

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1648685	CS721A	MO5000	AL125	AL124	—
1648869	CS721A	MO5000	AL125	AL124	—
1658869	CS721A	MO5000	AL125	AL124	—
1658870	CS721A	MO5000	AL65	AL99	—
1658989	CS721A	MO5000	AL65	AL99	—
1663025	CS721A	MO5000	AL125	AL124	—
1663026	CS721A	MO5000	AL125	AL124	—
1663122	CS721A	MO5000	AL125	AL124	—
1663189	CS721A	MO5000	AL125	AL124	—
1664956	CS721A	MO5000	AL125	AL124	—
1664970	CS725A	MO5000	AL125	AL124	—
1665020	CS721A	MO5000	AL125	AL124	—
1688647	CS721A	MO5000	AL125	AL124	—
1688648	CS721A	MO5000	AL125	AL124	—
1688649	CS721A	MO5000	AL125	AL124	—
1689303	CS721A	MO5000	AL125	AL124	—
1689318	CS723A	MO5000	AL125	AL124	—
1689319	CS723A	MO5000	AL125	AL124	—
1689320	CS723A	MO5000	AL125	AL124	—
1689323	CS719A	MO5000	AL107	AL106	—
1689324	CS719A	MO5000	AL107	AL106	—
1689325	CS723A	MO5000	AL125	AL124	—
1704260	CS721A	MO5000	AL125	AL124	—
1704261	CS721A	MO5000	AL125	AL124	—
1704262	CS721A	MO5000	AL125	AL124	—
1704308	—	—	AL125	AL124	—
1704309	CS721A	MO5000	AL125	AL124	—
1704310	CS721A	MO5000	AL125	AL124	—
1770750	CS723A	MO5000	AL125	AL124	—
1779937	CS723A	MO5000	AL125	AL124	—
1779938	CS723A	MO5000	AL125	AL124	—
1779940	CS723A	MO5000	AL125	AL124	—
1779941	—	—	AL125	AL124	—
1779943	CS723A	MO5000	AL125	AL124	—
1779950	CS729A	MO5000	AL125	AL124	—
1779951	CS723A	MO5000	AL125	AL124	—
1779952	CS721A	MO5000	AL125	AL124	—
1779983	CS729A	MO5000	AL125	AL124	—
1785139	CS721A	MO5000	AL125	AL124	—
1786940	CS753	FA66	FA157	FA79	—
1787055	CS721A	MO5000	AL125	AL124	—
1787878	CS721A	MO5000	AL125	AL124	—
1787892	CS725A	MO5000	AL107	AL106	—
1787972	CS725A	MO5000	AL107	AL128	—
1788638	CS723A	MO5000	AL125	AL124	—
1788688	CS725A	MO5000	AL107	AL106	—
1790977	CS753	FA66	FA157	FA79	—
1792701	CS723A	MO5000	AL125	AL124	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1792703	CS721A	MO5000	AL125	AL124	—
1792719	CS753	FA66	FA157	FA79	—
1793772	CS721A	MO5000	AL125	AL124	—
1798640	CS723A	MO5000	AL125	AL124	—
1838505	CS851P	MO5000	MO13	MO20	—
1838822	—	—	AL125	AL124	—
1841417	CS720P	MO5000	AL125	AL124	—
1841498	—	—	AL125	AL124	—
1841511	CS729A	MO5000	AL125	AL124	—
1841514	CS723A	MO5000	AL125	AL124	—
1841515	CS721A	MO5000	AL125	AL124	—
1841518	CS721A	MO5000	AL125	AL124	—
1841575	—	—	AL125	AL124	—
1842602	CS723A	MO5000	AL125	AL124	—
1842607	CS723A	MO5000	AL125	AL124	—
1842803	CS729A	MO5000	AL125	AL124	—
1842804	CS729A	MO5000	AL125	AL124	—
1842805	CS720P	MO5000	AL125	AL124	—
1842810	CS720P	MO5000	AL125	AL124	—
1842811	CS720P	MO5000	AL125	AL124	—
1842812	CS723A	MO5000	AL125	AL124	—
1889286	CS720P	—	—	—	—
1889305	CS723A	MO5000	AL125	AL124	—
1889310	CS729A	MO5000	AL125	AL124	—
1889370	CS721A	MO5000	AL125	AL124	—
1889485	CS729A	MO5000	AL125	AL129	—
1889550	CS719A	MO5000	AL107	AL106	—
1889552	CS719A	MO5000	AL107	AL106	—
1889554	CS723A	MO5000	AL125	AL129	—
1889560	CS723A	MO5000	AL125	AL124	—
1889562	CS729A	MO5000	AL125	AL124	—
1889564	CS729A	MO5000	AL125	AL124	—
1889568	CS720P	MO5000	AL125	AL124	—
1889570	CS729A	MO5000	AL125	AL124	—
1889598	CS725A	MO5000	AL107	AL106	—
1889600	CS723A	MO5000	AL125	AL124	—
1889666	CS721A	MO5000	AL125	AL124	—
1889710	CS851P	MO5000	MO13	MO20	—
1889715	CS851P	MO5000	MO13	MO20	—
1889750	CS851P	MO5000	MO13	MO40	—
1889838	CS729A	MO5000	AL125	AL124	—
1889851	CS729A	MO5000	AL125	AL124	—
1889862	CS729A	MO5000	AL125	AL129	—
1889869	CS729A	MO5000	AL125	AL129	—
1889891	CS721A	MO5000	AL125	AL124	—
1922654	CS723A	MO5000	AL125	AL124	—
1922670	CS723A	MO5000	AL125	AL124	—
1992454	CS723A	MO5000	AL125	AL124	—

(continued on next page)

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1992654	CS723A	MO5000	AL125	AL124	—
1992670	CS723A	MO5000	AL125	AL124	—
2084841	CS719A	MO5000	AL107	AL106	—
2084842	CS719A	MO5000	AL107	AL106	—
2084843	CS723A	MO5000	AL125	AL124	—
2084844	CS719A	MO5000	AL107	AL106	—
2084845	CS723A	MO5000	AL125	AL124	—
2095054	CS729A	MO5000	AL125	AL124	—
2095065	CS720P	MO5000	AL125	AL124	—
2095199	CS723A	MO5000	AL125	AL124	—
2095270	CS851P	MO5000	MO13	—	—
2095325	CS723A	MO5000	AL125	AL129	—
2095326	CS729A	MO5000	AL125	AL129	—
2095377	CS719A	MO5000	AL132	AL131	—
2095530	CS851P	MO5000	MO13	MO20	—
2095630	CS851P	MO5000	MO13	MO20	—
2095647	CS729A	MO5000	AL125	AL129	—
2095679	CS729A	MO5000	AL125	AL124	—
2095680	CS720P	MO5000	AL125	AL124	—
2095795	CS729A	MO5000	AL125	AL124	—
2095796	CS729A	MO5000	AL125	AL124	—
2095797	CS729A	MO5000	AL125	AL124	—
2095799	CS729A	MO5000	AL125	AL124	—
2095802	CS729A	MO5000	AL125	AL124	—
2095832	CS720P	MO5000	AL125	AL129	—
2095836	CS851P	MO5000	AL125	AL124	—
2095841	CS720P	MO5000	AL125	AL124	—
2095843	CS851P	MO5000	MO13	MO20	—
2095844	CS851P	MO5000	MO13	MO20	—
2095845	CS851P	MO5000	MO13	MO20	—
2095846	CS851P	MO5000	MO13	MO20	—
2095900	CS720P	MO5000	AL125	AL124	—
2095948	CS723A	MO5000	AL125	AL129	—
2095951	CS719A	MO5000	AL132	AL131	—
2095957	CS719A	MO5000	AL107	AL106	—
2095963	CS723A	MO5000	AL125	AL124	—
2095965	CS729A	MO5000	AL125	AL124	—
2095969	CS729A	MO5000	AL125	AL129	—
2095974	CS851P	MO5000	MO13	MO40	VC1135
2095976	CS851P	MO5000	MO13	MO40	VC1130
2095979	CS851P	MO5000	MO13	MO20	—
2095981	CS851P	MO5000	MO13	MO20	—
2095983	CS851P	MO5000	MO13	MO20	VC1135
2095987	CS851P	MO5000	MO13	MO20	—
2098085	CS721A	MO5000	AL125	AL124	—
2098238	CS729A	MO5000	AL125	AL124	—
2098295	CS851P	MO5000	MO13	MO40	—
2098313	CS720P	MO5000	AL125	AL124	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
2098324	CS719A	MO5000	AL107	AL106	—
2098325	CS723A	MO5000	AL125	AL124	—
2098326	CS729A	MO5000	AL125	AL124	—
2098475	CS851P	MO5000	MO13	MO40	—
2098477	—	—	MO13	MO40	—
2098486	—	—	MO13	MO40	—
2098488	—	—	MO13	MO40	—
2098495	CS720P	MO5000	AL125	AL124	—
2098509	CS851P	MO5000	MO13	MO20	—
2098524	CS851P	MO5000	MO13	MO40	VC1135
2098533	CS851P	MO5000	MO13	MO40	VC1135
2098537	CS851P	MO5000	MO13	MO40	—
2098568	CS720P	MO5000	—	—	—
2098582	CS720P	MO5000	AL125	AL124	—
2098617	CS851P	MO5000	MO13	MO40	—
2098620	CS720P	MO5000	AL125	AL124	—
2098644	CS851P	MO5000	MO13	MO20	—
2098665	CS851P	MO5000	MO13	MO40	VC1225
2098667	CS851P	MO5000	MO13	MO40	VC1225
2098670	CS851P	MO5000	MO13	MO40	VC1130
2098672	CS851P	MO5000	MO13	MO40	VC1130
2098674	CS851P	MO5000	MO13	MO20	—
2098675	CS851P	MO5000	MO13	MO40	VC1225
2098677	CS851P	MO5000	MO13	MO40	VC1225
2098679	CS851P	MO5000	MO13	MO20	VC1135
2098680	CS851P	MO5000	MO13	MO20	VC1135
2098682	CS851P	MO5000	MO13	MO20	—
2098683	CS851P	MO5000	MO13	MO20	—
2098684	CS851P	MO5000	MO13	MO20	—
2098685	CS851P	MO5000	MO13	MO20	—
2098687	CS851P	MO5000	MO13	MO20	—
2098689	CS851P	MO5000	MO13	MO20	—
2098690	CS851P	MO5000	MO13	MO20	—
2098692	CS851P	MO5000	MO13	MO40	VC1130
2098693	CS729A	MO5000	AL125	AL129	—
2098704	CS719A	MO5000	AL132	AL131	—
2098708	CS719A	MO5000	AL132	AL131	—
2098720	CS729A	MO5000	AL125	AL124	—
2098725	CS720P	MO5000	AL125	AL124	—
2098726	CS720P	MO5000	AL125	AL124	—
2098729	CS719A	MO5000	AL132	AL131	—
2098730	CS719A	MO5000	AL132	AL131	—
2098732	CS719A	MO5000	AL132	AL131	—
2098738	CS723A	MO5000	AL125	AL131	—
2098741	CS851P	MO5000	MO13	MO40	—
2098742	CS851P	MO5000	MO13	MO40	—
2098743	—	—	MO13	MO40	—
2098748	CS851P	MO5000	MO13	MO40	—

(continued on next page)

CHRYSLER (ALSO SEE MITSUBISHI) CONTACT CONTROLLED DISTRIBUTORS
CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
2098766	CS851P	MO5000	MO13	MO40	VC1130
2098772	—	—	MO13	MO40	—
2098789	CS729A	MO5000	AL125	AL124	—
2098831	CS719A	MO5000	AL132	AL131	—
2098832	CS729A ⁹	MO5000	AL125	AL124	—
2098851	CS851P	MO5000	MO13	MO20	VC1135
2098853	CS851P	MO5000	MO13	MO20	VC1135
2098877	CS851P	MO5000	MO13	MO20	VC1135
2098895	CS851P	MO5000	MO13	MO20	VC1135
2098896	CS720P	MO5000	—	—	—
2098956	CS723A	MO5000	AL160	MO40	—
2098962	CS723A	MO5000	MO13	MO40	VC1130
2098971	CS723A	MO5000	AL160	MO40	VC1130
2098975	CS723A	MO5000	AL160	MO40	VC1130
2098976	CS723A	MO5000	AL160	MO40	VC1130
2098977	CS723A	MO5000	AL160	MO40	VC1130
2196320	CS723A	MO5000	AL125	AL124	—
2287829	CS729A	MO5000	AL125	AL124	—
2298777	CS723A	MO5000	AL125	AL129	—
2298778	CS719A	MO5000	AL132	AL131	—
2298779	—	—	AL132	AL131	—
2298782	CS729A	MO5000	AL125	AL129	—
2444104	CS723A	MO5000	AL160	MO40	—
2444118	CS723A	MO5000	AL160	MO40	—
2444161	CS851P	MO5000	MO13	MO20	—
2444247	CS720P	MO5000	AL125	AL124	—
2444254	CS851P	MO5000	MO13	MO40	VC1130
2444255	CS851P	MO5000	MO13	MO40	—
2444256	CS851P	MO5000	MO13	MO40	VC1225
2444258	CS851P	MO5000	MO13	MO20	—
2444259	CS851P	MO5000	MO13	MO20	—
2444261	CS851P	MO5000	MO13	MO20	—
2444263	CS851P	MO5000	MO13	MO20	—
2444272	CS720P	MO5000	AL125	AL124	—
2444274	CS851P	MO5000	MO13	MO20	—
2444275	CS851P	MO5000	MO13	MO20	—
2444276	CS851P	MO5000	MO13	MO20	—
2444291	CS851P	MO5000	MO13	MO20	—
2444292	CS851P	MO5000	MO13	MO20	—
2444295	CS851P	MO5000	MO13	MO40	VC1130
2444326	CS851P	MO5000	MO13	MO40	VC1130
2444328	CS851P	MO5000	MO13	MO20	—
2444329	CS851P	MO5000	MO13	MO20	—
2444332	CS851P	MO5000	MO13	MO20	—
2444333	CS720P	MO5000	AL125	AL124	—
2444334	CS851P	MO5000	MO13	MO20	—
2444335	—	—	AL125	AL129	—
2444346	CS723A	MO5000	AL125	AL124	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
2444358	CS720P	MO5000	AL125	AL124	—
2444360	CS720P	MO5000	AL125	AL124	—
2444361	CS720P	MO5000	AL125	AL124	—
2444363	CS720P	MO5000	AL125	AL124	—
2444364	CS720P	MO5000	AL125	AL124	—
2444366	CS720P	MO5000	AL125	AL124	—
2444367	CS851P	MO5000	MO13	MO40	—
2444368	CS851P	MO5000	MO13	MO40	—
2444382	CS851P	MO5000	MO13	MO40	VC1130
2444384	CS851P	MO5000	MO13	MO20	VC1135
2444385	CS851P	MO5000	MO13	MO20	—
2444386	CS851P	MO5000	MO13	MO20	—
2444387	CS851P	MO5000	MO13	MO40	VC1130
2444399	CS851P	MO5000	MO13	MO20	VC1135
2444415	CS851P	MO5000	MO13	MO40	—
2444416	CS851P	MO5000	—	MO40	—
2444421	CS851P	MO5000	MO13	MO20	—
2444423	CS851P	MO5000	MO13	MO40	—
2444424	CS851P	MO5000	MO13	MO20	VC1135
2444430	CS851P	MO5000	MO13	MO40	—
2444448	CS851P	MO5000	MO13	MO20	VC1135
2444449	CS851P	MO5000	MO13	MO20	VC1135
2444450	CS851P	MO5000	MO13	MO20	—
2444451	CS851P	MO5000	MO13	MO20	VC1135
2444628	CS851P	MO5000	MO13	MO20	VC1135
2444648	CS851P	MO5000	MO13	MO40	VC1130
2444671	CS851P	MO5000	MO13	MO40	VC1225
2444676	CS851P	MO5000	MO13	MO20	—
2444683	CS720P	MO5000	AL125	AL129	—
2444684	CS720P	MO5000	AL125	AL129	—
2444699	CS851P	MO5000	MO13	MO40	VC1130
2444700	CS851P	MO5000	MO13	MO20	—
2444703	CS720P ⁹	MO5000	AL125	AL129	—
2444704	CS720P ⁹	MO5000	AL125	AL129	—
2444760	CS723A	MO5000	AL125	AL124	—
2444772	CS723A	MO5000	MO13	MO40	—
2444773	CS723A	MO5000	AL125	MO40	—
2444794	CS851P	MO5000	MO13	MO20	VC1135
2444795	CS851P	MO5000	MO13	MO20	VC1135
2444799	CS723A	MO5000	AL160	MO40	—
2444801	CS851P	MO5000	MO13	MO40	VC1130
2444803	CS723A	MO5000	AL160	MO40	—
2444808	CS723A	MO5000	AL132	AL124	—
2444809	CS723A	MO5000	AL132	AL124	—
2444810	CS723A	MO5000	AL132	AL124	—
2444811	CS723A	MO5000	AL132	AL124	—
2444813	CS723A	MO5000	AL132	AL124	—
2444814	—	—	AL125	AL129	—

(continued on next page)

⁹ Two required

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
2444816	CS723A	MO5000	AL132	AL124	—
2444821	CS851P	MO5000	MO13	MO40	VC1130
2444823	CS729A	MO5000	MO13	MO40	—
2444840	CS723A	MO5000	AL160	MO40	—
2444841	CS723A	MO5000	AL160	MO40	—
2444842	CS729A	MO5000	AL125	AL124	—
2444851	—	—	AL125	AL129	—
2444853	CS721A	MO5000	AL125	AL129	—
2444858	CS851P	MO5000	MO13	MO20	VC1135
2444859	CS851P	MO5000	MO13	MO20	VC1135
2444867	CS851P	MO5000	MO13	MO20	—
2444869	CS851P	MO5000	MO13	MO20	VC1135
2444873	CS721A ⁹	MO5000	AL125	AL129	—
2444879	CS851P	MO5000	MO13	MO40	VC1225
2444907	CS851P	MO5000	MO13	MO40	VC1130
2444913	CS851P	MO5000	MO13	MO40	VC1130
2444914	CS723A	MO5000	AL160	MO40	—
2444915	CS729A	MO5000	AL125	AL124	—
2444928	CS851P	MO5000	MO13	MO40	VC1130
2444967	CS720P ⁹	MO5000	AL125	AL129	—
2444983	CS720P	MO5000	AL125	—	—
2444986	CS720P	MO5000	AL125	—	—
2444987	CS720P ⁹	MO5000	AL125	AL129	—
2642001	CS851P	MO5000	MO13	MO40	VC1130
2642006	CS851P	MO5000	MO13	MO20	VC1135
2642234	CS851P	MO5000	MO13	MO20	VC1135
2642238	CS851P	MO5000	MO13	MO20	VC1135
2642242	CS721A	MO5000	AL125	AL129	—
2642244	CS851P	MO5000	MO13	MO20	—
2642248	CS851P	MO5000	MO13	MO20	—
2642252	CS851P	MO5000	MO13	MO20	—
2642254	CS851P	MO5000	MO13	MO40	—
2642287	CS851P	MO5000	MO13	MO20	—
2642289	CS851P	MO5000	MO13	MO20	—
2642329	CS851P	MO5000	MO13	MO40	VC1225
2642343	CS851P	MO5000	MO13	MO20	—
2642346	CS851P	MO5000	MO13	MO20	VC1135
2642349	CS851P	MO5000	MO13	MO40	—
2642352	CS851P	MO5000	MO13	MO40	VC1225
2642354	CS851P	MO5000	MO13	MO40	VC1225
2642356	CS851P	MO5000	MO13	MO40	—
2642358	CS721A	MO5000	AL125	AL129	—
2642360	CS851P	MO5000	MO13	MO20	—
2642363	CS851P	MO5000	MO13	MO20	—
2642365	CS851P	MO5000	MO13	MO20	—
2642367	CS851P	MO5000	MO13	MO20	—
2642369	CS851P	MO5000	MO13	MO20	—
2642371	CS851P	MO5000	MO13	MO20	VC1135

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
2642373	CS851P	MO5000	MO13	MO20	—
2642397	CS851P	MO5000	MO13	MO40	—
2642398	CS851P	MO5000	MO13	MO40	VC1225
2642399	CS851P	MO5000	MO13	MO40	VC1225
2642400	CS851P	MO5000	MO13	MO20	VC1225
2642401	CS851P	MO5000	MO13	MO20	—
2642402	CS851P	MO5000	MO13	MO20	—
2642403	CS851P	MO5000	MO13	MO20	—
2642404	CS851P	MO5000	MO13	MO20	VC1135
2642405	CS721A ⁹	MO5000	AL125	AL129	—
2642406	CS851P	MO5000	MO13	MO20	—
2642407	CS851P	MO5000	MO13	MO20	—
2642408	CS851P	MO5000	MO13	MO20	—
2642409	CS851P	MO5000	MO13	MO20	—
2642410	CS851P	MO5000	MO13	MO20	—
2642459	CS851P	MO5000	MO13	MO20	VC1135
2642460	CS851P	MO5000	MO13	MO20	VC1135
2642461	CS721A ⁹	MO5000	AL125	AL129	—
2642464	CS851P	MO5000	MO13	MO20	—
2642465	CS851P	MO5000	MO13	MO20	—
2642466	CS851P	MO5000	MO13	MO20	—
2642472	CS851P	MO5000	MO13	MO20	VC1135
2642482	CS720P	MO5000	AL125	AL129	—
2642484	CS720P	MO5000	AL125	AL129	—
2642507	CS851P	MO5000	MO13	MO40	—
2642508	CS851P	MO5000	MO13	MO40	—
2642513	CS851P	MO5000	MO13	MO40	—
2642531	CS851P	MO5000	MO13	MO20	—
2642532	CS851P	MO5000	MO13	MO20	—
2642535	CS851P	MO5000	MO13	MO20	—
2642536	CS851P	MO5000	MO13	MO20	—
2642551	CS851P	MO5000	MO13	MO20	—
2642554	CS851P	MO5000	MO13	MO20	—
2642591	CS719A	MO5000	AL107	AL106	—
2642607	CS719A	MO5000	AL107	AL128	—
2642608	CS719A	MO5000	AL107	AL106	—
2642718	CS851P	MO5000	MO13	MO20	VC1135
2642719	CS851P	MO5000	MO13	MO20	VC1135
2642721	CS851P	MO5000	MO13	MO20	VC1135
2642722	CS851P	MO5000	MO13	MO20	VC1135
2642724	CS851P	MO5000	MO13	MO20	VC1135
2642725	CS851P	MO5000	MO13	MO20	VC1135
2642727	CS851P	MO5000	MO13	MO20	VC1135
2642728	CS851P	MO5000	MO13	MO20	VC1135
2642730	CS851P	MO5000	MO13	MO20	—
2642731	CS851P	MO5000	MO13	MO20	—
2642745	CS851P	MO5000	MO13	MO20	—
2642746	CS851P	MO5000	MO13	MO20	—

(continued on next page)

⁹ Two required

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control	Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
2642748	CS851P	MO5000	MO13	MO20	—	2875098	CS851P	MO5000	MO13	MO40	—
2642749	CS851P	MO5000	MO13	MO20	—	2875102	CS720P ⁹	MO5000	AL125	AL129	—
2642752	CS851P	MO5000	MO13	MO40	VC1225	2875103	CS720P ⁹	MO5000	AL125	AL129	—
2642753	CS851P	MO5000	MO13	MO40	VC1225	2875105	CS720P ⁹	MO5000	AL125	AL129	—
2642755	CS851P	MO5000	MO13	MO20	VC1225	2875106	CS851P	MO5000	MO13	MO40	VC1225
2642756	CS851P	MO5000	MO13	MO20	VC1225	2875116	CS851P	MO5000	MO13	MO20	VC1135
2642758	CS851P	MO5000	MO13	MO20	—	2875124	CS720P ⁹	MO5000	AL125	AL129	—
2642759	CS851P	MO5000	MO13	MO20	—	2875128	CS851P	MO5000	MO13	MO20	—
2642786	CS851P	MO5000	MO13	MO20	—	2875132	CS851P	MO5000	MO13	MO40	VC1135
2642787	CS851P	MO5000	MO13	MO20	—	2875136	CS851P	MO5000	MO13	MO40	VC1135
2642789	CS851P	MO5000	MO13	MO20	VC1225	2875140	CS720P ⁹	MO5000	AL125	AL129	—
2642790	CS851P	MO5000	MO13	MO20	VC1225	2875141	CS720P ⁹	MO5000	AL125	AL129	—
2642792	CS851P	MO5000	MO13	MO20	—	2875142	CS851P	MO5000	MO13	MO20	—
2642793	CS851P	MO5000	MO13	MO20	—	2875156	CS851P	MO5000	MO13	MO20	—
2642795	CS851P	MO5000	MO13	MO20	VC1225	2875158	CS851P	MO5000	MO13	MO20	—
2642796	CS851P	MO5000	MO13	MO20	VC1225	2875162	CS851P	MO5000	MO13	MO20	—
2642805	CS851P	MO5000	MO13	MO20	VC1135	2875166	CS851P	MO5000	MO13	MO20	—
2642806	CS851P	MO5000	MO13	MO20	VC1135	2875168	CS851P	MO5000	MO13	MO40	—
2642810	CS851P	MO5000	MO13	MO20	—	2875170	CS851P	MO5000	MO13	MO20	—
2642811	CS851P	MO5000	MO13	MO20	—	2875172	CS851P	MO5000	MO13	MO40	—
2642813	CS851P	MO5000	MO13	MO20	—	2875181	CS851P	MO5000	MO13	MO20	—
2642814	CS851P	MO5000	MO13	MO20	—	2875182	CS851P	MO5000	MO13	MO20	—
2642816	CS851P	MO5000	MO13	MO20	—	2875186	CS851P	MO5000	MO13	MO20	—
2642817	CS851P	MO5000	MO13	MO20	—	2875194	CS851P	MO5000	MO13	MO20	—
2642819	CS851P	MO5000	MO13	MO20	—	2875199	CS851P	MO5000	MO13	MO40	VC1225
2642820	CS851P	MO5000	MO13	MO20	—	2875201	CS851P	MO5000	MO13	MO40	VC1225
2642822	CS851P	MO5000	MO13	MO20	—	2875202	CS851P	MO5000	MO13	MO40	VC1225
2642823	CS851P	MO5000	MO13	MO20	—	2875203	CS851P	MO5000	MO13	MO40	VC1225
2642832	CS720P	MO5000	AL125	AL124	—	2875206	CS851P	MO5000	MO13	MO40	VC1130
2642834	CS720P	MO5000	AL125	AL124	—	2875207	CS851P	MO5000	MO13	MO20	—
2642841	CS851P	MO5000	MO13	MO40	VC1225	2875209	CS851P	MO5000	MO13	MO20	—
2642842	CS851P	MO5000	MO13	MO40	VC1225	2875227	CS720P	MO5000	AL125	AL124	—
2642899	CS720P	MO5000	AL125	AL124	—	2875229	CS720P	MO5000	AL125	AL124	—
2642911	CS720P	MO5000	AL125	AL124	—	2875310	CS851P	MO5000	MO13	MO20	—
2642941	CS851P	MO5000	MO13	MO40	—	2875331	CS851P	MO5000	MO13	MO40	VC1130
2642942	CS851P	MO5000	MO13	MO40	—	2875332	CS851P	MO5000	MO13	MO40	VC1225
2642949	CS851P	MO5000	MO13	MO20	—	2875333	CS851P	MO5000	MO13	MO40	VC1225
2642952	CS725A	MO5000	AL104	—	—	2875334	CS851P	MO5000	MO13	MO20	VC1135
2642972	CS851P	MO5000	MO13	MO20	—	2875335	CS851P	MO5000	MO13	MO20	VC1135
2683081	—	EP10	—	—	—	2875338	CS851P	MO5000	MO13	MO20	VC1135
2871168	CS851P	MO5000	MO13	MO40	—	2875339	CS851P	MO5000	MO13	MO20	VC1135
2875001	CS851P	MO5000	MO13	MO20	—	2875340	CS851P	MO5000	MO13	MO20	VC1135
2875021	CS851P	MO5000	MO13	MO20	—	2875341	CS851P	MO5000	MO13	MO20	VC1135
2875069	CS851P	MO5000	MO13	MO40	VC1225	2875342	CS851P	MO5000	MO13	MO20	—
2875078	CS851P	MO5000	MO13	MO40	VC1225	2875343	CS851P	MO5000	MO13	MO20	—
2875086	CS720P ⁹	MO5000	AL125	AL129	—	2875344	CS851P	MO5000	MO13	MO20	—
2875087	CS720P ⁹	MO5000	AL125	AL129	—	2875345	CS851P	MO5000	MO13	MO20	—
2875094	CS851P	MO5000	MO13	MO40	—	2875346	CS851P	MO5000	MO13	MO20	—

(continued on next column)

(continued on next page)

⁹ Two required

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
2875347	CS851P	MO5000	MO13	MO20	—
2875348	CS851P	MO5000	MO13	MO20	—
2875349	CS851P	MO5000	MO13	MO20	—
2875350	CS851P	MO5000	MO13	MO20	—
2875351	CS851P	MO5000	MO13	MO20	—
2875352	CS851P	MO5000	MO13	MO20	—
2875353	CS851P	MO5000	MO13	MO20	—
2875354	CS851P	MO5000	MO13	MO20	—
2875355	CS851P	MO5000	MO13	MO20	—
2875356	CS851P	MO5000	MO13	MO20	—
2875357	CS851P	MO5000	MO13	MO20	—
2875358	CS851P	MO5000	MO13	MO20	—
2875359	CS851P	MO5000	MO13	MO20	—
2875360	CS851P	MO5000	MO13	MO20	—
2875361	CS851P	MO5000	MO13	MO20	—
2875362	CS851P	MO5000	MO13	MO20	—
2875364	CS851P	MO5000	MO13	MO40	—
2875365	CS851P	MO5000	MO13	MO40	—
2875366	CS851P	MO5000	MO13	MO40	—
2875367	CS851P	MO5000	MO13	MO40	—
2875653	CS757P	FA66	FA8000	FA98	—
2875654	CS757P	FA66	FA8000	FA98	—
2875655	CS757P	FA66	FA8000	FA98	—
2875693	CS757P	FA76	FA8000	FA98	—
2875694	CS757P	FA66	FA8000	FA98	—
2875696	CS757P	FA66	FA8000	FA98	—
2875698	CS757P	FA66	FA8000	FA98	—
2875715	CS720P ⁹	MO5000	AL125	AL129	—
2875718	CS720P ⁹	MO5000	AL125	AL129	—
2875731	CS851P	MO5000	MO13	MO20	—
2875732	CS851P	MO5000	MO13	MO20	—
2875742	CS851P	MO5000	MO13	MO20	—
2875743	CS851P	MO5000	MO13	MO20	—
2875747	CS851P	MO5000	MO13	MO20	—
2875748	CS851P	MO5000	MO13	MO20	—
2875750	CS851P	MO5000	MO13	MO20	—
2875751	CS851P	MO5000	MO13	MO20	—
2875758	CS851P	MO5000	MO13	MO20	—
2875759	CS851P	MO5000	MO13	MO20	—
2875764	CS851P	MO5000	MO13	MO20	—
2875765	CS851P	MO5000	MO13	MO20	—
2875770	CS851P	MO5000	MO13	MO20	—
2875771	CS851P	MO5000	MO13	MO20	—
2875772	CS720P ⁹	MO5000	AL125	AL129	—
2875773	CS720P ⁹	MO5000	AL125	AL129	—
2875779	CS851P	MO5000	MO13	MO20	—
2875780	CS851P	MO5000	MO13	MO20	—
2875782	CS721A ⁹	MO5000	AL125	AL124	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
2875783	CS721A ⁹	MO5000	AL125	AL124	—
2875790	CS851P	MO5000	MO13	MO20	—
2875791	CS851P	MO5000	MO13	MO20	—
2875796	CS851P	MO5000	MO13	MO20	VC3008
2875797	CS851P	MO5000	MO13	MO20	VC3008
2875800	CS851P	MO5000	MO13	MO20	VC3008
2875801	CS851P	MO5000	MO13	MO20	VC3008
2875804	CS851P	MO5000	MO13	—	—
2875805	CS851P	MO5000	MO13	—	—
2875813	CS851P	MO5000	MO13	MO40	—
2875814	CS851P	MO5000	MO13	MO40	—
2875822	CS851P	MO5000	MO13	MO40	—
2875823	CS851P	MO5000	MO13	MO40	—
2875826	CS851P	MO5000	MO13	MO40	VC3008
2875827	CS851P	MO5000	MO13	MO40	VC3008
2875830	CS851P	MO5000	MO13	MO40	—
2875831	CS851P	MO5000	MO13	MO40	—
2875833	CS851P	MO5000	MO13	MO40	—
2875834	CS851P	MO5000	MO13	MO40	—
2875838	CS851P	MO5000	MO13	MO40	—
2875839	CS851P	MO5000	MO13	MO40	—
2875842	CS851P	MO5000	MO13	MO40	—
2875843	CS851P	MO5000	MO13	MO40	—
2875846	CS720P ⁹	MO5000	AL125	AL129	—
2875847	CS720P ⁹	MO5000	AL125	AL129	—
2875855	CS851P	MO5000	MO13	MO40	—
2875856	CS851P	MO5000	MO13	MO40	—
2875876	CS729A	MO5000	AL125	AL129	—
2875877	CS729A	MO5000	AL125	AL129	—
2875901	CS851P	MO5000	MO13	MO20	—
2875919	CS851P	MO5000	MO13	MO20	—
2875920	CS851P	MO5000	MO13	MO20	—
2875966	CS851P	MO5000	MO13	MO20	—
2875982	CS720P ⁹	MO5000	AL125	AL129	—
2875983	CS720P ⁹	MO5000	AL125	AL129	—
2875985	CS851P	MO5000	MO13	MO20	—
2875986	CS851P	MO5000	MO13	MO20	—
2875987	CS720P ⁹	MO5000	AL125	AL129	—
2875988	CS720P ⁹	MO5000	AL125	AL129	—
2875989	CS720P ⁹	MO5000	AL125	AL129	—
2875990	CS720P ⁹	MO5000	AL125	AL129	—
2879339	CS757P	FA66	FA8000	FA98	—
2879396	CS757P	FA66	FA8000	FA98	—
2959339	CS757P	FA66	FA8000	FA98	—
2959396	CS757P	FA66	FA8000	FA98	—
3430309	CS851P	MO5000	MO13	MO40	—
3430310	CS851P	MO5000	MO13	MO40	—
3438219	CS851P	MO5000	MO13	MO20	VC3015

(continued on next page)

⁹ Two required

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
3438221	CS851P	MO5000	MO13	MO20	VC3015
3438222	CS851P	MO5000	MO13	MO20	VC3015
3438224	CS851P	MO5000	MO13	MO20	VC3015
3438225	CS851P	MO5000	MO13	MO20	VC3015
3438226	CS851P	MO5000	MO13	MO20	VC3015
3438227	CS851P	MO5000	MO13	MO40	VC3008
3438228	CS851P	MO5000	MO13	MO40	VC3008
3438231	CS851P	MO5000	MO13	MO20	VC3015
3438232	CS851P	MO5000	MO13	MO20	VC3015
3438233	CS851P	MO5000	MO13	MO20	VC3015
3438234	CS851P	MO5000	MO13	MO20	VC3015
3438237	CS851P	MO5000	MO13	MO40	VC3008
3438238	CS851P	MO5000	MO13	MO40	VC3008
3438255	CS851P	MO5000	MO13	MO20	—
3438256	CS851P	MO5000	MO13	MO20	—
3438306	CS851P	MO5000	MO13	MO40	—
3438307	CS851P	MO5000	MO13	MO40	—
3438309	CS851P	MO5000	MO13	MO20	—
3438314	CS720P ⁹	MO5000	AL125	AL129	—
3438316	CS720P ⁹	MO5000	AL125	AL129	—
3438317	CS720P ⁹	MO5000	AL125	AL129	—
3438318	CS720P ⁹	MO5000	AL125	AL129	—
3438325	CS851P	MO5000	MO13	MO20	—
3438326	CS851P	MO5000	MO13	MO20	—
3438348	CS720P ⁹	MO5000	AL125	AL129	—
3438349	CS720P ⁹	MO5000	AL125	AL129	—
3438355	CS720P ⁹	MO5000	AL125	AL129	—
3438356	CS720P ⁹	MO5000	AL125	AL129	—
3438422	CS851P	MO5000	MO13	MO20	VC3011
3438423	CS851P	MO5000	MO13	MO20	VC3011
3438433	CS851P	MO5000	MO13	MO20	—
3438434	CS851P	MO5000	MO13	MO20	—
3438440	CS851P	MO5000	MO13	MO20	—
3438441	CS851P	MO5000	MO13	MO20	—
3438442	CS851P	MO5000	MO13	MO20	VC3011
3438443	CS851P	MO5000	MO13	MO20	VC3011
3438453	CS851P	MO5000	MO13	MO20	—
3438454	CS851P	MO5000	MO13	MO20	—
3438509	CS851P	MO5000	MO13	MO40	—
3438510	CS851P	MO5000	MO13	MO40	—
3438517	CS851P	MO5000	MO13	MO20	VC3015
3438520	CS851P	MO5000	MO13	MO20	VC3015
3438521	CS721A ⁹	MO5000	AL125	AL129	—
3438522	CS721A ⁹	MO5000	AL125	AL129	—
3438523	CS721A ⁹	MO5000	AL125	AL129	—
3438524	CS851P	MO5000	MO13	MO40	VC3011
3438525	CS851P	MO5000	MO13	MO40	VC3011
3438530	CS721A ⁹	MO5000	AL125	AL129	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
3438531	CS721A ⁹	MO5000	AL125	AL129	—
3438532	CS721A ⁹	MO5000	AL125	AL129	—
3438534	CS851P	MO5000	MO13	MO20	—
3438535	CS851P	MO5000	MO13	MO20	—
3438544	CS851P	MO5000	MO13	MO20	—
3438545	CS851P	MO5000	MO13	MO20	—
3438559	CS851P	MO5000	MO13	MO20	—
3438560	CS851P	MO5000	MO13	MO20	—
3438577	CS720P ⁹	MO5000	AL125	AL129	—
3438578	CS720P ⁹	MO5000	AL125	AL129	—
3438579	CS720P ⁹	MO5000	AL125	AL129	—
3438580	CS720P ⁹	MO5000	AL125	AL129	—
3438588	CS720P	MO5000	AL125	AL124	—
3438615	CS721A ⁹	MO5000	AL125	AL129	—
3438616	CS721A ⁹	MO5000	AL125	AL129	—
3438617	CS721A ⁹	MO5000	AL125	AL129	—
3438618	CS721A ⁹	MO5000	AL125	AL129	—
3438690	CS851P	MO5000	MO13	MO20	—
3438691	CS851P	MO5000	MO13	MO20	—
3438694	CS851P	MO5000	MO13	MO20	—
3438695	CS851P	MO5000	MO13	MO20	—
3438774	CS725A	—	AL62	—	—
3438832	CS720P	MO5000	AL125	AL124	—
3438891	—	—	MO13	MO20	—
3438893	—	—	MO13	MO20	—
3438896	—	—	MO13	MO20	—
3497087	—	—	FA8000	—	—
3497096	—	—	FA8000	—	—
3497896	CS757P	FA66	FA8000	FA98	—
3565151	—	—	MO13	MO20	—
3656237	CS851P	MO5000	MO13	MO40	—
3656238	CS851P	MO5000	MO13	MO40	—
3656243	CS851P	MO5000	MO13	MO40	—
3656244	CS851P	MO5000	MO13	MO40	—
3656246	CS851P	MO5000	MO13	MO40	—
3656247	CS851P	MO5000	MO13	MO40	—
3656248	CS851P	MO5000	MO13	MO40	—
3656249	CS851P	MO5000	MO13	MO40	—
3656252	CS851P	MO5000	MO13	MO40	—
3656253	CS851P	MO5000	MO13	MO40	—
3656257	CS851P	MO5000	MO13	MO40	—
3656258	CS851P	MO5000	MO13	MO40	—
3656260	CS851P	MO5000	MO13	MO40	—
3656261	CS851P	MO5000	MO13	MO40	—
3656266	CS851P	MO5000	MO13	MO40	—
3656267	CS851P	MO5000	MO13	MO40	—
3656269	CS851P	MO5000	MO13	MO40	—
3656270	CS851P	MO5000	MO13	MO40	—

(continued on next page)

⁹ Two required

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
3656272	CS851P	MO5000	MO13	MO40	—
3656273	CS851P	MO5000	MO13	MO40	—
3656275	CS851P	MO5000	MO13	MO40	—
3656276	CS851P	MO5000	MO13	MO40	—
3656283	CS851P	MO5000	MO13	MO20	—
3656284	CS851P	MO5000	MO13	MO20	—
3656287	CS851P	MO5000	MO13	MO20	VC3008
3656288	CS851P	MO5000	MO13	MO20	VC3008
3656294	CS851P	MO5000	MO13	MO20	—
3656295	CS851P	MO5000	MO13	MO20	—
3656329	CS851P	MO5000	MO13	MO20	—
3656330	CS851P	MO5000	MO13	MO20	—
3656332	CS851P	MO5000	MO13	MO20	—
3656333	CS851P	MO5000	MO13	MO20	—
3656344	CS851P	MO5000	MO13	MO20	—
3656345	CS851P	MO5000	MO13	MO20	—
3656350	CS851P	MO5000	MO13	MO20	—
3656351	CS851P	MO5000	MO13	MO20	—
3656359	CS851P	MO5000	MO13	MO20	—
3656360	CS851P	MO5000	MO13	MO20	—
3656365	CS851P	MO5000	MO13	MO20	—
3656366	CS851P	MO5000	MO13	MO20	—
3656373	CS729A	MO5000	AL125	AL129	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
3656374	CS729A	MO5000	AL125	AL129	—
3656375	CS757P	FA76	FA8000	FA98	—
3656376	CS757P	FA76	FA8000	FA98	—
3656377	CS757P	FA76	FA8000	FA98	—
3656378	CS757P	FA76	FA8000	FA98	—
3656379	CS757P	FA76	FA8000	FA98	—
3656380	CS757P	FA76	FA8000	FA98	—
3656390	CS851P	MO5000	MO13	MO20	—
3656391	CS851P	MO5000	MO13	MO20	—
3656593	CS851P	MO5000	MO13	MO20	—
3656594	CS851P	MO5000	MO13	MO20	—
3656775	CS757P	FA66	FA8000	FA98	—
3656776	CS757P	FA66	FA8000	FA98	—
3656777	CS757P	FA66	FA8000	FA98	—
3656778	CS757P	FA66	FA8000	FA98	—
3656779	CS757P	FA66	FA8000	FA98	—
3656780	CS757P	FA66	FA8000	FA98	—
3656834	CS851P	MO5000	MO13	MO20	—
3656835	CS851P	MO5000	MO13	MO20	—
71244496	CS207A	EP29	EP41	EP48	—
71261566	CS207A	EP29	EP41	EP48	—

DELCO REMY

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
622A	—	—	RR74	RR302	—
622B	—	—	RR74	RR302	—
622C	—	—	RR74	RR302	—
622D	CS765	RR174	RR74	RR302	—
622E	CS765	RR174	RR74	RR302	—
622F	—	—	RR74	RR302	—
622G	CS779A	—	RR99	RR100	—
622H	—	—	RR74	RR302	—
622J	CS765	RR174	RR74	RR302	—
622K	CS765	RR174	RR74	RR302	—
622L	CS765	—	RR74	RR302	—
622M	CS765	RR174	—	—	—
622N	CS765	RR174	RR74	RR302	—
622P	CS765	—	RR74	RR302	—
622R	CS765	RR174	RR74	RR302	—
622S	CS765	RR176	RR74	RR302	—
622T	—	—	RR74	RR302	—
622U	—	—	RR74	RR302	—
622V	CS765	RR176	RR74	RR302	—
622W	CS765	RR176	RR74	RR302	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
622X	—	—	RR74	RR302	—
622Y	CS765	—	RR74	RR302	—
622Z	CS765	—	RR74	RR302	—
623A	CS765	RR176	RR74	RR302	—
623B	CS765	—	RR74	RR302	—
623C	CS765	RR174	RR74	RR302	—
623D	CS765	RR176	RR74	RR302	—
623E	CS765	—	RR74	RR302	—
623F	CS765	—	RR74	RR302	—
623G	CS765	RR174	RR74	RR302	—
623H	CS765	RR176	RR74	RR302	—
623J	CS765	RR174	RR74	RR302	—
623K	CS765	RR176	RR74	RR302	—
623L	CS765	RR174	RR74	—	—
623M	CS765	RR176	RR74	—	—
623N	CS765	—	RR74	—	—
623P	CS765	RR176	RR74	RR302	—
623R	CS765	RR174	RR74	RR302	—
623S	CS765	RR176	RR74	RR302	—
623T	CS765	RR174	RR74	RR302	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
625A	CS765	RR174	RR74	—	—
625B	CS765	RR174	RR74	—	—
625C	CS765	RR174	RR74	—	—
625D	CS765	RR174	RR74	—	—
625E	CS765	RR174	RR74	—	—
625F	CS765	RR174	RR74	—	—
625G	CS765	RR174	RR74	—	—
625H	CS765	RR174	RR74	—	—
625J	CS765	RR174	RR74	—	—
625K	CS765	—	RR74	—	—
625L	CS765	—	RR74	—	—
625M	CS765	—	RR74	—	—
625Z	CS765	—	RR74	—	—
629A	—	—	RR74	—	—
629B	—	—	RR74	—	—
629C	—	—	RR74	—	—
629D	—	—	RR74	—	—
629E	—	—	RR74	—	—
629G	—	—	RR74	—	—
629H	—	—	RR74	—	—
629J	—	—	RR74	—	—
629K	—	—	RR74	—	—
629L	—	—	RR74	—	—
629M	—	—	RR74	—	—
629N	—	—	RR74	—	—
629P	—	—	RR74	—	—
629R	—	—	RR74	—	—
629S	—	—	RR74	—	—
629T	—	—	RR74	—	—
629U	—	—	RR74	—	—
629V	—	—	RR74	—	—
629W	—	—	RR74	—	—
629X	—	—	RR74	—	—
629Y	—	—	RR74	—	—
629Z	—	—	RR74	—	—
632B	CS765	RR176	RR74	RR302	—
632C	CS765	RR176	RR74	RR302	—
632D	—	—	RR74	RR302	—
632E	—	—	RR74	RR302	—
632F	—	—	RR74	RR302	—
632G	—	—	RR74	RR302	—
632H	—	—	RR74	RR302	—
632J	—	—	RR74	RR302	—
632K	—	—	RR74	RR302	—
632L	—	—	RR74	RR302	—
632M	—	—	RR74	RR302	—
632N	—	—	RR74	RR302	—
632P	—	—	RR74	RR302	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
632R	—	—	RR74	RR302	—
632S	—	—	RR74	RR302	—
632V	—	—	RR74	RR302	—
632W	—	—	RR74	RR302	—
632Y	—	—	RR74	RR302	—
632Z	—	—	RR74	RR302	—
634A	—	—	—	RR145	—
634B	—	—	—	RR145	—
635A	—	—	RR74	—	—
635B	—	—	RR74	—	—
635C	—	—	RR74	—	—
635E	—	—	RR74	—	—
635F	—	—	RR74	—	—
635G	—	—	RR74	—	—
635H	—	—	RR74	—	—
635J	—	—	RR74	—	—
635K	—	—	RR74	—	—
635L	—	—	RR74	—	—
635M	—	—	RR74	—	—
635N	—	—	RR74	—	—
635P	—	—	RR74	—	—
635S	—	—	RR74	—	—
635T	—	—	RR74	—	—
635U	—	—	RR74	—	—
635V	—	—	RR74	—	—
635W	—	—	RR74	—	—
635X	—	—	RR74	—	—
635Y	—	—	RR74	—	—
635Z	—	—	RR74	—	—
637V	—	—	RR74	RR302	—
639W	CS765	—	RR74	RR302	—
640A	CS763A	RR174	RR83	—	—
640B	CS763A	RR174	RR83	RR142	—
640C	CS763A	RR174	RR83	RR142	—
640D	CS763A	RR174	RR83	RR142	—
640E	CS763A	RR174	RR83	RR142	—
640F	CS763A	RR174	RR83	RR142	—
640G	CS763A	RR174	RR83	—	—
640H	CS763A	RR174	RR83	RR142	—
640J	CS763A	RR174	RR83	RR142	—
640K	CS763A	RR174	RR83	RR142	—
640L	CS763A	RR174	RR83	RR142	—
640M	CS763A	RR174	RR83	—	—
640R	CS763A	RR174	RR83	RR142	—
640S	CS763A	RR174	RR83	—	—
640T	CS763A	RR174	RR83	RR142	—
640U	CS763A	RR174	RR83	RR142	—
640V	—	—	RR83	RR142	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
640W	CS763A	RR174	RR83	RR142	—
640X	CS763A	RR174	RR83	RR142	—
640Y	CS763A	RR174	RR83	RR142	—
640Z	CS763A	RR174	RR83	RR142	—
641C	CS763A	—	RR83	RR95	—
642A	CS763A	RR174	RR83	RR142	—
642B	CS763A	RR174	RR83	RR142	—
642C	CS763A	RR174	RR83	RR142	—
642D	CS763A	RR174	RR83	RR142	—
642E	CS763A	RR174	RR83	RR142	—
642F	CS763A	RR174	RR83	RR142	—
642G	CS763A	RR174	RR83	RR142	—
642H	CS763A	RR174	RR83	RR142	—
642J	CS763A	RR174	RR83	RR142	—
642M	CS763A	RR174	RR83	—	—
642N	CS763A	RR174	RR83	—	—
642P	CS763A	RR174	RR83	RR142	—
642R	CS763A	RR174	RR83	—	—
642S	CS763A	RR174	RR83	RR142	—
642T	CS763A	RR174	RR83	RR142	—
642U	CS763A	RR174	RR83	—	—
642V	CS763A	RR174	RR83	—	—
642W	CS763A	RR174	RR83	RR142	—
642X	CS763A	RR174	RR83	RR142	—
642Y	CS763A	RR174	RR83	—	—
642Z	CS763A	RR174	RR83	—	—
643A	CS763A	RR174	RR83	RR142	—
643B	CS763A	RR174	RR83	RR142	—
643C	CS763A	RR174	RR83	RR142	—
643D	CS763A	RR174	RR83	RR142	—
643E	CS763A	RR174	RR83	RR142	—
643F	CS763A	RR174	RR83	RR142	—
643G	CS763A	RR174	RR83	RR142	—
643H	CS763A	RR174	RR83	RR142	—
643J	CS763A	RR174	RR83	RR142	—
643K	CS763A	RR174	RR83	RR142	—
643L	CS763A	RR174	RR83	—	—
643M	CS763A	RR174	RR83	RR142	—
643MA	CS763A	RR174	RR83	RR142	—
643N	CS763A	RR174	RR83	—	—
643P	CS763A	RR174	RR83	—	—
643R	CS763A	RR174	RR83	RR142	—
643S	CS763A	RR174	RR83	RR142	—
643T	CS763A	RR174	RR83	—	—
643U	CS763A	RR174	RR83	—	—
643V	CS763A	RR174	RR83	RR142	—
643W	CS763A	RR174	RR83	RR142	—
643X	CS763A	RR174	RR83	RR142	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
643Y	CS763A	RR174	RR83	RR142	—
643Z	CS763A	RR174	RR83	RR142	—
644A	CS763A	RR174	RR83	RR142	—
644B	CS763A	RR176	RR83	RR142	—
644C	CS763A	RR174	RR83	RR142	—
644D	CS763A	RR176	RR83	RR142	—
644E	CS763A	RR174	RR83	RR142	—
644F	CS763A	RR174	RR83	RR142	—
644G	CS763A	RR176	RR83	RR142	—
644H	CS763A	RR176	RR83	RR142	—
644J	CS763A	RR176	RR83	RR142	—
644K	CS763A	RR176	RR83	RR142	—
644L	CS763A	RR176	RR83	RR142	—
644M	CS763A	RR174	RR83	RR142	—
644N	CS763A	RR176	RR83	RR142	—
644P	CS763A	RR176	RR83	RR142	—
644R	CS763A	RR176	RR83	RR142	—
644S	CS763A	RR176	RR83	RR142	—
644T	CS763A	RR174	RR83	—	—
644U	CS763A	RR176	RR83	RR142	—
644V	CS763A	RR174	RR83	RR142	—
644W	CS763A	RR176	RR83	RR142	—
644X	—	—	RR83	RR142	—
644Y	CS763A	RR176	RR83	RR142	—
644Z	CS763A	RR176	RR83	RR142	—
645A	CS763A	RR174	RR83	RR142	—
645B	CS763A	RR174	RR83	RR142	—
645C	CS763A	RR174	RR83	RR142	—
645D	CS763A	RR174	RR83	RR142	—
645E	CS763A	RR174	RR83	RR142	—
645G	CS763A	RR174	RR83	RR142	—
645H	CS763A	RR174	RR83	RR142	—
645J	CS763A	RR174	RR83	RR142	—
645K	CS763A	RR174	RR83	RR142	—
645L	CS763A	RR174	RR83	—	—
645M	CS763A	RR176	RR83	RR142	—
645N	CS763A	RR176	RR83	RR142	—
645P	CS763A	RR176	RR83	RR142	—
645R	CS763A	RR176	RR83	RR142	—
645S	CS763A	RR174	RR83	RR142	—
645T	CS763A	RR176	RR83	RR142	—
645U	CS763A	RR174	RR83	RR142	—
645V	CS763A	RR174	RR83	—	—
645W	CS763A	RR174	RR83	RR142	—
645X	CS763A	RR174	RR83	RR142	—
645Z	CS763A	RR174	RR83	RR142	—
647A	CS779A	—	RR83	RR142	—
647B	CS779A	—	RR83	RR142	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
647C	CS779A	—	RR83	RR142	—
647D	CS777A	RR174	RR83	RR142	—
647E	CS777A	RR174	RR83	RR142	—
647F	CS777A	RR174	RR83	RR142	—
647G	CS778A	RR174	RR83	RR142	—
647H	CS778A	RR174	RR83	RR142	—
647J	CS778A	RR174	RR83	—	—
647K	CS777A	—	RR83	RR142	—
649A	CS763A	RR174	RR83	RR142	—
649B	CS763A	RR174	RR83	RR142	—
649C	CS763A	RR174	RR83	RR142	—
649D	CS763A	RR174	RR83	—	—
649E	CS763A	RR174	RR83	RR142	—
649F	CS763A	RR174	RR83	RR142	—
649G	CS763A	RR174	RR83	RR142	—
649H	CS763A	RR174	RR83	RR142	—
649J	CS763A	RR174	RR83	RR142	—
649K	CS763A	RR174	RR83	—	—
649L	CS763A	RR174	RR83	RR142	—
649M	CS763A	RR174	RR83	RR142	—
649N	CS763A	RR174	RR83	RR142	—
649P	CS763A	RR174	RR83	RR142	—
649R	CS763A	RR174	RR83	RR142	—
649S	CS763A	RR174	RR83	RR142	—
649T	CS763A	RR174	RR83	RR142	—
649U	CS763A	RR174	RR83	RR142	—
649V	CS763A	RR174	RR83	—	—
649W	CS763A	—	—	—	—
649X	CS763A	—	—	—	—
649Y	CS763A	RR174	RR83	RR142	—
649Z	CS763A	RR174	RR83	RR142	—
656A	—	—	—	RR142	—
656E	CS779A	—	RR83	—	—
656F	CS779A	—	RR83	—	—
656H	CS779A	—	RR83	—	—
656J	CS779A	—	RR83	—	—
656K	CS779A	—	RR83	—	—
656L	CS779A	—	RR83	—	—
656M	CS779A	—	RR83	—	—
656N	CS779A	—	RR83	—	—
656P	CS779A	—	RR83	—	—
656Q	CS779A	—	RR83	—	—
656R	CS779A	—	RR83	—	—
656T	CS779A	—	RR83	—	—
656U	CS779A	—	RR83	—	—
656W	CS779A	—	RR83	—	—
656X	CS779A	—	RR83	—	—
656Y	CS779A	—	RR83	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
656Z	CS779A	—	RR83	—	—
660A	CS779A	—	RR99	—	—
660B	CS779A	—	RR99	RR100	—
660C	CS779A	—	RR99	RR100	—
660D	CS779A	—	RR99	RR100	—
660E	CS779A	—	RR99	RR100	—
660F	CS779A	—	RR99	—	—
660G	CS779A	—	RR99	RR100	—
660J	CS779A	—	RR99	—	—
660K	CS779A	—	RR99	—	—
660L	CS779A	—	RR99	RR100	—
660M	CS779A	—	RR99	—	—
660N	CS779A	—	RR99	RR100	—
660P	CS779A	—	RR99	—	—
660S	CS779A	RR174	RR99	—	—
660T	CS779A	RR174	RR99	—	—
660U	CS779A	RR174	RR99	RR100	—
660V	CS779A	RR174	RR99	RR100	—
660W	CS779A	RR174	RR99	RR100	—
660X	CS779A	—	RR99	RR100	—
660Y	CS779A	—	RR99	RR100	—
660Z	CS779A	—	RR99	—	—
661B	CS779A	—	RR99	—	—
661C	CS779A	RR174	RR99	—	—
661D	CS779A	RR174	RR99	RR100	—
661E	CS779A	RR174	RR99	—	—
661F	CS779A	RR174	RR99	—	—
661G	CS779A	RR174	RR99	RR100	—
661J	CS779A	RR174	RR99	RR100	—
661K	CS779A	RR174	RR99	RR100	—
661L	CS779A	RR174	RR99	RR100	—
661M	CS779A	RR174	RR99	RR100	—
661N	CS779A	RR174	RR99	—	—
661P	CS779A	RR174	—	RR100	—
661R	CS779A	RR174	—	RR100	—
661S	CS779A	RR174	—	RR100	—
661T	CS779A	RR174	—	RR100	—
661U	CS779A	RR174	RR99	—	—
661V	CS779A	RR174	RR99	RR100	—
661W	CS779A	RR174	RR99	RR100	—
661X	CS779A	RR174	RR99	RR100	—
661Y	CS779A	—	RR99	RR100	—
661Z	CS779A	RR174	RR99	—	—
662A	CS779A	—	RR99	—	—
662B	CS779A	—	RR99	RR100	—
662C	CS779A	—	RR99	RR100	—
662E	CS779A	—	RR99	RR100	—
662F	CS779A	—	RR99	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
662G	CS779A	—	RR99	—	—
662H	CS779A	—	RR99	—	—
662J	CS779A	—	RR99	—	—
662K	CS779A	—	RR99	RR100	—
662M	CS779A	—	RR99	—	—
662N	CS779A	—	RR99	RR100	—
662P	CS779A	—	RR99	RR100	—
662R	CS779A	—	RR99	RR100	—
662T	CS779A	—	RR99	—	—
662W	—	—	RR99	—	—
662Y	CS779A	—	RR99	RR100	—
663A	CS779A	RR174	RR99	RR100	—
663B	CS779A	RR174	RR99	RR100	—
663C	CS779A	RR174	RR99	RR100	—
663D	—	—	RR99	RR100	—
663E	—	—	RR99	RR100	—
663F	—	—	RR99	RR100	—
663G	—	—	RR99	RR100	—
663H	—	—	RR99	RR100	—
663J	—	—	RR99	RR100	—
663K	—	—	RR99	RR100	—
663L	—	—	RR99	—	—
663M	—	—	RR99	—	—
663W	—	—	RR99	RR100	—
663X	—	—	RR99	RR100	—
663Y	—	—	RR99	RR100	—
663Z	—	—	RR99	RR100	—
663ZX	—	—	RR99	RR100	—
664B	—	—	RR83	RR145	—
664C	—	—	RR83	RR145	—
664D	—	—	RR83	RR145	—
664E	—	—	RR83	RR145	—
664F	—	—	RR83	RR145	—
664G	—	—	RR83	RR145	—
665A	—	—	RR99	RR100	—
665B	—	—	RR99	RR100	—
665C	—	—	RR99	RR100	—
665E	—	—	RR99	RR100	—
665F	—	—	RR99	RR100	—
665G	—	—	RR99	RR100	—
665H	—	—	RR99	—	—
666B	CS779A	—	—	—	—
666C	CS779A	—	—	—	—
666D	CS779A	—	—	—	—
666E	CS779A	—	—	—	—
666F	CS779A	—	—	—	—
666G	CS779A	—	—	—	—
4059	CS779A	—	—	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
4060	CS779A	—	—	—	—
4061	CS779A	—	—	—	—
4062	CS779A	—	—	—	—
4063	CS779A	—	—	—	—
4065	CS779A	—	—	—	—
4070	CS779A	—	—	—	—
4071	CS779A	—	—	—	—
4071X	CS779A	—	—	—	—
4078	CS779A	—	—	—	—
4079	CS779A	—	—	—	—
4082	CS779A	—	—	—	—
4085	CS779A	—	—	—	—
4088	CS779A	—	—	—	—
4089	CS779A	—	—	—	—
4090	CS779A	—	—	—	—
4097	CS779A	—	—	—	—
4098	CS779A	—	—	—	—
4099	CS779A	—	—	—	—
4101	CS779A	—	—	—	—
4102	CS779A	—	—	—	—
4104	CS779A	—	—	—	—
4106	CS779A	—	—	—	—
4107	CS779A	—	—	—	—
4108	CS779A	—	—	—	—
4109	CS779A	—	—	—	—
4114	CS779A	—	—	—	—
4115	CS779A	—	—	—	—
4116	CS779A	—	—	—	—
4117	CS779A	—	—	—	—
4119	CS779A	—	—	—	—
4121	CS779A	—	—	—	—
4127	CS779A	—	—	—	—
4128	CS779A	—	—	—	—
4133	CS779A	—	—	—	—
4135	CS779A	—	—	—	—
4136	CS779A	—	—	—	—
4137	CS779A	—	—	—	—
4139	CS779A	—	—	—	—
4140	CS779A	—	—	—	—
4144	CS779A	—	—	—	—
4146	CS779A	—	—	—	—
4147	CS779A	—	—	—	—
4152	CS779A	—	—	—	—
4154	CS779A	—	—	—	—
4155	CS779A	—	—	—	—
4156	CS779A	—	—	—	—
4158	CS777A	—	—	—	—
4161	CS779A	—	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
4162	CS779A	—	—	—	—
4163	CS779A	—	—	—	—
4164	CS779A	—	—	—	—
4165	CS777A	—	—	—	—
4169	CS779A	—	—	—	—
4170	CS779A	—	—	—	—
4178	CS779A	—	—	—	—
4181	CS777A	—	—	—	—
4183	CS777A	—	—	—	—
4189	CS777A ⁹	—	—	—	—
4190	CS778A ⁹	—	—	—	—
4191	CS777A ⁹	—	—	—	—
4193	CS778A ⁹	—	—	—	—
4196	CS777A ⁹	—	—	—	—
4197	CS778A ⁹	—	—	—	—
4198	CS779A	—	—	—	—
4199	CS779A	—	—	—	—
4200	CS779A	—	—	—	—
4202	CS779A	RR174	—	—	—
4204	CS779A	—	—	—	—
4205	CS777A ⁹	—	—	—	—
4207	CS777A ⁹	—	—	—	—
4208	CS777A ⁹	—	—	—	—
4209	CS779A	—	—	—	—
4212	CS779A	—	—	—	—
4213	CS779A	—	—	—	—
4214	CS779A	—	—	—	—
4216	CS779A	—	—	—	—
4217	CS777A ⁹	—	—	—	—
4221	CS778A ⁹	—	—	—	—
4222	CS777A ⁹	—	—	—	—
4224	CS779A	—	—	—	—
4225	—	—	—	RR95	—
4226	CS779A	—	—	—	—
4227	CS777A ⁹	RR174	—	—	—
4228	CS777A ⁹	RR174	—	—	—
4229	CS778A ⁹	—	—	—	—
4230	CS777A ⁹	—	—	—	—
4231	CS777A ⁹	—	—	—	—
4234	CS777A ⁹	—	—	—	—
4238	CS779A	—	—	—	—
4239	CS779A	—	—	—	—
4240	CS779A	—	—	—	—
4243	CS779A	—	—	—	—
4244	CS779A	—	—	—	—
4245	CS779A	—	—	—	—
4248	—	—	—	RR95	—
4250	—	—	—	RR95	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
4258	—	—	—	RR95	—
41679	CS779A	—	—	—	—
1100628	CS779A	RR174	RR99	—	—
1100629	CS779A	RR174	RR99	—	—
1110001	CS763A	—	—	—	—
1110002	CS763A	RR174	RR83	RR95	—
1110003	CS763A	RR174	RR83	RR95	—
1110004	CS763A	RR174	RR83	RR95	—
1110005	CS763A	RR174	RR83	RR95	—
1110006	CS763A	RR174	RR83	RR95	—
1110007	CS763A	RR174	RR83	RR95	—
1110008	CS763A	RR174	RR83	RR95	—
1110009	CS763A	—	—	RR95	—
1110010	CS763A	—	RR83	RR95	—
1110011	CS763A	—	—	RR95	—
1110012	CS763A	RR174	RR83	—	—
1110013	CS763A	—	RR83	RR95	—
1110014	CS763A	RR174	RR83	RR95	—
1110015	CS763A	RR174	RR83	RR95	—
1110016	CS763A	—	—	—	—
1110017	CS763A	—	—	RR95	—
1110018	CS763A	—	RR83	RR95	—
1110019	CS763A	RR174	RR83	RR95	—
1110020	CS763A	RR174	RR83	RR95	—
1110021	CS763A	RR174	RR83	RR95	—
1110022	CS763A	RR174	RR83	—	—
1110023	CS763A	RR174	RR83	RR95	—
1110024	CS763A	RR174	RR83	RR145	—
1110025	CS763A	—	—	—	—
1110026	CS763A	RR174	RR83	RR95	—
1110027	CS763A	RR174	RR83	—	—
1110028	CS763A	RR174	RR83	—	—
1110029	CS763A	—	—	—	—
1110030	CS763A	RR174	RR83	RR95	—
1110031	CS763A	RR174	RR83	RR95	—
1110032	CS763A	—	—	—	—
1110033	CS763A	RR174	RR83	—	—
1110034	CS763A	RR174	RR83	RR95	—
1110035	CS763A	RR174	RR83	—	—
1110036	CS763A	RR174	RR83	RR95	—
1110037	CS763A	RR174	RR83	—	—
1110039	CS763A	—	—	—	—
1110040	CS763A	RR174	RR83	—	—
1110041	CS763A	RR174	RR83	—	—
1110042	CS763A	—	RR83	—	—
1110043	CS763A	RR174	RR83	RR95	—
1110044	CS763A	RR174	RR83	RR95	—
1110045	CS763A	RR174	RR83	RR95	—

(continued on next page)

⁹ Two required

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1110046	CS763A	—	—	—	—
1110047	CS763A	—	—	—	—
1110048	CS763A	—	RR83	RR95	—
1110049	CS763A	RR174	RR83	RR95	—
1110050	CS763A	—	—	—	—
1110051	CS763A	RR174	RR83	RR95	—
1110052	CS763A	RR174	RR83	RR95	—
1110053	CS763A	—	—	—	—
1110054	CS763A	—	—	—	—
1110055	CS763A	RR174	RR83	RR95	—
1110056	CS763A	RR174	RR83	—	—
1110057	CS763A	RR174	RR83	RR95	—
1110058	CS763A	—	—	—	—
1110059	CS763A	—	—	—	—
1110060	CS763A	RR174	RR83	—	—
1110061	CS763A	—	RR83	RR95	—
1110062	CS763A	RR174	RR83	RR95	—
1110063	CS763A	RR174	RR83	RR95	—
1110065	CS763A	RR174	RR83	RR95	—
1110066	—	—	RR169R	RR165	—
1110067	CS763A	—	—	—	—
1110069	CS763A	RR174	RR83	RR95	—
1110070	CS763A	RR174	RR83	RR95	—
1110071	CS763A	RR174	—	—	—
1110072	CS763A	—	—	—	—
1110073	CS763A	RR174	RR83	RR95	—
1110074	CS763A	RR174	RR83	RR95	—
1110075	CS763A	RR174	RR83	RR95	—
1110076	CS763A	RR174	RR83	—	—
1110077	CS763A	RR174	RR83	—	—
1110078	CS763A	RR174	RR83	—	—
1110079	CS763A	—	—	—	—
1110080	CS763A	—	RR83	RR95	—
1110081	CS763A	RR174	RR83	RR95	—
1110082	CS763A	RR174	RR83	RR95	—
1110083	CS763A	RR174	RR83	—	—
1110084	CS763A	RR174	RR83	RR95	—
1110085	CS763A	RR174	RR83	RR95	—
1110086	CS763A	RR174	RR83	RR95	—
1110087	CS763A	RR174	RR83	RR95	—
1110088	CS763A	RR174	RR83	RR95	—
1110089	CS763A	RR174	RR83	RR95	—
1110090	CS763A	RR174	RR83	RR95	—
1110091	CS763A	RR174	RR83	RR95	—
1110092	CS763A	RR174	RR83	RR95	—
1110093	CS763A	RR174	RR83	—	—
1110094	CS763A	RR174	RR83	RR95	—
1110095	CS763A	RR174	RR83	RR95	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1110096	CS763A	RR174	RR83	RR95	—
1110097	CS763A	RR174	RR83	—	—
1110098	CS763A	—	—	—	—
1110099	CS763A	RR174	RR83	RR95	—
1110100	CS763A	—	RR83	RR95	—
1110101	CS763A	—	RR83	RR95	—
1110102	CS763A	RR174	RR83	RR95	—
1110103	CS763A	RR174	RR83	RR95	—
1110104	CS763A	RR174	RR83	RR95	—
1110105	CS763A	—	—	RR95	—
1110106	CS763A	—	RR83	RR95	—
1110107	CS763A	RR174	RR83	RR95	—
1110108	CS763A	RR174	RR83	—	—
1110109	CS763A	RR174	RR83	—	—
1110110	CS763A	RR174	RR83	RR95	—
1110111	CS779A	RR174	RR83	RR95	—
1110112	CS763A	RR174	RR83	RR95	—
1110113	CS763A	RR174	RR83	RR95	—
1110114	CS763A	RR174	RR83	—	—
1110115	CS763A	—	RR83	RR95	—
1110116	CS763A	RR174	RR83	RR95	—
1110117	CS763A	RR174	RR83	RR95	—
1110118	CS763A	RR174	RR83	RR95	—
1110119	CS763A	RR174	RR83	RR95	—
1110120	CS763A	RR174	RR83	RR95	—
1110121	CS779A	—	—	—	—
1110122	CS763A	RR174	RR83	RR95	—
1110123	CS763A	RR174	RR83	RR95	—
1110124	CS763A	RR174	RR83	RR95	—
1110125	CS763A	RR174	RR83	RR95	—
1110126	CS763A	RR174	RR83	RR95	—
1110128	CS763A	RR174	RR83	RR95	—
1110129	CS763A	—	—	—	—
1110130	CS763A	RR174	RR83	RR95	—
1110131	CS763A	—	—	—	—
1110132	CS763A	RR174	RR83	RR95	—
1110133	CS763A	RR174	RR83	RR95	—
1110134	CS763A	RR174	RR83	RR95	—
1110135	CS763A	RR174	RR83	RR95	—
1110136	CS763A	RR174	RR83	RR95	—
1110137	CS763A	RR174	RR83	—	—
1110138	CS763A	RR174	RR83	RR95	—
1110139	CS763A	RR174	RR83	RR95	—
1110140	CS763A	RR174	RR83	RR95	—
1110141	CS763A	—	—	—	—
1110142	CS763A	—	—	—	—
1110143	CS763A	—	—	—	—
1110144	CS763A	—	—	RR95	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1110145	CS763A	RR174	RR83	—	—
1110146	CS763A	RR174	RR83	RR95	—
1110147	CS763A	RR174	RR83	RR95	—
1110148	CS763A	RR174	RR83	RR95	—
1110149	CS763A	RR174	RR83	RR95	—
1110150	CS763A	RR174	RR83	RR95	—
1110151	CS763A	RR174	RR83	RR95	—
1110152	CS763A	RR174	RR83	RR95	—
1110153	CS763A	—	RR83	RR95	—
1110154	CS763A	—	RR83	—	—
1110156	CS763A	RR174	RR83	RR95	—
1110157	CS763A	RR174	RR83	RR95	—
1110159	CS763A	RR174	RR83	RR95	—
1110160	CS763A	RR174	RR83	RR95	—
1110161	CS763A	RR174	RR83	RR95	—
1110162	CS763A	RR174	RR83	RR95	—
1110163	CS763A	RR174	RR83	RR95	—
1110164	CS763A	RR174	RR83	—	—
1110165	CS763A	RR174	RR83	RR95	—
1110167	CS763A	RR174	RR83	RR95	—
1110168	CS763A	RR174	RR83	RR95	—
1110169	CS763A	RR174	RR83	RR95	—
1110170	CS763A	RR174	RR83	RR95	—
1110172	CS763A	RR174	RR83	—	—
1110173	CS763A	RR174	RR83	—	—
1110174	CS763A	RR174	RR83	RR95	—
1110175	CS763A	RR174	RR83	RR95	—
1110176	CS763A	RR174	RR83	RR95	—
1110177	CS763A	RR174	RR83	RR95	—
1110178	CS763A	RR174	RR83	RR95	—
1110179	CS763A	RR174	RR83	RR95	—
1110180	CS763A	RR174	RR83	RR95	—
1110181	CS763A	RR174	RR83	RR95	—
1110182	CS763A	RR174	RR83	RR95	—
1110183	CS763A	RR174	RR83	RR95	—
1110184	CS763A	RR174	RR83	RR95	—
1110185	CS763A	RR174	RR83	RR95	—
1110187	CS763A	RR174	RR83	RR95	—
1110188	CS763A	RR174	RR83	RR95	—
1110189	CS763A	RR174	RR83	—	—
1110190	CS763A	RR174	RR83	RR95	—
1110191	CS763A	RR174	RR83	RR95	—
1110192	CS763A	RR174	RR83	RR95	—
1110193	CS763A	RR174	—	—	—
1110194	CS763A	RR174	RR83	—	—
1110195	CS763A	RR174	RR83	RR95	—
1110196	CS763A	RR174	RR83	—	—
1110197	CS763A	RR174	RR83	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1110198	CS763A	RR174	RR83	RR95	—
1110199	CS763A	RR174	RR83	RR95	—
1110200	CS763A	RR174	RR83	—	—
1110201	CS777A ⁹	—	—	—	—
1110202	CS777A ⁹	RR174	RR83	RR95	—
1110203	CS777A ⁹	RR174	RR83	RR95	—
1110204	CS777A ⁹	RR174	RR83	RR95	—
1110205	CS778A ⁹	—	RR83	RR95	—
1110206	CS778A ⁹	RR174	RR83	RR95	—
1110209	CS777A ⁹	RR174	RR83	RR95	—
1110210	CS777A ⁹	RR174	RR83	RR95	—
1110211	CS778A ⁹	RR174	RR83	RR95	—
1110212	CS778A ⁹	RR174	RR83	—	—
1110213	CS777A ⁹	RR174	RR83	RR95	—
1110214	CS777A ⁹	RR174	RR83	RR95	—
1110216	CS778A ⁹	RR174	RR83	RR95	—
1110217	CS777A ⁹	RR174	RR83	—	—
1110219	CS777A ⁹	RR174	RR83	—	—
1110220	CS777A ⁹	RR174	RR83	RR95	—
1110221	CS777A ⁹	RR174	RR83	RR95	—
1110222	CS777A ⁹	RR174	RR83	RR95	—
1110223	CS778A ⁹	RR174	RR83	RR95	—
1110224	CS777A ⁹	RR174	RR83	RR95	—
1110225	CS778A ⁹	RR174	RR83	RR95	—
1110227	CS778A ⁹	RR174	RR83	RR95	—
1110229	CS777A ⁹	RR174	RR83	RR95	—
1110230	CS777A ⁹	RR174	RR83	RR145	—
1110231	CS777A ⁹	RR174	RR83	RR95	—
1110232	CS777A ⁹	RR174	RR83	RR95	—
1110233	CS777A ⁹	RR174	RR83	RR95	—
1110234	CS777A ⁹	RR174	RR161	RR162	—
1110235	CS777A ⁹	RR174	RR161	RR162	—
1110236	CS786P	RR175	RR169R	RR165	—
1110236	CS791	RR175	RR169R	RR165	—
1110237	CS777A ⁹	RR174	RR83	RR95	—
1110241	CS778A ⁹	RR174	RR161	RR162	—
1110242	CS777A ⁹	RR174	RR161	RR162	—
1110244	CS777A ⁹	RR174	RR161	RR162	—
1110246	CS777A ⁹	RR174	RR161	RR162	—
1110248	CS786P	RR175	RR169R	RR179	—
1110249	CS777A ⁹	RR174	RR83	RR95	—
1110250	CS786P	RR174	RR169R	RR179	—
1110251	CS777A ⁹	RR174	RR83	RR95	—
1110252	CS787	RR176	RR178	RR177	—
1110253	CS777A ⁹	RR174	RR83	RR145	—
1110254	CS786P	RR175	RR169R	RR180	VC680
1110255	CS777A ⁹	RR174	RR83	RR145	—
1110256	CS787	RR176	RR178	RR177	—

(continued on next page)

⁹ Two required

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control	Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1110257	CS787	RR176	RR178	RR177	—	1110310	CS788P	RR176	RR182R	RR183	VC1420
1110258	CS787	RR176	RR178	RR177	—	1110311	CS788P	RR176	RR182R	RR183	VC1420
1110259	CS787	RR176	RR178	RR177	—	1110314	CS788P	RR176	RR182R	RR183	—
1110260	CS787	RR176	RR178	RR177	—	1110316	CS788P	RR176	RR182R	RR183	VC1415
1110261	CS786P	RR175	RR169R	RR180	VC680	1110317	CS788P	RR174	RR182R	RR183	—
1110262	CS786P	RR175	RR169R	RR179	—	1110318	CS788P	RR174	RR182R	RR183	VC1420
1110263	CS786P	RR176	RR169R	RR179	—	1110319	CS788P	RR176	RR182R	RR183	VC1415
1110264	CS777A ⁹	RR174	RR83	RR95	—	1110320	CS788P	RR174	RR182R	RR183	VC1420
1110265	CS777A ⁹	RR174	RR83	RR145	—	1110321	CS788P	RR176	RR182R	RR183	VC1415
1110266	CS786P	RR175	RR169R	RR180	—	1110322	CS786P	RR174	RR185	RR184	VC680
1110267	CS788P	RR176	RR182R	RR183	VC1420	1110323	CS788P	RR176	RR182R	RR181	VC1420
1110268	CS788P	RR176	RR182R	RR181	VC1420	1110324	CS788P	RR176	RR182R	RR183	VC1415
1110269	CS788P	RR176	RR182R	RR183	VC1420	1110328	CS788P	RR176	RR182R	RR183	—
1110270	CS786P	RR174	RR169R	RR180	—	1110329	CS788P	RR176	RR182R	RR183	—
1110271	CS788P	RR176	RR182R	RR183	VC1420	1110330	CS788P	RR176	RR182R	RR183	—
1110272	CS788P	RR176	RR182R	RR183	VC1420	1110331	CS788P	RR176	RR182R	RR183	—
1110274	CS786P	RR174	RR169R	RR180	—	1110334	CS788P	RR176	RR182R	RR183	—
1110275	CS787	RR176	RR178	RR177	—	1110335	CS786P	RR174	RR185	RR184	VC680
1110276	—	—	RR83	RR95	—	1110336	CS788P	RR176	RR182R	RR183	VC1415
1110277	CS786P	RR174	RR169R	RR179	—	1110337	CS788P	RR176	RR182R	RR183	VC1420
1110278	CS788P	RR176	RR182R	RR183	VC1420	1110338	CS788P	RR176	RR182R	RR183	VC1420
1110279	CS786P	RR174	RR169R	RR179	VC680	1110339	CS788P	RR176	RR182R	RR183	VC1420
1110280	CS788P	RR176	—	RR183	VC1415	1110340	CS788P	RR176	RR182R	RR183	VC1420
1110281	CS788P	RR176	RR182R	RR183	—	1110341	CS788P	RR176	RR182R	RR183	—
1110282	CS786P	RR175	RR169R	RR180	—	1110342	CS786P	RR174	RR185	RR184	VC680
1110283	CS786P	RR175	RR169R	RR180	—	1110343	CS788P	RR176	RR182R	RR183	—
1110284	CS788P	RR176	RR182R	RR181	VC1415	1110351	CS788P	RR176	RR182R	RR183	VC1415
1110285	CS788P	RR176	RR182R	RR181	VC1415	1110358	CS788P	RR176	RR182R	RR183	—
1110286	CS786P	RR174	RR185	RR184	VC680	1110359	CS788P	RR176	RR182R	RR183	—
1110287	CS786P	RR175	RR169R	—	—	1110360	CS788P	RR176	RR182R	RR183	VC1415
1110289	CS788P	RR176	RR182R	RR183	VC1420	1110361	CS788P	RR176	RR182R	RR183	VC1415
1110290	CS788P	RR176	RR182R	RR183	—	1110362	CS788P	RR176	RR182R	RR183	VC1415
1110291	CS786P	RR174	RR185	RR184	VC680	1110363	CS788P	RR176	RR182R	RR183	VC1415
1110292	CS788P	RR176	RR182R	RR181	VC1420	1110364	CS788P	RR176	RR182R	RR183	VC1420
1110293	CS788P	RR176	RR182R	RR183	VC1415	1110366	CS788P	RR176	RR182R	RR183	VC1420
1110294	CS788P	RR176	RR182R	RR183	VC1420	1110368	CS788P	RR176	RR182R	RR183	VC1420
1110295	CS788P	RR176	RR182R	RR183	VC1420	1110369	CS788P	RR176	RR182R	RR183	VC1420
1110296	CS788P	RR176	RR182R	RR183	VC1420	1110370	CS788P	RR176	RR182R	RR183	VC1420
1110297	CS788P	RR176	RR182R	RR183	VC1420	1110371	CS788P	RR176	RR182R	RR183	—
1110298	CS788P	RR176	RR182R	RR183	—	1110372	CS788P	RR176	RR182R	RR183	VC1420
1110299	CS788P	RR176	RR182R	RR183	—	1110373	CS788P	RR176	RR182R	RR183	VC1415
1110300	CS788P	RR176	RR182R	RR181	VC1415	1110374	CS788P	RR176	RR182R	RR183	VC1415
1110302	CS788P	RR176	RR182R	RR183	VC1420	1110375	CS788P	RR176	RR182R	RR183	VC1420
1110305	CS788P	RR176	RR182R	RR183	—	1110376	CS786P	RR175	RR185	RR189	VC680
1110306	CS788P	RR176	RR182R	RR183	—	1110377	CS788P	RR176	RR182R	RR183	VC1420
1110307	CS788P	RR176	RR182R	RR183	VC1420	1110378	CS788P	RR176	RR182R	RR183	—
1110308	CS788P	RR176	RR182R	RR183	—	1110379	CS788P	RR176	RR182R	RR183	—
1110309	CS786P	RR174	RR185	RR184	VC680	1110381	CS788P	RR176	RR182R	RR183	VC1415

(continued on next column)

(continued on next page)

⁹Two required

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1110382	CS788P	RR176	RR182R	RR183	VC1415
1110383	CS788P	RR176	RR182R	RR183	—
1110384	CS788P	RR176	RR182R	RR183	—
1110385	CS788P	RR176	RR182R	RR183	—
1110387	CS788P	RR176	RR182R	RR183	VC1415
1110388	CS788P	RR176	RR182R	RR183	VC1415
1110389	CS788P	RR176	RR182R	RR183	VC1420
1110390	CS788P	RR176	RR182R	RR183	VC1415
1110391	CS788P	RR176	RR182R	RR183	—
1110392	CS788P	RR176	RR182R	RR183	VC1415
1110393	CS788P	RR176	RR182R	RR183	—
1110395	CS788P	RR176	RR182R	RR183	VC1415
1110396	CS788P	RR176	RR182R	RR183	—
1110397	CS788P	RR176	RR182R	RR183	—
1110398	CS788P	RR176	RR182R	RR183	—
1110399	CS788P	RR176	RR182R	RR183	VC1420
1110401	CS765	RR174	RR74	RR106	—
1110402	CS765	RR174	RR74	RR106	—
1110403	CS765	RR174	RR74	RR106	—
1110404	CS765	RR174	RR74	RR106	—
1110405	CS765	RR174	RR74	RR106	—
1110406	CS765	RR174	RR74	RR106	—
1110407	CS765	RR174	RR74	RR106	—
1110408	CS765	RR174	RR74	RR106	—
1110409	CS765	RR174	RR74	RR106	—
1110410	CS765	RR174	RR74	RR106	—
1110411	CS765	RR174	RR74	RR106	—
1110412	CS765	RR174	RR74	RR106	—
1110413	CS765	RR174	RR74	RR106	—
1110414	CS765	RR174	RR74	RR106	—
1110415	CS765	RR174	RR74	RR106	—
1110416	CS765	RR174	RR74	RR106	—
1110417	CS765	RR174	RR74	RR106	—
1110418	CS765	RR174	RR74	RR106	—
1110419	CS765	RR174	RR74	RR106	—
1110420	CS765	RR174	RR74	RR106	—
1110421	CS765	RR174	RR74	RR106	—
1110423	CS765	RR174	RR74	—	—
1110424	CS765	RR174	RR74	—	—
1110425	CS765	RR174	RR74	—	—
1110426	CS788P	RR176	RR182R	RR181	VC1420
1110427	CS788P	RR176	RR182R	RR183	—
1110428	CS788P	RR176	RR182R	RR183	—
1110429	CS788P	RR176	RR182R	RR183	—
1110430	CS788P	RR176	RR182R	RR183	—
1110431	CS788P	RR176	RR182R	RR183	—
1110433	CS788P	RR176	RR182R	RR183	VC1420
1110434	—	—	RR182R	RR183	VC1420

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1110435	CS788P	RR176	RR182R	RR181	—
1110436	CS788P	RR176	RR182R	RR183	VC1420
1110437	CS788P	RR176	RR182R	RR183	VC1420
1110438	CS788P	RR176	RR182R	RR183	VC1420
1110439	CS788P	RR176	RR182R	RR183	VC1420
1110440	CS788P	RR176	RR182R	RR183	VC1420
1110441	CS788P	RR176	RR182R	RR183	VC1420
1110442	CS788P	RR176	RR182R	RR183	VC1420
1110443	CS788P	RR176	RR182R	RR183	VC1420
1110444	CS788P	RR176	RR182R	RR183	VC1420
1110445	CS788P	RR176	RR182R	RR183	—
1110446	CS788P	RR176	RR182R	RR183	—
1110447	CS788P	RR176	RR182R	RR181	VC1420
1110448	CS788P	RR176	RR182R	RR183	—
1110449	CS788P	RR176	RR182R	RR183	—
1110451	CS788P	RR176	RR182R	RR183	—
1110452	—	—	RR182R	RR183	VC1420
1110453	—	—	RR182R	RR183	VC1420
1110454	—	—	RR182R	RR183	VC1420
1110455	—	—	RR182R	RR183	VC1420
1110457	CS788P	RR176	RR182R	RR181	VC1420
1110458	CS788P	RR176	RR182R	RR181	VC1420
1110459	CS788P	RR176	RR182R	RR183	VC1420
1110460	CS788P	RR176	RR182R	RR183	VC1420
1110461	CS788P	RR176	RR182R	RR183	VC1420
1110462	CS788P	RR176	RR182R	RR183	VC1420
1110463	CS788P	RR176	RR182R	RR183	VC1420
1110464	CS788P	RR176	RR182R	RR183	VC1420
1110465	CS788P	RR176	RR182R	RR183	VC1420
1110466	CS788P	RR176	RR182R	RR183	VC1420
1110467	CS788P	RR176	RR182R	RR183	VC1420
1110468	CS788P	RR176	RR182R	RR183	VC1420
1110469	CS788P	RR176	RR182R	RR183	VC1420
1110470	CS788P	RR176	RR182R	RR183	VC1420
1110471	CS788P	RR176	RR182R	RR183	VC1415
1110472	CS788P	RR176	RR182R	RR183	—
1110473	CS788P	RR176	RR182R	RR183	—
1110474	CS788P	RR176	RR182R	RR183	VC1813
1110475	CS788P	RR176	RR182R	RR183	VC1813
1110478	CS788P	RR176	RR182R	RR183	—
1110479	CS788P	RR176	RR182R	RR183	VC1420
1110481	CS788P	RR176	RR182R	RR183	—
1110482	CS788P	RR176	RR182R	RR183	VC1420
1110483	CS788P	RR176	RR182R	RR183	VC1420
1110485	CS788P	RR176	RR182R	RR183	VC1420
1110486	CS788P	RR176	RR182R	RR183	—
1110489	CS788P	RR176	RR182R	RR183	VC1420
1110492	CS788P	RR176	RR182R	RR181	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1110493	CS788P	RR176	RR182R	RR183	—
1110494	CS788P	RR176	RR182R	RR181	—
1110496	CS788P	RR176	RR182R	RR181	—
1110497	CS788P	RR176	RR182R	RR183	VC1813
1110498	CS788P	RR176	RR182R	RR183	—
1110499	CS788P	RR174	RR182R	RR183	—
1110500	CS788P	RR176	RR182R	RR183	—
1110501	CS765	RR174	RR74	—	—
1110502	CS765	RR174	RR74	—	—
1110503	CS765	RR174	RR74	—	—
1110504	CS765	RR174	RR74	—	—
1110505	CS765	RR174	RR74	—	—
1110506	CS765	RR174	RR74	—	—
1110507	CS765	RR174	RR74	—	—
1110508	CS765	RR174	RR74	—	—
1110509	CS765	RR174	RR74	—	—
1110510	CS765	RR174	RR74	—	—
1110511	CS765	RR174	RR74	—	—
1110512	CS765	RR174	RR74	—	—
1110513	CS765	RR174	RR74	—	—
1110514	CS765	RR174	RR74	—	—
1110515	CS765	RR174	RR74	—	—
1110518	CS788P	RR176	RR182R	RR183	—
1110520	CS788P	RR176	RR182R	RR183	—
1110522	CS788P	RR176	RR182R	RR183	—
1110523	CS788P	RR176	RR182R	RR183	—
1110524	CS788P	RR176	RR182R	RR183	—
1110525	CS788P	RR176	RR182R	RR181	—
1110527	CS788P	RR176	RR182R	RR181	—
1110528	CS788P	RR176	RR182R	RR183	—
1110529	CS788P	RR176	RR182R	RR181	—
1110530	CS788P	RR176	RR182R	RR181	—
1110531	CS788P	RR176	RR182R	RR181	—
1110532	CS788P	RR176	RR182R	RR181	—
1110533	CS788P	RR176	RR182R	RR181	—
1110534	CS788P	RR176	RR182R	RR181	—
1110536	CS788P	RR176	RR182R	RR183	—
1110537	—	—	RR182R	RR181	—
1110540	CS788P	RR174	RR182R	RR181	—
1110541	CS788P	RR174	RR182R	RR181	—
1110542	CS788P	RR174	RR182R	RR183	—
1110543	—	—	RR182R	RR181	—
1110544	—	—	RR182R	RR183	—
1110545	—	—	RR182R	RR181	—
1110546	—	—	RR182R	RR181	—
1110547	CS788P	RR174	RR182R	RR183	—
1110601	CS765	—	RR99	RR100	—
1110603	CS779A	—	RR99	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1110604	CS779A	RR174	RR99	RR100	—
1110605	CS779A	—	RR99	RR100	—
1110606	CS779A	RR174	RR99	RR100	—
1110607	CS779A	RR174	RR99	RR100	—
1110609	CS779A	RR174	RR99	RR100	—
1110610	CS779A	RR174	RR99	RR100	—
1110611	CS779A	RR174	RR99	RR100	—
1110612	CS777A ⁹	RR174	—	—	—
1110614	CS779A	RR174	RR99	—	—
1110616	CS779A	RR174	RR99	—	—
1110617	CS779A	RR174	RR99	—	—
1110618	CS779A	RR174	RR99	—	—
1110619	CS777A ⁹	RR174	RR157	RR158	—
1110620	CS777A ⁹	RR174	RR157	RR158	—
1110621	CS777A ⁹	RR174	RR157	RR158	—
1110622	CS779A	RR174	RR99	—	—
1110623	CS777A ⁹	RR174	RR157	RR158	—
1110624	CS777A ⁹	RR174	RR157	RR158	—
1110625	CS777A ⁹	RR174	RR157	RR158	—
1110626	CS777A ⁹	RR174	RR157	RR158	—
1110627	CS777A ⁹	RR174	RR157	RR158	—
1110628	CS779A	RR174	RR99	RR100	—
1110629	CS779A	RR174	RR99	RR100	—
1110630	CS777A ⁹	RR174	RR157	RR158	—
1110631	CS777A ⁹	RR174	RR157	RR158	—
1110632	CS777A ⁹	RR174	RR157	RR158	—
1110633	CS777A ⁹	RR174	RR157	RR158	—
1110634	CS779A	RR174	RR99	—	—
1110635	CS777A ⁹	RR174	RR157	RR158	—
1110636	CS786P	RR174	RR169R	RR165	—
1110637	CS786P	RR176	RR169R	RR168	—
1110638	CS786P	RR176	RR169R	RR168	—
1110639	CS786P	RR176	RR169R	RR168	—
1110640	CS777A ⁹	RR176	RR157	RR158	—
1110643	CS89	RR176	RR169R	RR165	—
1110644	CS89	RR176	RR169R	RR165	—
1110645	CS89	RR176	RR169R	RR165	—
1110646	CS89	RR176	RR169R	RR165	—
1110648	CS777A ⁹	RR174	RR157	RR158	—
1110669	CS788P	RR176	RR182R	RR183	—
1110670	CS788P	RR176	RR182R	RR183	—
1110671	CS788P	RR176	RR182R	RR183	—
1110701	CS788P	RR176	RR182R	RR181	—
1110801	CS777A ⁹	RR174	RR99	RR100	—
1110802	CS777A ⁹	RR174	RR99	RR100	—
1110803	CS777A ⁹	RR174	RR99	—	—
1110804	CS777A ⁹	RR174	RR99	RR100	—
1110805	CS777A ⁹	RR174	RR99	RR100	—

(continued on next page)

⁹Two required

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1110806	CS778A ⁹	RR174	RR99	RR100	—
1110807	CS778A ⁹	RR174	RR99	RR100	—
1110808	CS777A ⁹	RR174	RR99	RR100	—
1110811	CS777A ⁹	RR174	RR99	RR100	—
1110812	CS777A ⁹	RR174	—	RR100	—
1110813	CS777A ⁹	RR174	RR99	—	—
1110814	CS777A ⁹	RR174	RR99	RR100	—
1110815	CS777A ⁹	RR174	RR99	RR100	—
1110816	CS777A ⁹	RR174	RR99	—	—
1110817	CS777A ⁹	RR174	RR99	RR100	—
1110818	CS777A ⁹	RR174	RR99	RR100	—
1110819	CS777A ⁹	RR174	—	RR100	—
1110820	CS777A ⁹	RR174	RR159	RR158	—
1110822	CS777A ⁹	RR174	RR159	RR158	—
1110823	CS777A ⁹	RR174	RR99	—	—
1110824	CS777A ⁹	RR174	RR159	RR158	—
1110825	CS777A ⁹	RR174	RR99	RR100	—
1110826	CS777A ⁹	RR174	RR159	RR158	—
1110827	CS778A ⁹	RR174	RR159	RR158	—
1110828	CS777A ⁹	RR174	RR157	RR158	—
1110829	CS778A ⁹	RR174	RR159	RR158	—
1110831	CS777A ⁹	RR174	RR99	RR100	—
1110832	CS777A ⁹	RR174	—	RR100	—
1110833	CS777A ⁹	RR174	RR159	RR158	—
1110835	CS777A ⁹	RR174	RR159	RR158	—
1110836	CS777A ⁹	RR174	RR159	RR158	—
1110838	CS777A ⁹	RR174	—	RR100	—
1110839	CS777A ⁹	RR174	RR159	RR158	—
1110841	CS777A ⁹	RR174	RR159	RR158	—
1110843	CS777A ⁹	RR174	RR159	RR158	—
1110844	CS777A ⁹	RR174	RR159	RR158	—
1110845	CS777A ⁹	RR174	RR159	RR158	—
1110847	CS778A ⁹	RR174	RR157	RR158	—
1110848	CS777A ⁹	RR174	RR159	RR158	—
1110849	CS778A ⁹	RR174	RR159	RR158	—
1110850	CS777A ⁹	RR174	RR159	RR158	—
1110852	CS777A ⁹	RR174	RR159	RR158	—
1110854	CS777A ⁹	RR174	RR159	RR158	—
1110855	CS778A ⁹	RR174	RR159	RR158	—
1110857	CS786P	RR175	RR169R	RR165	—
1110858	CS786P	RR175	RR169R	RR165	—
1110859	CS786P	RR175	RR169R	RR165	—
1110860	CS786P	RR174	RR157	RR158	—
1110861	CS778A ⁹	RR174	RR159	RR158	—
1110862	CS777A ⁹	RR174	RR157	RR158	—
1110863	CS777A ⁹	RR174	RR159	RR158	—
1110864	CS777A ⁹	RR174	RR159	RR158	—
1110865	CS777A ⁹	RR174	RR159	RR158	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1110866	CS778A ⁹	RR174	RR157	RR158	—
1110867	CS786P	RR175	RR169R	RR165	—
1110868	CS786P	RR175	RR169R	RR165	—
1110869	CS778A ⁹	RR174	RR157	RR158	—
1110870	CS786P	RR175	RR169R	RR165	—
1110871	CS786P	RR175	RR169R	RR165	—
1110872	CS777A ⁹	RR174	RR157	RR158	—
1110873	CS777A ⁹	RR174	RR159	RR158	—
1110874	CS786P	RR175	RR169R	RR165	—
1110875	CS777A ⁹	RR174	RR157	RR158	—
1110876	CS786P	RR175	RR169R	RR165	—
1110877	CS786P	RR175	RR169R	RR165	—
1110878	CS778A ⁹	RR174	RR157	RR158	—
1110879	CS777A ⁹	RR174	RR157	RR158	—
1110880	CS777A ⁹	RR174	RR159	RR158	—
1110883	CS786P	RR175	RR169R	RR165	—
1110884	CS786P	RR175	RR169R	RR165	—
1110887	CS786P	RR175	RR169R	RR165	—
1110888	CS777A ⁹	RR174	RR157	RR158	—
1110889	CS777A ⁹	RR174	RR157	RR158	—
1110890	CS786P	RR175	RR169R	RR165	—
1110891	CS786P	RR174	RR157	RR158	—
1110892	CS786	—	—	—	—
1110894	CS786P	RR175	RR169R	RR165	—
1110896	CS777A ⁹	RR174	RR159	RR158	—
1110897	CS777A ⁹	RR174	RR157	RR158	—
1110898	CS786P	RR175	RR169R	RR165	—
1110899	CS777A ⁹	RR174	RR159	RR158	—
1110905	CS777A ⁹	RR174	—	RR158	—
1110906	CS777A ⁹	RR174	RR157	RR158	—
1110907	CS786P	RR175	RR169R	RR165	—
1110908	CS777A ⁹	RR174	—	RR158	—
1110909	CS786P	RR175	RR169R	RR165	—
1110912	CS786P	RR175	RR169R	RR165	VC1605
1110913	CS786P	RR175	RR169R	RR165	—
1110914	CS786P	—	RR169R	RR165	—
1110915	CS786P	RR175	RR169R	RR165	—
1110919	CS786P	—	RR169R	RR165	—
1110920	CS786P	RR175	RR169R	RR165	—
1110921	CS777A ⁹	—	—	—	—
1110922	CS777A ⁹	—	—	—	—
1110923	CS786P	RR175	RR169R	RR165	—
1110924	CS786P	RR175	RR169R	RR165	—
1110925	CS786P	RR175	RR169R	RR165	—
1110926	CS786P	RR175	RR169R	RR165	—
1110927	CS786P	RR175	RR169R	RR165	—
1110929	CS786P	RR175	RR169R	RR165	—
1110930	CS786P	RR175	RR169R	RR165	—

(continued on next page)

⁹ Two required

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1110931	CS786P	RR175	RR169R	RR168	VC700
1110932	CS786P	RR175	RR169R	RR165	—
1110933	CS786P	RR175	RR169R	RR165	—
1110934	CS786P	RR175	RR169R	RR165	—
1110935	CS777A ⁹	RR174	RR157	RR158	—
1110936	CS786P	RR175	RR169R	RR165	—
1110937	CS777A ⁹	RR174	RR159	RR158	—
1110938	CS777A ⁹	RR174	RR159	RR158	—
1110941	CS786P	RR175	RR169R	RR165	—
1110942	CS786P	RR175	RR169R	RR165	—
1110943	CS786P	RR175	RR169R	RR165	—
1110946	CS786P	RR175	RR169R	RR165	VC680
1110947	CS786P	RR175	RR169R	RR165	VC680
1110948	CS786P	RR175	RR169R	RR165	VC680
1110949	CS786P	RR175	RR169R	RR165	—
1110950	CS786P	RR175	RR169R	RR165	VC680
1110952	CS786P	RR175	RR169R	RR165	—
1110953	CS786P	RR175	RR169R	RR165	—
1110954	CS786P	RR175	RR169R	RR165	—
1110955	CS786P	RR175	RR169R	RR165	—
1110956	CS786P	RR175	RR169R	RR165	—
1110957	CS777A ⁹	RR174	RR159	RR158	—
1110958	CS777A ⁹	RR174	RR159	RR158	—
1110959	CS786P	RR175	RR169R	RR165	—
1110960	CS777A ⁹	RR174	RR159	RR158	—
1110961	CS786P	RR175	RR169R	RR165	VC680
1110962	CS786P	RR175	RR169R	RR165	VC680
1110963	CS786P	RR175	RR169R	RR165	VC680
1110964	CS786P	RR175	RR169R	RR165	—
1110965	CS786P	RR175	RR169R	RR165	—
1110966	CS786P	RR175	—	—	—
1110967	CS786P	RR175	RR169R	RR165	—
1110968	CS786P	RR175	RR169R	RR168	VC700
1110969	CS786P	RR175	—	RR165	—
1110970	CS786P	RR175	RR169R	RR165	VC680
1110971	CS786P	RR175	RR169R	RR165	VC680
1110972	CS786P	RR175	—	RR165	—
1110973	CS786P	RR174	RR169R	RR165	—
1110975	CS786P	RR174	RR169R	RR165	VC700
1110976	CS777A	RR174	RR157	RR158	—
1110977	CS786P	RR174	RR169R	RR165	—
1110978	CS786P	RR175	RR169R	RR165	—
1110979	CS786P	RR175	RR169R	RR165	—
1110980	CS777A ⁹	RR174	RR159	RR158	—
1110981	CS786P	RR175	—	RR165	—
1110982	CS786P	RR175	—	RR165	—
1110983	CS786P	RR174	RR169R	RR165	—
1110984	CS786P	RR175	RR169R	RR165	VC680

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1110985	CS786P	RR175	RR169R	RR165	VC680
1110987	CS786P	RR175	RR169R	RR165	VC680
1110988	CS786P	RR175	RR169R	RR165	VC700
1110989	CS786P	RR175	RR169R	RR168	VC700
1110990	CS786P	—	RR169R	RR165	—
1110991	CS786P	RR174	RR169R	RR165	—
1110992	CS786P	RR174	RR169R	RR165	VC700
1110993	CS786P	RR175	RR169R	RR165	VC680
1110996	CS786P	RR175	RR169R	RR165	VC680
1110997	CS786P	RR175	RR169R	RR165	VC680
1110998	CS786P	RR174	RR169R	RR165	—
1110999	CS786P	RR175	RR169R	RR165	VC680
1111001	CS786P	RR175	RR169R	RR165	VC700
1111002	CS786P	RR175	RR169R	—	—
1111004	CS786P	RR175	RR169R	RR168	VC700
1111005	CS786P	RR175	RR169R	RR142	—
1111006	CS786P	RR175	RR169R	RR165	VC680
1111007	CS786P	RR174	RR169R	RR165	VC680
1111011	CS786P	—	RR169R	RR165	—
1111012	CS786P	RR174	RR169R	RR165	VC1420
1111013	CS786P	RR174	RR169R	RR165	VC680
1111014	CS786P	RR175	RR169R	RR165	VC700
1111015	CS786P	RR175	RR169R	RR165	VC680
1111016	CS786P	RR175	RR169R	RR165	VC680
1111020	CS786P	RR175	RR169R	RR165	VC680
1111021	CS786P	RR174	RR169R	RR165	VC700
1111022	CS786P	RR175	RR169R	RR165	VC680
1111023	CS786P	RR175	RR169R	RR165	VC680
1111024	CS786P	RR175	RR169R	RR165	VC680
1111025	CS786P	RR175	RR169R	RR165	VC680
1111029	CS786P	RR175	RR169R	RR165	VC680
1111030	CS786P	RR175	RR169R	RR165	VC680
1111031	CS786P	RR175	RR169R	RR165	VC680
1111032	CS786P	RR175	RR169R	RR165	VC700
1111033	CS786P	RR175	RR169R	RR168	VC700
1111034	CS786P	RR175	RR169R	RR165	VC700
1111035	CS786P	RR175	RR169R	RR168	VC680
1111039	CS786P	RR175	RR169R	RR165	VC680
1111042	CS786P	RR174	RR169R	RR165	VC680
1111044	CS786P	RR174	RR169R	RR165	VC680
1111046	CS786P	RR175	RR169R	RR165	VC680
1111048	CS786P	RR175	RR169R	RR165	VC680
1111049	CS786P	RR175	RR169R	RR165	—
1111050	CS786P	RR174	RR169R	RR165	VC680
1111051	CS786P	RR175	RR169R	RR165	VC680
1111052	CS786P	RR175	RR169R	RR165	VC680
1111053	CS786P	RR175	RR169R	RR165	VC680
1111054	CS786P	RR175	RR169R	RR165	VC680

(continued on next page)

⁹Two required

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1111055	CS786P	RR175	RR169R	RR165	VC680
1111058	CS786P	RR175	RR169R	RR165	VC680
1111061	CS786P	RR175	RR169R	RR165	VC700
1111062	CS786P	RR175	RR169R	RR165	—
1111063	CS786P	RR175	RR169R	RR168	—
1111069	CS89	RR175	RR169R	RR165	—
1111070	CS786P	RR175	RR169R	RR168	—
1111071	CS786P	RR175	RR169R	RR165	—
1111073	CS786P	RR175	RR169R	RR165	VC1765
1111075	CS786P	RR175	RR169R	RR165	VC680
1111076	CS89	RR175	RR169R	RR165	—
1111077	CS89	RR175	RR169R	RR165	—
1111078	CS89	RR175	RR169R	RR165	—
1111079	CS89	RR175	RR169R	RR165	—
1111080	—	—	RR169R	RR165	—
1111081	—	—	RR169R	RR165	—
1111082	CS786P	RR175	RR169R	RR165	—
1111083	CS786P	RR175	RR169R	RR165	VC680
1111085	CS786P	RR175	RR169R	RR165	—
1111086	—	—	RR169R	RR165	—
1111087	CS786P	RR175	RR169R	RR165	—
1111088	CS786P	RR175	RR169R	RR165	—
1111088	CS791	RR175	RR169R	RR165	—
1111089	CS786P	RR175	RR169R	RR165	VC680
1111090	CS786P	RR175	RR169R	RR165	—
1111094	CS89	RR175	RR169R	RR165	VC680
1111096	CS89	RR175	RR169R	RR165	VC680
1111100	CS786P	RR175	RR169R	RR165	VC680
1111101	CS786P	RR175	RR169R	RR165	VC680
1111102	CS89	RR175	RR169R	RR165	—
1111103	CS89	RR175	RR169R	RR165	—
1111104	CS89	RR175	RR169R	RR165	VC680
1111105	CS786P	RR175	RR169R	RR165	VC680
1111106	CS89	RR174	RR169R	RR165	—
1111107	CS89	RR175	RR169R	RR165	VC680
1111108	CS89	RR175	RR169R	RR165	—
1111109	CS89	RR175	RR169R	RR165	—
1111111	CS89	RR175	RR169R	RR165	—
1111112	CS89	RR175	RR169R	RR165	—
1111113	CS786P	RR175	RR169R	RR165	VC680
1111114	CS786P	RR175	RR169R	RR165	VC680
1111116	CS786P	RR175	RR169R	RR165	VC680
1111117	CS786P	RR175	RR169R	RR165	VC680
1111130	CS786P	RR175	RR169R	RR165	VC680
1111131	CS786P	RR175	RR169R	RR165	VC700
1111134	CS786P	RR175	RR169R	RR165	VC680
1111138	CS89	RR175	RR169R	RR165	—
1111141	CS89	RR175	RR169R	RR165	VC680

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1111144	CS786P	RR174	RR169R	RR165	VC680
1111147	CS786P	RR174	RR169R	RR165	VC680
1111148	CS89	RR175	RR169R	RR165	VC680
1111149	CS786P	RR175	RR169R	RR165	VC680
1111150	CS786P	RR175	RR169R	RR165	VC680
1111151	CS786P	RR175	RR169R	RR165	—
1111152	CS786P	RR175	RR169R	RR165	VC680
1111153	CS786P	RR175	RR169R	RR165	VC680
1111154	CS786P	RR175	RR169R	RR165	VC680
1111156	CS786P	RR175	RR169R	RR165	—
1111158	CS786P	RR175	RR169R	RR165	VC680
1111159	CS786P	RR175	RR169R	RR165	VC680
1111160	CS89	RR175	RR169R	RR165	—
1111161	CS89	RR175	RR169R	RR165	—
1111164	CS786P	RR175	RR169R	RR165	—
1111165	CS786P	RR175	RR169R	RR165	—
1111167	CS786P	RR175	RR169R	RR165	—
1111168	CS786P	RR175	RR169R	RR165	—
1111169	CS786P	RR175	RR169R	RR165	VC680
1111170	CS89	RR175	RR169R	RR165	—
1111175	CS786P	RR175	RR169R	RR165	—
1111176	CS89	RR175	RR169R	RR165	VC680
1111177	CS786P	RR175	RR169R	RR165	—
1111183	CS786P	RR175	RR169R	RR165	VC680
1111184	CS786P	RR175	RR169R	RR165	VC680
1111186	CS786P	RR175	RR169R	RR165	VC680
1111187	CS786P	RR175	RR169R	RR165	VC680
1111189	CS786	—	—	—	VC680
1111191	CS786P	RR175	RR169R	RR165	VC680
1111193	CS786P	RR175	RR169R	RR165	VC680
1111194	CS89	RR175	RR169R	RR165	VC1765
1111195	CS786P	RR175	RR169R	RR165	VC680
1111196	CS786P	RR175	RR169R	RR165	—
1111198	CS786P	RR175	RR169R	RR165	—
1111199	CS786P	RR175	RR169R	RR165	—
1111200	CS786P	RR175	RR169R	RR165	—
1111201	CS779A	—	—	—	—
1111202	CS779A	RR174	—	—	—
1111203	CS779A	—	—	—	—
1111204	CS779A	RR174	—	—	—
1111206	CS779A	—	—	—	—
1111207	CS779A	—	—	—	—
1111208	CS779A	—	—	—	—
1111209	CS779A	—	—	—	—
1111210	CS779A	—	—	—	—
1111211	CS779A	—	—	—	—
1111212	CS779A	—	—	—	—
1111214	CS779A	—	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1111215	CS779A	—	—	—	—
1111216	CS779A	—	—	—	—
1111217	CS779A	—	—	—	—
1111218	CS779A	—	—	—	—
1111219	CS779A	—	—	—	—
1111220	CS779A	—	—	—	—
1111221	CS779A	—	—	—	—
1111222	CS779A	—	—	—	—
1111223	CS779A	—	—	—	—
1111224	CS779A	—	—	—	—
1111225	CS779A	—	—	—	—
1111226	CS779A	—	—	—	—
1111227	CS779A	—	—	—	—
1111228	CS779A	—	—	—	—
1111229	CS779A	—	—	—	—
1111230	CS779A	RR174	—	—	—
1111231	CS779A	RR174	—	—	—
1111232	CS779A	—	—	—	—
1111233	CS779A	—	—	—	—
1111235	CS779A	—	—	—	—
1111237	CS786P	RR175	RR169R	RR165	—
1111238	CS786P	RR175	RR169R	RR165	—
1111239	CS786P	RR175	RR169R	RR165	—
1111241	CS786P	RR175	RR169R	RR165	—
1111242	CS786P	RR175	RR169R	RR165	—
1111243	CS786P	RR175	RR169R	RR165	—
1111244	CS786P	RR175	RR169R	RR165	—
1111247	CS89	RR175	RR169R	RR165	—
1111249	CS786P	RR175	RR169R	RR165	VC680
1111250	CS786P	RR175	RR169R	RR165	—
1111252	CS786P	RR175	RR169R	RR165	—
1111253	CS786P	RR175	RR169R	RR165	—
1111254	CS786P	RR175	RR169R	RR165	—
1111256	CS786P	RR175	RR169R	RR165	VC680
1111257	CS786P	RR175	RR169R	RR165	VC680
1111259	CS786P	RR175	RR169R	RR165	—
1111260	CS786P	RR175	RR169R	RR165	VC680
1111261	CS786P	RR175	RR169R	RR165	VC680
1111262	CS786P	RR175	RR169R	RR165	—
1111264	CS786P	RR175	RR169R	RR165	—
1111266	CS89	RR175	RR169R	RR165	—
1111268	CS786P	RR175	RR169R	RR165	—
1111269	CS786P	RR175	RR169R	RR165	—
1111270	CS786P	RR175	RR169R	RR165	VC680
1111272	CS786P	RR175	RR169R	RR165	—
1111273	CS786P	RR175	RR169R	RR165	—
1111276	CS786P	RR175	RR169R	RR165	—
1111281	CS786P	RR175	RR169R	RR165	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1111282	CS786P	RR175	RR169R	RR165	—
1111284	CS786P	RR175	RR169R	RR165	VC680
1111285	CS786P	RR175	RR169R	RR165	VC680
1111286	CS786P	RR175	RR169R	RR165	—
1111287	CS786P	RR175	RR169R	RR165	VC1765
1111288	CS786P	RR175	RR169R	RR165	—
1111289	CS786P	RR175	RR169R	RR165	—
1111293	CS89	RR175	RR169R	RR165	—
1111297	CS786P	RR175	RR169R	RR165	—
1111298	CS786P	RR175	RR169R	RR165	VC680
1111299	CS786P	RR175	RR169R	RR165	—
1111300	CS786P	RR175	RR169R	RR165	—
1111301	CS779A	—	—	—	—
1111302	CS763A	RR174	RR83	—	—
1111304	CS786P	RR174	RR169R	RR165	—
1111305	CS786P	RR174	RR169R	RR165	—
1111306	CS786P	RR174	RR169R	RR165	—
1111309	CS786P	RR174	RR169R	RR168	—
1111310	CS786P	RR174	RR182R	RR183	—
1111311	CS786P	RR174	RR182R	RR183	—
1111319	CS786P	RR174	RR169R	RR165	—
1111326	CS89	RR175	RR169R	RR165	—
1111327	CS786P	RR174	RR169R	RR165	—
1111330	CS786P	RR175	RR169R	RR165	VC680
1111331	CS786P	RR174	RR169R	RR165	—
1111332	CS763A	—	—	—	—
1111334	CS786P	RR175	RR169R	RR165	VC680
1111335	CS786P	RR175	RR169R	RR165	VC680
1111336	CS786P	RR174	RR169R	RR165	—
1111337	CS786P	RR174	RR169R	RR165	—
1111338	CS786P	RR174	RR169R	RR165	—
1111351	CS786P	RR174	RR169R	RR165	—
1111352	CS786P	RR174	RR169R	RR165	—
1111353	CS786P	RR174	RR169R	RR165	—
1111355	CS786P	RR176	RR169R	RR165	—
1111356	CS788P	RR176	RR182R	RR181	VC1765
1111362	—	—	RR182R	RR183	—
1111363	—	—	RR182R	RR183	—
1111364	CS786P	RR174	RR169R	RR165	—
1111365	CS786P	RR174	RR169R	RR165	—
1111367	CS786P	RR174	RR169R	RR165	—
1111368	CS786P	RR174	RR169R	RR165	—
1111369	CS786P	RR174	RR169R	RR165	—
1111370	CS786P	RR174	RR169R	RR165	—
1111371	CS786P	RR175	RR169R	RR165	VC1765
1111373	CS786P	RR175	RR169R	RR165	VC1765
1111374	CS786P	RR175	RR169R	RR165	VC1765
1111375	CS786P	RR175	RR169R	RR165	VC1765

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1111376	CS786P	RR175	RR169R	RR165	VC1765
1111378	CS786P	RR175	RR169R	RR165	VC1765
1111379	CS786P	RR175	RR169R	RR165	VC1765
1111380	CS786P	RR175	RR169R	RR165	VC1765
1111381	CS786P	RR175	RR169R	RR165	VC1765
1111384	CS786P	RR175	RR169R	RR165	VC1765
1111400	—	—	RR182R	RR181	—
1111401	CS763A	RR174	RR83	RR95	—
1111402	CS763A	RR174	RR83	RR145	—
1111405	CS763A	RR174	RR83	RR95	—
1111406	CS779A	—	—	—	—
1111408	CS763A	RR174	RR83	RR95	—
1111409	CS763A	RR174	RR83	RR145	—
1111410	CS763A	RR174	RR83	RR95	—
1111411	CS763A	RR174	RR83	RR145	—
1111412	CS763A	RR174	RR83	RR95	—
1111413	CS763A	—	RR83	—	—
1111414	CS763A	RR174	RR83	RR145	—
1111415	CS763A	RR174	RR83	—	—
1111416	CS763A	RR174	RR83	—	—
1111418	CS763A	RR174	RR83	RR354	—
1111419	CS763A	RR174	RR83	RR145	—
1111420	CS763A	RR174	RR83	—	—
1111421	CS763A	RR174	RR83	—	—
1111422	CS763A	RR174	RR83	—	—
1111423	CS763A	RR174	RR83	—	—
1111424	CS763A	RR174	RR83	—	—
1111425	CS763A	RR174	RR83	RR95	—
1111426	CS763A	RR174	RR83	—	—
1111427	CS763A	RR174	RR83	—	—
1111428	CS763A	RR174	RR83	RR145	—
1111429	CS763A	RR174	RR83	RR95	—
1111431	CS763A	RR174	RR83	RR142	—
1111432	CS763A	RR174	RR83	RR145	—
1111433	CS763A	RR174	RR83	—	—
1111434	CS763A	RR174	RR83	—	—
1111435	CS786P	RR175	RR169R	RR165	—
1111436	CS786P	RR175	RR169R	RR165	VC680
1111437	CS89	RR175	RR169R	RR165	—
1111438	CS89	RR175	RR169R	RR165	VC680
1111439	CS89	RR175	RR169R	RR165	VC680
1111440	CS89	RR175	RR169R	RR165	VC680
1111443	CS786P	RR175	RR169R	RR165	VC680
1111444	CS786P	RR175	RR169R	RR165	VC680
1111445	CS786P	RR175	RR169R	RR165	VC680
1111447	CS786P	RR175	RR169R	RR165	—
1111448	CS786P	RR175	RR169R	RR165	—
1111449	CS786P	RR175	RR169R	RR165	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1111450	CS786P	RR175	RR169R	RR165	—
1111460	CS89	RR175	RR169R	RR165	VC1605
1111461	CS89	RR175	RR169R	RR165	VC1605
1111462	CS763A	RR174	RR83	RR145	—
1111463	CS786P	RR175	RR169R	RR165	—
1111464	CS89	RR175	RR169R	RR165	—
1111466	CS786P	RR175	RR169R	RR165	—
1111467	CS89	RR175	RR169R	RR165	—
1111468	CS786P	RR175	RR169R	RR165	—
1111469	CS786P	RR175	RR169R	RR165	—
1111472	CS786P	RR174	RR169R	RR165	—
1111473	CS786P	RR174	RR169R	RR165	—
1111474	CS786P	RR175	RR169R	RR165	VC680
1111477	CS89	RR175	RR169R	RR165	VC680
1111478	CS786P	RR175	RR169R	RR165	VC680
1111479	CS786P	RR175	RR169R	RR165	VC680
1111480	CS89	RR175	RR169R	RR165	VC680
1111481	CS786P	RR175	RR169R	RR165	VC680
1111482	CS786P	RR175	RR169R	RR165	VC1605
1111483	CS786P	RR175	RR169R	RR165	VC1605
1111486	CS786P	RR175	RR169R	RR165	VC1765
1111487	CS786P	RR175	RR169R	RR165	—
1111488	CS786P	RR175	RR169R	RR165	—
1111489	CS786P	RR175	RR169R	RR165	VC1605
1111490	CS786P	RR175	RR169R	RR165	VC1605
1111492	CS786P	RR175	RR169R	RR165	VC680
1111493	CS786P	RR175	RR169R	RR165	—
1111494	CS786P	RR175	RR169R	RR165	VC680
1111495	CS786P	RR175	RR169R	RR165	VC680
1111496	CS89	RR175	RR169R	RR165	—
1111497	CS786P	RR175	RR169R	RR165	VC680
1111498	CS786P	RR175	RR169R	RR165	VC680
1111499	CS89	RR175	RR169R	RR165	VC680
1111500	CS786P	RR175	RR169R	RR165	VC680
1111501	CS779A	—	—	—	—
1111502	CS779A	—	—	—	—
1111505	CS763A	RR174	RR83	RR145	—
1111506	CS763A	RR174	RR83	RR145	—
1111507	CS765	RR174	RR74	—	—
1111508	CS763A	—	RR83	RR145	—
1111509	CS765	RR174	RR74	—	—
1111510	CS763A	—	RR83	—	—
1111511	CS765	RR174	RR74	—	—
1111512	CS765	RR174	RR74	—	—
1111513	CS763A	RR174	RR83	RR145	—
1111514	CS779A	RR174	—	—	—
1111515	CS763A	RR174	RR83	RR145	—
1111516	CS763A	RR174	RR83	RR145	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control	Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1111517	CS779A	—	—	—	—	1111657	CS777A	—	—	—	—
1111518	CS763A	RR174	RR83	RR145	—	1111660	CS786P	RR175	RR169R	RR165	—
1111519	CS779A	—	—	—	—	1111661	CS786P	RR175	RR169R	RR165	—
1111520	CS763A	RR174	RR83	RR145	—	1111663	CS777A	RR174	RR161	RR162	—
1111521	CS779A	—	—	—	—	1111672	CS777A	—	—	—	—
1111522	CS763A	RR174	RR83	—	—	1111673	CS777A	—	—	—	—
1111523	CS763A	RR174	RR83	RR145	—	1111676	CS777A ⁹	RR174	RR161	RR162	—
1111524	CS765	RR174	RR74	—	—	1111676	CS778A ⁹	RR174	RR161	RR162	—
1111525	CS763A	RR174	RR83	RR145	—	1111678	CS777A	—	—	—	—
1111526	CS763A	RR174	RR83	RR145	—	1111679	CS777A	—	—	—	—
1111529	CS779A	—	—	—	—	1111680	CS777A ⁹	RR174	RR161	—	—
1111530	CS763A	RR174	RR83	RR145	—	1111680	CS778A ⁹	RR174	RR161	—	—
1111531	CS779A	—	—	—	—	1111685	CS777A	—	—	—	—
1111532	CS763A	RR174	RR83	RR145	—	1111686	CS777A	—	—	—	—
1111533	CS779A	—	—	—	—	1111688	CS777A ⁹	RR174	RR161	RR162	—
1111534	CS763A	RR174	RR83	RR145	—	1111688	CS778A ⁹	RR174	RR161	RR162	—
1111535	CS765	RR174	RR74	—	—	1111689	CS777A ⁹	RR174	RR161	—	—
1111536	CS763A	RR174	RR83	RR145	—	1111689	CS778A ⁹	RR174	RR161	—	—
1111538	CS763A	RR174	RR83	RR145	—	1111690	CS777A	—	—	—	—
1111539	CS777A ⁹	RR174	—	—	—	1111697	—	—	RR182R	RR181	—
1111540	CS779A	—	—	—	—	1111700	CS788P	RR174	RR182R	RR181	—
1111541	CS777A ⁹	—	—	—	—	1111701	CS763A	RR174	RR83	RR354	—
1111542	CS763A	RR174	RR83	RR145	—	1111702	CS763A	RR174	RR83	RR95	—
1111543	CS763A	RR174	RR83	—	—	1111703	CS763A	RR174	RR83	RR145	—
1111544	CS763A	RR174	RR83	RR95	—	1111704	CS763A	RR174	RR83	RR145	—
1111545	CS779A	—	—	—	—	1111705	CS763A	RR174	RR83	RR145	—
1111546	CS763A	RR174	—	—	—	1111706	CS763A	RR174	RR83	RR95	—
1111547	CS779A	—	—	—	—	1111707	CS763A	RR174	RR83	RR145	—
1111548	CS779A	—	—	—	—	1111708	CS763A	RR174	RR83	RR145	—
1111549	CS779A	—	—	—	—	1111709	CS763A	RR174	RR83	RR354	—
1111550	CS777A ⁹	—	—	—	—	1111710	CS763A	RR174	RR83	RR145	—
1111551	CS777A ⁹	RR174	—	—	—	1111711	CS763A	RR174	RR83	RR145	—
1111552	CS763A	RR174	RR83	RR95	—	1111712	CS763A	RR174	RR83	RR145	—
1111553	CS763A	RR174	RR83	RR95	—	1111713	CS763A	RR174	RR83	RR145	—
1111554	CS763A	—	RR83	RR142	—	1111714	CS763A	RR174	RR83	RR145	—
1111555	CS779A	—	—	—	—	1111715	CS763A	RR174	RR83	RR145	—
1111557	CS779A	—	—	—	—	1111716	CS763A	RR174	RR83	RR145	—
1111558	CS763A	RR174	RR83	—	—	1111717	CS763A	RR174	RR83	RR145	—
1111559	CS763A	RR174	—	RR145	—	1111718	CS763A	RR174	RR83	RR145	—
1111566	CS779A	—	—	—	—	1111719	CS763A	RR174	RR83	RR145	—
1111567	CS779A	—	—	—	—	1111720	CS763A	RR174	RR83	RR95	—
1111579	CS763A	RR174	—	—	—	1111721	CS763A	RR174	RR83	RR95	—
1111582	CS763A	RR174	—	—	—	1111722	CS763A	RR174	RR83	RR145	—
1111635	CS777A	—	—	—	—	1111723	CS763A	RR174	RR83	RR145	—
1111642	CS777A	—	—	—	—	1111724	CS763A	RR174	RR83	RR145	—
1111644	CS763A	RR174	—	—	—	1111725	CS763A	RR174	RR83	RR145	—
1111645	CS763A	RR174	RR83	RR145	—	1111726	CS763A	RR174	RR83	RR145	—
1111652	CS777A	—	—	—	—	1111727	CS763A	RR174	RR83	RR145	—

(continued on next column)

(continued on next page)

⁹ Two required

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1111728	CS763A	RR174	RR83	RR95	—
1111729	CS763A	RR174	RR83	RR145	—
1111730	CS763A	RR174	RR83	RR95	—
1111731	CS763A	RR174	RR83	RR95	—
1111733	CS763A	RR174	RR83	RR145	—
1111734	CS763A	RR174	RR83	RR95	—
1111735	CS763A	RR174	RR301	RR145	—
1111736	CS763A	RR174	RR83	RR145	—
1111737	CS763A	RR174	RR83	RR145	—
1111738	CS763A	RR174	RR83	RR95	—
1111739	CS763A	RR174	RR83	RR145	—
1111740	CS763A	RR174	RR83	RR145	—
1111742	CS763A	RR174	RR83	RR145	—
1111744	CS763A	RR174	RR83	RR145	—
1111745	CS763A	RR174	RR301	RR145	—
1111747	CS763A	RR174	RR83	RR95	—
1111748	CS763A	RR174	RR83	RR95	—
1111750	CS763A	RR174	RR83	RR95	—
1111751	CS763A	RR174	RR83	—	—
1111752	CS763A	RR174	RR83	RR95	—
1111753	CS763A	RR174	RR83	—	—
1111754	CS763A	RR174	RR83	—	—
1111755	CS763A	RR174	RR83	—	—
1111756	CS763A	RR174	RR83	—	—
1111757	CS763A	RR174	RR83	—	—
1111759	CS763A	RR174	RR83	—	—
1111760	CS763A	RR174	RR83	—	—
1111761	CS763A	RR174	RR83	—	—
1111762	CS763A	RR174	RR83	RR95	—
1111763	CS763A	RR174	RR83	RR95	—
1111764	CS763A	RR174	RR83	RR95	—
1111765	CS763A	RR174	RR83	RR95	—
1111766	CS763A	RR174	RR83	RR95	—
1111767	CS763A	RR174	RR83	—	—
1111768	CS763A	RR174	RR83	—	—
1111769	CS763A	RR174	RR83	RR95	—
1111770	CS763A	RR174	RR83	RR95	—
1111771	CS763A	RR174	RR83	—	—
1111772	CS763A	RR174	RR83	—	—
1111773	CS763A	RR174	RR83	RR95	—
1111774	CS763A	RR174	RR83	RR95	—
1111775	CS763A	RR174	RR83	—	—
1111776	CS763A	RR174	RR83	—	—
1111777	CS763A	RR174	RR83	RR95	—
1111778	CS763A	RR174	RR83	RR95	—
1111779	CS763A	RR174	RR83	RR95	—
1111780	CS763A	RR174	RR83	—	—
1111781	CS763A	RR174	RR83	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1111782	CS763A	RR174	RR83	RR95	—
1111783	CS763A	RR174	RR83	RR95	—
1111784	CS763A	RR174	RR83	RR95	—
1111785	CS763A	RR174	RR83	RR95	—
1111786	CS763A	RR174	RR83	RR95	—
1111787	CS763A	RR174	RR83	—	—
1111788	CS763A	RR174	RR83	RR95	—
1111789	CS763A	RR174	RR83	—	—
1111790	CS763A	RR174	RR83	RR95	—
1111791	CS763A	RR174	RR83	—	—
1111793	CS763A	RR174	RR83	RR95	—
1111795	CS763A	RR174	RR83	—	—
1111796	CS763A	RR174	RR83	—	—
1111797	CS763A	RR174	RR83	RR95	—
1111798	CS763A	RR174	RR83	—	—
1111799	CS763A	RR174	RR83	RR95	—
1111800	CS763A	RR174	RR83	—	—
1111801	CS763A	RR174	RR83	—	—
1111802	CS763A	RR174	RR83	—	—
1111803	CS763A	RR174	RR83	RR95	—
1111804	CS763A	RR174	RR83	—	—
1111806	CS763A	RR174	RR83	RR95	—
1111807	CS763A	RR174	RR83	RR95	—
1111809	CS763A	RR174	RR83	—	—
1111810	CS763A	RR174	RR83	—	—
1111811	CS763A	RR174	—	RR95	—
1111812	CS763A	RR174	—	RR95	—
1111813	CS763A	RR174	RR83	RR142	—
1111814	CS763A	RR174	RR83	—	—
1111815	CS763A	RR174	RR83	RR95	—
1111816	CS763A	RR174	RR83	RR95	—
1111817	CS763A	RR174	RR83	RR95	—
1111818	CS763A	RR174	RR83	RR95	—
1111819	CS763A	RR174	RR83	RR95	—
1111820	CS763A	RR174	RR83	—	—
1111821	CS763A	RR174	RR83	—	—
1111822	CS763A	RR174	RR83	—	—
1111824	CS763A	RR174	RR83	RR95	—
1111825	CS763A	RR174	RR83	RR95	—
1111828	CS763A	RR174	RR83	—	—
1111829	CS763A	RR174	RR83	—	—
1111832	CS763A	RR174	RR83	RR95	—
1111833	CS763A	RR174	RR83	—	—
1111835	CS763A	RR174	RR83	RR95	—
1111836	CS763A	RR174	RR83	RR95	—
1111837	CS763A	RR174	RR83	RR95	—
1111838	CS763A	RR174	RR83	—	—
1111840	CS763A	RR174	RR83	RR95	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1111841	CS763A	RR174	RR83	RR95	—
1111842	CS763A	RR174	RR83	—	—
1111843	CS763A	RR174	RR83	RR95	—
1111844	CS763A	RR174	RR83	—	—
1111846	CS763A	RR174	RR83	RR95	—
1111848	CS763A	RR174	RR83	—	—
1111849	CS763A	RR174	RR83	RR95	—
1111850	CS763A	RR174	RR83	—	—
1111851	CS763A	RR174	RR83	—	—
1111853	CS763A	RR174	RR161	RR162	—
1111854	CS763A	RR174	RR161	RR162	—
1111859	CS763A	RR174	RR83	RR95	—
1111860	CS763A	RR174	RR83	RR95	—
1111862	CS763A	RR174	RR161	RR162	—
1111863	CS763A	RR174	RR83	—	—
1111864	CS763A	RR174	RR83	—	—
1111865	CS763A	RR174	RR83	—	—
1111866	CS763A	RR174	RR161	RR162	—
1111868	CS763A	RR174	RR83	RR142	—
1111869	CS763A	RR174	RR83	—	—
1111870	CS763A	RR174	RR83	RR95	—
1111871	CS763A	RR174	RR161	RR162	—
1111872	CS763A	RR174	RR161	RR162	—
1111873	CS763A	RR174	RR83	—	—
1111874	CS763A	RR174	RR83	—	—
1111876	CS763A	RR174	RR83	RR95	—
1111877	CS763A	RR174	RR161	RR162	—
1111878	CS763A	RR174	RR83	—	—
1111879	CS763A	RR174	RR83	RR95	—
1111880	CS763A	RR174	RR83	RR95	—
1111881	CS763A	RR174	RR83	—	—
1111882	CS763A	RR174	RR83	—	—
1111883	CS763A	RR174	RR83	—	—
1111886	CS763A	RR174	RR83	RR95	—
1111887	CS763A	RR174	RR83	RR95	—
1111888	CS763A	RR174	RR83	RR95	—
1111889	CS763A	RR174	RR83	RR95	—
1111890	CS763A	RR174	RR83	—	—
1111891	CS763A	RR174	RR83	RR95	—
1111892	CS763A	RR174	RR83	RR95	—
1111893	CS763A	RR174	RR83	RR95	—
1111896	CS763A	RR174	RR83	—	—
1111897	CS763A	RR174	RR83	—	—
1111898	CS763A	RR174	RR83	RR145	—
1111899	CS763A	RR174	RR83	RR95	—
1111900	CS763A	RR174	RR83	RR145	—
1111902	CS763A	RR174	RR83	—	—
1111903	CS763A	RR174	RR83	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1111904	CS763A	RR174	RR83	—	—
1111905	CS763A	RR174	RR161	RR162	—
1111906	CS763A	RR174	RR83	RR164	—
1111907	CS763A	RR174	RR83	RR145	—
1111908	CS763A	RR174	RR83	RR145	—
1111909	CS763A	RR174	RR83	RR145	—
1111910	CS763A	RR174	RR83	RR145	—
1111911	CS763A	RR174	RR83	—	—
1111912	CS763A	RR174	RR83	—	—
1111913	CS763A	RR174	RR83	RR95	—
1111914	CS763A	RR174	RR161	RR162	—
1111915	CS763A	RR174	RR161	RR162	—
1111916	CS763A	—	RR83	—	—
1111917	CS763A	RR174	RR83	RR95	—
1111918	CS763A	RR174	RR83	—	—
1111919	CS763A	RR174	RR83	—	—
1111920	CS763A	—	RR83	—	—
1111921	CS763A	RR174	RR83	RR95	—
1111922	CS763A	RR174	RR161	RR162	—
1111923	CS763A	RR174	RR161	RR162	—
1111925	CS89	RR175	RR169R	RR165	VC680
1111926	CS89	RR175	RR169R	RR165	—
1111929	CS786P	RR175	RR169R	RR165	VC1755
1111930	CS786P	RR175	RR169R	RR165	—
1111931	CS786P	RR175	RR169R	RR165	—
1111932	CS786P	RR175	RR169R	RR165	VC1755
1111933	CS786P	RR175	RR169R	RR165	—
1111934	CS786P	RR175	RR169R	RR165	VC1755
1111935	CS786P	RR175	RR169R	RR165	—
1111936	CS786P	RR175	RR169R	RR165	—
1111937	CS786P	RR175	RR169R	RR165	—
1111938	CS786P	RR175	RR169R	RR165	VC700
1111939	CS786P	RR175	RR169R	RR165	VC700
1111940	CS786P	RR175	RR169R	RR165	VC680
1111941	CS89	RR175	RR169R	RR165	VC680
1111942	CS786P	RR175	RR169R	RR165	VC680
1111943	CS786P	RR175	RR169R	RR165	—
1111944	CS786P	RR175	RR169R	RR165	—
1111945	CS786P	RR175	RR169R	RR165	—
1111946	CS89	RR175	RR169R	RR165	—
1111947	CS786P	RR175	RR169R	RR165	—
1111948	CS786P	RR174	RR169R	RR165	—
1111949	CS786P	RR175	RR169R	RR165	VC680
1111950	CS786P	RR175	RR169R	RR165	VC680
1111951	CS786P	RR175	RR169R	RR165	—
1111952	CS89	RR175	RR169R	RR165	—
1111953	CS786P	RR175	RR169R	RR165	—
1111955	CS786P	RR175	RR169R	RR165	VC700

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1111956	CS786P	RR175	RR169R	RR165	VC1760
1111957	CS89	RR175	RR169R	RR165	—
1111959	CS786P	RR175	RR169R	RR165	—
1111960	CS786P	RR175	RR169R	RR165	—
1111961	CS786P	RR175	RR169R	RR165	VC1755
1111962	CS786P	RR175	RR169R	RR165	VC700
1111963	CS89	RR175	RR169R	RR165	VC700
1111964	CS786P	RR175	RR169R	RR165	VC680
1111965	CS89	RR175	RR169R	RR165	VC680
1111966	CS89	RR175	RR169R	RR165	VC680
1111970	CS89	RR175	RR169R	RR165	VC680
1111973	CS786P	RR175	RR169R	RR165	—
1111974	CS786P	RR175	RR169R	RR165	VC1755
1111975	CS786P	RR175	RR169R	RR165	—
1111976	CS786P	RR175	RR169R	RR165	VC1755
1111977	CS786P	RR175	RR169R	RR165	—
1111978	CS786P	RR175	RR169R	RR165	—
1111979	CS786P	RR175	RR169R	RR165	—
1111980	CS786P	RR175	RR169R	RR165	VC1755
1111981	CS786P	RR175	RR169R	RR165	—
1111982	CS786P	RR175	RR169R	RR165	—
1111984	CS786P	RR175	RR169R	RR165	VC700
1111985	CS786P	RR175	RR169R	RR165	—
1111986	CS786P	RR175	RR169R	RR165	VC680
1111987	CS786P	RR174	RR169R	RR165	—
1111988	CS786P	RR174	RR169R	RR165	—
1111989	CS786P	RR174	RR169R	RR165	—
1111990	CS786P	RR174	RR169R	RR165	VC680
1111991	CS786P	RR174	RR169R	RR165	VC680
1111992	CS786P	RR174	RR169R	RR165	VC680
1111993	CS786P	RR174	RR169R	RR165	VC680
1111994	CS786P	RR175	RR169R	RR165	—
1111995	CS786P	RR175	RR169R	RR165	VC1765
1111996	CS786P	RR175	RR169R	RR165	VC1765
1111997	CS786P	RR175	RR169R	RR165	VC1605
1111998	CS786P	RR175	RR169R	RR165	VC680
1111999	CS786P	RR175	RR169R	RR165	VC680
1112000	CS89	RR175	RR169R	RR165	VC1765
1112001	CS786P	RR175	RR169R	RR165	VC1760
1112002	CS786P	RR175	RR169R	RR165	VC1760
1112003	CS786P	RR175	RR169R	RR165	VC1760
1112004	CS786P	RR175	RR169R	RR165	VC700
1112005	CS786P	RR175	RR169R	RR165	—
1112006	CS786P	RR175	RR169R	RR165	VC700
1112007	CS786P	RR175	RR169R	RR165	VC680
1112008	CS786P	RR175	RR169R	RR165	VC680
1112009	CS89	RR175	RR169R	RR165	VC680
1112010	CS89	RR175	RR169R	RR165	VC680

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1112011	CS89	RR175	RR169R	RR165	VC680
1112012	CS89	RR175	RR169R	RR165	VC680
1112013	CS89	RR175	RR169R	RR165	VC680
1112016	CS786P	RR175	RR169R	RR165	VC680
1112017	CS786P	RR175	RR169R	RR165	VC680
1112018	CS786P	RR174	RR169R	RR165	—
1112019	CS89	RR175	RR169R	RR165	VC700
1112020	CS89	RR175	RR169R	RR165	—
1112021	CS89	RR175	RR169R	RR165	—
1112022	CS786P	RR175	RR169R	RR165	VC700
1112023	CS786P	RR175	RR169R	RR165	VC680
1112024	CS89	RR175	RR169R	RR165	VC680
1112027	CS786P	RR175	RR169R	RR165	VC680
1112028	CS786P	RR175	RR169R	RR165	—
1112032	CS786P	RR175	RR169R	RR165	—
1112033	CS786P	RR175	RR169R	RR165	VC1755
1112034	CS786P	RR175	RR169R	RR165	—
1112035	—	—	—	—	VC1765
1112036	CS786P	RR175	RR169R	RR165	—
1112037	CS786P	RR175	RR169R	RR165	VC700
1112039	CS786P	RR175	RR169R	RR165	—
1112039	CS791	RR175	RR169R	RR165	—
1112040	CS786P	RR175	RR169R	RR165	—
1112041	CS786P	RR175	RR169R	RR165	—
1112042	CS786P	RR175	RR169R	RR165	—
1112043	CS786P	RR175	RR169R	RR165	—
1112044	CS786P	RR175	RR169R	RR165	—
1112045	CS786P	RR175	RR169R	RR165	—
1112046	CS786P	RR175	RR169R	RR165	—
1112047	CS786P	RR175	RR169R	RR165	—
1112047	CS791	RR175	RR169R	RR165	—
1112048	CS786P	RR175	RR169R	RR165	—
1112049	CS89	RR175	RR169R	RR165	VC1802
1112050	CS89	RR175	RR169R	RR165	VC1802
1112051	CS89	RR175	RR169R	RR165	—
1112052	CS89	RR175	RR169R	RR165	—
1112054	CS89	RR175	RR169R	RR165	—
1112055	CS786P	RR175	RR169R	RR165	—
1112056	CS786P	RR175	RR169R	RR165	—
1112057	CS786P	RR175	RR169R	RR165	—
1112064	CS786P	RR175	RR169R	RR165	—
1112065	CS786P	RR175	RR169R	RR165	VC700
1112066	CS786P	RR175	RR169R	RR165	VC680
1112067	CS786P	RR175	RR169R	RR165	—
1112068	CS786P	RR175	RR169R	RR165	VC680
1112069	CS786P	RR175	RR169R	RR165	VC680
1112070	CS89	RR175	RR169R	RR165	VC680
1112071	CS89	RR175	RR169R	RR165	VC680

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1112072	CS89	RR175	RR169R	RR165	VC680
1112073	CS89	RR175	RR169R	RR165	VC680
1112074	CS89	RR175	RR169R	RR165	—
1112075	CS89	RR175	RR169R	RR165	—
1112077	CS786P	RR175	RR178	RR165	—
1112078	CS786P	RR175	RR169R	RR165	VC1755
1112079	CS786P	RR175	RR169R	RR165	—
1112080	CS786P	RR175	RR169R	RR165	VC680
1112082	CS791 ²	—	RR169R	RR165	VC1755
1112083	CS786P	RR175	RR169R	RR165	VC680
1112085	CS786P	RR175	RR169R	RR165	—
1112086	CS791 ²	CS791 ²	RR169R	RR165	VC1765
1112087	CS791 ²	CS791 ²	RR169R	RR165	VC1765
1112088	CS791 ²	CS791 ²	RR169R	RR165	VC1765
1112089	CS786P	—	RR169R	RR165	VC680
1112090	CS786P	—	RR169R	RR165	VC680
1112091	CS791 ²	CS791 ²	RR169R	RR165	VC1802
1112093	CS786P	RR175	RR169R	RR165	VC1802
1112094	CS786P	RR175	RR169R	RR165	VC1802
1112095	CS89	RR175	RR169R	RR165	VC1802
1112096	CS786P	RR175	RR169R	RR165	—
1112097	CS786P	RR175	RR169R	RR165	—
1112098	CS89	RR175	RR169R	RR165	VC1807
1112099	CS786P	RR175	RR169R	RR165	—
1112100	CS791 ²	CS791 ²	RR169R	RR165	VC1765
1112101	CS89	RR175	RR169R	RR165	—
1112102	CS89	RR175	RR169R	RR165	—
1112104	CS89	RR175	RR169R	RR165	—
1112105	CS89	RR175	RR169R	RR165	—
1112106	CS786P	RR175	RR169R	RR165	—
1112107	CS89	RR175	RR169R	RR165	—
1112108	CS786P	RR175	RR169R	RR165	—
1112109	CS786P	RR175	RR169R	RR165	VC700
1112110	CS786P	RR175	RR169R	RR165	—
1112111	CS786P	RR174	RR169R	RR165	VC1765
1112112	CS786P	RR174	RR169R	RR165	VC1765
1112113	CS89	RR175	RR169R	RR165	VC680
1112114	CS89	RR175	RR169R	RR165	VC680
1112115	CS89	RR175	RR169R	RR165	VC680
1112116	CS786P	RR175	RR169R	RR165	VC680
1112117	CS786P	RR175	RR169R	RR165	VC680
1112118	CS786P	RR175	RR169R	RR165	VC680
1112119	CS786P	RR175	RR169R	RR165	VC680
1112120	CS89	RR175	RR169R	RR165	VC680
1112121	CS89	RR175	RR169R	RR165	VC680
1112122	CS786P	RR175	RR169R	RR165	VC680
1112124	CS89	RR175	RR169R	RR165	VC680
1112126	CS89	RR175	RR169R	RR165	VC680

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1112127	—	—	—	—	VC680
1112131	CS786P	RR175	RR169R	RR165	—
1112133	—	—	—	—	VC1765
1112134	CS791 ²	CS791 ²	RR169R	RR165	VC1605
1112136	CS791 ²	CS791 ²	RR169R	RR165	VC1765
1112138	CS791 ²	—	RR169R	RR165	VC680
1112139	CS791 ²	CS791 ²	RR169R	RR165	VC1765
1112140	CS786P	RR175	RR169R	RR165	VC680
1112141	CS791 ²	CS791 ²	RR169R	RR165	VC1765
1112142	CS791 ²	CS791 ²	RR169R	RR165	VC1765
1112143	CS786P	RR175	RR169R	RR165	VC680
1112144	CS791 ²	CS791 ²	RR169R	RR165	VC1765
1112145	CS89	RR175	RR169R	RR165	VC680
1112146	CS791 ²	CS791 ²	RR169R	RR165	VC1765
1112147	CS791 ²	—	RR169R	RR165	—
1112148	CS89	RR175	RR169R	RR165	—
1112149	CS786P	RR175	RR169R	RR165	—
1112150	CS89	RR175	RR169R	RR165	—
1112152	CS791 ²	—	RR169R	RR165	—
1112153	CS791 ²	—	RR169R	RR165	—
1112154	CS791 ²	—	RR169R	RR165	—
1112156	CS791 ²	CS791 ²	RR169R	RR165	VC1802
1112161	CS791 ²	—	RR169R	RR165	—
1112162	CS791 ²	—	RR169R	RR165	—
1112163	CS791 ²	—	RR169R	RR165	—
1112165	CS791 ²	CS791 ²	RR169R	RR165	VC1605
1112166	CS786P	RR175	RR169R	RR165	VC1802
1112167	CS791 ²	CS791 ²	RR169R	RR165	VC1605
1112168	CS786P	RR175	RR169R	RR165	—
1112169	CS791 ²	CS791 ²	RR169R	RR165	VC1605
1112171	CS786P	RR175	RR169R	RR165	—
1112172	CS786P	RR175	RR169R	RR165	VC1755
1112174	CS791 ²	—	RR169R	RR165	VC1755
1112179	CS786P	RR174	RR169R	RR165	—
1112183	CS791 ²	—	RR169R	RR165	VC680
1112184	CS786P	RR175	RR169R	RR165	—
1112185	CS89	RR175	RR169R	RR165	—
1112186	CS786P	RR175	RR169R	RR165	—
1112187	CS89	RR175	RR169R	RR165	—
1112189	CS786P	RR175	RR169R	RR165	VC680
1112189	CS791	RR175	RR169R	RR165	VC680
1112190	CS786P	RR175	RR169R	RR165	VC680
1112191	CS89	RR175	RR169R	RR165	—
1112195	CS786P	RR175	RR169R	RR165	VC1809
1112197	CS786P	RR175	RR169R	RR165	VC680
1112198	CS786P	RR175	RR169R	RR165	—
1112199	CS786P	RR175	RR169R	RR165	—
1112201	CS786P	RR175	RR169R	RR165	—

(continued on next page)

² Contact & condenser assembly

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1112202	CS786P	RR175	RR169R	RR165	—
1112205	CS89	RR175	RR169R	RR165	—
1112206	CS786P	RR175	RR169R	RR165	—
1112214	CS786P	RR174	RR169R	RR165	—
1112215	CS786P	RR174	RR169R	RR165	VC1765
1112216	CS786P	RR175	RR169R	RR165	—
1112218	CS786P	RR175	RR169R	RR165	—
1112220	CS786P	RR175	RR169R	RR165	—
1112222	CS786P	RR175	RR169R	RR165	VC1809
1112224	CS786P	RR175	RR169R	RR165	—
1112225	CS786P	RR175	RR169R	RR165	VC1809
1112226	CS786P	RR175	RR169R	RR165	—
1112227	CS786P	RR175	RR169R	RR165	—
1112228	CS786P	RR175	RR169R	RR165	—
1112229	CS786P	RR175	RR169R	RR165	—
1112230	CS786P	RR175	RR169R	RR165	—
1112231	CS89	RR175	RR169R	RR165	—
1112232	CS89	RR175	RR169R	RR165	—
1112234	CS791 ²	—	RR169R	RR165	VC680
1112235	CS791 ²	—	RR169R	RR165	—
1112236	CS791 ²	—	RR169R	RR165	VC680
1112237	CS791 ²	—	RR169R	RR165	VC680
1112238	CS791 ²	—	RR169R	RR165	—
1112239	CS791 ²	—	RR169R	RR165	—
1112240	CS791 ²	—	RR169R	RR165	—
1112243	CS791 ²	—	RR169R	RR165	—
1112247	CS791 ²	—	RR169R	RR165	VC1807
1112250	CS791 ²	—	RR169R	RR165	—
1112251	CS763A	RR174	RR83	RR95	—
1112252	CS763A	RR174	RR83	RR95	—
1112253	CS763A	RR174	RR83	RR95	—
1112254	CS763A	RR174	RR83	RR95	—
1112255	CS763A	RR174	RR83	RR95	—
1112256	CS763A	RR174	RR83	RR95	—
1112257	CS763A	RR174	RR83	RR95	—
1112258	CS763A	RR174	RR83	RR95	—
1112259	CS763A	RR174	RR83	RR95	—
1112260	CS763A	RR174	RR83	—	—
1112261	CS763A	RR174	RR83	—	—
1112262	CS763A	RR174	RR83	RR95	—
1112263	CS763A	RR174	RR83	RR95	—
1112264	CS763A	RR174	RR83	—	—
1112265	CS763A	RR174	RR83	—	—
1112266	CS763A	RR174	RR83	RR95	—
1112267	CS763A	RR174	RR83	—	—
1112268	CS763A	RR174	RR83	RR95	—
1112269	CS763A	RR174	RR83	RR95	—
1112270	CS763A	RR174	RR83	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1112271	CS763A	RR174	RR83	RR95	—
1112272	CS763A	RR174	RR83	RR95	—
1112273	CS763A	RR174	RR83	RR95	—
1112274	CS763A	RR174	RR83	RR95	—
1112275	CS763A	RR174	RR83	—	—
1112276	CS763A	RR174	RR83	RR95	—
1112277	CS763A	RR174	RR83	—	—
1112279	CS763A	RR174	RR83	—	—
1112280	CS763A	RR174	RR83	—	—
1112281	CS763A	RR174	RR83	—	—
1112284	CS763A	RR174	RR83	—	—
1112285	CS763A	RR174	RR83	—	—
1112286	CS763A	RR174	RR83	—	—
1112288	CS763A	RR174	RR83	RR95	—
1112290	CS763A	RR174	RR83	RR95	—
1112291	CS763A	RR174	RR83	RR95	—
1112292	CS763A	RR174	RR83	—	—
1112293	CS763A	RR174	—	RR95	—
1112295	CS763A	RR174	RR83	—	—
1112296	CS763A	RR174	RR83	RR95	—
1112297	CS763A	RR174	RR83	RR95	—
1112298	CS763A	RR174	RR83	—	—
1112299	CS763A	RR174	RR83	RR95	VC1755
1112300	CS763A	RR174	RR83	RR95	—
1112301	CS763A	RR174	RR83	RR95	—
1112302	CS763A	RR174	RR83	RR95	—
1112303	CS763A	RR174	RR83	—	—
1112304	CS763A	RR174	RR83	—	—
1112305	CS763A	RR174	RR83	RR95	—
1112306	CS763A	RR174	RR83	—	—
1112307	CS763A	RR174	RR161	RR162	—
1112309	CS763A	RR174	RR83	—	—
1112310	CS763A	RR174	RR83	RR95	—
1112311	CS763A	RR174	RR83	RR95	—
1112312	CS763A	RR174	RR83	—	—
1112313	CS763A	RR174	RR83	RR95	—
1112314	CS779A	RR174	RR161	RR162	—
1112315	CS763A	RR174	RR83	RR95	—
1112316	CS777A ⁹	RR95	RR83	RR95	—
1112317	CS763A	RR174	RR83	RR145	—
1112318	CS763A	RR174	RR161	RR162	—
1112319	CS763A	RR174	RR161	RR162	—
1112320	CS763A	RR174	RR161	RR162	—
1112321	CS763A	RR174	RR83	RR95	—
1112322	CS763A	RR174	RR83	RR95	—
1112323	CS763A	RR174	RR83	RR145	—
1112324	CS763A	RR174	RR83	RR95	—
1112326	CS763A	RR174	RR161	RR162	—

(continued on next page)

²Contact & condenser assembly ⁹Two required

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control	Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1112327	CS763A	RR174	RR161	RR162	—	1112387	CS763A	RR174	RR83	RR95	—
1112328	CS777A ⁹	RR174	RR157	RR158	—	1112388	CS763A	RR174	RR161	RR162	—
1112329	CS763A	RR174	RR161	RR162	—	1112389	CS763A	RR174	RR161	RR162	—
1112330	CS786P	RR174	RR169R	RR165	—	1112390	CS763A	RR174	RR161	RR162	—
1112331	CS786P	RR174	RR169R	RR165	—	1112391	CS763A	RR174	RR161	RR162	—
1112332	CS763A	RR174	RR83	RR95	—	1112392	CS763A	RR174	RR161	RR162	—
1112333	CS763A	RR174	RR161	RR162	—	1112395	CS763A	RR174	RR83	RR95	—
1112335	CS763A	RR174	RR83	RR95	—	1112396	CS763A	RR174	RR161	RR162	—
1112336	CS777A ⁹	RR174	RR157	RR158	—	1112397	CS763A	RR174	RR83	RR95	—
1112337	CS763A	RR174	RR83	—	—	1112398	CS763A	RR174	RR83	RR95	—
1112338	CS763A	RR174	RR83	—	—	1112399	CS763A	RR174	RR83	RR95	—
1112339	CS763A	RR174	RR161	RR162	—	1112400	CS763A	RR174	RR161	RR162	—
1112340	CS763A	RR174	RR83	RR95	—	1112401	CS763A	RR174	RR83	RR95	—
1112341	CS763A	RR174	RR83	RR95	—	1112402	CS763A	RR174	RR161	RR162	—
1112342	CS763A	RR174	RR83	RR95	—	1112403	CS763A	RR174	RR161	RR162	—
1112343	CS786P	RR174	RR169R	RR165	—	1112404	CS763A	RR174	RR83	RR95	—
1112345	CS763A	RR174	RR161	RR162	—	1112405	CS763A	RR174	RR83	RR95	—
1112346	CS763A	RR174	RR83	RR95	—	1112406	CS763A	RR174	RR83	RR95	—
1112347	CS786P	RR174	RR169R	RR165	—	1112407	CS763A	RR174	RR161	RR162	—
1112349	CS786P	RR174	RR169R	RR165	—	1112408	CS763A	RR174	RR83	RR95	—
1112350	CS786P	RR174	RR169R	RR165	—	1112409	CS763A	RR174	RR161	RR162	—
1112351	CS763A	RR174	RR83	RR95	—	1112410	CS763A	RR174	RR83	—	—
1112352	CS763A	RR174	RR83	RR142	—	1112411	CS763A	RR174	RR161	RR162	—
1112353	CS763A	RR174	RR83	RR95	—	1112412	CS763A	RR174	RR83	RR95	—
1112354	CS763A	RR174	RR83	RR95	—	1112413	CS763A	RR174	RR83	—	—
1112355	CS763A	RR174	RR83	RR95	—	1112414	CS763A	RR174	RR161	RR162	—
1112356	CS763A	RR174	RR83	RR95	—	1112416	CS763A	RR174	RR161	RR162	—
1112357	CS763A	RR174	RR83	RR95	—	1112417	CS763A	RR174	RR161	RR162	—
1112358	CS763A	RR174	RR83	RR95	—	1112418	CS763A	RR174	RR83	RR95	—
1112359	CS763A	RR174	RR83	RR95	—	1112419	CS763A	RR174	RR161	RR162	—
1112360	CS763A	RR174	RR83	RR95	—	1112420	CS763A	RR174	RR161	RR162	—
1112361	CS763A	RR174	RR83	RR95	—	1112421	CS763A	RR174	RR83	RR95	—
1112362	CS763A	RR174	RR83	RR95	—	1112422	CS763A	RR174	RR161	—	—
1112363	CS763A	RR174	RR83	RR95	—	1112423	CS763A	RR174	RR161	RR162	—
1112364	CS763A	RR174	RR83	RR95	—	1112424	CS763A	RR174	RR161	RR162	—
1112365	CS763A	RR174	RR83	RR95	—	1112425	CS763A	RR174	RR161	—	—
1112366	CS763A	RR174	RR83	RR95	—	1112426	CS763A	RR174	RR83	RR95	—
1112367	CS763A	RR174	RR83	RR95	—	1112427	CS763A	RR174	RR83	RR95	—
1112368	CS763A	RR174	RR83	—	—	1112428	CS763A	RR174	RR161	RR162	—
1112369	CS763A	RR174	RR83	RR95	—	1112429	CS763A	RR174	RR161	RR162	—
1112370	CS763A	RR174	RR83	—	—	1112430	CS763A	RR174	RR161	—	—
1112371	CS763A	RR174	RR83	—	—	1112431	CS763A	RR174	RR83	RR95	—
1112372	CS763A	RR174	RR83	RR95	—	1112432	CS763A	RR174	RR83	RR145	—
1112374	CS763A	RR174	RR83	—	—	1112433	CS763A	RR174	RR161	RR162	—
1112378	CS763A	RR174	RR83	RR95	—	1112434	CS763A	RR174	RR161	RR162	—
1112382	CS763A	RR174	RR83	RR95	—	1112435	CS763A	RR174	RR161	RR162	—
1112385	CS763A	RR174	RR83	RR95	—	1112437	CS763A	RR174	RR161	RR162	—
1112386	CS763A	RR174	RR83	RR95	—	1112438	CS763A	RR174	RR161	RR162	—

(continued on next column)

(continued on next page)

⁹ Two required

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1112439	CS763A	RR174	RR161	RR162	—
1112440	CS763A	RR174	RR161	—	—
1112441	CS763A	RR174	RR161	—	—
1112442	CS763A	RR174	RR83	RR145	—
1112443	CS788P	RR174	RR182R	RR181	—
1112444	CS788P	RR174	RR182R	RR183	—
1112446	CS788P	RR174	RR182R	RR181	—
1112447	CS788P	RR174	RR182R	RR181	—
1112448	CS788P	RR174	RR182R	RR181	—
1112449	CS788P	RR174	RR182R	RR183	—
1112450	CS788P	RR174	RR182R	—	—
1112452	—	—	RR182R	RR181	—
1112453	—	—	RR182R	RR181	—
1112454	CS788P	RR176	RR182R	RR183	—
1112455	CS788P	RR176	RR182R	RR181	—
1112456	CS788P	RR176	RR182R	RR183	—
1112457	CS788P	RR176	RR182R	—	—
1112458	CS788P	RR176	RR182R	RR181	—
1112459	CS788P	RR176	RR182R	RR181	—
1112460	CS788P	RR176	RR182R	RR181	—
1112461	CS788P	RR176	RR182R	RR183	—
1112462	CS788P	RR176	RR182R	RR183	—
1112463	CS788P	RR176	RR182R	RR181	—
1112465	CS788P	RR176	RR182R	RR183	—
1112466	CS788P	RR176	RR182R	RR183	—
1112467	CS788P	RR176	RR182R	RR181	—
1112468	CS788P	RR176	RR182R	RR183	—
1112469	CS788P	RR176	RR182R	RR183	—
1112470	CS788P	RR176	RR182R	RR181	—
1112471	CS788P	RR176	RR182R	RR183	—
1112472	CS788P	RR176	RR182R	RR183	—
1112473	CS788P	RR176	RR182R	RR183	—
1112474	CS788P	RR176	RR182R	RR181	—
1112475	CS788P	RR176	RR182R	RR181	—
1112476	CS788P	RR176	RR182R	RR183	—
1112477	—	—	RR182R	RR181	—
1112478	—	—	RR182R	RR181	—
1112479	—	—	RR182R	RR183	—
1112480	CS788P	RR174	RR182R	RR162	—
1112481	CS788P	RR176	RR182R	RR181	—
1112482	—	—	RR182R	RR183	—
1112484	CS788P	RR176	RR182R	RR181	—
1112486	CS788P	RR176	RR182R	RR181	—
1112487	CS788P	RR176	—	—	—
1112488	CS765	RR176	RR74	RR106	—
1112489	CS788P	RR176	RR182R	RR181	—
1112490	CS788P	RR176	RR182R	RR181	—
1112491	CS788P	RR176	RR182R	RR183	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1112492	CS788P	RR176	RR182R	RR183	—
1112493	—	—	RR182R	RR181	—
1112496	CS791 ²	—	RR169R	RR165	—
1112501	—	—	—	RR157	—
1112502	CS786P	RR175	RR169R	RR165	VC680
1112503	CS786P	RR175	RR169R	RR165	VC680
1112504	CS89	RR175	RR169R	RR165	—
1112508	CS788P	RR176	RR182R	RR183	—
1112509	CS788P	RR176	RR182R	RR181	—
1112510	CS786P	RR175	RR169R	RR165	—
1112511	CS786P	RR175	RR169R	RR165	—
1112512	CS791 ²	—	RR169R	RR165	VC680
1112513	CS791 ²	—	RR169R	RR165	VC680
1112514	CS788P	RR176	RR182R	RR181	—
1112515	CS786P	RR175	RR169R	RR165	VC680
1112516	CS786P	RR175	RR169R	RR165	VC680
1112517	CS788P	RR176	RR182R	RR181	—
1112522	CS791 ²	—	RR169R	RR165	VC680
1112526	CS89	RR175	RR169R	RR165	VC1802
1112531	CS791 ²	—	RR169R	RR165	—
1112541	CS791 ²	—	RR169R	RR165	VC680
1112542	CS791 ²	—	RR169R	RR165	VC680
1112543	CS786P	RR175	RR169R	RR165	VC1807
1112544	CS786P	RR175	RR169R	RR165	VC1807
1112545	CS786P	RR175	RR169R	RR165	VC1802
1112550	CS791 ²	—	RR169R	RR165	—
1112551	CS763A	RR174	RR83	RR145	—
1112553	CS763A	RR174	RR83	RR95	—
1112554	CS763A	RR174	RR83	RR95	—
1112555	CS763A	RR174	RR83	RR145	—
1112556	CS763A	RR174	RR83	RR95	—
1112557	CS763A	RR174	RR83	RR145	—
1112558	CS763A	RR174	RR83	RR142	—
1112559	CS763A	RR174	RR83	—	—
1112560	CS763A	RR174	RR83	RR142	—
1112561	CS763A	RR174	RR83	RR95	—
1112562	CS763A	RR174	RR83	RR95	—
1112563	CS763A	RR174	RR83	RR95	—
1112565	CS763A	RR174	RR83	RR145	—
1112566	CS763A	RR174	RR83	RR95	—
1112568	CS763A	RR174	RR83	RR145	—
1112569	CS763A	RR174	RR83	RR355	—
1112570	CS763A	RR174	RR83	RR145	—
1112571	CS763A	RR174	RR83	RR354	—
1112573	CS763A	RR174	RR83	RR145	—
1112574	CS763A	RR174	RR83	RR95	—
1112575	CS763A	RR174	RR83	RR145	—
1112576	CS763A	RR174	RR83	RR355	—

(continued on next page)

² Contact & condenser assembly

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control	Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1112577	CS763A	RR174	RR83	RR145	—	1112626	CS763A	RR174	RR83	RR142	—
1112578	CS763A	RR174	RR83	RR95	—	1112627	CS763A	RR174	RR83	RR145	—
1112579	CS763A	RR174	RR83	RR95	—	1112628	CS788P	RR176	RR182R	RR183	—
1112580	CS763A	RR174	RR83	RR95	—	1112629	CS763A	RR176	RR83	RR145	—
1112581	CS763A	RR174	RR83	RR95	—	1112631	CS788P	RR176	RR182R	RR183	—
1112582	CS763A	RR174	RR83	RR142	—	1112632	CS788P	RR176	RR182R	RR183	—
1112583	CS763A	RR174	RR83	RR145	—	1112633	CS763A	RR174	RR83	RR95	—
1112584	CS763A	RR174	RR301	RR95	—	1112634	—	—	RR182R	RR183	—
1112585	CS763A	RR174	RR83	RR145	—	1112635	CS788P	RR176	—	—	—
1112586	CS763A	RR174	RR83	RR145	—	1112636	CS788P	RR176	RR182R	—	—
1112587	CS763A	RR174	RR83	RR95	—	1112637	CS788P	RR176	RR182R	RR181	—
1112588	CS763A	RR174	RR83	RR95	—	1112638	CS788P	RR176	RR182R	RR183	—
1112589	CS763A	RR174	RR83	RR145	—	1112639	CS788P	RR176	RR182R	RR181	—
1112590	CS763A	RR174	RR83	RR145	—	1112640	—	—	RR182R	RR183	—
1112591	CS763A	RR174	RR83	RR145	—	1112641	CS788P	RR176	RR182R	RR183	—
1112593	CS763A	RR174	RR301	RR145	—	1112642	CS788P	RR176	RR182R	RR181	—
1112594	CS763A	RR174	RR83	RR95	—	1112643	CS788P	RR176	RR182R	RR181	—
1112595	CS763A	RR174	RR83	RR95	—	1112644	CS788P	RR176	RR182R	RR181	—
1112596	CS763A	RR174	RR83	RR145	—	1112645	CS763A	RR174	RR83	RR95	—
1112597	CS763A	RR174	RR83	RR95	—	1112647	CS788P	RR176	RR182R	RR181	—
1112598	CS763A	RR174	RR83	RR145	—	1112648	CS788P	RR176	RR182R	RR181	—
1112599	CS763A	RR174	RR83	RR95	—	1112649	CS788P	RR176	RR182R	RR183	—
1112601	CS763A	RR174	RR83	RR95	—	1112650	CS788P	RR176	RR182R	RR183	—
1112602	CS763A	RR174	RR83	RR145	—	1112651	CS788P	RR176	RR182R	RR183	—
1112603	CS763A	RR174	RR83	RR95	—	1112653	CS788P	RR176	RR182R	RR183	—
1112604	CS763A	RR174	RR83	RR145	—	1112654	CS788P	RR176	RR182R	RR181	—
1112605	CS763A	RR174	RR83	RR95	—	1112655	CS763A	RR174	RR83	RR95	—
1112606	CS763A	RR174	RR83	RR145	—	1112656	CS763A	RR174	RR83	RR145	—
1112607	CS763A	RR174	RR301	RR145	—	1112657	CS763A	RR174	RR83	RR95	—
1112608	CS763A	RR174	RR83	RR95	—	1112658	CS788P	RR176	RR182R	RR183	—
1112609	CS763A	RR174	RR301	RR145	—	1112659	CS788P	RR176	RR182R	RR183	—
1112610	CS763A	RR174	RR83	RR145	—	1112660	CS788P	RR176	RR182R	RR181	—
1112611	CS763A	RR174	RR83	RR145	—	1112661	CS788P	RR176	RR182R	RR181	—
1112612	CS763A	RR174	RR83	RR95	—	1112662	CS788P	RR176	RR182R	RR183	—
1112613	CS763A	RR174	RR83	RR95	—	1112663	CS788P	RR176	RR182R	RR181	—
1112614	CS763A	RR174	RR83	RR145	—	1112664	CS788P	RR176	RR182R	RR181	—
1112615	CS763A	RR174	RR83	RR95	—	1112665	CS788P	RR176	RR182R	RR181	—
1112616	CS763A	RR174	RR83	RR95	—	1112666	CS788P	RR176	RR182R	RR181	—
1112617	CS763A	RR174	RR83	RR95	—	1112667	CS788P	RR176	RR182R	RR183	—
1112618	CS763A	RR174	RR83	RR145	—	1112668	CS788P	RR176	RR182R	RR183	—
1112619	CS763A	RR174	RR83	RR95	—	1112670	CS763A	RR174	RR161	RR162	—
1112620	—	—	RR182R	RR181	—	1112671	CS788P	RR176	RR182R	RR181	—
1112621	—	—	RR182R	RR183	—	1112672	CS788P	RR176	RR182R	RR183	—
1112622	CS788P	RR176	RR182R	RR183	—	1112673	CS788P	RR176	RR182R	RR181	—
1112623	CS788P	RR176	RR182R	RR181	—	1112674	CS788P	RR176	RR182R	RR183	—
1112623	CS788P	RR176	RR182R	RR183	—	1112676	CS788P	RR176	RR182R	RR183	—
1112624	CS788P	RR176	RR182R	RR183	—	1112677	CS788P	RR176	—	—	—
1112625	CS763A	RR174	RR83	RR145	—	1112678	CS788P	RR176	RR182R	RR183	—

(continued on next column)

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1112679	CS788P	RR176	RR182R	RR183	—
1112680	—	—	RR182R	RR183	—
1112681	—	—	RR182R	—	—
1112682	CS788P	RR176	RR182R	RR183	—
1112683	CS788P	RR176	RR182R	RR183	—
1112684	CS788P	RR176	RR182R	RR183	—
1112685	CS788P	RR176	RR182R	RR181	—
1112687	CS788P	RR176	RR182R	RR183	—
1112688	CS788P	RR176	RR182R	RR181	—
1112689	CS788P	RR176	RR182R	RR181	—
1112690	CS788P	RR176	RR182R	RR183	—
1112691	CS788P	RR176	RR182R	RR183	—
1112692	CS788P	RR176	RR182R	RR183	—
1112693	CS788P	RR176	RR182R	RR181	—
1112694	CS788P	RR176	RR182R	RR183	—
1112695	CS788P	RR176	RR182R	RR181	—
1112696	CS788P	RR176	RR182R	RR183	—
1112697	CS788P	RR176	RR182R	RR181	—
1112698	CS788P	RR176	RR182R	—	—
1112699	CS788P	RR176	RR182R	RR183	—
1112700	—	—	RR182R	—	—
1112701	CS786P	RR174	RR169R	RR165	—
1112702	CS786P	RR174	RR169R	RR165	—
1112703	CS786P	RR174	RR169R	RR165	—
1112704	CS763A	RR174	RR161	RR162	—
1112705	CS763A	RR174	RR161	RR162	—
1112706	CS763A	RR174	RR161	RR162	—
1112707	CS786P	RR174	RR169R	RR165	—
1112708	CS763A	RR174	RR161	RR162	—
1112709	CS763A	RR174	RR83	RR95	—
1112710	CS763A	RR174	RR83	RR95	—
1112711	CS763A	RR174	RR161	RR162	—
1112712	CS786P	RR174	RR169R	RR165	—
1112713	CS763A	RR174	RR161	RR162	—
1112714	CS763A	RR174	RR161	RR162	—
1112715	CS786P	RR174	RR169R	RR165	—
1112716	CS763A	RR174	RR161	RR162	—
1112718	CS777A	RR174	RR157	RR158	—
1112720	CS786P	RR174	RR169R	RR165	—
1112721	CS786P	RR174	RR169R	RR165	—
1112722	CS786P	RR174	RR169R	RR165	—
1112723	CS763A	RR174	RR83	RR95	—
1112724	CS763A	—	RR83	—	—
1112725	CS786P	RR174	RR169R	RR165	—
1112726	CS786P	RR174	RR169R	RR165	—
1112727	CS786P	RR174	RR169R	RR165	—
1112728	CS786P	RR174	RR169R	RR165	—
1112729	CS786P	RR174	RR169R	RR165	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1112730	CS763A	RR174	RR161	—	—
1112731	CS786P	RR174	RR169R	RR165	—
1112732	CS786P	RR174	RR169R	RR165	—
1112734	CS763A	RR174	RR161	RR162	—
1112735	CS786P	RR174	RR169R	RR165	—
1112737	CS763A	RR174	RR161	—	—
1112738	CS786P	RR174	RR169R	RR165	—
1112739	CS786P	RR174	RR169R	RR165	—
1112740	CS786P	RR175	RR169R	RR165	—
1112741	CS763A	RR174	RR83	—	—
1112742	CS763A	RR174	RR161	RR162	—
1112743	CS786P	RR175	RR169R	RR165	—
1112743	CS791	RR175	RR169R	RR165	—
1112744	CS786P	RR175	RR169R	RR165	—
1112745	CS786P	RR175	RR169R	RR165	—
1112746	CS786P	RR175	RR169R	RR165	—
1112747	CS786P	RR175	RR169R	—	—
1112748	CS786P	RR175	RR169R	RR165	—
1112749	CS786P	RR175	RR169R	—	—
1112750	CS763A	RR174	RR83	RR95	—
1112751	CS763A	RR174	RR83	RR95	—
1112752	CS786P	RR175	—	RR165	—
1112752	CS791	RR175	—	RR165	—
1112753	CS786P	RR175	RR169R	RR165	—
1112755	CS786P	RR175	RR169R	RR165	—
1112756	CS786P	RR175	RR169R	RR165	—
1112757	CS786P	RR174	—	RR165	—
1112758	CS786P	RR174	—	RR165	—
1112759	CS786P	RR175	RR169R	RR165	—
1112760	CS786P	RR174	RR169R	—	—
1112762	CS786P	—	—	RR165	—
1112764	CS786P	RR176	RR169R	RR165	—
1112765	CS786P	RR174	RR169R	RR165	—
1112767	CS786P	RR174	RR169R	RR165	—
1112768	CS786P	RR174	RR169R	RR165	—
1112769	CS786P	RR174	RR169R	RR165	—
1112770	CS786P	RR174	RR169R	RR165	—
1112771	CS786P	RR174	RR169R	RR165	—
1112772	CS786P	RR175	RR169R	RR165	—
1112773	CS763A	RR174	RR83	RR95	—
1112774	CS763A	RR174	RR161	RR162	—
1112775	CS786P	RR175	RR169R	RR165	—
1112775	CS791	RR175	RR169R	RR165	—
1112776	CS786P	RR175	RR169R	RR165	—
1112776	CS791	RR175	RR169R	RR165	—
1112777	CS786P	RR175	RR169R	RR165	—
1112778	CS786P	RR175	RR169R	RR165	—
1112779	CS786P	RR175	—	RR165	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control	Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1112780	CS786P	RR175	RR169R	RR168	—	1112844	CS791 ²	—	RR169R	RR165	—
1112781	CS786P	RR175	RR169R	RR168	—	1112845	CS786P	RR175	RR169R	RR165	—
1112782	CS786P	RR175	RR169R	RR168	—	1112846	CS791 ²	—	RR169R	RR165	—
1112783	CS786P	RR175	RR169R	RR165	—	1112856	CS791 ²	—	RR169R	RR165	VC680
1112784	CS786P	RR175	RR169R	RR165	—	1112858	CS788P	RR176	RR182R	—	—
1112785	CS786P	RR174	RR169R	RR165	—	1112860	CS791 ²	—	RR169R	RR165	VC680
1112786	CS786P	RR174	RR169R	RR165	—	1112861	CS791 ²	—	RR169R	RR165	VC680
1112787	CS786P	RR174	RR169R	RR165	—	1112900	CS791 ²	—	RR169R	RR165	—
1112788	CS788P	RR176	RR182R	—	—	1112904	CS786P	RR174	RR169R	RR165	—
1112789	CS788P	RR176	—	—	—	1112915	CS791 ²	—	RR169R	RR165	—
1112790	CS786P	RR174	RR169R	RR165	—	1112925	CS791 ²	—	RR169R	RR165	—
1112791	CS763A	RR174	RR83	RR95	—	1112942	CS788P	RR176	RR182R	RR183	—
1112792	CS786P	RR175	RR169R	RR165	—	1112986	CS788P	RR176	RR182R	RR181	—
1112793	CS786P	RR175	RR169R	RR168	—	1114415	CS763A	—	RR83	—	—
1112795	CS786P	RR174	RR169R	RR165	—	1115226	CS763A	RR174	RR83	RR145	—
1112796	CS786P	RR174	RR169R	RR165	—	1211008	CS313	—	EP143	EP274	—
1112797	CS786P	RR174	RR169R	RR165	—	1211009	CS313	—	EP143	EP274	—
1112801	CS786P	RR175	RR169R	RR165	—	1211028	CS313	—	EP143	EP274	—
1112804	CS786P	RR175	RR169R	RR165	VC680	1212006	CS313	EP290	EP143	EP274	—
1112805	CS786P	RR175	RR169R	RR165	VC680	1212007	CS313	EP250	EP143	EP131	—
1112806	CS786P	RR175	RR169R	RR165	VC680	1212018	CS313	EP250	EP143	EP131	—
1112807	CS89	RR175	RR169R	RR165	VC680	1212025	CS313	EP290	EP143	EP131	—
1112808	CS786P	RR175	RR169R	RR165	—	1212026	CS313	EP289	EP143	EP131	—
1112809	CS786P	RR175	RR169R	RR165	—	1212029	CS313	—	EP143	EP131	—
1112810	—	—	—	—	VC680	1212033	CS313	EP290	EP143	EP274	—
1112811	CS89	RR175	RR169R	RR165	—	1212044	CS301	EP147	EP143	EP131	—
1112812	—	—	—	—	VC680	1212050	CS301	—	—	EP131	—
1112813	CS89	RR175	RR169R	RR165	VC680	1816400	CS763A	RR174	RR161	RR162	—
1112814	—	—	RR169R	RR165	—	1825570	CS777A	RR174	RR83	RR142	—
1112817	CS791 ²	—	RR169R	RR165	—	1826067	CS786P	RR175	RR169R	RR165	—
1112818	CS791 ²	—	RR169R	RR165	VC680	1826068	CS788P	RR176	RR182R	RR181	VC1420
1112821	CS786P	RR175	RR169R	RR165	VC680	1826069	CS788P	RR176	RR182R	RR183	VC1420
1112822	CS791 ²	—	RR169R	RR165	VC680	1826070	CS788P	RR176	RR182R	RR183	VC1420
1112823	CS786P	RR175	RR169R	RR165	VC680	1830135	CS786P	RR175	RR169R	RR165	VC1765
1112823	CS791	RR175	RR169R	RR165	VC680	1830960	CS786P	RR175	RR169R	RR165	VC1765
1112824	CS791 ²	—	RR169R	RR165	—	1912414	CS777A ⁹	RR174	RR99	RR100	—
1112825	CS791 ²	—	RR169R	RR165	—	1912884	CS777A ⁹	RR174	RR83	RR95	—
1112827	CS791 ²	—	RR169R	RR165	—	1912885	CS777A ⁹	RR174	RR99	RR100	—
1112828	CS791 ²	—	RR169R	RR165	—	1913162	CS777A ⁹	RR174	RR99	RR100	—
1112831	CS791 ²	—	RR169R	RR165	—	1922284	CS778A ⁹	RR174	RR159	RR158	—
1112832	CS786P	RR175	RR169R	RR165	VC1807	1923176	CS777A ⁹	RR174	—	RR100	—
1112833	CS786P	RR175	RR169R	RR165	VC680	1924745	CS777A ⁹	RR174	—	RR100	—
1112834	CS791 ²	—	RR169R	RR165	VC680	1925570	CS777A ⁹	RR174	RR83	RR95	—
1112835	CS786P	RR175	RR169R	RR165	—	1925987	CS777A	RR174	—	—	—
1112836	CS786P	RR175	RR169R	RR165	—	1928820	CS777A	RR174	—	—	—
1112837	CS786P	RR175	RR169R	RR165	—	1928821	CS777A	RR174	—	—	—
1112838	CS786P	RR175	RR169R	RR165	—	1929000	CS778A	RR174	RR159	RR158	—
1112843	CS791 ²	—	RR169R	RR165	—	1930531	CS777A	RR174	RR157	RR158	—

(continued on next column)

(continued on next page)

²Contact & condenser assembly ⁹Two required

DELCO REMY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
1932666	CS778A	RR174	RR159	RR158	—
1934591	CS777A	RR174	RR157	RR158	—
1935428	CS786P	RR175	RR169R	RR165	—
1938591	CS786P	RR175	RR169R	RR165	—
1942654	CS786P	RR175	RR169R	RR165	—
2110543	CS788P	RR176	RR182R	RR183	—
5726138	CS786P	RR174	RR169R	RR165	—
5726139	CS786P	RR174	RR169R	RR165	—
5726140	CS786P	RR174	RR169R	RR165	—
11110892	CS786P	RR175	RR169R	RR165	—
90003444	CS313	EP293	EP143	EP131	—
94021066	CS355	EP300	EP312	EP718	—
94022575	CS355	EP300	EP312	EP718	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
94022577	CS355	EP300	EP312	EP718	—
94023319	CS351	EP300	EP312	EP718	—
94023966	CS351	EP300	EP312	EP718	—
94023996	CS351	EP300	EP312	EP718	—
94206542	CS375	EP300	EP324	EP323	—
94209564	CS375	EP300	EP324	EP323	—
94209901	CS375	EP300	EP324	EP323	—
94218016	CS375	EP300	EP324	EP323	—
94218017	CS375	EP300	EP324	EP323	—
94218018	CS375	EP300	EP324	EP323	—
94219954	CS375	EP300	EP324	EP323	—

DUCELLIER

Unit No	Contact Assembly	Condenser	Rotor	Cap
4274A	—	EP153	—	—
4275A	—	EP153	—	—
4286A	—	EP153	—	—
4286B	—	EP153	—	—
4363A	CS252	EP153	EP173	—
4441A	CS252	EP153	EP173	—
4442A	CS252	EP153	EP173	—
4482A	—	EP153	—	—
4483A	—	EP153	—	—
4483B	—	EP153	—	—
4483C	—	EP153	—	—
4483D	—	EP153	—	—
4544	—	—	EP173	EP163
4549	CS234	EP153	EP173	—
6820	—	—	EP173	EP163
525003A	CS252	EP153	EP173	—
525025A	CS236	EP153	EP173	EP163
525026A	CS236	EP153	EP173	EP163
525026B	CS236	EP153	EP173	EP163
525057A	CS236	EP153	EP173	EP163
525092A	CS236	EP153	EP173	EP163
525097A	CS236	EP153	EP173	EP163

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
525098A	CS236	EP153	EP173	EP163
525102A	CS236	EP153	EP173	EP163
525115A	CS236	EP153	EP173	EP163
525116A	CS236	EP153	EP173	—
525117A	CS236	EP153	EP173	—
525118A	CS236	EP153	EP173	—
525122A	—	—	EP173	—
525133A	—	—	EP173	EP163
525134A	CS236	EP153	EP173	—
525145A	CS236	EP153	EP173	EP163
525150A	CS236	EP153	EP173	EP163
525151A	CS236	EP153	EP173	EP163
525164A	CS236	EP153	EP173	EP163
525171A	CS236	EP153	EP173	—
525177A	CS236	EP153	EP173	EP163
525183A	CS236	EP153	EP173	EP163
525184A	CS236	EP153	EP173	EP163
525195A	CS236	EP153	EP173	—
525198A	—	—	EP173	EP163
525255A	CS252	EP153	EP173	—
525256A	CS252	EP153	EP173	—

FIAT

Unit No	Contact Assembly	Condenser	Rotor	Cap
4130900	—	—	EP247	EP214

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
4132068	CS231	EP215	—	EP214

(continued on next page)

FIAT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
4171158	—	—	EP247	EP241
4183244	—	—	EP247	EP214
4186935	CS231	EP215	EP247	EP214
4217192	—	—	EP472	EP163
4217193	—	—	EP472	EP384
4217194	CS231	EP215	EP247	EP241
4240672	CS231	EP235	EP473	EP242
4242308	CS231	EP235	EP473	EP245
4250151	CS232	—	EP473	EP241
4254642	CS231	EP235	EP473	EP242
4258693	CS232	—	EP247	EP240
4272875	CS232	—	EP244	EP248
4293052	CS232	—	EP244	EP248

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
4315011	CS234	EP153	EP472	EP471
4315012	CS234	EP153	EP472	EP384
4350698	CS232	EP238 ¹⁵	EP244	EP248
4350968	CS232	EP236 ¹⁵	EP244	EP248
4364097	CS232	—	EP244	EP248
4364179	CS234	EP153	EP472	EP471
4364180	CS234	EP153	EP472	EP384
4364181	CS234	EP153	EP472	—
4388851	CS232	—	EP244	EP248
4430224	—	—	EP247	EP732
82328028	CS232	—	EP244	EP248

FORD-MOTORCRAFT

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
A1A12127A	CS35	FA54	—	—	VC915
A2A12127B	CS47	FA54	—	—	VC915
A72SX12100AA	CS313P	EP282	EP143	EP274	—
A72SX12100BA	CS313P	EP282	EP143	EP274	—
A73SX12100ACA	CS313P	EP408	EP143	EP274	—
A73SX12100AFA	CS313P	EP282	EP143	EP274	—
A73SX12100AGA	CS313P	EP282	EP143	EP274	—
A73SX12100AHA	CS313P	EP408	EP143	EP274	—
B4A12127A	CS750	FA76	FA67	FA78	—
B5A12127B	CS750	FA76	FA67	FA78	—
B5A12127C	CS753	FA66	FA67	FA6900	VC915
B5A12127F	CS750	FA76	FA67	FA78	—
B5C12127B	CS750	FA76	FA67	FA78	—
B5S12127D	CS750	FA76	FA67	FA78	—
B5S12127E	CS750	FA76	FA67	FA78	—
B6A12127A	CS750	FA76	FA67	FA78	—
B6A12127B	CS750	FA76	FA67	FA78	—
B6A12127D	CS750	FA76	FA67	FA78	—
B6A12127E	CS753	FA66	FA67	FA6900	VC915
B6Q12127A	CS750	FA76	FA67	FA78	—
B6Q12127B	CS750	FA76	FA67	FA78	—
B6Q12127B	CS750	FA76	FA67	FA78	—
B6S12127B	CS750	FA76	FA67	FA78	—
B6T12127A	CS750	FA76	FA67	FA78	—
B6T12127B	CS750	FA76	FA67	FA78	—
B7A12127A	CS751	FA8200	FA157	FA79	—
B7A12127B	CS751	FA8200	FA157	FA79	—
B7A12127C	CS753	FA66	FA67	FA6900	VC915
B7A12127D	CS751	FA66	FA67	FA6900	VC915

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
B7A12127E	CS751	FA66	FA67	FA6900	VC915
B7A12127G	CS750 ⁹	FA8200	FA157	FA79	—
B7A12127H	CS753	FA66	FA67	FA6900	VC915
B7AF12127A	CS751	FA8200	FA157	FA79	VC945
B7QH12127B	CS750	FA76	FA67	FA78	—
B7QH12127C	CS750	FA76	FA67	FA78	—
B7S12127A	CS751	FA8200	FA157	FA79	—
B7S12127B	CS751	FA8200	FA157	FA79	—
B7S12127C	CS750 ⁹	FA8200	FA157	FA79	—
B7S12127D	CS751	FA8200	FA157	FA79	—
B7T12127B	CS750	FA76	FA67	FA78	—
B8A12127B	CS751	FA8200	FA157	FA79	—
B8A12127F	CS751	FA8200	FA157	FA79	—
B8A12127G	CS751	FA8200	FA157	FA79	—
B8A12127J	CS753	FA66	FA67	FA6900	VC915
B8A12127K	CS751	FA8200	FA157	FA79	—
B8A12127L	CS751	FA8200	FA157	FA79	—
B8A12127M	CS753	FA66	FA67	FA6900	VC915
B8C12127B	CS751	FA8200	FA157	FA79	—
B8C12127C	CS751	FA8200	FA157	FA79	—
B8C12127D	CS751	FA8200	FA157	FA79	—
B8C12127E	CS751	FA8200	FA157	FA79	—
B8E12127B	CS751	FA8200	FA157	FA79	—
B8E12127C	CS751	FA8200	FA157	FA79	—
B8E12127G	CS751	FA8200	FA157	FA79	—
B8Q12127A	CS751	FA8200	FA157	FA79	—
B8Q12127B	CS751	FA8200	FA157	FA79	—
B8Q12127C	CS751	FA8200	FA157	FA79	—
B8Q12127D	CS751	FA8200	FA157	FA79	—
B8QH12127A	CS751	FA8200	FA157	FA79	—

(continued on next page)

⁹Two required ¹⁵Two required. Physical comparison may be needed.

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
B8QH12127B	CS751	FA8200	FA157	FA79	—
B8QH12127C	CS751	FA8200	FA157	FA79	—
B8QH12127D	CS751	FA8200	FA157	FA79	—
B8QH12127E	CS751	FA8200	FA157	FA79	—
B8QH12127F	CS751	FA8200	FA157	FA79	—
B8S12127A	CS751	FA8200	FA157	FA79	—
B8T12127A	CS751	FA8200	FA157	FA79	—
B8T12127B	CS751	FA8200	FA157	FA79	—
B9A12127B	CS751	FA8200	FA157	FA79	—
B9AF12127A	CS751	FA8200	FA157	FA79	—
B9AF12127B	CS751	FA8200	FA157	FA79	VC945
B9AF12127D	CS751	FA8200	FA157	FA79	VC945
B9MF12127B	CS751	FA8200	FA157	FA79	—
B9QH12127A	CS751	FA8200	FA157	FA79	—
B9QH12127B	CS751	FA8200	FA157	FA79	—
B9QH12127C	CS751	FA8200	FA157	FA79	—
B9QH12127D	CS751	FA8200	FA157	FA79	—
B9S12127B	CS751	FA8200	FA157	FA79	—
B9T12127A	CS751	FA8200	FA157	FA79	—
B9TF12102D	CS751	FA8200	FA157	FA79	—
B9TF12102E	CS751	FA8200	FA157	FA79	—
B9TF12102F	CS751	FA8200	FA157	FA79	—
B9TF12102G	CS751	FA8200	FA157	FA79	—
B9TF12127A	CS751	FA8200	FA157	FA79	—
B9TF12127B	CS751	FA8200	FA157	FA79	VC945
C0AF12127A	CS751	FA8200	FA157	FA79	VC945
C0AF12127B	CS751	FA8200	FA157	FA79	VC945
C0AF12127C	CS753	FA66	FA67	FA6900	VC915
C0AF12127D	CS751	FA8200	FA157	FA79	VC945
C0AF12127E	CS751	FA8200	FA157	FA79	VC945
C0AF12127F	CS753	FA66	FA67	FA6900	—
C0AF12127G	CS750	FA66	FA67	FA6900	VC915
C0AF12127H	CS756 ⁹	FA66	FA157	FA79	—
C0AF12127J	CS756 ⁹	FA66	FA157	FA79	—
C0AF12127K	CS756 ⁹	FA66	FA157	FA79	—
C0AZ12127C	CS751	FA8200	FA157	FA79	VC970
C0AZ12127L	CS756 ⁹	FA66	FA157	FA79	—
C0DF12127A	CS753	FA66	FA67	FA6900	VC915
C0DF12127B	CS750	FA66	FA67	FA6900	VC915
C0LF12127A	CS751	FA8200	FA157	FA79	VC945
C0MF12127C	CS751	FA8200	FA157	FA79	VC945
C0NN12127C	CS753	FA76	FA67	FA6900	—
C0NN12127E	CS753	FA66	FA67	—	—
C0TF12102C	CS751	FA8200	FA157	FA79	—
C0TF12102D	CS751	FA8200	FA157	FA79	—
C0TF12102E	CS751	FA8200	FA157	FA79	—
C0TF12102F	CS751	FA8200	FA157	FA79	—
C0TF12127B	CS751	FA8200	FA157	FA79	VC945

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C0TF12127C	CS751	FA8200	FA157	FA79	VC965
C0TF12127D	CS751	FA8200	FA157	FA79	VC965
C0TZ12127A	CS751	FA8200	FA157	FA79	—
C0TZ12127B	CS751	FA8200	FA157	FA79	VC965
C0TZ12127C	CS751	FA8200	FA157	FA79	—
C0TZ12127D	CS751	FA8200	FA157	FA79	—
C0TZ12127E	CS751	FA8200	FA157	FA79	—
C0TZ12127F	CS751	FA8200	FA157	FA79	—
C0TZ12127G	CS751	FA8200	FA157	FA79	—
C0TZ12127H	CS751	FA8200	FA157	FA79	VC965
C0TZ12127K	CS751	FA8200	FA157	FA79	VC945
C1AF12127A	CS753	FA76	FA67	FA6900	VC915
C1AF12127D	CS753	FA66	FA67	FA6900	—
C1AF12127E	CS753	FA66	FA67	FA6900	VC915
C1AF12127F	CS753	FA66	FA67	FA6900	VC915
C1AF12127G	CS753	FA76	FA67	FA6900	VC915
C1AZ12127A	CS753	FA66	FA67	FA6900	VC915
C1DF12127A	CS753	FA66	FA67	FA6900	VC915
C1DF12127B	CS753	FA66	FA67	FA6900	—
C1DF12127C	CS753	FA66	FA67	FA6900	VC915
C1DF12127D	CS753	FA66	FA67	FA6900	VC915
C1DF12127F	CS753	FA66	FA67	FA6900	VC915
C1GF12127A	CS753	FA66	FA67	FA6900	VC915
C1SF12127A	CS751	FA8200	FA157	FA79	VC945
C1SF12127B	CS751	FA8200	FA157	FA79	VC945
C1TF12102A	CS751	FA8200	FA157	FA79	VC965
C1TF12102B	CS751	FA8200	FA157	FA79	VC965
C1TF12127C	CS753	FA66	FA67	FA6900	—
C1TF12127D	CS753	FA66	FA67	FA6900	—
C1VF12127A	CS751	FA8200	FA157	FA79	VC945
C2AB12127E	CS753	FA66	FA67	FA6900	VC915
C2AF12127A	CS751	FA8200	FA157	FA79	VC945
C2AF12127B	CS751	FA8200	FA157	FA79	VC945
C2AF12127D	CS751	FA8200	FA157	FA79	VC945
C2AF12127E	CS753	FA66	FA67	FA6900	VC915
C2AF12127F	CS753	FA76	FA67	FA6900	—
C2AF12127G	CS753	FA66	FA67	FA6900	VC915
C2AF12127H	CS753	FA66	FA67	FA6900	—
C2AF12127J	CS753	FA66	FA67	FA6900	—
C2AF12127K	CS753	FA66	FA67	FA6900	—
C2AZ12127A	CS751	FA8200	FA157	FA79	VC945
C2AZ12127B	CS751	FA8200	FA157	FA79	VC945
C2AZ12127E	CS753	FA66	FA67	FA6900	VC915
C2AZ12127G	CS753	FA66	FA67	FA6900	VC915
C2AZ12127H	CS753	FA76	FA67	FA6900	—
C2AZ12127J	CS753	FA66	FA67	FA6900	—
C2DF12127A	CS753	FA66	FA67	FA6900	VC915
C2DF12127B	CS753	FA66	FA67	FA6900	VC915

(continued on next page)

⁹ Two required

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C2DF12127C ...	CS753	FA66	FA67	FA6900	VC915
C2DF12127D ...	CS753	FA66	FA67	FA6900	VC915
C2DF12127E ...	CS753	FA66	FA67	FA6900	VC915
C2DF12127F ...	CS753	FA66	FA67	FA6900	VC915
C2DF12127G ...	CS753	FA66	FA67	FA6900	VC915
C2DF12127H ...	CS753	FA66	FA67	FA6900	VC915
C2DF12127I ...	CS753	FA66	FA67	FA6900	VC915
C2DF12127J ...	CS753	FA66	FA67	FA6900	VC915
C2DF12127K ...	CS753	FA66	FA67	FA6900	VC915
C2DZ12127A ...	CS753	FA76	FA67	FA6900	VC915
C2DZ12127B ...	CS753	FA66	FA67	FA6900	VC915
C2DZ12127G ...	CS753	FA66	FA67	FA6900	VC915
C2DZ12127H ...	CS753	FA76	FA67	FA6900	VC915
C2DZ12127K ...	CS753	FA76	FA67	FA6900	VC915
C2GF12127A ...	CS753	FA66	FA67	FA6900	VC915
C2GF12127B ...	CS753	FA66	FA67	FA6900	VC915
C2OF12127A ...	CS751	FA8200	FA157	FA79	VC945
C2OF12127C ...	CS753	FA76	FA67	FA6900	—
C2OF12127D ...	CS751	FA8200	FA157	FA79	VC945
C2OF12127E ...	CS751	FA8200	FA157	FA79	VC945
C2OF12127F ...	CS751	FA8200	FA157	FA79	VC945
C2OF12127H ...	CS751	FA8200	FA157	FA79	VC970
C2OF12127J ...	CS751	FA8200	FA157	FA79	VC945
C2OZ12127A ...	CS751	FA8200	FA157	FA79	VC945
C2OZ12127B ...	CS751	FA8200	FA157	FA79	VC945
C2OZ12127C ...	CS751	FA8200	FA157	FA79	VC945
C2OZ12127D ...	CS751	FA8200	FA157	FA79	VC945
C2OZ12127K ...	CS751	FA8200	FA157	FA79	VC945
C2SF12127A ...	CS751	FA8200	FA157	FA79	VC945
C2SF12127B ...	CS751	FA8200	FA157	FA79	VC945
C2SZ12127A ...	CS751	FA8200	FA157	FA79	VC945
C2SZ12127B ...	CS751	FA8200	FA157	FA79	VC945
C2TF12102A ...	CS751	FA8200	FA157	FA79	VC965
C2TF12102B ...	CS751	FA8200	FA157	FA79	VC965
C2TF12102D ...	CS751	FA8200	FA157	FA79	VC965
C2TF12102E ...	CS751	FA8200	FA157	FA79	VC965
C2TF12102F ...	CS751	FA8200	FA157	FA79	—
C2TF12102H ...	CS751	FA8200	FA157	FA79	—
C2TF12127A ...	CS753	FA66	FA67	FA6900	VC915
C2TZ12127A ...	CS751	FA8200	FA157	FA79	VC965
C2TZ12127B ...	CS751	FA8200	FA157	FA79	VC965
C2TZ12127C ...	CS751	FA8200	FA157	FA79	VC965
C2TZ12127D ...	CS751	FA8200	FA157	FA79	VC965
C2TZ12127E ...	CS753	FA66	FA67	FA6900	VC915
C2TZ12127H ...	CS751	FA8200	FA157	FA79	VC965
C2TZ12127J ...	CS751	FA8200	FA157	FA79	VC965
C2UF12127A ...	CS753	FA66	FA67	FA6900	VC915
C2UF12127B ...	CS753	FA66	FA67	FA6900	VC915

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C2UF12127C ...	CS753	FA66	FA67	FA6900	VC915
C2UZ12127A ...	CS753	FA66	FA67	FA6900	VC915
C2UZ12127C ...	CS753	FA66	FA67	FA6900	VC915
C2VF12127B ...	CS753	FA76	FA67	FA6900	VC915
C3AF12127AA ...	CS753	FA66	FA67	FA6900	—
C3AF12127AB ...	CS751	FA8200	FA157	FA79	VC945
C3AF12127AD ...	CS751	FA8200	FA157	FA79	VC945
C3AF12127AE ...	CS756 ⁹	FA66	FA157	FA79	—
C3AF12127AF ...	CS751	FA66	FA157	FA79	—
C3AF12127AG ...	CS751	FA8200	FA157	FA79	VC945
C3AF12127AH ...	CS751	FA8200	FA157	FA79	VC945
C3AF12127AI ...	CS751	FA8200	FA157	FA79	VC945
C3AF12127AJ ...	CS751	FA8200	FA157	FA79	VC945
C3AF12127G ...	CS753	FA66	FA67	FA6900	VC915
C3AF12127H ...	CS753	FA66	FA67	FA6900	VC915
C3AF12127J ...	CS753	FA66	FA67	FA6900	—
C3AF12127U ...	CS751	FA8200	FA157	FA79	VC945
C3AF12127Z ...	CS753	FA66	FA67	FA6900	VC915
C3AZ12127AA ...	CS751	FA8200	FA157	FA79	VC945
C3AZ12127AB ...	CS751	FA8200	FA157	FA79	VC945
C3AZ12127AD ...	CS751	FA8200	FA157	FA79	VC945
C3AZ12127AE ...	CS756 ⁹	FA66	FA157	FA79	—
C3AZ12127AF ...	CS751	FA66	FA157	FA79	—
C3AZ12127AG ...	CS751	FA8200	FA157	FA79	VC945
C3AZ12127AH ...	CS751	FA8200	FA157	FA79	VC945
C3AZ12127U ...	CS751	FA8200	FA157	FA79	VC945
C3DF12127E ...	CS753	FA66	FA67	FA6900	VC915
C3DF12127F ...	CS753	FA66	FA67	FA6900	VC915
C3DF12127G ...	CS753	FA66	FA67	FA6900	VC915
C3DF12127H ...	CS753	FA76	FA67	FA6900	VC915
C3DF12127J ...	CS753	FA66	FA67	FA6900	VC915
C3DF12127L ...	CS753	FA66	FA67	FA6900	VC915
C3DZ12127A ...	CS753	FA76	FA67	FA6900	VC915
C3DZ12127B ...	CS753	FA76	FA67	FA6900	VC915
C3DZ12127C ...	CS753	FA76	FA67	FA6900	VC915
C3DZ12127D ...	CS750	FA66	FA67	FA6900	VC915
C3JZ12127A ...	CS753	FA76	—	FA352	—
C3MF12127A ...	CS751	FA8200	FA157	FA79	VC945
C3MY12127A ...	CS751	FA8200	FA157	FA79	VC945
C3OF12127A ...	CS751	FA8200	FA157	FA79	VC945
C3OF12127B ...	CS751	FA8200	FA157	FA79	VC945
C3OF12127C ...	CS753	FA66	FA67	FA6900	VC915
C3OF12127D ...	CS756 ⁹	FA66	FA157	FA79	—
C3OF12127E ...	CS751	FA8200	FA157	FA79	VC970
C3OF12127F ...	CS756 ⁹	FA8200	FA157	FA79	—
C3OF12127G ...	CS751	FA8200	FA157	FA79	VC945
C3OF12127H ...	CS751	FA8200	FA157	FA79	VC945
C3OF12127I ...	CS751	FA8200	FA157	FA79	VC945

(continued on next page)

⁹ Two required

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C30F12127J ...	CS751	FA8200	FA157	FA79	VC945
C30Z12127A ...	CS751	FA8200	FA157	FA79	VC945
C30Z12127B ...	CS751	FA8200	FA157	FA79	VC945
C30Z12127C ...	CS753	FA76	FA67	FA6900	VC915
C30Z12127D ...	CS756 ⁹	FA66	FA157	FA79	—
C3SF12127D ...	CS751	FA8200	FA157	FA79	VC945
C3SZ12127D ...	CS751	FA8200	FA157	FA79	VC945
C3TF12102A ...	CS751	FA8200	FA157	FA79	—
C3TF12102C ...	CS751	FA8200	FA157	FA79	VC965
C3TF12102D ...	CS751	FA8200	FA157	FA79	VC965
C3TF12102E ...	CS751	FA8200	FA157	FA79	—
C3TF12102F ...	CS751	FA8200	FA157	FA79	—
C3TF12102G ...	CS751	FA8200	FA157	FA79	—
C3TF12102H ...	CS751	FA8200	FA157	FA79	VC965
C3TF12102J ...	CS751	FA8200	FA157	FA79	VC965
C3TF12127A ...	CS751	FA8200	FA157	FA79	VC945
C3TF12127C ...	CS753	FA66	FA67	FA6900	—
C3TF12127D ...	CS753	FA66	FA67	FA6900	VC915
C3TF12127H ...	CS751	FA8200	FA157	FA79	VC965
C3TF12127J ...	CS751	FA8200	FA157	FA79	VC965
C3TF12127K ...	CS751	FA8200	FA157	FA79	VC945
C3TF12127L ...	CS751	FA8200	FA157	FA79	VC965
C3TF12127M ...	CS751	FA8200	FA157	FA79	VC965
C3TZ12127A ...	CS751	FA8200	FA157	FA79	VC945
C3TZ12127AK ...	CS751	FA8200	FA157	FA79	VC945
C3TZ12127C ...	CS753	FA66	FA67	FA6900	VC915
C3TZ12127H ...	CS751	FA8200	FA157	FA79	VC965
C3TZ12127K ...	CS751	FA8200	FA157	FA79	VC945
C3TZ12127M ...	CS751	FA8200	FA157	FA79	VC965
C3UF12127D ...	CS753	FA66	FA67	FA6900	VC915
C3UF12127E ...	CS753	FA66	FA67	FA6900	VC915
C3UZ12127A ...	CS753	FA66	FA67	FA6900	VC915
C3UZ12127B ...	CS753	FA66	FA67	FA6900	VC915
C3VF12127A ...	CS751	FA8200	FA157	FA79	—
C3VF12127B ...	CS751	FA8200	FA157	FA79	VC970
C3VY12127A ...	CS751	FA8200	FA157	FA79	—
C3VY12127B ...	CS751	FA8200	FA157	FA79	—
C4AF12127C ...	CS751	FA8200	FA157	FA79	VC945
C4AF12127G ...	CS753	FA66	FA67	FA6900	VC915
C4AF12127H ...	CS753	FA66	FA67	FA6900	—
C4AF12127J ...	CS753	FA66	FA67	FA6900	VC915
C4AF12127K ...	CS753	FA66	FA67	FA6900	VC915
C4AF12127L ...	CS751	FA8200	FA157	FA79	VC945
C4AF12127M ...	CS751	FA8200	FA157	FA79	VC945
C4AF12127N ...	CS751	FA8200	FA157	FA79	VC970
C4AF12127R ...	CS753	FA66	FA67	FA6900	VC915
C4AF12127U ...	CS751	FA8200	FA157	FA79	VC945
C4AZ12127A ...	CS753	FA76	FA67	FA6900	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C4AZ12127D ...	CS753	FA76	FA67	FA6900	VC915
C4AZ12127E ...	CS753	FA76	FA67	FA6900	VC915
C4AZ12127F ...	CS753	FA76	FA67	FA6900	—
C4AZ12127L ...	CS751	FA8200	FA157	FA79	VC945
C4AZ12127M ...	CS751	FA8200	FA157	FA79	VC945
C4AZ12127N ...	CS751	FA8200	FA157	FA79	VC970
C4AZ12127P ...	CS751	FA8200	FA157	FA79	VC970
C4AZ12127U ...	CS751	FA8200	FA157	FA79	VC945
C4DF12127A ...	CS753	FA66	FA67	FA6900	VC915
C4DF12127B ...	CS753	FA66	FA67	FA6900	VC915
C4DF12127C ...	CS753	FA66	FA67	FA6900	VC915
C4DF12127D ...	CS753	FA66	FA67	FA6900	VC915
C4DZ12127A ...	CS753	FA76	FA67	FA6900	VC915
C4DZ12127B ...	CS753	FA66	FA67	FA6900	VC915
C4DZ12127D ...	CS753	FA66	FA67	FA6900	VC915
C4DZ12127E ...	CS753	FA66	FA67	FA6900	VC915
C4FT12102C ...	CS751	FA8200	FA157	FA79	VC965
C4FT12102D ...	CS751	FA8200	FA157	FA79	VC965
C4FT12102G ...	CS751	FA8200	FA157	FA79	VC965
C4FT12102H ...	CS751	FA8200	FA157	FA79	VC965
C4GF12127A ...	CS751	FA8200	FA157	FA79	VC945
C4GF12127B ...	CS751	FA8200	FA157	FA79	VC945
C4GY12127A ...	CS751	FA76	FA157	FA79	VC945
C4GY12127B ...	CS751	FA8200	FA157	FA79	VC945
C4JZ12127D ...	CS753	FA66	FA67	FA352	—
C4OF12127A ...	CS751	FA8200	FA157	FA79	VC945
C4OF12127B ...	CS751	FA8200	FA157	FA79	—
C4OF12127E ...	CS753	FA66	FA67	FA6900	VC915
C4OZ12127A ...	CS751	FA8200	FA157	FA79	VC945
C4OZ12127B ...	CS751	FA8200	FA157	FA79	—
C4OZ12127E ...	CS753	FA76	FA67	FA6900	VC915
C4OZ12127F ...	CS753	FA66	FA67	FA6900	VC915
C4SF12127A ...	CS751	—	FA157	FA79	VC945
C4SF12127B ...	CS751	—	FA157	FA79	VC945
C4SZ12127A ...	CS751	FA8200	FA157	FA79	VC945
C4SZ12127B ...	CS751	FA8200	FA157	FA79	VC945
C4TF12102A ...	CS751	FA8200	FA157	FA79	VC965
C4TF12102C ...	CS751	FA8200	FA157	FA79	VC965
C4TF12102D ...	CS751	—	FA157	FA79	VC965
C4TF12102E ...	CS751	FA8200	FA157	FA79	VC965
C4TF12102F ...	CS751	—	FA157	FA79	VC945
C4TF12102G ...	CS751	FA8200	FA157	FA79	VC965
C4TF12102H ...	CS751	—	FA157	FA79	VC965
C4TF12127C ...	CS753	FA66	FA67	FA6900	VC915
C4TF12127D ...	CS753	FA66	FA67	FA6900	VC915
C4TF12127E ...	CS751	FA8200	FA157	FA79	VC945
C4TF12127F ...	CS751	FA8200	FA157	FA79	VC945
C4TZ12127A ...	CS753	FA66	FA67	FA6900	VC915

(continued on next page)

⁹ Two required

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C4TZ12127B ...	CS753	FA66	FA67	FA6900	VC915
C4TZ12127E ...	CS751	FA8200	FA157	FA79	VC965
C4TZ12127F ...	CS751	FA8200	FA157	FA79	VC965
C4TZ12127G ...	CS751	FA8200	FA157	FA79	VC965
C4TZ12127H ...	CS751	FA8200	FA157	FA79	VC965
C4TZ12127J ...	CS751	FA8200	FA157	FA79	—
C4TZ12127K ...	CS751	FA8200	FA157	FA79	—
C4TZ12127L ...	CS751	FA8200	FA157	FA79	VC965
C4TZ12127M ...	CS751	FA8200	FA157	FA79	VC965
C4TZ12127N ...	CS751	FA8200	FA157	FA79	VC965
C4UF12127B ...	CS753	FA66	FA67	FA6900	VC915
C4UF12127C ...	CS753	FA66	FA67	FA6900	VC915
C4UZ12127B ...	CS750	FA66	FA67	FA6900	VC915
C4UZ12127C ...	CS750	FA66	FA67	FA6900	VC915
C4VF12127B ...	CS751	FA8200	FA157	FA79	VC945
C4VF12127C ...	CS751	FA8200	FA157	FA79	VC945
C4VY12127A ...	CS751	FA8200	FA157	FA79	VC945
C4ZF12127A ...	CS753	FA66	FA67	FA6900	VC915
C4ZF12127B ...	CS751	FA8200	FA157	FA79	VC945
C4ZF12127C ...	CS751	FA8200	FA157	FA79	VC945
C4ZF12127D ...	CS756 ⁹	FA66	FA157	FA79	—
C4ZF12127E ...	CS751	FA8200	FA157	FA79	VC945
C5AF12127A ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127AD ...	CS753	FA66	FA67	FA6900	VC915
C5AF12127AE ...	CS753	FA66	FA67	FA6900	VC915
C5AF12127AF ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127AK ...	CS753	FA8200	FA158	FA6900	—
C5AF12127AL ...	CS753	FA76	FA158	FA6900	—
C5AF12127AM ...	CS753	FA8200	FA158	FA6900	—
C5AF12127AN ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127AU ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127AV ...	CS756 ⁹	FA66	FA157	FA79	—
C5AF12127AZ ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127B ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127BD ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127BF ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127BG ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127BK ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127BM ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127BN ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127BR ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127BU ...	CS753	FA8200	FA158	FA6900	—
C5AF12127C ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127E ...	CS756 ⁹	FA66	FA157	FA79	—
C5AF12127F ...	CS751	—	FA157	FA79	—
C5AF12127G ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127K ...	CS753	FA66	FA67	FA6900	—
C5AF12127L ...	CS753	FA76	FA67	FA6900	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C5AF12127M ...	CS751	FA8200	FA157	FA79	VC970
C5AF12127N ...	CS751	FA8200	FA157	FA79	VC970
C5AZ12127A ...	CS753	FA66	FA67	FA6900	VC915
C5AZ12127AA ...	CS753	FA8200	FA158	FA6900	—
C5AZ12127AL ...	CS753	FA8200	FA158	FA6900	—
C5AZ12127B ...	CS751	FA8200	FA157	FA79	VC970
C5AZ12127BU ...	CS753	FA8200	FA158	FA6900	—
C5AZ12127C ...	CS751	FA8200	FA157	FA79	VC970
C5AZ12127E ...	CS756 ⁹	FA66	FA157	FA79	—
C5AZ12127F ...	CS751	—	FA157	FA79	—
C5AZ12127K ...	CS753	FA66	FA67	FA6900	VC915
C5AZ12127L ...	CS753	FA66	FA67	FA6900	VC915
C5AZ12127M ...	CS751	FA8200	FA157	FA79	VC970
C5AZ12127N ...	CS751	FA8200	FA157	FA79	VC970
C5AZ12127P ...	CS753	FA66	FA67	FA6900	VC915
C5AZ12127W ...	CS751	FA8200	FA157	FA79	VC970
C5DF12127C ...	CS753	FA66	FA67	FA6900	VC915
C5DF12127D ...	CS753	FA66	FA67	FA6900	VC915
C5DF12127E ...	CS753	FA66	FA67	FA6900	VC915
C5DF12127F ...	CS753	FA66	FA67	FA6900	VC915
C5DF12127J ...	CS753	FA66	FA67	FA6900	—
C5DF12127K ...	CS753	FA66	FA67	FA6900	VC915
C5DZ12127C ...	CS753	FA66	FA67	FA6900	VC915
C5DZ12127D ...	CS753	FA66	FA67	FA6900	VC915
C5DZ12127E ...	CS753	FA66	FA67	FA6900	VC915
C5DZ12127F ...	CS753	FA66	FA67	FA6900	VC915
C5FT12102A ...	CS751	FA8200	FA157	FA79	VC965
C5FT12102B ...	CS751	FA8200	FA157	FA79	VC965
C5FT12102D ...	CS751	FA8200	FA157	FA79	VC965
C5GA12127A ...	CS751	FA8200	FA157	FA79	VC970
C5GF12127A ...	CS751	FA8200	FA157	FA79	VC970
C5GF12127B ...	CS751	FA8200	FA157	FA79	VC970
C5GF12127C ...	CS751	FA8200	FA157	FA79	VC970
C5GF12127D ...	CS751	FA8200	FA157	FA79	VC970
C5GY12127A ...	CS751	FA8200	FA157	FA79	VC970
C5GY12127B ...	CS751	FA8200	FA157	FA79	VC970
C5JF12127A ...	CS751	FA8200	FA157	FA79	VC970
C5JF12127B ...	CS751	FA8200	FA157	FA79	VC970
C5JF12127C ...	CS751	FA8200	FA157	FA79	VC970
C5MF12127A ...	CS751	FA8200	FA157	FA79	VC970
C5MF12127N ...	CS751	FA8200	FA157	FA79	VC970
C5MY12127A ...	CS751	FA8200	FA157	FA79	VC970
C5NF12127B ...	CS751	FA90	FA91	FA92	—
C5NF12127C ...	CS751	FA90	FA91	FA92	—
C5OF12127E ...	CS756 ⁹	FA8200	FA157	FA79	—
C5OF12127L ...	CS751	FA8200	FA157	FA79	VC970
C5OF12127M ...	CS751	FA8200	FA157	FA79	VC970
C5OF12127S ...	CS751	FA8200	FA157	FA79	VC970

(continued on next page)

⁹ Two required

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C5OF12127T ...	CS751	FA8200	FA157	FA79	VC970
C5OF12127U ...	CS751	FA8200	FA157	FA79	VC970
C5OZ12127E ...	CS756 ⁹	FA66	FA157	FA79	—
C5SF12127B ...	CS751	—	FA157	FA79	VC970
C5SZ12127B ...	CS751	—	FA157	FA79	VC970
C5TF12102A ...	CS751	FA8200	FA157	FA79	VC965
C5TF12102B ...	CS751	—	FA157	FA79	VC965
C5TF12102C ...	CS751	FA8200	FA157	FA79	VC965
C5TF12102D ...	CS751	—	FA157	FA79	VC965
C5TF12127A ...	CS751	FA8200	FA157	FA79	VC970
C5TF12127AB ...	CS751	FA8200	FA157	FA79	VC970
C5TF12127AC ...	CS753	FA66	FA67	FA6900	—
C5TF12127AD ...	CS751	FA8200	FA157	FA79	VC970
C5TF12127B ...	CS751	FA8200	FA157	FA79	VC970
C5TF12127C ...	CS751	—	FA157	FA79	VC970
C5TF12127J ...	CS753	FA8200	FA158	FA6900	—
C5TF12127K ...	CS753	FA8200	FA158	FA6900	—
C5TF12127L ...	CS753	FA8200	FA158	FA6900	—
C5TF12127M ...	CS753	FA8200	FA158	FA6900	—
C5TF12127V ...	CS753	FA8200	FA158	FA6900	—
C5TZ12127A ...	CS751	FA8200	FA157	FA79	VC970
C5TZ12127AA ...	CS751	FA8200	FA157	FA79	VC965
C5TZ12127AB ...	CS751	FA8200	FA157	FA79	VC965
C5TZ12127AC ...	CS753	FA66	FA67	FA6900	—
C5TZ12127AD ...	CS753	FA66	FA67	FA6900	—
C5TZ12127AE ...	CS751	FA8200	FA157	FA79	VC970
C5TZ12127AF ...	CS751	FA8200	FA157	FA79	VC965
C5TZ12127B ...	CS751	FA8200	FA157	FA79	VC970
C5TZ12127C ...	CS751	FA8200	FA157	FA79	VC970
C5TZ12127D ...	CS750	FA8200	FA158	FA6900	—
C5TZ12127E ...	CS750	FA8200	FA158	FA6900	—
C5TZ12127F ...	CS750	FA8200	FA158	FA6900	—
C5TZ12127J ...	CS750	FA8200	FA158	FA6900	—
C5TZ12127K ...	CS750	FA8200	FA158	FA6900	—
C5TZ12127L ...	CS750	FA8200	FA158	FA6900	—
C5TZ12127N ...	CS750	FA8200	FA158	FA6900	—
C5TZ12127P ...	CS750	FA8200	FA158	FA6900	—
C5UF12127B ...	CS751	FA8200	FA157	FA79	VC970
C5UF12127C ...	CS751	FA8200	FA157	FA79	VC970
C5UF12127G ...	CS753	FA66	FA67	FA6900	VC915
C5UF12127H ...	CS753	FA66	FA67	FA6900	VC915
C5UF12127I ...	CS753	FA66	FA67	FA6900	VC915
C5UF12127J ...	CS753	FA66	FA67	FA6900	VC915
C5UF12127K ...	CS753	FA66	FA67	FA6900	VC915
C5UF12127L ...	CS753	FA66	FA67	FA6900	VC915
C5UZ12127E ...	CS753	FA66	FA67	FA6900	VC915
C5UZ12127J ...	CS753	FA66	FA67	FA6900	VC915
C5UZ12127K ...	CS753	FA66	FA67	FA6900	VC915

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C5UZ12127L ...	CS753	FA66	FA67	FA6900	VC915
C5VF12127A ...	CS751	FA8200	FA157	FA79	VC970
C5VF12127B ...	CS751	—	FA157	FA79	VC970
C5VY12127A ...	CS751	FA8200	FA157	FA79	VC970
C5VY12127B ...	CS751	—	FA157	FA79	VC970
C5VY12127C ...	CS751	FA8200	FA157	FA79	VC945
C5ZF12127J ...	CS751	FA8200	FA157	FA79	VC970
C5ZZ12127A ...	CS753	FA66	FA67	FA6900	VC915
C5ZZ12127B ...	CS751	FA8200	FA157	FA79	VC970
C5ZZ12127C ...	CS751	FA8200	FA157	FA79	VC945
C5ZZ12127D ...	CS756 ⁹	FA66	FA157	FA79	—
C5ZZ12127E ...	CS751	FA8200	FA157	FA79	VC945
C6AF12127A ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127AA ...	CS753	FA8200	FA158	FA6900	—
C6AF12127AB ...	CS753	FA8200	FA158	FA6900	—
C6AF12127AC ...	CS753	FA8200	FA158	FA6900	—
C6AF12127AD ...	CS753	FA8200	FA158	FA6900	—
C6AF12127AF ...	CS753	FA8200	FA158	FA6900	—
C6AF12127AG ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127AH ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127AI ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127AJ ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127AK ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127B ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127BA ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127C ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127D ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127E ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127F ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127J ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127K ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127L ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127M ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127S ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127T ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127U ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127V ...	CS751	FA8200	FA157	FA79	VC970
C6AF12127Y ...	CS753	FA66	FA67	FA6900	VC915
C6AH12100A ...	CS751	EP30	EP49	EP50	—
C6AH12100B ...	CS751	EP30	EP49	EP50	—
C6AH12100C ...	CS751	EP30	EP49	EP50	—
C6AZ12127A ...	CS751	FA8200	FA157	FA79	VC970
C6AZ12127AG ...	CS751	FA8200	FA157	FA79	VC970
C6AZ12127AH ...	CS751	FA8200	FA157	FA79	VC970
C6AZ12127BA ...	CS751	FA8200	FA157	FA79	VC970
C6AZ12127C ...	CS751	FA8200	FA157	FA79	VC970
C6AZ12127D ...	CS751	FA8200	FA157	FA79	VC970
C6AZ12127E ...	CS751	FA8200	FA157	FA79	VC970

(continued on next page)

⁹ Two required

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C6AZ12127F ...	CS751	FA8200	FA157	FA79	VC970
C6AZ12127G ...	CS753	FA8200	FA158	FA6900	—
C6AZ12127J ...	CS751	FA8200	FA157	FA79	VC970
C6AZ12127K ...	CS751	FA8200	FA157	FA79	VC970
C6AZ12127L ...	CS751	FA8200	FA157	FA79	VC970
C6AZ12127M ...	CS751	FA8200	FA157	FA79	VC970
C6AZ12127N ...	CS753	FA8200	FA158	FA6900	—
C6AZ12127S ...	CS751	FA8200	FA157	FA79	VC970
C6AZ12127T ...	CS751	FA8200	FA157	FA79	VC970
C6AZ12127U ...	CS751	FA8200	FA157	FA79	VC970
C6AZ12127V ...	CS751	FA8200	FA157	FA79	VC970
C6DF12127A ...	CS753	FA8200	FA158	FA6900	—
C6DF12127C ...	CS753	FA8200	FA158	FA6900	—
C6DF12127D ...	CS753	FA8200	FA158	FA6900	—
C6DF12127E ...	CS753	FA8200	FA158	FA6900	—
C6DF12127F ...	CS753	FA8200	FA158	FA6900	—
C6DF12127K ...	CS753	FA8200	FA158	FA6900	—
C6DZ12127A ...	CS753	FA8200	FA158	FA6900	—
C6DZ12127C ...	CS753	FA8200	FA158	FA6900	—
C6DZ12127D ...	CS753	FA8200	FA158	FA6900	—
C6DZ12127E ...	CS753	FA8200	FA158	FA6900	—
C6DZ12127K ...	CS753	FA8200	FA158	FA6900	—
C6MF12127A ...	CS751	FA8200	FA157	FA79	VC970
C6MY12127B ...	CS751	FA8200	FA157	FA79	VC970
C6NF12127A ...	CS751	FA90	FA91	FA92	—
C6OF12127E ...	CS751	FA8200	FA157	FA79	VC970
C6OF12127F ...	CS751	FA8200	FA157	FA79	VC970
C6OF12127G ...	CS751	FA8200	FA157	FA79	VC970
C6OF12127H ...	CS751	FA8200	FA157	FA79	VC970
C6OF12127I ...	CS751	FA8200	FA157	FA79	VC970
C6OF12127J ...	CS751	FA8200	FA157	FA79	VC970
C6OZ12127E ...	CS751	FA8200	FA157	FA79	VC970
C6OZ12127F ...	CS751	FA8200	FA157	FA79	VC970
C6OZ12127G ...	CS751	FA8200	FA157	FA79	VC970
C6OZ12127H ...	CS751	FA8200	FA157	FA79	VC970
C6OZ12127J ...	CS751	FA8200	FA157	FA79	VC970
C6OZ12127K ...	CS751	FA8200	FA157	FA79	VC970
C6SF12127B ...	CS751	—	FA157	FA79	VC970
C6SF12127D ...	CS751	—	FA157	FA79	VC970
C6SZ12127B ...	CS751	—	FA157	FA79	VC970
C6SZ12127D ...	CS751	—	FA157	FA79	VC970
C6TF12127AA ...	CS751	FA8200	FA157	FA79	VC970
C6TF12127AB ...	CS751	—	FA157	FA79	VC970
C6TF12127AC ...	CS753	FA66	FA67	FA6900	VC915
C6TF12127AD ...	CS753	FA8200	FA158	FA6900	—
C6TF12127AE ...	CS753	FA8200	FA158	FA6900	—
C6TF12127AF ...	CS753	FA8200	FA158	FA6900	—
C6TF12127AG ...	CS753	FA8200	FA158	FA6900	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C6TF12127AH ...	CS753	FA8200	FA158	FA6900	—
C6TF12127AI ...	CS753	FA8200	FA158	FA6900	—
C6TF12127AJ ...	CS753	FA8200	FA158	FA6900	—
C6TF12127AM ...	CS753	—	FA67	FA6900	VC915
C6TF12127AN ...	CS753	—	FA67	FA6900	VC915
C6TF12127AR ...	CS753	—	FA158	FA6900	—
C6TF12127AS ...	CS753	—	FA158	FA6900	—
C6TF12127AT ...	CS753	—	FA158	FA6900	—
C6TF12127AU ...	CS753	—	FA158	FA6900	—
C6TF12127AV ...	CS753	—	FA158	FA6900	—
C6TF12127AW ...	CS753	—	FA158	FA6900	—
C6TF12127AX ...	CS753	—	FA158	FA6900	—
C6TF12127AY ...	CS753	—	FA158	FA6900	—
C6TF12127BA ...	CS753	—	FA158	FA6900	—
C6TF12127BB ...	CS753	—	FA158	FA6900	—
C6TF12127BC ...	CS753	—	FA158	FA6900	—
C6TF12127BD ...	CS753	—	FA158	FA6900	—
C6TF12127BE ...	CS753	—	FA158	FA6900	—
C6TF12127BH ...	CS753	FA8200	FA157	FA79	VC970
C6TF12127BJ ...	CS753	FA8200	FA157	FA79	VC970
C6TF12127G ...	CS751	—	FA157	FA79	VC970
C6TF12127H ...	CS751	—	FA157	FA79	VC970
C6TF12127M ...	CS753	—	FA158	FA6900	—
C6TZ12127A ...	CS750	FA8200	FA158	FA6900	—
C6TZ12127AA ...	CS751	FA8200	FA157	FA79	VC970
C6TZ12127AB ...	CS751	FA8200	FA157	FA79	VC970
C6TZ12127B ...	CS750	FA8200	FA158	FA6900	—
C6TZ12127BH ...	CS751	FA8200	FA157	FA79	VC970
C6TZ12127C ...	CS750	FA8200	FA158	FA6900	—
C6TZ12127D ...	CS750	FA8200	FA158	FA6900	—
C6TZ12127E ...	CS750	FA8200	FA158	FA6900	—
C6TZ12127F ...	CS750	FA66	FA67	FA6900	VC915
C6TZ12127G ...	CS751	FA8200	FA157	FA79	VC970
C6TZ12127H ...	CS751	FA8200	FA157	FA79	VC970
C6TZ12127J ...	CS750	FA66	FA67	FA6900	VC915
C6TZ12127N ...	CS750	FA8200	FA158	FA6900	—
C6TZ12127R ...	CS750	FA8200	FA158	FA6900	—
C6TZ12127S ...	CS750	FA8200	FA158	FA6900	—
C6TZ12127T ...	CS750	FA8200	FA158	FA6900	—
C6TZ12127V ...	CS750	FA8200	FA158	FA6900	—
C6UF12127F ...	CS753	FA66	FA67	FA6900	VC915
C6UF12127H ...	CS753	FA8200	FA158	FA6900	—
C6UZ12127E ...	CS750	FA8200	FA158	FA6900	—
C6VF12127A ...	CS751	FA8200	FA157	FA79	VC970
C6VF12127B ...	CS751	—	FA157	FA79	VC970
C6VY12127A ...	CS751	FA8200	FA157	FA79	VC970
C6VY12127B ...	CS751	—	FA157	FA79	VC970
C6VY12127C ...	CS751	FA8200	FA157	FA79	VC970

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C6ZF12127A ...	CS751	FA8200	FA157	FA79	VC970
C6ZF12127B ...	CS751	FA8200	FA157	FA79	VC970
C6ZZ12127A ...	CS751	FA8200	FA157	FA79	VC970
C6ZZ12127B ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127A ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127AA ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127AC ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127AD ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127AE ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127AF ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127AG ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127AH ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127B ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127C ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127D ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127E ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127F ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127H ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127J ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127L ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127M ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127N ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127S ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127T ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127U ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127V ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127Y ...	CS751	FA8200	FA157	FA79	VC970
C7AF12127Z ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127A ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127AE ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127AG ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127AH ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127AJ ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127B ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127D ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127E ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127F ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127H ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127J ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127L ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127M ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127N ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127S ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127T ...	CS751	FA8200	FA157	FA79	VC970
C7AZ12127U ...	CS751	FA8200	FA157	FA79	VC970
C7BH12100A ...	CS751	EP30	EP49	EP50	—
C7BH12100D ...	CS751	EP30	EP49	EP50	—
C7BH12100K ...	CS751	EP30	EP49	EP50	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C7DF12127A ...	CS753	FA8200	FA158	FA6900	—
C7DF12127B ...	CS753	FA8200	FA158	FA6900	—
C7DF12127C ...	CS753	FA8200	FA158	FA6900	—
C7DF12127D ...	CS753	FA8200	FA158	FA6900	—
C7DF12127F ...	CS753	FA8200	FA158	FA6900	—
C7DF12127G ...	CS753	FA8200	FA158	FA6900	—
C7DZ12127A ...	CS753	FA8200	FA158	FA6900	—
C7DZ12127F ...	CS753	FA8200	FA158	FA6900	—
C7DZ12127G ...	CS753	FA8200	FA158	FA6900	—
C7MF12127A ...	CS751	FA8200	FA157	FA79	VC970
C7MF12127G ...	CS751	FA8200	FA157	FA79	VC970
C7MF12127H ...	CS751	FA8200	FA157	FA79	VC970
C7NF12127A ...	CS751	FA90	FA91	FA92	—
C7NF12127B ...	CS751	FA90	—	—	—
C7NF12127D ...	CS751	FA90	FA91	FA92	—
C7NF12127E ...	CS751	FA90	—	—	—
C7OF12127A ...	CS751	FA8200	FA157	FA79	VC970
C7OF12127B ...	CS751	FA8200	FA157	FA79	VC970
C7OF12127D ...	CS751	FA8200	FA157	FA79	VC970
C7OF12127E ...	CS751	FA8200	FA157	FA79	VC970
C7OF12127F ...	CS751	FA8200	FA157	FA79	VC970
C7OF12127G ...	CS751	FA8200	FA157	FA79	VC970
C7OF12127H ...	CS751	FA8200	FA157	FA79	VC970
C7OF12127I ...	CS751	FA8200	FA157	FA79	VC970
C7OF12127J ...	CS751	FA8200	FA157	FA79	VC970
C7OF12127K ...	CS756 ⁹	FA66	FA157	FA79	—
C7OZ12127A ...	CS751	FA8200	FA157	FA79	VC970
C7OZ12127B ...	CS751	FA8200	FA157	FA79	VC970
C7OZ12127D ...	CS751	FA8200	FA157	FA79	VC970
C7OZ12127E ...	CS751	FA8200	FA157	FA79	VC970
C7OZ12127F ...	CS751	FA8200	FA157	FA79	VC970
C7OZ12127H ...	CS751	FA8200	FA157	FA79	VC970
C7SF12127A ...	CS751	FA8200	FA157	FA79	VC970
C7SF12127B ...	CS751	FA8200	FA157	FA79	VC970
C7SF12127C ...	CS751	FA8200	FA157	FA79	VC970
C7SF12127E ...	CS751	FA8200	FA157	FA79	VC970
C7SF12127F ...	CS751	FA8200	FA157	FA79	VC970
C7SZ12127A ...	CS751	FA8200	FA157	FA79	VC970
C7SZ12127B ...	CS751	FA8200	FA157	FA79	VC970
C7SZ12127C ...	CS751	FA8200	FA157	FA79	VC970
C7SZ12127D ...	CS751	FA8200	FA157	FA79	VC970
C7SZ12127E ...	CS751	FA8200	FA157	FA79	VC970
C7SZ12127F ...	CS751	FA8200	FA157	FA79	VC970
C7SZ12127H ...	CS751	FA8200	FA157	FA79	VC970
C7TF12102A ...	CS751	FA8200	FA157	FA79	VC965
C7TF12102D ...	CS751	FA8200	FA157	FA79	VC965
C7TF12127A ...	CS751	FA8200	FA157	FA79	VC970
C7TF12127D ...	CS751	FA8200	FA157	FA79	VC970

(continued on next page)

⁹ Two required

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C7TF12127F ...	CS751	FA8200	FA157	FA79	VC970
C7TF12127J ...	CS753	FA8200	FA158	FA6900	—
C7TF12127L ...	CS753	FA8200	FA158	FA6900	—
C7TF12127M ...	CS751	FA8200	FA157	—	VC970
C7TF12127T ...	CS751	FA8200	FA157	FA79	VC970
C7TZ12127A ...	CS751	FA8200	FA157	FA79	VC970
C7TZ12127J ...	CS751	FA8200	FA157	FA79	—
C7TZ12127M ...	CS751	FA8200	FA157	FA79	VC970
C7TZ12127T ...	CS751	FA8200	FA157	FA79	VC970
C7VF12127A ...	CS751	FA8200	FA157	FA79	VC970
C7ZF12127A ...	CS751	FA8200	FA157	FA79	VC970
C7ZF12127B ...	CS751	FA8200	FA157	FA79	VC970
C7ZF12127C ...	CS751	FA8200	FA157	FA79	VC970
C7ZF12127D ...	CS751	FA8200	FA157	FA79	VC970
C7ZF12127E ...	CS751	FA8200	FA157	FA79	VC970
C7ZF12127F ...	CS751	FA8200	FA157	FA79	VC970
C7ZF12127G ...	CS751	FA8200	FA157	FA79	VC970
C7ZF12127H ...	CS751	FA8200	FA157	FA79	VC970
C7ZF12127J ...	CS756 ⁹	FA66	FA157	FA79	—
C7ZZ12127A ...	CS751	FA8200	FA157	FA79	VC970
C7ZZ12127B ...	CS751	FA8200	FA157	FA79	VC970
C7ZZ12127C ...	CS751	FA8200	FA157	FA79	VC970
C7ZZ12127D ...	CS751	FA8200	FA157	FA79	VC970
C7ZZ12127E ...	CS751	FA8200	FA157	FA79	VC970
C7ZZ12127F ...	CS751	FA8200	FA157	FA79	VC970
C7ZZ12127G ...	CS751	FA8200	FA157	FA79	VC970
C7ZZ12127H ...	CS751	FA8200	FA157	FA79	VC970
C7ZZ12127J ...	CS756 ⁹	FA66	FA157	FA79	—
C7ZZ12127K ...	CS756 ⁹	FA66	FA157	FA79	—
C8AF12127A ...	CS753	FA8200	FA158	FA6900	VC2025
C8AF12127AD ...	CS751	FA8200	FA157	FA79	VC970
C8AF12127AE ...	CS751	FA8200	FA157	FA79	—
C8AF12127AF ...	CS751	FA8200	FA157	FA79	—
C8AF12127AG ...	CS751	FA8200	FA157	FA79	—
C8AF12127AH ...	CS751	FA8200	FA157	FA79	—
C8AF12127AI ...	CS751	FA8200	FA157	FA79	—
C8AF12127AJ ...	CS751	FA8200	FA157	FA79	—
C8AF12127B ...	CS753	FA8200	FA158	FA6900	VC2025
C8AF12127C ...	CS753	FA8200	FA158	FA6900	—
C8AF12127D ...	CS753	FA8200	FA158	FA6900	—
C8AF12127E ...	CS751	FA8200	FA157	FA79	VC2027
C8AF12127F ...	CS751	FA8200	FA157	FA79	VC2027
C8AF12127J ...	CS751	FA8200	FA157	FA79	VC970
C8AF12127M ...	CS751	FA8200	FA157	FA79	VC2000
C8AF12127N ...	CS751	FA8200	FA157	FA79	VC2027
C8AF12127R ...	CS751	FA8200	FA157	FA79	VC2027
C8AF12127S ...	CS751	FA8200	FA157	FA79	VC2027
C8AF12127T ...	CS751	FA8200	FA157	FA79	VC2027

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C8AF12127Y ...	CS751	FA8200	FA157	FA79	VC970
C8AT12127Y ...	CS751	FA8200	FA157	FA79	VC970
C8AZ12127A ...	CS753	FA8200	FA158	FA6900	VC2025
C8AZ12127AD ...	CS751	FA8200	FA157	FA79	VC970
C8AZ12127B ...	CS753	FA8200	FA158	FA6900	VC2025
C8AZ12127E ...	CS751	FA8200	FA157	FA79	VC2027
C8AZ12127F ...	CS751	FA8200	FA157	FA79	VC2027
C8AZ12127J ...	CS751	FA8200	FA157	FA79	VC970
C8AZ12127M ...	CS751	FA8200	FA157	FA79	—
C8AZ12127N ...	CS751	FA8200	FA157	FA79	VC2027
C8AZ12127R ...	CS751	FA8200	FA157	FA79	VC2027
C8AZ12127S ...	CS751	FA8200	FA157	FA79	VC2027
C8AZ12127T ...	CS751	FA8200	FA157	FA79	VC2027
C8AZ12127Y ...	CS751	FA8200	FA157	FA79	VC970
C8BH12100A ...	CS751	EP30	EP49	EP50	—
C8BH12100C ...	CS751	EP30	EP49	EP50	—
C8BH12100E ...	CS751	EP30	EP49	EP50	—
C8BH12100G ...	CS751	EP30	EP49	EP50	—
C8DF12127A ...	CS753	FA8200	FA158	FA6900	VC2025
C8DF12127B ...	CS753	FA8200	FA158	FA6900	—
C8DF12127C ...	CS753	FA8200	FA158	FA6900	VC2025
C8DF12127D ...	CS753	FA8200	FA158	FA6900	VC2025
C8DF12127G ...	CS753	FA66	FA67	FA6900	VC915
C8DF12127H ...	CS753	FA66	FA67	FA6900	VC915
C8DF12127J ...	CS753	FA8200	FA158	FA6900	—
C8DF12127K ...	CS753	FA8200	FA158	FA6900	—
C8DF12127L ...	CS753	FA8200	FA158	FA6900	—
C8DF12127N ...	CS753	FA8200	FA158	FA6900	—
C8DZ12127A ...	CS753	FA8200	FA158	FA6900	VC2025
C8DZ12127B ...	CS753	FA8200	FA158	FA6900	—
C8DZ12127C ...	CS753	FA8200	FA158	FA6900	—
C8DZ12127D ...	CS753	FA8200	FA158	FA6900	—
C8DZ12127J ...	CS753	FA8200	FA158	FA6900	—
C8OF12127B ...	CS751	FA8200	FA157	FA79	VC2000
C8OF12127C ...	CS751	FA8200	FA157	FA79	VC2027
C8OF12127D ...	CS751	FA8200	FA157	FA79	—
C8OF12127G ...	CS751	FA8200	FA157	FA79	VC970
C8OF12127H ...	CS751	FA8200	FA157	FA79	—
C8OF12127J ...	CS751	FA8200	FA157	FA79	VC970
C8OF12127K ...	CS751	FA8200	FA157	FA79	—
C8OF12127M ...	CS751	FA8200	FA157	FA79	—
C8OF12127N ...	CS751	FA8200	FA157	FA79	—
C8OZ12127B ...	CS751	FA8200	FA157	FA79	VC2000
C8OZ12127C ...	CS751	FA8200	FA157	FA79	VC2027
C8OZ12127D ...	CS751	FA8200	FA157	FA79	—
C8OZ12127G ...	CS751	FA8200	FA157	FA79	VC970
C8OZ12127H ...	CS751	FA8200	FA157	FA79	—
C8OZ12127J ...	CS751	FA8200	FA157	FA79	VC970

(continued on next page)

⁹ Two required

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C8TF12102A ...	CS751	FA8200	FA157	FA79	VC965
C8TF12102B ...	CS751	FA8200	FA157	FA79	VC965
C8TF12127A ...	CS753	FA8200	FA158	FA6900	—
C8TF12127B ...	CS753	FA8200	FA158	FA6900	—
C8TF12127C ...	CS753	FA8200	FA158	FA6900	—
C8TF12127D ...	CS753	FA8200	FA158	FA6900	—
C8TF12127E ...	CS753	FA8200	FA158	FA6900	—
C8TF12127F ...	CS751	FA8200	FA157	FA79	VC2027
C8TF12127G ...	CS751	FA8200	FA157	FA79	VC2000
C8TF12127H ...	CS751	FA8200	FA157	FA79	VC970
C8TF12127K ...	CS751	FA8200	FA157	FA79	—
C8TF12127L ...	CS751	FA8200	FA157	FA79	VC970
C8TF12127M ...	CS751	FA8200	FA157	FA79	VC970
C8TF12127T ...	CS751	FA8200	FA157	FA79	—
C8TF12127U ...	CS753	FA8200	FA158	FA6900	—
C8TF12127V ...	CS753	FA8200	FA158	FA6900	—
C8TZ12127A ...	CS753	FA8200	FA158	FA6900	—
C8TZ12127D ...	CS750	FA8200	FA158	FA6900	—
C8TZ12127F ...	CS751	FA8200	FA157	FA79	VC2027
C8TZ12127G ...	CS751	FA8200	FA157	FA79	VC2000
C8TZ12127H ...	CS751	FA8200	FA157	FA79	VC970
C8TZ12127L ...	CS751	FA8200	FA157	FA79	VC970
C8TZ12127M ...	CS751	FA8200	FA157	FA79	VC965
C8TZ12127N ...	CS751	FA8200	FA157	FA79	VC965
C8TZ12127V ...	CS753	FA8200	FA158	FA6900	—
C8UF12127A ...	CS753	FA8200	FA158	FA6900	—
C8UF12127C ...	CS753	FA8200	FA158	FA6900	—
C8UF12127D ...	CS753	FA8200	FA158	FA6900	—
C8UF12127E ...	CS751	FA8200	FA157	FA79	—
C8UF12127F ...	CS751	FA8200	FA157	FA79	—
C8UF12127G ...	CS751	FA8200	FA157	FA79	VC970
C8UF12127H ...	CS751	FA8200	FA157	FA79	VC970
C8UF12127J ...	CS753	FA66	FA67	FA6900	VC915
C8UF12127K ...	CS753	FA8200	FA158	FA6900	VC2025
C8UF12127M ...	CS753	FA8200	FA158	FA6900	VC2025
C8UF12127T ...	CS751	FA8200	FA157	FA79	—
C8UF12127U ...	CS753	FA76	FA67	FA6900	VC915
C8UZ12127A ...	CS753	FA8200	FA158	FA6900	—
C8UZ12127D ...	CS753	FA8200	FA158	FA6900	—
C8UZ12127F ...	CS751	FA8200	FA157	FA79	—
C8UZ12127G ...	CS751	FA8200	FA157	FA79	VC970
C8UZ12127H ...	CS751	FA8200	FA157	FA79	VC970
C8UZ12127K ...	CS753	FA8200	FA158	FA6900	—
C8UZ12127M ...	CS753	FA8200	FA158	FA6900	—
C8UZ12127T ...	CS751	FA8200	FA157	FA79	—
C8VF12127A ...	CS751	FA8200	FA157	FA79	VC970
C8VF12127C ...	CS751	FA8200	FA157	FA79	VC2027
C8VF12127E ...	CS751	FA8200	FA157	FA79	VC970

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C8VF12127F ...	CS751	FA8200	FA157	FA79	VC970
C8VF12127G ...	CS751	FA8200	FA157	FA79	VC970
C8VF12127H ...	CS751	FA8200	FA157	FA79	—
C8VF12A132A ...	CS751	FA8200	FA157	FA79	VC970
C8VY12127C ...	CS751	FA8200	FA157	FA79	VC970
C8VY12127E ...	CS751	FA8200	FA157	FA79	VC970
C8VY12127G ...	CS751	FA8200	FA157	FA79	VC970
C8WF12127B ...	CS751	FA8200	FA157	FA79	VC2027
C8WF12127C ...	CS751	FA8200	FA157	FA79	VC2000
C8WY12127B ...	CS751	FA8200	FA157	FA79	VC2027
C8ZE12127A ...	CS751	FA8200	FA157	FA79	VC2000
C8ZE12127B ...	CS751	FA8200	FA157	FA79	VC2000
C8ZF12127A ...	CS751	FA8200	FA157	FA79	—
C8ZF12127B ...	CS751	FA8200	FA157	FA79	—
C8ZF12127D ...	CS751	FA8200	FA157	FA79	VC970
C8ZF12127F ...	CS751	FA8200	FA157	FA79	—
C8ZF12127J ...	CS751	FA8200	FA157	FA79	VC970
C8ZF12127K ...	CS751	FA8200	FA157	FA79	VC970
C8ZF12127M ...	CS751	FA8200	FA157	FA79	VC970
C8ZF12127N ...	CS751	FA8200	FA157	FA79	VC970
C8ZZ12127A ...	CS751	FA8200	FA157	FA79	—
C8ZZ12127B ...	CS751	FA8200	FA157	FA79	—
C8ZZ12127D ...	CS751	FA8200	FA157	FA79	VC970
C9AF12127AB ...	CS751	FA8200	FA157	FA79	—
C9AF12127AC ...	CS751	FA8200	FA157	FA79	—
C9AF12127J ...	CS751	FA8200	FA157	FA79	VC970
C9AF12127K ...	CS751	FA8200	FA157	FA79	VC970
C9AF12127M ...	CS751	FA8200	FA157	FA79	VC970
C9AF12127N ...	CS751	FA8200	FA157	FA79	VC970
C9AF12127R ...	CS751	FA8200	FA157	FA79	VC970
C9AF12127U ...	CS750 ⁹	FA8200	FA157	FA79	—
C9AF12127Y ...	CS751	FA8200	FA157	FA79	—
C9AZ12127B ...	CS751	FA8200	FA157	FA79	VC970
C9AZ12127D ...	CS751	FA8200	FA157	FA79	VC970
C9AZ12127F ...	CS751	FA8200	FA157	FA79	VC2027
C9AZ12127M ...	CS751	FA8200	FA157	FA79	VC970
C9AZ12127R ...	CS751	FA8200	FA157	FA79	VC2027
C9AZ12127U ...	CS750 ⁹	FA8200	FA157	FA79	—
C9AZ12127Y ...	CS751	FA8200	FA157	FA79	—
C9BH12100G ...	CS751	EP30	EP49	EP50	—
C9DF12127B ...	CS753	FA8200	FA158	FA6900	VC2025
C9DZ12127B ...	CS753	FA8200	FA158	FA6900	VC2025
C9OF12127M ...	CS751	FA8200	FA157	FA79	VC970
C9OF12127N ...	CS751	FA8200	FA157	FA79	VC970
C9OF12127R ...	CS753	FA8200	FA158	FA6900	—
C9OF12127T ...	CS751	FA8200	FA157	FA79	VC970
C9OF12127U ...	CS753	FA8200	FA158	FA6900	—
C9OF12127V ...	CS753	FA8200	FA158	FA6900	—

(continued on next page)

⁹ Two required

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
C90F12127Z ...	CS751	FA8200	FA157	FA79	VC970
C90Z12127A ...	CS753	FA8200	FA158	FA6900	—
C90Z12127E ...	CS751	FA8200	FA157	FA79	VC970
C90Z12127G ...	CS751	FA8200	FA157	FA79	VC970
C90Z12127T ...	CS751	FA8200	FA157	FA79	VC970
C90Z12127U ...	CS753	FA8200	FA158	FA6900	—
C90Z12127V ...	CS753	FA8200	FA158	FA6900	—
C90Z12127Z ...	CS751	FA8200	FA157	FA79	VC970
C9TZ12127F ...	CS753	FA8200	FA158	FA6900	—
C9UF12127A ...	CS753	FA8200	FA158	FA6900	—
C9UF12127C ...	CS751	FA8200	FA157	FA79	VC970
C9UF12127D ...	CS751	FA8200	FA157	FA79	VC970
C9UF12127E ...	CS751	FA8200	FA157	FA79	VC2000
C9UF12127F ...	CS753	FA8200	FA158	FA6900	VC2025
C9UZ12127A ...	CS753	FA8200	FA158	FA6900	—
C9UZ12127C ...	CS751	FA8200	FA157	FA79	VC970
C9UZ12127D ...	CS751	FA8200	FA157	FA79	VC970
C9UZ12127E ...	CS751	FA8200	FA157	FA79	—
C9UZ12127F ...	CS753	FA8200	FA158	FA6900	VC2025
C9ZF12127AB ...	CS751	FA8200	FA157	FA79	—
C9ZF12127AC ...	CS751	FA8200	FA157	FA79	VC2030
C9ZF12127B ...	CS750 ⁹	FA8200	FA157	FA79	—
C9ZF12127D ...	CS751	FA8200	FA157	FA79	—
C9ZF12127E ...	CS750 ⁹	FA8200	FA157	FA79	—
C9ZF12127F ...	CS751	FA8200	FA157	FA79	—
C9ZF12127J ...	CS751	FA8200	FA157	FA79	—
C9ZF12127K ...	CS751	FA8200	FA157	FA79	—
C9ZF12127M ...	CS751	FA8200	FA157	FA79	—
C9ZF12127N ...	CS751	FA8200	FA157	FA79	—
C9ZF12127R ...	CS751	FA8200	FA157	FA79	—
C9ZZ12127B ...	CS750 ⁹	FA8200	FA157	FA79	—
C9ZZ12127D ...	CS750 ⁹	FA8200	FA157	FA79	—
C9ZZ12127E ...	CS750 ⁹	FA8200	FA157	FA79	—
C30Z12127D ...	CS756	FA76	FA157	FA79	—
C40Z12127B ...	CS751	FA8200	FA157	FA79	VC945
C40Z12127E ...	CS753	FA76	FA67	FA6900	VC915
D0AF12127AC ...	CS751	FA8200	FA157	FA79	VC2000
D0AF12127AE ...	CS751	FA8200	FA157	FA79	—
D0AF12127AF ...	CS751	FA8200	FA157	FA79	—
D0AF12127AG ...	CS751	FA8200	FA157	FA79	—
D0AF12127AH ...	CS751	FA8200	FA157	FA79	—
D0AF12127AI ...	CS751	FA8200	FA157	FA79	—
D0AF12127AJ ...	CS751	FA8200	FA157	FA79	—
D0AF12127AK ...	CS751	FA8200	FA157	FA79	—
D0AF12127AL ...	CS751	FA8200	FA157	FA79	—
D0AF12127H ...	CS751	FA8200	FA157	FA79	—
D0AF12127M ...	CS751	FA8200	FA157	FA79	VC2027
D0AF12127T ...	CS751	FA8200	FA157	FA79	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D0AF12127V ...	CS751	FA8200	FA157	FA79	VC2000
D0AF12127Y ...	CS751	FA8200	FA157	FA79	VC2027
D0AF12127Z ...	CS751	FA8200	FA157	FA79	VC970
D0AH12127A ...	CS751	EP30	EP51	EP50	—
D0AZ12127AE ...	CS751	FA8200	FA157	FA79	—
D0AZ12127H ...	CS751	FA8200	FA157	FA79	—
D0AZ12127M ...	CS751	FA8200	FA157	FA79	VC2027
D0AZ12127T ...	CS751	FA8200	FA157	FA79	—
D0AZ12127V ...	CS751	FA8200	FA157	FA79	VC2000
D0AZ12127Y ...	CS751	FA8200	FA157	FA79	VC2027
D0AZ12127Z ...	CS751	FA8200	FA157	FA79	VC970
D0DF12127C ...	CS753	FA8200	FA158	FA6900	VC2025
D0DF12127E ...	CS751	FA8200	FA158	FA79	—
D0DF12127H ...	CS753	FA8200	FA158	FA6900	—
D0DF12127J ...	CS753	FA8200	FA158	FA6900	—
D0DF12127K ...	CS753	FA8200	FA158	FA6900	—
D0DF12127L ...	CS753	FA8200	FA158	FA6900	—
D0DZ12127B ...	CS751	FA8200	FA157	FA79	—
D0DZ12127C ...	CS753	FA8200	FA158	FA6900	VC2025
D0DZ12127H ...	CS753	FA8200	FA158	FA6900	—
D0DZ12127J ...	CS753	FA8200	FA158	FA6900	—
D0OF12127A ...	CS753	FA8200	FA158	FA6900	VC2025
D0OF12127AA ...	CS750 ⁹	FA8200	FA157	FA79	—
D0OF12127AC ...	CS751	FA8200	FA157	FA79	—
D0OF12127AE ...	CS751	FA8200	FA157	FA79	—
D0OF12127AF ...	CS751	FA8200	FA157	FA79	—
D0OF12127AG ...	CS751	FA8200	FA157	FA79	—
D0OF12127AH ...	CS750 ⁹	FA8200	FA157	FA79	—
D0OF12127AK ...	CS751	FA8200	FA157	FA79	—
D0OF12127AL ...	CS751	FA8200	FA157	FA79	—
D0OF12127E ...	CS751	FA8200	FA157	FA79	—
D0OF12127F ...	CS751	FA8200	FA157	FA79	—
D0OF12127G ...	CS751	FA8200	FA157	FA79	—
D0OF12127J ...	CS750	FA8200	FA157	FA79	—
D0OF12127M ...	CS751	FA8200	FA157	FA79	VC970
D0OF12127N ...	CS751	FA8200	FA157	FA79	VC970
D0OF12127R ...	CS751	FA8200	FA157	FA79	VC970
D0OF12127T ...	CS751	FA8200	FA157	FA79	VC2000
D0OF12127U ...	CS751	FA8200	FA157	FA79	VC970
D0OF12127V ...	CS751	FA8200	FA157	FA79	VC2027
D0OF12127Y ...	CS751	FA8200	FA157	FA79	VC2000
D0OF12127Z ...	CS751	FA8200	FA157	FA79	—
D0ON12127A ...	CS753	FA8200	FA158	FA6900	VC2025
D0ON12127AC ...	CS751	FA8200	FA157	FA79	—
D0ON12127AL ...	CS751	FA8200	FA157	FA79	—
D0ON12127E ...	CS751	FA8200	FA157	FA79	—
D0ON12127F ...	CS753	FA8200	FA158	FA6900	—
D0ON12127G ...	CS751	FA8200	FA157	FA79	—

(continued on next page)

⁹ Two required

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D00N12127J ...	CS753	FA8200	FA157	FA79	—
D00N12127K ...	CS751	FA8200	FA157	FA79	VC2000
D00N12127M ...	CS751	FA8200	FA157	FA79	VC970
D00N12127N ...	CS751	FA8200	FA157	FA79	VC970
D00N12127R ...	CS751	FA8200	FA157	FA79	VC970
D00N12127T ...	CS751	FA8200	FA157	FA79	—
D00N12127U ...	CS751	FA8200	FA157	FA79	VC970
D00N12127V ...	CS751	FA8200	FA157	FA79	VC2027
D00Z12127A ...	CS753	FA8200	FA158	FA6900	—
D00Z12127AC ...	CS751	FA8200	FA157	FA79	—
D00Z12127E ...	CS751	FA8200	FA157	FA79	VC2000
D00Z12127F ...	CS751	FA8200	FA157	FA79	—
D00Z12127G ...	CS751	FA8200	FA157	FA79	—
D00Z12127J ...	CS750 ⁹	FA8200	FA157	FA79	—
D00Z12127K ...	CS751	FA8200	FA157	FA79	VC2000
D00Z12127M ...	CS751	FA8200	FA157	FA79	VC970
D00Z12127N ...	CS751	FA8200	FA157	FA79	VC970
D00Z12127R ...	CS751	FA8200	FA157	FA79	VC970
D00Z12127T ...	CS751	FA8200	FA157	FA79	—
D00Z12127U ...	CS751	FA8200	FA157	FA79	VC970
D00Z12127V ...	CS751	FA8200	FA157	FA79	VC2027
D00Z12127Y ...	CS751	FA8200	FA157	FA79	—
D0RY12127A ...	CS751	EP30	EP51	EP50	—
D0RY12127B ...	CS751	EP30	EP51	EP50	—
D0TF12127F ...	CS751	FA8200	FA157	FA79	—
D0TF12127G ...	CS751	FA8200	FA157	FA79	VC970
D0TF12127H ...	CS751	FA8200	FA157	FA79	—
D0TF12127J ...	CS751	FA8200	FA157	FA79	—
D0TF12127K ...	CS751	FA8200	FA157	FA79	VC970
D0TF12127L ...	CS751	FA8200	FA157	FA79	—
D0TF12127M ...	CS751	FA8200	FA157	FA79	VC2000
D0TZ12127F ...	CS751	FA8200	FA157	FA79	—
D0TZ12127G ...	CS751	FA8200	FA157	FA79	VC970
D0TZ12127H ...	CS751	FA8200	FA157	FA79	—
D0TZ12127J ...	CS751	FA8200	FA157	FA79	—
D0TZ12127K ...	CS751	FA8200	FA157	FA79	VC970
D0TZ12127L ...	CS751	FA8200	FA157	FA79	—
D0TZ12127M ...	CS751	FA8200	FA157	FA79	VC2000
D0VF12127B ...	CS751	FA8200	FA157	FA79	VC970
D0VY12127A ...	CS751	FA8200	FA157	FA79	VC970
D0ZF12127C ...	CS750 ⁹	FA8200	FA157	FA79	—
D0ZF12127F ...	CS750	FA8200	FA157	FA79	VC970
D0ZF12127G ...	CS751	FA8200	FA157	FA79	VC970
D0ZF12127J ...	CS751	FA8200	FA157	FA79	—
D0ZZ12127C ...	CS750 ⁹	FA8200	FA157	FA79	—
D0ZZ12127D ...	CS751	FA8200	FA157	FA79	VC970
D1AF12127CA ...	CS753	FA8200	FA158	FA6900	VC2025
D1AF12127FA ...	CS751	FA8200	FA157	FA79	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D1AF12127GA ...	CS751	FA8200	FA157	FA79	—
D1AF12127GB ...	CS751	FA8200	FA157	FA79	—
D1AF12127HA ...	CS751	FA8200	FA157	FA79	VC2000
D1AF12127HB ...	CS751	FA8200	FA157	FA79	—
D1AF12127KB ...	CS751	FA8200	FA157	FA79	VC2000
D1AF12127KC ...	CS751	FA8200	FA157	FA79	—
D1AF12127LB ...	CS751	FA8200	FA157	FA79	—
D1AF12127LC ...	CS751	FA8200	FA157	FA79	—
D1AF12127NA ...	CS751	FA8200	FA157	FA79	—
D1AF12127NB ...	CS751	FA8200	FA157	FA79	—
D1AF12127SA ...	CS751	FA8200	FA157	FA79	—
D1AF12127SB ...	CS751	FA8200	FA157	FA79	VC2034
D1AF12127TA ...	CS750 ⁹	FA8200	FA157	FA79	VC2000
D1AZ12127C ...	CS753	FA8200	FA158	FA6900	VC2025
D1AZ12127G ...	CS751	FA8200	FA157	FA79	—
D1AZ12127H ...	CS751	FA8200	FA157	FA79	—
D1AZ12127K ...	CS751	FA8200	FA157	FA79	—
D1AZ12127L ...	CS751	FA8200	FA157	FA79	—
D1AZ12127N ...	CS751	FA8200	FA157	FA79	—
D1AZ12127S ...	CS751	FA8200	FA157	FA79	—
D1AZ12127T ...	CS750 ⁹	FA8200	FA157	FA79	VC2000
D1BF12127EA ...	CS751	FA8200	FA157	FA79	—
D1DF12127BA ...	CS753	FA8200	FA158	FA6900	—
D1DF12127BB ...	CS753	FA8200	FA158	FA6900	VC2025
D1DF12127EA ...	CS751	FA8200	FA157	FA79	VC2027
D1DF12127EB ...	CS751	FA8200	FA157	FA79	—
D1DF12127FA ...	CS753	FA8200	FA158	FA6900	VC2025
D1DF12127FB ...	CS753	FA8200	FA158	FA6900	VC2025
D1DF12127GA ...	CS753	FA8200	FA158	FA6900	VC2025
D1DZ12127B ...	CS753	FA8200	FA158	FA6900	VC2025
D1DZ12127E ...	CS751	FA8200	FA157	FA79	—
D1DZ12127F ...	CS753	FA8200	FA158	FA6900	—
D1DZ12127G ...	CS753	FA8200	FA158	FA6900	VC2025
D1FZ12127A ...	CS313P	EP282	EP143	EP274	—
D1FZ12127B ...	CS751	EP30	EP51	EP50	—
D1FZ12127C ...	CS313P	EP282	EP143	EP274	—
D1HF12102AA ...	CS751	FA8200	FA157	FA79	VC965
D1HF12102BA ...	CS751	FA8200	FA157	FA79	VC965
D1HF12127AA ...	CS751	FA8200	FA157	FA79	VC965
D1HZ12127A ...	CS751	FA8200	FA157	FA79	VC965
D1HZ12127B ...	CS751	FA8200	FA157	FA79	VC965
D1MF12127FA ...	CS751	FA8200	FA157	FA79	—
D1MF12127FB ...	CS751	FA8200	FA157	FA79	—
D1MY12127F ...	CS751	FA8200	FA157	FA79	—
D1OF12127AA ...	CS753	FA8200	FA158	FA6900	—
D1OF12127AB ...	CS753	FA8200	FA158	FA6900	—
D1OF12127BA ...	CS753	FA8200	FA158	FA6900	—
D1OF12127BB ...	CS753	FA8200	FA158	FA6900	—

(continued on next page)

⁹ Two required

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control	Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D10F12127CA .	CS753	FA8200	FA158	FA6900	—	D2AF12127EA .	CS751	FA8200	FA157	FA79	—
D10F12127CB .	CS753	FA8200	FA158	FA6900	—	D2AF12127FA .	CS751	FA8200	FA157	FA79	—
D10F12127GA .	CS751	FA8200	FA157	FA79	VC2027	D2AF12127KA .	CS751	FA8200	FA157	FA79	VC2032
D10F12127LA .	CS751	FA8200	FA157	FA79	VC2000	D2AF12127MA .	CS751	FA8200	FA157	FA79	—
D10F12127LB .	CS751	FA8200	FA157	FA79	—	D2AF12127MB .	CS751	FA8200	FA157	FA79	—
D10F12127PA .	CS751	FA8200	FA157	FA79	VC2000	D2AF12127NA .	CS751	FA8200	FA157	FA79	—
D10Z12127A .	CS753	FA8200	FA158	FA6900	—	D2AF12127NC .	CS751	FA8200	FA157	FA79	—
D10Z12127B .	CS753	FA8200	FA158	FA6900	—	D2AF12127PA .	CS751	FA8200	FA157	FA79	—
D10Z12127C .	CS753	FA8200	FA158	FA6900	—	D2AF12127RA .	CS751	FA8200	FA157	FA79	—
D10Z12127G .	CS751	FA8200	FA157	FA79	VC2027	D2AF12127SA .	CS751	FA8200	FA157	FA79	—
D10Z12127L .	CS751	FA8200	FA157	FA79	VC2000	D2AZ12127B .	CS753	FA8200	FA158	FA6900	—
D10Z12127P .	CS751	FA8200	FA157	FA79	VC2000	D2AZ12127C .	CS751	FA8200	FA157	FA79	VC2031
D1RY12127B .	CS313P	EP282	EP143	EP274	—	D2AZ12127D .	CS751	FA8200	FA157	FA79	VC2031
D1RY12127C .	CS313P	EP282	EP143	EP274	—	D2AZ12127E .	CS751	FA8200	FA157	FA79	—
D1RY12127D .	CS751	EP30	EP51	EP50	—	D2AZ12127F .	CS751	FA8200	FA157	FA79	—
D1RY12127E .	CS751	EP30	EP51	EP50	—	D2AZ12127H .	CS751	FA8200	FA157	FA79	VC2034
D1RY12127F .	CS751	EP30	EP51	EP50	—	D2AZ12127J .	CS751	FA8200	FA157	FA79	VC2034
D1TF12127CA .	CS753	FA8200	FA158	FA6900	—	D2AZ12127K .	CS751	FA8200	FA157	FA79	VC2032
D1TF12127DA .	CS751	FA8200	FA157	FA79	—	D2AZ12127M .	CS751	FA8200	FA157	FA79	—
D1TF12127EA .	CS751	FA8200	FA157	FA79	VC970	D2AZ12127N .	CS751	FA8200	FA157	FA79	—
D1TF12127GA .	CS751	FA8200	FA157	FA79	—	D2AZ12127R .	CS751	FA8200	FA157	FA79	—
D1TZ12127C .	CS753	FA8200	FA158	FA6900	—	D2BF12127AA .	CS753	FA8200	FA158	FA6900	—
D1TZ12127D .	CS751	FA8200	FA157	FA79	—	D2BF12127EA .	CS751	FA8200	FA157	FA79	—
D1TZ12127E .	CS751	FA8200	FA157	FA79	VC970	D2BX12127A .	CS753	FA8200	FA158	FA6900	VC2029
D1TZ12127G .	CS751	FA8200	FA157	FA79	—	D2BZ12127A .	CS753	FA8200	FA158	FA6900	—
D1UF12127AA .	CS751	FA8200	FA157	FA79	VC970	D2BZ12127E .	CS751	FA8200	FA157	FA79	—
D1UZ12127A .	CS751	FA8200	FA157	FA79	VC970	D2DF12127AA .	CS753	FA8200	FA158	FA6900	—
D1VF12127AA .	CS751	FA8200	FA157	FA79	VC970	D2DF12127BA .	CS753	FA8200	FA158	FA6900	—
D1VY12127A .	CS751	FA8200	FA157	FA79	VC970	D2DF12127CA .	CS753	FA8200	FA158	FA6900	—
D1ZF12127AA .	CS751	FA8200	FA157	FA79	—	D2DF12127DA .	CS753	FA8200	FA158	FA6900	—
D1ZF12127AB .	CS750 ⁹	FA8200	FA157	FA79	—	D2DF12127EA .	CS753	FA8200	FA158	FA6900	—
D1ZF12127BA .	CS750 ⁹	FA8200	FA157	FA79	—	D2DF12127FA .	CS753	FA8200	FA158	FA6900	—
D1ZF12127DA .	CS750 ⁹	FA8200	FA157	FA79	—	D2DZ12127A .	CS753	FA8200	FA158	FA6900	—
D1ZF12127DB .	CS750 ⁹	FA8200	FA157	FA79	—	D2DZ12127B .	CS753	FA8200	FA158	FA6900	—
D1ZF12127EA .	CS750 ⁹	FA8200	FA157	FA79	—	D2DZ12127C .	CS753	FA8200	FA158	FA6900	—
D1ZF12127EB .	CS750 ⁹	FA8200	FA157	FA79	—	D2DZ12127D .	CS753	FA8200	FA158	FA6900	—
D1ZF12127FA .	CS751	FA8200	FA157	FA79	VC970	D2DZ12127E .	CS753	FA8200	FA158	FA6900	—
D1ZF12127GA .	CS751	FA8200	FA157	FA79	—	D2DZ12127F .	CS753	FA8200	FA158	FA6900	—
D1ZF12127GB .	CS751	FA8200	FA157	FA79	—	D2FZ12127A .	CS751	EP30	EP51	EP50	—
D1ZZ12127A .	CS750 ⁹	FA8200	FA157	FA79	—	D2FZ12127B .	CS751	EP30	EP51	EP50	—
D1ZZ12127B .	CS750 ⁹	FA8200	FA157	FA79	—	D2FZ12127C .	CS313P	EP282	EP143	EP274	—
D1ZZ12127D .	CS750 ⁹	FA8200	FA157	FA79	—	D2FZ12127D .	CS313P	EP282	EP143	EP274	—
D1ZZ12127E .	CS750 ⁹	FA8200	FA157	FA79	—	D2FZ12127E .	CS313P	EP282	EP143	EP274	—
D1ZZ12127F .	CS751	FA8200	FA157	FA79	VC970	D2FZ12127F .	CS751	EP30	EP51	EP50	—
D1ZZ12127G .	CS751	FA8200	FA157	FA79	—	D2FZ12127G .	CS751	EP30	EP51	EP50	—
D2AF12127BA .	CS753	FA8200	FA158	FA6900	—	D2HF12102AA .	CS751	FA8200	FA157	FA79	VC965
D2AF12127CA .	CS751	FA8200	FA157	FA79	VC2031	D2MF12127EA .	CS751	FA8200	FA157	FA79	VC2034
D2AF12127DA .	CS751	FA8200	FA157	FA79	VC2031	D2MF12127FA .	CS751	FA8200	FA157	FA79	VC2034

(continued on next column)

(continued on next page)

⁹ Two required

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D2MF12127GA .	CS751	FA8200	FA157	FA79	—
D2MY12127B .	CS751	FA8200	FA157	FA79	—
D2MY12127G .	CS751	FA8200	FA157	FA79	—
D2OF12127AA .	CS751	FA8200	FA157	FA79	—
D2OF12127DA .	CS753	FA8200	FA158	FA6900	—
D2OF12127EA .	CS753	FA8200	FA158	FA6900	—
D2OF12127HA .	CS751	FA8200	FA157	FA79	VC2031
D2OF12127JA .	CS751	FA8200	FA157	FA79	VC2031
D2OF12127PA .	CS753	FA8200	FA158	FA6900	—
D2OF12127RA .	CS751	FA8200	FA157	FA79	—
D2OZ12127A .	CS751	FA8200	FA157	FA79	—
D2OZ12127D .	CS753	FA8200	FA158	FA6900	—
D2OZ12127E .	CS753	FA8200	FA158	FA6900	—
D2OZ12127H .	CS751	FA8200	FA157	FA79	VC2031
D2OZ12127J .	CS751	FA8200	FA157	FA79	VC2031
D2OZ12127P .	CS753	FA8200	FA158	FA6900	—
D2OZ12127R .	CS751	FA8200	FA157	FA79	VC2031
D2PE12127BA .	CS753	FA8200	FA158	FA6900	—
D2PE12127CA .	CS751	—	FA157	FA79	—
D2PE12127DA .	CS751	FA8200	FA157	FA79	—
D2PE12127FA .	CS751	FA8200	FA157	FA79	—
D2PE12127HA .	CS751	FA8200	FA157	FA79	—
D2PE12127JA .	CS751	FA8200	FA157	FA79	—
D2PE12127KA .	CS751	FA8200	FA157	FA79	—
D2RY12127B .	CS313P	EP282	EP143	EP274	—
D2RY12127C .	CS313P	EP282	EP143	EP274	—
D2RY12127D .	CS313P	EP434	EP407	EP406	—
D2RY12127E .	CS313P	EP434	EP407	EP406	—
D2RY12127F .	CS751	EP30	EP51	EP50	—
D2RY12127G .	CS751	EP30	EP51	EP50	—
D2RY12127H .	CS751	EP30	EP51	EP50	—
D2RY12127J .	CS313P	EP434	EP407	EP406	—
D2RY12127K .	CS313P	EP434	EP407	EP406	—
D2SF12127EA .	CS751	FA8200	FA157	FA79	—
D2SZ12127E .	CS751	FA8200	FA157	FA79	—
D2TF12102FA .	CS751	FA8200	FA157	FA79	—
D2TF12102FB .	CS751	FA8200	FA157	FA79	—
D2TF12127A .	CS751	FA8200	FA157	FA79	—
D2TF12127AA .	CS751	FA8200	FA157	FA79	—
D2TF12127BA .	CS753	FA8200	FA158	FA6900	—
D2TF12127CA .	CS753	FA8200	FA158	FA6900	—
D2TF12127DA .	CS751	FA8200	FA157	FA79	—
D2TF12127EA .	CS753	FA8200	FA158	FA6900	—
D2TF12127FA .	CS751	FA8200	FA157	FA79	—
D2TF12127FB .	CS751	FA8200	FA157	FA79	—
D2TF12127GH .	CS751	FA8200	FA157	FA79	—
D2TF12127JA .	CS751	FA8200	FA157	FA79	—
D2TF12127KA .	CS751	FA8200	FA157	FA79	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D2TF12127LA .	CS751	FA8200	FA157	FA79	—
D2TF12127LB .	CS751	FA8200	FA157	FA79	—
D2TF12127MA .	CS751	FA8200	FA157	FA79	—
D2TF12127PA .	CS751	FA8200	FA157	FA79	—
D2TF12127RA .	CS751	FA8200	FA157	FA79	—
D2TF12127SA .	CS751	FA8200	FA157	FA79	—
D2TF12127TA .	CS751	FA8200	FA157	FA79	—
D2TF12127VA .	CS751	FA8200	FA157	FA79	—
D2TF12127XA .	CS751	FA8200	FA157	FA79	—
D2TF12127YA .	CS751	FA8200	FA157	FA79	—
D2TZ12127A .	CS751	FA8200	FA157	FA79	—
D2TZ12127AA .	CS751	FA8200	FA157	FA79	—
D2TZ12127E .	CS751	FA8200	FA157	FA79	—
D2TZ12127F .	CS751	FA8200	FA157	FA79	—
D2TZ12127J .	CS751	FA8200	FA157	FA79	—
D2TZ12127K .	CS751	FA8200	FA157	FA79	—
D2TZ12127L .	CS751	FA8200	FA157	FA79	—
D2TZ12127M .	CS751	FA8200	FA157	FA79	—
D2TZ12127X .	CS751	FA8200	FA157	FA79	—
D2UF12127AA .	CS753	FA8200	FA158	FA6900	—
D2UF12127CA .	CS753	FA8200	FA158	FA6900	—
D2UF12127DA .	CS753	FA8200	FA158	FA6900	—
D2UF12127EA .	CS751	FA8200	FA157	FA79	—
D2UF12127FA .	CS751	FA8200	FA157	FA79	—
D2UF12127GA .	CS751	FA8200	FA157	FA79	—
D2UF12127HA .	CS751	FA8200	FA157	FA79	—
D2UF12127JA .	CS753	FA8200	FA158	FA6900	—
D2UF12127KA .	CS751	FA8200	FA157	FA79	—
D2UF12127LA .	CS751	FA8200	FA157	FA79	—
D2UF12127MA .	CS751	FA8200	FA157	FA79	—
D2UF12127NA .	CS751	FA8200	FA157	FA79	—
D2UF12127PA .	CS751	FA8200	FA157	FA79	—
D2UZ12127A .	CS753	FA8200	FA158	FA6900	—
D2UZ12127C .	CS753	FA8200	FA158	FA6900	—
D2UZ12127D .	CS753	FA8200	FA158	FA6900	—
D2UZ12127E .	CS751	FA8200	FA157	FA79	VC2034
D2UZ12127EH .	CS751	FA8200	FA157	FA79	—
D2UZ12127F .	CS751	FA8200	FA157	FA79	—
D2UZ12127G .	CS751	FA8200	FA157	FA79	—
D2UZ12127H .	CS751	FA8200	FA157	FA79	—
D2UZ12127J .	CS753	FA8200	FA158	FA6900	—
D2UZ12127K .	CS753	FA8200	FA157	FA79	—
D2UZ12127L .	CS753	FA8200	FA157	FA79	—
D2UZ12127M .	CS753	FA8200	FA157	FA79	—
D2UZ12127N .	CS753	FA8200	FA157	FA79	—
D2UZ12127O .	CS753	FA8200	FA157	FA79	—
D2UZ12127P .	CS753	FA8200	FA157	FA79	—
D2VF12127AA .	CS751	FA8200	FA157	FA79	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D2VF12127BA .	CS751	FA8200	FA157	FA79	—
D2VY12127A . . .	CS751	FA8200	FA157	FA79	—
D2VY12127B . . .	CS751	FA8200	FA157	FA79	—
D2WF12127AA .	CS751	FA8200	FA157	FA79	—
D2WY12127A . .	CS751	FA8200	FA157	FA79	—
D2ZF12127AA .	CS751	FA8200	FA157	FA79	—
D2ZF12127CA .	CS751	FA8200	FA157	FA79	—
D2ZF12127EA . .	CS750 ⁹	FA8200	FA157	FA79	—
D2ZF12127FA . .	CS751	FA8200	FA157	FA79	—
D2ZF12127GA .	CS751	FA8200	FA157	FA79	—
D2ZF12127GB .	CS751	FA8200	FA157	FA79	—
D2ZF12127GC .	CS751	FA8200	FA157	FA79	—
D2ZF12127GE .	CS751	FA8200	FA157	FA79	—
D2ZF12127HA .	CS751	FA8200	FA157	FA79	—
D2ZF12127HB .	CS751	FA8200	FA157	FA79	—
D2ZF12127JA . .	CS750 ⁹	FA8200	FA157	FA79	—
D2ZF12127LA . .	CS751	FA8200	FA157	FA79	—
D2ZZ12127A . . .	CS751	FA8200	FA157	FA79	—
D2ZZ12127C . . .	CS751	FA8200	FA157	FA79	—
D2ZZ12127E . . .	CS750 ⁹	FA8200	FA157	FA79	—
D2ZZ12127F . . .	CS751	FA8200	FA157	FA79	—
D2ZZ12127G . . .	CS751	FA8200	FA157	FA79	—
D2ZZ12127H . . .	CS751	FA8200	FA157	FA79	—
D2ZZ12127J . . .	CS750 ⁹	FA8200	FA157	FA79	—
D3AF12127AA .	CS751	FA8200	FA157	FA79	—
D3AF12127BA .	CS751	FA8200	FA157	FA79	—
D3AF12127DA .	CS751	FA8200	FA157	FA79	—
D3AF12127GA .	CS751	FA8200	FA157	FA79	—
D3AZ12127A . . .	CS751	FA8200	FA157	FA79	—
D3AZ12127B . . .	CS751	FA8200	FA157	FA79	—
D3AZ12127C . . .	CS751	FA8200	FA157	FA79	—
D3AZ12127G . .	CS751	FA8200	FA157	FA79	—
D3BF12127BA .	CS751	FA8200	FA157	FA79	VC2029
D3BF12127CA .	CS753	FA8200	FA158	FA6900	VC2029
D3BF12127DA .	CS751	FA8200	FA157	FA79	—
D3BZ12127B . . .	CS751	FA8200	FA157	FA79	VC2029
D3BZ12127C . . .	CS753	FA8200	FA158	FA6900	—
D3BZ12127D . . .	CS751	FA8200	FA157	FA79	—
D3DF12127AA .	CS753	FA8200	FA158	FA6900	VC2029
D3DF12127BA .	CS753	FA8200	FA158	FA6900	—
D3DF12127FA .	CS753	FA8200	FA158	FA6900	—
D3DF12127HA .	CS753	FA8200	FA158	FA6900	—
D3DF12127KA .	CS753	FA8200	FA158	FA6900	VC2029
D3DZ12127A . . .	CS753	FA8200	FA158	FA6900	VC2029
D3DZ12127B . . .	CS753	FA8200	FA158	FA6900	—
D3FZ12127A . . .	CS313P	EP282	EP143	EP274	—
D3FZ12127B . . .	CS313P	EP282	EP143	EP274	—
D3FZ12127C . . .	CS313P	EP282	EP143	EP274	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D3HF12102BA .	CS751	FA8200	FA157	FA102 ²⁸	—
D3HF12102BA .	CS751	FA8200	FA157	FA79 ²⁵	—
D3HF12102DA .	CS751	FA8200	FA157	FA102 ²⁸	—
D3HF12102DA .	CS751	FA8200	FA157	FA79 ²⁵	—
D3HF12127AA .	CS751	FA8200	FA157	FA79	—
D3HF12127BA .	CS751	FA8200	FA157	FA79	—
D3HF12127DA .	CS751	FA8200	FA157	FA79	—
D3HF12127EA .	CS751	FA8200	FA157	FA102 ²⁸	—
D3HF12127EA .	CS751	FA8200	FA157	FA79 ²⁵	—
D3HZ12127A . . .	CS751	FA8200	FA157	FA79	—
D3HZ12127BA .	CS751	FA8200	FA157	FA79	—
D3HZ12127D . . .	CS751	FA8200	FA157	FA79	—
D3HZ12127DA .	CS751	FA8200	FA157	FA79	—
D3HZ12127E . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3HZ12127E . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3JF12127BA . .	CS753	FA8200	FA158	—	—
D3JF12127CA . .	CS753	FA8200	FA158	—	—
D3MF12127AA .	CS751	FA8200	FA157	FA79	—
D3MF12127BA .	CS751	FA8200	FA157	FA79	—
D3MF12127CA .	CS751	FA8200	FA157	FA79	VC2030
D3MF12127DA .	CS751	FA8200	FA157	FA79	VC2030
D3MF12127GA .	CS751	FA8200	FA157	FA79	—
D3MY12127B . .	CS751	FA8200	FA157	FA79	—
D3MY12127C . .	CS751	FA8200	FA157	FA79	—
D3MY12127D . .	CS751	FA8200	FA157	FA79	—
D3MY12127G . .	CS751	FA8200	FA157	FA79	VC2030
D3OF12127AA .	CS753	FA8200	FA158	FA6900	VC2030
D3OF12127BA .	CS753	FA8200	FA158	FA6900	VC2030
D3OF12127DA .	CS751	FA8200	FA157	FA79	—
D3OF12127FA .	CS750 ⁹	FA8200	FA157	FA79	—
D3OF12127GA .	CS751	FA8200	FA157	FA79	—
D3OF12127HB .	CS751	FA8200	FA157	FA79	—
D3OF12127JA .	CS751	FA8200	FA157	FA79	—
D3OF12127KA .	CS751	FA8200	FA157	FA79	—
D3OF12127LA .	CS753	FA8200	FA158	FA6900	VC2030
D3OF12127MA .	CS751	FA8200	FA157	FA79	—
D3OF12127RA .	CS753	FA8200	FA158	FA6900	VC2030
D3OF12127VA .	CS751	FA8200	FA157	FA79	—
D3OF12127XA .	CS751	FA8200	FA157	FA79	—
D3OF12127YA .	CS751	FA8200	FA157	FA79	—
D3OZ12127A . .	CS753	FA8200	FA158	FA6900	VC2030
D3OZ12127B . .	CS753	FA8200	FA158	FA6900	VC2030
D3OZ12127D . .	CS751	FA8200	FA157	FA79	—
D3OZ12127F . . .	CS750 ⁹	FA8200	FA157	FA79	—
D3OZ12127G . .	CS751	FA8200	FA157	FA79	—
D3OZ12127H . .	CS751	FA8200	FA157	FA79	—
D3OZ12127I . . .	CS751	FA8200	FA157	FA79	—
D3OZ12127J . .	CS751	FA8200	FA157	FA79	—

(continued on next page)

⁹ Two required ²⁵ For 1973-76 ²⁸ For 1977

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D3OZ12127K . . .	CS751	FA8200	FA157	FA79	—
D3OZ12127L . . .	CS753	FA8200	FA158	FA6900	VC2030
D3OZ12127M . . .	CS751	FA8200	FA157	FA79	—
D3OZ12127R . . .	CS753	FA8200	FA158	FA6900	VC2030
D3OZ12127V . . .	CS751	FA8200	FA157	FA79	—
D3OZ12127X . . .	CS751	FA8200	FA157	FA79	—
D3PE12127CA . . .	CS753	FA8200	FA158	FA6900	—
D3PE12127DA . . .	CS753	FA8200	FA158	FA6900	—
D3PE12127EA . . .	CS753	FA8200	FA158	FA6900	—
D3PE12127GA . . .	CS753	FA8200	FA158	FA6900	VC2029
D3PE12127HA . . .	CS753	FA8200	FA158	FA6900	—
D3PE12127KA . . .	CS751	FA8200	FA157	FA79	—
D3PE12127MA . . .	CS751	FA8200	FA157	FA79	—
D3PE12127PA . . .	CS751	FA8200	FA157	FA79	—
D3PE12127SA . . .	CS751	FA8200	FA157	FA79	—
D3PE12127TA . . .	CS751	FA8200	FA157	FA79	—
D3PE12127YA . . .	CS751	FA8200	FA157	FA79	VC2032
D3PF12127GA . . .	CS753	FA8200	FA158	FA6900	VC2029
D3PF12127MA . . .	CS751	FA8200	FA157	FA79	—
D3PF12127PA . . .	CS750	FA8200	FA157	FA79	VC2031
D3PZ12127D . . .	CS753	FA8200	FA158	FA6900	—
D3PZ12127G . . .	CS753	FA8200	FA158	FA6900	VC2029
D3PZ12127H . . .	CS753	FA8200	FA158	FA6900	—
D3PZ12127K . . .	CS751	FA8200	FA157	FA79	—
D3PZ12127M . . .	CS751	FA8200	FA157	FA79	—
D3PZ12127P . . .	CS751	FA8200	FA157	FA79	—
D3PZ12127S . . .	CS751	FA8200	FA157	FA79	—
D3RY12127A . . .	CS313P	EP282	EP143	EP274	—
D3RY12127B . . .	CS313P	EP282	EP143	EP274	—
D3SF12127AA . . .	CS751	FA8200	FA157	FA79	—
D3SF12127BA . . .	CS751	FA8200	FA157	FA79	—
D3SZ12127A . . .	CS751	FA8200	FA157	FA79	—
D3TF12102AA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TF12102AA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TF12102BA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TF12102BA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TF12102CA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TF12102CA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TF12102FA . . .	CS751	FA8200	FA157	FA102 ²⁵	—
D3TF12102FA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TF12102GA . . .	CS751	FA8200	FA157	FA102 ²⁵	—
D3TF12102GA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TF12127AA . . .	CS751	FA8200	FA157	FA79	—
D3TF12127BA . . .	CS751	FA8200	FA157	FA79	—
D3TF12127CA . . .	CS751	FA8200	FA157	FA79	—
D3TF12127EA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TF12127EA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TF12127FA . . .	CS751	FA8200	FA157	FA79	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D3TF12127GA . . .	CS753	FA8200	FA158	FA6900	—
D3TF12127HA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TF12127HA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TF12127MA . . .	CS753	FA8200	FA158	FA6900	—
D3TF12127PA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TF12127PA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TF12127SA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TF12127SA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TF12127UA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TF12127UA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TF12127VA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TF12127VA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TF12127XA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TF12127XA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TF12127YA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TF12127YA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TZ12127A . . .	CS753	FA8200	FA158	FA6900	—
D3TZ12127AA . . .	CS751	FA8000	FA157	FA79 ²⁵	—
D3TZ12127AA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TZ12127B . . .	CS751	FA8200	FA157	FA79	—
D3TZ12127BA . . .	CS751	FA8000	FA157	FA79 ²⁵	—
D3TZ12127BA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TZ12127CA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TZ12127CA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TZ12127E . . .	CS751	FA8200	FA157	FA79	—
D3TZ12127F . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TZ12127F . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TZ12127FA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TZ12127FA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TZ12127GA . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TZ12127GA . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TZ12127H . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TZ12127H . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TZ12127M . . .	CS753	FA8200	FA158	FA6900	—
D3TZ12127S . . .	CS751	FA8200	FA157	FA79	—
D3TZ12127U . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TZ12127U . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TZ12127V . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TZ12127V . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TZ12127X . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TZ12127X . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3TZ12127Y . . .	CS751	FA8200	FA157	FA102 ²⁸	—
D3TZ12127Y . . .	CS751	FA8200	FA157	FA79 ²⁵	—
D3UF12127AA . . .	CS753	FA8200	FA158	FA6900	—
D3UF12127BA . . .	CS753	FA8200	FA158	FA6900	—
D3UF12127DA . . .	CS751	FA8200	FA157	FA79	—
D3UF12127EA . . .	CS751	FA8200	FA157	FA79	—
D3UF12127FA . . .	CS751	FA8200	FA157	FA79	—

(continued on next page)

²⁵ For 1973-76 ²⁸ For 1977

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D3UF12127GA .	CS751	FA8200	FA157	FA79	—
D3UF12127HA .	CS751	FA8200	FA157	FA79	—
D3UF12127JA .	CS751	FA8200	FA157	FA79	—
D3UF12127KA .	CS751	FA8200	FA157	FA79	—
D3UF12127LA .	CS753	FA8200	FA158	FA6900	—
D3UF12127MA .	CS753	FA8200	FA158	FA6900	—
D3UF12127PA .	CS753	FA8200	FA158	FA6900	—
D3UF12127RA .	CS753	FA8200	FA158	FA6900	—
D3UZ12127A .	CS753	FA8200	FA158	FA6900	—
D3UZ12127B .	CS753	FA8200	FA158	FA6900	—
D3UZ12127E .	CS751	FA8200	FA157	FA79	—
D3UZ12127F .	CS751	FA8200	FA157	FA79	—
D3UZ12127G .	CS751	FA8200	FA157	FA79	—
D3UZ12127H .	CS751	FA8200	FA157	FA79	—
D3UZ12127I .	CS751	FA8200	FA157	FA79	—
D3UZ12127J .	CS751	FA8200	FA157	FA79	—
D3UZ12127K .	CS751	FA8200	FA157	FA79	—
D3UZ12127L .	CS753	FA8200	FA158	FA6900	—
D3UZ12127M .	CS753	FA8200	FA158	FA6900	—
D3UZ12127P .	CS753	FA8200	FA158	FA6900	—
D3UZ12127R .	CS753	FA8200	FA158	FA6900	—
D3VF12127AA .	CS751	FA8200	FA157	FA79	—
D3VF12127BA .	CS751	FA8200	FA157	FA79	—
D3VF12127CA .	CS751	FA8200	FA157	FA79	—
D3VY12127A .	CS751	FA8200	FA157	FA79	—
D3VY12127B .	CS751	FA8200	FA157	FA79	—
D3ZF12127AA .	CS751	FA8200	FA157	FA79	—
D3ZF12127BA .	CS751	FA8200	FA157	FA79	—
D3ZF12127CA .	CS751	FA8200	FA157	FA79	—
D3ZF12127GA .	CS751	FA8200	FA157	FA79	—
D3ZZ12127A .	CS751	FA8200	FA157	FA79	—
D3ZZ12127B .	CS751	FA8200	FA157	FA79	—
D3ZZ12127G .	CS751	FA8200	FA157	FA79	—
D4DE12127NA .	CS753	FA8200	FA158	FA6900	—
D4DZ12127A .	CS753	FA8200	FA158	FA6900	—
D4DZ12127H .	CS753	FA8200	FA158	FA6900	—
D4DZ12127K .	CS753	FA8200	FA158	FA6900	—
D4DZ12127N .	CS758	FA99	FA108	FA135	VC2030
D4FZ12127A .	CS313P	EP408	EP143	EP274	—
D4FZ12127B .	CS313P	EP408	EP143	EP274	—
D4FZ12127C .	CS313P	EP408	EP143	EP274	—
D4FZ12127D .	CS758	FA99	FA108	FA107	—
D4HE12102AA .	CS751	FA8200	FA157	FA102 ²⁸	—
D4HE12102AA .	CS751	FA8200	FA157	FA79 ²⁵	—
D4HE12127AA .	CS751	FA8200	FA157	FA79	—
D4HE12127JA .	CS751	FA8200	FA157	FA102 ²⁸	—
D4HE12127JA .	CS751	FA8200	FA157	FA79 ²⁵	—
D4HZ12127AA .	CS751	FA8200	FA157	FA102 ²⁸	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D4HZ12127AA .	CS751	FA8200	FA157	FA79 ²⁵	—
D4HZ12127J .	CS751	FA8200	FA157	FA102 ²⁸	—
D4HZ12127J .	CS751	FA8200	FA157	FA79 ²⁵	—
D4RY12127G .	CS313P	EP282	EP143	EP274	—
D4RY12127J .	CS313P	EP435	EP407	EP406	—
D4RY12127K .	CS313P	EP435	EP407	EP406	—
D4RY12127L .	CS313P	EP282	EP143	EP274	—
D4RY12127T .	CS313P	EP435	—	EP406	—
D4TE12102AA .	CS751	FA8200	FA157	FA102 ²⁸	—
D4TE12102AA .	CS751	FA8200	FA157	FA79 ²⁵	—
D4TE12102BA .	CS751	FA8200	FA157	FA102 ²⁸	—
D4TE12102BA .	CS751	FA8200	FA157	FA79 ²⁵	—
D4TE12102CA .	CS751	FA8200	FA157	FA102 ²⁸	—
D4TE12102CA .	CS751	FA8200	FA157	FA79 ²⁵	—
D4TE12127AA .	CS751	FA8200	FA157	FA79	—
D4TE12127BA .	CS751	FA8200	FA157	FA102	—
D4TE12127CA .	CS751	FA8200	FA157	FA102	—
D4TE12127UA .	CS751	FA8200	FA157	FA102 ²⁸	—
D4TE12127UA .	CS751	FA8200	FA157	FA79 ²⁵	—
D4TE12127ZA .	CS751	FA8200	FA157	FA79	—
D4TZ12127AA .	CS751	FA8200	FA157	FA102 ²⁸	—
D4TZ12127AA .	CS751	FA8200	FA157	FA79 ²⁵	—
D4TZ12127BA .	CS751	FA8200	FA157	FA102 ²⁸	—
D4TZ12127BA .	CS751	FA8200	FA157	FA79 ²⁵	—
D4TZ12127CA .	CS751	FA8200	FA157	FA102 ²⁸	—
D4TZ12127CA .	CS751	FA8200	FA157	FA79 ²⁵	—
D4TZ12127U .	CS751	FA8200	FA157	FA102 ²⁸	—
D4TZ12127U .	CS751	FA8200	FA157	FA79 ²⁵	—
D4ZE12127AA .	CS758	FA99	FA108	FA107	—
D4ZE12127BA .	CS758	FA99	FA108	FA107	—
D4ZE12127DA .	CS758	FA99	FA108	FA135	—
D4ZE12127KA .	CS758	FA99	FA108	FA107	—
D4ZF12127AA .	CS758	FA99	FA108	FA107	—
D4ZF12127DA .	CS758	FA99	FA108	FA107	—
D4ZZ12127A .	CS758	FA99	FA108	FA107	—
D4ZZ12127D .	CS758	FA99	FA108	FA107	—
D4ZZ12127K .	CS758	FA99	FA108	FA107	—
D4ZZ12127L .	CS313P	EP434	EP407	EP406	—
D4ZZ12127M .	CS313P	EP434	EP407	EP406	—
D4ZZ12127S .	CS313P	EP434	EP407	EP406	—
D5HE12127CA .	CS751	FA8200	FA157	FA102 ²⁸	—
D5HE12127CA .	CS751	FA8200	FA157	FA79 ²⁵	—
D5HZ12127C .	CS751	FA8200	FA157	FA102 ²⁸	—
D5HZ12127C .	CS751	FA8200	FA157	FA79 ²⁵	—
D5TE12102CA .	CS751	FA8200	FA157	FA102 ²⁸	—
D5TE12102CA .	CS751	FA8200	FA157	FA79 ²⁵	—
D5TE12102D .	CS751	FA8200	FA157	FA79	—
D5TE12102DA .	CS751	FA8200	FA157	FA102 ²⁸	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D5TE12102DA .	CS751	FA8200	FA157	FA79 ²⁵	—
D5TE12127ADA	CS751	FA8200	FA157	FA102 ²⁸	—
D5TE12127ADA	CS751	FA8200	FA157	FA79 ²⁵	—
D5TE12127CA .	CS751	FA8200	FA157	FA79	—
D5TE12127VA .	CS758	FA99	FA158	FA104	VC2042
D5TZ12127CA .	CS751	FA8200	FA157	FA102 ²⁸	—
D5TZ12127CA .	CS751	FA8200	FA157	FA78 ²⁵	—
D5TZ12127EA .	CS751	FA8200	FA157	FA102 ²⁸	—
D5TZ12127EA .	CS751	FA8200	FA157	FA78 ²⁵	—
D5TZ12127H .	CS758	FA99	FA158	FA104	VC2042
D5TZ12127KA .	CS751	FA8200	FA157	FA102 ²⁸	—
D5TZ12127KA .	CS751	FA8200	FA157	FA78 ²⁵	—
D7JL12100D .	CS751	FA8200	FA144	FA134	—
D7TE12127ZA .	CS751	FA8200	FA157	FA102	—
D7TZ12127Z .	CS751	FA8200	FA157	FA102	—
D8TE12127ANA	CS751	FA8200	FA157	FA102	—
D8TE12127GA .	CS751	FA8200	FA157	FA102	—
D8TE12127KA .	CS751	FA8200	FA157	FA102	—
D8TE12127LA .	CS751	FA8200	FA157	FA102	—
D8TZ12127AA .	CS751	FA8200	FA157	FA102	—
D8TZ12127G .	CS751	FA8200	FA157	FA102	—
D8TZ12127K .	CS751	FA8200	FA157	FA102	—
D8TZ12127L .	CS751	FA8200	FA157	FA102	—
D9JE12127AA .	CS758	FA99	FA155	FA135	—
D10Z12127A .	CS753	FA8200	FA158	FA6900	—
D20Z12127R .	CS751	FA8200	FA157	FA79	—
D27Z12127A .	CS363 ⁹	—	EP321	EP706	—
D27Z12127B .	CS351	EP300	EP342	EP706	—
D27Z12127C .	CS351	EP300	EP342	EP706	—
D27Z12127G .	CS751	FA8200	FA157	FA6900	—
D42E12127AA .	CS758	FA99	FA108	FA107	—
D47Z12127A .	CS359	EP351	EP342	EP706	—
D47Z12127B .	CS359	EP351	EP342	EP706	—
D47Z12127C .	CS359	EP351	EP342	EP706	—
D67Z12127A .	CS359	EP366	EP342	EP706	—
D67Z12127B .	CS359	EP366	EP342	EP706	—
D67Z12127C .	CS359	EP366	EP342	EP706	—
D67Z12127D .	CS359	EP366	EP342	EP706	—
D67Z12127E .	CS359	EP391	EP342	EP706	—
D67Z12127F .	CS359	EP391	EP342	EP706	—
D67Z12127G .	CS359	EP391	EP342	EP706	—
D67Z12127H .	CS359	EP391	EP342	EP706	—
D77Z12127A .	—	—	EP342	EP706	—
D77Z12127B .	—	—	EP342	EP706	—
D77Z12127C .	CS359	EP391	EP342	EP706	—
D77Z12127D .	—	—	EP342	EP706	—
D77Z12127E .	CS359	EP391	EP342	EP706	—
D87Z12127A .	—	—	EP342	EP706	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D87Z12127B .	CS359	EP391	—	EP706	—
D87Z12127C .	—	—	—	EP706	—
D97Z12127A .	—	—	EP342	EP706	—
D97Z12127B .	CS359	EP366	EP342	EP706	—
D97Z12127C .	—	—	EP342	EP706	—
D97Z12127D .	—	—	EP342	EP706	—
D97Z12127E .	—	—	EP658	EP660	—
D97Z12127F .	—	—	EP658	EP660	—
E4JE12127AA .	CS758	FA99	FA159	FA136	—
E07Z12127A .	—	—	EP342	EP706	—
E17Z12127B .	—	—	EP342	EP706	—
FAA12127A .	CS753	FA66	FA67	FA6900	VC915
FAA12127C .	CS753	FA66	FA67	FA6900	VC915
FAB12127A .	CS750	FA76	FA67	FA78	—
FAC12127D .	CS753	FA66	FA67	FA352	—
FAD12127A .	CS750	FA76	FA67	FA78	—
FAD12127B .	CS750	FA76	FA67	FA78	—
FAD12127C .	CS750	FA76	FA67	FA78	—
FAE12127A .	CS750	FA76	FA67	FA78	—
FAE12127C .	CS750	FA76	FA67	FA78	—
FAF12127A .	CS750	FA66	FA67	FA78	VC915
FAF12127B .	CS750	FA76	FA67	FA78	—
FDB12127A .	CS750	FA76	FA67	FA78	—
FDC12127A .	CS750	FA76	FA67	FA78	—
FDD12127A .	CS750	FA76	FA67	FA78	—
FDD12127S .	CS751	FA8200	FA157	FA79	—
FDE12127A .	CS750	FA76	FA67	FA78	—
FDE12127B .	CS750	FA76	FA67	FA78	—
FDH12127A .	CS753	FA66	FA67	FA6900	VC915
FDJ12127C .	CS750	FA76	FA67	FA78	—
FDK12127C .	CS750	FA76	FA67	FA78	—
FDL12127B .	CS750	FA76	FA67	FA78	—
FDM12127B .	CS750	FA76	FA67	FA78	—
FDN12127A .	CS753	FA66	FA67	FA352	—
FDR12127A .	CS753	FA66	FA67	FA6900	VC915
FDS12127A .	CS750	FA76	FA67	FA78	—
FDS12127B .	CS750	FA76	FA67	FA78	—
FDT12127B .	CS750	FA76	FA67	FA78	—
FDU12127B .	CS750	FA76	FA67	FA78	—
FDV12127B .	CS750	FA76	FA67	FA78	—
FDV12127C .	CS750	FA76	FA67	FA78	—
FDV12127D .	CS750	FA76	FA67	FA78	—
FDV12127E .	CS750	FA76	FA67	FA78	—
FDV12127F .	CS750	FA76	FA67	FA78	—
FDV12127G .	CS750	FA76	FA67	FA78	—
FEA12127E .	CS750	FA76	FA67	FA79	—
FEA12127F .	CS750	FA76	FA67	FA78	—
FEC12127A .	CS750	FA76	FA67	FA78	—

(continued on next page)

⁹ Two required ²⁵ For 1973-76 ²⁸ For 1977

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
FEC12127B	CS750	FA76	FA67	FA78	—
FED12102G	CS751	FA8200	FA157	FA79	—
FED12102K	CS751	FA8200	FA157	FA79	—
FED12102S	CS751	FA8200	FA157	FA79	—
FED12102T	CS751	FA8200	FA157	FA79	—
FEF12127B	CS750	FA76	FA67	FA78	—
FEG12127B	CS753	FA66	FA67	FA6900	VC915
FEG12127D	CS753	FA66	FA67	FA6900	VC915
FEH12127A	CS751	FA8200	FA157	FA79	—
FEH12127B	CS751	FA8200	FA157	FA79	—
FEH12127C	CS751	FA8200	FA157	FA78	—
FEJ12127A	CS751	FA8200	FA157	FA78	—
FEJ12127B	CS751	FA8200	FA157	FA78	—
FEK12127A	CS751	FA8200	FA157	FA79	—
FEK12127B	CS751	FA8200	FA157	FA79	—
FEK12127C	CS751	FA8200	FA157	FA79	—
FEK12127E	CS751	FA8200	FA157	FA79	—
FEK12127K	CS751	FA8200	FA157	FA78	—
FEL12127A	CS751	FA8200	FA157	FA79	—
FEL12127B	CS751	FA8200	FA157	FA78	—
FEM12127C	CS750	FA76	FA67	FA78	—
FEM12127E	CS750	FA76	FA67	FA78	—
FEM12127F	CS750	FA76	FA67	FA78	—
FER12127A	CS750	FA76	FA67	FA78	—
FET12127B	CS753	FA66	FA67	FA6900	VC915
FET12127C	CS753	FA66	FA67	FA6900	VC915
FET12127D	CS753	FA66	FA67	FA6900	—
FEU12127A	CS751	FA8200	FA157	FA79	—
FEU12127B	CS751	FA8200	FA157	FA79	—
FEU12127C	CS751	FA8200	FA157	FA79	—
FEU12127D	CS751	FA8200	FA157	FA79	—
FEU12127E	CS751	FA8200	FA157	FA79	—
FEU12127F	CS751	FA8200	FA157	FA79	—
FEU12127G	CS751	FA8200	FA157	FA79	—
FEU12127H	CS751	FA8200	FA157	FA79	—
FEU12127I	CS751	FA8200	FA157	FA79	—
FEU12127J	CS751	FA8200	FA157	FA79	—
FEU12127K	CS751	FA8200	FA157	FA79	—
FEU12127L	CS751	FA8200	FA157	FA79	—
FEU12127M	CS751	FA8200	FA157	FA79	—
FEU12127N	CS751	FA8200	FA157	FA79	—
FEW12127A	CS751	FA8200	FA157	FA79	—
FEW12127D	CS751	FA8200	FA157	FA79	—
FEW12127E	CS751	FA8200	FA157	FA79	—
FEW12127F	CS751	FA8200	FA157	FA79	—
FEW12127H	CS751	FA8200	FA157	FA79	—
FEY12127A	CS753	FA8200	FA157	FA79	—
FFA12127D	CS751	FA8200	FA157	FA79	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
FFA12127E	CS751	FA8200	FA157	FA79	—
FFC12127A	CS751	FA8200	FA157	FA79	—
FFD12102F	CS751	FA8200	FA157	FA79	—
FFD12102G	CS751	FA8200	FA157	FA79	—
FFD12102H	CS751	FA8200	FA157	FA79	—
FFD12102K	CS751	FA8200	FA157	FA79	—
FFD12102M	CS751	FA8200	FA157	FA79	—
FFD12102N	CS751	FA8200	FA157	FA79	—
FFD12102S	CS751	FA8200	FA157	FA79	—
FFD12102Series	CS751	FA8200	FA157	FA79	—
FFD12102T	CS751	FA8200	FA157	FA79	—
FFD12127B	CS751	FA8200	FA157	FA79	—
FFD12127C	CS751	FA8200	FA157	FA79	—
FFD12127D	CS751	FA8200	FA157	FA79	—
FFD12127E	CS751	FA8200	FA157	FA79	—
FFD12127F	CS751	FA8200	FA157	FA79	—
FFD12127G	CS751	FA8200	FA157	FA79	—
FFD12127H	CS751	FA8200	FA157	FA79	—
FFD12127I	CS751	FA8200	FA157	FA79	—
FFD12127J	CS751	FA8200	FA157	FA79	—
FFD12127K	CS751	FA8200	FA157	FA79	—
FFD12127L	CS751	FA8200	FA157	FA79	—
FFD12127M	CS751	FA8200	FA157	FA79	—
FFD12127N	CS751	FA8200	FA157	FA79	—
FFD12127O	CS751	FA8200	FA157	FA79	—
FFD12127P	CS751	FA8200	FA157	FA79	—
FFD12127Q	CS751	FA8200	FA157	FA79	—
FFD12127R	CS751	FA8200	FA157	FA79	—
FFD12127S	CS751	FA8200	FA157	FA79	—
FFD12127T	CS751	FA8200	FA157	FA79	—
FFD12127U	CS751	FA8200	FA157	FA79	—
FFD12127V	CS751	FA8200	FA157	FA79	—
FFD12127W	CS751	FA8200	FA157	FA79	—
FFD12127X	CS751	FA8200	FA157	FA79	—
FFD12127Y	CS751	FA8200	FA157	FA79	—
FFD12127Z	CS751	FA8200	FA157	FA79	—
IGA12127	CS35	FA54	—	—	VC915
MHK12127A	CS751	FA8200	FA157	FA79	—
MHK12127C	CS751	FA8200	FA157	FA79	—
MHK12127D	CS751	FA8200	FA157	FA79	—
MHK12127E	CS751	FA8200	FA157	FA79	—
MUK12127C	CS751	FA8200	FA157	FA79	—
MUK12127D	CS751	FA8200	FA157	FA79	—
OBA12127	CS753	FA66	FA67	FA6900	VC915
OCM12127A	CS753	FA66	FA67	FA6900	VC915
OCM12127B	CS753	FA66	FA67	FA78	VC915
OEL12127	CS753	FA66	FA67	FA78	VC915
IGA12127	CS35	—	—	—	VC915

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
7HA12127	CS753	FA66	FA67	FA6900	VC915
7RA12127C	CS753	FA66	FA67	FA78	VC915
7RA12127D	CS753	FA66	FA67	FA78	VC915
8BA12127	CS753	FA66	FA67	FA6900	VC915
8EL12127	—	—	AL65	AL66	—
8EQ12127A	CS753	FA66	FA67	FA78	VC915
8EQ12127C	CS753	FA66	FA67	FA78	VC915
8MTH12127	CS753	FA66	FA67	FA6900	—
8N12127A	CS753	FA76	FA67	FA352	—
8N12127B	CS753	FA76	FA67	FA352	—
9N12100	CS35	FA200	FA300	FA350	—
9W12100	—	—	FA300	—	—
11A12127	CS47	—	—	—	—
21A12127	CS47	FA54	—	—	—
59A12127	CS47	FA54	FA67	—	VC915
70AB12100DA	CS751	EP30	EP51	EP50	—
70IF12100DA	CS751	EP30	EP51	EP50	—
70IF12100EA	CS751	EP30	EP51	EP50	—
71BB12100BEA	CS751	EP30	EP49	EP50	—
71EB12100TA	CS313P	EP30	EP51	EP50	—
71EB12100ZA	CS751	EP30	EP51	EP50	—
71HM12100ABA	CS313P	EP282	EP143	EP274	—
71HM12100ACA	CS313P	EP30	EP143	EP274	—
71HM12100AEA	CS313P	EP282	EP143	EP274	—
71HM12100AFA	CS313P	EP30	EP143	EP274	—
72BB12100AGA	CS751	EP30	EP51	EP50	—
72BB12100AHA	CS751	EP30	EP51	EP50	—
72BB12100LA	CS751	EP30	EP51	EP50	—
72HF12100AJA	CS313P	EP282	EP143	EP274	—
72HF12100DC	CS313P	EP282	EP143	EP274	—
72HF12100EA	CS313P	—	EP143	EP274	—
72HF12100FA	CS313P	EP282	EP143	EP274	—
72HF12100GA	CS313P	—	EP51	EP50	—
72HF12100SC	CS313P	EP282	EP143	EP274	—
72IF12100AHA	CS751	EP30	EP51	EP50	—
72IF12100AJA	CS751	EP30	EP51	EP50	—
72IF12100TA	CS751	EP30	EP51	EP50	—
72IF12100YA	CS751	EP30	EP51	EP50	—
72TF12100AB	CS313P	EP434	EP407	EP406	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
72TF12100AC	CS313P	EP434	EP407	EP406	—
72TF12100ADB	CS313P	EP434	EP407	EP406	—
72TF12100ADC	CS313P	EP434	EP407	EP406	—
73HF12100AA	CS313P	EP282	EP143	EP274	—
73HF12100BA	CS313P	EP282	EP143	EP274	—
73HF12100CA	CS313P	EP282	EP143	EP274	—
73HF12100DA	CS313P	EP282	EP143	EP274	—
73HF12100GA	CS313P	EP282	EP143	EP274	—
73TF12100AA	CS313P	EP434	EP407	EP406	—
73TF12100BA	CS313P	EP434	EP407	EP406	—
74HF12100CA	CS313P	EP282	EP143	EP274	—
74HF12100DA	CS313P	—	EP143	EP274	—
74HF12100EA	CS313P	EP408	EP143	EP274	—
74HF12100JA	CS313P	EP282	EP143	EP274	—
74HF12100LA	CS313P	EP408	EP143	EP274	—
74TF12100LA	CS313P	EP434	EP407	EP406	—
74TF12100MA	CS313P	EP434	EP407	EP406	—
74TF12100NA	CS313P	EP435	EP407	EP406	—
74TF12100RA	CS313P	EP435	EP407	EP406	—
74TF12100SA	CS313P	EP434	EP407	EP406	—
74TF12100TA	CS313P	EP435	—	EP406	—
76FT12100HB	CS313P	EP293	—	—	—
76IF12100FA	CS751	EP30	—	EP50	—
76IF12100HB	CS313P	EP293	—	—	—
84BF12100HA	—	—	EP143	EP274	—
701F12100EA	CS751	EP30	EP51	EP50	—
721F12100AHA	CS751	EP30	EP51	EP50	—
721F12100TA	CS751	EP30	EP51	EP50	—
721F12100YA	CS751	EP30	EP51	EP50	—
311185	CS753	FA76	FA67	FA352	—
7812127	CS47	FA79	—	—	—
184318200A	—	—	EP342	—	—
184518200	—	—	EP342	—	—
184918200	—	—	EP342	—	—
184918200A	CS359	EP366	EP342	—	—
376318200A	CS359	EP366	EP342	—	—
718812100ANB	CS751	EP30	EP49	EP50	—

HOLLEY

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D179A	CS750	FA66	FA67	FA6900	—
D659IAS	CS753	FA66	FA67	FA6900	—
D661A	CS753	FA66	FA67	FA6900	—
D668AS	CS750	FA79	FA67	FA78	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D687AS	CS750	FA76	FA67	FA78	—
D813A	CS750	FA76	FA67	FA78	—
D813AS	CS750	FA76	FA67	FA78	—
D816A	CS750	FA76	FA67	FA78	—

(continued on next page)

HOLLEY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D816AS	CS750	FA76	FA67	FA78	—
D835AS	CS753	FA66	FA67	FA78	—
D844A	CS750	FA76	FA67	FA78	—
D912A	CS750	FA76	FA67	FA78	—
D915A	CS750	FA76	FA67	FA78	—
D915AS	CS750	FA76	FA67	FA78	—
D916A	CS750	FA76	FA67	FA78	—
D916AS	CS750	FA76	FA67	FA78	—
D918A	CS750	FA76	FA67	FA78	—
D918AS	CS750	FA76	FA67	FA78	—
D1013A	CS753	FA66	FA67	FA6900	—
D1014A	CS750	FA76	FA67	FA78	—
D1014AS	CS750	FA76	FA67	FA78	—
D1016A	CS750	FA76	FA67	FA78	—
D1016AS	CS750	FA76	FA67	FA78	—
D1017A	CS750	FA76	FA67	FA78	—
D1017AS	CS750	FA76	FA67	FA78	—
D1019A	CS750	FA76	FA67	FA78	—
D1019AS	CS750	FA76	FA67	FA78	—
D1020A	CS750	FA76	FA67	FA78	—
D1020AS	CS750	FA76	FA67	FA78	—
D1021A	CS750	FA76	FA67	FA78	—
D1022A	CS750	FA76	FA67	FA78	—
D1022AS	CS750	FA76	FA67	FA78	—
D1023A	CS750	FA76	FA67	FA78	—
D1024A	CS750	FA76	FA67	FA78	—
D1025A	CS750	FA76	FA67	FA78	—
D1064AA	CS750	FA76	FA81	FA78	—
D1065AA	CS750	FA76	FA81	FA78	—
D1066AA	CS750	FA76	FA81	FA78	—
D1100A	CS750	FA76	FA67	FA78	—
D1100AS	CS750	FA76	FA67	FA78	—
D1104A	CS750	FA76	FA67	FA78	—
D1104AS	CS750	FA76	FA67	FA78	—
D1105A	CS750	FA76	FA67	FA78	—
D1105AS	CS750	FA76	FA67	FA78	—
D1111A	CS750	FA76	FA67	FA78	—
D1111AS	CS750	FA76	FA67	FA78	—
D1112A	CS750	FA76	FA67	FA78	—
D1112AS	CS750	FA76	FA67	FA78	—
D1113A	CS750	FA76	FA67	FA78	—
D1113AS	CS750	FA76	FA67	FA78	—
D1114A	CS750	FA76	FA67	FA78	—
D1114AS	CS750	FA76	FA67	FA78	—
D1138A	CS750	FA76	FA67	FA78	—
D1138AS	CS750	FA76	FA67	FA78	—
D1139A	CS750	FA76	FA67	FA78	—
D1139AS	CS750	FA76	FA67	FA78	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D1140A	CS750	FA76	FA67	FA78	—
D1140AS	CS750	FA76	FA67	FA78	—
D1141A	CS750	FA76	FA67	FA78	—
D1141AS	CS750	FA76	FA67	FA78	—
D1142A	CS750	FA76	FA67	FA78	—
D1142AS	CS750	FA76	FA67	FA78	—
D1143A	CS750	FA76	FA67	FA78	—
D1143AS	CS750	FA76	FA67	FA78	—
D1145A	CS750	FA76	FA67	FA78	—
D1145AS	CS750	FA76	FA67	FA78	—
D1208A	CS753	FA66	FA67	FA6900	—
D1208AS	CS753	FA66	FA67	FA6900	—
D1223A	CS753	FA66	FA67	FA6900	—
D1293A	CS750	FA76	FA67	FA78	—
D1294A	CS750	FA76	FA67	FA78	—
D1295A	CS750	FA76	FA67	FA78	—
D1296A	CS750	FA76	FA67	FA78	—
D1304A	CS751	FA8200	FA157	FA79	—
D1305A	CS751	FA8200	FA157	FA79	—
D1306A	CS751	FA8200	FA157	FA79	—
D1307A	CS751	FA8200	FA157	FA79	—
D1309AA	CS750	FA76	FA81	FA78	—
D1319AA	CS750	FA66	FA157	FA79	—
D1336A	CS751	FA8200	FA157	FA79	—
D1338A	CS753	FA66	FA67	FA6900	—
D1357AA	CS750	FA76	FA81	FA78	—
D1364A	CS750	FA76	FA67	FA78	—
D1365A	CS750	FA76	FA67	FA78	—
D1367A	CS750	FA76	FA67	FA78	—
D1374A	CS751	FA8200	FA157	FA79	—
D1375A	CS751	FA8200	FA157	FA79	—
D1376A	CS751	FA8200	FA157	FA79	—
D1397A	CS751	FA8200	FA157	FA79	—
D1408A	—	—	FA8000	FA98	—
D1409A	CS751	FA8200	FA157	FA79	—
D1429A	CS751	FA8200	FA157	FA79	—
D1430A	CS751	FA8200	FA157	FA79	—
D1474AA	CS750	FA66	FA157	FA79	—
D1475AA	CS750	FA66	FA157	FA79	—
D1479AA	CS753	FA66	FA157	FA79	—
D1484A	CS751	FA8200	FA157	FA79	—
D1484AA	CS751	FA8200	FA157	FA79	—
D1490A	CS751	FA8200	FA157	FA79	—
D1527AA	CS750	FA66	FA157	FA79	—
D1528AA	CS750	FA66	FA157	FA79	—
D1529AA	CS750	FA66	FA157	FA79	—
D1531AA	CS750	FA66	FA157	FA79	—
D1532AA	CS750	FA66	FA157	FA6900	—

(continued on next page)

HOLLEY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D1534A	CS751	FA8200	FA157	FA79	—
D1537A	CS750	FA76	FA67	FA78	—
D1558A	CS753	FA66	FA67	FA6900	—
D1576A	CS751	FA8200	FA157	FA79	—
D1600A	CS753	FA66	FA67	FA6900	—
D1653A	CS751	FA8200	FA157	FA79	—
D1654A	CS751	FA8200	FA157	FA79	—
D1657A	CS751	FA8200	FA157	FA79	—
D1658A	CS751	FA8200	FA157	FA79	—
D1664A	CS751	FA8200	FA157	FA79	—
D1683A	CS751	FA8200	FA157	FA79	—
D1701AA	CS753	FA66	FA157	FA79	—
D1702A	CS751	FA8200	FA157	FA79	—
D1743A	CS751	FA8200	FA157	FA79	—
D1744A	CS751	FA8200	FA157	FA79	—
D1765A	CS751	FA8200	FA157	FA79	—
D1766A	CS751	FA8200	FA157	FA79	—
D1766A	CS753	FA66	FA67	FA6900	—
D1766AS	CS753	FA66	FA67	FA6900	—
D1773A	CS751	FA8200	FA157	FA79	—
D1775A	CS751	FA8200	FA157	FA6900	—
D1775AS	CS751	FA8200	FA157	FA6900	—
D1803A	CS750	FA66	FA157	FA79	—
D1803AA	CS750	FA66	FA157	FA79	—
D1804A	CS750	FA66	FA157	FA79	—
D1804AA	CS750	FA66	FA157	FA79	—
D1827A	CS753	FA66	FA67	FA6900	—
D1870A	CS751	FA8200	FA157	FA6900	—
D1871A	CS751	FA8200	FA157	FA79	—
D1872A	CS751	FA8200	FA157	FA79	—
D1900A	CS751	FA8200	FA157	FA79	—
D1909A	CS751	FA8200	FA157	FA79	VC945
D1909AS	CS751	FA8200	FA157	FA79	VC945
D1920A	CS751	FA8200	FA157	FA79	—
D1925A	CS753	FA66	FA67	FA6900	—
D1935A	CS750	FA66	FA157	FA79	—
D1935AAS	CS750	FA66	FA157	FA79	—
D1935AS	CS750	FA66	FA157	FA79	—
D1936A	CS750	FA66	FA157	FA79	—
D1936AAS	CS750	FA66	FA157	FA79	—
D1936AS	CS750	FA66	FA157	FA79	—
D1937A	CS750	FA66	FA157	FA79	—
D1937AAS	CS750	FA66	FA157	FA79	—
D1937AS	CS750	FA66	FA157	FA79	—
D1938A	CS750	FA66	FA157	FA79	—
D1938AAS	CS750	FA66	FA157	FA79	—
D1938AS	CS750	FA66	FA157	FA79	—
D1939A	CS750	FA66	FA157	FA79	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D1939AAS	CS750	FA66	FA157	FA79	—
D1939AS	CS750	FA66	FA157	FA79	—
D1940A	CS750	FA66	FA157	FA79	—
D1940AAS	CS750	FA66	FA157	FA79	—
D1940AS	CS750	FA66	FA157	FA79	—
D1941A	CS750	FA66	FA157	FA79	—
D1941AAS	CS750	FA66	FA157	FA79	—
D1941AS	CS750	FA66	FA157	FA79	—
D1942A	CS750	FA66	FA157	FA79	—
D1942AAS	CS750	FA66	FA157	FA79	—
D1942AS	CS750	FA66	FA157	FA79	—
D1943A	CS750	FA66	FA157	FA79	—
D1943AAS	CS750	FA66	FA157	FA79	—
D1943AS	CS750	FA66	FA157	FA79	—
D1944A	CS750	FA66	FA157	FA79	—
D1944AAS	CS750	FA66	FA157	FA79	—
D1944AS	CS750	FA66	FA157	FA79	—
D1945A	CS750	FA66	FA157	FA79	—
D1945AAS	CS750	FA66	FA157	FA79	—
D1945AS	CS750	FA66	FA157	FA79	—
D1950A	CS751	FA8200	FA157	FA79	VC945
D1950AS	CS751	FA8200	FA157	FA79	VC945
D1955A	CS751	FA8200	FA157	FA79	—
D1955AS	CS751	FA8200	FA157	FA79	—
D1983A	CS751	FA8200	FA157	FA79	—
D1983AS	CS751	FA8200	FA157	FA79	—
D2001A	CS751	FA8200	FA157	FA79	—
D2034A	CS751	FA8200	FA157	FA79	—
D2034AS	CS751	FA8200	FA157	FA79	—
D2081A	CS751	FA8200	FA157	FA79	—
D2081AS	CS751	FA8200	FA157	FA79	—
D2082A	CS751	FA8200	FA157	FA79	—
D2082AS	CS751	FA8200	FA157	FA79	—
D2115A	CS753	FA66	FA67	FA6900	—
D2115AS	CS753	FA66	FA67	FA6900	—
D2169A	CS753	FA66	FA67	FA6900	—
D2169AS	CS753	FA66	FA67	FA6900	—
D2214A	CS750	FA66	FA157	FA79	—
D2214AAS	CS750	FA66	FA157	FA79	—
D2214AS	CS750	FA66	FA157	FA79	—
D2215A	CS750	FA66	FA157	FA79	—
D2215AAS	CS750	FA66	FA157	FA79	—
D2215AS	CS750	FA66	FA157	FA79	—
D2216A	CS750	FA66	FA157	FA79	—
D2216AAS	CS750	FA66	FA157	FA79	—
D2216AS	CS750	FA66	FA157	FA79	—
D2217A	CS750	FA66	FA157	FA79	—
D2217AAS	CS750	FA66	FA157	FA79	—

(continued on next page)

HOLLEY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D2217AS	CS750	FA66	FA157	FA79	—
D2218A	CS750	FA66	FA157	FA79	—
D2218AAS	CS750	FA66	FA157	FA79	—
D2218AS	CS750	FA66	FA157	FA79	—
D2219A	CS750	FA66	FA157	FA79	—
D2219AAS	CS750	FA66	FA157	FA79	—
D2219AS	CS750	FA66	FA157	FA79	—
D2220A	CS750	FA66	FA157	FA79	—
D2220AAS	CS750	FA66	FA157	FA79	—
D2220AS	CS750	FA66	FA157	FA79	—
D2222A	CS753	FA66	FA67	FA6900	—
D2222AS	CS753	FA66	FA67	FA6900	—
D2263A	CS753	FA83	FA8000	FA98	—
D2263AA	CS753	FA83	FA8000	FA79	—
D2263AAS	CS753	FA83	FA8000	FA98	—
D2263S	CS753	FA83	—	FA98	—
D2274A	CS753	FA76	FA8000	FA86	—
D2274AA	CS753	FA83	FA8000	FA86	—
D2293AA	CS750	FA76	FA157	FA79	—
D2293AAS	CS750	FA76	FA157	FA79	—
D2322AA	CS753	FA83	FA8000	FA98	—
D2361AA	CS753	FA83	FA8000	FA79	—
D2363AA	CS753	FA83	FA8000	FA79	—
D2370AA	CS750	FA83	FA8000	FA98	—
D2372	CS750	FA83	FA8000	FA98	—
D2372A	CS750	FA83	FA8000	FA98	—
D2372AA	CS750	FA83	FA8000	FA98	—
D2373AA	CS750	FA83	FA8000	FA79	—
D2377A	CS750	FA66	FA67	FA6900	—
D2399AA	CS753	FA83	FA8000	FA79	—
D2399GT	CS753	FA83	FA8000	FA98	—
D2441	CS753	FA83	FA8000	FA86	—
D2475AA	CS753	FA83	FA8000	FA98	VC145
D2503	CS753	FA76	FA67	FA6900	VC915
D2503A	CS753	FA66	FA67	FA6900	—
D2503AS	CS753	FA66	FA67	FA6900	—
D2504A	CS753	FA6900	—	FA67	—
D2504AS	CS753	FA6900	—	FA67	—
D2505A	CS753	FA66	FA67	FA6900	—
D2505AS	CS753	FA66	FA67	FA6900	—
D2511AA	CS753	FA83	—	—	—
D2563A	CS753	FA83	FA8000	—	—
D2564A	CS753	FA66	FA67	FA6900	—
D2564AS	CS753	FA66	FA67	FA6900	—
D2565A	CS753	FA66	FA67	FA6900	—
D2565AS	CS753	FA66	FA67	FA6900	—
D2566A	CS753	FA66	FA67	FA6900	—
D2566AS	CS753	FA66	FA67	FA6900	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D2567A	CS753	FA66	FA67	FA6900	—
D2567AS	CS753	FA66	FA67	FA6900	—
D2573A	CS751	FA8200	FA157	FA79	—
D2573AS	CS751	FA8200	FA157	FA79	—
D2591A	CS753	FA66	FA67	FA6900	—
D2591AS	CS753	FA66	FA67	FA6900	—
D2594A	CS753	FA66	FA67	FA6900	—
D2594AS	CS753	FA66	FA67	FA6900	—
D2595A	CS753	FA66	FA67	FA6900	—
D2595AS	CS753	FA66	FA67	FA6900	—
D2598A	CS753	FA66	FA67	FA6900	—
D2598AS	CS753	FA66	FA67	FA6900	—
D2610A	CS751	FA8200	FA157	FA79	VC965
D2610AS	CS751	FA8200	FA157	FA79	VC965
D2623A	CS751	FA8200	FA157	FA79	—
D2623AS	CS751	FA8200	FA157	FA79	—
D2624A	CS751	—	FA157	FA79	VC965
D2641AA	CS753	FA83	—	—	—
D2654A	CS753	FA66	FA67	FA6900	—
D2654AS	CS753	FA66	FA67	FA6900	—
D2655A	CS753	FA66	FA67	FA6900	—
D2655AS	CS753	FA66	FA67	FA6900	—
D2656AA	CS750	FA83	FA8000	FA98	—
D2663	CS753	FA83	FA8000	FA98	—
D2663A	—	—	FA8000	FA98	—
D2757AA	CS753	FA83	FA8000	FA79	—
D2789A	CS753	FA83	FA8000	—	—
D2789AA	CS753	FA83	FA8000	—	—
D2819A	CS751	FA8200	FA157	FA79	VC965
D2819AS	CS751	FA8200	FA157	FA79	VC965
D2820A	CS751	FA8200	FA157	FA79	VC965
D2820AS	CS751	FA8200	FA157	FA79	VC965
D2821A	CS751	FA8200	FA157	FA79	—
D2821AS	CS751	FA8200	FA157	FA79	—
D2822A	CS751	FA8200	FA157	FA79	—
D2822AS	CS751	FA8200	FA157	FA79	—
D2823A	CS751	FA8200	FA157	FA79	—
D2823AS	CS751	FA8200	FA157	FA79	—
D2835A	CS751	FA8200	FA157	FA79	VC965
D2836A	CS751	—	FA157	FA79	VC965
D2841A	CS751	FA8200	FA157	FA79	VC965
D2844A	CS751	FA8200	FA157	FA79	—
D2851A	CS751	FA8200	FA157	FA79	VC965
D2851AS	CS751	FA8200	FA157	FA79	VC965
D2852A	CS751	—	FA157	FA79	VC965
D2874AA	CS750	FA83	FA8000	—	—
D2877A	CS753	FA76	FA8000	—	—
D2892	CS753	FA83	FA8000	FA98	—

(continued on next page)

HOLLEY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D2892AA	CS753	FA83	FA8000	FA79	—
D2892S	CS753	FA83	FA8000	FA98	—
D2893	CS753	FA83	FA8000	FA98	—
D2893AA	CS753	FA83	FA8000	FA79	—
D2894AA	CS753	FA83	FA8000	FA79	—
D2895	CS753	FA83	FA8000	—	—
D2895AA	CS753	FA83	FA8000	—	—
D2897	CS753	FA83	FA8000	—	—
D2897AA	CS753	FA83	FA8000	—	—
D2899AA	CS753	FA83	FA8000	—	—
D2910A	CS751	FA8200	FA157	FA79	VC965
D2911A	CS751	FA8200	FA157	FA79	—
D2913AA	CS753	FA83	FA8000	FA79	—
D2913AAS	CS753	FA83	FA8000	FA98	—
D2958AA	CS750	FA83	FA8000	FA98	—
D2959AA	CS750	FA83	FA8000	—	—
D2960AA	CS753	FA83	FA8000	FA98	—
D2961AA	CS753	FA83	FA8000	—	—
D2962AA	CS750	FA83	FA8000	—	—
D2972AA	CS753	FA83	—	—	—
D3011AAS	CS750	FA83	FA8000	FA79	—
D3015A	CS751	FA8200	FA157	FA79	VC965
D3038AAS	CS753	FA83	FA8000	FA79	—
D3039AAS	CS753	FA83	FA8000	FA79	—
D3040AAS	CS753	FA83	FA8000	FA79	—
D3119AA	CS753	FA83	FA8000	FA86	—
D3159A	CS751	FA8200	FA157	FA79	VC965
D3172A	CS751	FA8200	FA157	FA79	VC965
D3194A	CS751	—	FA157	FA79	VC965
D3195AA	CS753	FA83	—	—	—
D3196AA	CS753	FA83	—	—	—
D3221A	CS750	FA83	FA8000	FA79	—
D3221AA	CS750	FA83	FA8000	FA79	—
D3222A	CS750	FA83	FA8000	FA79	—
D3222AA	CS750	FA83	FA8000	FA79	—
D3223AA	CS753	FA83	FA8000	FA6900	—
D3224AA	CS753	FA83	FA8000	FA79	—
D3228AA	CS757P	FA83	FA8000	MO40	—
D3238AA	CS753	FA83	FA8000	FA79	—
D3260AAS	CS753	FA83	FA8000	FA79	—
D3261AAS	CS753	FA83	FA8000	FA79	—
D3263AA	CS753	FA83	—	—	—
D3296A	CS751	FA8200	FA157	FA79	VC965
D3315A	CS751	FA8200	FA157	FA79	VC965
D3323AA	CS753	FA83	FA8000	FA79	—
D3383A	CS751	FA8200	FA157	FA79	VC965
D3384A	CS751	—	FA157	FA79	VC965
D3385A	CS751	FA8200	FA157	FA79	VC965

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D3386A	CS751	—	FA157	FA79	VC965
D3458A	CS751	FA8200	FA157	FA79	VC965
D3479A	CS757P	FA66	FA8000	FA98	—
D3497A	CS757P	FA66	FA8000	FA79	—
D3504AA	CS753	FA83	FA8000	FA86	—
D3505A	CS753	FA83	FA8000	FA98	—
D3505AA	CS753	FA83	FA8000	FA79	—
D3511AA	CS753	FA83	FA8000	FA79	—
D3513AA	CS753	FA83	FA8000	FA98	—
D3539A	CS757P	FA66	FA8000	FA79	—
D3563AA	CS757P	FA83	FA8000	—	—
D3635A	CS751	FA8200	FA157	FA79	VC965
D3651AA	CS753	FA83	FA8000	FA79	—
D3690AA	CS757P	FA66	FA8000	FA98	—
D3693A	CS757P	FA66	FA8000	FA79	—
D3694A	CS757P	FA66	FA8000	FA98	—
D3694AA	CS757P	FA66	FA8000	FA98	—
D3695A	CS757P	FA66	FA8000	FA79	—
D3695AA	CS757P	FA66	FA8000	FA98	—
D3698A	CS757P	FA66	FA8000	FA79	—
D3698AA	CS757P	FA66	FA8000	FA98	—
D3717A	CS757P	FA66	FA8000	FA86	—
D3717AA	CS757P	FA66	FA8000	FA86	—
D3719AA	CS750	FA83	FA8000	FA79	—
D3723A	CS757P	FA66	FA8000	FA86	—
D3723AA	CS757P	FA66	FA8000	FA86	—
D3723AN	CS757P	FA66	FA8000	FA86	—
D3724A	CS757P	FA66	FA8000	FA79	—
D3724AA	CS757P	FA66	FA8000	FA98	—
D3726A	CS757P	FA66	FA8000	FA98	—
D3727A	CS757P	FA66	FA8000	FA79	—
D3730AA	CS753	FA83	—	—	—
D3752A	CS751	FA8200	FA157	FA79	VC965
D3754A	CS751	FA8200	FA157	FA79	VC965
D3755A	CS751	FA8200	FA157	FA79	VC965
D3758A	CS757P	FA66	FA8000	—	—
D3758AS	CS757P	FA66	FA8000	—	—
D3759A	CS757P	FA66	FA8000	—	—
D3759AS	CS757P	FA66	FA8000	—	—
D3760A	CS757P	FA66	—	—	—
D3760AS	CS757P	FA66	—	—	—
D3818A	CS757P	FA66	FA8000	FA79	—
D3818AA	CS757P	FA66	FA8000	FA98	—
D3819A	CS757P	FA66	FA8000	FA98	—
D3826A	CS751	FA8200	FA157	FA79	VC965
D3827A	CS751	FA8200	FA8000	FA79	—
D3833A	—	—	FA89	FA87	—
D3834A	—	—	FA89	FA87	—

(continued on next page)

HOLLEY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D3839AA	CS750	FA83	FA8000	FA98	—
D3841AA	CS757P	FA83	FA8000	FA98	—
D3852	CS753	FA83	FA8000	FA86	—
D3852AA	CS753	FA83	FA8000	FA86	—
D3854A	CS753	FA83	FA8000	FA98	—
D3854AA	CS753	FA83	FA8000	FA79	—
D3857AA	CS753	FA83	FA8000	FA86	—
D3874A	CS753	FA83	FA8000	FA98	—
D3874AA	CS753	FA83	FA8000	FA98	—
D3875AA	CS753	FA83	FA8000	—	—
D3876AA	CS753	FA83	FA8000	FA79	—
D3891AA	CS753	FA83	FA8000	FA98	—
D3927A	CS751	FA83	FA157	FA79	VC965
D3939AA	CS750	FA83	FA8000	FA98	—
D3941AA	CS753	FA83	FA8000	FA79	—
D4016A	CS757P	FA66	FA8000	FA86	—
D4017A	CS757P	FA66	FA8000	FA79	—
D4017AA	CS757P	FA66	FA8000	FA98	—
D4018A	CS757P	FA66	FA8000	FA79	—
D4018AA	CS757P	FA66	FA8000	FA98	—
D4019A	CS757P	FA66	FA8000	FA79	—
D4019AA	CS757P	FA66	FA8000	FA98	—
D4036A	CS757P	FA66	FA8000	FA79	—
D4037A	CS757P	FA66	FA8000	FA86	—
D4038A	CS757P	FA66	FA8000	FA86	—
D4040A	CS757P	FA66	FA8000	FA79	—
D4041A	CS757P	FA66	FA8000	FA79	—
D4042A	CS757P	FA66	FA8000	FA79	—
D4042AA	CS757P	FA66	FA8000	FA98	—
D4043A	CS757P	FA66	FA8000	FA98	—
D4044A	CS757P	FA66	FA8000	FA98	—
D4046A	CS757P	FA66	FA8000	FA98	—
D4047A	CS757P	FA66	FA8000	FA79	—
D4047AA	CS757P	FA66	FA8000	FA98	—
D4048A	CS757P	FA66	FA8000	FA98	—
D4049A	CS757P	FA66	FA8000	FA98	—
D4050A	CS757P	FA66	FA8000	FA79	—
D4068	CS757P	FA66	FA8000	FA98	—
D4068A	CS757P	FA66	FA8000	FA98	—
D4092A	CS757P	FA66	FA8000	FA86	—
D4095A	CS757P	FA66	FA8000	FA79	—
D4104A	CS757P	FA66	FA8000	FA86	—
D4108A	CS757P	FA66	FA8000	FA79	—
D4128A	—	—	—	—	VC965
D4129A	—	—	—	—	VC965
D4141A	CS757P	FA66	FA8000	FA98	—
D4182A	CS751	FA8200	FA157	FA79	VC965
D4183A	CS751	FA8200	FA157	FA79	VC965

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D4224AS	CS757P	FA66	FA8000	FA98	—
D4225AAA	CS757P	FA66	FA8000	FA98	—
D4225AAS	CS757P	FA66	FA8000	FA79	—
D4242AAS	CS757P	FA66	FA8000	FA98	—
D4243AS	CS757P	FA66	FA8000	FA98	—
D4244AS	CS757P	FA66	FA8000	FA98	—
D4245AS	CS757P	FA66	FA8000	FA98	—
D4246AS	CS757P	FA66	FA8000	FA98	—
D4247AAS	CS757P	FA66	FA8000	FA98	—
D4247AS	CS757P	FA66	FA8000	FA98	—
D4248AAS	CS757P	FA66	FA8000	FA98	—
D4248AS	CS757P	FA66	FA8000	FA98	—
D4249AS	CS757P	FA66	FA8000	FA86	—
D4251AS	CS757P	FA66	FA8000	FA86	—
D4252AS	CS757P	FA66	FA8000	FA86	—
D4253AS	CS757P	FA66	FA8000	FA86	—
D4254AAS	CS757P	FA66	FA8000	FA98	—
D4255AAS	CS757P	FA66	FA8000	FA98	—
D4255AS	CS757P	FA66	FA8000	FA98	—
D4256AS	CS757P	FA66	FA8000	FA98	—
D4256AS	CS757P	FA83	FA8000	FA98	—
D4257AAS	CS757P	FA66	FA8000	FA98	—
D4257AS	CS757P	FA66	FA8000	FA98	—
D4258AS	CS757P	FA66	FA8000	FA98	—
D4259AS	CS757P	FA66	FA8000	FA98	—
D4261AS	CS757P	FA66	FA8000	FA79	—
D4262A	CS757P	FA66	FA8000	FA98	—
D4262AS	CS757P	FA66	FA8000	FA98	—
D4263AS	CS757P	FA66	FA8000	FA98	—
D4264AS	CS757P	FA66	FA8000	FA79	—
D4265AA	CS757P	FA66	FA8000	FA86	—
D4265AAA	CS757P	FA66	FA8000	FA86	—
D4265AS	CS757P	FA66	FA8000	FA79	—
D4266AAS	CS757P	FA66	FA8000	MO20	—
D4266AS	CS757P	FA66	FA8000	FA79	—
D4284A	CS757P	FA66	FA8000	FA79	—
D4284AAS	CS757P	FA66	FA8000	FA79	—
D4285A	CS757P	FA66	FA8000	FA79	—
D4286A	CS757P	FA66	FA8000	FA79	—
D4290A	CS757P	FA66	—	FA79	—
D4292A	—	—	FA8000	FA98	—
D4294AS	CS757P	FA66	FA8000	FA86	—
D4298A	CS757P	FA66	FA8000	FA98	—
D4299A	CS757P	FA66	FA8000	FA98	—
D4585A	CS757P	FA66	FA8000	FA98	—
D4707A	CS757P	FA66	FA8000	FA98	—
D4727A	CS757P	FA66	FA8000	FA98	—
D4728A	CS757P	FA66	FA8000	FA98	—

(continued on next page)

HOLLEY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D4729A	CS757P	FA66	FA8000	FA98	—
D4730A	CS757P	FA66	FA8000	FA98	—
D4747A	CS753	FA83	FA8000	—	—
D4782A	CS757P	FA66	FA8000	FA98	—
D4812A	CS757P	FA66	FA8000	FA98	—
D4813	CS757P	FA66	FA8000	FA98	—
D4813A	CS757P	FA66	FA8000	FA98	—
D4814AA	CS757P	FA66	FA8000	FA86	—
D4814AAA	CS757P	FA66	FA8000	FA86	—
D4816AAA	CS757P	FA66	FA8000	FA98	—
D4817AAA	CS757P	FA66	FA8000	FA98	—
D4929AS	CS757P	FA66	FA8000	FA86	—
D6229A	CS753	FA83	FA8000	—	—
D6331	CS757P	FA76	FA8000	FA98	—
D6332	CS757P	FA76	FA8000	FA98	—
D6333AA	CS757P	FA76	FA8000	FA98	—
D6403A	CS757P	FA66	FA8000	—	—
D6413A	CS757P	FA66	FA8000	—	—
D6426A	CS753	FA83	—	—	—
D6427A	CS753	FA66	—	FA87	—
D6428A	CS753	FA83	—	—	—
D6429A	CS753	FA83	FA8000	—	—
D6430A	CS757P	FA66	—	FA87	—
D6431A	CS757P	FA66	—	FA87	—
D6591A	CS753	FA66	FA67	FA6900	—
D6591AS	CS753	FA66	FA67	FA6900	—
D6872A	CS750	FA76	FA67	FA78	—
D7771AS	CS750	FA76	FA67	FA78	—
D8441A	CS750	FA76	FA67	FA78	—
D8441AS	CS750	FA76	FA67	FA78	—
D9121A	CS750	FA76	FA67	FA78	—
D9121AS	CS750	FA76	FA67	FA78	—
D10171A	CS750	FA76	FA67	FA78	—
D10171AS	CS750	FA76	FA67	FA78	—
D10181A	CS750	FA76	FA67	FA78	—
D10181AS	CS750	FA76	FA67	FA78	—
D10182A	CS750	FA76	FA67	FA78	—
D13071A	CS751	FA8200	FA157	FA79	—
D13531AA	CS753	FA66	FA157	FA79	—
D13532AA	CS753	FA66	FA157	FA79	—
D13533AA	CS753	FA66	FA157	FA79	—
D13641A	CS750	FA76	FA67	FA78	—
D13651A	CS750	FA76	FA67	FA78	—
D13651AS	CS750	FA76	FA67	FA78	—
D13671A	CS750	FA76	FA67	FA78	—
D13672A	CS750	FA76	FA67	FA78	—
D13672AS	CS750	FA76	FA67	FA78	—
D14791AA	CS753	FA66	FA157	FA79	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D14961A	CS751	FA8200	FA157	FA79	—
D14962A	CS751	FA8200	FA157	FA79	—
D14963A	CS751	FA8200	FA157	FA79	—
D15371A	CS750	FA76	FA67	FA78	—
D15371AS	CS750	FA76	FA67	FA78	—
D15861A	CS751	FA8200	FA157	FA79	—
D15862A	CS751	FA8200	FA157	FA79	—
D15863A	CS751	FA8200	FA157	FA79	—
D15881A	CS751	FA8200	FA157	FA79	—
D15882A	CS751	FA8200	FA157	FA79	—
D15883A	CS751	FA8200	FA157	FA79	—
D16411A	CS751	FA8200	FA157	FA79	—
D16431A	CS751	FA8200	FA157	FA79	—
D16432A	CS751	FA8200	FA157	FA79	—
D16433A	CS751	FA8200	FA157	FA79	—
D16441A	CS751	FA8200	FA157	FA79	—
D16442A	CS751	FA8200	FA157	FA79	—
D16443A	CS751	FA8200	FA157	FA79	—
D17021A	CS751	FA8200	FA157	FA79	—
D17022A	CS751	FA8200	FA157	FA79	—
D17031A	CS751	FA8200	FA157	FA79	—
D17731A	CS751	FA8200	FA157	FA79	—
D17731AS	CS751	FA8200	FA157	FA79	—
D17732A	CS751	FA8200	FA157	FA79	—
D18821AA	CS750	FA76	FA157	FA79	—
D18821AAS	CS750	FA76	FA157	FA79	—
D18831AA	CS750	FA76	FA157	FA79	—
D18831AAS	CS750	FA76	FA157	FA79	—
D20241A	CS751	FA8200	FA157	FA79	—
D20251A	CS751	FA8200	FA157	FA79	—
D20251AS	CS751	FA8200	FA157	FA79	—
D20252A	CS751	FA8200	FA157	FA79	—
D20252AS	CS751	FA8200	FA157	FA79	—
D23101A	CS753	FA66	FA67	FA6900	—
D23101AAS	CS753	FA66	FA67	FA6900	—
D23221A	CS753	FA83	FA8000	FA98	—
D23221AA	CS753	FA83	FA8000	FA98	—
D23631A	CS750	FA83	FA8000	FA98	—
D23631AA	CS750	FA83	FA8000	FA98	—
D23701A	CS750	FA83	FA8000	FA98	—
D23991AA	CS753	FA83	FA8000	FA79	—
D23991AAS	CS753	FA83	FA8000	FA79	—
D23992A	CS753	FA83	FA8000	FA98	—
D23992AA	CS753	FA83	FA8000	FA79	—
D24411AA	CS753	FA83	FA8000	FA86	—
D24751A	CS753	FA83	FA8000	FA98	VC145
D25610A	CS751	FA8200	FA8000	FA79	—
D25631AA	CS753	FA83	—	—	—

(continued on next page)

HOLLEY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D26561A	CS750	FA83	FA8000	FA98	—
D26561AA	CS750	FA83	FA8000	FA98	—
D27571A	CS753	FA83	FA8000	FA98	—
D27571AA	CS753	FA83	FA8000	FA79	—
D27891AA	CS753	FA83	FA8000	—	—
D28741AA	CS750	FA83	FA8000	—	—
D28931AA	CS753	FA83	FA8000	FA79	—
D28941AA	CS753	FA83	FA8000	FA79	—
D28971AA	CS753	FA83	FA8000	—	—
D29131A	CS750	FA83	FA8000	FA98	—
D29131AA	CS753	FA83	FA8000	FA79	—
D29581A	CS750	FA83	FA8000	FA98	—
D29581AA	CS750	FA83	FA8000	FA98	—
D29591AA	CS750	FA83	FA8000	—	—
D29601AA	CS753	FA83	FA8000	FA98	—
D29611AA	CS753	FA83	FA8000	—	—
D29621AA	CS750	FA83	FA8000	—	—
D29641AA	CS750	FA83	FA8000	FA98	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
D31191AA	CS753	FA83	FA8000	FA86	—
D32211AA	CS750	FA83	FA8000	FA98	—
D32221A	CS750	FA83	FA8000	FA98	—
D32221AA	CS750	FA83	FA8000	FA79	—
D38060S	CS753	FA66	FA67	FA78	—
D38092S	CS753	FA66	FA67	FA78	—
D38223S	CS753	FA66	FA67	FA78	—
D38321A	—	—	FA89	FA87	—
D38551S	CS753	FA66	FA67	FA78	—
D38592S	CS753	FA66	FA67	FA78	—
D38757S	CS753	FA66	FA67	FA78	—
D38771S	CS753	FA66	FA67	FA78	—
D39581A	CS750	FA83	FA8000	FA98	—
D42421A	CS753	FA83	FA8000	FA86	—
D42921A	CS753	FA83	FA8000	—	—

HONDA

Unit No	Contact Assembly	Condenser	Rotor	Cap
30100634671 ..	CS351	EP300	EP312	EP718
30100634672 ..	CS351	EP300	EP312	EP718
30100634673 ..	CS351	EP300	EP312	EP718
30100634674 ..	CS351	EP300	EP312	EP718
30100634675 ..	CS351	EP300	EP312	EP718
30100634676 ..	CS351	EP300	EP312	EP718
30100634771 ..	CS351	EP300	EP312	EP718
30100634772 ..	CS351	EP300	EP312	EP718
30100634773 ..	CS351	EP300	EP312	EP718
30100634774 ..	CS351	EP300	EP312	EP718
30100634775 ..	CS351	EP300	EP312	EP718
30100639671 ..	CS351	EP300	EP312	EP718
30100639672 ..	CS351	EP300	EP312	EP718
30100657671 ..	CS351	EP300	EP312	EP718
30100657672 ..	CS351	EP300	EP312	EP718
30100657673 ..	CS351	EP300	EP312	EP718

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
30100657674 ..	CS351	EP300	EP312	EP718
30100657771 ..	CS351	EP344	EP345	EP346
30100657772 ..	CS351	EP344	EP345	EP346
30100657773 ..	CS351	EP300	EP312	EP718
30100657781 ..	CS351	EP300	EP312	EP718
30100657791 ..	CS351	EP300	EP312	EP718
30100657792 ..	CS351	EP300	EP312	EP718
30100657811 ..	CS351	EP300	EP312	EP718
30100657812 ..	CS351	EP300	EP312	EP718
30100663771 ..	CS351	EP300	EP312	EP718
30100663772 ..	CS351	EP300	EP312	EP718
30100663791 ..	CS351	EP300	EP312	EP718
30100663811 ..	CS351	EP300	EP312	EP718
30100671771 ..	CS351	EP300	EP312	EP718

I.H.C.

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
H4	CS1601	IH201	IH301	IH351	—
J4	CS1600	IH200	—	IH350	—
68830C91	CS729A	—	—	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
107573C91	CS729A	—	—	—	—
133879R91	CS750	FA76	FA81	FA78	—
133880R91	CS750	FA76	FA81	FA78	—

(continued on next page)

I.H.C. (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control	Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
133881R91	CS750	FA76	FA81	FA78	—	324472C91	CS753	FA83	FA8000	FA86	—
133888R91	CS750	FA76	—	FA78	—	329280C91	CS750	FA83	FA8000	FA98	—
148522R91	CS750	FA76	—	FA78	—	337277C91	CS750	FA83	FA8000	FA98	—
148523R91	CS750	FA76	—	FA78	—	337279C91	CS753	FA83	FA8000	—	—
148524R91	CS750	FA76	—	FA78	—	337281C91	CS750	FA83	FA8000	FA98	—
171582R91	CS750	FA76	—	FA78	—	337282C91	CS750	FA83	FA8000	FA98	—
171592R91	CS750	FA76	FA81	FA78	—	337285C91	CS750	FA83	FA8000	FA98	—
171593R91	CS750	FA76	—	FA78	—	337286C91	CS757P	FA66	FA8000	FA98	—
171594R91	CS750	FA76	—	FA78	—	337288C91	CS750	FA83	FA8000	FA98	—
171595R91	CS750	FA76	—	FA78	—	337291C91	CS757P	FA66	FA8000	FA98	—
215267R91	CS207A	EP29	—	EP40	—	337294C91	CS750	FA83	FA8000	FA98	—
262019C91	CS750	FA83	FA8000	FA98	—	337297C91	CS753	FA83	FA8000	FA98	—
262020C91	CS750	FA83	FA8000	FA98	—	337298C91	CS750	FA83	FA8000	FA98	—
268437C91	CS750	FA83	FA8000	FA98	—	337301C91	CS753	FA83	FA8000	FA98	—
280533C91	CS750	FA83	FA8000	FA98	—	337302C91	CS753	FA83	FA8000	FA98	—
281612C91	CS750	FA83	FA8000	FA98	—	337303C91	CS753	FA83	FA8000	FA98	—
285091C91	CS753	FA83	FA8000	FA98	—	337304C91	CS753	FA83	FA8000	FA98	—
285092C91	CS753	FA83	FA8000	FA98	—	338299C91	CS753	FA83	FA8000	FA98	—
285093C91	CS753	FA83	FA8000	FA98	—	338844C91	CS750	FA83	FA8000	FA98	—
285094C91	CS753	FA83	FA8000	FA98	—	338849C91	CS754	FA83	—	—	—
285095C91	CS753	FA83	FA8000	FA98	—	344203C91	CS753	FA83	FA8000	FA86	—
285096C91	CS753	FA83	FA8000	FA98	—	344730C91	CS753	FA83	FA8000	FA86	—
285097C91	CS753	FA83	FA8000	FA98	—	345476C91	CS753	FA83	FA8000	FA98	—
285098C91	CS753	FA83	FA8000	FA98	—	345477C91	CS753	FA83	FA8000	FA98	—
286437C91	CS753	FA83	FA8000	FA98	—	345478C91	CS753	FA83	FA8000	FA98	—
286684C91	CS750	FA83	FA8000	FA98	—	345497C91	CS753	FA83	FA8000	FA98	—
286685C91	CS750	FA83	FA8000	FA98	—	345746C91	CS753	FA83	FA8000	FA98	—
286686C91	CS750	FA83	FA8000	FA98	—	353148C91	CS757P	FA66	FA8000	FA98	—
286686C93	CS757P	FA66	FA8000	FA98	—	353892R91	CS1600	IH200	IH300	IH350	—
286686R91	CS750	FA83	FA8000	FA98	—	353893R91	CS1600	IH200	—	IH350	—
290043C91	CS753	FA83	FA8000	FA98	—	356657R91	CS1600	IH200	IH300	IH350	—
291259C92	CS750	FA83	FA8000	FA98	—	358381R91	CS1600	IH200	IH300	IH352	—
291259C94	CS757P	FA66	FA8000	FA98	—	358381R92	CS1600	IH200	IH300	IH352	—
291259R94	CS757P	FA66	FA8000	FA98	—	359206C91	CS757P	FA66	FA8000	FA98	—
291260C92	CS750	FA83	FA8000	FA98	—	359207C91	CS757P	FA66	FA8000	FA98	—
291260C94	CS757P	FA66	FA8000	FA98	—	359208C91	CS757P	FA66	FA8000	FA98	—
291260R94	CS757P	FA66	FA8000	FA98	—	359209C91	CS757P	FA66	FA8000	FA98	—
291261C91	CS750	FA83	FA8000	FA98	—	359210C91	CS757P	FA66	FA8000	FA98	—
291261C92	CS757P	FA66	FA8000	FA98	—	359211C91	CS757P	FA66	FA8000	FA98	—
291262C91	CS753	FA83	FA8000	FA98	—	359212C91	CS757P	FA66	FA8000	FA86	—
291262C92	CS757P	FA66	FA8000	FA98	—	359213C91	CS757P	FA66	FA8000	FA86	—
301573C91	CS753	FA83	FA8000	FA86	—	359214C91	CS757P	FA66	FA8000	FA86	—
301574C91	CS753	FA83	FA8000	FA86	—	359215C91	CS757P	FA66	FA8000	FA86	—
323418C91	CS750	FA83	FA8000	FA98	—	359216C91	CS757P	FA66	FA8000	FA86	—
323418C93	CS757P	FA66	FA8000	FA98	—	359217C91	CS757P	FA66	FA8000	FA98	—
323420C91	CS753	FA83	FA8000	FA98	—	359218C91	CS757P	FA66	FA8000	FA98	—
323421C91	CS753	FA83	FA8000	FA98	—	359219C91	CS757P	FA66	FA8000	FA98	—
324427C91	CS753	FA83	FA8000	FA86	—	359220C91	CS757P	FA66	FA8000	FA98	—

(continued on next column)

(continued on next page)

I.H.C. (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control	Unit No	Contact Assembly	Condenser	Rotor	Cap	Vac Control
359221C91	 CS757P	FA66	FA8000	FA98	—	427199C91	 CS757P	FA66	FA8000	FA98	—
359222C91	 CS757P	FA66	FA8000	FA98	—	427200C91	 CS757P	FA66	FA8000	FA98	—
359223C91	 CS757P	FA66	FA8000	FA98	—	427201C91	 CS757P	FA66	FA8000	FA98	—
359224C91	 CS757P	FA66	FA8000	FA98	—	427908C91	 CS757P	FA66	FA8000	FA98	—
359226C91	 CS757P	FA66	FA8000	FA98	—	427964C91	 CS757P	FA66	FA8000	FA98	—
359227C91	 CS757P	FA66	FA8000	FA98	—	427965C91	 CS757P	FA66	FA8000	FA98	—
359228C91	 CS757P	FA66	FA8000	FA98	—	427966C91	 CS757P	FA66	FA8000	FA98	—
359229C91	 CS757P	FA66	FA8000	FA98	—	427967C91	 CS757P	FA66	FA8000	FA98	—
359230C91	 CS757P	FA66	FA8000	FA98	—	428078C91	 CS757P	FA66	FA8000	FA98	—
359231C91	 CS757P	FA66	FA8000	FA98	—	428079C91	 CS757P	FA66	FA8000	FA98	—
359232C91	 CS757P	FA66	FA8000	FA98	—	428095C91	 CS757P	FA66	FA8000	FA98	FA157
359233C91	 CS757P	FA66	FA8000	FA98	—	428908C91	 CS757P	FA66	FA8000	FA98	—
359330C91	 CS757P	FA66	FA8000	FA98	—	433142C91	 CS757P	FA66	FA8000	FA98	—
360514C91	 CS757P	FA66	FA8000	FA98	—	436869C91	 CS757P	FA66	FA8000	FA98	—
360724C91	 CS757P	FA66	FA8000	FA86	—	436889C91	 CS757P	FA66	FA8000	FA98	—
361558C91	 CS757P	FA66	FA8000	FA98	—	448509C91	 CS757P	FA66	FA8000	FA98	—
364653R91	 CS1600	IH200	IH300	IH350	—	448510C91	 CS757P	FA66	FA8000	FA98	—
364696R92	 CS1600	IH200	IH300	IH350	—	448511C91	 CS757P	FA66	FA8000	FA98	—
366928R91	 CS1600	IH200	IH300	IH350	—	448512C91	 CS757P	FA66	FA8000	FA98	—
367839R91	 CS1600	IH200	IH300	IH352	—	461326C91	 CS757P	FA66	FA8000	FA98	—
367839R92	 CS1600	IH200	IH300	IH352	—	469620C91	 CS757P	FA66	FA8000	FA98	—
372867R92	 —	—	IH300	IH352	—	469620C92	 CS757P	FA66	FA8000	FA98	—
376555R92	 CS1603	IH200	IH300	IH350	—	470399C91	 CS757P	FA66	FA8000	FA98	—
379282C91	 CS757P	FA66	FA8000	FA98	—	484780C91	 CS730A	MO5000	AL163	AL162	—
380892R91	 CS1603	IH200	IH300	IH352	—	484781C91	 CS730A	MO5000	AL163	AL162	—
383143C91	 CS757P	FA66	FA8000	FA98	—	484795C91	 CS730A	MO5000	AL163	AL162	—
383148C91	 CS757P	FA66	FA8000	FA98	—	484799C91	 CS730A	MO5000	AL163	AL162	—
383149C91	 CS757P	FA66	FA8000	FA98	—	484824C91	 CS730A	MO5000	AL163	AL161	—
383150C91	 CS757P	FA66	FA8000	FA98	—	484830C91	 CS730A	MO5000	AL163	AL162	—
383151C91	 CS757P	FA66	FA8000	FA98	—	484831C91	 CS730A	MO5000	AL163	AL162	—
383177R91	 —	—	IH300	IH352	—	484834C91	 CS730A	MO5000	AL163	AL162	—
388592R91	 —	IH200	IH300	IH352	—	484835C91	 CS730A	MO5000	AL163	AL162	—
398157R91	 CS1603	IH200	IH300	IH352	—	484836C91	 CS730A	MO5000	AL163	AL162	—
399597R91	 CS1603	IH200	IH300	IH352	—	484999C91	 CS730A	MO5000	AL163	AL162	—
401030C91	 CS757P	FA66	FA8000	FA98	—	487830C91	 CS730A	MO5000	AL163	AL162	—
401031C91	 CS757P	FA66	FA8000	FA98	—	487877C91	 CS730A	MO5000	AL163	AL162	—
401032C91	 CS757P	FA66	FA8000	FA98	—	491357C91	 CS730A	MO5000	AL163	AL162	—
401033C91	 CS757P	FA66	FA8000	FA98	—	500142C91	 CS730A	MO5000	AL163	AL162	—
401034C91	 CS757P	FA66	FA8000	FA98	—	500159C91	 CS730A	MO5000	AL163	AL162	—
401035C91	 CS757P	FA66	FA8000	FA98	—	500160C91	 CS730A	MO5000	AL163	AL162	—
401170R91	 CS1603	IH200	IH300	IH352	—	873638R91	 CS750 ⁹	FA76	FA8000	FA98	—
404967R92	 CS729A	—	AL150	—	—	873639R91	 CS750 ⁹	FA76	FA8000	FA98	—
408129C91	 CS757P	FA66	FA8000	FA98	—	877337R91	 CS750 ⁹	FA76	FA8000	FA98	—
408130C91	 CS757P	FA66	FA8000	FA98	—	949822C91	 CS753	FA83	FA8000	FA86	—
413317C91	 CS757P	FA66	FA8000	FA98	—						
413377C91	 CS757P	FA66	FA8000	FA98	—						

(continued on next column)

⁹ Two required

LUCAS

Unit No	Contact Assembly	Condenser	Rotor	Cap
45D4	CS208	—	EP62	EP61
4049A	CS207A	EP29	EP41	—
4049B	CS207A	EP29	EP41	—
4073A	CS207A	EP29	EP41	—
4083A	CS207A	EP29	EP41	—
4109D	CS201	—	—	—
4112A	CS201	—	—	—
4147A	CS207A	EP29	EP41	EP39
4185A	—	—	EP173	—
4267A	—	—	EP173	—
40033J	CS201	EP22	—	—
40048	CS201	—	EP41	—
40050	CS201	—	—	—
40050J	CS201	—	—	—
40056	CS201	—	EP41	—
40056J	CS201	—	EP41	—
40058F	CS201	—	EP41	—
40069H	CS201	—	—	—
40070	CS201	—	—	—
40070E	CS201	—	—	—
40081	CS201	—	—	—
40081F	CS201	—	—	—
40089	CS201	—	—	—
40089E	CS201	—	EP41	—
40093	CS201	EP22	EP44	—
40109D	CS201	EP22	—	—
40112A	CS201	EP22	—	—
40114	CS201	EP22	—	—
40116J	CS201	EP22	—	—
40117H	CS201	—	EP41	—
40121H	CS201	EP22	EP41	—
40125	CS201	EP22	—	—
40125E	CS201	EP22	—	—
40125F	CS201	EP22	—	—
40129F	CS201	—	EP41	—
40135H	CS201	EP22	—	—
40137H	CS201	EP22	—	—
40141	CS201	—	EP41	—
40141F	CS201	—	EP41	—
40142F	CS201	—	EP41	—
40143	CS201	EP22	—	—
40143F	CS201	EP22	—	—
40147	CS201	EP22	EP44	—
40147H	CS201	EP22	—	—
40148F	CS201	—	—	—
40149	CS201	EP22	—	—
40149F	CS201	EP22	—	—
40151F	CS201	—	EP41	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
40152	CS201	—	EP41	—
40154D	CS201	EP22	—	—
40155	CS201	EP22	EP44	—
40156F	CS201	EP22	—	—
40157D	CS201	EP22	—	—
40158D	CS201	EP22	—	—
40161F	CS201	EP22	—	—
40162	CS201	—	EP41	—
40162E	CS201	—	EP41	—
40165E	CS201	EP22	—	—
40166B	CS201	EP22	—	—
40167	CS201	—	EP41	—
40167H	CS201	—	EP41	—
40168B	CS201	—	—	—
40172F	CS201	EP22	—	—
40175F	CS201	EP22	—	—
40179D	CS201	EP22	—	—
40181B	CS201	EP22	—	—
40182E	CS201	—	—	—
40192	CS201	—	—	—
40192D	CS201	—	—	—
40198D	CS201	EP22	—	—
40199	CS201	EP22	EP44	—
40199E	CS201	EP22	—	—
40200	CS201	EP22	EP44	—
40200D	CS201	EP22	—	—
40201	CS201	EP22	—	—
40201B	CS201	EP22	—	—
40206E	CS201	—	—	—
40207E	CS201	EP22	—	—
40210B	CS201	EP22	—	—
40215E	CS201	EP22	—	—
40216B	CS201	EP22	—	—
40217	CS201	—	—	—
40217E	CS201	EP22	—	—
40218D	CS201	—	—	—
40228D	CS201	EP22	—	—
40230E	CS201	EP22	—	—
40232	CS201	—	EP41	—
40232B	CS201	—	EP41	—
40235A	CS201	EP22	—	—
40236D	CS201	—	—	—
40237	CS201	—	EP41	—
40237B	CS201	—	EP41	—
40239B	CS201	EP22	—	—
40241B	—	—	EP41	—
40243	CS201	—	—	—
40244	CS207A	EP29	EP41	—

(continued on next page)

LUCAS (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
40244A	CS206	EP29	EP41	—
40244F	CS206	EP29	EP41	—
40245D	CS206	EP29	—	—
40249	CS201	EP22	EP44	—
40249B	CS201	EP22	—	—
40251	CS201	—	EP41	—
40251F	CS201	—	EP41	—
40252	CS206	EP29	EP44	—
40252B	—	—	EP44	—
40257D	CS201	—	EP41	—
40258B	CS201	—	EP41	—
40262D	CS201	—	EP41	—
40263B	CS201	EP22	—	—
40264	CS201	EP22	—	—
40264B	CS201	EP22	—	—
40268	CS206	EP29	EP44	—
40269B	CS201	—	EP41	—
40270D	CS201	—	EP41	—
40276B	CS201	EP22	—	—
40277D	CS201	—	EP41	—
40278D	CS201	EP22	—	—
40280B	CS201	EP22	—	—
40283	—	EP29	EP44	—
40283D	—	EP29	—	—
40284	CS201	EP29	EP41	EP39
40284E	CS201	EP29	EP41	EP39
40286A	CS206	—	EP41	—
40289E	CS206	EP29	EP41	—
40290E	—	EP29	—	—
40293	CS201	EP22	EP44	—
40293A	CS201	EP22	—	—
40294B	CS201	EP22	—	—
40295E	CS206	EP29	EP41	—
40297D	CS201	EP22	—	—
40299	CS206	EP29	EP41	EP39
40299E	CS206	EP29	EP41	EP39
40299L	CS206	EP29	EP41	EP39
40301D	CS201	EP22	—	—
40305D	—	EP29	—	—
40307B	—	EP29	—	—
40307E	CS206	—	—	—
40308	CS206	EP29	EP44	—
40308B	—	EP29	—	—
40308D	CS206	EP29	—	—
40308F	CS206	EP29	EP44	—
40308H	CS206	EP29	EP44	—
40310A	—	EP29	—	—
40311D	—	EP29	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
40312F	—	EP29	—	—
40312H	CS206	EP29	—	—
40317A	CS206	EP29	EP41	EP39
40319A	CS206	EP29	EP41	EP39
40320	—	—	EP41	—
40320B	—	—	EP41	—
40321	CS206	EP29	EP41	—
40321F	CS206	EP29	EP41	—
40327	CS206	EP29	EP44	—
40327A	—	EP29	—	—
40327B	CS206	EP29	—	—
40327D	CS206	EP29	—	—
40327F	CS206	EP29	—	—
40330E	CS206	EP29	EP41	EP39
40332A	CS206	EP29	—	EP39
40333	—	—	EP41	—
40336A	CS206	EP29	EP41	—
40337D	CS206	EP29	EP41	—
40345	CS201	EP22	—	—
40345A	CS201	EP22	—	—
40346	CS201	EP22	—	—
40346A	—	EP22	—	—
40347A	CS201	EP29	EP41	—
40354A	—	EP29	—	—
40355A	CS206	EP29	EP41	—
40356A	—	—	EP41	—
40357A	—	EP22	—	—
40358	CS201	—	EP41	—
40358A	—	—	EP41	—
40358E	CS201	—	EP41	—
40359	CS206	EP29	EP44	—
40359A	—	—	EP44	—
40359E	CS206	EP29	EP44	—
40359F	CS206	EP29	EP44	—
40360	CS206	EP29	EP44	—
40360A	CS206	EP29	EP44	—
40360D	CS206	EP29	—	—
40360E	CS206	EP29	EP44	—
40363	CS206	EP29	EP41	—
40363A	CS206	EP29	EP41	—
40364A	—	EP29	—	—
40365	CS206	EP29	EP41	—
40365A	CS206	EP29	EP41	—
40366A	—	EP29	—	—
40367	CS201	—	EP41	—
40367A	—	—	EP41	—
40367E	CS201	—	EP41	—
40368	CS201	—	EP41	—

(continued on next page)

LUCAS (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
40368A	—	—	EP41	—
40369A	—	—	EP41	—
40371	CS206	EP29	EP44	—
40371A	CS206	EP29	EP44	—
40371E	CS206	EP29	EP44	—
40372	CS201	EP22	—	—
40372A	CS201	EP22	—	—
40375A	—	EP22	—	—
40376	CS206	EP29	—	—
40376A	CS206	EP29	—	—
40376B	CS206	EP29	—	—
40377	CS206	EP29	—	EP39
40377A	CS206	EP29	—	EP39
40380	CS206	EP29	—	EP39
40386	CS206	EP29	EP41	EP39
40386A	CS206	EP29	EP41	EP39
40392	CS206	EP29	EP44	—
40396	CS206	EP29	—	EP39
40401B	CS206	EP29	—	—
40402	CS201	—	EP41	—
40403	CS206	EP29	EP41	EP39
40403A	CS206	EP29	EP41	EP39
40404	CS206	EP29	EP44	—
40405	CS206	EP29	EP44	—
40407A	CS207A	EP29	EP41	EP39
40408	CS206	EP29	EP44	—
40408E	CS206	EP29	—	—
40410	CS206	EP29	—	—
40410B	CS206	EP29	—	—
40410D	CS206	EP29	—	—
40411	CS201	EP22	—	—
40414	—	—	EP41	—
40415A	CS206	EP29	EP41	EP39
40422A	CS206	EP29	EP41	—
40423	CS206	EP29	—	—
40424	CS206	EP29	—	—
40425B	CS206	EP29	—	EP39
40427	CS207A	EP29	EP41	EP40
40427D	CS206	EP29	EP41	EP39
40427F	CS206	EP29	EP41	EP39
40428	CS206	EP29	—	EP39
40430	CS206	EP29	—	EP39
40431	CS206	EP29	—	—
40432	CS206	EP29	EP44	—
40435	CS201	EP22	—	—
40436	CS201	EP22	—	—
40442	—	—	EP44	—
40444D	—	EP29	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
40445	CS201	EP22	—	—
40459	CS206	EP29	EP44	—
40462	CS201	EP22	—	—
40464	CS206	EP29	EP44	—
40467	CS206	EP29	EP44	—
40470	CS206	EP29	—	—
40470A	CS206	EP29	EP44	—
40471	CS206	EP29	—	—
40471A	CS206	EP29	EP44	—
40472	CS206	EP29	EP44	—
40472A	CS206	EP29	EP44	—
40472B	—	—	EP44	—
40473	CS201	EP22	—	—
40476	CS206	EP29	EP44	—
40476A	CS206	EP29	EP44	—
40477	CS207A	EP29	EP41	—
40477A	CS207A	EP29	EP41	—
40477D	CS207A	EP29	EP41	—
40478	CS207A	EP29	EP41	EP39
40478A	CS207A	EP29	EP41	EP39
40479	CS207A	EP29	EP41	—
40479A	CS207A	EP29	EP41	—
40480	CS207A	EP29	EP41	EP39
40480A	CS207A	EP29	EP41	EP39
40480D	CS207A	EP29	EP41	EP39
40484	CS201	EP22	—	—
40484A	CS201	EP22	—	—
40485	CS206	EP29	EP44	—
40485A	CS206	EP29	EP44	—
40489	CS201	EP22	—	—
40490	CS207A	EP29	EP41	EP39
40490A	CS207A	EP29	EP41	EP39
40490B	CS207A	EP29	EP41	EP39
40491A	CS207A	EP29	—	EP39
40491B	CS207A	EP29	—	EP39
40492	CS207A	EP29	—	EP39
40492A	CS207A	EP29	—	EP39
40492B	CS207A	EP29	—	EP39
40493	CS206	EP29	—	—
40494	CS207A	EP29	EP41	EP39
40494A	CS207A	EP29	EP41	EP39
40494B	CS207A	EP29	EP41	EP40
40494D	CS207A	EP29	EP41	EP40
40495	CS207A	EP29	EP41	—
40495A	CS207A	EP29	EP41	EP149
40496	CS207A	EP29	EP41	—
40496A	CS207A	EP29	EP41	EP149
40496B	CS207A	EP29	EP41	EP149

(continued on next page)

LUCAS (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
40497	CS206	EP29	EP41	EP39
40498A	CS206	EP29	EP41	EP39
40499	CS207A	EP29	EP41	EP40
40499D	CS207A	EP29	EP41	EP40
40500	CS207A	EP29	EP41	—
40503	CS207A	EP29	EP41	EP39
40503A	CS207A	EP29	EP41	EP39
40504	CS207A	EP29	EP41	EP39
40504A	CS207A	EP29	EP41	EP39
40504B	CS207A	EP29	EP41	EP39
40509	CS207A	EP29	EP41	EP40
40509A	CS207A	EP29	EP41	EP39
40510	CS207A	EP29	EP41	EP40
40512	CS207A	EP29	EP41	—
40513	CS206	EP29	EP44	—
40514	CS206	EP29	EP44	—
40515	CS207A	EP29	—	EP39
40518	CS206	EP29	—	—
40519	CS206	EP29	—	—
40520	CS207A	EP29	—	—
40520A	CS207A	EP29	EP41	—
40523	CS206	EP29	EP44	—
40524	CS206	EP29	EP44	—
40524A	CS206	EP29	EP44	—
40526	CS207A	EP29	—	—
40527	CS207A	EP29	EP41	—
40528	CS206	EP29	EP44	—
40528B	CS206	EP29	EP44	—
40530	CS207A	EP29	EP41	EP39
40531	CS206	EP29	EP44	—
40531A	CS206	EP29	EP44	—
40532	CS206	EP29	EP44	—
40539	CS207A	EP29	EP41	—
40542	CS207A	EP29	EP41	EP39
40543	CS206	EP29	EP41	—
40544F	CS207A	EP29	EP41	—
40546	CS206	EP29	EP44	—
40548	CS207A	EP29	EP41	EP39
40551	—	EP22	—	—
40551B	CS201	—	—	—
40552	CS207A	EP29	EP41	EP39
40552A	CS207A	EP29	EP41	EP39
40552B	CS207A	EP29	EP41	EP39
40554	CS206	EP29	—	—
40555	CS206	EP29	—	—
40557	CS206	EP29	EP44	—
40557A	CS206	EP29	EP44	—
40559	CS207A	EP29	EP41	EP39

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
40559A	CS207A	EP29	EP41	—
40559E	CS207A	EP29	EP41	—
40560	CS207A	EP29	EP41	EP40
40561	CS207A	EP29	EP41	EP40
40561D	CS207A	EP29	EP41	EP39
40561E	CS207A	EP29	EP41	EP40
40561F	CS207A	EP29	EP41	EP40
40561H	CS207A	EP29	EP41	EP40
40562	CS201	—	EP41	—
40564	CS201	—	EP41	—
40564A	CS201	—	EP41	—
40564D	CS201	—	EP41	—
40566	CS201	EP22	—	—
40569	CS207A	EP29	EP41	EP40
40569D	CS207A	EP29	EP41	EP40
40569F	CS207A	EP29	EP41	EP40
40569K	CS207A	EP29	EP41	EP40
40570	CS207A	EP29	EP41	EP40
40570B	CS207A	EP29	EP41	EP40
40570D	CS207A	EP29	EP41	EP40
40576	CS206	EP29	EP44	—
40576B	CS206	EP29	EP44	—
40576D	CS206	EP29	EP44	—
40577	CS206	EP29	EP44	—
40577B	CS206	EP29	EP44	—
40578	CS206	EP29	EP44	—
40578A	CS206	EP29	EP44	—
40578B	CS206	EP29	EP44	—
40578D	CS206	EP29	EP44	—
40579A	CS201	—	EP41	—
40580	CS206	EP29	EP44	—
40580A	CS206	EP29	EP44	—
40581	CS206	EP29	EP44	—
40581A	CS206	EP29	EP44	—
40582A	CS201	—	EP41	—
40583A	CS207A	EP29	EP41	—
40583B	CS207A	EP29	EP41	—
40583D	CS207A	EP29	EP41	—
40583E	CS207A	EP29	EP41	EP149
40583J	CS207A	EP29	EP41	EP149
40586	CS201	—	—	—
40587	CS207A	EP29	EP41	EP40
40587A	CS207A	—	EP41	EP39
40587B	CS207A	EP29	EP41	EP40
40587D	CS207A	EP29	EP41	EP40
40588	CS207A	EP29	EP41	—
40588A	CS207A	EP29	EP41	—
40588D	CS207A	EP29	EP41	EP149

(continued on next page)

LUCAS (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
40589	CS201	—	—	—
40593	CS207A	EP29	EP41	EP39
40593E	CS207A	EP29	EP41	—
40598	CS207A	EP29	EP41	EP39
40598B	CS207A	EP29	EP41	—
40600	CS207A	EP29	EP41	EP40
40600A	CS207A	EP29	EP41	EP40
40600B	CS207A	EP29	EP41	EP40
40600D	CS207A	EP29	EP41	EP40
40601	CS206	EP29	EP44	—
40606	CS207A	EP29	EP41	EP39
40606D	CS207A	EP29	EP41	—
40606E	CS207A	EP29	EP41	—
40607	CS207A	EP29	EP41	EP39
40608	CS206	EP29	EP44	—
40609	CS207A	EP29	EP41	—
40609B	CS207A	EP29	EP41	—
40609E	CS207A	EP29	EP41	—
40609F	CS207A	EP29	EP41	EP149
40611	CS207A	EP29	EP41	EP39
40611B	CS207A	EP29	EP41	—
40613	CS206	EP29	EP44	—
40613A	CS206	EP29	EP44	—
40613B	CS206	EP29	EP44	—
40614	—	—	EP44	—
40616	—	—	EP44	—
40616A	CS206	EP29	EP44	—
40616B	CS206	EP29	EP44	—
40617	CS206	EP29	EP44	—
40617A	CS206	EP29	EP44	—
40617B	CS206	EP29	EP44	—
40617D	CS206	EP29	EP44	—
40620A	CS206	EP29	EP41	EP39
40622	CS207A	EP29	EP41	EP39
40622B	CS207A	EP29	EP41	EP39
40622D	CS207A	EP29	EP41	—
40623	CS207A	EP29	EP41	EP39
40624	CS207A	EP29	EP41	EP39
40624A	CS207A	EP29	EP41	EP40
40624B	CS207A	EP29	EP41	EP40
40624D	CS207A	EP29	EP41	EP40
40624H	CS207A	EP29	EP41	EP40
40631	CS207A	EP29	EP41	EP149
40635A	CS206	EP29	EP44	—
40637	CS207A	EP29	EP41	EP39
40638	CS207A	EP29	EP41	EP39
40638A	CS207A	EP29	EP41	EP39
40640	CS206	EP29	EP44	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
40640A	CS206	EP29	EP44	—
40640D	CS206	EP29	EP44	—
40643	CS207A	EP29	EP41	EP40
40643A	CS207A	EP29	EP41	EP40
40643B	CS207A	EP29	EP41	EP40
40643D	CS207A	EP29	EP41	EP40
40644	CS207A	EP29	—	EP40
40644A	CS207A	EP29	EP41	EP40
40644B	CS207A	EP29	EP41	EP40
40644D	CS207A	EP29	EP41	EP40
40647B	CS207A	EP29	EP41	—
40647D	CS207A	EP29	EP41	—
40648	CS207A	EP29	EP41	EP40
40648A	CS207A	EP29	EP41	EP40
40648B	CS207A	EP29	EP41	EP40
40649	CS206	EP29	—	—
40649A	—	—	—	EP149
40649B	—	—	—	EP149
40650D	—	—	EP44	—
40652	CS207A	EP29	EP41	—
40653B	CS207A	EP29	EP41	—
40653E	CS207A	EP29	EP41	—
40656	CS207A	EP29	EP41	EP40
40656A	CS207A	EP29	EP41	EP40
40656F	CS207A	EP29	EP41	EP40
40658D	CS207A	EP29	EP41	—
40658F	CS207A	EP29	EP41	—
40660	CS206	EP29	EP44	—
40661	CS206	EP29	EP44	—
40662	CS206	EP29	EP44	—
40662A	CS206	EP29	EP44	—
40662D	CS206	EP29	EP44	—
40665	CS206	EP29	EP44	—
40665B	CS206	EP29	EP44	—
40667A	CS207A	EP29	—	EP39
40670A	—	—	EP44	—
40673F	CS207A	EP29	EP39	EP41
40674	CS207A	EP29	EP41	EP40
40675A	CS207A	EP29	EP41	EP40
40675B	CS207A	EP29	EP41	EP40
40681	CS207A	EP29	EP41	—
40681A	CS207A	EP29	EP41	EP39
40682	CS207A	EP29	EP41	—
40682A	CS207A	EP29	EP41	EP39
40683	CS207A	EP29	EP41	—
40683A	CS207A	EP29	EP41	EP39
40685A	CS206	EP29	EP44	—
40687	CS207A	EP29	EP41	EP39

(continued on next page)

LUCAS (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
40687A	CS207A	EP29	EP41	EP39
40688A	—	—	EP41	—
40691A	CS207A	EP29	EP41	—
40692	CS207A	EP29	EP41	EP40
40698	CS207A	EP29	EP41	EP39
40698B	CS207A	EP29	EP41	—
40705A	CS207A	EP29	EP41	EP149
40706A	CS301	—	EP41	—
40707A	CS207A	EP29	EP41	EP40
40707D	CS207A	EP29	EP41	EP40
40708	CS207A	EP29	EP41	EP149
40709A	CS207A	EP29	EP41	EP149
40709B	CS207A	EP29	EP41	EP149
40719A	—	—	EP44	—
40720	—	—	EP44	—
40721A	—	—	EP44	—
40723	CS207A	EP29	—	EP149
40724	CS207A	EP29	—	EP149
40726	CS207A	EP29	—	—
40730	—	—	EP44	—
40731	—	—	EP44	—
40734	CS207A	EP29	EP41	—
40735	CS207A	EP29	EP41	EP39
40736A	CS207A	EP29	EP41	EP149
40743	CS207A	EP29	EP41	EP39
40744	CS207A	EP29	EP41	EP149
40750	—	—	EP44	—
40752	CS207A	EP29	EP41	EP39
40755	CS207A	EP29	EP41	—
40766	CS207A	EP29	EP41	—
40766A	CS207A	EP29	EP41	—
40767	CS207A	EP29	EP41	EP40
40767A	CS207A	EP29	EP41	EP40
40768	CS207A	EP29	EP41	EP40
40768A	CS207A	EP29	EP41	EP40
40769	CS207A	EP29	EP41	EP40
40770	CS207A	EP29	EP41	—
40773A	CS207A	EP29	EP41	—
40774	CS207A	EP29	EP41	EP40
40775	CS207A	EP29	EP41	EP40
40776A	CS207A	EP29	EP41	EP40
40778A	CS207A	EP29	EP41	EP40
40781	CS207A	EP29	EP41	EP40
40781B	CS207A	EP29	EP41	EP40
40782	CS207A	EP29	EP41	EP40
40783A	CS207A	EP29	EP41	—
40785	CS207A	EP29	EP41	—
40785D	CS207A	EP29	EP41	EP149

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
40785E	CS207A	EP29	EP41	EP149
40786	CS207A	EP29	EP41	—
40787	CS207A	EP29	EP41	—
40788A	CS207A	EP29	EP41	EP39
40790	CS207A	EP29	EP41	EP39
40791	CS207A	EP29	EP41	EP39
40794	CS207A	EP29	EP41	—
40795	CS207A	EP29	EP41	EP39
40795A	CS207A	EP29	EP41	EP39
40797	CS207A	EP29	EP41	—
40798A	CS207A	EP29	EP41	—
40798B	CS207A	EP29	EP41	—
40799	CS207A	EP29	EP41	—
40799A	CS207A	EP29	EP41	—
40799B	CS207A	EP29	EP41	—
40800	CS207A	EP29	—	EP149
40801	CS207A	EP29	—	EP149
40802	CS207A	EP29	—	—
40810D	CS207A	EP29	EP41	EP149
40811	CS207A	EP29	EP41	EP149
40812	CS207A	EP29	EP41	EP149
40813	CS207A	EP29	EP41	EP149
40814	CS207A	EP29	EP41	EP40
40817A	CS207A	EP29	EP41	—
40819	CS207A	EP29	EP41	EP40
40819H	CS207A	EP29	EP41	EP40
40821	CS207A	EP29	EP41	EP40
40822	CS207A	EP29	EP41	EP40
40822B	CS207A	EP29	EP41	EP40
40823	CS207A	EP29	EP41	EP40
40823A	CS207A	EP29	EP41	EP40
40826	CS207A	EP29	EP44	—
40827	CS207A	EP29	EP44	—
40840	CS207A	EP29	EP44	—
40841A	CS207A	EP29	EP44	—
40841B	CS207A	EP29	EP44	—
40842A	CS207A	EP29	EP44	—
40845	CS207A	EP29	EP44	—
40847	CS207A	EP29	EP41	EP39
40849	CS207A	EP29	EP41	EP40
40850	CS207A	EP29	EP41	—
40851	CS207A	EP29	EP41	EP149
40852	CS207A	EP29	EP41	EP149
40853	CS207A	EP29	EP41	EP40
40853A	CS207A	EP29	EP41	EP40
40854	CS207A	EP29	EP41	EP40
40855	CS207A	EP29	EP41	EP40
40855B	CS207A	EP29	EP41	EP40

(continued on next page)

LUCAS (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
40856	CS207A	EP29	EP41	—
40857	CS207A	EP29	EP41	—
40865D	CS207A	EP29	EP44	—
40866	CS207A	EP29	EP44	—
40866A	CS207A	EP29	EP44	—
40873	CS207A	EP29	EP41	EP40
40882	CS207A	EP29	EP44	—
40883	CS207A	EP29	EP44	—
40884	CS207A	EP29	EP44	—
40885	CS207A	EP29	EP44	—
40886	CS207A	EP29	EP44	—
40887	CS207A	EP29	EP44	—
40888	CS207A	EP29	EP44	—
40891	CS207A	EP29	EP44	—
40892	CS207A	EP29	EP41	EP149
40893	CS207A	EP29	EP41	EP149
40894	CS207A	EP29	EP44	—
40895	CS207A	EP29	EP44	—
40895A	CS207A	EP29	EP44	—
40896	CS207A	EP29	EP44	—
40896A	CS207A	EP29	EP44	—
40897	CS207A	EP29	EP41	EP40
40897A	CS207A	EP29	EP41	EP40
40899B	CS207A	EP29	EP41	EP40
40900	CS207A	EP29	EP44	—
40901	CS207A	EP29	EP44	—
40901A	CS207A	EP29	EP44	—
40902	CS207A	EP29	EP41	EP39
40903	CS207A	EP29	EP41	EP149
40904	CS207A	EP29	EP44	—
40905	CS207A	EP29	EP41	EP40
40915B	CS207A	EP29	EP41	EP40
40916	CS207A	EP29	EP41	EP40
40919	CS207A	EP29	EP41	EP40
40919A	CS207A	EP29	EP41	EP40
40920	CS207A	EP29	EP44	—
40920A	CS207A	EP29	EP44	EP40
40920B	CS207A	EP29	EP44	EP40
40921	CS207A	EP29	EP44	—
40921B	CS207A	EP29	EP44	—
40922	CS207A	EP29	EP44	—
40923	CS207A	EP29	EP44	—
40924	CS207A	EP29	EP41	—
40927	CS207A	EP29	EP41	—
40931	CS207A	EP29	EP41	EP40
40933	CS207A	EP29	EP41	—
40934	CS207A	EP29	EP41	—
40935	CS207A	EP29	EP41	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
40942	CS207A	EP29	EP41	—
40944	CS207A	EP29	EP41	—
40949	CS207A	EP29	—	—
40950A	CS207A	EP29	EP44	—
40953	CS207A	EP29	—	EP40
40955	CS207A	EP29	EP41	EP40
40958	CS207A	EP29	EP41	EP40
40961	CS207A	EP29	EP44	—
40966	CS207A	EP29	EP44	—
40967	CS207A	EP29	EP44	—
40968	CS207A	EP29	EP41	EP40
40969	CS207A	EP29	EP41	EP40
40970	CS207A	EP29	EP41	EP40
40975A	CS207A	EP29	EP44	—
40983	CS207A	EP29	EP41	EP48
40984	CS207A	EP29	EP41	EP48
40992	CS207A	EP29	EP41	—
41025	CS207A	EP29	EP41	EP48
41026	CS207A	EP29	EP41	EP48
41036	CS207A	EP29	EP41	—
41039	CS207A	EP29	EP41	EP40
41042	CS207A	EP29	EP41	EP48
41043	CS207A	EP29	EP41	EP48
41046	CS207A	EP29	—	EP48
41047	CS207A	EP29	—	EP48
41048	CS207A	EP29	—	EP48
41049	CS207A	EP29	EP44	EP55
41050	CS207A	EP29	EP44	EP55
41051	CS207A	EP29	EP44	—
41052	CS207A	EP29	EP44	—
41053	CS207A	EP29	EP44	—
41054	CS207A	EP29	EP44	—
41060	CS207A	EP29	EP44	—
41061	CS207A	EP29	EP44	—
41062	CS207A	EP29	EP44	—
41063	CS207A	EP29	EP44	—
41064	CS207A	EP29	EP44	—
41065	CS207A	EP29	—	—
41069	CS207A	EP29	—	—
41070	CS207A	EP29	—	—
41071	CS207A	EP29	—	—
41072	CS207A	EP29	—	—
41077	CS207A	EP29	EP41	EP48
41077A	CS207A	EP29	EP41	EP48
41083	CS207A	EP29	EP44	—
41085	CS207A	EP29	EP41	—
41086	CS207A	EP29	EP44	—
41087	CS207A	EP29	EP44	—

(continued on next page)

LUCAS (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Unit No	Contact Assembly	Condenser	Rotor	Cap
41119	CS207A	EP29	EP41	—	41228	CS207A	EP29	EP41	EP48
41122	CS207A	EP29	EP41	EP40	41229	CS207A	EP29	EP41	EP40
41124	CS207A	EP29	EP41	EP40	41231	CS207A	EP29	EP41	EP48
41125	CS207A	EP29	EP41	EP48	41237	CS207A	EP29	EP41	EP48
41127	CS207A	EP29	EP41	EP48	41240	CS207A	EP29	EP41	—
41128	CS207A	EP29	EP44	—	41242	CS207A	EP29	EP41	EP48
41129	CS207A	EP29	EP41	EP40	41247	CS207A	EP29	EP44	EP55
41132	CS207A	EP29	EP41	EP40	41249	CS207A	EP29	EP41	EP40
41134	CS207A	EP29	EP41	EP40	41264	CS207A	EP29	EP41	EP48
41141	CS207A	EP29	EP41	—	41264B	CS207A	EP29	EP41	EP48
41142	CS207A	EP29	EP41	EP40	41267	CS207A	EP29	EP41	EP48
41143	CS207A	EP29	EP44	—	41271	CS207A	EP29	EP41	EP40
41144	CS207A	EP29	EP44	—	41276	CS207A	EP29	EP71	EP78
41146	CS207A	EP29	EP41	EP48	41277	CS207A	EP29	EP71	EP78
41147	CS207A	EP29	EP41	EP48	41288	CS207A	EP29	EP41	EP48
41148	CS207A	EP29	EP41	EP48	41290	CS207A	EP29	EP41	EP48
41149	CS207A	EP29	EP41	EP48	41291	CS207A	EP29	EP41	EP48
41150	CS207A	EP29	EP41	EP48	41296	CS207A	EP29	EP44	—
41151	CS207A	EP29	EP41	EP48	41297	CS207A	EP29	—	—
41154	CS207A	EP29	EP41	EP48	41300	CS207A	EP29	EP71	—
41155	CS207A	EP29	EP41	EP48	41301	CS207A	EP29	EP41	EP48
41156	CS207A	EP29	EP41	EP48	41306	CS207A	EP29	EP44	EP55
41157	CS207A	EP29	EP41	EP48	41307	CS207A	EP29	EP41	EP48
41158	CS207A	EP29	EP41	EP48	41309	CS207A	EP29	EP41	EP48
41159	CS207A	EP29	EP41	EP48	41311	CS207A	EP29	EP71	EP78
41160	CS207A	EP29	EP41	EP48	41315	CS207A	EP29	EP41	EP48
41165A	CS207A	EP29	EP41	EP40	41316	CS207A	EP29	EP41	EP48
41166	CS207A	EP29	EP44	EP55	41319	CS207A	EP29	—	EP48
41166A	CS207A	EP29	EP44	—	41322	CS207A	EP29	EP41	—
41167	CS207A	EP29	EP44	—	41323	CS207A	EP29	—	—
41168	CS207A	EP29	EP44	EP55	41336	—	—	EP71	—
41168A	CS207A	EP29	EP44	—	41337	—	—	EP71	—
41170	CS207A	EP29	EP41	EP48	41339	CS207A	EP29	EP41	EP48
41181	CS207A	EP29	EP41	EP40	41340	CS207A	EP29	EP44	EP55
41182	CS207A	EP29	EP44	—	41346A	CS207A	EP29	EP41	EP149
41189	CS207A	—	—	EP40	41349A	CS207A	EP29	EP41	EP149
41199	CS207A	EP29	EP41	EP48	41352	CS207A	EP29	EP44	EP55
41200	CS207A	EP29	EP41	EP48	41353	CS207A	EP29	EP44	EP48
41201	CS207A	EP29	EP44	—	41355A	CS207A	EP29	EP41	EP149
41202	CS207A	EP29	EP44	EP55	41356A	CS207A	EP29	EP41	EP149
41207	CS207A	EP29	EP44	—	41359	—	—	EP71	—
41212	CS207A	EP29	EP41	—	41363	CS207A	EP29	EP41	EP48
41214	CS207A	EP29	EP41	EP48	41365	CS207A	EP29	EP41	EP48
41216	CS207A	EP29	EP41	EP48	41369	CS207A	EP29	EP41	EP40
41216A	CS207A	EP29	EP41	EP48	41370	CS207A	EP29	EP41	EP48
41220	CS207A	EP29	EP41	EP48	41371	CS207A	EP29	EP41	EP48
41224	CS207A	EP29	EP44	EP55	41373A	CS207A	EP29	EP41	EP48
41225	CS207A	EP29	—	EP40	41374A	CS207A	EP29	EP41	EP48

(continued on next column)

(continued on next page)

LUCAS (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
41379	—	—	EP71	—
41384	—	—	EP71	—
41385	CS207A	EP29	EP44	EP55
41388	CS207A	EP29	EP44	EP55
41395	CS207A	EP29	EP41	EP40
41397	—	—	EP71	—
41400	CS207A	EP29	EP41	EP40
41401	CS207A	EP29	EP41	EP48
41455	CS208	EP60	EP62	EP61
41455A	CS208	EP60	EP62	EP61
41455D	CS208	EP60	EP62	EP61
41455E	CS208	EP60	EP62	EP61
41455F	CS208	EP60	EP62	EP61
41456	CS207A	—	—	EP40
41456	CS208	EP60	EP62	EP61
41456A	CS208	EP60	EP62	EP61
41456D	CS208	EP60	EP62	EP61
41456E	CS208	—	EP62	EP61
41456F	CS208	—	EP62	EP61
41477	CS207A	EP29	EP41	EP39
41491	CS207A	EP29	EP41	EP48

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
41497	CS207A	EP29	—	EP48
41500	—	—	EP71	—
41521	CS207A	EP29	EP71	—
41523	CS207A	EP29	EP44	EP55
41527	CS207A	EP29	EP41	EP48
41530	—	—	EP71	—
41558	CS207A	EP29	EP44	EP55
41576	CS208	EP60	EP62	—
41581	CS207A	EP29	—	EP40
41584	CS207A	EP29	—	EP48
41599	CS208	EP60	EP62	—
41614	CS206	EP29	EP44	—
41616	CS206	EP29	EP44	—
41626	CS208	EP60	—	EP61
41634	CS207A	EP29	—	EP48
41644	CS208	EP60	EP62	EP61
407669	CS207A	EP29	EP41	EP40
409639	CS201	—	EP41	—
409641	CS201	—	—	—

MALLORY

Unit No	Contact Assembly	Condenser	Rotor	Cap
YC	CS2301	—	—	MA10
YC345A	CS2300	RR175	AL65	MA8
YC345B	CS2300	RR175	AL65	MA8
YD349A	CS2300	MA3	AL104	AL110
YD350A	CS2300	MA3	FA64	MA1
YD350AV	CS2300	MA3	FA64	MA1
YD356	CS2300	MA3	FA64	MA1
YD356A	CS2300	MA3	FA64	MA1
YD359C	CS2300	MA3	AL65	MA8
YD359D	CS2300	MA3	AL65	MA8
YD359E	CS2300	MA3	AL65	MA8
YD359F	CS2300	MA3	AL65	MA8
YD362A	CS2300	MA3	FA64	MA1
YD362B	CS2300	MA3	FA64	MA1
YD370A	CS2300	MA3	AL104	AL110
YD370B	CS2300	MA3	AL104	AL105
YD370C	CS2300	MA3	AL104	AL110
YD372A	CS2300	MA3	FA64	MA1
YD372B	CS2300	MA3	FA64	MA1
YD372C	CS2300	MA3	FA64	MA1
YD372D	CS2300	MA3	FA64	MA1

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
YD372F	CS2300	MA3	FA64	MA1
YD372F1	CS2300	MA3	FA64	MA1
YD372F2	CS2300	MA3	FA64	MA1
YD375A	CS2300	MA3	AL65	MA8
YD377A	CS2300	MA3	AL104	AL105
YD396A	CS2300	MA3	AL104	AL105
YD397A	CS2300	MA3	AL104	AL105
YD410A	CS2300	MA3	AL104	AL110
YD410C	CS2300	MA3	AL104	AL105
YD411A	CS2300	MA3	AL104	AL110
YD411B	CS2300	MA3	AL104	AL110
YD411C	CS2300	MA3	AL104	AL105
YD411D	CS2300	MA3	AL104	AL105
YD420A	CS2300	MA3	FA64	MA1
YD420B	CS2300	MA3	FA64	MA1
YD420C	CS2300	MA3	FA64	MA1
YD420D	CS2300	MA3	FA64	MA1
YD429A	CS2300	MA3	AL65	MA8
YD429B	CS2300	MA3	AL65	MA8
YD429C	CS2300	MA3	FA64	MA1
YD429D	CS2300	MA3	FA64	MA1

(continued on next page)

MALLORY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
YL350A	CS2300	MA3	AL65	MA8
YL356A	CS2300	MA3	FA64	MA1
YL356A1	CS2300	MA3	FA64	MA1
YL356A2	CS2300	MA3	FA64	MA1
YL356AV	CS2300	MA3	FA64	MA1
YL356AV2	CS2300	MA3	FA64	MA1
YL362A	CS2300	MA3	FA64	MA1
YL362AV	CS2300	MA3	FA64	MA1
YL362B	CS2300	MA3	FA64	MA1
YL362BV	CS2300	MA3	FA64	MA1
YL362C	CS2300	MA3	FA64	MA1
YL362CV	CS2300	MA3	FA64	MA1
YL362D	CS2300	MA3	FA64	MA1
YL362DV	CS2300	MA3	FA64	MA1
YL362F	CS2300	MA3	FA64	MA1
YL362G	CS2300	MA3	FA64	MA1
YL362H	CS2300	MA3	FA64	MA1
YL370A	CS2300	MA3	AL104	AL110
YL370B	CS2300	MA3	AL104	AL105
YL372C	CS2300	MA3	FA64	MA1
YL372D	CS2300	MA3	FA64	MA1
YL372E2	CS2300	MA3	FA64	MA1
YL387A	CS2300	MA3	AL65	MA8
YL411A	CS2300	MA3	AL104	AL110
YL411B	CS2300	MA3	AL104	AL110
YL411C	CS2300	MA3	AL104	AL105
YL411D	CS2300	MA3	AL104	AL105
YL414D	CS2300	MA3	AL104	AL105
YL414E	CS2300	MA3	AL104	AL105
YL414J	CS2300	MA3	AL104	AL105
YL414K	CS2300	MA3	AL104	AL105
YL420E	CS2300	MA3	FA64	MA1
YL429C	CS2300	MA3	FA64	MA1
YL429D	CS2300	MA3	FA64	MA1
YL431A	CS2300	MA3	FA64	MA1
YL436A	CS2300	MA3	AL104	AL105
YL436B	CS2300	MA3	AL104	AL105
YL445A	CS2300	MA3	FA64	MA1
YL445B	CS2300	MA3	FA64	MA1
YL445BO	CS2300	MA3	FA64	MA1
YL445JV	CS2300	MA3	FA64	MA1
YL445KV	CS2300	MA3	FA64	MA1
YL455A	CS2300	MA3	AL65	MA8
YL455B	CS2300	MA3	AL65	MA8
YL455BO	CS2300	MA3	FA64	MA1
YL457A	CS2300	MA3	FA64	MA1
YL457AV	CS2300	MA3	FA64	MA1
YL457BV	CS2300	MA3	FA64	MA1

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
YL457C	CS2300	MA3	FA64	MA1
YL457CV	CS2300	MA3	FA64	MA1
YL457DV	CS2300	MA3	FA64	MA1
YL458B	CS2300	MA3	AL65	MA8
YL459A	CS2300	MA3	FA64	MA1
YL461A	CS2300	MA3	AL65	MA8
YL461B	CS2300	MA3	AL65	MA8
YL461B2	CS2300	MA3	AL65	MA8
YL462	CS2300	MA3	AL65	MA8
YL467A	CS2300	MA3	AL65	MA8
YL469A	CS2300	MA3	FA64	MA1
YL474D	CS2300	MA3	AL104	AL105
YL474E	CS2300	MA3	AL104	AL105
YL481A	CS2300	MA3	AL104	AL105
YL481B	CS2300	MA3	AL104	AL105
YL486A	CS2300	MA3	AL104	AL105
YL486AV	CS2300	MA3	AL104	—
YL486B	CS2300	MA3	AL104	AL105
YL486BV	CS2300	MA3	AL104	—
YL486C	CS2300	MA3	AL104	AL110
YL486D	CS2300	MA3	AL104	AL110
YL487A	CS2300	MA3	AL65	MA8
YL487AV	CS2300	MA3	AL104	MA2
YL488D	CS751	—	—	—
YL488E	CS751	—	—	—
YL488J	CS751	—	—	—
YL488K	CS751	—	—	—
YL494A	CS2300	MA3	AL65	MA8
YL494A2	CS2300	MA3	AL65	MA8
YL494B	CS2300	MA3	AL65	MA2
YL494B2	CS2300	MA3	AL65	MA8
YL494BO	CS2300	MA3	AL65	MA8
YL495A	CS2300	MA3	AL104	AL105
YL495B	CS2300	MA3	AL104	AL105
YL496A	CS2300	MA3	FA64	MA1
YL496B	CS2300	MA3	FA64	MA1
YL501AV	CS2300	MA3	AL65	MA1
YL501CV	CS2300	MA3	AL65	MA1
YL501EV	CS2300	MA3	AL65	MA1
YL501GV	CS2300	MA3	AL65	MA1
YL502A	CS2300	MA3	FA64	MA1
YL502AV	CS2300	MA3	FA64	MA1
YL502B	CS2300	MA3	FA64	MA1
YL502BV	CS2300	MA3	FA64	MA1
YL512A	CS2300	MA3	AL65	MA8
YL512CV	CS2300	MA3	AL65	MA8
YL512DV	CS2300	MA3	AL65	MA8
YL513A	CS2300	MA3	AL65	MA8

(continued on next page)

MALLORY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
YL513B	CS2300	MA3	AL65	MA8
YL513CV	CS2300	MA3	AL65	MA8
YL513DV	CS2300	MA3	AL65	MA8
YL514A	CS2300	MA3	AL65	MA8
YL514B	CS2300	MA3	AL65	MA8
YL514C	CS2300	MA3	AL65	MA8
YL514D	CS2300	MA3	AL65	MA8
YL515A	CS2300	MA3	FA64	MA1
YL515B	CS2300	MA3	FA64	MA1
YL519A	CS2300	MA3	FA64	MA1
YL519AV	CS2300	MA3	FA64	MA1
YL519B	CS2300	MA3	FA64	MA1
YL519BV	CS2300	MA3	FA64	MA1
YL520AV	CS2300	MA3	FA64	MA1
YL520BV	CS2300	MA3	FA64	MA1
YL520CV	CS2300	MA3	FA64	MA1
YL520CV2	CS2300	MA3	FA64	MA1
YL520DV	CS2300	MA3	FA64	MA1
YL520EV	CS2300	MA3	FA64	MA1
YL520JV	CS2300	MA3	FA64	MA1
YL524AV	CS2300	MA3	AL104	AL105
YL524BV	CS2300	MA3	AL104	AL105
YL529A	CS2300	MA3	FA64	MA1
YL529AV	CS2300	MA3	FA64	MA1
YL529B	CS2300	MA3	FA64	MA1
YL529BV	CS2300	MA3	FA64	MA1
YL532A	CS751	—	—	—
YL532B	CS751	—	—	—
YL532C	CS751	—	—	—
YL532D	CS751	—	—	—
YL532E	CS751	—	—	—
YL532F	CS751	—	—	—
YL532G	CS751	—	—	—
YL532H	CS751	—	—	—
YL532J	CS751	—	—	—
YL532K	CS751	—	—	—
YL532L	CS751	—	—	—
YL532M	CS751	—	—	—
YL539AV	CS2300	MA3	FA64	MA1
YL554CV	CS2300	MA3	AL65	MA8
YL554DV	CS2300	MA3	AL65	MA8
YL554EV	CS2300	MA3	AL65	MA8
YL554FV	CS2300	MA3	AL65	MA8
YL555CV	CS2300	MA3	AL65	MA8
YL555DV	CS2300	MA3	AL65	MA8
YL558AV	CS2300	MA3	FA64	MA1
YL558BV	CS2300	MA3	FA64	MA1
YL566AV	CS2300	MA3	FA64	MA1

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
YL567CV	CS2300	MA3	AL65	MA8
YL567DV	CS2300	MA3	AL65	MA8
YL585AV	CS2300	MA3	FA64	MA1
YL585CV2	CS2300	MA3	FA64	MA1
YL621CV	CS2300	MA3	—	MA8
YL623AV	CS2300	MA3	AL65	MA1
YL623AV2	CS2300	MA3	AL65	MA1
YL624AV	CS2300	MA3	AL65	MA1
YL624AV2	CS2300	MA3	AL65	MA1
YL624JV	CS2300	MA3	AL65	MA8
YL624MV	CS2300	MA3	AL65	MA8
YL670AV	CS2300	MA3	AL65	MA8
YL673AV	CS2300	MA3	AL65	—
YL676AV	CS2300	MA3	—	—
YL677AV	CS2300	MA3	AL65	—
YL694AV	CS2300	MA3	AL65	—
YL700AV	CS2300	MA3	AL65	—
YL703AV	CS2300	MA3	AL65	MA2
YP451A	CS2300	MA3	MO13	MO40
YP451B	CS2300	MA3	MO13	MO40
YP451C	CS2300	MA3	MO13	MO40
YP451D	CS2300	MA3	MO13	MO40
YP451E	CS2300	MA3	MO13	MO40
YP451F	CS2300	MA3	MO13	MO40
YP451G	CS2300	MA3	MO13	MO40
YS621CV	CS2300	MA3	AL65	MA12
YS700AV	CS2300	MA3	AL65	—
YS703AV	CS2300	MA3	AL65	MA8
ZC	CS2301	—	—	MA10
ZC263A	CS729A	MO5000	AL107	AL128
ZC263B	CS729A	MO5000	AL107	AL128
ZC291L	CS851P	MO5000	MO13	MO20
ZC291M	CS851P	MO5000	MO13	MO20
ZC291R	CS851P	MO5000	MO13	MO20
ZC291S	CS851P	MO5000	MO13	MO20
ZC291V	CS851P	MO5000	MO13	MO20
ZC291X	CS851P	MO5000	MO13	MO20
ZC292B	CS786P	RR175	RR169R	RR165
ZC292D	CS786P	RR175	RR169R	RR165
ZC292F	CS786P	RR175	RR169R	RR165
ZC292G	CS786P	RR175	RR169R	RR165
ZC303D	CS786P	RR175	RR169R	RR165
ZC303E	CS786P	RR175	RR169R	RR165
ZC310AA	CS786P	RR175	RR169R	RR165
ZC310AB	CS786P	RR175	RR169R	RR165
ZC310AC	CS786P	RR175	RR169R	RR165
ZC310AD	CS786P	RR175	RR169R	RR165
ZC310AE	CS786P	RR175	RR169R	RR165

(continued on next page)

MALLORY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
ZC310AF	CS786P	RR175	RR169R	RR165
ZC310AG	CS786P	RR175	RR169R	RR165
ZC310AH	CS786P	RR175	RR169R	RR165
ZC310AJ	CS786P	RR175	RR169R	RR165
ZC310AK	CS786P	RR175	RR169R	RR165
ZC310AL	CS786P	RR175	RR169R	RR165
ZC310AM	CS786P	RR175	RR169R	RR165
ZC310AN	CS786P	RR175	RR169R	RR165
ZC310AP	CS786P	RR175	RR169R	RR165
ZC310AR	CS786P	RR175	RR169R	RR165
ZC310AS	CS786P	RR175	RR169R	RR165
ZC310AT	CS786P	RR175	RR169R	RR165
ZC310AV	CS786P	RR175	RR169R	RR165
ZC310F	CS786P	RR175	RR169R	RR165
ZC310G	CS786P	RR175	RR169R	RR165
ZC310H	CS786P	RR175	RR169R	RR165
ZC310J	CS786P	RR175	RR169R	RR165
ZC310K	CS786P	RR175	RR169R	RR165
ZC310L	CS786P	RR175	RR169R	RR165
ZC310M	CS786P	RR175	RR169R	RR165
ZC310N	CS786P	RR175	RR169R	RR165
ZC310P	CS786P	RR175	RR169R	RR165
ZC310Q	CS786P	RR175	RR169R	RR165
ZC310R	CS786P	RR175	RR169R	RR165
ZC310S	CS786P	RR175	RR169R	RR165
ZC310T	CS786P	RR175	RR169R	RR165
ZC310U	CS786P	RR175	RR169R	RR165
ZC310V	CS786P	RR175	RR169R	RR165
ZC310W	CS786P	RR175	RR169R	RR165
ZC310X	CS786P	RR175	RR169R	RR165
ZC310Y	CS786P	RR175	RR169R	RR165
ZC310Z	CS786P	RR175	RR169R	RR165
ZC312AA	CS786P	RR175	RR169R	RR165
ZC312AB	CS786P	RR175	RR169R	RR165
ZC312AC	CS786P	RR175	RR169R	RR165
ZC312AD	CS786P	RR175	RR169R	RR165
ZC312AE	CS786P	RR175	RR169R	RR165
ZC312AF	CS786P	RR175	RR169R	RR165
ZC312AH	CS786P	RR175	RR169R	RR165
ZC312AJ	CS786P	RR175	RR169R	RR165
ZC312AK	CS786P	RR175	RR169R	RR165
ZC312AL	CS786P	RR175	RR169R	RR165
ZC312AM	CS786P	RR175	RR169R	RR165
ZC312AN	CS786P	RR175	RR169R	RR165
ZC312AP	CS786P	RR175	RR169R	RR165
ZC312AQ	CS786P	RR175	RR169R	RR165
ZC312AR	CS786P	RR175	RR169R	RR165
ZC312AS	CS786P	RR175	RR169R	RR165

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
ZC312AT	CS786P	RR175	RR169R	RR165
ZC312AU	CS786P	RR175	RR169R	RR165
ZC312G	CS786P	RR175	RR169R	RR165
ZC312J	CS786P	RR175	RR169R	RR165
ZC312K	CS786P	RR175	RR169R	RR165
ZC312L	CS786P	RR175	RR169R	RR165
ZC312M	CS786P	RR175	RR169R	RR165
ZC312N	CS786P	RR175	RR169R	RR165
ZC312P	CS786P	RR175	RR169R	RR165
ZC312Q	CS786P	RR175	RR169R	RR165
ZC312R	CS786P	RR175	RR169R	RR165
ZC312S	CS786P	RR175	RR169R	RR165
ZC312T	CS786P	RR175	RR169R	RR165
ZC312U	CS786P	RR175	RR169R	RR165
ZC312V	CS786P	RR175	RR169R	RR165
ZC312W	CS786P	RR175	RR169R	RR165
ZC312X	CS786P	RR175	RR169R	RR165
ZC312Y	CS786P	RR175	RR169R	RR165
ZC312Z	CS786P	RR175	RR169R	RR165
ZC313D	CS753	MA3	FA67	FA6900
ZC313E	CS753	MA3	FA67	FA6900
ZC332A	CS786P	RR175	RR169R	RR165
ZC332C	CS786P	RR175	RR169R	RR165
ZC336F	CS751	FA8200	FA157	FA79
ZC343D	CS751	FA8200	FA157	FA79
ZC343E	CS751	FA8200	FA157	FA79
ZC343F	CS751	FA8200	FA157	FA79
ZC343G	CS751	FA8200	FA157	FA79
ZC343H	CS751	FA8200	FA157	FA79
ZC343J	CS751	FA8200	FA157	FA79
ZC343K	CS751	FA8200	FA157	FA79
ZC343M	CS751	FA8200	FA157	FA79
ZC343N	CS751	FA8200	FA157	FA79
ZC343P	CS751	FA8200	FA157	FA79
ZC343Q	CS751	FA8200	FA157	FA79
ZC343R	CS751	FA8200	FA157	FA79
ZC343S	CS751	FA8200	FA157	FA79
ZC344A	CS751	FA8200	FA157	FA79
ZC344C	CS751	FA8200	FA157	FA79
ZC344E	CS751	FA8200	FA157	FA79
ZC345A	CS786P	RR175	RR169R	RR165
ZC346A	CS729A	MO5000	AL125	AL124
ZC346B	CS729A	MO5000	AL125	AL124
ZC346C	CS720P	MO5000	AL125	AL124
ZC346D	CS851P	MO5000	MO13	MO20
ZC346F	CS851P	MO5000	MO13	MO20
ZC346G	CS851P	MO5000	MO13	MO20
ZC346H	CS851P	MO5000	MO13	MO20

(continued on next page)

MALLORY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
ZC346J	CS851P	MO5000	MO13	MO20
ZC346K	CS720P	MO5000	AL125	AL124
ZC346L	CS851P	MO5000	MO13	MO20
ZC346M	CS851P	MO5000	MO13	MO20
ZC346N	CS851P	MO5000	MO13	MO20
ZC346P	CS851P	MO5000	MO13	MO20
ZC346Q	CS851P	MO5000	MO13	MO20
ZC346S	CS851P	MO5000	MO13	MO20
ZC346T	CS851P	MO5000	MO13	MO20
ZC365A	CS729A	MO5000	AL125	AL124
ZC365AA	CS851P	MO5000	MO13	MO20
ZC365AC	CS851P	MO5000	MO13	MO20
ZC365AD	CS851P	MO5000	MO13	MO20
ZC365B	CS851P	MO5000	AL125	AL124
ZC365E	CS720P	MO5000	AL125	AL124
ZC365F	CS720P	MO5000	AL125	AL124
ZC365G	CS851P	MO5000	MO13	MO20
ZC365H	CS720P	MO5000	AL125	AL124
ZC365J	CS720P	MO5000	AL125	AL124
ZC365K	CS720P	MO5000	AL125	AL124
ZC365L	CS851P	MO5000	MO13	MO20
ZC365M	CS721A	MO5000	AL125	AL124
ZC365N	CS851P	MO5000	MO13	MO20
ZC365P	CS851P	MO5000	MO13	MO20
ZC365Q	CS851P	MO5000	MO13	MO20
ZC365R	CS721A	MO5000	AL125	AL124
ZC365S	CS720P	MO5000	AL125	AL124
ZC365T	CS720P	MO5000	AL125	AL124
ZC365U	CS720P	MO5000	AL125	AL124
ZC365V	CS851P	MO5000	MO13	MO20
ZC365W	CS720P	MO5000	AL125	AL124
ZC365Y	CS851P	MO5000	MO13	MO20
ZC365Z	CS720P	MO5000	AL125	AL124
ZC389A	CS786P	RR175	RR169R	RR168
ZC414A	CS753	FA76	FA67	FA6900
ZC414C	CS753	FA76	FA67	FA6900
ZC414G	CS753	FA76	FA67	FA6900
ZC414H	CS753	FA76	FA67	FA6900
ZC423	CS788P	MA3	RR182R	RR183
ZC423A	CS788P	MA3	RR182R	RR183
ZC423B	CS788P	MA3	RR182R	RR183
ZC423C	CS788P	MA3	RR182R	RR183
ZC423D	CS788P	MA3	RR182R	RR183
ZC423E	CS788P	MA3	RR182R	RR183
ZC423F	CS788P	MA3	RR182R	RR183
ZC423G	CS788P	MA3	RR182R	RR183
ZC423H	CS788P	MA3	RR182R	RR183
ZC423J	CS788P	MA3	RR182R	RR183

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
ZC423K	CS788P	MA3	RR182R	RR183
ZC423L	CS788P	MA3	RR182R	RR183
ZC423M	CS788P	MA3	RR182R	RR183
ZC424A	CS851P	MO5000	MO13	MO40
ZC424B	CS851P	MO5000	MO13	MO40
ZC424C	CS851P	MO5000	MO13	MO40
ZC424D	CS851P	MO5000	MO13	MO40
ZC424E	CS851P	MO5000	MO13	MO40
ZC424F	CS851P	MO5000	MO13	MO40
ZC424G	CS851P	MO5000	MO13	MO40
ZC424J	CS851P	MO5000	MO13	MO40
ZC424L	CS851P	MO5000	MO13	MO40
ZC424M	CS851P	MO5000	MO13	MO40
ZC424N	CS851P	MO5000	MO13	MO40
ZC432A	CS786P	MA3	RR169R	RR165
ZC432B	CS786P	MA3	RR169R	RR165
ZC432C	CS786P	MA3	RR169R	RR165
ZC432D	CS786P	MA3	RR169R	RR165
ZC432E	CS786P	MA3	RR169R	RR165
ZC432F	CS786P	MA3	RR169R	RR165
ZC432H	CS786P	MA3	RR169R	RR165
ZC432J	CS786P	MA3	RR169R	RR165
ZC432K	CS786P	MA3	RR169R	RR165
ZC432L	CS786P	MA3	RR169R	RR165
ZC432P	CS786P	MA3	RR169R	RR165
ZC444A	CS763A	MA3	RR161	RR162
ZC449A	CS751	FA8200	FA157	FA79
ZC449B	CS751	FA8200	FA157	FA79
ZC449C	CS751	FA8200	FA157	FA79
ZC449D	CS751	FA8200	FA157	FA79
ZC449E	CS751	FA8200	FA157	FA79
ZC449F	CS751	FA8200	FA157	FA79
ZC449G	CS751	FA8200	FA157	FA79
ZC449H	CS751	FA8200	FA157	FA79
ZC449K	CS751	FA8200	FA157	FA79
ZC449L	CS751	FA8200	FA157	FA79
ZC449M	CS751	FA8200	FA157	FA79
ZC449N	CS751	FA8200	FA157	FA79
ZC449Q	CS751	FA8200	FA157	FA79
ZC449R	CS751	FA8200	FA157	FA79
ZC449S	CS751	FA8200	FA157	FA79
ZC449T	CS751	FA8200	FA157	FA79
ZC449U	CS751	FA8200	FA157	FA79
ZC449V	CS751	FA8200	FA157	FA79
ZC452A	CS788P	MA3	RR182R	RR181
ZC452B	CS788P	MA3	RR182R	RR181
ZC452C	CS788P	MA3	RR182R	RR181
ZC452D	CS788P	MA3	RR182R	RR181

(continued on next page)

MALLORY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
ZC452E	CS788P	MA3	RR182R	RR181
ZC452F	CS788P	MA3	RR182R	RR181
ZC465G	CS786P	RR175	RR169R	RR165
ZC465H	CS786P	RR175	RR169R	RR165
ZC465J	CS786P	RR175	RR169R	RR165
ZC465K	CS786P	RR175	RR169R	RR165
ZC465L	CS786P	RR175	RR169R	RR165
ZC465N	CS786P	RR175	RR169R	RR165
ZC465P	CS786P	RR175	RR169R	RR165
ZC465Q	CS786P	RR175	RR169R	RR165
ZC465R	CS786P	—	—	—
ZC465S	CS786P	RR175	RR169R	RR165
ZC465U	CS786P	RR175	RR169R	RR165
ZC465V	CS786P	RR175	RR169R	RR165
ZC465X	CS786P	RR175	RR169R	RR165
ZC470A	CS753	MA3	—	FA6900
ZC470B	CS753	MA3	FA67	FA6900
ZC470C	CS753	MA3	FA67	FA6900
ZC470D	CS753	MA3	FA67	FA6900
ZC471A	CS753	MA3	FA67	FA6900
ZC471B	CS753	MA3	FA67	FA6900
ZC476A	CS788P	MA3	RR182R	RR183
ZC476B	CS788P	MA3	RR182R	RR183
ZC476C	CS788P	MA3	RR182R	RR183
ZC476D	CS788P	MA3	RR182R	RR183
ZC476E	CS788P	MA3	RR182R	RR183
ZC476F	CS788P	MA3	RR182R	RR183
ZC476G	CS788P	MA3	RR182R	RR183
ZC476H	CS788P	MA3	RR182R	RR183
ZC476J	CS788P	MA3	RR182R	RR183
ZC477A	CS786P	RR175	RR169R	RR165
ZC477B	CS786P	RR175	RR169R	RR165
ZC490A	CS753	MA3	FA67	FA6900
ZC490B	CS753	MA3	FA67	FA6900
ZC491A	CS788P	MA3	RR182R	RR183
ZC493A	CS753	MA3	FA67	FA6900
ZC493AA	CS753	FA8200	—	—
ZC493AB	CS753	FA8200	—	—
ZC493B	CS753	MA3	FA67	FA6900
ZC493C	CS753	MA3	FA67	FA6900
ZC493D	CS753	MA3	FA67	FA6900
ZC493E	CS753	MA3	FA67	FA6900
ZC493F	CS753	MA3	FA67	FA6900
ZC493G	CS753	MA3	FA67	FA6900
ZC493H	CS753	MA3	FA67	FA6900
ZC493K	CS753	MA3	FA67	FA6900
ZC493L	CS753	FA8200	—	—
ZC493M	CS753	FA8200	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
ZC493N	CS753	FA8200	—	—
ZC493P	CS753	FA8200	—	—
ZC493P	CS753	MA3	FA67	FA6900
ZC493Q	CS753	FA8200	—	—
ZC493R	CS753	FA8200	—	—
ZC493S	CS753	FA8200	—	—
ZC493T	CS753	FA8200	—	—
ZC493U	CS753	FA8200	—	—
ZC493V	CS753	FA8200	—	—
ZC493W	CS753	FA8200	—	—
ZC493X	CS753	FA8200	—	—
ZC493Y	CS753	FA8200	—	—
ZC493Z	CS753	FA8200	—	—
ZC497A	CS851P	MO5000	MO13	MO20
ZC497B	CS721A	MO5000	—	AL124
ZC497E	CS851P	MO5000	MO13	MO20
ZC497F	CS721A	MO5000	AL125	AL124
ZC497G	CS851P	MO5000	MO13	MO20
ZC497H	CS851P	MO5000	MO13	MO20
ZC497J	CS851P	MO5000	MO13	MO20
ZC497L	CS851P	MO5000	MO13	MO20
ZC497M	CS721A	MO5000	AL125	AL124
ZC497N	CS851P	MO5000	MO13	MO20
ZC497P	CS851P	MO5000	MO13	MO20
ZC497R	CS851P	MO5000	MO13	MO20
ZC497S	CS721A	MO5000	AL125	AL124
ZC501A	CS786P	RR175	RR169R	RR165
ZC501B	CS786P	RR175	RR169R	RR165
ZC501C	CS786P	RR175	RR169R	RR165
ZC501D	CS786P	RR175	RR169R	RR165
ZC501E	CS786P	RR175	RR169R	RR165
ZC501F	CS786P	RR175	RR169R	RR165
ZC501G	CS786P	RR175	RR169R	RR165
ZC501H	CS786P	RR175	RR169R	RR165
ZC501J	CS786P	RR175	RR169R	RR165
ZC501K	CS786P	RR175	RR169R	RR165
ZC501L	CS786P	RR175	RR169R	RR165
ZC501M	CS786P	RR175	RR169R	RR165
ZC501N	CS786P	RR175	RR169R	RR165
ZC501P	CS786P	RR175	RR169R	RR165
ZC501Q	CS786P	RR175	RR169R	RR165
ZC501R	CS786P	RR175	RR169R	RR165
ZC501S	CS786P	RR175	RR169R	RR165
ZC501T	CS786P	RR175	RR169R	RR165
ZC501U	CS786P	RR175	RR169R	RR165
ZC508A	CS753	MA3	FA67	FA6900
ZC508B	CS753	MA3	FA67	FA6900
ZC508E	CS753	MA3	FA67	FA6900

(continued on next page)

MALLORY (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Unit No	Contact Assembly	Condenser	Rotor	Cap
ZC508F	CS753	MA3	—	—	ZC546F	CS751	FA8200	FA157	FA79
ZC508G	CS753	MA3	—	—	ZC546G	CS751	FA8200	FA157	FA79
ZC508H	CS753	MA3	—	—	ZC546H	CS751	FA8200	FA157	FA79
ZC508J	CS753	MA3	—	—	ZC546J	CS751	FA8200	FA157	FA79
ZC510A	CS788P	MA3	RR182R	RR183	ZC546K	CS751	FA8200	FA157	FA79
ZC510B	CS788P	MA3	RR182R	RR183	ZC546L	CS751	FA8200	FA157	FA79
ZC510D	CS788P	MA3	RR182R	RR183	ZC546M	CS751	FA8200	FA157	FA79
ZC510E	CS788P	MA3	RR182R	RR183	ZC546N	CS751	FA8200	FA157	FA79
ZC510F	CS788P	MA3	RR182R	RR183	ZC546P	CS751	FA8200	FA157	FA79
ZC526A	CS788P	MA3	RR169R	RR165	ZC546Q	CS751	FA8200	FA157	FA79
ZC526B	CS788P	MA3	RR169R	RR165	ZC546R	CS751	FA8200	FA157	FA79
ZC526C	CS788P	MA3	RR169R	RR165	ZC546S	CS751	FA8200	FA157	FA79
ZC526D	CS788P	MA3	RR169R	RR165	ZC546T	CS751	FA8200	FA157	FA79
ZC526E	CS788P	MA3	RR169R	RR165	ZC546U	CS751	FA8200	FA157	FA79
ZC526F	CS788P	MA3	RR169R	RR165	ZC546V	CS751	FA8200	FA157	FA79
ZC531A	CS788P	RR175	RR169R	RR165	ZC546W	CS751	FA8200	FA157	FA79
ZC531C	CS786P	MA3	RR169R	RR165	ZC546X	CS751	FA8200	FA157	FA79
ZC531D	CS786P	MA3	RR169R	RR165	ZC548A	CS786P	RR175	RR169R	RR165
ZC531E	CS786P	MA3	RR169R	RR165	ZC563A	CS751	FA8200	FA157	FA79
ZC531G	CS786P	MA3	RR169R	RR165	ZC563B	CS751	FA8200	FA157	FA79
ZC531H	CS786P	MA3	RR169R	RR165	ZC563C	CS751	FA8200	FA157	FA79
ZC531J	CS786P	MA3	RR169R	RR165	ZC563D	CS751	FA8200	FA157	FA79
ZC531K	CS786P	MA3	RR169R	RR165	ZC563E	CS751	FA8200	FA157	FA79
ZC531L	CS786P	MA3	RR169R	RR165	ZC563F	CS751	FA8200	FA157	FA79
ZC533A	CS786P	RR175	RR169R	RR165	ZCJ80W	CS763A	MA3	RR161	RR162
ZC537A	CS786P	RR175	RR169R	RR165	ZD347A	CS2300	RR175	FA64	MA1
ZC537B	CS786P	RR175	RR169R	RR165	ZD347B	CS2300	RR175	FA64	MA1
ZC537C	CS786P	RR175	RR169R	RR165	ZD352	CS2300	RR175	FA64	MA1
ZC537E	CS786P	RR175	RR169R	RR165	ZD358A	CS2300	RR175	FA64	MA1
ZC546A	CS751	FA8200	FA157	FA79	ZD366A	CS2300	RR175	FA64	MA1
ZC546B	CS751	FA8200	FA157	FA79	ZD366B	CS2300	RR175	FA64	MA1
ZC546C	CS751	FA8200	FA157	FA79	ZD430A	—	—	FA64	MA1
ZC546D	CS751	FA8200	FA157	FA79	ZD431A	CS2300	MA3	FA64	MA1
ZC546E	CS751	FA8200	FA157	FA79					

(continued on next column)

MARELLI

Unit No	Contact Assembly	Condenser	Rotor	Cap	Unit No	Contact Assembly	Condenser	Rotor	Cap
S69A	—	—	EP221	EP211	S86B	CS228	—	EP221	EP211
S70B	CS225	—	—	—	S86D	CS228	—	EP221	EP211
S76D	CS225	EP235	—	—	S88B	CS225	—	—	—
S76E	CS225	EP235	—	—	S88BC	CS225	—	—	—
S76G	CS225	EP235	—	—	S88S	CS225	—	—	—
S76H	CS225	EP235	—	—	S91AC	CS787	—	—	—
S77A	CS225	—	—	—	S91ACX	CS787	—	—	—
S83CK	CS225	EP235	—	—	S91B	CS787	—	—	—
S83DK	CS225	—	—	—	S91BX	CS787	—	—	—

(continued on next column)

(continued on next page)

MARELLI (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Unit No	Contact Assembly	Condenser	Rotor	Cap
S96AC	CS787	—	—	—	S139A	CS232	—	EP247	EP240
S96ACX	CS787	—	—	—	S140A	CS231	EP235	EP473	EP242
S103B	CS787	—	—	—	S140B	CS231	EP235	EP473	EP470
S103BA	CS232	—	—	—	S144AA	CS232	—	EP244	EP259
S105C	CS787	—	—	—	S144B	CS232	—	EP473	EP246
S105CX	CS787	—	—	—	S144BA	CS232	—	EP244	EP259
S106AC	CS787	—	—	—	S144BX	CS232	—	EP473	EP246
S106ACX	CS787	—	—	—	S144CAY	CS232 ⁹	EP236	EP244	EP248
S108AA	CS787	—	—	—	S144CAY	CS232 ⁹	EP238	EP244	EP248
S108B	CS787	—	—	—	S144CBY	CS232 ⁹	EP236	EP244	EP248
S118AA	CS231	EP215	EP247	EP214	S144CBY	CS232 ⁹	EP238	EP244	EP248
S118AAX	CS231	EP215	EP247	EP214	S144E	CS232	—	EP244	EP248
S118BB	CS231	EP215	EP247	EP245	S144F	CS232	—	EP244	EP248
S118BBX	CS231	EP215	EP247	EP245	S144H	CS232	—	EP244	EP248
S118CA	CS231	EP215	EP247	EP214	S144L	CS232	—	EP244	EP248
S118CAX	CS231	EP215	EP247	EP214	S144M	CS232	—	EP244	EP248
S118H	CS787	—	—	—	S144N	CS232	—	EP244	EP248
S118K	CS787	—	—	—	S144P	CS232	—	EP244	EP248
S120A	CS231	EP215	EP247	EP214	S145B	CS232	—	—	—
S120AX	CS231	EP215	EP247	EP214	S145C	CS232	—	—	—
S124AX	CS231	EP215	EP247	EP241	S146A	CS232	—	EP247	—
S124B	CS231	EP215	EP247	EP241	S146AX	CS232	—	EP247	—
S124BX	CS231	EP215	EP247	EP241	S146BX	CS232	—	—	—
S130AAX	CS232	—	—	EP240	S147A	CS232	—	EP247	EP240
S130AX	CS232	—	—	—	S147AX	CS232	—	EP247	EP240
S134AA	CS232	—	EP247	EP240	S147B	CS232	—	EP247	EP240
S134B	CS232	EP215	EP247	EP246	S147C	CS232	—	EP247	EP240
S134BX	CS232	EP215	EP247	EP246	S147CX	CS232	—	EP247	EP240
S134CX	CS232	—	EP247	EP240	S147D	CS232	—	EP247	EP240
S134D	CS232	—	EP247	EP240	S147DX	CS232	—	EP247	EP240
S134E	CS232	—	EP247	EP240	S147E	CS232	—	EP247	EP240
S134F	CS232	—	EP247	EP240	S147H	CS232	—	EP247	EP240
S134G	CS232	—	EP247	EP240	S147HX	CS232	—	EP247	EP240
S135B	CS231	EP235	EP473	EP242	S147N	CS232	—	EP247	EP240
S135BX	CS231	EP235	EP473	EP242	S147P	CS232	—	—	—
S135C	CS231	EP235	EP473	EP242	S147VX	CS232	—	—	—
S135D	CS231	EP235	EP473	EP242	S147ZX	CS232	—	—	—
S135F	CS231	EP235	EP473	EP470	S152A	CS225	EP235	—	—
S136A	CS232	—	EP247	EP240	S153A	CS232	—	EP244	EP248
S136AX	CS232	—	EP247	EP240	S166A	CS232 ⁹	—	—	—
S137F	CS232	—	EP247	EP240					

(continued on next column)

MAZDA

Unit No	Contact Assembly	Condenser	Rotor	Cap	Unit No	Contact Assembly	Condenser	Rotor	Cap
030518200A	—	—	EP342	—	030518200B	—	—	EP342	—

(continued on next column)

(continued on next page)

⁹ Two required

MAZDA (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
030518200D ...	CS351	EP300	EP342	—
030518200E ...	CS351	EP300	EP342	—
154018200A ...	CS351	EP300	EP342	—
154018200B ...	CS351	EP300	EP342	—
154618200B ...	CS363	—	EP312	EP718
163718200 ...	CS363	—	EP312	EP718
165418200A ...	CS351	EP300	EP342	—
165418200B ...	CS351	EP300	EP342	—
165518200A ...	CS351	EP300	EP342	—
165518200B ...	CS351	EP300	EP342	—
166318200A ...	CS362	EP360	EP337	EP336
166318200C ...	CS362 ⁹	EP360 ⁹	EP337	EP336
166318700A ...	CS362 ⁹	EP360 ⁹	EP337	EP336
166324300 ...	CS362	EP360	EP337	EP336
166818200 ...	CS362	EP360	EP337	EP336
166918200 ...	CS360	EP360	EP337	EP336
170018200B ...	CS363	—	EP312	EP718
175718200A ...	CS367	EP358	EP361	EP353
175818200 ...	CS367	EP358	EP361	EP353
184518200A ...	CS359	EP366	EP342	EP706
188118200 ...	CS367	EP358	EP361	EP353
189318200 ...	—	—	EP342	—
209018200 ...	CS360	EP360	EP337	EP336
209018700 ...	CS360	EP360	EP337	EP336
209024400 ...	CS360	EP360	EP337	EP336
358718200 ...	CS367 ⁹	EP358 ⁹	EP370	EP353
364818200 ...	CS367 ⁹	EP358 ⁹	EP370	EP353
371018200 ...	—	—	EP342	EP718
371618200 ...	CS359	EP366	EP342	EP706
371918200 ...	CS359	EP366	EP342	EP723

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
372518200A ...	—	—	EP342	EP723
374318200 ...	CS367	EP358	EP370	EP353
377018200A ...	—	—	EP342	EP723
377518200 ...	CS367 ⁹	EP358 ⁹	EP370	EP353
387918200 ...	CS359	EP391	EP342	—
387918200A ...	CS359	EP391	EP342	EP706
388418200 ...	CS367	—	EP342	—
388418200A ...	CS367	—	EP342	EP706
390018200 ...	CS367 ⁹	EP358 ⁹	EP370	EP353
392818200 ...	CS367	—	EP342	EP723
395818200 ...	—	—	EP342	EP718
396218200 ...	CS359	EP391	EP342	EP706
398018200 ...	—	—	EP342	—
802818200 ...	CS359	EP366	EP342	EP706
802818200A ...	CS359	EP391	EP342	EP706
862918200 ...	CS359	EP391	EP342	EP706
862918200A ...	CS359	EP391	EP342	EP706
864918200B ...	CS367	EP358	EP370	EP353
864918200C ...	CS367	EP359	EP370	EP353
865018200 ...	CS367	EP358	EP370	EP353
873518200 ...	CS367	EP358	EP370	EP353
876118200 ...	CS359	EP358	EP370	EP353
882618200 ...	CS367	EP358	EP370	EP353
882618200A ...	CS367 ⁹	EP358 ⁹	EP370	EP353
882718200A ...	CS367 ⁹	EP358 ⁹	EP370	EP353
891418200 ...	—	—	EP342	EP718
892618200A ...	CS367	—	EP342	EP706
892718200A ...	CS359	EP391	EP342	EP706

MITSUBISHI

Unit No	Contact Assembly	Condenser	Rotor	Cap
MD015589 ...	—	—	EP342	—
MD017694 ...	CS351	—	EP342	—
MD019893 ...	—	—	EP342	—
MD025751 ...	CS351	—	EP342	—
MD027820 ...	CS351	—	EP342	—
MD075634 ...	—	—	EP342	—
MD075635 ...	—	—	EP342	—
MD083135 ...	CS351	—	—	—
MD087843 ...	CS351	—	—	—
MD093764 ...	CS351	EP656	EP342	EP513
MD093765 ...	CS351	EP656	EP342	EP513
MD100434 ...	—	—	EP342	EP513
MD100625 ...	CS351	—	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
MD108019 ...	CS351	EP656	EP342	EP513
MD111795 ...	CS351	EP656	EP342	EP513
MD114760 ...	CS351	—	—	—
MD114764 ...	CS351	—	—	—
T3T031711823 ...	CS351	EP300	EP342	EP706
T3T031721843 ...	CS351	EP300	EP342	EP706
T3T032711824 ...	CS363 ⁹	—	EP321	EP706
T3T036721845 ...	CS359	EP351	EP342	EP706
T3T036731849 ...	CS359	EP351	EP242	EP706
T3T036781843 ...	CS359	EP351	EP342	EP706
T3T051271845 ...	CS359	EP366	EP342	EP706
T3T051271849 ...	CS359	EP366	EP342	EP706
T3T051781843 ...	CS359	EP366	EP342	EP706

(continued on next page)

⁹ Two required

MITSUBISHI (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
T3T051793763	CS359	EP366	EP342	EP706
T3T071721845	CS359	EP391	EP342	EP706
T3T071731849	CS359	EP391	EP342	EP706
T3T071781843	CS359	EP391	EP342	EP706
T3T071793763	CS359	EP391	EP342	EP706
T3T071823879	CS359	EP391	EP342	EP706
T3T071833975	CS359	EP366	EP342	EP706
T3T071858629	CS359	EP391	EP342	EP706
T3T607713874	—	—	EP342	EP706
T3T607723877	—	—	EP342	EP706
T3T607738633	—	—	EP342	EP706
T3T607743874	—	—	EP342	EP706
T3T607758786	—	—	EP342	EP706
T3T607768791	—	—	EP342	EP706
T3T607778495	—	—	EP342	EP706
T3T616748682	—	—	EP342	EP706
T3T616778684	—	—	EP342	EP706
T3T818748682	—	—	EP342	EP706
T4T611748678	—	—	EP658	EP660
T4T611758944	—	—	EP658	EP660
T000T00271	—	—	—	EP775
T003T04485	CS351	—	EP342	—
T003T04581	CS351	—	EP342	—
T003T05778	CS351	EP656	EP342	EP513
T003T05789	CS351	EP656	EP342	EP513
T003T05790	CS351	EP656	EP342	EP513
T003T05791	—	—	EP342	EP513
T003T05792	CS351	EP656	EP342	EP513
T003T05793	CS351	EP656	EP342	EP513
T003T05795	CS351	EP656	EP342	EP513
T003T06371	CS351	—	EP342	—
T003T07085	CS359	—	EP342	—
T003T07471	CS359	EP391	EP342	—
T003T07473	CS359	—	EP342	—
T003T07474	CS359	—	EP342	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
T003T07671	CS359	—	EP342	—
T003T07771	CS359	—	EP342	—
T003T08171	—	—	EP342	—
T003T08173	—	—	EP342	—
T003T08174	—	—	EP342	—
T003T08175	—	—	EP342	—
T003T13491	CS351	—	—	—
T003T15081	CS351	—	—	—
T003T15091	CS351	—	—	—
T003T15473	CS351	—	—	—
T003T20976	CS351	—	—	—
T003T21083	CS351	—	—	—
T003T21083A	CS351	—	—	—
T003T21089A	CS351	—	—	—
T003T43491	CS351	—	—	—
T003T43491V	CS351	—	—	—
T004T00571	CS351	—	—	—
T004T10475	CS351	—	—	—
T004T10673	CS351	—	—	—
T004T10691	CS351	—	—	—
T004T21075	CS351	—	—	—
T004T21078	CS351	—	—	—
T004T21079	CS351	—	—	—
T004T21474	CS351	—	—	—
T004T21476	CS351	—	—	—
T004T21674	CS351	—	—	—
T004T21680	CS351	—	—	—
T004T21774	CS351	—	—	—
T004T21774B	CS351	—	—	—
T004T21875	CS351	—	—	—
T004T21876	CS351	—	—	—
T004T21878	CS351	—	—	—
T004T21880	CS351	—	—	—

NISSAN-DATSUN

Unit No	Contact Assembly	Condenser	Rotor	Cap
D4A201	CS351	EP344	EP345	EP346
D4A202	CS351	EP344	EP345	EP346
D4A402	CS351	EP344	EP345	EP346
D4A403	CS351	EP344	EP345	EP346
D4A404	CS351	EP344	EP345	EP346
D4A406	CS351	EP344	EP345	EP346
D4A407	CS351	EP344	EP345	EP346
D4A503	CS351	EP344	EP345	EP346

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
D4A504	CS351	EP344	EP345	EP346
D4A505	CS351	EP344	EP345	EP346
D4A509	CS351	EP344	EP345	EP346
D4A513	CS351	EP344	EP345	EP346
D4A514	CS351	EP344	EP345	EP346
D4A603	CS351	EP344	EP345	EP346
D4A604	CS351	EP344	EP345	EP346
D4A605	CS351	EP344	EP345	EP346

(continued on next page)

NISSAN-DATSUN (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
D4A702	CS351	EP344	EP345	EP346
D4A703	CS351	EP344	EP345	EP346
D41066A	CS355 ⁹	EP300	EP312	EP718
D41066A	CS355 ⁹	EP330	EP312	EP718
D41067	CS355 ⁹	EP330	EP312	EP718
D41068	CS355 ⁹	EP300	EP312	EP718
D41068	CS355 ⁹	EP330	EP312	EP718
D41069	CS355 ⁹	EP300	EP312	EP718
D41069	CS355 ⁹	EP330	EP312	EP718
D41280	CS351	EP300	EP312	EP718
D41284A	CS355 ⁹	EP300	EP312	EP718
D41284A	CS355 ⁹	EP330	EP312	EP718
D41289	CS351	EP300	EP312	EP718
D61154	CS351	EP300	EP312	EP331
D61252	CS351	EP300	EP312	EP331
D61254	CS355 ⁹	EP300	EP312	EP331
D61254	CS355 ⁹	EP330	EP312	EP331
D61452	CS355 ⁹	EP300	EP312	EP331
D61452	CS355 ⁹	EP330	EP312	EP331
22100A2300	CS351	EP300	EP312	EP718
22100A5500	CS355 ⁹	EP300	EP312	EP718
22100A5500	CS355 ⁹	EP330	EP312	EP718
22100A5501	CS355	—	EP312	EP718
22100A5502	CS355	—	EP312	EP718
22100A5503	CS355	—	EP312	EP718
22100A5504	CS355	—	EP312	EP718
22100A5505	CS355	—	EP312	EP718
22100A7700	CS351	EP300	EP312	EP718
22100A7701	CS351	EP300	EP312	EP718
22100B8001	CS351	EP344	EP345	EP346
22100B8100	CS351	EP344	EP345	EP346
22100B8900	CS351	EP344	EP345	EP346
22100D0113	—	—	—	EP775
22100E4601	CS351	EP300	EP312	EP331
22100E4603	CS351	EP300	EP312	EP331
22100E8000	CS355 ⁹	EP300	EP312	EP331
22100E8000	CS355 ⁹	EP330	EP312	EP331
22100G5710	CS351	—	—	—
22100G8410	CS351	—	—	—
22100H1001	CS351	EP300	EP312	EP718
22100H1901	CS351	EP300	EP312	EP718
22100H1902	CS351	EP300	EP312	EP718
22100H3900	CS351	EP300	EP312	EP718
22100H3901	CS351	EP300	EP312	EP718
22100H5901	CS351	EP300	EP312	—
22100H6201	CS351	EP344	EP345	EP346
22100H7100	CS351	EP300	EP312	EP718
22100H7200	CS351	EP344	EP345	EP346

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
22100H7201	CS351	EP344	EP345	EP346
22100H7205	CS351	EP344	EP345	EP346
22100H7206	CS351	EP344	EP345	EP346
22100H7260	CS351	EP344	EP345	EP346
22100H7263	CS351	EP344	EP345	EP346
22100H7268	CS351	EP344	EP345	EP346
22100H7601	CS351	EP344	EP345	EP346
22100H7606	CS351	EP344	EP345	EP346
22100N2800	CS355 ⁹	EP300	EP312	EP718
22100N2800	CS355 ⁹	EP330	EP312	EP718
22100N2801	CS355 ⁹	EP300	EP312	EP718
22100N2801	CS355 ⁹	EP330	EP312	EP718
22100N3300	CS351	EP330	EP312	EP331
22100N3305	CS355 ⁹	EP300	EP312	EP331
22100N3305	CS355 ⁹	EP330	EP312	EP331
22100N5900	CS351	EP344	EP345	EP346
22100N5906	CS351	EP344	EP345	EP346
22100N5908	CS351	EP344	EP345	—
22100N6000	CS351	EP344	EP345	EP346
22100N6005	CS351	EP344	EP345	EP346
22100N7380	CS351	EP344	EP345	EP346
22100N7385	CS351	EP344	EP345	EP346
22100R9711	CS351	—	—	—
22100T6011	CS351	—	—	—
22100T7012	CS351	—	—	—
22100U2001	CS355 ⁹	EP300	EP312	EP718
22100U2001	CS355 ⁹	EP330	EP312	EP718
22100U2002	CS355 ⁹	EP300	EP312	EP718
22100U2002	CS355 ⁹	EP330	EP312	EP718
22100U2003	CS355 ⁹	EP330	EP312	EP718
22100U2004	CS355 ⁹	EP330	EP312	EP718
22100U6000	CS351	EP344	EP345	EP346
22100U6001	CS351	EP344	EP345	EP346
2210001M12	CS351	—	—	—
2210001M14	CS351	—	—	—
2210001M15	CS351	—	—	—
2210002W00	CS351	—	—	—
2210002W01	CS351	—	—	—
2210009E11	CS351	—	—	—
2210009M12	CS351	—	—	—
2210009M14	CS351	—	—	—
2210009M15	CS351	—	—	—
2210015G15	CS351	—	—	—
2210016G15	CS351	—	—	—
2210018W11	CS351	—	—	—
2210026G11	CS351	—	—	—
2210035G15	CS351	—	—	—
2210008300	CS351	EP300	—	EP718

(continued on next page)

⁹ Two required

NISSAN-DATSUN (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap
2210013301 ...	CS351	EP300	EP312	EP718
2210014600 ...	CS351	EP300	EP312	EP718
2210014605 ...	CS351	EP300	EP312	EP718
2210014606 ...	CS351	EP300	EP312	EP718
2210014700 ...	CS351	EP300	EP312	EP718
2210014705 ...	CS351	EP300	EP312	EP718
2210016501 ...	CS351	EP300	EP312	EP718
2210016505 ...	CS351	EP300	EP312	EP718
2210016506 ...	CS351	EP300	EP312	EP718
2210016507 ...	CS351	EP300	EP312	EP718
2210018800 ...	CS351	EP300	EP312	EP718
2210020600 ...	CS351	EP300	EP312	EP304
2210020605 ...	CS351	EP300	EP312	EP304
2210021000 ...	CS351	EP300	EP312	EP718
2210021005 ...	CS351	EP300	EP312	EP718
2210021006 ...	CS351	EP300	EP312	EP718
2210021007 ...	CS351	EP300	EP312	EP718
2210022000 ...	CS351	EP300	EP312	EP718

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
2210022005 ...	CS351	EP300	EP312	EP718
2210023000 ...	CS351	EP300	EP312	EP718
2210023005 ...	CS351	EP300	EP312	EP718
2210023100 ...	CS355 ⁹	EP300	EP312	EP718
2210023100 ...	CS355 ⁹	EP330	EP312	EP718
2210023101 ...	CS355 ⁹	EP300	EP312	EP718
2210023101 ...	CS355 ⁹	EP330	EP312	EP718
2210023102 ...	CS355 ⁹	EP300	EP312	EP718
2210023102 ...	CS355 ⁹	EP330	EP312	EP718
2210023105 ...	CS355 ⁹	EP300	EP312	EP718
2210023105 ...	CS355 ⁹	EP330	EP312	EP718
2210025500 ...	CS351	EP300	EP312	EP718
2210025505 ...	CS351	EP300	EP312	EP718
2210025506 ...	CS351	EP300	EP312	EP718
2210025600 ...	CS351	EP300	EP312	EP718
2210025605 ...	CS351	EP300	EP312	EP718
2210025606 ...	CS351	EP300	EP312	EP718

OMC (OUTBOARD MARINE CORP.)

Unit No	Contact Assembly	Condenser	Rotor	Cap
380534	CS788P	RR176	RR182R	RR181
380535	CS786P	RR176	RR185	—
381700	CS786P	RR176	RR185	—
381710	CS786P	RR176	RR185	—
381775	CS2300	MA3	FA64	MA1
382124	CS786P	RR175	RR185	—
382127	CS786P	RR175	RR169R	RR215
383110	CS751	EP30	EP49	—
383581	CS788P	RR176	RR182R	RR181
383584	CS786P	RR175	RR185	—
383711	CS751	EP30	EP49	EP50
384193	CS2300	MA3	FA64	MA1
384254	CS788P	RR176	RR182R	RR181
384720	CS788P	RR176	RR182R	RR181

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
580534	CS788P	RR176	RR182R	RR181
979856	CS788P	RR176	RR182R	RR181
980156	CS788P	RR176	RR182R	RR183
980500	CS788P	RR176	RR182R	RR181
980680	CS2300	MA3	FA64	MA1
980902	CS720P	MO5000	AL125	AL168
981080	CS720P	MO5000	AL125	AL168
981659	CS2300	MA3	AL65	MA2
982320	CS720P	MO5000	AL125	AL168
982351	CS788P	RR176	RR182R	RR181
983453	CS2300	MA3	AL65	MA2
985560	CS2300	MA3	AL65	MA2

PORSCHE

Unit No	Contact Assembly	Condenser	Rotor	Cap
047905205B ...	—	—	EP278	—

⁹ Two required

RENAULT

Unit No	Contact Assembly	Condenser	Rotor	Cap
8542377	CS251	—	—	—
8544150	CS251	—	—	—
8544151	CS252	EP153	—	EP163
8544485	CS252	EP153	—	EP163
8544487	CS251	—	—	—
8549046	CS252	EP153	EP472	EP163
8549868	CS251	—	—	—
8549870	CS251	—	—	—
8549872	CS251	—	—	—
8554297	CS251	—	—	—
8556360	CS252	EP153	—	EP163
8556398	CS251	—	—	—
8556403	CS251	—	—	—
8556405	CS251	—	—	—
8557926	CS252	EP153	—	EP163
6000057302 ...	—	—	—	EP163
7700502165 ...	CS314	—	—	—
7700503831 ...	CS252	EP153	—	EP163
7700509132 ...	CS252	EP153	—	EP163
7700509133 ...	CS252	EP153	—	EP163
7700513423 ...	CS252	EP153	—	EP163
7700513425 ...	CS252	EP153	—	EP163
7700513427 ...	CS252	EP153	—	EP163
7700514359 ...	CS252	EP153	—	EP163
7700517042 ...	CS251	—	—	—
7700518586 ...	CS252	EP153	—	EP163
7700524691 ...	CS252	EP153	—	EP163
7700525424 ...	CS252	EP153	—	EP163
7700537066 ...	CS252	EP153	—	EP163
7700541873 ...	CS252	EP153	—	EP163

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
7700547699 ...	CS252	EP153	—	—
7700549050 ...	CS252	EP153	—	EP163
7700550056 ...	CS252	EP153	—	EP163
7700551465 ...	CS252	EP153	—	EP163
7700552516 ...	CS314	—	EP143	—
7700554382 ...	CS252	EP153	—	EP163
7700559113 ...	CS252	EP153	—	EP163
7700559114 ...	—	—	—	EP163
7700559147 ...	CS252	EP153	—	EP163
7700560225 ...	CS252	EP153	—	—
7700560482 ...	CS252	EP153	—	—
7700570355 ...	CS252	EP153	—	EP163
7700574809 ...	CS252	EP153	—	EP163
7700621030 ...	CS252	—	—	—
7700622062 ...	CS252	EP153	—	EP163
7700624965 ...	CS252	EP153	—	EP163
7700627824 ...	—	—	—	EP163
7700632899 ...	CS252	EP153	—	EP163
7700633332 ...	—	—	—	EP163
7700633939 ...	—	—	—	EP163
7700639141 ...	CS252	EP153	—	—
7700649728 ...	—	—	—	EP163
7700665436 ...	CS252	EP153	—	—
7700668068 ...	CS252	—	—	—
7700668426 ...	CS252	EP153	—	—
7701020090 ...	—	—	—	EP163
7701348260 ...	CS252	EP153	—	EP163

SAAB

Unit No	Contact Assembly	Condenser	Rotor	Cap
8308355	CS787	—	—	—
8309429	CS787	—	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
8352676	CS787	—	—	—

SEVELIER

Unit No	Contact Assembly	Condenser	Rotor	Cap
41350002	—	—	EP766	EP770

SIMCA

Unit No	Contact Assembly	Condenser	Rotor	Cap
S6543	CS251	EP125	—	—
S6805	CS251	EP125	—	—
S19915	CS251	EP125	—	—
S19916	CS252	EP153	—	—
S23702	CS251	—	—	—
S24152	CS252	EP153	—	—
S24173	CS252	FA83	—	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
S34889	CS252	FA83	—	—
S36255	CS252	FA83	—	—
S36807	CS252	FA83	—	—
S36818	CS252	FA83	—	—
S37975	CS252	FA83	—	—

SUBARU

Unit No	Contact Assembly	Condenser	Rotor	Cap
329870600	CS351	—	EP312	—
329874600	CS351	—	EP312	—
329878102	CS375	EP325	EP324	—

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
429871902	CS375	EP325	EP324	EP891
829877600	CS351	—	EP312	EP718

TOYOTA

Unit No	Contact Assembly	Condenser	Rotor	Cap
1610026200 ...	CS376	—	EP324	EP323
1910013090 ...	—	—	EP324	EP891
1910013091 ...	—	—	EP324	EP891
1910013240 ...	—	—	EP324	EP891
1910014030 ...	—	—	EP324	—
1910014031 ...	—	—	EP324	—
1910015030 ...	—	—	EP674	EP668
1910015050 ...	—	—	EP674	EP668
1910015060 ...	—	—	EP674	EP668
1910015061 ...	—	—	EP674	EP668
1910015070 ...	—	—	EP674	EP668
1910022010 ...	CS376	EP381	EP315	EP308
1910022020 ...	CS376	EP381	EP315	EP308
1910022030 ...	CS376	EP381	EP315	EP308
1910024010 ...	CS376	EP381	EP315	EP308
1910024011 ...	CS376	EP381	EP315	EP308
1910024012 ...	CS376	EP381	EP315	EP308
1910024013 ...	CS376	EP381	EP315	EP308
1910024130 ...	CS376	—	EP324	EP891
1910024140 ...	CS376	—	EP324	EP891
1910024141 ...	—	—	EP324	EP891
1910024160 ...	—	—	EP324	EP891
1910024180 ...	—	—	EP324	EP891
1910024200 ...	—	—	EP324	EP891
1910025010 ...	CS376	EP325	EP324	EP323
1910025011 ...	CS376	EP325	EP324	EP323
1910025012 ...	CS376	EP325	EP324	EP323

(continued on next column)

Unit No	Contact Assembly	Condenser	Rotor	Cap
1910026010 ...	CS376	EP325	EP324	EP323
1910026011 ...	CS376	EP325	EP324	EP323
1910026012 ...	CS376	EP325	EP324	EP323
1910026030 ...	CS376	EP325	EP324	EP323
1910026031 ...	CS376	EP325	EP324	EP323
1910026050 ...	CS376	EP325	EP324	EP323
1910026051 ...	CS376	EP325	EP324	EP323
1910026070 ...	CS376	EP325	EP324	EP323
1910026071 ...	CS376	EP325	EP324	EP323
1910026090 ...	CS368	EP378	EP324	EP323
1910026090 ...	CS369	EP378	EP324	EP323
1910026110 ...	CS376	—	EP324	EP323
1910026111 ...	CS376	—	EP324	EP891
1910026112 ...	CS376	—	EP324	EP891
1910026120 ...	CS376	—	EP324	EP323
1910026121 ...	CS376	—	EP324	EP891
1910026122 ...	CS376	—	EP324	EP891
1910026130 ...	CS368	EP378	EP324	EP323
1910026130 ...	CS369	EP378	EP324	EP323
1910026200 ...	CS376	—	EP324	EP323
1910026201 ...	CS376	—	EP324	EP891
1910026202 ...	CS376	—	EP324	EP891
1910026230 ...	CS376	—	EP324	EP891
1910026231 ...	—	—	EP324	EP891
1910026232 ...	—	—	EP324	EP891
1910026240 ...	CS376	—	EP324	EP891
1910026241 ...	—	—	EP324	EP891

(continued on next page)

TOYOTA (Cont'd)

Unit No	Contact Assembly	Condenser	Rotor	Cap	Unit No	Contact Assembly	Condenser	Rotor	Cap
1910026260 ...	—	—	EP324	EP891	1910038240 ...	—	—	EP674	EP671
1910026261 ...	—	—	EP324	EP891	1910038250 ...	—	—	EP674	EP671
1910026270 ...	—	—	EP324	EP891	1910038260 ...	—	—	EP674	EP671
1910026271 ...	—	—	EP324	EP891	1910038270 ...	—	—	EP674	EP671
1910026280 ...	—	—	EP324	EP891	1910038280 ...	—	—	EP674	EP671
1910026290 ...	—	—	EP324	EP891	1910040010 ...	CS353	EP381	EP314	EP318
1910028030 ...	—	—	EP674	EP669	1910040013 ...	CS353	EP316	EP314	—
1910028040 ...	—	—	EP674	EP669	1910040014 ...	CS353	EP381	EP315	EP308
1910028050 ...	—	—	EP674	EP669	1910040023 ...	CS353	EP316	EP314	—
1910028061 ...	—	—	EP674	EP669	1910040024 ...	CS353	EP316	EP314	—
1910028100 ...	—	—	EP674	EP669	1910040025 ...	CS353	EP381	EP315	EP308
1910034020 ...	CS353	EP381	EP315	EP308	1910040050 ...	CS353	EP381	EP315	EP308
1910034021 ...	CS376	EP325	EP324	EP323	1910040051 ...	CS353	EP381	EP315	EP308
1910034022 ...	CS376	EP325	EP324	EP323	1910041010 ...	CS376	EP381	EP314	EP318
1910034030 ...	CS353	EP381	EP315	EP308	1910041032 ...	CS376	EP381	EP314	EP318
1910034040 ...	CS353	EP381	EP315	EP308	1910042010 ...	CS376	EP381	EP314	EP318
1910034041 ...	CS376	EP325	EP324	EP323	1910042020 ...	CS376	EP381	EP314	EP318
1910034042 ...	CS376	EP325	EP324	EP323	1910042030 ...	CS376	EP381	EP314	EP318
1910034043 ...	CS376	EP325	EP324	EP323	1910045010 ...	CS376	—	EP314	EP318
1910034044 ...	CS376	EP325	EP324	EP323	1910045011 ...	CS376	EP381	EP314	EP318
1910034050 ...	CS353	EP381	EP315	EP308	1910045012 ...	CS376	—	EP314	EP318
1910034051 ...	CS376	EP325	EP324	EP323	1910045020 ...	CS376	—	EP314	EP318
1910034052 ...	CS376	EP325	EP324	EP323	1910045040 ...	CS376	—	EP314	EP318
1910034053 ...	CS376	EP325	EP324	EP323	1910045050 ...	CS376	EP381	EP314	EP318
1910034070 ...	CS376	EP325	EP324	EP323	1910045051 ...	CS376	EP379	EP314	EP318
1910034160 ...	CS368	EP378	EP324	EP323	1910045060 ...	CS376	—	EP376	EP377
1910034160 ...	CS369	EP378	EP324	EP323	1910045062 ...	CS376	—	EP376	EP377
1910034170 ...	CS376	EP325	EP324	EP323	1910045091 ...	CS376	—	EP376	EP377
1910035030 ...	—	—	EP674	EP671	1910045150 ...	—	—	EP376	EP388
1910035040 ...	—	—	EP674	EP671	1910045160 ...	—	—	EP376	EP388
1910038010 ...	CS376	—	EP324	EP323	1910060061 ...	CS353	EP316	EP314	EP318
1910038011 ...	CS376	—	EP324	EP323	1910060062 ...	CS353	EP381	EP314	EP318
1910038012 ...	CS376	—	EP324	EP323	1910060063 ...	CS353	EP381	EP314	EP318
1910038020 ...	CS376	—	EP324	EP323	1910060064 ...	CS353	EP381	EP314	EP318
1910038030 ...	CS376	—	EP324	EP323	1910060065 ...	CS353	EP381	EP314	EP318
1910038040 ...	—	—	EP324	EP891	1910060066 ...	CS376	EP381	EP314	EP318
1910038080 ...	—	—	EP324	EP891	1910060080 ...	CS376	—	EP376	EP377
1910038081 ...	—	—	EP324	—	1910061010 ...	CS376	EP316	EP314	EP318
1910038090 ...	—	—	EP324	EP891	1910061020 ...	CS376	—	EP376	EP377
1910038091 ...	—	—	EP324	—	1910061021 ...	CS376	—	EP376	EP377
1910038140 ...	—	—	EP324	EP891	1910061060 ...	CS376	—	EP376	EP377
1910038150 ...	—	—	EP324	—	1910061061 ...	—	—	EP376	EP670
1910038160 ...	—	—	EP324	EP891	1910061090 ...	CS376	EP316	EP314	EP318
1910038180 ...	—	—	EP324	—	1910061091 ...	—	—	EP376	EP670
1910038190 ...	—	—	EP324	—	1910061092 ...	—	—	EP376	—
1910038200 ...	—	—	EP324	—	1910061100 ...	—	—	EP376	EP670
1910038210 ...	—	—	EP674	EP671	1910061101 ...	—	—	EP376	—
1910038220 ...	—	—	EP674	EP671	1910061110 ...	—	—	EP379	EP670

(continued on next column)

VOLVO

Unit No	Contact Assembly	Condenser	Rotor	Cap	Unit No	Contact Assembly	Condenser	Rotor	Cap
463694	—	—	EP143	EP274	2431849	CS313	—	—	EP131
1219625	CS313P	EP446	—	EP274	2431864	CS313	—	EP143	EP131
1219661	CS313	EP446	EP278	—	2433142	CS313	EP446	EP143	EP131
1219848	—	—	EP143	EP274	2437648	CS313	EP446	EP143	EP131
1266478	CS313	EP446	EP278	—	4625513	CS314	EP284	EP143	EP274
2387314	CS303	EP147	—	EP131	4625521	CS313P	EP446	EP143	EP274
2394476	CS303	EP147	—	EP131	4626578	CS314	EP284	EP143	EP274
2394575	CS303	EP147	EP143	EP131	4627626	—	—	EP143	EP274
2399350	CS303	EP147	EP143	EP131	4628962	—	—	EP143	EP274
2402089	CS321	EP147	EP143	EP131	4636924	CS313	EP446	EP143	EP274
2412986	CS321	EP147	EP143	EP131	12186714	—	—	EP143	EP274
2415297	—	—	EP143	EP131	12186722	—	—	EP143	EP274
2415305	CS313	—	—	EP131	12196259	CS313	EP446	EP143	EP274
2415321	CS314	—	—	—	12196614	CS313	EP446	EP143	EP274
2431310	CS329	EP445	—	—	12664785	CS313	EP446	EP143	EP274

(continued on next column)

AMERICAN MOTORS

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
3163761	—	AC6P	AC6N	—
3167668	VR140	AC2P	AC2N	R426
3176579	—	—	—	R428
3182888	VR1004	—	—	R428
3182889	VR1004	—	—	R428
3184090	VR1004	—	—	R428
3184091	VR1004	—	—	R428
3184094	VR1004	—	—	R428
3189458	VR1004	—	—	R428
3189459	VR1004	—	—	R428
3191060	VR1004	—	—	R428
3195534	VR1005	—	—	R428
3195535	VR1005	—	—	R428
3199804	VR1005	—	—	R428
3199805	VR1005	—	—	R428
3199806	VR1005	—	—	R428
3204159	VR140	—	—	A439
3204215	VR140	AC2P	AC2N	R426

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
3206966	VR1004	—	—	A439
3207739	VR1004	—	—	A439
3207740	VR1004	—	—	A439
3207741	VR1004	—	—	A439
3527125	VR34	—	—	M401
4488289	VR1005	—	—	A439
4488290	VR1005	—	—	A439
4489410	—	—	—	A439
4489411	VR1005	—	—	A439
8122449	—	—	—	A439
8122450	—	—	—	A439
8125155	VR148	AC12	AC9	R437
8125949	VR1010	—	—	A439
8125995	—	—	—	A439
8126436	—	—	—	F417
8127023	VR148	AC12	AC9	R437

AUDI-VOLKSWAGEN

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
04993023R	VR506	—	—	M407
06893023S	—	—	—	M407
021903023E ...	VR503	—	—	E455
021903023F ...	VR503	—	—	E453
025903023	—	—	—	M407
025903023A ...	—	—	—	M407
025903023B ...	—	—	—	M407
025903023C ...	—	—	—	M407
025903023D ...	—	—	—	M407
025903023E ...	—	—	—	M407
026903015A ...	—	—	—	M407
026903015B ...	—	—	—	M407
026903015C ...	—	—	—	M407
026903015D ...	VR505	—	—	M407
026903015E ...	VR505	—	—	M407
026903015F ...	—	—	—	M407
026903023	—	—	—	M407
027903015A ...	—	—	—	M407
027903015C ...	—	—	—	M407
034903015	—	—	—	M407
034903015D ...	—	—	—	M407
034903015F ...	—	—	—	M407
034903015G ...	—	—	—	M407
034903015H ...	—	—	—	M407
034903015J ...	—	—	—	M407

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
034903015K ...	—	—	—	M407
034903016	—	—	—	M407
034903016A ...	—	—	—	M407
034903016D ...	—	—	—	M407
034903016G ...	—	—	—	M407
034903016H ...	—	—	—	M407
034903017	—	—	—	M407
035903015	VR510	—	—	E455
035903015A ...	VR510	—	—	E455
035903015B ...	VR510	—	—	E455
035903015D ...	VR510	—	—	E455
035903015E ...	VR510	—	—	E455
035903015G ...	VR510	—	—	E455
035903015J ...	VR505	—	—	A439
035903015K ...	—	—	—	M407
035903015L ...	—	—	AC50	E455
035903015M ...	—	—	—	M407
035903015N ...	—	—	—	M407
035903015P ...	—	—	—	M407
035903015Q ...	—	—	—	M407
035903015R ...	—	—	—	M407
035903015T ...	—	—	AC50	M407
035903016A ...	—	—	—	M407
035903016C ...	—	—	—	M407
035903023B ...	—	—	—	M407

(continued on next page)

AUDI-VOLKSWAGEN (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
035903023C ...	—	—	—	M407
035903023D ...	—	—	—	M407
035911023N ...	—	—	—	E552
043903023 ...	VR504	—	—	E455
043903023A ...	VR504	—	—	E455
043903023C ...	VR637	—	—	E455
043903023E ...	VR637	—	—	E455
043903027A ...	—	—	—	M407
047903015 ...	VR510	—	—	E455
049903015 ...	VR505	—	—	A439
049903015D ...	VR510	—	—	E455
049903015J ...	VR510	—	AC50	E455
049903023E ...	VR510	—	AC50	E455
049903023F ...	VR505	—	—	—
049903023G ...	VR510	—	AC50	E455
049903023H ...	VR505	—	—	A439
049903023J ...	—	—	AC50	E455
049903023K ...	—	—	AC50	M407
049903023L ...	—	—	AC50	M407
049903023M ...	—	—	—	M407
049903023N ...	—	—	—	M407
049903023R ...	—	—	AC50	M407
049903023S ...	VR505	—	—	—
049903023T ...	VR505	—	—	—
049903025 ...	—	—	AC50	M407
049903027 ...	—	—	—	M407
049903027A ...	—	—	—	M407
054903015J ...	—	—	—	M407
055903025B ...	—	—	—	M407
056903015B ...	VR510	—	AC50	E455
056903015C ...	VR510	—	—	E455
059903017D ...	VR510	—	—	E455
063903017 ...	VR510	—	—	E455
068903017C ...	VR510	—	—	E455
068903017D ...	VR510	—	—	E455
068903023A ...	VR505	—	—	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
068903023B ...	VR505	—	—	—
068903023C ...	VR505	—	—	—
068903023D ...	VR505	—	—	—
068903023H ...	VR510	—	AC50	E455
068903023K ...	—	—	AC50	M407
068903023M ...	—	—	—	M407
068903023R ...	—	—	AC50	M407
068903023S ...	—	—	—	M407
068903025F ...	VR505	—	—	A439
068903025H ...	—	—	—	M407
068903025J ...	—	—	—	M407
068903025K ...	—	—	—	M407
068903025L ...	—	—	—	M407
068903025R ...	—	—	AC50	M407
068903029E ...	—	—	—	M407
068903029F ...	—	—	—	M407
068903031 ...	—	—	—	M407
068903031B ...	—	—	—	M407
068903031E ...	VR505	—	—	M407
068903031F ...	VR505	—	—	M407
068903031G ...	VR505	—	—	M407
068903031H ...	VR505	—	—	M407
068903025F ...	VR505	—	—	A439
069903023A ...	—	—	—	M407
069903023C ...	—	—	—	M407
069903023D ...	—	—	—	M407
069903023G ...	—	—	—	M407
070903023B ...	VR510	—	—	E455
070903023C ...	VR510	—	—	E455
070903023E ...	—	—	AC50	—
076903023E ...	—	—	AC50	M407
077903015 ...	—	—	—	M407
077903015C ...	—	—	—	M407
176903027 ...	VR506	—	—	M407
176903029 ...	VR506	—	—	M407

AUTOLITE-PRESTOLITE

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
ALB5001 ...	VR32	—	—	—
ALB5002 ...	VR32	—	—	A409
ALB5003 ...	—	—	—	A409
ALB5003S ...	—	—	—	A409
ALB5004 ...	—	—	—	A409
ALB5102S1 ...	VR32	—	—	—
ALB5201 ...	VR1001	—	—	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
ALB5202 ...	VR1001	—	—	—
ALB5202S ...	VR1001	—	—	—
ALC5001 ...	—	AC6P	AC6N	—
ALD5001 ...	VR32	—	—	—
ALD5002 ...	VR32	—	—	—
ALD5002S ...	VR32	—	—	—
ALD5003 ...	VR32	—	—	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
ALD5004	VR32	—	—	—	ALE5209	—	—	AC6N	—
ALD5005	—	AC6P	AC6N	—	ALE5210	—	AC6P	AC6N	—
ALD5006	VR222	—	—	—	ALE5220	—	—	AC6N	—
ALD5007	VR222	—	—	—	ALE5220YS	VR1001	—	AC6N	—
ALD5101	—	AC6P	AC6N	—	ALE6009	VR222	—	AC6N	—
ALD5101S	VR32	—	—	—	ALE6010A	—	—	AC6N	—
ALE5001	VR32	—	AC6N	—	ALE6010S	—	—	AC6N	—
ALE5001S	VR32	—	AC6N	—	ALE6011B	—	—	AC6N	—
ALE5003A	—	—	AC6N	—	ALE6012	VR1014	—	AC6N	—
ALE5003B	VR32	—	—	—	ALE6012S	VR1014	—	AC6N	—
ALE5003C	VR136	—	—	—	ALE6013S	—	—	AC6N	—
ALE5003S	—	—	AC6N	—	ALE6020	VR1014	—	AC6N	—
ALE5004	VR222	—	AC6N	—	ALE6020S	VR1014	—	AC6N	—
ALE5004S	VR222	—	AC6N	—	ALE6207AY	VR1007	—	AC6N	—
ALE5005	VR222	—	AC6N	—	ALE6207Y	VR1007	—	AC6N	—
ALE5006	VR32	—	AC6N	—	ALE6207YS	VR1007	—	AC6N	—
ALE5006S	VR32	—	AC6N	—	ALE6221AY	VR1007	—	AC6N	—
ALE5007	VR222	—	AC6N	—	ALE6221Y	VR1007	—	AC6N	—
ALE5007S	VR222	—	—	—	ALE6221YS	VR1007	—	AC6N	—
ALE5014	—	—	AC6N	—	ALE6303	VR1002	—	AC6N	—
ALE5022	—	—	AC6N	—	ALE6304	VR1004	—	AC6N	—
ALE5101	VR123	AC6P	—	—	ALE6304S	VR1004	—	AC6N	—
ALE5101A	VR222	—	—	—	ALE6305	VR1004	—	AC6N	—
ALE5101P	VR123	AC6P	—	—	ALE6305S	VR1004	—	AC6N	—
ALE5101PS	VR123	AC6P	—	—	ALE6306	VR1004	—	AC6N	—
ALE5101S	—	—	AC6N	—	ALE6306S	VR1004	—	AC6N	—
ALE5102S	VR32	—	—	—	ALE6401S	—	—	AC6N	—
ALE5104PS1	—	AC6P	—	—	ALE6403A	—	—	AC6N	—
ALE5104S1	—	—	AC6N	—	ALE6404B	—	—	AC6N	—
ALE5106	—	—	AC6N	—	ALE6406	—	—	AC6N	—
ALE5120	—	—	AC6N	—	ALE6406G	—	—	AC6N	—
ALE5201A	VR222	—	AC6N	—	ALE6406R	—	—	AC6N	—
ALE5201B	—	—	AC6N	—	ALE6406RG	—	—	AC6N	—
ALE5201C	VR222	—	AC6N	—	ALE6420	—	—	AC6N	—
ALE5201PS1	VR32	—	—	—	ALE6420G	—	—	AC6N	—
ALE5201S	VR222	—	AC6N	—	ALE6420R	—	—	AC6N	—
ALE5201S1	—	—	AC6N	—	ALE6420RG	—	—	AC6N	—
ALE5201SS	VR222	—	AC6N	—	ALE7012	VR1014	—	AC6N	—
ALE5202	VR222	—	AC6N	—	ALE7020	VR1014	—	AC6N	—
ALE5202B	VR222	—	AC6N	—	ALE8105A	—	—	AC6N	—
ALE5202S	VR222	—	AC6N	—	ALE8406	—	—	AC6N	—
ALE5202Y	VR222	—	AC6N	—	ALE8406G	—	—	AC6N	—
ALE5202YS	VR222	—	AC6N	—	ALE8406R	—	—	AC6N	—
ALE5203	VR1008	—	AC6N	—	ALE8406RG	—	—	AC6N	—
ALE5203A	VR1008	—	AC6N	—	ALE8408	—	—	AC6N	—
ALE5203S	VR1008	—	AC6N	—	ALE8408R	—	—	AC6N	—
ALE5204	VR1001	—	AC6N	—	ALE8420	—	—	AC6N	—
ALE5204S	VR1001	—	AC6N	—	ALE8420G	—	—	AC6N	—

(continued on next column)

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
ALE8420R	—	—	AC6N	—	ALH6322	VR1015	—	AC6N	—
ALE8420RG	—	—	AC6N	—	ALH6322S	VR1015	—	AC6N	—
ALE8421	—	—	AC6N	—	ALH6401S	—	—	AC6N	—
ALE8421R	—	—	AC6N	—	ALH7005	VR1014	—	AC6N	—
ALF5101	VR222	—	AC6N	—	ALH7305	VR1015	—	AC6N	—
ALF5101S	VR222	—	AC6N	—	ALH7306	VR1015	—	AC6N	—
ALF5201	VR222	—	AC6N	—	ALH7306S	VR1015	—	AC6N	—
ALF5201A1	—	—	AC6N	—	ALH7307	VR1015	—	AC6N	—
ALF5201B	VR222	—	AC6N	—	ALH7307A	VR1015	—	AC6N	—
ALF5201P	—	AC6P	—	—	ALH7307B	VR1015	—	AC6N	—
ALF5201S	VR222	—	AC6N	—	ALH7321	VR1015	—	AC6N	—
ALF52011	—	—	AC6N	—	ALH7321A	VR1015	—	AC6N	—
ALG5101A	VR222	—	AC6N	—	ALH7321B	VR1015	—	AC6N	—
ALG5101AS	VR222	—	AC6N	—	ALH7322	VR1015	—	AC6N	—
ALG5101S	VR428	—	—	—	ALH7322S	VR1015	—	AC6N	—
ALG5102	VR222	—	—	—	ALI5101S	VR412	—	—	—
ALH5101S	—	—	AC6N	—	ALI5102S1	—	—	AC6N	—
ALH5103	VR222	—	—	—	ALJ5101S	VR1015	—	AC6N	—
ALH5104PS1	—	AC6P	—	—	ALJ5102PS1	—	AC6P	—	—
ALH5104S1	—	—	AC6N	—	ALJ5102S1	—	—	AC6N	—
ALH5105	—	—	AC6N	—	ALK5001	VR32	—	—	—
ALH5105S	—	—	AC6N	—	ALK5001A	VR32	—	—	—
ALH5106S	—	—	AC6N	—	ALK5001B	VR32	—	—	—
ALH5107	—	—	AC6N	—	ALK5001C	VR32	—	—	—
ALH5120	—	—	AC6N	—	ALK5001D	VR32	—	AC6N	—
ALH5307	VR1015	—	AC6N	—	ALK5001S	—	—	AC6N	—
ALH5307A	VR1015	—	AC6N	—	ALK5001S1	—	—	AC6N	—
ALH5307AS	VR1015	—	AC6N	—	ALK5001ST	—	—	AC6N	—
ALH5307B	VR1015	—	AC6N	—	ALK5003	—	AC6P	AC6N	—
ALH5307S	VR1015	—	AC6N	—	ALK5005A	VR32	—	AC6N	—
ALH5321	VR1015	—	AC6N	—	ALK5101	—	—	AC6N	—
ALH5321A	VR1015	—	AC6N	—	ALK5101S	—	—	AC6N	—
ALH5321B	VR1015	—	AC6N	—	ALK5101S1	—	—	AC6N	—
ALH5321S	VR1015	—	AC6N	—	ALK5101ST	—	—	AC6N	—
ALH5406	—	—	AC6N	—	ALK5201S	VR222	—	AC6N	—
ALH5420	—	—	AC6N	—	ALK5202	VR222	—	AC6N	—
ALH6003	VR32	—	AC6N	—	ALK5202Y	VR222	—	AC6N	—
ALH6004	VR32	—	AC6N	—	ALK5202YS	VR222	—	AC6N	—
ALH6005	VR1014	—	AC6N	—	ALK5205	VR1001	—	AC6N	—
ALH6303	VR1002	—	AC6N	—	ALK5205Y	—	—	AC6N	—
ALH6304	VR1004	—	AC6N	—	ALK5205YS	—	—	AC6N	—
ALH6304S	VR1004	—	AC6N	—	ALK5206	VR1008	—	AC6N	—
ALH6305	VR1015	—	AC6N	—	ALK5206S	—	—	AC6N	—
ALH6305S	VR1015	—	AC6N	—	ALK5228YS	VR222	—	AC6N	—
ALH6306	VR1015	—	AC6N	—	ALK6003	VR32	—	AC6N	—
ALH6306S	VR1015	—	AC6N	—	ALK6004	VR1014	—	AC6N	—
ALH6320	VR1015	—	AC6N	—	ALK6004A	—	—	AC6N	—
ALH6320S	VR1015	—	AC6N	—	ALK6006	VR1014	—	AC6N	—

(continued on next column)

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
ALK6020	VR1014	—	AC6N	—	ALK6307	VR1015	—	AC6N	—
ALK6020A	—	—	AC6N	—	ALK6307S	VR1015	—	AC6N	—
ALK6022	VR1014	—	AC6N	—	ALK6308	VR1011	—	AC6N	—
ALK6204	—	—	AC6N	—	ALK6308S	VR1011	—	AC6N	—
ALK6204A	VR222	—	AC6N	—	ALK6309	—	—	AC6N	—
ALK6204AY	VR1001	—	AC6N	—	ALK6309S	—	—	AC6N	—
ALK6204AYS	VR1001	—	AC6N	—	ALK6310	—	—	AC6N	—
ALK6204S	VR222	—	AC6N	—	ALK6310A	—	—	AC6N	—
ALK6204YS	—	—	AC6N	—	ALK6310S	—	—	AC6N	—
ALK6207	VR1008	—	AC6N	—	ALK6310S1	—	—	AC6N	—
ALK6207S	VR1008	—	AC6N	—	ALK6311	—	—	AC6N	—
ALK6208	—	—	AC6N	—	ALK6311A	—	—	AC6N	—
ALK6208P	—	AC6P	—	—	ALK6311S	—	—	AC6N	—
ALK6209Y	VR1007	—	AC6N	—	ALK6311S1	—	—	AC6N	—
ALK6209YS	VR1007	—	AC6N	—	ALK6312	VR1005	—	AC6N	—
ALK6210	VR1006	—	AC6N	—	ALK6312A	VR1005	—	AC6N	—
ALK6210A	VR1006	—	AC6N	—	ALK6312S	VR1005	—	AC6N	—
ALK6210AS	VR1006	—	AC6N	—	ALK6312S1	VR1005	—	AC6N	—
ALK6210S	VR1006	—	AC6N	—	ALK6313	VR1005	—	AC6N	—
ALK6211A	VR1016	—	AC6N	—	ALK6313A	VR1005	—	AC6N	—
ALK6211AS	VR1016	—	AC6N	—	ALK6313S	VR1005	—	AC6N	—
ALK6211S	VR1016	—	AC6N	—	ALK6313S1	VR1005	—	AC6N	—
ALK6212Y	—	—	AC6N	—	ALK6314	VR1015	—	AC6N	—
ALK6212YS	—	—	AC6N	—	ALK6314S	VR1015	—	AC6N	—
ALK6220Y	—	—	AC6N	—	ALK6315S	VR1011	—	AC6N	—
ALK6220YS	—	—	AC6N	—	ALK6320	VR1011	—	AC6N	—
ALK6221A	VR1016	—	AC6N	—	ALK6320S	VR1011	—	AC6N	—
ALK6221AS	VR1016	—	AC6N	—	ALK6321	VR1011	—	AC6N	—
ALK6221S	VR1016	—	AC6N	—	ALK6321A	VR1011	—	AC6N	—
ALK6222	VR1006	—	AC6N	—	ALK6321S	VR1011	—	AC6N	—
ALK6222A	VR1006	—	AC6N	—	ALK6322	VR1015	—	AC6N	—
ALK6222AS	—	—	AC6N	—	ALK6322S	VR1015	—	AC6N	—
ALK6222AY	VR1006	—	AC6N	—	ALK6323S	VR1011	—	AC6N	—
ALK6222AYS	VR1006	—	AC6N	—	ALK6402	VR222	—	AC6N	—
ALK6222Y	VR1006	—	AC6N	—	ALK6403	VR32	—	AC6N	—
ALK6223	VR1008	—	AC6N	—	ALK6403S	VR32	—	AC6N	—
ALK6223S	VR1008	—	AC6N	—	ALK7004	VR1014	—	AC6N	—
ALK6223YS	VR1008	—	AC6N	—	ALK7006	VR1014	—	AC6N	—
ALK6225Y	—	—	AC6N	—	ALK7022	VR1014	—	AC6N	—
ALK6225YS	VR1007	—	AC6N	—	ALK7211A	VR1016	—	AC6N	—
ALK6302	VR1002	—	AC6N	—	ALK7211AS	VR1016	—	AC6N	—
ALK6304	VR1004	—	AC6N	—	ALK7211S	—	—	AC6N	—
ALK6304S	VR1004	—	AC6N	—	ALK7221A	VR1016	—	AC6N	—
ALK6305	VR1011	—	AC6N	—	ALK7221AS	VR1016	—	AC6N	—
ALK6305S	VR1011	—	AC6N	—	ALK7305	VR1011	—	AC6N	—
ALK6306	VR1011	—	AC6N	—	ALK7305S	VR1011	—	AC6N	—
ALK6306A	VR1011	—	AC6N	—	ALK7306A	VR1011	—	AC6N	—
ALK6306S	VR1011	—	AC6N	—	ALK7306AS	VR1011	—	AC6N	—

(continued on next column)

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
ALK7306S	—	—	AC6N	—	ALX8403	—	—	AC6N	—
ALK7307	VR1015	—	AC6N	—	ALX8403G	—	—	AC6N	—
ALK7308	VR1011	—	AC6N	—	ALX8403LS	—	—	AC6N	—
ALK7314	VR1015	—	AC6N	—	ALX8403LSG ..	—	—	AC6N	—
ALK7315S	VR1011	—	AC6N	—	ALX8403R	—	—	AC6N	—
ALK7320	VR1011	—	AC6N	—	ALX8403RG	—	—	AC6N	—
ALK7320S	VR1011	—	AC6N	—	ALX8403RS	—	—	AC6N	—
ALK7321A	VR1011	—	AC6N	—	ALX8403RSG ..	—	—	AC6N	—
ALK7321AS	VR1011	—	AC6N	—	ALX8421	—	—	AC6N	—
ALK7322	VR1015	—	AC6N	—	ALX8421G	—	—	AC6N	—
ALK7323S	VR1011	—	AC6N	—	ALX8421LRS ..	—	—	AC6N	—
ALK52021	VR222	—	AC6N	—	ALX8421LSG ..	—	—	AC6N	—
ALK63111	—	—	AC6N	—	ALX8421R	—	—	AC6N	—
ALL5201A	—	—	AC6N	—	ALX8421RG	—	—	AC6N	—
ALL5201S	—	—	AC6N	—	ALX8421RSG ..	—	—	AC6N	—
ALM5101	—	AC6P	AC6N	—	ALX9402	—	—	AC6N	—
ALM5102S1	—	—	AC6N	—	ALX9404L	—	—	AC6N	—
ALM5103	—	—	AC6N	—	ALX9404LG	—	—	AC6N	—
ALM5201S1	—	—	AC6N	—	ALX9404R	—	—	AC6N	—
ALP5201	VR222	—	AC6N	—	ALX9404RG	—	—	AC6N	—
ALT5101A	—	—	AC6N	—	ALX9405	—	—	AC6N	—
ALT5102S	—	—	AC6N	—	ALX9422L	—	—	AC6N	—
ALT8403	—	—	AC6N	—	ALX9422LG	—	—	AC6N	—
ALT8404	—	—	AC6N	—	ALX9422R	—	—	AC6N	—
ALT8404LS	—	—	AC6N	—	ALX9422RG	—	—	AC6N	—
ALT8404R	—	—	AC6N	—	ALX9424	—	—	AC6N	—
ALT8404RS	—	—	AC6N	—	ALX9425	—	—	AC6N	—
ALT8407	—	—	AC6N	—	ALX9425A	—	—	AC6N	—
ALT8420	—	—	AC6N	—	ALX9425B	—	—	AC6N	—
ALT8421	—	—	AC6N	—	ALY6403	—	—	AC6N	—
ALT8421LS	—	—	AC6N	—	ALY6403G	—	—	AC6N	—
ALT8421R	—	—	AC6N	—	ALY6403R	—	—	AC6N	—
ALT8421RS	—	—	AC6N	—	ALY6403RG	—	—	AC6N	—
ALT9405	—	—	AC6N	—	ALY6406	—	—	AC6N	—
ALT9422	—	—	AC6N	—	ALY6406G	—	—	AC6N	—
ALU8403	—	—	AC6N	—	ALY6406R	—	—	AC6N	—
ALU8403LS	—	—	AC6N	—	ALY6406RG	—	—	AC6N	—
ALU8403R	—	—	AC6N	—	ALY6407	—	AC6P	AC6N	—
ALU8403RS	—	—	AC6N	—	ALY6408	—	—	AC6N	—
ALU8421	—	AC6P	AC6N	—	ALY6409	—	—	AC6N	—
ALU8421LS	—	AC6P	AC6N	—	ALY6412	—	—	AC6N	—
ALU8421R	—	AC6P	AC6N	—	ALY6420	—	—	AC6N	—
ALU8421RS	—	AC6P	AC6N	—	ALY6420G	—	—	AC6N	—
ALU9404L	—	—	AC6N	—	ALY6420R	—	—	AC6N	—
ALU9404R	—	—	AC6N	—	ALY6420RG	—	—	AC6N	—
ALX6406	—	AC6P	AC6N	—	ALY6421	—	—	AC6N	—
ALX6408	—	—	AC6N	—	ALY6422	—	—	AC6N	—
ALX6423	—	—	AC6N	—	ALY6425	—	—	AC6N	—

(continued on next column)

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
ALY6427	—	—	AC6N	—	ALY8426RG ...	—	—	AC6N	—
ALY6427G	—	—	AC6N	—	ALZ8401	—	—	AC6N	—
ALY6427R	—	—	AC6N	—	ALZ8401G	—	—	AC6N	—
ALY6427RG ...	—	—	AC6N	—	ALZ8401R	—	—	AC6N	—
ALY8402	—	—	AC6N	—	ALZ8401RG ...	—	—	AC6N	—
ALY8403	—	—	AC6N	—	ALZ8423	—	—	AC6N	—
ALY8403G	—	—	AC6N	—	ALZ8423G	—	—	AC6N	—
ALY8403LS	—	—	AC6N	—	ALZ8423R	—	—	AC6N	—
ALY8403LSG ..	—	—	AC6N	—	ALZ8423RG ...	—	—	AC6N	—
ALY8403R	—	—	AC6N	—	ANA6201	—	—	AC6N	—
ALY8403RG ...	—	—	AC6N	—	ANA6201P	—	AC6P	—	—
ALY8403RS ...	—	—	AC6N	—	ANA6220	—	—	AC6N	—
ALY8403RSG ..	—	—	AC6N	—	ANA6220P	—	AC6P	—	—
ALY8405	—	—	AC6N	—	ANC6601	VR1014	—	AC6N	—
ALY8405G	—	—	AC6N	—	ANC6601S	VR1014	—	AC6N	—
ALY8405R	—	—	AC6N	—	ANC6620	VR1014	—	AC6N	—
ALY8405RG ...	—	—	AC6N	—	ANC6620S	VR1014	—	AC6N	—
ALY8410	—	—	AC6N	—	ANC7601	VR1014	—	AC6N	—
ALY8410R	—	—	AC6N	—	ANC7601S	VR1014	—	AC6N	—
ALY8411	—	—	AC6N	—	ANC7620	VR1014	—	AC6N	—
ALY8420	—	—	AC6N	—	ANC7620S	VR1014	—	AC6N	—
ALY8420G	—	—	AC6N	—	ANE5201S	VR1001	—	AC6N	—
ALY8420LS	—	—	AC6N	—	ANE5202S	VR1001	—	AC6N	—
ALY8420LSG ..	—	—	AC6N	—	ANE5202YS ...	VR1001	—	AC6N	—
ALY8420R	—	—	AC6N	—	ANG6401	—	—	AC6N	—
ALY8420RG ...	—	—	AC6N	—	ANG6402	—	—	AC6N	—
ALY8420RS ...	—	—	AC6N	—	ANG6423	—	—	AC6N	—
ALY8420RSG ..	—	—	AC6N	—	ANG6423S	—	—	AC6N	—
ALY8423	—	—	AC6N	—	ANK5201	VR1006	—	AC6N	—
ALY8423R	—	—	AC6N	—	ANK5201S	VR1006	—	AC6N	—
ALY8424	—	—	AC6N	—	ANK5201Y	VR1006	—	AC6N	—
ALY8426	—	—	AC6N	—	ANK5201YS ...	VR1006	—	AC6N	—
ALY8426G	—	—	AC6N	—	AWA6201	VR32	—	—	—
ALY8426R	—	—	AC6N	—					

(continued on next column)

BMW

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
12311288409 ..	VR639	—	—	—	12311730753 ..	VR639	—	—	—
12311289403 ..	VR639	—	—	M407	12311735403 ..	VR639	—	—	—
12311309801 ..	VR639	—	—	—	12311735704 ..	VR506	—	—	M407
12311310075 ..	VR639	—	—	—	12311735706 ..	VR506	—	—	M407
12311706056 ..	VR639	—	—	M407					
12311726602 ..	VR639	—	—	M407					
12311726603 ..	VR639	—	—	—					

(continued on next column)

BOSCH

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
0001362029 ...	—	—	—	E521
0031510701 ...	—	—	—	E516
0031515001 ...	—	—	—	E517
0041513501 ...	—	—	—	E518
0041513701 ...	—	—	—	E517
0041514401 ...	—	—	—	E518
0041514501 ...	—	—	—	E517
0041515201 ...	—	—	—	E518
0041515601 ...	—	—	—	E518
0041516301 ...	—	—	—	E518
0041516501 ...	—	—	—	E517
0041516701 ...	—	—	—	E518
0120300511 ...	—	—	—	E455
0120300514 ...	—	—	—	E455
0120300529 ...	VR503	—	—	E455
0120300530 ...	VR503	—	—	E455
0120300531 ...	VR503	—	—	E455
0120300552 ...	VR503	—	—	E455
0120300558 ...	VR503	—	—	E455
0120300559 ...	VR503	—	—	E455
0120300562 ...	—	—	—	E455
0120300568 ...	VR503	—	—	E455
0120300569 ...	VR503	—	—	E455
0120340001 ...	VR503	—	—	E453
0120400504 ...	VR503	—	—	E453
0120400505 ...	VR503	—	—	E453
0120400510 ...	VR503	—	—	E453
0120400522 ...	VR503	—	—	E453
0120400523 ...	—	—	—	E453
0120400526 ...	VR503	—	—	E453
0120400528 ...	VR503	—	—	E453
0120400530 ...	VR503	—	—	E453
0120400531 ...	VR503	—	—	E453
0120400535 ...	VR503	—	—	E453
0120400537 ...	VR503	—	—	E453
0120400545 ...	—	—	—	E453
0120400547 ...	VR503	—	—	E453
0120400548 ...	VR503	—	—	E453
0120400553 ...	VR503	—	—	E453
0120400555 ...	VR503	—	—	E453
0120400565 ...	VR503	—	—	E453
0120400566 ...	—	—	—	E453
0120400600 ...	VR503	—	—	E453
0120400601 ...	VR503	—	—	E453
0120400603 ...	VR503	—	—	E453
0120400604 ...	VR503	—	—	E453
0120400605 ...	VR503	—	—	E453
0120400606 ...	VR503	—	—	E453

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
0120400607 ...	VR503	—	—	E453
0120400608 ...	VR503	—	—	E453
0120400609 ...	VR503	—	—	E453
0120400611 ...	VR503	—	—	E453
0120400614 ...	VR503	—	—	E453
0120400615 ...	VR503	—	—	E453
0120400620 ...	VR503	—	—	E453
0120400621 ...	VR503	—	—	E453
0120400622 ...	VR503	—	—	E453
0120400623 ...	VR503	—	—	E453
0120400627 ...	VR503	—	—	E453
0120400628 ...	VR503	—	—	E453
0120400629 ...	VR503	—	—	E453
0120400630 ...	VR503	—	—	E453
0120400631 ...	VR503	—	—	E453
0120400633 ...	—	—	—	E453
0120400634 ...	VR503	—	—	E453
0120400635 ...	VR503	—	—	E453
0120400637 ...	VR503	—	—	E453
0120400640 ...	—	—	—	E453
0120400647 ...	VR503	—	—	E453
0120400648 ...	VR503	—	—	E453
0120400649 ...	VR503	—	—	E453
0120400650 ...	VR503	—	—	E453
0120400654 ...	VR503	—	—	E453
0120400655 ...	VR503	—	—	E453
0120400656 ...	VR503	—	—	E453
0120400657 ...	VR503	—	—	E453
0120400658 ...	VR503	—	—	E453
0120400659 ...	VR503	—	—	E453
0120400665 ...	VR503	—	—	E455
0120400670 ...	VR503	—	—	E455
0120400679 ...	VR503	—	—	E453
0120400680 ...	VR503	—	—	E453
0120400683 ...	—	—	—	E453
0120400684 ...	—	—	—	E453
0120400685 ...	—	—	—	E453
0120400686 ...	VR503	—	—	E453
0120400687 ...	VR503	—	—	E453
0120400690 ...	—	—	—	E453
0120400691 ...	VR503	—	—	E453
0120400692 ...	VR503	—	—	E453
0120400693 ...	VR503	—	—	E453
0120400699 ...	—	—	—	E453
0120400700 ...	—	—	—	E453
0120400702 ...	VR503	—	—	E453
0120400703 ...	VR503	—	—	E453
0120400704 ...	VR503	—	—	E455

(continued on next page)

BOSCH (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
0120400705 ...	VR503	—	—	—
0120400712 ...	VR503	—	—	E453
0120400713 ...	VR503	—	—	E453
0120400716 ...	—	—	—	E453
0120400717 ...	VR503	—	—	E453
0120400719 ...	VR503	—	—	E453
0120400721 ...	VR503	—	—	E453
0120400722 ...	VR503	—	—	E455
0120400723 ...	VR503	—	—	E455
0120400724 ...	VR503	—	—	E455
0120400725 ...	VR503	—	—	E455
0120400726 ...	VR503	—	—	E453
0120400728 ...	VR503	—	—	E453
0120400729 ...	VR503	—	—	E453
0120400730 ...	VR503	—	—	E453
0120400731 ...	VR503	—	—	E453
0120400733 ...	VR503	—	—	E455
0120400737 ...	VR503	—	—	E453
0120400740 ...	VR503	—	—	E455
0120400741 ...	VR503	—	—	E455
0120400742 ...	VR503	—	—	E455
0120400743 ...	VR503	—	—	E455
0120400750 ...	VR503	—	—	E455
0120400751 ...	VR503	—	—	E455
0120400752 ...	VR503	—	—	E453
0120400753 ...	VR503	—	—	E453
0120400755 ...	—	—	—	E453
0120400756 ...	VR503	—	—	E453
0120400757 ...	VR503	—	—	E453
0120400758 ...	VR503	—	—	E455
0120400759 ...	VR503	—	—	E455
0120400760 ...	—	—	—	E455
0120400761 ...	—	—	—	E455
0120400763 ...	—	—	—	E455
0120400764 ...	VR503	—	—	E453
0120400765 ...	VR503	—	—	E453
0120400767 ...	VR503	—	—	E455
0120400768 ...	VR503	—	—	E455
0120400771 ...	VR503	—	—	E455
0120400772 ...	VR503	—	—	E455
0120400776 ...	VR503	—	—	E453
0120400777 ...	VR503	—	—	E453
0120400782 ...	VR503	—	—	E455
0120400783 ...	VR503	—	—	E455
0120400786 ...	VR503	—	—	E453
0120400787 ...	VR503	—	—	E453
0120400790 ...	—	—	—	E453
0120400791 ...	—	—	—	E453

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
0120400794 ...	VR503	—	—	E453
0120400795 ...	VR503	—	—	E453
0120400796 ...	—	—	—	E453
0120400799 ...	—	—	—	E453
0120400800 ...	—	—	—	E453
0120400803 ...	VR503	—	—	E453
0120400804 ...	VR503	—	—	E453
0120400806 ...	VR510	—	—	E455
0120400807 ...	VR503	—	—	—
0120400808 ...	VR503	—	—	E455
0120400809 ...	VR503	—	—	E455
0120400815 ...	VR503	—	—	E453
0120400816 ...	VR503	—	—	E453
0120400824 ...	VR503	—	—	E453
0120400832 ...	VR503	—	—	E455
0120400840 ...	VR503	—	—	E455
0120400841 ...	VR503	—	—	E455
0120400847 ...	VR503	—	—	E453
0120400848 ...	VR503	—	—	E453
0120400849 ...	VR503	—	—	E455
0120400850 ...	VR503	—	—	E455
0120400856 ...	VR503	—	—	E455
0120400857 ...	VR503	—	—	E455
0120400858 ...	VR503	—	—	E455
0120400859 ...	VR503	—	—	E455
0120400860 ...	VR503	—	—	E455
0120400861 ...	VR503	—	—	—
0120400864 ...	VR503	—	—	E455
0120400865 ...	VR503	—	—	E455
0120400868 ...	VR503	—	—	—
0120400869 ...	VR503	—	—	—
0120400870 ...	VR503	—	—	E453
0120400871 ...	VR503	—	—	E453
0120400872 ...	VR503	—	—	—
0120400873 ...	VR503	—	—	—
0120400895 ...	—	—	—	E453
0120400898 ...	VR503	—	—	—
0120400899 ...	VR503	—	—	—
0120400913 ...	—	—	—	E455
0120400922 ...	VR503	—	—	E453
0120400933 ...	VR510	—	—	E455
0120450001 ...	VR503	—	—	E455
0120450003 ...	VR503	—	—	E455
0120450004 ...	VR503	—	—	E455
0120469500 ...	—	—	—	E455
0120469502 ...	—	—	—	E455
0120469503 ...	—	—	—	E455
0120489029 ...	VR510	—	—	—

(continued on next page)

BOSCH (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
0120489031 ...	VR510	—	—	—
0120489040 ...	VR510	—	—	—
0120489064 ...	VR510	—	—	—
0120489500 ...	—	—	—	E455
0120489501 ...	—	—	—	E455
0120489519 ...	—	—	—	E455
0120489520 ...	—	—	—	E455
0120489521 ...	—	—	—	E455
0120489523 ...	—	—	—	E455
0120489526 ...	VR510	—	—	E455
0120489527 ...	—	—	—	E455
0120489532 ...	—	—	—	E455
0120489533 ...	—	—	—	E455
0120489535 ...	—	—	—	E455
0120489541 ...	—	—	—	E455
0120489542 ...	—	—	—	E455

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
0120489547 ...	—	—	—	E455
0120489549 ...	—	—	—	E455
0120489550 ...	—	—	—	E455
0120489556 ...	VR510	—	—	E455
0120489559 ...	—	—	—	E455
0120489560 ...	—	—	—	E455
0120489562 ...	—	—	—	E455
0120489565 ...	VR637	—	—	E455
0120489595 ...	—	—	—	E455
0120489601 ...	—	—	—	E455
0120489602 ...	—	—	—	E455
0120489609 ...	—	—	—	E455
0120489667 ...	VR506	—	—	—
0120489669 ...	VR503	—	—	—
0120489671 ...	VR503	—	—	—
0120489932 ...	VR510	—	—	—

(continued on next column)

CHRYSLER (ALSO SEE MITSUBISHI)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Capacitor
MD003501	VR1064	—	—	E484	—
MD003502	VR1064	—	—	E484	—
MD003511	VR1064	—	—	E486	—
MD003512	VR1064	—	—	E486	—
MD003516	VR1064	—	—	E486	—
MD006187	—	—	—	E486	—
MD007509	—	—	—	E486	—
MD009053	—	—	—	E486	—
MD009070	VR1064	—	—	E480	—
MD009071	—	—	—	E480	—
MD021650	VR1064	—	—	E486	—
MD021651	VR1064	—	—	E486	—
MD021660	VR1064	—	—	E486	—
MD021668	VR1064	—	—	E486	—
MD022570	VR1064	—	—	E486	—
MD022572	—	—	—	E486	—
MD022578	—	—	—	E486	—
MD025215	—	AC30 ⁹	—	—	—
MD025679	VR595	AC38 ⁹	—	—	—
MD062007	VR595	AC30 ⁹	—	—	—
MD063781	VR595	AC39 ⁹	—	—	—
MD064066	VR595	AC39 ⁹	—	—	—
MD086048	VR595	—	—	—	—
MD607100	—	—	—	E480	—
2095000	—	AC6P	AC6N	M400	—
2095060	—	AC6P	AC6N	M400	—
2095100	—	AC6P	AC6N	M400	—

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Capacitor
2095300	—	AC6P	AC6N	M400	—
2095320	—	AC6P	AC6N	M400	—
2095425	VR32	—	—	M400	—
2095661	VR32	—	—	M400	—
2095663	VR32	—	—	M400	—
2095666	VR32	—	—	M400	—
2095667	VR32	—	—	M400	—
2095850	VR32	—	—	M400	—
2095857	VR32	—	—	—	—
2095860	VR32	—	—	—	—
2098256	VR32	—	—	M400	—
2098260	VR32	—	—	M400	—
2098262	VR32	—	—	M400	—
2098265	VR32	—	—	M400	—
2098268	VR32	—	—	M400	—
2098270	VR32	—	—	M400	—
2098275	VR32	—	—	M400	—
2098290	VR32	—	—	M400	—
2098319	VR32	—	—	M400	—
2098320	VR32	—	—	M400	—
2098330	VR32	—	—	M400	—
2098394	VR32	—	—	—	—
2098395	VR32	—	—	—	—
2098525	VR32	AC6P	AC6N	M400	—
2098530	VR32	AC6P	AC6N	M400	—
2098535	VR32	AC6P	AC6N	M400	—
2098615	VR32	—	—	—	—

(continued on next column)

(continued on next page)

⁹ Two required

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Capacitor
2098724	VR32	—	—	M400	—
2098725	—	AC6P	AC6N	M400	—
2098824	VR32	—	—	M400	—
2098825	VR32	—	—	M400	—
2098830	VR32	AC6P	AC6N	M400	—
2098835	VR32	AC6P	AC6N	M400	—
2098840	VR32	—	—	M400	—
2098845	VR32	—	—	M400	—
2098850	VR32	AC6P	AC6N	M400	—
2098855	VR32	AC6P	AC6N	M400	—
2098860	VR32	—	—	M400	—
2098865	VR32	—	—	M400	—
2098870	VR32	—	—	M400	—
2098875	VR32	—	—	M400	—
2098880	VR32	—	—	M400	—
2299306	VR32	—	—	M400	—
2444369	VR154	—	—	R431	—
2444370	—	—	—	R431	—
2444420	VR154	—	—	R431	—
2444437	VR32	—	—	—	—
2444599	VR32	—	—	—	—
2444722	VR32	—	—	M400	—
2444897	VR34	—	—	M400	—
2444898	VR34	—	—	M400	—
2444899	—	—	—	M400	—
2444900	—	—	—	M400	—
2642121	VR34	—	—	M400	—
2642210	—	AC6P	AC6N	—	—
2642211	VR32	—	—	M400	—
2642228	VR32	—	—	—	—
2642229	VR32	—	—	—	—
2642411	VR32	—	—	—	—
2642412	VR32	—	—	—	—
2642487	VR34	—	—	M400	—
2642490	VR32	—	—	—	—
2642537	VR32	AC6P	AC6N	M400	—
2642538	VR32	—	—	M400	—
2642630	VR32	AC6P	AC6N	M400	—
2642635	VR32	AC6P	AC6N	M400	—
2642851	VR32	—	—	M400	—
2642880	VR32	—	—	M400	—
2642895	VR32	—	—	M400	—
2642944	VR32	—	—	—	—
2642945	VR32	—	—	M400	—
2875437	VR32	—	—	—	—
2875442	—	—	—	M401	—
2875453	VR32	—	—	—	—
2875712	—	—	—	M401	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Capacitor
2875713	VR32	—	—	—	—
2875714	VR32	—	—	M400	—
2875720	—	—	—	M401	—
2875724	VR32	—	—	M400	—
2875844	VR34	—	—	M400	—
2959214	VR32	—	—	—	—
3000005	VR34	AC6P	AC6N	M400	—
3000010	VR34	AC6P	AC6N	M400	—
3000011	VR34	AC6P	AC6N	M400	—
3436806	VR38	AC10P	AC10N	M401	—
3438161	VR38	—	—	M401	—
3438162	VR38	—	—	M401	—
3438163	VR38	—	—	M401	—
3438164	VR38	—	—	M401	—
3438165	VR38	—	—	M401	—
3438166	VR38	—	—	M401	—
3438167	VR38	—	—	M401	—
3438168	VR38	—	—	M401	—
3438170	VR38	AC6P	AC6N	M401	—
3438171	VR38	AC6P	AC6N	M401	—
3438172	VR38	AC6P	AC6N	M401	—
3438173	VR38	AC6P	AC6N	M401	—
3438174	VR38	AC6P	AC6N	M401	—
3438176	VR38	AC6P	AC6N	M401	—
3438177	VR38	AC6P	AC6N	M401	—
3438178	VR38	AC6P	AC6N	M401	—
3438179	VR38	AC6P	AC6N	M401	—
3438180	VR38	AC6P	AC6N	M401	—
3438375	—	—	—	M401	—
3438378	VR38	—	—	M401	—
3438780	VR38	AC6P	AC6N	M401	—
3438782	VR38	AC6P	AC6N	M401	—
3438803	VR38	AC10P	AC10N	M401	MO10
3438804	VR38	AC10P	AC10N	M401	MO10
3438806	VR38	AC10P	AC10N	M401	MO10
3438807	VR38	AC10P	AC10N	M401	MO10
3438809	VR38	—	—	M401	—
3438811	VR38	AC10P	AC10N	M401	MO10
3438812	VR38	AC10P	AC10N	M401	MO10
3438813	VR38	AC10P	AC10N	M401	MO10
3438841	VR38	—	—	M401	—
3438843	VR38	—	—	M401	—
3438844	VR38	—	—	M401	—
3438846	VR38	—	—	M401	—
3438847	VR38	—	—	M401	—
3438861	VR38	—	—	M401	—
3438862	VR38	—	—	M401	—
3458803	VR38	—	—	M401	—

(continued on next page)

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Capacitor
3527125	—	—	—	M401	—
3527502	VR1001	—	—	R428	—
3556217	VR38	—	—	M401	MO10
3556218	VR38	—	—	M401	MO10
3556219	VR38	—	—	M401	MO10
3621853	VR38	—	—	M401	—
3621854	VR38	—	—	M401	—
3621861	VR38	—	—	M401	—
3621862	VR38	—	—	—	—
3621867	VR38	—	—	M401	—
3656131	VR38	—	—	M401	—
3656135	VR38	—	—	M401	—
3656136	VR38	—	—	M401	—
3656137	VR38	—	—	M401	—
3656217	VR38	AC10P	AC10N	M401	MO10
3656218	VR38	AC10P	AC10N	M401	MO10
3656219	VR38	AC10P	AC10N	M401	MO10
3656313	VR38	—	—	M401	—
3656315	VR38	—	—	M401	—
3656395	VR38	—	—	M401	—
3656396	VR38	—	—	M401	—
3656397	VR38	—	—	M401	—
3656414	VR38	—	—	—	—
3656455	VR38	AC10P	AC10N	M401	MO10
3656456	VR38	AC10P	AC10N	M401	MO10
3656459	VR38	AC10P	AC10N	M401	MO10
3656471	VR38	AC10P	AC10N	M401	MO10
3656570	VR38	AC10P	AC10N	M401	MO10
3656614	VR38	AC10P	AC10N	M401	MO10
3656615	VR38	AC10P	AC10N	M401	MO10
3656617	VR38	AC10P	AC10N	M401	MO10
3656618	VR38	AC10P	AC10N	M401	MO10
3656645	VR38	AC10P	AC10N	M401	MO10
3656671	VR38	AC10P	AC10N	M401	MO10
3656711	VR38	AC10P	AC10N	M401	MO10
3656713	VR38	AC10P	AC10N	M401	MO10
3744890	VR32	—	—	M400	MO10
3755190	VR38	—	—	M401	MO10
3755191	VR38	—	—	M401	MO10
3755192	VR38	—	—	M401	MO10
3755193	VR38	—	—	M401	MO10
3755230	VR38	—	—	M401	MO10
3755403	VR38	AC10P	AC10N	M401	MO10
3755404	VR38	AC10P	AC10N	M401	MO10
3755405	VR38	AC10P	AC10N	M401	MO10
3755406	VR38	AC10P	AC10N	M401	MO10
3755407	VR38	AC10P	AC10N	M401	MO10
3755410	VR38	AC10P	AC10N	M401	MO10

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Capacitor
3755411	VR38	—	AC10N	M401	MO10
3755412	VR38	—	—	—	—
3755413	VR38	—	AC10N	M401	MO10
3755414	VR38	AC10P	AC10N	M401	MO10
3755441	VR38	AC10P	AC10N	M401	MO10
3755444	VR38	AC10P	AC10N	M401	MO10
3755445	VR38	AC10P	AC10N	M401	MO10
3755447	VR38	AC10P	AC10N	M401	MO10
3755585	VR38	—	—	—	—
3780588	VR38	AC10P	AC10N	M401	MO10
3780589	VR38	—	AC10N	M401	MO10
3780590	VR38	—	—	—	—
3837163	—	AC10P	AC10N	M401	MO10
3837164	—	AC10P	AC10N	M401	MO10
3874296	—	—	—	—	MO10
3874641	—	AC10P	AC10N	M401	MO10
3874695	VR38	—	AC10N	M401	MO10
3874696	VR38	—	AC10N	M401	MO10
3874697	VR38	—	—	M401	MO10
3874698	VR38	—	AC10N	M401	MO10
3874701	VR38	—	—	M401	MO10
3874728	VR38	AC10P	AC10N	M401	MO10
3874729	—	—	AC10N	M401	MO10
3874730	—	—	—	M401	MO10
3874776	VR38	—	AC10N	M401	MO10
3874777	VR38	—	AC10N	M401	MO10
3895326	VR38	—	AC10N	M401	MO10
3895641	VR38	—	AC10N	M401	MO10
4057935	VR38	AC10P	AC10N	M405	MO10
4091002	VR38	—	—	—	—
4091460	VR38	—	AC14N	M404	—
4091461	VR38	—	—	—	—
4091556	VR38	AC10P	AC10N	M405	MO10
4091563	VR38	—	AC10N	M401	MO10
4091564	VR38	—	AC10N	M401	MO10
4091565	VR38	—	AC10N	M401	MO10
4091566	VR38	—	—	M401	MO10
4091568	VR38	—	AC10N	M401	MO10
4091569	VR38	—	—	M401	MO10
4091572	VR38	—	AC10N	M401	MO10
4091647	VR38	AC10P	AC10N	M401	MO10
4091727	VR38	—	AC10N	M401	MO10
4091795	VR38	—	AC10N	M401	MO10
4111204	VR38	AC10P	AC10N	M401	MO10
4111226	VR38	—	AC10N	M401	MO10
4111928	VR38	—	AC10N	M401	MO10
4111944	VR38	AC10P	AC10N	M405	MO10
4176002	VR38	—	AC10N	M401	MO10

(continued on next page)

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Capacitor
4176004	VR38	—	AC10N	M401	MO10
4176006	VR38	—	AC10N	M401	MO10
4176007	VR38	—	AC10N	M401	MO10
4176094	VR38	AC10P	AC10N	M401	MO10
4289689	VR38	AC10P	—	—	MO10
5206573	VR38	—	AC10N	M401	MO10
5206574	VR38	—	AC10N	M401	MO10
5206820	—	—	—	M401	MO10
5206822	—	—	—	M401	MO10
5206971	—	—	—	—	MO10
5206981	VR38	—	—	M402	MO10
5213053	VR38	AC10P	AC10N	M402	MO10

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Capacitor
5213079	VR38	AC10P	AC10N	M402	MO10
5213540	VR38	AC10P	AC10N	M402	—
5213541	VR38	AC10P	AC10N	M402	—
5213756	VR506	—	—	M407	—
5213762	VR38	—	AC10N	M402	—
5213763	VR38	AC10P	AC10N	M402	MO10
5213831	VR38	—	—	M407	—
5213847	VR38	—	—	M402	—
5226135	VR38	—	AC10N	M402	—
5226432	VR38	—	—	M402	—
5226600	—	—	—	M407	—

DAIHATSU

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
2770087207000	VR250	—	—	—

DELCO REMY

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
111795A	VR443	—	—	—	—	—
1100056	—	AC2P	AC2N	R434	R429	—
1100057	VR142	AC2P	AC2N	R434	R429	—
1100059	VR142	AC2P	AC2N	R434	R429	—
1100061	—	AC2P	AC2N	R434	R429	—
1100062	—	AC2P	AC2N	R434	R429	—
1100063	—	AC2P	AC2N	R434	R429	—
1100064	—	AC2P	AC2N	R434	R429	—
1100065	VR126	AC2P	AC2N	R434	R429	—
1100066	VR126	AC2P	AC2N	R434	R429	—
1100067	—	AC2P	AC2N	R434	R429	—
1100068	VR142	AC2P	AC2N	R434	R429	—
1100071	VR126	AC2P	AC2N	R434	R429	—
1100072	VR162	AD1204	AD1206	R437	R432	—
1100073	VR162	AD1204	AD1206	R437	R432	—
1100074	—	AC2P	AC2N	R434	R429	—
1100075	VR162	—	AD1206	R437	R432	—
1100076	VR162	—	AD1206	R437	R432	—
1100077	VR182	AD1204	AD1206	R437	R432	—
1100078	VR182	AD1204	AD1206	R437	R432	—
1100080	VR184	AD1204	AD1206	R437	R432	—
1100081	VR184	AD1204	AD1206	R437	R432	—
1100082	VR184	—	AD1206	R437	R432	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1100083	VR184	—	AD1206	R437	R432	—
1100086	VR184	AD1204	AD1206	R437	R432	—
1100087	VR184	AD1204	AD1206	R437	R432	—
1100088	VR184	—	AD1206	R437	R432	—
1100091	VR184	AD1204	AD1206	R437	R432	—
1100092	VR148	AC9	AC12	R437	R432	—
1100094	VR148	AD1204	AD1206	R437	R432	—
1100095	VR148	AC9	AD1206	R437	R432	—
1100096	VR148	AC9	AD1206	R437	R432	—
1100109	VR148	AC9	AC12	R437	R432	—
1100110	VR148	AC9	AC12	R437	R432	—
1100111	VR148	AC9	AC12	R437	R432	—
1100113	VR148	AC9	AC12	R437	R432	—
1100114	VR148	AC9	AC12	R451	R422	—
1100115	VR148	AC9	AC12	R437	R432	—
1100119	VR148	AC9	AC12	R437	R432	—
1100120	VR148	AC9	AC12	R437	R432	—
1100121	VR148	AC9	AC12	R437	R432	—
1100122	VR148	AC9	AC12	R437	R432	—
1100124	VR148	AC9	AC12	R437	R432	—
1100125	VR148	AC9	AC12	R437	R432	—
1100127	VR148	AC9	AC12	R437	R432	—
1100129	VR148	AC9	AC12	R437	R432	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1100130	VR148	AC9	AC12	R437	R432	—
1100131	VR148	AC9	AC12	R437	R432	—
1100132	VR148	AC9	AC12	R437	R432	—
1100133	VR148	AC9	AC12	R437	R432	—
1100138	VR148	AC9	AC12	R437	R432	—
1100139	VR148	AC9	AC12	R437	R432	—
1100140	VR148	AC9	AC12	R437	R432	—
1100141	VR148	AC9	AC12	R437	R432	—
1100142	VR148	AC9	AC12	R437	R432	—
1100143	VR148	AC9	AC12	R437	R432	—
1100145	VR148	AC9	AC12	R437	R432	—
1100146	VR148	AC9	AC12	R437	R432	—
1100148	VR148	AC9	AC12	R437	R432	—
1100149	VR148	AC9	AC12	R437	R432	—
1100150	VR148	AC9	AC12	R437	R432	—
1100151	VR148	AC9	AC12	R437	R432	—
1100152	VR148	AC9	AC12	R437	R432	—
1100153	VR148	AC9	AC12	R437	R432	—
1100154	VR148	AC9	AC12	R437	R432	—
1100155	VR148	AC9	AC12	R437	R432	—
1100156	VR148	AC9	AC12	R437	R432	—
1100158	VR148	AC9	AC12	R437	R432	—
1100159	VR148	AC9	AC12	R437	R432	—
1100162	VR148	AC9	AC12	R437	R432	—
1100163	VR148	AC9	AC12	R437	R432	—
1100164	VR148	AC9	AC12	R437	R432	—
1100165	VR148	AC9	AC12	R437	R432	—
1100166	VR148	AC9	AC12	R437	R432	—
1100167	VR148	AC9	AC12	R437	R432	—
1100168	VR148	AC9	AC12	R437	R432	—
1100169	VR148	AC9	AC12	R437	R432	—
1100170	VR148	AC9	AC12	R451	R422	—
1100171	VR148	AC9	AC12	R451	R422	—
1100173	VR148	AC9	AC12	R437	R432	—
1100174	VR148	AC9	AC12	R437	R432	—
1100175	VR148	AC9	AC12	R437	R432	—
1100176	VR148	AC9	AC12	R437	R432	—
1100177	VR148	AD1204	AD1206	R437	R432	—
1100178	VR148	AC9	AC12	R437	R432	—
1100179	VR148	AC9	AC12	R437	R432	—
1100180	VR148	AC9	AC12	R437	R432	—
1100181	VR148	AC9	AC12	R437	R432	—
1100182	VR148	AC9	AC12	R437	R432	—
1100183	VR148	AC13	AC12	R440	R443	—
1100184	VR148	AC13	AC12	R440	R443	—
1100186	VR148	AC9	AC12	R437	R432	—
1100187	VR148	AC13	AC12	R440	R443	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1100188	VR184	AD1204	AD1206	R437	R432	—
1100189	VR184	AD1204	AD1206	R437	R432	—
1100190	VR148	AC13	AC12	R440	R443	—
1100192	VR148	AC13	AC12	R440	R443	—
1100193	VR148	AC13	AC12	R440	R443	—
1100194	VR148	AC13	AC12	R440	R443	—
1100195	VR148	AC13	AC12	R440	R443	—
1100196	VR148	AC9	AC12	R437	R432	—
1100198	VR148	AC9	AC12	R437	R432	—
1100199	VR148	AC9	AC12	R437	R432	—
1100200	VR148	AC26	AC12	R437	R432	—
1100201	VR148	AC9	AC12	R437	R432	—
1100202	VR148	AC26	AC12	R437	R432	—
1100203	VR148	AC26	AC12	R437	R432	—
1100204	VR148	AC26	AC12	R437	R432	—
1100206	VR148	AC26	AC12	R437	R432	—
1100207	VR148	AC26	AC12	R437	R432	—
1100208	VR148	AC26	AC12	R437	R432	—
1100209	VR148	AC26	AC12	R437	R432	—
1100210	VR182	AD1204	AD1206	R437	R432	—
1100211	VR182	AD1204	AD1206	R437	R432	—
1100212	VR184	AD1204	AD1206	R437	R432	—
1100213	VR184	AD1204	AD1206	R437	R432	—
1100214	VR184	—	AD1206	R437	R432	—
1100215	VR184	AD1204	AD1206	R437	R432	—
1100216	VR148	AD1204	AD1206	R437	R432	—
1100217	VR148	AC26	AC12	R437	R432	—
1100218	VR148	AC9	AC12	R437	R432	—
1100219	VR148	AC13	AC12	R440	R443	—
1100220	VR148	AC9	AC12	R437	R432	—
1100221	VR148	AC9	AC12	R437	R432	—
1100222	VR148	AC9	AC12	R437	R432	—
1100223	VR148	AC13	AC12	R440	R443	—
1100224	VR148	AC13	AC12	R440	R443	—
1100225	VR148	AC26	AC12	R437	R432	—
1100226	VR148	AC26	AC12	R437	R432	—
1100227	VR148	AC26	AC12	R437	R432	—
1100228	VR148	AC26	AC12	R437	R432	—
1100229	VR148	AC26	AC12	R437	R432	—
1100230	VR148	AC26	AC12	R437	R432	—
1100231	VR148	AC26	AC12	R437	R432	—
1100232	VR148	AC26	AC12	R437	R432	—
1100233	VR148	AC26	AC12	R437	R432	—
1100234	VR148	AC12	AC26	R437	R432	—
1100235	VR148	AC9	AC12	R437	R432	—
1100236	VR148	AC26	AC12	R437	R432	—
1100237	VR148	AC26	AC12	R437	R432	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1100238	VR148	AC9	AC12	R437	R432	—
1100239	VR148	AC26	AC12	R437	R432	—
1100240	VR148	AC26	AC12	R437	R432	—
1100241	VR148	AC26	AC12	R437	R432	—
1100242	VR148	AC26	AC12	R437	R432	—
1100243	VR148	AC26	AC12	R437	R432	—
1100244	VR148	AC26	AC12	R437	R432	—
1100246	VR148	AC26	AC12	R437	R432	—
1100247	VR148	AC26	AC12	R437	R432	—
1100249	VR148	AC26	AC12	R437	R432	—
1100250	VR148	AC26	AC12	R437	R432	—
1100251	VR148	AC26	AC12	R437	R432	—
1100252	VR148	AC26	AC12	R437	R432	—
1100253	VR148	AC26	AC12	R437	R432	—
1100254	VR148	AC26	AC12	R437	R432	—
1100255	VR148	AC26	AC12	R437	R432	—
1100256	VR148	AC9	AC12	R437	R432	—
1100257	VR148	AC26	AC12	R437	R432	—
1100258	VR148	AC26	AC12	R437	R432	—
1100259	VR148	AC26	AC12	R437	R432	—
1100260	VR148	AC26	AC12	R437	R432	—
1100261	VR148	AC26	AC12	R437	R432	—
1100263	VR148	AC26	AC12	R437	R432	—
1100264	VR148	AC26	AC12	R437	R432	—
1100265	VR148	AC26	AC12	R437	R432	—
1100267	VR148	AC9	AC12	R437	R432	—
1100268	VR148	AC9	AC12	R437	R432	—
1100269	VR148	AC9	AC12	R437	R432	—
1100270	VR148	AC9	AC12	R437	R432	—
1100271	VR148	AC13	AC12	R440	R443	—
1100272	VR148	AC26	AC12	R437	R432	—
1100273	VR148	AC26	AC12	R437	R432	—
1100274	VR182	AD1204	AD1206	R437	R432	—
1100275	VR148	AC26	AC12	R437	R432	—
1100276	VR148	AC26	AC12	R437	R432	—
1100278	VR148	AC43	AC12	R440	R443	—
1100280	VR148	AC9	AC12	R437	R432	—
1100281	VR148	AC9	AC12	R437	R432	—
1100282	VR148	AC13	AC12	R440	R443	—
1100283	VR148	AC13	AC12	R440	R443	—
1100284	VR148	AC13	AC12	R440	R443	—
1100285	VR148	AC13	AC12	R440	R443	—
1100286	VR148	AC13	AC12	R440	R443	—
1100287	VR148	AC26	AC12	R437	R432	—
1100288	VR148	AC26	AC12	R437	R432	—
1100289	VR148	AC26	AC12	R437	R432	—
1100290	VR148	AC26	AC12	R437	R432	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1100291	VR148	AC26	AC12	R437	R432	—
1100293	VR148	AC13	AC12	R440	R443	—
1100294	VR148	AC9	AC12	R437	R432	—
1100295	VR148	AC13	AC12	R440	R443	—
1100296	VR148	AC13	AC12	R440	R443	—
1100297	VR148	AC26	AC12	R437	R432	—
1100298	VR148	AC26	AC12	R437	R432	—
1100299	VR148	AC26	AC12	R437	R432	—
1100300	VR148	AC26	AC12	R437	R432	—
1100326	VR122	—	—	—	—	—
1100486	VR148	AC9	AC12	R437	R432	—
1100487	VR148	AC9	AC12	R437	R432	—
1100490	VR148	AC9	AC12	R437	R432	—
1100491	VR148	AC9	AC12	R437	R432	—
1100492	VR148	AC9	AC12	R437	R432	—
1100493	VR148	AC9	AC12	R437	R432	—
1100494	VR148	AC9	AC12	R437	R432	—
1100497	VR148	AC9	AC12	R437	R432	—
1100499	VR148	AC9	AC12	R437	R432	—
1100542	VR148	AC9	AC12	R437	R432	—
1100543	VR148	AC9	AC12	R437	R432	—
1100544	VR148	AC9	AC12	R437	R432	—
1100545	VR148	AC9	AC12	R437	R432	—
1100546	VR148	AC9	AC12	R437	R432	—
1100547	VR148	AC9	AC12	R437	R432	—
1100548	VR148	AC9	AC12	R437	R432	—
1100549	VR148	AC9	AC12	R437	R432	—
1100550	VR148	AC9	AC12	R437	R432	—
1100552	VR148	AC9	AC12	R437	R432	—
1100553	VR142	AC2P	AC2N	R434	R429	—
1100554	VR148	AC9	AC12	R437	R432	—
1100557	VR142	AC2P	AC2N	R434	R429	—
1100558	VR142	AC2P	AC2N	R434	R429	—
1100559	VR148	AC9	AC12	R437	R432	—
1100560	VR148	AC9	AC12	R437	R432	—
1100566	VR142	AC2P	AC2N	R434	R429	—
1100567	VR142	AC2P	AC2N	R434	R429	—
1100568	VR142	AC2P	AC2N	R434	R429	—
1100569	VR142	AC2P	AC2N	R434	R429	—
1100570	VR142	AC2P	AC2N	R434	R429	—
1100571	VR142	AC2P	AC2N	R434	R429	—
1100572	VR142	AC2P	AC2N	R434	R429	—
1100573	VR148	AC9	AC12	R437	R432	—
1100574	VR148	AC9	AC12	R437	R432	—
1100575	VR148	AC9	AC12	R437	R432	—
1100576	VR148	AC9	AC12	R437	R432	—
1100577	VR148	AC9	AC12	R437	R432	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1100578	VR148	AC9	AC12	R437	R432	—
1100579	VR148	AC9	AC12	R437	R432	—
1100580	VR148	AC9	AC12	R437	R432	—
1100581	VR148	AC9	AC12	R437	R432	—
1100582	VR148	AC9	AC12	R437	R432	—
1100583	VR148	AC9	AC12	R437	R432	—
1100584	VR148	AC9	AC12	R437	R432	—
1100585	VR148	AC9	AC12	R437	R432	—
1100586	—	AC2P	AC2N	R434	R429	—
1100587	VR148	AC9	AC12	R437	R432	—
1100588	VR148	AC9	AC12	R437	R432	—
1100589	VR148	AC9	AC12	R437	R432	—
1100590	VR142	AC2P	AC2N	R434	R429	—
1100591	VR142	AC2P	AC2N	R434	R429	—
1100592	VR148	AC9	AC12	R437	R432	—
1100593	VR148	AC9	AC12	R437	R432	—
1100597	VR148	AC9	AC12	R437	R432	—
1100600	VR142	—	—	R426	—	—
1100601	VR142	—	—	R426	—	—
1100605	—	AC2P	AC2N	R434	R429	—
1100613	VR142	—	—	R426	—	—
1100615	VR142	AC2P	AC2N	R426	—	—
1100616	VR142	AC2P	AC2N	R426	—	—
1100617	—	AC2P	AC2N	R426	—	—
1100618	VR142	AC2P	AC2N	R426	—	—
1100619	—	AC2P	AC2N	R434	R429	—
1100620	VR142	AC2P	AC2N	R426	—	—
1100621	—	AC2P	AC2N	R426	—	—
1100622	VR142	AC2P	AC2N	R426	—	—
1100623	VR142	AC2P	AC2N	R426	—	—
1100624	—	AC2P	AC2N	R426	—	—
1100625	VR142	AC2P	AC2N	R426	—	—
1100627	—	AC2P	AC2N	R426	—	—
1100628	—	AC2P	AC2N	R426	—	—
1100629	—	AC2P	AC2N	R426	—	—
1100630	—	AC2P	AC2N	R426	—	—
1100631	—	AC2P	AC2N	R426	—	—
1100632	VR140	AC2P	AC2N	R426	—	—
1100633	—	AC2P	AC2N	R426	—	—
1100634	VR140	AC2P	AC2N	R426	—	—
1100636	VR140	AC2P	AC2N	R426	—	—
1100637	VR140	AC2P	AC2N	R426	—	—
1100638	VR142	AC2P	AC2N	R426	—	—
1100639	VR142	AC2P	AC2N	R434	R429	—
1100640	—	AC2P	AC2N	R426	—	—
1100642	VR142	AC2P	AC2N	R426	—	—
1100646	VR142	AC2P	AC2N	R426	—	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1100647	VR142	AC2P	AC2N	R426	—	—
1100648	—	AC2P	AC2N	R426	—	—
1100649	VR140	AC2P	AC2N	R426	—	—
1100650	—	AC2P	AC2N	R426	—	—
1100651	VR140	AC2P	AC2N	R426	—	—
1100652	VR154	AC2P	AC2N	R426	—	—
1100653	—	AC2P	AC2N	R434	R429	—
1100654	VR142	AC2P	AC2N	R434	R429	—
1100655	—	AC2P	AC2N	R426	—	—
1100656	VR142	AC2P	AC2N	R426	—	—
1100657	VR142	AC2P	AC2N	R426	—	—
1100658	VR142	AC2P	AC2N	R426	—	—
1100659	VR142	AC2P	AC2N	R426	—	—
1100660	VR154	AC2P	AC2N	—	—	—
1100661	VR142	AC2P	AC2N	R426	—	—
1100662	VR142	AC2P	AC2N	R426	—	—
1100663	VR142	AC2P	AC2N	R426	—	—
1100664	VR142	AC2P	AC2N	R426	—	—
1100665	VR142	AC2P	AC2N	R426	—	—
1100667	—	AC2P	AC2N	—	—	—
1100668	VR142	AC2P	AC2N	R426	—	—
1100669	VR142	AC2P	AC2N	R426	—	—
1100670	VR142	AC2P	AC2N	R426	—	—
1100671	VR142	AC2P	AC2N	R426	—	—
1100672	—	AC2P	AC2N	R426	—	—
1100674	—	AC2P	AC2N	R426	—	—
1100675	—	AC2P	AC2N	R426	—	—
1100676	VR142	AC2P	AC2N	R426	—	—
1100677	VR142	AC2P	AC2N	R426	—	—
1100678	—	AC2P	AC2N	R426	—	—
1100679	VR142	AC2P	AC2N	R426	—	—
1100680	VR140	AC2P	AC2N	R426	—	—
1100681	VR140	AC2P	AC2N	R426	—	—
1100682	VR140	AC2P	AC2N	R426	—	—
1100683	VR142	AC2P	AC2N	R426	—	—
1100684	—	AC2P	AC2N	R426	—	—
1100685	VR156	AC2P	AC2N	—	—	—
1100686	VR142	AC2P	AC2N	R434	R429	—
1100687	—	AC2P	AC2N	R434	R429	—
1100688	—	AC2P	AC2N	R434	R429	—
1100689	—	AC2P	AC2N	R434	R429	—
1100690	—	AC2P	AC2N	R434	R429	—
1100691	VR142	AC2P	AC2N	R434	R429	—
1100692	VR142	AC2P	AC2N	R434	R429	—
1100693	VR142	AC2P	AC2N	R434	R429	—
1100694	VR142	AC2P	AC2N	R434	R429	—
1100695	VR142	AC2P	AC2N	R434	R429	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1100696	VR142	AC2P	AC2N	R434	R429	—
1100697	VR148	AC2P	AC2N	R434	R429	—
1100698	—	AC2P	AC2N	R434	R429	—
1100699	VR142	AC2P	AC2N	R434	R429	—
1100700	VR142	AC2P	AC2N	R434	R429	—
1100701	VR142	AC2P	AC2N	R434	R429	—
1100702	VR148	AC2P	AC2N	R434	R429	—
1100703	VR148	AC2P	AC2N	R434	R429	—
1100704	VR142	AC2P	AC2N	R434	R429	—
1100705	VR142	AC2P	AC2N	R434	R429	—
1100706	VR142	AC2P	AC2N	R434	R429	—
1100707	VR142	AC2P	AC2N	R434	R429	—
1100708	VR142	AC2P	AC2N	R434	R429	—
1100709	—	AC2P	AC2N	R434	R429	—
1100710	VR142	AC2P	AC2N	R434	R429	—
1100711	—	AC2P	AC2N	R434	R429	—
1100713	VR142	AC2P	AC2N	R434	R429	—
1100714	VR142	AC2P	AC2N	R434	R429	—
1100715	VR154	AC2P	AC2N	R434	R429	—
1100716	VR154	AC2P	AC2N	R434	R429	—
1100717	VR154	AC2P	AC2N	—	—	—
1100718	VR156	AC2P	AC2N	—	—	—
1100719	VR142	AC2P	AC2N	R434	R429	—
1100720	—	AC2P	AC2N	R434	R429	—
1100721	—	AC2P	AC2N	R434	R429	—
1100722	—	AC2P	AC2N	R434	R429	—
1100723	VR156	AC2P	AC2N	—	—	—
1100724	VR142	AC2P	AC2N	R434	R429	—
1100725	VR140	AC2P	AC2N	R434	R429	—
1100726	—	AC2P	AC2N	R434	R429	—
1100727	VR140	AC2P	AC2N	R434	R429	—
1100728	—	AC2P	AC2N	R434	R429	—
1100729	VR142	AC2P	AC2N	R434	R429	—
1100730	VR142	AC2P	AC2N	R434	R429	—
1100731	VR140	AC2P	AC2N	R434	R429	—
1100732	—	AC2P	AC2N	R434	R429	—
1100733	VR142	AC2P	AC2N	R434	R429	—
1100734	VR142	AC2P	AC2N	R434	R429	—
1100735	VR142	AC2P	AC2N	R434	R429	—
1100736	VR142	AC2P	AC2N	R434	R429	—
1100737	—	AC2P	AC2N	R434	R429	—
1100738	—	AC2P	AC2N	R434	R429	—
1100739	VR140	AC2P	AC2N	R434	R429	—
1100740	VR148	AC2P	AC2N	R434	R429	—
1100741	VR148	AC2P	AC2N	R434	R429	—
1100742	VR142	AC2P	AC2N	R434	R429	—
1100744	VR142	AC2P	AC2N	R434	R429	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1100745	VR142	AC2P	AC2N	R434	R429	—
1100747	VR156	AC2P	AC2N	—	—	—
1100748	—	AC2P	AC2N	R434	R429	—
1100749	VR154	AC2P	AC2N	—	—	—
1100750	—	AC2P	AC2N	R434	R429	—
1100751	VR142	AC2P	AC2N	R434	R429	—
1100752	VR142	AC2P	AC2N	R434	R429	—
1100753	VR156	AC2P	AC2N	—	—	—
1100758	—	AC2P	AC2N	R434	R429	—
1100759	—	AC2P	AC2N	R434	R429	—
1100760	VR142	AC2P	AC2N	R434	R429	—
1100761	VR142	AC2P	AC2N	R434	R429	—
1100762	VR142	AC2P	AC2N	R434	R429	—
1100763	—	AC2P	AC2N	R434	R429	—
1100764	—	AC2P	AC2N	R434	R429	—
1100765	VR142	AC2P	AC2N	R434	R429	—
1100767	VR142	AC2P	AC2N	R434	R429	—
1100768	VR142	AC2P	AC2N	R434	R429	—
1100769	VR140	AC2P	AC2N	R434	R429	—
1100770	VR142	AC2P	AC2N	R434	R429	—
1100771	—	AC2P	AC2N	R434	R429	—
1100772	VR142	AC2P	AC2N	R434	R429	—
1100773	VR142	AC2P	AC2N	R434	R429	—
1100774	—	AC2P	AC2N	R434	R429	—
1100775	—	AC2P	AC2N	R434	R429	—
1100776	—	AC2P	AC2N	R434	R429	—
1100777	VR142	AC2P	AC2N	R434	R429	—
1100778	VR142	AC2P	AC2N	R434	R429	—
1100779	—	AC2P	AC2N	R434	R429	—
1100780	VR148	AC2P	AC2N	R434	R429	—
1100781	VR142	AC2P	AC2N	R434	R429	—
1100782	VR142	AC2P	AC2N	R434	R429	—
1100783	—	AC2P	AC2N	R429	—	—
1100786	—	AC2P	AC2N	R434	R429	—
1100787	VR142	AC2P	AC2N	R434	R429	—
1100788	VR142	AC2P	AC2N	R434	R429	—
1100789	—	AC2P	AC2N	R429	—	—
1100790	VR142	AC2P	AC2N	R434	R429	—
1100791	—	AC2P	AC2N	R434	R429	—
1100792	VR156	AC2P	AC2N	—	—	—
1100793	VR142	AC2P	AC2N	R434	R429	—
1100794	VR142	AC2P	AC2N	R434	R429	—
1100795	VR142	AC2P	AC2N	R434	R429	—
1100796	VR142	AC2P	AC2N	R434	R429	—
1100797	VR142	AC2P	AC2N	R434	R429	—
1100798	—	AC2P	AC2N	—	—	—
1100799	—	AC2P	AC2N	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1100800	—	AC2P	AC2N	—	—	—
1100801	—	AC2P	AC2N	—	—	—
1100802	VR142	AC2P	AC2N	R434	R429	—
1100803	VR142	AC2P	AC2N	R434	R429	—
1100804	VR142	AC2P	AC2N	R434	R429	—
1100805	—	AC2P	AC2N	R434	R429	—
1100806	—	AC2P	AC2N	R434	R429	—
1100807	VR142	AC2P	AC2N	R434	R429	—
1100808	—	AC2P	AC2N	R434	R429	—
1100809	—	AC2P	AC2N	R434	R429	—
1100810	VR142	AC2P	AC2N	—	—	—
1100812	—	AC2P	AC2N	R434	R429	—
1100813	VR142	AC2P	AC2N	R434	R429	—
1100814	VR142	AC2P	AC2N	R434	R429	—
1100815	VR142	AC2P	AC2N	R434	R429	—
1100816	VR142	AC2P	AC2N	R434	R429	—
1100817	VR142	AC2P	AC2N	R434	R429	—
1100818	VR142	AC2P	AC2N	R434	R429	—
1100819	VR142	AC2P	AC2N	R434	R429	—
1100820	VR142	AC2P	AC2N	R434	R429	—
1100821	VR142	AC2P	AC2N	R434	R429	—
1100822	VR142	AC2P	AC2N	R434	R429	—
1100825	VR148	AC9	AC12	R437	R432	—
1100826	VR148	AC9	AC12	R437	R432	—
1100827	VR142	AC2P	AC2N	R434	R429	—
1100828	VR142	AC2P	AC2N	R434	R429	—
1100830	VR148	AC9	AC12	R437	R432	—
1100832	VR148	AC9	AC12	R437	R432	—
1100833	VR148	AC9	AC12	R437	R432	—
1100834	VR142	AC2P	AC2N	R434	R429	—
1100836	VR142	AC2P	AC2N	R434	R429	—
1100837	VR142	AC2P	AC2N	R434	R429	—
1100838	VR142	AC2P	AC2N	R434	R429	—
1100839	VR142	AC2P	AC2N	R434	R429	—
1100841	VR142	AC2P	AC2N	R434	R429	—
1100842	VR142	AC2P	AC2N	R434	R429	—
1100843	VR142	AC2P	AC2N	R434	R429	—
1100845	VR142	AC2P	AC2N	R434	R429	—
1100846	VR142	AC2P	AC2N	R434	R429	—
1100847	VR142	AC2P	AC2N	R434	R429	—
1100849	VR142	AC2P	AC2N	R434	R429	—
1100850	—	AC2P	AC2N	R429	—	—
1100851	—	AC2P	AC2N	R434	R429	—
1100852	VR148	AC9	AC12	R437	R432	—
1100853	VR148	AC9	AC12	R437	R432	—
1100854	VR148	AC9	AC12	R437	R432	—
1100855	VR148	AC9	AC12	R437	R432	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1100856	VR142	AC2P	AC2N	R434	R429	—
1100857	—	AC2P	AC2N	R434	R429	—
1100859	VR148	AC9	AC12	R437	R432	—
1100860	VR142	AC2P	AC2N	R434	R429	—
1100861	VR148	AC9	AC12	R437	R432	—
1100862	—	AC2P	AC2N	R434	R429	—
1100863	—	AC2P	AC2N	R434	R429	—
1100864	—	AC2P	AC2N	R434	R429	—
1100865	VR148	AC9	AC12	R437	R432	—
1100870	VR142	AC2P	AC2N	R434	R429	—
1100871	VR142	AC2P	AC2N	R434	R429	—
1100875	VR142	AC2P	AC2N	R434	R429	—
1100878	VR142	AC2P	AC2N	R434	R429	—
1100879	VR142	AC2P	AC2N	R434	R429	—
1100880	VR148	AC9	AC12	R437	R432	—
1100881	VR148	AC9	AC12	—	—	—
1100882	VR148	AC9	AC12	—	—	—
1100883	VR142	AC2P	AC2N	R434	R429	—
1100884	VR148	AC9	AC12	R437	R432	—
1100885	VR142	AC2P	AC2N	R434	R429	—
1100886	VR142	AC2P	AC2N	R434	R429	—
1100887	VR142	AC2P	AC2N	—	—	—
1100888	VR142	AC2P	AC2N	R434	R429	—
1100889	VR142	AC2P	AC2N	R434	R429	—
1100890	VR148	AC9	AC12	R437	R432	—
1100891	VR142	AC2P	AC2N	R434	R429	—
1100892	VR142	AC2P	AC2N	R434	R429	—
1100893	VR142	AC2P	AC2N	R434	R429	—
1100894	VR148	AC9	AC12	R437	R432	—
1100895	VR142	AC2P	AC2N	R434	R429	—
1100896	VR142	AC2P	AC2N	R434	R429	—
1100897	VR148	AC9	AC12	R437	R432	—
1100899	VR148	AC9	AC12	R437	R432	—
1100900	VR148	AC9	AC12	R437	R432	—
1100901	VR148	AC9	AC12	R437	R432	—
1100902	VR148	AC9	AC12	R437	R432	—
1100903	VR148	AC9	AC12	R437	R432	—
1100904	VR148	AC9	AC12	R437	R432	—
1100905	VR142	AC2P	AC2N	R434	R429	—
1100906	VR142	AC2P	AC2N	R434	R429	—
1100907	VR142	AC2P	AC2N	R434	R429	—
1100908	VR142	AC2P	AC2N	R434	R429	—
1100909	VR142	AC2P	AC2N	R434	R429	—
1100910	VR142	AC2P	AC2N	R434	R429	—
1100911	VR148	AC9	AC12	R437	R432	—
1100912	VR148	AC9	AC12	R437	R432	—
1100914	VR148	AC9	AC12	R437	R432	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1100915	VR148	AC9	AC12	R437	R432	—
1100916	VR142	AC2P	AC2N	R434	R429	—
1100917	VR142	AC2P	AC2N	R434	R429	—
1100919	VR148	AC9	AC12	R437	R432	—
1100920	VR148	AC9	AC12	R437	R432	—
1100921	VR142	AC2P	AC2N	R434	R429	—
1100922	VR148	AC9	AC12	R437	R432	—
1100923	VR148	AC9	AC12	R437	R432	—
1100924	VR148	AC9	AC12	R437	R432	—
1100925	VR148	AC9	AC12	R437	R432	—
1100926	VR148	AC9	AC12	R437	R432	—
1100927	VR148	AC9	AC12	R437	R432	—
1100928	VR148	AC9	AC12	R437	R432	—
1100929	VR148	AC9	AC12	R437	R432	—
1100930	VR148	AC9	AC12	R437	R432	—
1100931	VR142	AC2P	AC2N	R434	R429	—
1100932	VR142	AC2P	AC2N	R434	R429	—
1100933	VR142	AC2P	AC2N	R434	R429	—
1100934	VR148	AC9	AC12	R437	R432	—
1100935	VR148	AC9	AC12	R437	R432	—
1100936	VR148	AC9	AC12	R437	R432	—
1100937	VR148	AC9	AC12	R437	R432	—
1100939	VR142	AC2P	AC2N	R434	R429	—
1100940	VR148	AC9	AC12	R437	R432	—
1100943	VR142	AC2P	AC2N	R434	R429	—
1100944	VR142	AC2P	AC2N	R434	R429	—
1100946	VR148	AC9	AC12	R437	R432	—
1100947	VR148	AC9	AC12	R437	R432	—
1100948	VR148	AC9	AC12	R437	R432	—
1100949	VR148	AC9	AC12	R437	R432	—
1100950	VR148	AC9	AC12	R437	R432	—
1101015	VR148	AD1204	AD1206	R437	R432	—
1101016	VR148	AD1204	AD1206	R437	R432	—
1101018	VR148	AD1204	AD1206	R437	R432	—
1101019	VR148	AD1204	AD1206	R437	R432	—
1101020	VR148	AD1204	AD1206	R437	R432	—
1101022	VR148	AD1204	AD1206	R437	R432	—
1101023	VR148	AD1204	AD1206	R437	R432	—
1101024	VR148	AD1204	AD1206	R437	R432	—
1101025	VR148	AD1204	AD1206	R437	R432	—
1101026	VR148	AD1204	AD1206	R437	R432	—
1101027	VR148	AD1204	AD1206	R437	R432	—
1101028	VR148	AD1204	AD1206	R437	R432	—
1101029	VR148	AD1204	AD1206	R437	R432	—
1101030	VR148	AD1204	AD1206	R437	R432	—
1101031	VR148	AD1204	AD1206	R437	R432	—
1101033	VR148	AD1204	AD1206	R437	R432	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1101034	VR148	AD1204	AD1206	R437	R432	—
1101035	VR148	AD1204	AD1206	R437	R432	—
1101036	VR148	AD1204	AD1206	R437	R432	—
1101037	VR148	AC13	AC12	R440	R443	—
1101038	VR148	AC13	AC12	R440	R443	—
1101039	VR148	AC13	AC12	R440	R443	—
1101040	VR148	AC13	AC12	R440	R443	—
1101041	VR148	AC13	AC12	R440	R443	—
1101042	VR148	AC13	AC12	R440	R443	—
1101043	VR148	AD1204	AD1206	R437	R432	—
1101044	VR148	AC13	AC12	R440	R443	—
1101045	VR148	AC13	AC12	R440	R443	—
1101046	VR148	AD1204	AD1206	R437	R432	—
1101047	VR148	AD1204	AD1206	R437	R432	—
1101048	VR148	AD1204	AD1206	R437	R432	—
1101049	VR148	AD1204	AD1206	R437	R432	—
1101050	VR148	AD1204	AD1206	R437	R432	—
1101058	VR148	AD1204	AD1206	R437	R432	—
1101059	VR148	AD1204	AD1206	R437	R432	—
1101060	VR148	AD1204	AD1206	R437	R432	—
1101061	VR148	AD1204	AD1206	R437	R432	—
1101062	VR148	AD1204	AD1206	R437	R432	—
1101063	VR148	AD1204	AD1206	R437	R432	—
1101064	VR148	AD1204	AD1206	R437	R432	—
1101065	VR148	AC13	AC12	R440	R443	—
1101066	VR148	AC13	AC12	R440	R443	—
1101067	VR148	AC13	AC12	R440	R443	—
1101068	VR148	AC13	AC12	R440	R443	—
1101070	VR148	AC13	AC12	R440	R443	—
1101071	VR148	AC13	AC12	R440	R443	—
1101073	VR148	AD1204	AD1206	R437	R432	—
1101075	VR148	AC13	AC12	R440	R443	—
1101076	VR148	AC13	AC12	R440	R443	—
1101077	VR148	AC13	AC12	R440	R443	—
1101078	VR148	AC13	AC12	R440	R443	—
1101079	VR148	AC13	AC12	R440	R443	—
1101080	VR148	AC13	AC12	R440	R443	—
1101081	VR148	AC13	AC12	R440	R443	—
1101082	VR148	AC13	AC12	R440	R443	—
1101084	VR148	AC13	AC12	R440	R443	—
1101085	VR148	AC13	AC12	R440	R443	—
1101086	VR148	AC13	AC12	R440	R443	—
1101087	VR148	AC13	AC12	R440	R443	—
1101088	VR148	AC13	AC12	R440	R443	—
1101090	VR148	AD1204	AD1206	R437	R432	—
1101091	VR148	AD1204	AD1206	R437	R432	—
1101092	VR148	AC13	AC12	R440	R443	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1101093	VR148	AC13	AC12	R440	R443	—
1101094	VR148	AC13	AC12	R440	R443	—
1101095	VR148	AC13	AC12	R440	R443	—
1101096	VR148	AC13	AC12	R440	R443	—
1101097	VR148	AC13	AC12	R440	R443	—
1101101	VR191	AC84	—	R445	R444	—
1101102	VR148	AD1204	AD1206	R437	R432	—
1101103	VR148	AD1204	AD1206	R437	R432	—
1101104	VR184	AD1204	AD1206	R437	R432	—
1101105	VR184	AD1204	AD1206	R437	R432	—
1101107	VR191	AC84	—	R445	R444	—
1101109	VR148	AD1204	AD1206	R437	R432	—
1101110	VR191	AC84	—	R445	R444	—
1101111	VR191	AC84	—	R445	R444	—
1101112	VR148	AC43	AC12	R440	R443	—
1101113	VR148	AC43	AC12	R440	R443	—
1101115	VR148	AC43	AC12	R440	R443	—
1101118	VR148	AC13	AC12	R440	R443	—
1101123	VR191	AC84	—	R445	R444	—
1101124	VR191	AC84	—	R445	R444	—
1101125	VR191	AC84	—	R445	R444	—
1101126	VR191	AC84	—	R445	R444	—
1101127	VR191	AC84	—	R445	R444	—
1101133	VR130	AC62	—	R446	R447	—
1101134	VR148	AC29	AC12	R437	R432	—
1101135	VR191	AC84	—	R445	R444	—
1101136	VR191	AC84	—	R445	R444	—
1101137	VR191	AC84	—	R445	R444	—
1101138	VR191	AC84	—	R445	R444	—
1101139	VR191	AC84	—	R445	R444	—
1101140	VR191	AC84	—	R445	R444	—
1101141	VR191	AC84	—	R445	R444	—
1101142	VR191	AC84	—	R445	R444	—
1101143	VR191	AC84	—	R445	R444	—
1101144	VR191	AC84	—	R445	R444	—
1101145	VR191	AC84	—	R445	R444	—
1101146	VR192	AC84	—	R445	R444	—
1101148	VR191	AC84	—	R445	R444	—
1101149	VR191	AC84	—	R445	R444	—
1101150	VR191	AC84	—	R445	R444	—
1101151	VR191	AC84	—	R445	R444	—
1101154	VR191	AC84	—	R445	R444	—
1101155	VR148	AC26	AC12	R437	R432	—
1101156	VR148	AC26	AC12	R437	R432	—
1101157	VR148	AC26	AC12	R437	R432	—
1101158	VR192	AC84	—	R445	R444	—
1101159	VR148	AC26	AC12	R437	R432	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1101164	VR148	AC43	AC12	R440	R443	—
1101167	VR191	AC84	—	R445	R444	—
1101170	VR191	AC84	—	R445	R444	—
1101173	VR191	AC84	—	R445	R444	—
1101178	VR148	AD1204	AD1206	R437	R432	—
1101179	VR191	AC84	—	R445	R444	—
1101180	VR191	AC84	—	R444	—	—
1101181	VR191	AC84	—	R445	R444	—
1101182	VR191	AC62	—	R446	R447	—
1101183	VR191	AC62	—	R446	R447	—
1101184	VR191	AC84	—	R445	R444	—
1101186	VR191	AC84	—	R445	R444	—
1101192	VR148	AC26	AC12	R451	R422	—
1101193	VR148	AC26	AC12	R451	R422	—
1101194	VR148	—	AC12	—	—	—
1101195	—	AC26	AC12	R451	R422	—
1101201	VR148	AC26	AC12	R451	R422	—
1101202	VR148	AC26	AC12	R451	R422	—
1101203	VR148	AC26	AC12	R451	R422	—
1101204	—	AC26	AC12	R451	R422	—
1101205	VR148	—	AC12	—	—	—
1101212	VR191	AC62	—	R446	R447	—
1101213	VR191	AC62	—	R446	R447	—
1101214	VR191	AC62	—	R446	R447	—
1101215	VR190	AC62	AC101	R440	R443	—
1101224	VR148	AC43	AC12	R440	R443	—
1101225	VR148	AC43	AC12	R440	R443	—
1101227	VR191	AC84	—	R445	R444	—
1101228	VR148	AC26	AC12	R437	R432	—
1101229	VR191	AC84	—	R445	R444	—
1101231	VR191	AC84	—	R445	R444	—
1101236	VR148	AC43	AC12	R440	R443	—
1101237	VR191	AC62	—	R446	R447	—
1101238	VR191	AC62	—	R446	R447	—
1101239	VR191	AC100	—	R446	R447	—
1101240	VR148	AC29	AC12	R437	R432	—
1101241	VR148	AC29	AC12	R437	R432	—
1101242	VR148	AC26	AC12	R437	R432	—
1101243	VR148	AC26	AC12	R437	R432	—
1101244	VR148	AC26	AC12	R437	R432	—
1101245	VR148	AC29	AC12	R437	R432	—
1101246	VR191	AC84	—	R445	R444	—
1101250	VR191	AC62	—	R446	R447	—
1101251	VR184	AD1204	AD1206	R437	R432	—
1101252	VR148	AC62	AC101	R440	R443	—
1101253	VR191	AC84	—	R445	R444	—
1101254	VR191	AC84	—	R445	R444	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1101255	VR191	AC84	—	R445	R444	—
1101258	VR190	AC62	AC101	R440	R443	—
1101259	VR191	AC84	—	R445	R444	—
1101263	VR191	AC62	—	R446	R447	—
1101264	VR191	AC84	—	R445	R444	—
1101266	VR191	AC84	—	R445	R444	—
1101267	VR191	AC84	—	R445	R444	—
1101268	VR148	AC26	AC12	R437	R432	—
1101270	VR130	AC62	—	R446	R447	—
1101271	VR191	AC84	—	R445	R444	—
1101272	VR191	AC84	—	R445	R444	—
1101273	VR191	AC84	—	R445	R444	—
1101274	VR191	AC62	—	R446	R447	—
1101275	VR191	AC84	—	R445	R444	—
1101277	VR191	AC84	—	R445	R444	—
1101278	VR191	AC84	—	R445	R444	—
1101279	VR148	AC26	AC12	R437	R432	—
1101282	VR148	AC26	AC12	R437	R432	—
1101285	—	AC26	AC12	R437	R432	—
1101287	VR184	AD1204	AD1206	R437	R432	—
1101288	VR184	AD1204	AD1206	R437	R432	—
1101289	VR184	AD1204	AD1206	R437	R432	—
1101290	VR190	AC62	AC101	R440	R443	—
1101292	VR191	AC84	—	R445	R444	—
1101293	VR191	AC84	—	R445	R444	—
1101294	VR192	AC62	—	R446	R447	—
1101295	VR130	AC62	—	R446	R447	—
1101296	VR192	AC62	—	R446	R447	—
1101297	VR148	AC43	AC12	R440	R443	—
1101298	VR148	AC26	AC12	R437	R432	—
1101299	VR148	AC29	AC12	R437	R432	—
1101300	VR148	AC26	AC12	R437	R432	—
1101301	VR148	AC29	AC12	R437	R432	—
1101302	VR148	AC29	AC12	R437	R432	—
1101303	VR148	AC26	AC12	R437	R432	—
1101304	VR148	AC29	AC12	R437	R432	—
1101305	VR148	AC29	AC12	R437	R432	—
1101306	VR148	AC43	AC12	R440	R443	—
1101307	VR148	AC26	AC12	R437	R432	—
1101308	VR148	AC29	AC12	R437	R432	—
1101309	VR190	AC43	AC12	R440	R443	—
1101310	VR191	AC84	—	R445	R444	—
1101316	VR191	AC62	—	R446	R447	—
1101317	VR191	AC84	—	R445	R444	—
1101318	VR191	AC84	—	R445	R444	—
1101322	VR148	AC13	AC12	R440	R443	—
1101323	VR148	AC13	AC12	R440	R443	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1101324	VR148	AC29	AC12	R437	R432	—
1101325	VR192	AC62	—	R446	R447	—
1101326	VR192	AC62	—	R446	R447	—
1101329	VR192	AC62	—	R446	R447	—
1101330	VR130	AC62	—	R446	R447	—
1101331	VR192	AC62	—	R446	R447	—
1101344	VR191	AC84	—	R445	R444	—
1101345	VR148	AC26	AC12	—	—	—
1101346	VR191	AC84	—	R445	R444	—
1101349	VR191	AC62	—	R446	R447	—
1101436	VR148	AC13	AC12	R440	R443	—
1101437	VR148	AC13	AC12	R440	R443	—
1101438	VR148	AC13	AC12	R440	R443	—
1101439	VR148	—	AC12	—	—	—
1101440	VR148	—	AC12	—	—	—
1101441	VR148	AC13	AC12	R440	R443	—
1101443	VR148	AC13	AC12	R440	R443	—
1101446	VR148	AC13	AC12	R440	R443	—
1101447	VR148	AC13	AC12	R440	R443	—
1101448	VR148	AC13	AC12	R440	R443	—
1101449	VR148	AC13	AC12	R440	R443	—
1101450	VR148	AD1204	AD1206	R437	R432	—
1101454	VR191	AC62	—	R446	R447	—
1101461	VR191	AC84	—	R445	R444	—
1101464	VR191	AC84	—	R445	R444	—
1101465	VR191	AC84	—	R445	R444	—
1101466	VR191	AC84	—	R445	R444	—
1101467	VR191	AC84	—	R445	R444	—
1101475	VR191	AC84	—	R445	R444	—
1101478	—	AC84	—	R445	R444	—
1101480	—	AC84	—	R445	R444	—
1101482	—	AC62	—	R446	R447	—
1101484	VR148	AC29	AC12	R437	R432	—
1101486	VR191	AC62	—	R446	R447	—
1101487	VR191	AC62	—	R446	R447	—
1101490	VR192	AC62	—	R446	R447	—
1101491	VR191	AC62	—	R446	R447	—
1101493	VR191	AC62	—	R446	R447	—
1101500	VR191	AC84	—	R445	R444	—
1101518	VR192	AC62	—	R446	R447	—
1101519	VR192	AC62	—	R446	R447	—
1101521	VR191	AC84	—	R445	R444	—
1101561	—	AC62	—	R446	R447	—
1101566	—	AC62	—	R446	R447	—
1101567	VR191	AC62	—	R446	R447	—
1101571	—	AC84	—	R445	R444	—
1101573	VR191	AC62	—	R446	R447	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1101574	VR130	AC62	—	R446	R447	—
1101577	VR191	AC84	—	R445	R444	—
1101578	VR192	—	—	R446	R447	—
1101582	VR191	AC84	—	R445	R444	—
1101583	VR191	AC84	—	R445	R444	—
1101590	VR192	—	—	R446	R447	—
1101591	VR130	AC62	—	R446	R447	—
1101593	VR191	AC84	—	R445	R444	—
1101595	VR191	AC84	—	R445	R444	—
1101596	VR191	AC84	—	R445	R444	—
1101597	VR191	AC62	—	R446	R447	—
1101599	VR191	AC84	—	R445	R444	—
1101600	VR191	AC84	—	R445	R444	—
1101601	VR191	AC84	—	R445	R444	—
1101603	VR191	AC84	—	R445	R444	—
1101604	VR191	AC62	—	R446	R447	—
1101605	VR191	AC84	—	R445	R444	—
1101606	VR191	AC84	—	R445	R444	—
1101608	VR191	AC84	—	R445	R444	—
1101612	VR191	AC84	—	R445	R444	—
1101616	VR191	AC84	—	R445	R444	—
1101617	VR191	AC84	—	R445	R444	—
1101618	VR191	AC84	—	R445	R444	—
1101619	VR191	AC84	—	R445	R444	—
1101620	VR191	AC84	—	R445	R444	—
1101621	VR191	AC84	—	R445	R444	—
1101623	VR191	AC62	—	R446	R447	—
1101628	VR191	AC84	—	R445	R444	—
1101629	VR191	AC84	—	R445	R444	—
1101630	VR191	AC84	—	R445	R444	—
1101632	VR191	AC84	—	R445	R444	AD144
1101633	VR191	AC84	—	R445	R444	AD144
1101634	VR191	AC84	—	R445	R444	AD144
1101635	VR191	AC84	—	R445	R444	AD144
1101636	VR191	AC84	—	R445	R444	AD144
1101637	VR191	AC84	—	R445	R444	AD144
1101638	VR191	AC84	—	R445	R444	—
1101642	VR191	AC84	—	R445	R444	AD144
1101644	VR191	AC84	—	R445	R444	—
1101645	VR191	AC84	—	R445	R444	AD144
1101646	VR191	AC84	—	R445	R444	AD144
1101647	VR191	AC84	—	R445	R444	AD144
1101648	VR191	AC62	—	R446	R447	—
1101649	VR191	AC84	—	R445	R444	AD144
1101650	VR191	AC84	—	R445	R444	AD144
1101694	VR191	AC84	—	—	—	—
1101700	VR148	AC13	AC12	R440	R443	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1101805	VR191	AC62	—	R446	R447	—
1101806	—	AC84	—	R445	R444	AD144
1101807	VR191	AC84	—	R445	R444	AD144
1101810	VR191	AC84	—	R445	R444	AD144
1101812	VR191	AC84	—	R445	R444	AD144
1101814	VR191	AC84	—	R445	R444	AD144
1101815	VR191	AC84	—	R445	R444	AD144
1101818	—	AC103	—	R446	R447	—
1101819	VR191	AC103	—	R446	R447	—
1101822	VR191	AC84	—	R445	R444	AD144
1101832	VR191	AC84	—	R445	R444	AD144
1101843	VR191	AC84	—	R444	—	—
1101844	VR192	—	—	R446	R447	—
1101846	VR191	AC84	—	R445	R444	AD144
1101847	VR192	—	—	R446	R447	—
1101849	VR191	AC62	—	R446	R447	—
1101850	VR130	AC103	—	R446	R447	—
1101924	VR148	AC13	AC12	R440	R443	—
1101925	VR148	AC13	AC12	R440	R443	—
1102225	VR122	—	—	—	—	—
1102326	VR122	—	—	—	—	—
1102346	VR148	AC9	AC12	R437	R432	—
1102347	VR148	AC9	AC12	R437	R432	—
1102348	—	AC9	AC12	R437	R432	—
1102349	VR148	AC9	AC12	R437	R432	—
1102350	VR148	AC9	AC12	R437	R432	—
1102352	VR148	AC9	AC12	R437	R432	—
1102353	VR148	AC9	AC12	R437	R432	—
1102354	VR148	AC9	AC12	R437	R432	—
1102359	VR148	AC9	AC12	R437	R432	—
1102360	—	AC9	—	R437	R432	—
1102361	VR148	AC9	AC12	R437	R432	—
1102362	VR148	AC9	AC12	R437	R432	—
1102363	VR148	AC9	AC12	R437	R432	—
1102364	VR162	AC9	AC12	R437	R432	—
1102365	VR162	AC9	AC12	R437	R432	—
1102366	—	AC9	AC12	R437	R432	—
1102367	VR148	AC9	AC12	R437	R432	—
1102368	VR148	AC9	AC12	R437	R432	—
1102369	VR148	AC9	AC12	R437	R432	—
1102370	VR162	AC9	AC12	R437	R432	—
1102375	VR148	AC9	AC12	R437	R432	—
1102379	—	AC9	AC12	R437	R432	—
1102380	VR148	AC9	AC12	R437	R432	—
1102381	VR148	AC9	AC12	R437	R432	—
1102382	VR148	AC9	AC12	R437	R432	—
1102383	VR148	AC9	AC12	R437	R432	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1102384	VR148	AC9	AC12	R437	R432	—
1102385	VR148	AC9	AC12	R437	R432	—
1102386	VR148	AC9	AC12	R437	R432	—
1102387	VR148	AC9	AC12	R437	R432	—
1102388	VR148	AC9	AC12	R437	R432	—
1102389	VR148	AC9	AC12	R437	R432	—
1102390	VR148	AC9	AC12	R437	R432	—
1102391	VR148	AC9	AC12	R437	R432	—
1102392	VR148	AC9	AC12	R437	R432	—
1102393	VR184	AC9	AC12	R437	R432	—
1102394	VR148	AC9	AC12	R437	R432	—
1102395	VR148	AC9	AC12	R437	R432	—
1102396	—	AC9	AC12	R437	R432	—
1102397	VR148	AC9	AC12	R437	R432	—
1102398	—	AC9	AC12	R437	R432	—
1102399	VR148	AC9	AC12	R437	R432	—
1102400	VR148	AC9	AC12	R437	R432	—
1102433	VR142	AC9	—	R437	R432	—
1102434	VR142	AC9	—	R437	R432	—
1102435	VR142	AC9	—	R437	R432	—
1102436	VR142	AC9	—	R437	R432	—
1102437	VR142	AC9	—	R437	R432	—
1102438	VR142	AC9	—	R437	R432	—
1102439	VR142	AC9	—	R437	R432	—
1102440	VR142	AC9	—	R437	R432	—
1102441	VR142	AC9	—	R437	R432	—
1102442	VR142	AC9	—	R437	R432	—
1102443	VR142	AC9	—	R437	R432	—
1102444	VR142	AC9	—	R437	R432	—
1102445	VR142	AC9	—	R437	R432	—
1102446	VR142	AC9	—	R437	R432	—
1102447	VR142	AC9	—	R437	R432	—
1102448	VR142	AC9	—	R437	R432	—
1102449	VR142	AC9	—	R437	R432	—
1102450	VR142	AC9	—	R437	R432	—
1102451	VR142	AC9	—	R437	R432	—
1102452	VR142	AC9	—	R437	R432	—
1102453	VR142	AC9	—	R437	R432	—
1102454	VR142	AC9	—	R437	R432	—
1102455	VR142	AC9	—	R437	R432	—
1102456	VR142	AC9	—	R437	R432	—
1102457	VR148	AC9	—	R437	R432	—
1102458	VR142	AC9	—	R437	R432	—
1102459	VR142	AC9	—	R437	R432	—
1102460	VR148	AC9	AC12	R437	R432	—
1102461	VR148	AC9	AC12	R437	R432	—
1102463	—	AC9	—	R437	R432	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1102464	—	AC9	—	R437	R432	—
1102465	VR148	AC9	AC12	R437	R432	—
1102466	VR148	AC9	AC12	R437	R432	—
1102467	VR148	AC9	AC12	R437	R432	—
1102468	VR148	AC9	AC12	R437	R432	—
1102471	VR148	AC9	AC12	R437	R432	—
1102472	VR148	AC9	AC12	R437	R432	—
1102474	VR148	AC9	AC12	R437	R432	—
1102475	VR148	AC9	AC12	R437	R432	—
1102476	VR148	AC9	AC12	R437	R432	—
1102477	VR148	AC9	AC12	R437	R432	—
1102478	VR148	AC9	AC12	R437	R432	—
1102479	VR148	AC9	AC12	R437	R432	—
1102480	VR148	AC9	AC12	R437	R432	—
1102481	VR148	AC9	AC12	R437	R432	—
1102482	VR148	AC9	AC12	R437	R432	—
1102483	VR148	AC9	AC12	R437	R432	—
1102484	VR148	AC9	AC12	R437	R432	—
1102485	VR148	AC9	AC12	R437	R432	—
1102486	VR148	AC9	AC12	R437	R432	—
1102488	VR148	AC9	AC12	R437	R432	—
1102491	VR148	AC9	AC12	R437	R432	—
1102493	VR148	AC9	AC12	R437	R432	—
1102494	VR148	AC9	AC12	R437	R432	—
1102495	VR148	AC9	AC12	R437	R432	—
1102496	VR184	AC9	AC12	R437	R432	—
1102497	VR148	AC9	AC12	R437	R432	—
1102498	VR148	AC9	AC12	R437	R432	—
1102499	VR148	AC9	AC12	R437	R432	—
1102500	VR148	AC9	AC12	R437	R432	—
1102548	VR148	AC9	AC12	R437	R432	—
1102549	VR148	AC9	AC12	R437	R432	—
1102550	VR148	AC9	AC12	R437	R432	—
1102551	VR148	—	—	—	—	—
1102553	VR184	AD1204	AD1206	R437	R432	—
1102600	VR192	AC62	—	R447	—	—
1102605	—	—	—	R446	R447	—
1102607	VR191	AC84	—	R445	R444	AD144
1102616	—	—	—	R446	R447	—
1102617	VR191	AC84	—	R445	R444	—
1102629	VR191	AC84	—	R445	R444	AD144
1102630	VR191	AC84	—	R445	R444	AD144
1102631	VR191	AC84	—	R445	R444	AD144
1102634	VR191	AC62	—	R446	R447	—
1102635	—	AC62	—	R446	R447	—
1102636	—	AC62	—	R447	—	—
1102637	VR191	AC62	—	R446	R447	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1102639	VR191	AC62	—	R446	R447	—
1102641	VR191	AC62	—	R446	R447	—
1102642	VR191	AC62	—	R446	R447	—
1102643	VR191	AC62	—	R446	R447	—
1102839	VR148	AC9	AC12	R437	R432	—
1102840	VR148	AC9	AC12	R437	R432	—
1102841	VR148	AC9	AC12	R437	R432	—
1102842	VR148	AC9	AC12	R437	R432	—
1102843	VR148	AC9	AC12	R437	R432	—
1102844	VR148	AC9	AC12	R437	R432	—
1102845	VR148	AC9	AC12	R437	R432	—
1102846	VR148	AC9	AC12	R437	R432	—
1102847	VR148	AC9	AC12	R437	R432	—
1102848	VR148	AC9	AC12	R437	R432	—
1102849	VR148	AC9	AC12	R437	R432	—
1102850	VR148	AC9	AC12	R437	R432	—
1102851	VR148	AC9	AC12	R437	R432	—
1102853	VR148	AC9	AC12	R437	R432	—
1102854	VR148	AC9	AC12	R437	R432	—
1102856	VR148	AC9	AC12	R437	R432	—
1102857	VR148	AC9	AC12	R437	R432	—
1102858	VR148	AC9	AC12	R437	R432	—
1102859	VR148	AC9	AC12	R437	R432	—
1102860	VR148	AC9	AC12	R437	R432	—
1102861	VR148	AC9	AC12	R437	R432	—
1102862	VR148	AC9	AC12	R437	R432	—
1102866	VR148	AC9	AC12	R437	R432	—
1102867	VR148	AC9	AC12	R437	R432	—
1102869	VR148	AC9	AC12	R437	R432	—
1102871	VR148	AC9	AC12	R437	R432	—
1102876	VR148	AC9	AC12	R437	R432	—
1102877	VR148	AC9	AC12	R437	R432	—
1102878	VR148	AC9	AC12	R437	R432	—
1102879	VR148	AC9	AC12	R437	R432	—
1102881	VR148	AC9	AC12	R437	R432	—
1102882	VR148	AC9	AC12	R437	R432	—
1102883	VR148	AC9	AC12	R437	R432	—
1102884	VR148	AC9	AC12	R437	R432	—
1102885	VR148	AC9	AC12	R437	R432	—
1102886	VR148	AC9	AC12	R437	R432	—
1102887	VR148	AC9	AC12	R437	R432	—
1102888	VR148	AC9	AC12	R437	R432	—
1102889	VR148	AC9	AC12	R437	R432	—
1102891	VR148	AC9	AC12	R437	R432	—
1102892	VR148	AC9	AC12	R437	R432	—
1102893	VR148	AC9	AC12	R437	R432	—
1102894	VR148	AC9	AC12	R437	R432	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1102895	VR148	AC9	AC12	R437	R432	—
1102896	VR148	AC9	AC12	R437	R432	—
1102897	VR148	AC9	AC12	R437	R432	—
1102898	VR148	AC9	AC12	R437	R432	—
1102901	VR148	AC9	AC12	R437	R432	—
1102902	VR148	AC9	AC12	R437	R432	—
1102903	VR148	AC9	AC12	R437	R432	—
1102904	VR148	AC9	AC12	R437	R432	—
1102905	VR148	AC9	AC12	R437	R432	—
1102906	VR148	AC9	AC12	R437	R432	—
1102907	VR148	AC9	AC12	R437	R432	—
1102908	VR148	AC9	AC12	R437	R432	—
1102909	VR148	AC9	AC12	R437	R432	—
1102910	VR148	AC9	AC12	R437	R432	—
1102911	VR148	AC9	AC12	R437	R432	—
1102913	VR148	AC9	AC12	R437	R432	—
1102914	VR148	AC9	AC12	R437	R432	—
1102915	VR148	AC9	AC12	R437	R432	—
1102918	—	AC9	AC12	R451	R422	—
1102919	—	AC9	AC12	R451	R422	—
1102920	VR148	AC9	AC12	R451	R422	—
1102921	VR148	AC9	AC12	R451	R422	—
1102922	VR148	AC9	AC12	R451	R422	—
1102924	VR162	AC9	AC12	R451	R422	—
1102925	VR148	AC9	AC12	R451	R422	—
1102926	VR148	AC9	AC12	R451	R422	—
1102927	VR148	AC9	AC12	R451	R422	—
1102928	VR148	AC9	AC12	R451	R422	—
1102929	VR148	AC9	AC12	R451	R422	—
1102930	VR148	AC9	AC12	R451	R422	—
1102931	VR162	AC9	AC12	R451	R422	—
1102932	VR148	AC9	AC12	R451	R422	—
1102933	VR148	AC9	AC12	R451	R422	—
1102934	—	AC9	AC12	R451	R422	—
1102935	VR148	AC9	AC12	R451	R422	—
1102936	VR148	AC9	AC12	R451	R422	—
1102937	VR148	AC9	AC12	R451	R422	—
1102938	VR148	AC9	AC12	R437	R432	—
1102939	VR148	AC9	AC12	R437	R432	—
1102940	VR148	AC9	AC12	R451	R422	—
1102941	VR148	AC9	AC12	R437	R432	—
1102942	VR148	AC9	AC12	R451	R422	—
1102943	VR142	AC2P	AC2N	R434	R429	—
1102944	VR142	AC2P	AC2N	R434	R429	—
1102945	VR142	AC2P	AC2N	R434	R429	—
1103033	VR148	AC9	AC12	R437	R432	—
1103034	VR148	AC9	AC12	R437	R432	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1103035	VR148	AC9	AC12	R451	R422	—
1103036	VR148	AC9	AC12	R437	R432	—
1103037	VR148	AC9	AC12	R437	R432	—
1103039	VR148	AC9	AC12	R437	R432	—
1103040	VR148	AC9	AC12	R437	R432	—
1103041	VR148	AC9	AC12	R437	R432	—
1103042	VR148	AC9	AC12	R437	R432	—
1103043	VR148	AC9	AC12	R437	R432	—
1103044	VR148	AC9	AC12	R437	R432	—
1103045	VR148	AC9	AC12	R437	R432	—
1103046	VR148	AC9	AC12	R437	R432	—
1103047	VR148	AC9	AC12	R437	R432	—
1103048	VR148	AC9	AC12	R437	R432	—
1103049	VR148	AC9	AC12	R437	R432	—
1103050	VR148	AC9	AC12	R437	R432	—
1103051	VR148	AC9	AC12	R437	R432	—
1103052	VR148	AC9	AC12	R437	R432	—
1103053	VR148	AC9	AC12	R437	R432	—
1103054	VR148	AC9	AC12	R451	R422	—
1103055	VR148	AC9	AC12	R437	R432	—
1103056	VR148	AC9	AC12	R437	R432	—
1103057	VR148	AC9	AC12	R437	R432	—
1103058	VR148	AC9	AC12	R437	R432	—
1103059	VR148	AC9	AC12	R437	R432	—
1103060	VR148	AC9	AC12	R437	R432	—
1103061	VR148	AC9	AC12	R437	R432	—
1103062	VR148	AC9	AC12	R437	R432	—
1103063	VR148	AC9	AC12	R437	R432	—
1103064	VR148	AC9	AC12	R437	R432	—
1103065	VR148	AC9	AC12	R437	R432	—
1103066	VR148	AC9	AC12	R437	R432	—
1103067	VR148	AC9	AC12	R437	R432	—
1103068	VR148	AC9	AC12	R437	R432	—
1103069	VR148	AC9	AC12	R437	R432	—
1103070	VR148	AC9	AC12	R437	R432	—
1103071	VR148	AC9	AC12	R437	R432	—
1103072	VR148	AC9	AC12	R451	R422	—
1103073	VR148	AC9	AC12	R437	R432	—
1103074	VR148	AC9	AC12	R437	R432	—
1103075	VR148	AC9	AC12	R437	R432	—
1103076	VR148	AC9	AC12	R437	R432	—
1103078	VR148	AC9	AC12	R437	R432	—
1103079	VR148	AC9	AC12	R437	R432	—
1103080	VR148	AC9	AC12	R437	R432	—
1103081	VR148	AC9	AC12	R437	R432	—
1103082	VR148	AC9	AC12	R437	R432	—
1103083	VR148	AC9	AC12	R437	R432	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1103084	VR148	AC9	AC12	R437	R432	—
1103085	VR148	AC9	AC12	R437	R432	—
1103086	VR148	AC9	AC12	R437	R432	—
1103088	VR148	AC9	AC12	R437	R432	—
1103089	VR148	AC9	AC12	R437	R432	—
1103090	VR148	AC9	AC12	R437	R432	—
1103091	VR148	AC9	AC12	R437	R432	—
1103092	VR148	AC9	AC12	R437	R432	—
1103093	VR148	AC9	AC12	R437	R432	—
1103094	VR148	AC9	AC12	R437	R432	—
1103095	VR148	AC9	AC12	R437	R432	—
1103096	VR148	AC9	AC12	R437	R432	—
1103097	VR148	AC9	AC12	R437	R432	—
1103098	VR148	AC9	AC12	R437	R432	—
1103099	VR148	AC9	AC12	R437	R432	—
1103100	VR148	AC9	AC12	R437	R432	—
1103101	VR148	AC9	AC12	R437	R432	—
1103102	VR148	AC9	AC12	R437	R432	—
1103103	VR148	AC9	AC12	R437	R432	—
1103104	VR148	AC9	AC12	R437	R432	—
1103105	VR148	AC9	AC12	R437	R432	—
1103106	VR148	AC9	AC12	R437	R432	—
1103107	VR148	AC9	AC12	R451	R422	—
1103111	VR148	AC9	AC12	R437	R432	—
1103112	VR148	AC9	AC12	R437	R432	—
1103113	VR148	AC9	AC12	R437	R432	—
1103114	VR148	AC9	AC12	R437	R432	—
1103116	VR148	AC9	AC12	R451	R422	—
1103117	VR148	AC9	AC12	R437	R432	—
1103118	VR148	AC9	AC12	R437	R432	—
1103119	VR148	AC9	AC12	R437	R432	—
1103120	VR148	AC9	AC12	R437	R432	—
1103121	VR148	AC9	AC12	R437	R432	—
1103122	VR148	AC9	AC12	R437	R432	—
1103123	—	AC9	AC12	R451	R422	—
1103124	VR148	AC9	AC12	R451	R422	—
1103125	VR148	AC9	AC12	R451	R422	—
1103126	VR148	AC9	AC12	R451	R422	—
1103127	VR148	AC9	AC12	R451	R422	—
1103128	VR148	AC9	AC12	R451	R422	—
1103129	VR148	AC9	AC12	R451	R422	—
1103130	VR148	AC9	AC12	R451	R422	—
1103131	VR148	AC9	AC12	R451	R422	—
1103132	VR182	AC9	AC12	R437	R432	—
1103133	VR148	AC9	AC12	R451	R422	—
1103134	VR148	AC9	AC12	R437	R432	—
1103135	VR148	AC9	AC12	R451	R422	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1103136	VR162	AC9	AC12	R451	R422	—
1103137	VR162	AC9	AC12	R451	R422	—
1103138	VR148	AC9	AC12	R451	R422	—
1103139	VR148	AC9	AC12	R437	R432	—
1103140	VR148	AC9	AC12	R437	R432	—
1103141	VR148	AC9	AC12	R451	R422	—
1103142	VR148	AC9	AC12	R437	R432	—
1103143	VR148	AC9	AC12	R437	R432	—
1103144	VR148	AC9	AC12	R437	R432	—
1103145	VR148	AC9	AC12	R437	R432	—
1103146	VR148	AC9	AC12	R437	R432	—
1103147	VR148	AC9	AC12	R437	R432	—
1103148	VR148	AC9	AC12	R437	R432	—
1103149	VR148	AC9	AC12	R437	R432	—
1103151	VR148	AC9	AC12	R437	R432	—
1103152	VR148	AC9	AC12	R437	R432	—
1103153	VR148	AC9	AC12	R437	R432	—
1103154	VR148	AC9	AC12	R437	R432	—
1103155	VR148	AC9	AC12	R437	R432	—
1103156	VR148	AC9	AC12	R437	R432	—
1103157	VR148	AC9	AC12	R437	R432	—
1103158	VR148	AC9	AC12	R437	R432	—
1103160	VR148	AC9	AC12	R451	R422	—
1103161	VR148	AC9	AC12	R437	R432	—
1103162	VR148	AC9	AC12	R437	R432	—
1103164	—	AC9	AC12	R451	R422	—
1103165	VR148	AC9	AC12	R451	R422	—
1103166	VR148	AC9	AC12	R451	R422	—
1103167	—	AC9	AC12	R451	R422	—
1103169	VR148	AC9	AC12	R437	R432	—
1103170	VR148	AC9	AC12	R437	R432	—
1103171	VR148	AC9	AC12	R451	R422	—
1103172	VR148	AC9	AC12	R451	R422	—
1103173	VR148	AC9	AC12	R451	R422	—
1103174	VR148	AC9	AC12	R451	R422	—
1103175	VR148	AC9	AC12	R451	R422	—
1103182	VR148	AC9	AC12	R437	R432	—
1103183	VR148	AC9	AC12	R451	R422	—
1103184	VR148	AC9	AC12	R451	R422	—
1103185	VR148	AC9	AC12	R451	R422	—
1103186	VR148	AC9	AC12	R437	R432	—
1103187	VR148	AC9	AC12	R437	R432	—
1103188	VR148	AC9	AC12	R451	R422	—
1103189	VR148	AC9	AC12	R451	R422	—
1103190	VR148	AC9	AC12	R437	R432	—
1103191	—	AC9	AC12	R451	R422	—
1103193	VR148	AC9	AC12	R437	R432	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1103195	VR148	AC9	AC12	R437	R432	—
1103196	VR148	AC9	AC12	R437	R432	—
1103197	VR148	AC9	AC12	R437	R432	—
1105022	VR148	AC26	AC12	R437	R432	—
1105023	VR148	AC26	AC12	R437	R432	—
1105025	VR148	AC26	AC12	R437	R432	—
1105027	VR148	AC26	AC12	R437	R432	—
1105028	VR148	AC26	AC12	R437	R432	—
1105029	VR148	AC26	AC12	R437	R432	—
1105032	VR148	AC26	AC12	R437	R432	—
1105034	VR148	AC26	AC12	R437	R432	—
1105036	VR148	AC26	AC12	R437	R432	—
1105040	VR148	AC13	AC12	R440	R443	—
1105041	VR148	AC26	AC12	R437	R432	—
1105042	VR148	AC26	AC12	R437	R432	—
1105043	VR148	AC26	AC12	R437	R432	—
1105044	VR148	AC26	AC12	R437	R432	—
1105045	VR148	AC26	AC12	R437	R432	—
1105046	VR148	AC26	AC12	R437	R432	—
1105047	VR148	AC26	AC12	R437	R432	—
1105048	VR148	AC26	AC12	R437	R432	—
1105049	VR148	AC26	AC12	R437	R432	—
1105050	VR148	AC26	AC12	R437	R432	—
1105058	VR148	AC26	AC12	R437	R432	—
1105059	VR148	AC26	AC12	R437	R432	—
1105060	VR148	AC26	AC12	R437	R432	—
1105063	VR148	AC26	AC12	R437	R432	—
1105064	VR148	AC26	AC12	R437	R432	—
1105065	VR148	AC26	AC12	R437	R432	—
1105066	VR148	AC26	AC12	R451	R422	—
1105067	VR148	AC26	AC12	R437	R432	—
1105068	VR148	AC26	AC12	R451	R422	—
1105069	VR148	AC26	AC12	R451	R422	—
1105070	VR148	AC26	AC12	R451	R422	—
1105071	VR148	AC26	AC12	R437	R432	—
1105072	VR148	AC26	AC12	R451	R422	—
1105073	VR148	AC26	AC12	R451	R422	—
1105074	VR148	AC26	AC12	R451	R422	—
1105075	VR148	AC26	AC12	R451	R422	—
1105076	VR148	AC26	AC12	R437	R432	—
1105077	—	AC26	AC12	R451	R422	—
1105078	VR148	AC26	AC12	R437	R432	—
1105079	VR148	AC26	AC12	R437	R432	—
1105080	VR148	AC26	AC12	R437	R432	—
1105081	VR148	AC26	AC12	R437	R432	—
1105082	VR148	AC26	AC12	R437	R432	—
1105083	VR148	AC26	AC12	R437	R432	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1105084	VR148	AC26	AC12	R437	R432	—
1105085	VR148	AC43	AC12	R440	R443	—
1105086	VR148	AC26	AC12	R451	R422	—
1105087	VR182	AC26	AC12	R437	R432	—
1105088	VR148	AC26	AC12	R437	R432	—
1105089	VR184	AC26	AC12	R437	R432	—
1105091	VR148	AC26	AC12	R437	R432	—
1105092	VR148	AC26	AC12	R437	R432	—
1105094	VR162	AC26	AC12	R437	R432	—
1105096	VR182	AC26	AC12	R437	R432	—
1105097	VR148	AC26	AC12	R437	R432	—
1105098	VR148	AC26	AC12	R451	R422	—
1105099	VR148	AC26	AC12	R451	R422	—
1105100	VR148	AC26	AC12	R451	R422	—
1105159	—	AC26	AC12	R451	R422	—
1105160	VR148	AC26	AC12	R451	R422	—
1105161	VR184	AC26	AC12	R451	R422	—
1105162	VR148	AC26	AC12	R451	R422	—
1105163	VR148	AC26	AC12	R451	R422	—
1105164	—	AC26	AC12	R451	R422	—
1105165	VR148	AC26	AC12	R451	R422	—
1105166	VR148	AC26	AC12	R451	R422	—
1105167	VR148	AC26	AC12	R451	R422	—
1105168	VR184	AC26	AC12	R451	R422	—
1105169	VR148	AC26	AC12	R451	R422	—
1105170	VR148	AC26	AC12	R451	R422	—
1105171	VR148	AC26	AC12	R451	R422	—
1105172	VR148	AC26	AC12	R451	R422	—
1105173	VR148	AC26	AC12	R451	R422	—
1105174	VR148	AC26	AC12	R451	R422	—
1105175	VR148	AC26	AC12	R451	R422	—
1105176	VR148	AC26	AC12	R451	R422	—
1105177	VR148	AC26	AC12	R451	R422	—
1105178	VR148	AC26	AC12	R451	R422	—
1105179	—	AC26	AC12	R451	R422	—
1105180	VR182	AC26	AC12	R451	R422	—
1105183	VR148	AC26	AC12	R437	R432	—
1105185	VR148	AC26	AC12	R437	R432	—
1105186	VR148	AC13	AC12	R440	R443	—
1105189	VR148	AC13	AC12	R440	R443	—
1105190	VR148	AC13	AC12	R440	R443	—
1105193	VR148	AC26	AC12	R437	R432	—
1105194	VR148	AC26	AC12	R437	R432	—
1105195	VR148	AC26	AC12	R437	R432	—
1105196	VR148	AC13	AC12	R440	R443	—
1105197	VR148	AC13	AC12	R440	R443	—
1105198	VR148	AC13	AC12	R440	R443	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1105199	VR148	AC13	AC12	R440	R443	—
1105200	VR148	AC13	AC12	R440	R443	—
1105243	VR148	AC13	AC12	R440	R443	—
1105244	VR148	AC26	AC12	R451	R422	—
1105245	VR148	AC26	AC12	R451	R422	—
1105246	VR148	AC13	AC12	R440	R443	—
1105249	VR148	AC13	AC12	R440	R443	—
1105250	VR148	AC13	AC12	R440	R443	—
1105329	VR148	AC13	AC12	R440	R443	—
1105331	VR148	AC13	AC12	R440	R443	—
1105332	VR148	AC13	AC12	R440	R443	—
1105333	VR148	AC13	AC12	R440	R443	—
1105334	VR148	AC13	AC12	R440	R443	—
1105335	VR148	AC13	AC12	R440	R443	—
1105336	VR148	AC13	AC12	R440	R443	—
1105337	VR148	AC13	AC12	R440	R443	—
1105338	VR148	AC13	AC12	R440	R443	—
1105339	VR148	AC13	AC12	R440	R443	—
1105340	VR148	AC13	AC12	R440	R443	—
1105341	VR148	AC13	AC12	R440	R443	—
1105343	VR148	AC13	AC12	R440	R443	—
1105345	VR148	AD1204	AD1206	R437	R432	—
1105346	VR148	AC13	AC12	R440	R443	—
1105347	VR148	AC13	AC12	R440	R443	—
1105348	VR148	AC26	AC12	R437	R432	—
1105351	VR148	AC26	AC12	R437	R432	—
1105354	VR148	AC26	AC12	R437	R432	—
1105355	VR148	AC26	AC12	R437	R432	—
1105356	VR148	AC26	AC12	R437	R432	—
1105357	VR148	AC26	AC12	R437	R432	—
1105358	VR148	AC26	AC12	R437	R432	—
1105359	VR148	AC26	AC12	R437	R432	—
1105360	VR148	AC26	AC12	R437	R432	—
1105361	VR148	AC26	AC12	R437	R432	—
1105363	VR148	AC26	AC12	R437	R432	—
1105364	VR148	AC26	AC12	R437	R432	—
1105365	VR148	AC26	AC12	R437	R432	—
1105366	VR148	AC43	AC12	R440	R443	—
1105367	VR148	AC26	AC12	R437	R432	—
1105368	VR148	AC26	AC12	R437	R432	—
1105369	VR148	AC26	AC12	R437	R432	—
1105370	VR148	AC26	AC12	R437	R432	—
1105371	VR148	AC26	AC12	R437	R432	—
1105372	VR148	AC26	AC12	R437	R432	—
1105373	VR148	AC43	AC12	R440	R443	—
1105374	VR148	AC13	AC12	R440	R443	—
1105387	VR148	AC26	AC12	R437	R432	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1105402	VR148	AC29	AC12	R437	R432	—
1105415	VR148	AC13	AC12	R440	R443	—
1105416	VR148	AC43	AC12	R440	R443	—
1105418	VR148	—	AC12	—	—	—
1105419	—	AC26	AC12	R451	R422	—
1105420	VR148	AC26	AC12	R451	R422	—
1105422	VR148	AC26	AC12	R451	R422	—
1105423	VR148	AC26	AC12	R451	R422	—
1105424	VR148	AC26	AC12	R451	R422	—
1105425	VR148	AC29	AC12	R437	R432	—
1105426	VR148	AC26	AC12	R437	R432	—
1105427	VR148	AC26	AC12	R437	R432	—
1105428	VR148	AC29	AC12	R437	R432	—
1105429	VR148	AC26	AC12	R451	R422	—
1105430	VR148	AC26	AC12	R451	R422	—
1105431	—	AC26	AC12	R451	R422	—
1105432	VR148	AC26	AC12	R437	R432	—
1105433	VR148	AC13	AC12	R440	R443	—
1105434	VR162	AC26	AC12	R451	R422	—
1105435	VR148	AC26	AC12	R451	R422	—
1105436	—	AC26	AC12	R451	R422	—
1105437	VR182	AC26	AC12	R451	R422	—
1105438	VR148	AC13	AC12	R437	R432	—
1105439	VR148	AC26	AC12	R437	R432	—
1105440	VR148	AC26	AC12	R437	R432	—
1105441	VR148	AC29	AC12	R437	R432	—
1105443	VR148	AC29	AC12	R437	R432	—
1105444	VR148	AC29	AC12	R437	R432	—
1105446	VR148	AC29	AC12	R437	R432	—
1105447	VR148	AC29	AC12	R437	R432	—
1105449	VR148	AC29	AC12	R437	R432	—
1105450	VR148	AC43	AC12	R440	R443	—
1105451	VR148	AC43	AC12	R440	R443	—
1105453	VR182	AC26	AC12	R437	R432	—
1105454	VR182	AC26	AC12	R437	R432	—
1105455	VR184	AC26	AC12	R451	R422	—
1105456	VR184	AC26	AC12	R451	R422	—
1105457	VR184	AC26	AC12	R451	R422	—
1105458	VR182	AC26	AC12	R451	R422	—
1105459	VR182	AC26	AC12	R451	R422	—
1105460	VR184	AD1204	AD1206	R437	R432	—
1105461	VR184	—	AD1206	R437	R432	—
1105463	VR184	AD1204	AD1206	R437	R432	—
1105464	VR184	AD1204	AD1206	R437	R432	—
1105465	VR184	AD1204	AD1206	R437	R432	—
1105466	VR184	—	AD1206	R437	R432	—
1105469	VR184	AD1204	AD1206	R437	R432	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1105470	VR184	AD1204	AD1206	R437	R432	—
1105471	VR184	—	AD1206	R437	R432	—
1105472	VR184	AD1204	AD1206	R437	R432	—
1105473	VR184	AD1204	AD1206	R437	R432	—
1105474	VR182	AD1204	AD1206	R437	R432	—
1105475	VR182	AD1204	AD1206	R437	R432	—
1105476	VR182	AD1204	AD1206	R437	R432	—
1105477	VR182	AD1204	AD1206	R437	R432	—
1105478	VR184	AC26	AC12	R437	R432	—
1105479	VR148	AC43	AC12	R440	R443	—
1105480	VR148	AC29	AC12	R437	R432	—
1105481	VR148	AC43	AC12	R440	R443	—
1105482	VR184	AC26	AC12	R437	R432	—
1105491	VR148	AC43	AC12	—	—	—
1105492	VR148	AC29	AC12	R437	R432	—
1105493	VR148	AC29	AC12	R437	R432	—
1105494	VR148	AC26	AC12	R437	R432	—
1105495	VR148	AC29	AC12	R437	R432	—
1105496	VR148	AC29	AC12	R437	R432	—
1105497	VR148	AC43	AC12	R440	R443	—
1105500	VR148	AD1204	AD1206	R437	R432	—
1105503	VR148	AC26	AC12	R437	R432	—
1105504	VR148	AC26	AC12	R437	R432	—
1105505	VR148	AC26	AC12	R437	R432	—
1105506	VR148	AC29	AC12	R437	R432	—
1105507	VR148	AC29	AC12	R437	R432	—
1105508	VR148	AC26	AC12	R437	R432	—
1105509	VR148	AC43	AC12	R437	R432	—
1105510	—	AC26	AC12	R451	R422	—
1105511	VR148	AC26	AC12	R440	R443	—
1105512	VR148	AC13	AC12	R437	R432	—
1105513	VR148	AC43	AC12	R440	R443	—
1105514	VR148	AC26	AC12	R451	R422	—
1105515	VR148	AC43	AC12	R440	R443	—
1105516	VR148	AC26	AC12	R440	R443	—
1105517	VR148	AC26	AC12	R437	R432	—
1105518	VR148	AC13	AC12	R437	R432	—
1105519	VR148	AC13	AC12	R440	R443	—
1105521	VR148	AC26	AC12	R440	R443	—
1105522	VR148	AC26	AC12	R437	R432	—
1105523	VR148	AC26	AC12	R437	R432	—
1105536	VR148	—	AC12	—	—	—
1105537	—	AC26	AC12	R451	R422	—
1105538	—	—	AC12	—	—	—
1105539	VR148	—	AC12	—	—	—
1105540	VR148	—	AC12	—	—	—
1105541	VR148	AC29	AC12	R437	R432	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1105542	VR148	AC29	AC12	R437	R432	—
1105543	VR148	AC29	AC12	R437	R432	—
1105544	VR148	AC29	AC12	R437	R432	—
1105545	VR148	AC29	AC12	R437	R432	—
1105547	VR148	AC29	AC12	R440	R443	—
1105548	VR148	AC13	AC12	R440	R443	—
1105549	VR148	AC43	AC12	R440	R443	—
1105552	VR148	AC13	AC12	R440	R443	—
1105553	VR148	AC43	AC12	R440	R443	—
1105555	VR148	AC26	AC12	R437	R432	—
1105556	VR148	AC26	AC12	R437	R432	—
1105558	VR148	AC26	AC12	R451	R422	—
1105559	VR148	AC26	AC12	R451	R422	—
1105560	VR148	—	AC12	—	—	—
1105561	VR148	AC29	AC12	R437	R432	—
1105562	VR148	AC29	AC12	R437	R432	—
1105564	VR148	AC26	AC12	R437	R432	—
1105565	VR148	AC26	AC12	R437	R432	—
1105566	VR148	AC26	AC12	R437	R432	—
1105567	VR148	AC26	AC12	R437	R432	—
1105568	VR148	AC26	AC12	R437	R432	—
1105569	VR148	AC26	AC12	R437	R432	—
1105570	VR148	AC43	AC12	R440	R443	—
1105572	VR148	AC29	AC12	R437	R432	—
1105573	—	AC26	AC12	R451	R422	—
1105574	—	AC26	AC12	R451	R422	—
1105575	VR148	AC26	AC12	R437	R432	—
1105576	VR148	AC26	AC12	R437	R432	—
1105577	VR148	AD1204	AD1206	R437	R432	—
1105578	VR148	AD1204	AD1206	R437	R432	—
1105579	VR148	—	AC12	—	—	—
1105580	VR148	AC26	AC12	R437	R432	—
1105581	VR148	AC29	AC12	R437	R432	—
1105582	VR148	AC29	AC12	R437	R432	—
1105584	VR148	AC26	AC12	R451	R422	—
1105585	VR190	AC62	AC101	R440	R443	—
1105586	VR148	AC26	AC12	R451	R422	—
1105587	VR148	AC43	AC12	R440	R443	—
1105588	VR148	AC26	AC12	R437	R432	—
1105590	VR148	AC26	AC12	R437	R432	—
1105591	VR148	AC26	AC12	R437	R432	—
1105592	VR148	AC29	AC12	R437	R432	—
1105594	VR148	AC26	AC12	R437	R432	—
1105595	VR148	AC43	AC12	R440	R443	—
1105596	VR148	AC43	AC12	R440	R443	—
1105597	VR148	AC26	AC12	R437	R432	—
1105598	VR148	AC26	AC12	R437	R432	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1105599	VR148	AC26	AC12	R437	R432	—
1105600	VR148	AC26	AC12	R437	R432	—
1105602	VR148	AC29	AC12	R437	R432	—
1105603	VR148	AC26	AC12	R437	R432	—
1105604	VR148	AC29	AC12	R437	R432	—
1105606	VR148	AC29	AC12	R437	R432	—
1105607	VR148	AC26	AC12	R437	R432	—
1105608	VR148	AC26	AC12	R437	R432	—
1105609	VR148	—	AC12	—	—	—
1105610	VR148	AC26	AC12	R437	R432	—
1105611	VR148	AC26	AC12	R437	R432	—
1105612	VR192	AC84	—	R445	R444	—
1105613	VR190	AC62	AC101	R440	R443	—
1105615	VR192	AC62	—	R446	R447	—
1105616	VR192	AC62	—	R446	R447	—
1105617	VR148	AC29	AC12	R437	R432	—
1105618	VR148	AC43	AC12	R440	R443	—
1105619	VR148	AC26	AC12	R451	R422	—
1105620	VR148	AC26	AC12	R437	R432	—
1105621	VR148	AC26	AC12	R437	R432	—
1105622	VR148	AC13	AC12	R440	R443	—
1105623	VR190	AC26	AC12	R437	R432	—
1105624	VR148	AC26	AC12	R437	R432	—
1105625	VR192	AC62	—	R446	R447	—
1105626	VR192	AC62	—	R446	R447	—
1105627	VR190	AC26	AC12	R437	R432	—
1105628	VR190	AC26	AC12	R437	R432	—
1105629	VR190	AC29	AC12	R437	R432	—
1105630	VR190	AC29	AC12	R437	R432	—
1105631	VR190	AC26	AC12	R437	R432	—
1105632	VR190	AC26	AC12	R437	R432	—
1105633	VR190	AC26	AC12	R437	R432	—
1105634	VR190	AC26	AC12	R437	R432	—
1105635	VR190	AC26	AC12	R437	R432	—
1105637	VR148	AD1204	AD1206	R437	R432	—
1105639	VR148	AC43	AC12	R440	R443	—
1105643	VR190	AC62	AC101	R440	R443	—
1105645	VR148	AC26	AC12	R451	R422	—
1105647	VR148	AC26	AC12	R437	R432	—
1105648	VR148	AC29	AC12	R437	R432	—
1105649	VR148	AC26	AC12	R437	R432	—
1105650	VR148	AC26	AC12	R437	R432	—
1105651	VR148	AC29	AC12	R437	R432	—
1105652	VR148	AC26	AC12	R437	R432	—
1105653	VR148	AC26	AC12	R437	R432	—
1105654	VR148	AC29	AC12	R437	R432	—
1105656	VR190	AC62	AC101	R440	R443	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1105657	VR192	AC62	—	R446	R447	—
1105658	VR190	AC62	AC101	R440	R443	—
1105661	VR191	AC84	—	R445	R444	—
1105662	VR192	AC84	—	R445	R444	—
1105663	VR192	AC84	—	R445	R444	—
1105664	VR192	AC84	—	R445	R444	—
1105665	VR192	AC84	—	R445	R444	—
1105667	VR192	AC84	—	R445	R444	—
1105669	VR192	AC84	—	R445	R444	—
1105670	VR192	AC84	—	R445	R444	—
1105671	VR192	AC84	—	R445	R444	—
1105672	VR192	AC84	—	R445	R444	—
1105673	VR148	AC26	AC12	R437	R432	—
1105674	VR148	AC26	AC12	R437	R432	—
1105675	VR148	AC26	AC12	R437	R432	—
1105676	VR148	AC26	AC12	R437	R432	—
1105677	VR148	AC26	AC12	R437	R432	—
1105678	VR192	AC84	—	R445	R444	—
1105680	VR190	AC62	AC101	R440	R443	—
1105681	VR148	AC43	AC12	R440	R443	—
1105683	VR190	AC62	AC101	R440	R443	—
1105684	VR192	AC62	—	R446	R447	—
1105685	VR192	AC62	—	R446	R447	—
1105686	—	AC26	AC12	R451	R422	—
1105688	VR191	AC84	—	R445	R444	—
1105690	VR190	AC62	AC101	R440	R443	—
1105691	VR148	AC26	AC12	R437	R432	—
1105692	VR148	AC26	AC12	R437	R432	—
1105693	VR148	AD1204	AD1206	R437	R432	—
1105694	VR191	AC84	—	R445	R444	—
1105696	VR190	AC43	AC12	R440	R443	—
1105698	VR191	AC84	—	R445	R444	—
1105701	VR191	AC84	—	R445	R444	—
1105702	VR148	AC26	AC12	R451	R422	—
1105703	VR148	AC26	AC12	R437	R432	—
1105704	VR148	AC26	AC12	R437	R432	—
1105705	VR148	AC26	AC12	R437	R432	—
1105706	VR148	AC26	AC12	R437	R432	—
1105707	VR148	AC26	AC12	R437	R432	—
1105708	VR148	AC26	AC12	R437	R432	—
1105709	VR148	AD1204	AD1206	R437	R432	—
1105710	VR191	AC84	—	R445	R444	—
1105711	VR191	AC84	—	R445	R444	—
1105712	VR191	AC84	—	R445	R444	—
1105715	VR191	AC84	—	R445	R444	—
1105716	VR191	AC84	—	R445	R444	—
1105718	VR191	AC84	—	R445	R444	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1105720	VR191	AC84	—	R445	R444	—
1105722	VR191	AC84	—	R445	R444	—
1105725	VR191	AC84	—	R445	R444	—
1117067	VR184	AD1204	AC63	—	—	—
1117068	VR184	AD1204	AC63	—	—	—
1117069	VR195	AC2P	AC2N	—	—	—
1117131	VR154	—	—	—	—	—
1117133	VR160	—	—	—	—	—
1117141	VR162	AC9	—	R437	R432	—
1117142	VR162	AC9	—	R437	R432	—
1117143	VR162	AC9	—	R437	R432	—
1117144	VR162	AC9	—	R437	R432	—
1117145	VR162	AC9	—	R437	R432	—
1117146	VR162	AC9	—	R437	R432	—
1117147	VR184	AC9	—	R437	R432	—
1117148	VR184	AC9	—	R437	R432	—
1117149	VR184	AC9	—	R437	R432	—
1117150	VR184	AC9	—	R437	R432	—
1117151	VR184	AC9	—	R437	R432	—
1117152	VR184	AC9	—	R437	R432	—
1117155	VR193	AC2P	AC2N	—	—	—
1117160	VR184	AD1204	—	—	—	—
1117161	VR184	AD1204	—	—	—	—
1117162	VR184	AC9	—	—	—	—
1117163	VR182	AD1204	—	—	—	—
1117164	VR184	AD1204	—	—	—	—
1117165	VR184	AD1204	—	—	—	—
1117180	VR188	—	—	—	—	—
1117182	VR188	—	—	—	—	—
1117183	VR188	—	—	—	—	—
1117185	VR188	—	—	—	—	—
1117225	VR193	AC2P	AC2N	—	—	—
1117226	VR195	AC2P	AC2N	—	—	—
1117227	VR193	AC2P	AC2N	—	—	—
1117228	VR193	AC2P	AC2N	—	—	—
1117229	VR195	AC2P	AC2N	—	—	—
1117231	VR193	AC2P	AC2N	—	—	—
1117232	VR193	AC2P	AC2N	—	—	—
1117233	—	AC2P	AC2N	—	—	—
1117234	VR193	AC2P	AC2N	—	—	—
1117235	VR193	AC2P	AC2N	—	—	—
1117236	VR195	AC2P	AC2N	—	—	—
1117237	—	AC2P	AC2N	—	—	—
1117238	VR195	AC2P	AC2N	—	—	—
1117239	VR195	AC2P	AC2N	—	—	—
1117240	VR193	AC2P	AC2N	—	—	—
1117241	VR193	AC2P	AC2N	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1117242	VR193	AC2P	AC2N	—	—	—
1117243	VR195	AC2P	AC2N	—	—	—
1117244	VR193	AC2P	AC2N	—	—	—
1117245	VR193	AC2P	AC2N	—	—	—
1117246	—	AC2P	AC2N	—	—	—
1117248	VR195	AC2P	AC2N	—	—	—
1117249	VR195	AC2P	AC2N	—	—	—
1117250	VR195	AC2P	AC2N	—	—	—
1117251	VR193	AC2P	AC2N	—	—	—
1117252	VR193	AC2P	AC2N	—	—	—
1117253	VR195	AC2P	AC2N	—	—	—
1117254	VR195	AC2P	AC2N	—	—	—
1117255	VR193	AC2P	AC2N	—	—	—
1117256	VR195	AC2P	AC2N	—	—	—
1117261	VR193	AC2P	AC2N	—	—	—
1117262	VR193	AC2P	AC2N	—	—	—
1117263	VR193	AC2P	AC2N	—	—	—
1117264	VR193	AC2P	AC2N	—	—	—
1117265	VR193	AC2P	AC2N	—	—	—
1117266	VR193	AC2P	AC2N	—	—	—
1117267	VR193	AC2P	AC2N	—	—	—
1117268	VR193	AC2P	AC2N	—	—	—
1117269	VR193	AC2P	AC2N	—	—	—
1117270	VR193	AC2P	AC2N	—	—	—
1117271	—	AC2P	AC2N	—	—	—
1117272	VR193	AC2P	AC2N	—	—	—
1117276	VR193	AC2P	AC2N	—	—	—
1117278	VR193	AC2P	AC2N	—	—	—
1117279	VR193	AC2P	AC2N	—	—	—
1117481	VR184	AD1204	AC63	—	—	—
1117482	VR184	AD1204	AC63	—	—	—
1117483	VR184	AD1204	AC63	—	—	—
1117484	VR184	AD1204	AC63	—	—	—
1117485	VR184	AD1204	AC63	—	—	—
1117611	VR184	AC9	AC12	—	—	—
1117612	VR184	AC9	AC12	—	—	—
1117616	VR184	AC9	AC12	—	—	—
1117618	VR184	AC9	AC12	—	—	—
1117619	VR182	AC9	AC12	—	—	—
1117621	VR184	AC9	AC12	—	—	—
1117622	VR182	AC9	AC12	—	—	—
1117623	VR182	AC9	AC12	—	—	—
1117625	VR182	AC9	AC12	—	—	—
1117640	VR182	AC9	AC12	—	—	—
1117641	VR184	AC9	AC12	—	—	—
1117642	VR182	AC9	AC12	—	—	—
1117643	VR182	AC9	AC12	—	—	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1117644	VR182	AC9	AC12	—	—	—
1117645	VR182	AC9	AC12	—	—	—
1117647	VR182	AC9	AC12	—	—	—
1117648	VR182	—	AC63	—	—	—
1117649	—	—	AC63	—	—	—
1117655	—	AC9	AC12	—	—	—
1117732	VR184	AD1204	AC63	—	—	—
1117733	—	—	AC63	—	—	—
1117734	VR182	—	AC63	—	—	—
1117735	VR184	—	AC63	—	—	—
1117736	VR184	AD1204	AC63	—	—	—
1117737	VR182	AD1204	—	—	—	—
1117738	VR184	—	AC63	—	—	—
1117742	VR184	AD1204	AC63	—	—	—
1117743	VR184	—	AC63	—	—	—
1117744	VR184	AD1204	AC63	—	—	—
1117745	VR184	—	AC63	—	—	—
1117746	VR182	—	AC63	—	—	—
1117747	—	—	AC63	—	—	—
1117750	—	—	—	R427	—	—
1117752	—	—	—	R427	—	—
1117753	VR142	—	—	R427	—	—
1117754	—	—	—	R427	—	—
1117756	VR154	—	—	R431	—	—
1117760	VR154	—	—	R427	—	—
1117761	VR154	—	—	R427	—	—
1117763	VR154	—	—	R431	—	—
1117765	—	—	—	R427	—	—
1117767	VR154	—	—	R427	—	—
1117769	VR154	—	—	R431	—	—
1117772	VR156	—	—	R431	—	—
1117773	—	—	—	R431	—	—
1117774	VR156	—	—	R431	—	—
1117777	VR148	—	—	R431	—	—
1117778	VR154	—	—	R431	—	—
1117779	—	—	—	R431	—	—
1117780	VR142	—	—	R427	—	—
1117781	VR154	—	—	R431	—	—
1117782	VR148	—	—	R427	—	—
1117783	VR154	—	—	R431	—	—
1117784	VR156	—	—	R431	—	—
1117785	VR160	—	—	R431	—	—
1117786	VR156	—	—	R431	—	—
1117787	VR154	—	—	R427	—	—
1117800	VR184	AD1204	AC63	—	—	—
1117801	VR184	AD1204	AC63	—	—	—
1117802	VR184	—	AC63	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1117803	VR184	AD1204	AC63	—	—	—
1117804	VR184	AD1204	AC63	—	—	—
1117805	VR182	AD1204	AC63	—	—	—
1117806	VR184	AD1204	AC63	—	—	—
1117807	VR184	AD1204	AC63	—	—	—
1117808	VR184	AD1204	AC63	—	—	—
1117809	VR184	AD1204	AC63	—	—	—
1117811	VR184	AD1204	AC63	—	—	—
1117812	VR184	AD1204	AC63	—	—	—
1117813	VR184	AD1204	AC63	—	—	—
1117816	VR184	AD1204	AC63	R432	—	—
1117817	VR182	AD1204	AC63	—	—	—
1117818	VR184	AD1204	AC63	—	—	—
1117819	VR184	AD1204	AC63	—	—	—
1117820	—	AD1204	AC63	—	—	—
1117821	VR182	AD1204	AC63	—	—	—
1117822	VR184	AD1204	AC63	—	—	—
1117823	VR184	AD1204	AC63	—	—	—
1117825	—	—	AC63	—	—	—
1117826	VR182	—	AC63	—	—	—
1117827	VR184	—	AC63	—	—	—
1117828	VR182	AD1204	AC63	—	—	—
1117830	—	AD1204	AC63	—	—	—
1117831	VR182	AD1204	AC63	—	—	—
1117880	VR184	AC62	AC101	R451	R450	—
1117885	VR184	AC62	AC101	R451	R450	—
1117886	VR184	AC62	AC101	R451	R450	—
1117887	VR184	AC62	AC101	R451	R450	—
1117890	VR184	AC62	AC101	R451	R450	—
1117891	VR184	—	AC101	R451	R450	—
1117892	VR184	AC62	AC101	R451	R450	—
1117894	VR184	AC62	AC101	R451	R450	—
1117895	—	AC94	AC101	R451	R450	—
1117896	—	AC100	AC101	R451	R450	—
1117897	VR182	AC62	AC101	R451	R450	—
1117898	—	—	AC101	R451	R450	—
1117899	VR148	AC100	AC101	R451	R450	—
1117900	VR182	AC62	AC101	R451	R450	—
1117903	VR148	AC94	AC101	R451	R450	—
1117904	VR148	AC100	AC101	R451	R450	—
1117905	VR184	AC94	AC101	R451	R450	—
1117906	VR184	AC62	AC101	R451	R450	—
1117909	VR184	AC100	AC101	R451	R450	—
1117910	VR184	AC62	AC101	R451	R450	—
1117911	—	AC100	AC101	R451	R450	—
1117912	—	AC62	AC101	R451	R450	—
1117913	VR184	—	AC101	R451	R450	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1117914	VR184	—	AC101	R451	R450	—
1117915	VR182	AC62	AC101	R451	R450	—
1117916	VR184	AC100	AC101	R451	R450	—
1117917	VR184	AC100	AC101	R451	R450	—
1117918	VR184	AC100	AC101	R451	R450	—
1117919	VR184	AC100	AC101	R451	R450	—
1117920	VR184	AC100	AC101	R451	R450	—
1117921	VR184	AC100	AC101	R451	R450	—
1117922	VR184	AC100	AC101	R451	R450	—
1117923	VR184	AC62	AC101	R451	R450	—
1117924	—	AC100	AC101	R451	R450	—
1117925	—	AC62	AC101	R451	R450	—
1117926	—	AC100	AC101	R451	R450	—
1117927	—	AC94	AC101	R451	R450	—
1117928	VR148	AC100	AC101	R451	R450	—
1117929	VR184	AC100	AC101	R451	R450	—
1117931	VR184	AC62	AC101	R451	R450	—
1117932	VR184	—	AC101	R451	R450	—
1117933	VR184	AC100	AC101	R451	R450	—
1117934	VR184	AC100	AC101	R451	R450	—
1117936	—	AC100	AC101	R451	R450	—
1117937	—	AC94	AC101	R451	R450	—
1117938	—	AC100	AC101	R451	R450	—
1117939	—	AC62	AC101	R451	R450	—
1117940	—	AC62	AC101	R451	R450	—
1117941	VR184	AC62	AC101	R451	R450	—
1117942	VR184	AC62	AC101	R451	R450	—
1117943	VR184	AC100	AC101	R451	R450	—
1117944	—	AC62	AC101	R451	R450	—
1117945	—	AC100	AC101	R451	R450	—
1117946	VR184	—	AC101	R451	R450	—
1117947	—	AC62	AC101	R451	R450	—
1117948	—	AC100	AC101	R451	R450	—
1117949	—	AC100	AC101	R451	R450	—
1117950	—	AC62	AC101	R451	R450	—
1117951	—	AC62	AC101	R451	R450	—
1117952	—	AC100	AC101	R451	R450	—
1117953	—	AC62	AC101	R451	R450	—
1117954	VR184	AC62	AC101	R451	R450	—
1117955	VR184	AC62	AC101	R451	R450	—
1117956	VR184	AC62	AC101	R451	R450	—
1117957	VR184	AC94	AC101	R451	R450	—
1117958	VR184	AC94	AC101	R451	R450	—
1117959	VR184	AC94	AC101	R451	R450	—
1117960	VR184	AC94	AC101	R451	R450	—
1117961	VR184	AC100	AC101	R451	R450	—
1117962	VR184	AC94	AC101	R451	R450	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
1117963	VR184	AC94	AC101	R451	R450	—
1117964	VR184	AC100	AC101	R451	R450	—
1117965	VR184	—	AC101	R451	R450	—
1117966	VR184	—	AC101	R451	R450	—
1204091	—	—	—	E453	—	—
1204093	—	—	—	E453	—	—
1204102	—	—	—	E453	—	—
1204160	—	—	—	E453	—	—
1204161	—	—	—	E453	—	—
4117684	VR184	AC63	AD1204	—	—	—
4267281	VR191	AC62	—	R447	—	—
5214262	VR191	AC84	—	—	—	—
9484298	VR575	—	—	E601	—	—
10459002	VR182	AD1204	AC63	—	—	—
10459003	VR193	AC2P	AC2N	—	—	—
10459004	VR184	AD1204	AC63	—	—	—
10459005	VR193	AC2P	AC2N	—	—	—
10459006	VR195	AC2P	AC2N	—	—	—
10459007	VR195	AC2P	AC2N	—	—	—
10459008	VR184	AD1204	AC63	—	—	—
10459009	VR184	AD1204	AC63	—	—	—
10459010	VR184	—	AC63	—	—	—
10463070	VR130	AC103	—	—	—	—
10463201	VR191	—	—	R447	—	—
10463338	VR191	AC103	—	R447	—	—
10463523	VR191	AC103	—	R447	—	—
10463634	VR131	—	—	R447	—	—
10463637	VR191	AC103	—	—	—	—
10463680	VR191	AC103	—	R447	—	—
10463686	VR191	AC62	—	—	—	—
10463691	VR130	—	—	R447	—	—
10463844	—	AC103	—	R447	—	—
10464076	VR196	AC103	—	R447	—	—
10464089	VR196	—	—	R447	—	—
10470040	VR191	AC84	—	R445	R444	—
10470201	VR191	AC103	—	R447	—	—
10479800	VR191	AC84	—	R445	R444	—
10479801	VR191	AC84	—	R445	R444	—
10479802	VR191	AC84	—	R445	R444	—
10479806	VR191	AC84	—	R445	R444	—
10479807	VR191	AC84	—	R445	R444	—
10479808	VR191	AC84	—	R445	R444	—
10479809	VR191	AC62	—	R446	R447	—
10479814	VR191	AC84	—	R445	R444	—
10479817	VR191	—	—	R446	R447	—
10479821	—	AC103	—	R446	R447	—
10479823	VR148	AC13	AC12	R440	R443	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
10479825	VR148	AC13	AC12	R440	R443	—
10479826	VR148	AC13	AC12	R440	R443	—
10479827	VR148	AC13	AC12	R440	R443	—
10479832	VR148	AC13	AC12	R440	R443	—
10479833	VR148	AC13	AC12	R440	R443	—
10479834	VR148	AC13	AC12	R440	R443	—
10479836	VR191	AC94	—	R446	R447	—
10479838	VR191	AC94	—	R446	R447	—
10479839	VR191	AC100	—	R446	R447	—
10479843	VR192	AC62	—	R446	R447	—
10479844	VR191	AC62	—	R446	R447	—
10479847	VR191	AC62	—	R446	R447	—
10479852	—	AC103	—	R446	R447	—
10479853	VR191	AC62	—	R446	R447	—
10479854	VR191	AC62	—	R446	R447	—
10479855	VR191	AC62	—	R446	R447	—
10479858	VR148	AC43	AC12	R440	R443	—
10479860	VR148	AC43	AC12	R440	R443	—
10479862	VR148	AC43	AC12	R440	R443	—
10479864	VR190	AC62	AC101	R440	R443	—
10479865	VR148	AC43	AC12	R440	R443	—
10479866	VR190	AC43	AC12	R440	R443	—
10479867	VR148	AC43	AC12	R440	R443	—
10479868	VR190	AC62	AC101	R440	R443	—
10479869	VR148	AC43	AC12	R440	R443	—
10479870	VR190	AC62	AC101	R440	R443	—
10479874	VR191	AC84	—	R445	R444	—
10479883	VR191	AC84	—	R445	R444	—
10479884	VR191	AC62	—	R446	R447	—
10479891	VR191	AC103	—	R446	R447	—
10479893	VR191	AC84	—	R445	R444	—
10479895	VR191	AC84	—	R445	R444	—
10479896	VR191	AC84	—	R445	R444	—
10479897	VR191	AC84	—	R445	R444	—
10479898	VR191	AC84	—	R445	R444	—
10479901	VR191	AC84	—	R445	R444	—
10479902	VR191	AC84	—	R445	R444	AD144
10479903	VR191	AC84	—	R445	R444	AD144
10479904	VR191	AC62	—	R446	R447	—
10479905	VR191	AC84	—	R445	R444	AD144
10479906	VR191	AC84	—	R445	R444	AD144
10479907	VR191	AC62	—	R446	R447	—
10479909	VR191	AC84	—	R445	R444	AD144
10479910	VR191	AC84	—	R445	R444	AD144
10479911	VR191	AC84	—	R445	R444	AD144
10479912	VR191	AC84	—	R445	R444	AD144
10479913	VR191	AC84	—	R445	R444	AD144

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
10479915	VR190	AC62	AC101	R440	R443	—
10479916	VR190	AC43	AC12	R440	R443	—
10479920	VR191	AC84	—	R445	R444	AD144
10479921	VR191	AC84	—	R445	R444	AD144
10479922	VR191	AC84	—	R445	R444	AD144
10479924	VR148	—	AC12	—	—	—
10479925	VR148	—	AC12	—	—	—
10479926	—	—	AC12	—	—	—
10479927	VR148	—	AC12	—	—	—
10479929	VR148	—	AC12	—	—	—
10479930	VR148	—	AC12	—	—	—
10479938	VR191	AC84	—	R445	R444	AD144
10479954	VR191	AC84	—	R445	R444	—
10479959	—	AC62	—	R446	R447	—
10479962	VR191	AC84	—	R445	R444	AD144
10479963	VR191	AC84	—	R445	R444	AD144
10479969	VR191	AC84	—	R445	R444	AD144
10479974	VR191	AC84	—	—	—	—
10479976	—	AC84	—	R445	R444	AD144
10479989	VR191	—	AC84	R444	—	AD144
10479993	VR191	AC84	—	R445	R444	—
10479995	VR192	AC103	—	R446	R447	—
10479996	VR192	—	—	R447	—	—
10479998	VR191	AC84	—	R445	R444	—
10480005	VR148	AC26	AC12	R437	R432	—
10480008	VR192	AC103	—	R446	R447	—
10480009	VR192	AC103	—	R447	—	—
10480011	VR192	AC103	—	R446	R447	—
10480018	VR130	AC103	—	R446	R447	—
10480019	VR130	AC103	—	R446	R447	—
10480022	—	AC103	—	R446	R447	—
10480023	—	AC103	—	R446	R447	—
10480024	VR191	AC103	—	R446	R447	—
10480025	VR191	AC84	—	R445	R444	—
10480026	VR191	—	—	R446	R447	—
10480027	VR191	AC84	—	R445	R444	—
10480028	VR191	AC84	—	R445	R444	—
10480033	VR192	AC103	—	R446	R447	—
10480035	VR191	AC84	—	R445	R444	—
10480036	VR191	AC84	—	R445	R444	—
10480037	VR191	AC84	—	R445	R444	—
10480040	VR191	—	AC84	—	—	—
10480048	VR192	AC103	—	R446	R447	—
10480051	—	AC103	—	R446	R447	—
10480055	VR196	AC84	—	R445	R444	—
10480058	VR148	AC26	AC12	R451	R422	—
10480060	—	AC26	AC12	R451	R422	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
10480068	VR191	AC84	—	R445	R444	—
10480069	VR191	AC84	—	R445	R444	—
10480077	VR191	AC103	—	R446	R447	—
10480082	VR191	AC84	—	R445	R444	—
10480083	VR191	AC84	—	R445	R444	—
10480084	VR191	AC84	—	R445	R444	—
10480085	VR191	AC84	—	R445	R444	—
10480086	VR191	AC84	—	R445	R444	—
10480087	VR191	AC84	—	R445	R444	—
10480088	—	AC84	—	R445	R444	—
10480089	—	AC84	—	R445	R444	—
10480090	VR191	AC84	—	R445	R444	—
10480091	VR191	AC84	—	R445	R444	—
10480092	VR191	AC84	—	R445	R444	—
10480093	—	AC84	—	R445	R444	—
10480094	VR191	AC84	—	R445	R444	—
10480097	VR191	AC84	—	R445	R444	—
10480098	—	AC84	—	R445	R444	—
10480099	VR191	AC84	—	R445	R444	—
10480104	VR191	AC84	—	R445	R444	—
10480105	VR191	AC84	—	R445	R444	—
10480111	VR191	AC103	—	R446	R447	—
10480114	VR191	AC84	—	R445	R444	—
10480115	VR191	AC84	—	R445	R444	—
10480116	VR192	—	—	R447	—	—
10480120	VR130	AC103	—	R446	R447	—
10480121	VR191	AC62	—	R446	R447	—
10480122	VR191	AC103	—	R446	R447	—
10480127	VR191	AC84	—	R445	R444	—
10480130	VR191	AC103	—	R446	R447	—
10480131	VR191	AC62	—	R446	R447	—
10480133	VR191	AC103	—	R446	R447	—
10480134	VR191	AC84	—	R445	R444	—
10480135	VR131	AC103	—	R446	R447	—
10480136	VR191	AC84	—	R445	R444	—
10480137	VR191	AC84	—	R445	R444	—
10480138	VR191	AC103	—	R446	R447	—
10480139	VR191	AC103	—	R446	R447	—
10480156	—	AC103	—	R446	R447	—
10480157	VR191	AC84	—	R445	R444	—
10480171	VR131	AC103	—	R446	R447	—
10480177	VR130	AC103	—	R446	R447	—
10480181	VR191	AC84	—	R445	R444	—
10480186	VR130	AC103	—	R446	R447	—
10480192	—	AC103	—	R446	R447	—
10480200	VR191	AC103	—	R446	R447	—
10480201	VR191	AC103	—	R446	R447	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
10480202	VR191	AC103	—	R446	R447	—
10480203	VR191	AC103	—	R446	R447	—
10480204	VR130	AC103	—	R446	R447	—
10480205	VR196	AC103	—	R446	R447	—
10480206	VR191	AC103	—	R446	R447	—
10480211	VR191	AC103	—	R446	R447	—
10480227	VR196	AC103	—	R446	R447	—
10480255	VR191	AC103	—	R446	R447	—
10480267	—	AC103	—	R446	R447	—
10480269	—	AC103	—	R446	R447	—
10480278	VR196	AC103	—	R446	R447	—
10480279	VR130	AC103	—	R446	R447	—
10480282	VR130	AC103	—	R446	R447	—
10480310	VR196	AC103	—	R446	R447	—
10480311	VR196	AC103	—	R446	R447	—
12482707	VR191	AC84	—	—	—	AD144
15598491	VR191	AC62	—	R447	—	—
15679680	VR191	AC84	—	—	—	—
19010000	VR182	AC2P	AC2N	—	—	—
19010001	VR182	AC2P	AC2N	—	—	—
19010002	VR182	AC2P	AC2N	—	—	—
19010003	VR184	AC2P	AC2N	—	—	—
19010004	VR182	AC2P	AC2N	—	—	—
19010005	VR184	AC2P	AC2N	—	—	—
19010006	VR182	AC2P	AC2N	—	—	—
19010007	—	AC2P	AC2N	—	—	—
19010008	VR182	AC2P	AC2N	—	—	—
19010009	VR184	AC2P	AC2N	—	—	—
19010010	—	AC2P	AC2N	—	—	—
19010011	VR184	AC2P	AC2N	—	—	—
19010012	VR184	AC2P	AC2N	—	—	—
19010013	VR184	AC2P	AC2N	—	—	—
19010014	VR184	AC2P	AC2N	—	—	—
19010018	VR184	AC2P	AC2N	—	—	—
19010019	—	AC2P	AC2N	—	—	—
19010020	VR182	AC2P	AC2N	—	—	—
19010100	VR184	AC62	AC101	R451	R450	—
19010103	VR184	AC62	AC101	R451	R450	—
19010104	VR184	AC94	AC101	R451	R450	—
19010105	VR184	AC62	AC101	R451	R450	—
19010108	VR182	AC62	AC101	R451	R450	—
19010110	—	—	—	R450	—	—
19010111	VR182	AC62	AC101	R451	R450	—
19010112	—	—	AC101	R451	R450	—
19010113	—	AC100	AC101	R451	R450	—
19010114	VR184	AC94	AC101	R451	R450	—
19010115	VR184	AC100	AC101	R451	R450	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
19010118	—	AC62	AC101	R451	R450	—
19010120	VR184	AC94	AC101	R451	R450	—
19010124	VR184	AC100	AC101	R451	R450	—
19010125	VR184	AC100	AC101	R451	R450	—
19010126	VR184	AC100	AC101	R451	R450	—
19010127	VR184	AC100	AC101	R451	R450	—
19010129	VR184	AC62	AC101	R451	R450	—
19010134	VR184	AC100	AC101	R451	R450	—
19010136	VR184	AC62	AC101	R451	R450	—
19010137	VR184	AC94	AC101	R451	R450	—
19010138	VR184	AC100	AC101	R451	R450	—
19010141	—	AC94	AC101	R451	R450	—
19010145	—	AC100	AC101	R451	R450	—
19010147	—	AC100	AC101	R451	R450	—
19010153	—	AC100	AC101	R451	R450	—
19010154	—	AC62	AC101	R451	R450	—
19010155	—	AC62	AC101	R451	R450	—
19010156	—	AC100	AC101	R451	R450	—
19010157	—	AC62	AC101	R451	R450	—
19010158	VR184	AC62	AC101	R451	R450	—
19010159	VR184	AC62	AC101	R451	R450	—
19010160	VR184	AC62	AC101	R451	R450	—
19010161	VR184	AC94	AC101	R451	R450	—
19010162	VR184	AC94	AC101	R451	R450	—
19010163	VR184	AC94	AC101	R451	R450	—
19010165	VR184	AC100	AC101	R451	R450	—
19010166	VR184	AC94	AC101	R451	R450	—
19010168	—	AC100	AC101	R451	R450	—
19010171	VR184	AC100	AC101	R451	R450	—
19010173	VR184	AC100	AC101	R451	R450	—
19010174	VR184	AC100	AC101	R451	R450	—
19010176	VR184	AC100	AC101	R451	R450	—
19010178	VR184	—	AC101	R451	R450	—
19010180	VR184	—	AC101	R451	R450	—
19010181	VR184	AC62	AC101	R451	R450	—
19010182	VR182	AC62	AC101	R451	R450	—
19010183	—	AC100	AC101	R451	R450	—
19010184	—	AC100	AC101	R451	R450	—
19010185	VR182	AC62	AC101	R451	R450	—
19010190	VR184	AC62	AC101	R451	R450	—
19010191	VR184	AC100	AC101	R451	R450	—
19010192	VR184	AC100	AC101	R451	R450	—
30002523	VR614	—	—	—	—	—
30016320	VR614	—	—	—	—	—
30016321	VR614	—	—	—	—	—
94021045	VR537	AC21	—	E481	—	—
94024347	VR550	AC21	—	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
94024348	VR550	—	—	—	—	—
94137345	VR572	—	—	—	—	—
94201052	VR552	AC21	—	E480	—	—
94206081	VR550	AC21	—	—	—	—
94207358	VR550	—	—	—	—	—
94211350	—	—	—	E480	—	—
94221717	VR552	—	—	—	—	—
94238983	VR552	AC44	—	—	—	—
94238984	VR552	AC44	—	—	—	—
94238985	VR552	AC44	—	—	—	—
94246956	VR642	AC70	—	E396	—	—
94246957	VR642	—	—	E396	—	—
94445672	VR572	—	—	—	—	—
94449781	VR572	—	—	—	—	—
94840298	VR572	—	—	—	—	—
94844554	VR572	—	—	—	—	—
94845639	VR572	—	—	—	—	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Brush & Holder	Tolerance Ring
94849282	VR572	—	—	E601	—	—
94849284	VR572	—	—	E601	—	—
94854169	VR652	—	—	—	—	—
94854172	VR652	—	—	—	—	—
94854195	VR652	—	—	—	—	—
94855415	VR572	—	—	—	—	—
96055601	VR633	—	—	—	—	—
96056770	VR575	—	—	—	—	—
96056922	VR633	—	—	—	—	—
96060337	VR633	—	—	E601	—	—
96068024	VR633	—	—	—	—	—
96069102	VR614	—	—	—	—	—
97023652	VR575	—	—	E601	—	—
97027568	VR575	—	—	E601	—	—
97029986	VR575	—	—	—	—	—
97070343	VR575	—	—	E601	—	—

FORD-MOTORCRAFT

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
A006T41591	VR441	—	—	—
A0012300JB	VR432	—	—	—
A0012500JB	VR432	—	—	—
A0012600JB	VR432	—	—	—
A0016240AA	—	—	AC7	—
A0016242AA	—	—	AC7	—
A0016258AA	—	AC7	—	—
A0017024AA	VR428	—	—	L101
A0017026AA	—	—	AC7	—
A0017501AA	VR440	—	—	—
A0017601AA	VR428	—	—	—
A0017704JA	—	—	—	SD720
A001090302	—	—	AC7	—
A001090303	—	—	AC7	—
A001090304	—	—	AC7	—
A001090305	—	—	AC7	—
A001090325	VR428	—	—	L101
A001090599	VR440	—	—	—
A001090600	VR440	—	—	—
A001090601	VR440	—	—	—
A001090633	VR440	—	—	—
A200099128	VR440	—	—	—
A200099129	VR440	—	—	—
A200099130	VR440	—	—	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
B9FA10300B	—	—	—	L101
B9FA10300G	—	—	—	L101
B9MF10300C	—	—	—	L101
C1AF10300C	—	—	—	L101
C1AF10300D	—	—	—	L101
C1MF10300A	—	—	—	L101
C2AF10300A	—	—	—	L101
C3SF10300B	—	AC6P	AC6N	—
C4AF10300B	—	—	—	L101
C4MF10300A	—	—	—	L101
C4TE10300BG	—	—	AC7	F417
C4TE10300BJ	—	—	AC7	F417
C4TE10300BL	—	—	AC7	F417
C4TE10300BM	—	—	AC7	F417
C4TF10300AA	—	—	—	L101
C4TF10300AB	—	—	—	L101
C4TF10300AC	—	AC6P	AC6N	—
C4TF10300AZ	—	—	—	F415
C4TF10300BA	—	—	—	F415
C4TF10300BB	—	—	AC7	F417
C4TF10300BC	—	—	AC7	F417
C4TF10300BD	—	—	AC7	F417
C4TF10300BE	—	—	AC7	F417
C4TF10300BF	—	—	AC7	F417

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
C4TF10300BH . . .	—	—	AC7	F417	C5TF10300U . . .	—	—	—	L101
C4TF10300BK . . .	—	—	AC7	F417	C5TF10300V . . .	—	—	—	L101
C4TF10300BN . . .	—	—	AC7	F417	C5TF10300Y . . .	—	—	—	L101
C4TF10300D . . .	—	—	—	L101	C5TF10300Z . . .	—	—	—	F415
C4TF10300E . . .	—	—	—	L101	C5TF10346A . . .	—	—	—	F415
C4TF10300F . . .	—	—	—	L101	C5TF10346B . . .	—	—	—	F415
C4TF10300G . . .	—	—	—	L101	C5TF10346C . . .	—	—	—	L101
C4TF10300H . . .	—	—	—	L101	C5TF10346D . . .	VR428	—	—	L101
C4TF10300I . . .	—	—	—	L101	C5TF10346G . . .	—	—	—	F415
C4TF10300J . . .	—	—	—	L101	C5TF10346H . . .	—	—	AC7	F417
C4TF10300K . . .	—	—	—	L101	C5TZ10346D . . .	VR428	—	—	L101
C4TF10300T . . .	—	—	—	L101	C5TZ10346H . . .	—	—	—	F415
C5AF10300A . . .	—	—	—	F415	C6AF10300A . . .	—	—	—	F415
C5AF10300B . . .	—	—	—	F415	C6AF10300B . . .	—	—	—	F415
C5AF10300C . . .	—	—	—	F415	C6AF10300C . . .	—	—	—	F415
C5AF10300D . . .	—	—	—	F415	C6AF10300D . . .	—	—	—	F415
C5AF10300E . . .	—	—	—	F415	C6AF10300E . . .	—	—	—	F415
C5AF10300F . . .	—	—	—	F415	C6AF10300F . . .	—	—	—	F415
C5AF10300G . . .	—	—	—	F415	C6AF10300G . . .	—	—	—	F415
C5AF10346A . . .	—	—	—	F415	C6AF10346A . . .	—	—	—	F415
C5AZ10346B . . .	—	—	—	L101	C6AF10346B . . .	—	—	—	F415
C5DF10300A . . .	—	—	—	F415	C6DF10300A . . .	—	—	—	F415
C5DF10300B . . .	—	—	—	F415	C6DF10300B . . .	—	—	—	F415
C5DF10346A . . .	—	—	—	F415	C6DF10346A . . .	—	—	—	F415
C5DF10346B . . .	—	—	—	F415	C6GF10300A . . .	—	—	—	F415
C5DZ10346B . . .	—	—	—	F415	C6GF10300B . . .	—	—	—	F415
C5TF10300A . . .	—	—	—	F415	C6TF10300A . . .	—	—	—	F415
C5TF10300AA . . .	—	—	—	F415	C6TF10300AH . . .	—	—	AC7	F417
C5TF10300AB . . .	VR428	—	—	L101	C6TF10300AJ . . .	—	—	AC7	F417
C5TF10300AN . . .	—	—	—	F415	C6TF10300AK . . .	—	—	AC7	F417
C5TF10300AS . . .	—	—	—	F415	C6TF10300AL . . .	—	—	AC7	F417
C5TF10300AT . . .	—	—	—	F415	C6TF10300B . . .	—	—	—	F415
C5TF10300AU . . .	—	—	—	F415	C6TF10300C . . .	—	—	—	F415
C5TF10300AV . . .	—	—	—	F415	C6TF10300D . . .	—	—	—	F415
C5TF10300B . . .	—	—	—	F415	C6TF10300E . . .	—	—	—	F415
C5TF10300C . . .	—	—	—	F415	C6TF10300F . . .	—	—	—	F415
C5TF10300D . . .	—	—	—	F415	C6TF10300G . . .	—	—	—	F415
C5TF10300E . . .	—	—	—	F415	C6TF10300H . . .	—	—	—	F415
C5TF10300F . . .	—	—	—	F415	C6TF10300I . . .	—	—	—	F415
C5TF10300H . . .	—	—	—	F415	C6TF10300J . . .	—	—	—	F415
C5TF10300J . . .	—	—	—	F415	C6TF10300K . . .	—	—	—	F415
C5TF10300K . . .	—	—	—	L101	C6TF10300L . . .	—	—	—	F415
C5TF10300L . . .	—	—	—	L101	C6TF10300M . . .	—	—	—	F415
C5TF10300M . . .	—	—	—	L101	C6TF10346A . . .	—	—	—	F415
C5TF10300N . . .	—	—	—	L101	C6TF10346B . . .	—	—	—	F415
C5TF10300R . . .	—	—	—	L101	C6TF10346C . . .	—	—	—	F415
C5TF10300S . . .	—	—	—	L101	C7AF10300A . . .	—	—	—	F416
C5TF10300T . . .	—	—	—	L101	C7AF10346A . . .	—	—	—	F416

(continued on next column)

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
C7AF10346B . . .	—	—	—	F416
C7SF10300A . . .	—	—	—	F415
C7SF10300B . . .	—	—	AC7	F417
C7TF10300A . . .	—	—	—	F416
C7TF10300B . . .	—	—	—	F416
C7TF10300C . . .	—	—	—	F415
C7TF10300D . . .	—	—	—	F415
C7TF10300E . . .	—	—	—	F415
C7TF10346A . . .	—	—	—	F416
C7ZF10300A . . .	—	—	—	F415
C8LF10300B . . .	—	—	AC7	—
C8TF10300A . . .	—	—	—	F416
C9AF10300A . . .	—	—	—	F415
C9AF10300B . . .	—	—	AC7	F417
C9HF10300B . . .	VR428	—	—	L101
C9HF10346B . . .	—	—	—	F416
C9SF10300A . . .	—	—	AC7	F417
C9SF10300B . . .	—	—	AC7	—
C9ZF10300A . . .	—	—	—	F415
C9ZF10300B . . .	—	—	AC7	F417
C9ZF10300C . . .	—	—	AC7	F417
C20F10300D . . .	—	—	—	L101
C40F10300A . . .	—	—	—	L101
D0AF10300A . . .	—	—	—	F416
D0AF10300C . . .	—	—	AC7	F417
D0AF10300E . . .	—	—	AC7	F417
D0AF10300F . . .	—	—	AC7	F417
D0AF10300G . . .	—	—	AC7	F417
D0AF10300H . . .	—	—	AC7	F417
D0AF10346F . . .	—	—	AC7	F417
D0HF10300A . . .	—	—	—	F416
D0HF10300B . . .	—	—	—	F416
D0HF10300C . . .	—	—	—	F416
D0HF10300D . . .	—	—	AC7	F417
D0LF10300A . . .	—	—	AC7	—
D0SF10300A . . .	—	—	AC7	F417
D0SF10346A . . .	—	—	AC7	—
D0TF10300A . . .	—	—	—	F416
D0TF10300B . . .	—	—	—	F416
D0TF10300C . . .	—	—	AC7	F417
D0TF10300D . . .	—	—	AC7	F417
D0TF10300E . . .	—	—	AC7	F417
D0TF10300F . . .	—	—	AC7	F417
D0TF10300G . . .	—	—	AC7	F417
D0TF10300J . . .	—	—	AC7	F417
D0TF10300K . . .	—	—	AC7	F417
D0TF10346B . . .	—	—	AC7	F417
D0TF10346C . . .	—	—	AC7	F417

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
D0UF10300A . . .	—	—	AC7	F417
D0ZF10300A . . .	—	—	AC7	F417
D0ZF10300B . . .	—	—	AC7	F417
D0ZF10300C . . .	—	—	AC7	F417
D0ZF10346B . . .	—	—	AC7	F417
D1AF10300AA . . .	—	—	AC7	F417
D1AF10300BA . . .	—	—	—	F416
D1AF10300CA . . .	—	—	—	F416
D1AF10346BA . . .	VR428	—	—	F418
D1HF10300AA . . .	—	—	—	F417
D1HF10300BA . . .	—	—	—	F417
D1HF10300CA . . .	—	—	—	F417
D1HF10300DA . . .	VR428	—	—	—
D1HF10300EA . . .	VR428	—	—	—
D1HF10300FA . . .	VR428	—	—	—
D1HF10346BA . . .	VR428	—	—	F418
D1HF10346CA . . .	VR428	—	—	—
D1HZ10346C . . .	VR428	—	—	—
D1TF10300AA . . .	—	—	—	F416
D1TF10300BA . . .	—	—	—	F416
D1TF10346DA . . .	—	—	—	SD720
D1ZF10300AA . . .	—	—	AC7	F417
D2AF10300AA . . .	—	—	AC7	F417
D2AF10300AB . . .	—	—	AC7	F417
D2AF10300BA . . .	—	—	AC7	F417
D2AF10300BB . . .	—	—	AC7	F417
D2AF10300BC . . .	—	—	AC7	F417
D2AF10300CA . . .	—	—	AC7	F417
D2AF10300DA . . .	—	—	—	F416
D2AF10300EA . . .	VR428	—	—	—
D2AF10346BA . . .	VR428	AC7	—	F417
D2AF10346CA . . .	VR428	AC7	—	F417
D2AF10346DA . . .	VR428	AC7	—	F417
D2AZ10346C . . .	VR428	AC7	—	F417
D2AZ10346D . . .	VR428	AC7	—	F417
D2BF10300AA . . .	—	—	AC7	F417
D2DF10300AB . . .	—	—	AC7	F417
D2DF10300AC . . .	VR428	AC7	—	F417
D2HF10300AA . . .	—	—	AC7	F417
D2HF10300AB . . .	—	—	AC7	F417
D2HF10300AC . . .	VR428	AC7	—	F417
D2HF10300BA . . .	VR428	—	—	—
D2HF10300CA . . .	—	—	—	F416
D2HF10300DA . . .	VR428	—	—	—
D2HF10300EA . . .	VR428	—	—	—
D2HF10300FA . . .	VR428	—	—	—
D2HF10346BA . . .	VR428	—	—	F418
D2OF10300AA . . .	VR428	—	—	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
D2OF10300BA .	—	—	AC7	F417	D2ZF10300AC .	VR428	AC7	—	F417
D2OF10300BB .	VR428	AC7	—	F417	D2ZF10300BA .	—	—	AC7	F417
D2OF10300CA .	—	—	AC7	F417	D2ZF10300BB .	VR428	AC7	—	F417
D2OF10300CB .	VR428	AC7	—	F417	D2ZF10346BA .	VR428	AC7	—	F417
D2OF10300DA .	—	—	AC7	F417	D2ZZ10346B . . .	VR428	AC7	—	F417
D2OF10300DB .	VR428	AC7	—	F417	D3DF10300AA .	VR428	AC7	—	F417
D2OF10300EA .	—	—	AC7	F417	D3HF10300AA .	VR428	—	—	—
D2OF10300EB .	VR428	AC7	—	F417	D3HF10300BA .	VR428	—	—	—
D2OF10300FA .	—	—	AC7	F417	D3HF10300BB .	VR428	—	—	—
D2OF10300FB .	VR428	AC7	—	F417	D3HF10300CA .	VR440	—	—	—
D2OF10300GA .	VR428	—	—	—	D3HF10300DA .	VR428	AC7	—	F417
D2OF10346BA .	—	—	AF1000	F420	D3OF10300AA .	—	—	AF1000	F420
D2OF10346CA .	—	—	AC7	F417	D3OF10300BA .	—	—	AC7	F417
D2OF10346DA .	—	—	AC7	F417	D3OF10300CA .	—	—	AC7	F417
D2OF10346FA .	—	—	AC7	F417	D3OF10300DA .	—	—	AC7	F417
D2OF10346GA .	—	—	AC7	F417	D3OF10300EA .	—	—	AC7	F417
D2OF10346HA .	—	—	AC7	F417	D3OF10300FA .	—	—	AC7	F417
D2OF10346JA .	—	—	AC7	F417	D3TF10300AA .	VR428	—	—	—
D2OF10346KA .	—	—	AC7	F417	D3TF10300BA .	VR428	AC7	—	F417
D2RY10346C . .	VR503	—	—	—	D3TF10300CA .	VR428	AC7	—	F417
D2SF10300AA .	—	—	AC7	F417	D3TF10300DA .	VR428	AC7	—	F417
D2SF10300AB .	VR428	AC7	—	F417	D3UF10300AA .	VR428	AC7	—	F417
D2TB10346BA .	VR428	AC7	—	F417	D3VF10300AA .	VR428	—	—	—
D2TF10300AA .	—	—	AC7	F417	D3VF10300AB .	VR428	—	—	—
D2TF10300AB .	—	—	AC7	F417	D3VF10346BA .	VR428	—	—	—
D2TF10300AC .	VR428	AC7	—	F417	D3VY10346A . . .	VR428	—	—	—
D2TF10300BA .	—	—	AC7	F417	D3ZF10300AA .	VR428	AC7	—	F417
D2TF10300BB .	—	—	AC7	F417	D4DF10300AA .	VR428	AC7	—	F417
D2TF10300BC .	VR428	AC7	—	F417	D4HF10300BA .	VR428	—	—	—
D2TF10300BD .	VR428	AC7	—	F417	D4HF10346BA .	VR428	—	—	—
D2TF10300CB .	—	—	AC7	F417	D4HF10346CA .	VR162	—	—	—
D2TF10300CC .	VR428	AC7	—	F417	D4HS10346CA .	—	—	—	SD720
D2TF10300DA .	—	—	AC7	F417	D4HZ10346A . . .	VR162	—	—	—
D2TF10300DB .	—	—	AC7	F417	D4HZ10346B . . .	VR428	—	—	F418
D2TF10300DC .	VR428	AC7	—	F417	D4LF10300AA .	VR428	—	—	F417
D2TF10300EA .	—	—	AC7	F417	D4LF10300BA .	VR428	—	—	F417
D2TF10300EB .	—	—	AC7	F417	D4LF10300CA .	VR428	—	—	F417
D2TF10300EC .	VR428	AC7	—	F417	D4LF10300DA .	VR428	—	—	F417
D2TF10300FA .	VR428	—	—	—	D4OF10300AA .	VR428	AC7	—	F417
D2TF10300GA .	VR428	—	—	—	D4OF10300BA .	VR428	AC7	—	F417
D2TF10300HA .	VR440	—	—	—	D4OF10300CA .	VR428	AC7	—	F417
D2TF10346BA .	VR428	—	—	F417	D4OF10300DA .	VR428	AC7	—	F417
D2TF10346DA .	VR428	—	—	F418	D4OF10300EA .	VR428	—	—	—
D2UF10300AA .	—	—	AC7	F417	D4OF10300FA .	VR428	AC7	—	F417
D2UF10300AB .	—	—	AC7	F417	D4OF10346AA .	VR428	AC7	—	F417
D2UF10300AC .	VR428	AC7	—	F417	D4OF10346BA .	VR428	AC7	—	F417
D2ZF10300AA .	—	—	AC7	F417	D4OF10346CA .	VR428	AC7	—	F417
D2ZF10300AB .	VR428	AC7	—	F417	D4OF10346DA .	VR428	AC7	—	F417

(continued on next column)

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
D4OZ10346A . .	VR428	AC7	—	F417
D4OZ10346B . .	VR428	AC7	—	F417
D4OZ10346C . .	VR428	AC7	—	F417
D4OZ10346D . .	VR428	—	—	—
D4RY10346A . .	VR503	—	—	—
D4RY10346B . .	VR503	—	—	—
D4RY10346C . .	VR503	—	—	—
D4RY10346D . .	VR503	—	—	—
D4SF10300AA . .	—	—	—	F417
D4SF10346AA . .	—	—	—	F417
D4SZ10346A . . .	—	—	—	F417
D4TF10300AA . .	VR428	AC7	—	F417
D4TF10300BA . .	VR440	—	—	—
D4TF10300CA . .	VR440	—	—	—
D4TF10300DA . .	VR440	—	—	—
D4TF10346BA . .	VR440	—	—	—
D4TZ10346A . . .	VR440	—	—	—
D4TZ10346B . . .	VR428	—	—	F418
D4UF10300AA . .	VR428	AC7	—	F417
D4ZF10300AA . .	VR428	—	—	—
D4ZF10300BA . .	VR428	AC7	—	F417
D4ZF10300CA . .	VR428	—	—	—
D5AF10300AA . .	VR428	AC7	—	F417
D5AF10300BA . .	VR428	AC7	—	F417
D5AF10300CA . .	VR428	AC7	—	F417
D5AF10300DA . .	VR428	AC7	—	F417
D5AF10300EA . .	VR428	AC7	—	F417
D5AF10300FA . .	VR428	AC7	—	F417
D5AF10300GA . .	VR428	AC7	—	F417
D5AF10300HA . .	VR428	AC7	—	F417
D5AF10300JA . .	VR428	AC7	—	F417
D5AF10300KA . .	VR428	AC7	—	F417
D5AF10300LA . .	VR428	AC7	—	F417
D5AF10346AA . .	VR428	AC7	—	F417
D5AF10346BA . .	VR428	AC7	—	F417
D5AF10346CA . .	VR428	AC7	—	F417
D5AZ10346A . . .	VR428	AC7	—	F417
D5AZ10346B . . .	VR428	AC7	—	F417
D5AZ10346C . . .	VR428	AC7	—	F417
D5DF10300AA . .	VR428	—	—	—
D5OF10300AA . .	VR428	—	—	—
D5OF10300BA . .	VR428	—	—	—
D5OF10300CA . .	VR428	—	—	—
D5RY10346B . .	VR503	—	—	—
D5RY10346C . .	VR503	—	—	—
D5RY10346D . .	VR503	—	—	—
D5TF10300AA . .	VR428	AC7	—	F417
D5TF10300BA . .	VR428	AC7	—	F417

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
D5UF10300AA . .	VR428	—	—	—
D5ZF10300AA . .	VR428	—	—	—
D5ZF10300BA . .	VR428	—	—	—
D6UF10300AA . .	VR428	—	—	—
D7AF10300AA . .	VR428	AC7	—	F417
D7AF10300BA . .	VR428	AC7	—	F417
D7AF10300CA . .	VR428	AC7	—	F417
D7AF10300DA . .	VR428	AC7	—	F417
D7AF10300EA . .	VR428	AC7	—	F417
D7AF10300FA . .	VR428	AC7	—	F417
D7AF10300GA . .	VR428	AC7	—	F417
D7AF10300HA . .	VR428	AC7	—	F417
D7AF10300JA . .	VR428	AC7	—	F417
D7AF10300KA . .	VR428	AC7	—	F417
D7AF10300LA . .	VR428	AC7	—	F417
D7AF10346AA . .	VR428	AC7	—	F417
D7AF10346BA . .	VR428	AC7	—	F417
D7AF10346CA . .	VR428	AC7	—	F417
D7AZ10346A . . .	VR428	AC7	—	F417
D7AZ10346B . . .	VR428	AC7	—	F417
D7AZ10346C . . .	VR428	AC7	—	F417
D7DF10300AA . .	VR428	—	—	—
D7EF10300AA . .	VR428	—	—	—
D7EF10300BA . .	VR428	—	—	—
D7EF10300CA . .	VR428	—	—	—
D7EF10300DA . .	VR428	—	—	—
D7HT10300AA . .	VR162	—	—	—
D7HT10300BA . .	VR162	—	—	—
D7HT10300CA . .	VR432	—	—	—
D7HT10300DA . .	VR432	—	—	—
D7HT10300EA . .	VR432	—	—	—
D7HZ10346A . . .	—	AC2P	AC2N	—
D7OF10300AA . .	—	—	AC24	F420
D7OF10300BA . .	—	—	AC24	F420
D7OF10300CA . .	—	—	AF1000	F420
D7OF10300DA . .	—	—	AF1000	F420
D7OF10300EA . .	—	—	AC24	F420
D7OF10346AA . .	VR428	—	—	—
D7OF10346BA . .	VR428	—	—	—
D7OZ10346A . .	VR428	—	—	—
D7OZ10346B . .	VR428	—	—	—
D7RY10346A . .	VR503	—	—	—
D7RY10346B . .	VR503	—	—	—
D7RY10346C . .	VR503	—	—	—
D7TF10300AA . .	VR428	AC7	—	F417
D7TF10300BA . .	VR428	AC7	—	F417
D7TF10300CA . .	VR428	AC7	—	F417
D7UF10300AA . .	VR428	—	—	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
D7UF10300BA .	VR428	—	—	—	D9HT10300BA .	VR440	—	—	—
D7UF10300CA .	VR428	—	—	—	D9HT10300CA .	VR440	—	—	—
D7VF10346AA .	VR428	—	—	—	D9HT10300DA .	VR440	AC7	—	F417
D7VZ10346A . . .	VR428	—	—	—	D9HT10300EA .	VR440	AC7	—	F417
D7ZE10346AA .	VR428	AC7	—	F417	D9HT10300FA .	VR440	—	—	—
D7ZF10300AA .	VR428	AC7	—	F417	D9HZ10346A . . .	VR440	—	—	—
D7ZF10300BA .	VR428	—	—	—	D9HZ10346B . . .	VR440	—	—	—
D7ZF10300CA .	VR428	—	—	—	D9HZ10346C . . .	VR440	—	—	—
D7ZF10300DA .	VR428	—	—	—	D9OF10300AA .	VR440	—	—	—
D7ZF10300EA .	VR428	—	—	—	D9SF10300AA .	VR440	—	—	F417
D7ZF10346AA .	VR440	AC7	—	F417	D9TF10300AA .	VR440	—	—	—
D8BF10300AA .	VR440	AC7	—	F417	D9UE10300CA .	VR440	AC7	—	F417
D8BF10300BA .	VR440	AC7	—	F417	D9UF10300AA .	VR440	AC7	—	F417
D8BF10300CA .	VR440	AC7	—	F417	D9UF10300BA .	VR440	AC7	—	F417
D8BF10300DA .	VR440	—	—	—	D9UF10300CA .	VR440	AC7	—	F417
D8BF10346AA .	VR440	AC7	—	F417	D9UF10300DA .	VR440	AC7	—	F417
D8BF10346BA .	VR440	AC7	—	F417	D9UF10300EA .	VR440	—	—	—
D8BF10346CA .	VR440	—	—	—	D9UF10300FA .	VR440	—	—	—
D8HZ10346A . . .	VR432	—	—	—	D9UF10300GA .	VR440	—	—	—
D8HZ10346B . . .	VR432	—	—	—	D9VF10300AA .	VR440	—	—	F417
D8HZ10346C . . .	VR432	—	—	—	D9VF10346AA .	VR440	—	—	F417
D8HZ10346D . . .	VR162	AC9	—	—	D9VY10346A . . .	VR440	AC7	—	F417
D8HZ10346E . . .	VR162	—	—	—	D9VY10346AA .	—	—	—	F417
D8HZ10346F . . .	VR148	AC12	—	—	D9VY10346B . . .	VR440	—	—	F417
D8RZ10346A . . .	VR506	—	—	—	D9VY10346C . . .	VR440	—	—	—
D8VF10300AA .	—	AC7	—	F417	D9VY10346D . . .	VR440	—	—	—
D8VF10300BA .	VR440	—	—	—	D9ZF10300AA .	VR440	AC7	—	F417
D8VF10300CA .	VR440	—	—	—	D9ZF10300BA .	VR440	—	—	—
D8VF10346AA .	VR440	AC7	—	F417	D9ZZ10346A . . .	VR440	AC7	—	F417
D8VF10346BA .	VR440	—	—	—	D20F10346BA . .	VR428	—	—	—
D8VF10346CA .	VR440	—	—	—	D20F10346DA . .	VR428	AC7	—	F418
D8ZE10300CA .	VR440	AC7	—	F417	D20F10346GA .	VR428	AC7	—	F417
D8ZF10300AA .	VR440	AC7	—	F417	D20F10346HA . .	VR428	AC7	—	F417
D8ZF10300BA .	VR440	AC7	—	F417	D20F10346JA . .	VR428	AC7	—	F417
D8ZF10300CA .	VR440	AC7	—	F417	D20F10346KA . .	VR428	AC7	—	F417
D8ZF10300EA .	VR440	AC7	—	F417	D20Z10346B . . .	VR428	—	—	—
D8ZF10300FA . .	VR440	—	—	—	D22F10300AA . .	—	—	AF1000	F420
D8ZF10300HA .	VR440	AC7	—	F417	D22F10300AB . .	VR428	—	—	—
D8ZF10346AA .	VR440	AC7	—	F417	D22F10300BA . .	VR428	AC7	—	F417
D8ZZ10346A . . .	VR440	AC7	—	F417	D22F10346BB . .	VR428	—	—	—
D9AF10300AA .	VR440	—	—	—	D30F10300AA . .	VR428	—	—	—
D9AF10300BA .	VR440	AC7	—	F417	D30F10300BA . .	VR428	AC7	—	F417
D9AF10300CA .	VR440	—	—	—	D30F10300CA . .	VR428	AC7	—	F417
D9BF10300AA .	VR440	—	—	—	D30F10300DA . .	VR428	AC7	—	F417
D9BZ10346A . . .	VR440	AC7	—	F417	D30F10300EA . .	VR428	AC7	—	F417
D9BZ10346B . . .	VR440	AC7	—	F417	D30F10300FA . .	VR428	AC7	—	F417
D9BZ10346C . . .	VR440	—	—	—	D32F10300AA . .	VR428	—	—	—
D9DF10300AA .	VR440	—	—	—	D32F10300BA . .	VR428	AC7	—	F417

(continued on next column)

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
D42F10300AA . .	VR428	AC7	—	F417
D42F10300BA . .	VR428	AC7	—	F417
D42F10300CA . .	VR428	—	—	—
D42F10300DA . .	VR428	AC7	—	F417
D42F10300EA . .	VR428	AC7	—	F417
D42F10300FA . .	VR428	AC7	—	F417
D52F10300AA . .	VR428	AC7	—	F417
D52F10300BA . .	VR428	—	—	—
D70F10300AA . .	VR428	—	—	—
D70F10300BA . .	VR428	—	—	—
D70F10300CA . .	VR428	—	—	—
D70F10300DA . .	VR428	—	—	—
D70F10300EA . .	VR428	—	—	—
D94F10300AA . .	VR440	—	—	F417
E0HT10300AA . .	VR162	—	—	—
E0SF10300AA . .	—	AC7	—	F417
E0TF10300AA . .	—	AC7	—	F417
E1AF10300BA . .	VR440	—	—	—
E1AF10300CA . .	VR440	AC7	—	F417
E1AF10300DA . .	VR440	—	—	—
E1BF10300AA . .	VR440	AC7	—	F417
E1BF10300BA . .	VR440	—	—	—
E1BF10300CA . .	VR440	—	—	—
E1BF10300HA . .	—	AC7	—	F417
E1BF10346AA . .	VR440	AC7	—	F417
E1BF10346BA . .	VR440	AC7	—	F417
E1BF10346CA . .	VR440	—	—	—
E1BZ10346A . . .	VR440	—	—	F420
E1BZ10346B . . .	VR440	AC7	—	F417
E1EF10300EB . .	VR440	AC7	—	F417
E1EF10300FB . .	VR440	AC7	—	F417
E1EF10300GB . .	VR440	AC7	—	F417
E1EF10300HA . .	VR440	AC7	—	F417
E1EF10300JA . .	VR440	AC7	—	F417
E1EF10300KA . .	VR440	AC7	—	F417
E1EF10300LA . .	VR440	AC7	—	F417
E1EF10300MA . .	VR440	AC7	—	F417
E1EF10346BA . .	VR440	AC7	—	F417
E1EF10346CA . .	VR440	AC7	—	F417
E1FZ10346A . . .	VR440	AC7	—	F417
E1FZ10346B . . .	VR440	AC7	—	F417
E1GF10300AA . .	VR440	AC7	—	F417
E1GF10300BA . .	VR440	AC7	—	F417
E1GF10300CA . .	VR440	AC7	—	F417
E1GF10300DA . .	—	AC7	—	F417
E1GF10300EA . .	—	AC7	—	F417
E1GF10346BA . .	—	AC7	—	F417
E1GF10346CA . .	VR440	AC7	—	F417

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
E1GF10346DA . .	VR440	AC7	—	F417
E1GF10346EA . .	VR440	AC7	—	F417
E1HT10300AA . .	VR440	—	—	—
E1HT10300BA . .	VR440	—	—	—
E1TF10300AA . .	VR440	AC7	—	F417
E1TF10300BA . .	VR440	—	—	—
E1UF10300AA . .	VR440	—	—	—
E1VF10300AA . .	—	AC24	—	F420
E1VF10346AA . .	VR440	—	—	—
E1VZ10346A . . .	VR440	AC24	—	F420
E1ZF10300AA . .	VR440	AC7	—	F417
E1ZF10300BA . .	VR440	AC7	—	F417
E1ZF10300CA . .	VR440	AC7	—	F417
E1ZF10300DA . .	VR440	AC7	—	F417
E1ZF10300EA . .	VR440	—	—	—
E1ZF10300FA . .	VR440	AC7	—	F417
E1ZF10346AA . .	VR440	AC7	—	F417
E1ZZ10346A . . .	VR440	AC7	—	F417
E2DF10300AA . .	VR440	AC7	—	F417
E2DF10346AA . .	VR440	AC7	—	F417
E2DZ10346A . . .	VR440	AC7	—	F417
E2GZ10346A . . .	VR440	AC7	—	F417
E2GZ10346B . . .	VR440	AC7	—	F417
E2GZ10346C . . .	VR440	AC7	—	F417
E2HF10346AA . .	VR440	—	—	—
E2HF10346BA . .	VR440	—	—	—
E2HF10346CA . .	VR440	—	—	—
E2HF10346DA . .	VR440	—	—	—
E2HT10300CA . .	VR440	—	—	—
E2HT10300DB . .	VR440	—	—	—
E2HT10300EB . .	VR440	—	—	—
E2HT10300FA . .	VR440	—	—	—
E2HT10300GA . .	VR440	—	—	—
E2HZ10346A . . .	VR440	—	—	—
E2HZ10346B . . .	VR440	—	—	—
E2HZ10346C . . .	VR440	—	—	—
E2HZ10346D . . .	VR440	—	—	—
E2HZ10346E . . .	VR440	—	—	—
E3EF10300AA . .	—	AC7	—	F417
E3EF10300AB . .	—	AF1000	—	F420
E3EF10300BA . .	—	AC7	—	F417
E3EF10346BA . .	—	AC7	—	F417
E3UF10300AB . .	—	AC24	—	F420
E3ZF10300AA . .	—	AF1000	—	F420
E3ZF10300BA . .	—	AC7	—	F417
E3ZF10300EA . .	—	AC7	—	F417
E4EF10300AA . .	—	AC7	—	F417
E4EF10300CA . .	—	AC7	—	F417

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
E4EF10300DA . . .	—	AC7	—	F417
E4HT10300AA . . .	—	—	—	F510
E4LF10300CA . . .	—	AF1000	—	F420
E4TF10300AA . . .	—	AC7	—	F417
E4TF10300BA . . .	—	AC7	—	F417
E4TF10300CA . . .	—	AC7	—	F417
E4UF10300AA . . .	—	AC7	—	F417
E5LF10300AA . . .	—	AF1000	—	F420
E5RY10346A . . .	VR440	AC24	—	F420
E5VF10300AA . . .	—	AC24	—	—
E5ZF10300AA . . .	—	AF1000	—	F420
E6AF10300AF . . .	VR441	AC60	—	—
E6AF10300BA . . .	VR441	AC60	—	—
E6DF10300BA . . .	VR441	AC60	—	—
E6DF10300CA . . .	—	AF1000	—	—
E6DF10300DA . . .	VR441	AC83	—	—
E6DF10300EA . . .	VR441	AC60	—	—
E6DF10300FB . . .	—	AF1000	—	—
E6DF10300GA . . .	VR441	AC83	—	—
E6DF10300HA . . .	—	AF1000	—	—
E6DF10346BA . . .	VR441	AC83	—	—
E6DF10346CA . . .	VR441	AC60	—	—
E6DZ10346C . . .	VR441	—	—	—
E6EF10300EA . . .	VR441	AC60	—	—
E6EF10300GA . . .	VR441	AC60	—	—
E6EF10300HA . . .	VR441	AC60	—	—
E6EF10300JA . . .	VR441	AC60	—	—
E6EF10346AA . . .	VR441	AC60	—	—
E6EF10346CA . . .	VR441	—	—	—
E6EF10346FA . . .	VR441	AC60	—	—
E6SF10300BA . . .	VR441	AC60	—	—
E6SF10300CA . . .	—	AC7	—	F417
E6SF10300DA . . .	—	AC7	AC7	F417
E6SF10300EA . . .	—	AC7	AC7	F417
E6TF10300BA . . .	VR441	AC60	—	—
E6TF10300CA . . .	VR441	AC60	—	—
E6TF10300DA . . .	VR441	AC60	—	—
E6TF10346AA . . .	VR441	AC60	—	—
E6TZ10346A . . .	VR441	—	—	—
E6UF10300AA . . .	VR441	AC60	—	—
E6ZF10300CA . . .	VR441	AC60	—	—
E6ZF10346BA . . .	VR441	AC60	—	—
E7AF10300BA . . .	VR441	AC60	—	—
E7AF10300CA . . .	VR441	AC60	AC60	—
E7AF10300DA . . .	VR441	AC60	AC60	—
E7DF10300BA . . .	—	—	AF1000	F420
E7DF10300GA . . .	VR441	AC83	AC83	—
E7EF10300CB . . .	VR441	AC60	AC60	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
E7EF10300DB . . .	VR441	AC60	AC60	—
E7EF10300EB . . .	VR441	AC60	AC60	—
E7EF10300FB . . .	VR441	AC60	AC60	—
E7EF10300GA . . .	VR441	AC83	AC83	—
E7PF10346BA . . .	VR441	—	—	—
E7PF10346CA . . .	VR441	—	—	—
E7PF10346DA . . .	VR441	—	—	—
E7PF10346FA . . .	VR441	AC60	—	—
E7PF10346GA . . .	VR441	AC60	—	—
E7PF10346KA . . .	VR441	AC60	—	—
E7PF10346LA . . .	VR441	AC83	—	—
E7PF10346MA . . .	VR441	AC83	—	—
E7PF10346NA . . .	VR441	AC83	—	—
E7PF10346PA . . .	—	AF1000	—	F420
E7PF10346RA . . .	—	AC24	—	F420
E7PF10346UA . . .	VR441	AC60	—	—
E7PF10346XA . . .	VR441	AC60	—	—
E7PF10346ZA . . .	VR441	AC83	—	F511
E7SF10300FA . . .	VR441	AC83	—	F511
E7SF10300GA . . .	VR441	AC60	—	—
E7SF10300HA . . .	VR441	AC83	—	—
E7SF10300KA . . .	VR441	AC60	—	—
E7SF10300LA . . .	VR441	AC60	—	—
E7SF10300MA . . .	VR441	AC83	—	F511
E7TF10300GA . . .	—	AC24	—	F420
E7TF10300JA . . .	—	AC24	—	F420
E7TF10300MA . . .	VR441	—	—	—
E7TF10300NA . . .	—	AC24	—	F420
E7TF10300SA . . .	VR441	AC60	—	—
E7UF10300AA . . .	—	AF1000	—	F420
E7ZF10300BA . . .	VR441	AC83	—	—
E7ZF10300DA . . .	VR441	AC60	—	—
E7ZF10300FA . . .	VR441	AC83	—	F511
E8BF10300BA . . .	—	AC6P	AD310	F417
E8DF10300AB . . .	VR126	—	—	—
E8EF10300AB . . .	—	AC83	—	—
E8HT10300HA . . .	VR441	AC60	—	—
E8PF10346AA . . .	VR441	AC60	—	F511
E8PF10346BA . . .	—	AC24	—	F420
E8PF10346CB . . .	VR441	AC83	—	—
E8PF10346DA . . .	VR441	AC83	—	—
E8SF10300AA . . .	VR441	—	—	—
E8SF10300BA . . .	VR441	AC60	—	F511
E8TF10300BA . . .	VR441	AC83	—	—
E8TF10300CA . . .	VR441	AC83	—	—
E8US10300AA . . .	VR445	—	—	—
E9DF10300BB . . .	VR446	—	—	—
E9DF10300DA . . .	VR440	—	—	F420

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
E9DF10300EA	VR440	—	—	F420
E9EF10300AA	VR441	AC83	—	F511
E9EF10300BA	VR441	AC60	—	F511
E9PF10346AB	—	AC83	—	—
E9PF10346BA	VR441	AC60	—	—
E9PF10346CB	—	AC83	—	—
E9PF10346DA	—	—	—	F420
E9SF10300BA	VR441	AC60	—	F511
E9SF10300DA	VR447	—	—	—
E9UF10300AA	—	AC24	—	F420
E9UF10300BA	VR441	AC83	—	—
E9UF10300DA	VR441	AC60	—	—
E9US10300AA	VR445	—	—	—
E25F10300BA	VR440	AC7	—	F417
E27F10300AA	—	AC7	—	F417
E27F10300BA	—	AC7	—	F417
E37F10300AA	—	AF1000	—	F420
E37F10300BA	—	AC7	—	F417
E37F10300CA	—	AC7	—	F417
E37F10300DA	—	AC7	—	F417
E43F10300AA	—	AC7	—	F417
E43F10300BA	—	AC7	—	F417
E43F10300CA	—	AC7	—	F417
E43F10300DA	—	AC7	—	F417
E43F10300EA	VR441	AC60	—	—
E43F10300FA	—	AC7	—	F417
E43F10300GA	VR441	AC7	—	F417
E43F10300LA	VR441	AC7	—	F417
E43F10300MA	VR441	AC7	—	F417
E43F10300PA	VR441	AC60	—	—
E43F10300RA	VR441	AC60	—	—
E43F10346AA	—	AC7	—	F417
E43F10346BA	VR441	AC60	—	—
E43Z10346A	VR440	AC7	—	F417
E47F10300AA	—	AC7	—	F417
E47F10300BA	—	AC7	—	F417
E47F10300CA	—	AC7	—	F417
E53F10300AA	VR441	AC60	—	—
E53F10300BA	VR441	AC60	—	—
E53F10300DA	VR441	AC60	—	—
E53F10300EA	VR441	AC60	—	—
E53F10300FA	VR441	AC60	—	—
E53F10300GA	VR441	AC60	—	—
E53F10300HA	VR441	AC60	—	—
E53F10346AA	—	AC7	—	—
E53F10346BA	VR441	AC60	—	—
E53F10346DA	VR441	AC60	—	—
E57F10300AA	VR441	AC60	—	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
E57F10300BA	VR441	AC60	—	—
E57F10346BA	VR441	AC60	—	—
E59F10300DA	VR441	AC60	—	—
E63F10300AA	VR441	AC60	—	—
E63F10300AB	VR441	AC60	—	—
E63F10300BB	VR441	AC60	—	—
E63F10300CB	VR441	AC60	—	—
E63F10346BA	VR441	AC60	—	—
E63Z10346A	VR441	—	—	—
E63Z10346B	VR441	—	—	—
E67F10300CA	VR441	AC60	—	—
E67F10300DA	VR441	AC60	—	—
E67F10300EA	VR441	AC60	—	—
E67F10300FA	VR441	AC60	—	—
E67F10346AA	VR441	AC60	—	—
E69F10300AA	VR441	AC60	—	—
E69F10300BA	VR441	AC60	—	—
E69F10346AA	VR441	AC60	—	—
E69F10346BA	VR441	AC60	—	—
E73F10300BA	VR441	AC83	—	F511
E73F10300CA	VR441	AC60	—	F511
E79F10300BA	VR441	AC83	—	—
E83F10300BA	VR460	AC61	—	—
E87F10300AA	VR441	AC83	—	—
E87F10300BA	VR441	AC83	—	—
E87F10300CA	VR441	AC60	—	—
E97F10300AB	VR441	AC83	—	—
E97F10300BA	VR441	AC60	—	—
E99F10300AB	VR441	AC83	—	—
E99F10300BA	VR441	AC83	—	—
EDD8BF10300BA	VR440	—	—	F417
EDE6DF10300EA	VR441	AC83	—	—
EDE7AF10300BA	VR441	AC60	—	—
EDE7DF10300BA	—	AF1000	—	F420
EDE7DF10300GA	VR441	AC83	—	—
EOHT10300AA	VR162	—	—	—
EOSF10300AA	VR440	AC7	—	F417
EOTF10300AA	VR440	AC7	—	F417
F0AU10300AA	—	—	—	F420
F0CF10300AA	VR443	—	—	F424
F0CF10300AB	VR443	—	—	—
F0CF10300AC	VR443	—	—	—
F0CU10300AA	VR443	—	—	F424
F0CU10300AB	VR443	—	—	F424
F0CU10300AC	VR443	—	—	F424
F0DF10300BA	VR443	—	—	F424
F0DU10300AA	VR443	—	—	—
F0DU10300AC	VR443	—	—	F424

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
F0DU10300BA .	VR443	—	—	—	F1PU10346CA .	—	—	—	F424
F0DU10300BB .	VR443	—	—	—	F1SU10300AC .	—	—	—	F424
F0DU10300BC .	VR443	—	—	F424	F1SU10300AD .	VR443	—	—	F424
F0HT10300GA .	—	—	—	F510	F1VU10300BB .	VR443	—	—	F424
F0HT10300HA .	—	—	—	F510	F1VU10300BC .	VR443	—	—	F424
F0HT10300JA .	—	—	—	F510	F2F818300D .	VR456	—	—	—
F0HT10300KA .	—	—	—	F510	F2PU10346DE .	—	—	—	F424
F0HT10300LA .	—	—	—	F510	F2PU10346ED .	VR443	—	—	F424
F0HT10300MA .	—	—	—	F510	F2PU10346FC .	—	—	—	F424
F0HT10300RA .	—	—	—	F510	F2PU10346GA .	—	—	—	F424
F0HU10346AA .	—	—	—	F510	F2UU10300BE .	—	—	—	F424
F0HU10346BA .	—	—	—	F510	F2UU10300CD .	—	—	—	F424
F0HU10346CA .	—	—	—	F510	F2UU10300DC .	—	—	—	F424
F0HU10346DA .	—	—	—	F510	F2UU10300EA .	—	—	—	F424
F0HU10346EA .	—	—	—	F510	F2UU10300FA .	—	—	—	F424
F0HU10346FA .	—	—	—	F510	F3AU10300AC .	VR443	—	—	F424
F0LU10300AA .	—	—	—	F420	F3AU10300BA .	VR443	—	—	F424
F0PF10346AA .	—	AC83	—	—	F3AU10300CA .	VR441	—	—	F424
F0PF10346BA .	—	AC83	—	—	F3CU10300AD .	VR443	—	—	—
F0PU10300AD .	VR443	—	—	F424	F3CU10300DA .	VR443	—	—	F424
F0PU10300DD .	VR443	—	—	—	F3DU10300BB .	VR443	—	—	F424
F0PU10300MC .	VR443	—	—	—	F3DU10300CB .	VR441	—	—	—
F0PU10346AD .	VR443	—	—	F424	F3DU10300DA .	VR443	—	—	—
F0PU10346BD .	—	—	—	F424	F3PU10346AC .	VR443	—	—	F424
F0PU10346DD .	VR443	—	—	F424	F3SU10300AA .	VR447	—	—	—
F0PU10346JA .	—	—	—	F420	F3VU10300AA .	VR443	—	—	F424
F0PU10346KA .	—	—	—	F420	F4DU10300AA .	VR443	—	—	F424
F0PU10346MC .	VR443	—	—	F424	F4DU10300DA .	VR441	—	—	F424
F0PU10346NC .	VR443	—	—	F424	F4PD10300CA .	VR441	—	—	F424
F0TU10300AA .	VR441	—	—	F420	F4PU10346BA .	VR443	—	—	F424
F0TU10300BA .	VR441	—	—	F420	F4PU10346CA .	VR443	—	—	F424
F0TU10300CA .	VR441	AC60	—	—	F4PU10346DA .	VR441	—	—	F424
F0TU10300DA .	VR441	AC83	—	—	F4PZ10300AB .	VR443	—	—	F424
F0TU10300EA .	VR441	AC83	—	—	F4SU10346AB .	VR443	—	—	F424
F0TU10300FA .	VR441	AC83	—	—	F4ZU10300DZ .	VR443	—	—	F424
F0TU10300GA .	VR441	AC83	—	—	F02U10300AA .	VR446	—	—	—
F0TU10300HA .	—	AC83	—	—	F02U10300AC .	VR446	—	—	—
F0UU10300AA .	—	—	—	F420	F02U18300AA .	VR446	—	—	—
F0UU10300BA .	—	—	—	F420	F02U18300AC .	VR446	—	—	—
F0VF10300AA .	—	—	—	F424	F07U10300AA .	—	—	—	F424
F0VU10300AC .	—	—	—	F424	F07U10300AB .	—	—	—	F424
F1DU10300AD .	—	—	—	F424	F07U10300AC .	—	—	—	F424
F1DU10300AE .	VR443	—	—	F424	F07U10346AC .	—	—	—	F424
F1HT10300AA .	VR443	—	—	F424	F09F10300AA .	—	AC83	—	—
F1HT10300AB .	VR443	—	—	F424	F09F10300BA .	—	AC83	—	—
F1HT10300AC .	VR443	—	—	F424	F13U10300AC .	VR443	—	—	F424
F1PU10346AC .	VR443	—	—	F424	F13U10300AD .	VR443	—	—	F424
F1PU10346BE .	VR443	—	—	F424	F23U10300CA .	VR443	—	—	F424

(continued on next column)

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
F23U10300DA ..	VR443	—	—	F424
F23U10300EA ..	VR443	—	—	F424
F23U10346ED ..	VR443	—	—	—
F29U10300AB ..	—	—	—	F424
F33U10300BA ..	VR446	—	—	—
F20218300	VR511	—	—	—
F28510300B ..	VR446	—	—	—
F28518300C ..	VR456	—	—	—
F28810300A ..	VR446	—	—	—
F28810300B ..	VR446	—	—	—
F28818300B ..	VR456	—	—	—
F29018300B ..	VR456	—	—	—
FS1118300A ..	VR441	—	—	—
KL1118300D ..	VR441	—	—	—
MB3C718300B ..	VR441	—	—	—
71BB10300FA ..	—	—	—	E455
71BB10300FB ..	—	—	—	E455
75EB10300HA ..	—	—	—	E455
75EB10300HB ..	—	—	—	E455

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
75EB10300JA ..	—	—	—	E455
75EB10300JB ..	—	—	—	E455
76BB10300EA ..	—	—	—	E455
76BB10300GA ..	—	—	—	F420
76BB10300JA ..	—	—	—	E455
76EB10300AA ..	—	—	—	E455
77EB10300CB ..	—	—	—	E455
87HU10300AA ..	—	—	—	F510
87HU10300BA ..	—	—	—	F510
87HU10300DA ..	—	—	AC7	F417
7024AA	VR428	—	—	L101
7601AA	VR428	—	—	—
90325	VR428	—	—	L101
310277	VR440	—	—	—
310279	VR440	—	—	—
310309	VR440	—	—	—
400758759	VR503	—	—	—

HITACHI

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
LR17022	VR603	—	—	—
LR150197B	VR603	—	—	E593
LR160151	VR603	—	—	—
LR170404	VR642	—	—	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
LR190706	—	—	—	E615
LR190711	—	—	—	E615
S1345B	—	—	—	E523

HONDA

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
31100PH1004 ..	VR572	—	—	E601
31100PJ0661 ..	VR605	—	—	E601
31100PK1014 ..	VR572	—	—	E601
31100PK2014 ..	VR605	—	—	E601
31100PK2A01 ..	VR605	—	—	E601
31100PM4051 ..	—	—	—	E601
31100PM5A01 ..	—	—	—	E601
31100PM5A02 ..	—	—	—	E601
31100PM5A04 ..	VR627	—	—	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
31100PM5A07 ..	VR627	—	—	—
31100PM8A01 ..	—	—	—	E601
31100PM8A03 ..	—	—	—	E601
31100PRRA01R ..	VR219	—	—	E601
3140060A20	VR630	—	—	—
3140083010	VR633	—	—	E601
3140086010	VR633	—	—	E601

ISUZU

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
8944367300 ...	VR653	—	—	—
8944367310 ...	VR653	—	—	—
8944492650 ...	VR653	—	—	—
8944492660 ...	VR653	—	—	—
8970236520 ...	—	—	—	E601
8970275682 ...	—	—	—	E601

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
8970348990 ...	—	—	—	E601
8970428521 ...	VR633	—	—	E601
8970703430 ...	—	—	—	E601
8970845780 ...	VR653	—	—	—
8970845790 ...	VR653	—	—	—

LUCAS

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
23521	—	—	—	E405
23716	—	—	—	E405
23737	—	—	—	E405
23748	—	—	—	E405

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
23804	—	—	—	E405
23807	—	—	—	E405

MAZDA

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
AM1518300 ...	VR622	—	AC73	—
B61P18300D ...	VR456	—	—	—
B64J18300A ...	VR456	—	—	—
B10118300 ...	VR596	—	—	E480
B10118300A ...	VR596	—	—	E480
B10118300B ...	VR596	—	—	E480
B11310300B ...	VR457	—	—	—
B35918300 ...	VR511	—	—	E480
B36618300G ...	VR456	—	—	—
B36618300H ...	VR441	—	—	F424
B60318300A ...	—	—	—	E480
B65518300A ...	—	—	AC82	E480
B67518300A ...	VR511	—	—	—
B67518300B ...	VR511	—	—	—
B67518300C ...	VR511	—	—	—
BJ0118300 ...	VR596	—	—	E480
BP0218300 ...	VR457	—	—	—
BP0218300A ...	VR441	—	—	—
F8B118300A ...	VR579	—	—	—
F8B118300B ...	VR511	—	—	—
F8B118300C ...	VR511	—	—	—
F21018300D ...	—	—	—	E480
F22518300 ...	VR511	—	—	—
F26218300 ...	VR511	—	—	—
F28518300C ...	VR456	—	—	—
F65118300B ...	VR596	—	—	E480
F65118300C ...	VR596	—	—	E480

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
F87318300B ...	VR579	—	—	E480
F88118300A ...	VR596	—	—	E480
FE6518300 ...	VR579	—	—	E480
FE6518300C ...	VR579	—	—	E480
FE6818300C ...	VR579	—	—	E480
FE8518300A ...	VR596	—	—	E480
FE8718300A ...	VR596	—	—	E480
G60818300 ...	VR626	—	—	—
HE4518300A ...	VR595	—	AC38	E486
JE0718300 ...	VR579	—	—	—
JE1518300 ...	VR626	—	—	—
JE1518300A ...	VR626	—	—	—
JE2718300A ...	VR626	—	—	—
JE2818300 ...	VR626	—	—	—
JE3418300A ...	VR626	—	—	—
JF0718300A ...	VR626	—	—	—
N24518300B ...	VR579	—	—	E480
N31818300 ...	VR579	—	AC82	E480
N32018300 ...	VR579	—	AC82	—
N32618300 ...	VR579	—	AC82	—
N34918300A ...	VR626	—	—	—
N35018300A ...	VR456	—	—	—
N37018300A ...	VR626	—	—	—
N37018300B ...	VR626	—	—	—
N39018300A ...	VR456	—	—	—
S51518300 ...	—	—	—	E486
S51618300 ...	—	—	—	E486

(continued on next page)

MAZDA (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
SE2118300A ...	—	—	—	E486
SE4518300 ...	—	—	—	E486
SE4718300 ...	—	—	—	E486
SL0118300 ...	—	—	—	E486
SL0718300 ...	—	—	—	E486
SL2118300A ...	—	—	—	E486
SL2218300 ...	—	—	—	E486
SL2418300 ...	—	—	—	E486
SL2518300A ...	—	—	—	E486
SL4418300A ...	—	—	—	E486
SL5018300C ...	—	—	—	E486

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
SL5418300B ...	—	—	—	E397
SL5618300A ...	—	—	—	E486
029018300A ...	VR1064	—	—	—
045318300 ...	VR1064	—	—	—
060518300A ...	VR1064	—	—	—
083918300 ...	VR1064	—	—	—
086618300 ...	VR1064	—	—	—
101118300 ...	VR1064	—	—	—
175718300 ...	VR1064	—	—	—
286918300 ...	VR1064	—	—	—

MITSUBISHI

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
A2T48298 ...	—	AC96	—	—
A001T03672 ...	—	—	—	E394
A001T03872 ...	—	—	—	E394
A001T03972 ...	—	—	—	E394
A001T04072 ...	—	—	—	E394
A001T04172 ...	—	—	—	E394
A001T04572 ...	—	—	—	E394
A001T21171 ...	VR521	—	—	—
A001T22581 ...	VR521	—	—	—
A001T24371 ...	VR521	—	—	—
A001T24471 ...	VR521	—	—	—
A001T33576 ...	—	—	—	E486
A001T33676 ...	—	—	—	E486
A001T34572 ...	—	—	—	E394
A001T71076 ...	—	—	—	E486
A001T71176 ...	—	—	—	E486
A001T71276 ...	—	—	—	E486
A001T71576 ...	—	—	—	E486
A002T00991 ...	VR579	—	AC72	E480
A002T02271 ...	VR578	—	AC72	E394
A002T02394 ...	VR597	—	—	E480
A002T02471 ...	VR578	—	AC72	E394
A002T02572 ...	VR578	—	AC72	E394
A002T02577 ...	VR578	—	AC72	E394
A002T02671 ...	VR578	—	AC72	E394
A002T02771 ...	VR578	—	AC72	E394
A002T02871 ...	VR578	—	AC72	E394
A002T02977 ...	VR578	—	AC72	E394
A002T03171 ...	VR578	—	AC72	E394
A002T03477 ...	VR578	—	AC72	E394
A002T03571 ...	VR579	—	AC72	E480

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
A002T03691 ...	VR579	—	—	E480
A002T04277 ...	VR578	—	AC72	E394
A002T04677 ...	—	—	—	E480
A002T05772 ...	VR511	—	—	—
A002T05892 ...	VR511	—	—	—
A002T07071 ...	VR578	—	AC72	E394
A002T07172 ...	VR578	—	AC72	E480
A002T07292 ...	—	—	AC72	—
A002T07777 ...	—	—	—	E486
A002T09291 ...	VR512	—	—	E480
A002T09392 ...	VR512	—	—	E394
A002T09493 ...	VR512	—	—	E394
A002T09691 ...	VR578	AC72	—	E394
A002T09792 ...	VR578	AC72	—	E394
A002T13977 ...	VR626	—	—	—
A002T14694 ...	VR635	—	—	—
A002T18177 ...	VR626	—	—	—
A002T18277 ...	VR626	—	—	—
A002T18792 ...	VR635	—	—	—
A002T18874 ...	VR626	—	—	—
A002T19991 ...	VR456	—	—	—
A002T22991 ...	VR512	—	—	E394
A002T27176 ...	—	—	—	E486
A002T27376 ...	—	—	—	E486
A002T28291 ...	VR578	AC72	—	E394
A002T34477 ...	VR456	—	—	—
A002T34794 ...	—	AC67	—	—
A002T40891 ...	VR579	AC72	—	E480
A002T41674 ...	VR579	—	—	E480
A002T41677 ...	VR579	—	—	E480
A002T43891 ...	VR579	AC72	—	E480

(continued on next page)

MITSUBISHI (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
A002T45494 ...	—	—	—	E480
A002T45494B ...	—	—	—	E480
A002T46395 ...	—	—	—	E480
A002T46395B ...	—	—	—	E480
A002T47694 ...	—	—	—	E480
A002T47694B ...	—	—	—	E480
A002T47794 ...	—	—	—	E480
A002T47794B ...	—	—	—	E480
A002T47974 ...	VR579	AC82	—	E480
A002T48195A ...	VR578	—	—	E480
A002T48195B ...	—	—	—	E480
A002T48292 ...	—	—	—	E480
A002T48298 ...	—	—	—	E480
A002T48691 ...	VR578	AC72	—	E480
A002T48791 ...	VR578	AC72	—	E394
A002T49094 ...	VR597	—	—	E480
A002T49094B ...	VR597	—	—	E480
A002T49891 ...	VR579	AC72	—	E480
A002T49977 ...	VR578	AC72	—	E480
A002T49992 ...	VR578	AC72	—	E480
A002T72306 ...	—	—	—	E397
A002T72576 ...	—	—	—	E486
A002T72676 ...	—	—	—	E486
A002T73176 ...	—	—	—	E486
A003T00692 ...	VR578	—	—	E394
A003T00792 ...	VR578	—	—	E394
A003T02192 ...	VR578	AC76	—	E394
A003T02193 ...	VR578	AC76	—	E394
A003T02198 ...	VR578	AC76	—	E394
A003T03391 ...	VR578	AC76	—	E394
A003T03392 ...	VR578	AC76	—	E394
A003T03393 ...	VR578	AC76	—	E394
A003T03492 ...	VR578	AC76	—	E394
A003T03493 ...	VR578	AC76	—	E394
A003T05192 ...	VR635	—	—	—
A003T05274 ...	VR626	—	—	—
A003T06591 ...	VR578	AC76	—	E394
A003T06691 ...	VR578	—	—	E394
A003T06791 ...	VR456	—	—	—
A003T08293 ...	VR578	AC76	—	E394
A003T41876 ...	VR578	AC76	—	E394
A003T41892 ...	VR578	AC76	—	E394
A003T45594 ...	—	—	—	E480
A003T45691 ...	VR578	—	—	E394
A003T45693 ...	VR578	—	—	E394
A003T45694 ...	VR578	AC76	—	E394
A004T01493 ...	VR628	—	—	—
A004T01793 ...	VR628	—	—	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
A004T01893 ...	VR628	—	—	—
A004T02991 ...	VR628	—	—	—
A004T03091 ...	VR628	—	—	—
A004T03191 ...	VR628	—	—	—
A004T30593 ...	VR628	—	—	—
A005T01577 ...	VR456	—	—	—
A005T01897 ...	—	—	—	E480
A005T01977 ...	VR456	—	—	—
A005T03092 ...	VR629	—	—	—
A005T03192 ...	VR629	—	—	—
A005T10377 ...	VR596	—	—	E480
A005T10477 ...	VR596	—	—	E480
A005T15171 ...	VR595	AC38	—	E486
A005T15471 ...	VR595	AC38	—	E486
A005T16471 ...	VR596	—	—	E480
A005T20377 ...	VR595	AC38	—	E486
A005T20481 ...	VR576	—	—	E486
A005T20484 ...	VR576	—	—	E486
A005T21077 ...	VR595	AC38	—	E486
A005T22578 ...	—	—	—	E486
A005T22583 ...	—	—	—	E486
A005T23171 ...	VR596	—	—	E480
A005T30977 ...	VR596	—	—	E480
A005T31277 ...	VR579	—	—	E480
A005T40377 ...	VR579	—	—	E480
A005T41277 ...	VR579	—	—	E480
A005T70178 ...	—	—	—	E486
A005T70183 ...	—	—	—	E486
A005T70283 ...	—	—	—	E486
A005T70383 ...	—	—	—	E486
A006T40199 ...	—	—	—	E486
A006T40559 ...	—	—	—	E486
A006T40699 ...	VR576	—	—	E486
A006T65299 ...	—	—	—	E486
AHGA03 ...	VR627	—	—	—
AT48292 ...	—	AC96	—	—
MD007577 ...	—	—	—	E486
MD018230 ...	VR595	AC78	—	E486
MD022579 ...	VR595	AC25	—	E486
MD069978 ...	VR579	AC82	—	E480
MD073067 ...	VR579	AC72	—	E480
MD074644 ...	VR579	—	—	E480
MD074992 ...	VR579	AC82	—	E480
MD086047 ...	VR595	AC69	—	E486
MD089570 ...	VR576	—	—	E486
MD091793 ...	VR579	AC72	—	E480
MD091794 ...	VR579	AC72	—	E480
MD091849 ...	VR579	AC72	—	E480

(continued on next page)

MITSUBISHI (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
MD091850	VR579	AC99	—	E480	MD133171	VR578	AC76	—	E394
MD099624	VR579	AC72	—	E480	MD133513	VR578	AC76	—	E394
MD099625	VR579	AC72	—	E480	MD134315	VR578	AC76	—	E394
MD102084	VR578	AC72	—	E480	MD136838	VR578	AC76	—	E394
MD102085	VR578	AC72	—	E480	MD136839	VR578	AC76	—	E394
MD102088	VR578	AC72	—	E394	MD139736	—	—	—	E394
MD102095	VR578	AC72	—	E480	MD140247	VR578	AC72	—	E480
MD105339	VR578	AC72	—	E480	MD141855	VR578	AC76	—	E394
MD106506	VR579	AC72	—	E480	MD143480	—	—	—	E394
MD106712	VR578	AC72	—	E394	MD143481	—	—	—	E394
MD106713	VR578	—	—	E480	MD143512	—	—	—	E394
MD108022	VR578	AC72	—	E394	MD143513	—	—	—	E394
MD108023	VR578	AC72	—	E394	MD147149	VR579	—	—	E480
MD108229	VR578	AC72	—	E394	MD147950	VR578	AC76	—	E394
MD108230	—	—	—	E480	MD149750	VR578	AC76	—	E394
MD108305	VR579	AC72	—	E480	MD149751	VR578	AC76	—	E394
MD108320	VR578	AC72	—	E394	MD150421	VR578	AC72	—	E394
MD108509	VR578	AC72	—	E394	MD150657	VR628	—	—	—
MD108872	VR578	AC72	—	E394	MD152872	VR512	—	—	E394
MD109741	VR579	AC72	—	E480	MD153357	VR578	—	—	E394
MD110318	VR578	AC72	—	E394	MD153843	VR578	—	—	E394
MD111148	VR512	—	—	E394	MD156741	—	—	—	E394
MD111149	VR512	—	—	E480	MD158495	VR578	AC76	—	E394
MD111151	VR579	AC72	—	E480	MD160539	VR628	—	—	—
MD111228	VR578	AC72	—	E394	MD160540	VR628	—	—	—
MD111231	VR578	AC72	—	E394	MD162518	VR578	AC76	—	E394
MD111233	VR578	AC76	—	E394	MD162519	VR578	—	—	E394
MD111238	VR578	AC76	—	E394	MD166174	VR578	—	—	E394
MD111286	VR579	AC72	—	E480	MD168989	VR578	AC76	—	E394
MD111607	VR579	—	—	E480	MD197468	VR628	—	—	—
MD112208	VR578	AC72	—	E394	MD197469	VR628	—	—	—
MD112322	VR578	—	—	E394	MD197470	VR628	—	—	—
MD112323	VR578	—	—	E394	MD604066	VR595	AC38	—	E486
MD114620	VR512	—	—	E394	ME001570	—	—	—	E486
MD114991	—	—	—	E394	ME007578	—	—	—	E486
MD115582	VR578	AC72	—	E480	ME013740	VR576	—	—	E486
MD115583	VR578	AC72	—	E394	ME017560	—	—	—	E486
MD116418	—	AC72	—	—	ME017561	—	—	—	E486
MD117156	VR578	AC72	—	E394	ME034130	VR595	—	AC38	E486
MD120365	VR628	—	—	—	ME049165	—	—	—	E486
MD125096	VR578	AC72	—	E394	ME050190	VR576	—	—	E486
MD125569	VR578	AC72	—	E480	ME063781	VR595	—	AC38	E486
MD126110	VR578	AC76	—	E394	ME064068	VR595	—	AC38	E486
MD126796	VR578	AC76	—	E394					

(continued on next column)

MOTOROLA

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
A12800	VR1036	—	—	—	RA24N901	VR1023	—	—	—
A44798	VR1033	—	—	—	8AR2001	VR1020	—	—	—
A47263	VR1031	—	—	—	8AR2002	VR1020	—	—	—
AR2053F	VR1026	—	—	—	8AR2004	VR1020	—	—	—
AR38429	VR1020	—	—	—	8AR2004S	VR1020	—	—	—
AR40419	VR1032	—	—	—	8AR2005	VR1020	—	—	—
AR40527	VR1020	—	—	—	8AR2007	VR1020	—	—	—
AR41592	VR1020	—	—	—	8AR2008	VR1020	—	—	—
AR42110	VR1020	—	—	—	8AR2009	VR1020	—	—	—
AR43632	VR1020	—	—	—	8AR2014G	VR1020	—	—	—
AR45526	VR1031	—	—	—	8AR2015K	VR1020	—	—	—
AR74033	VR1025	—	—	—	8AR2016K	VR1020	—	—	—
AR80420	VR1025	—	—	—	8AR2016R	VR1020	—	—	—
AR114058	VR1025	—	—	—	8AR2017F	VR1020	—	—	—
AT27827	VR1020	—	—	—	8AR2018F	VR1020	—	—	—
AT45526	VR1031	—	—	—	8AR2021K	VR1021	—	—	—
AT56246	VR1031	—	—	—	8AR2022F	VR1020	—	—	—
AT56249	VR1024	—	—	—	8AR2023K	VR1020	—	—	—
AT56722	VR1029	—	—	—	8AR2024F	VR1020	—	—	—
L74747	VR1033	—	—	—	8AR2026F	VR1026	—	—	—
R30818	VR1026	—	—	—	8AR2033F	VR1020	—	—	—
R36588	VR1031	—	—	—	8AR2037F	VR1020	—	—	—
R42414	VR1026	—	—	—	8AR2041F	VR1020	—	—	—
R45238	VR1026	—	—	—	8AR2052	VR1020	—	—	—
RA12N35JD1 ..	VR1020	—	—	—	8AR2063F	VR1020	—	—	—
RA12N401	VR1020	—	—	—	8AR2065F	VR1026	—	—	—
RA12N451	VR1020	—	—	—	8AR2066F	VR1030	—	—	—
RA12N451D ...	VR1020	—	—	—	8AR2067L	VR1030	—	—	—
RA12N451T ...	VR1020	—	—	—	8AR2072F	VR1030	—	—	—
RA12N452	VR1020	—	—	—	8AR2081F	VR1030	—	—	—
RA12N452D ...	VR1020	—	—	—	8HA2023V	—	—	—	AMO1005
RA12N453	VR1020	—	—	—	8HC2001L	—	—	—	AMO1005
RA12N550	VR1020	—	—	—	8HC2009P	—	—	—	AMO1005
RA12N550D ...	VR1020	—	—	—	8HC3002F	—	—	—	AMO1005
RA12N55JD1 ..	VR1020	—	—	—	8LA2011R	—	—	—	AMO1005
RA12N55JD5 ..	VR1020	—	—	—	8LA2012R	—	—	—	AMO1005
RA12N55JD6 ..	VR1020	—	—	—	8LA2022R	—	—	—	AMO1005
RA12N55JD7 ..	VR1020	—	—	—	8LA2024R	—	—	—	AMO1005
RA12N600	VR1020	—	—	—	8LA2030R	—	—	—	AMO1005
RA12N600D ...	VR1020	—	—	—	8MA2003P	VR1036	AC28	AC27	—
RA12N600T ...	VR1020	—	—	—	8MR2008P	VR1036	AC28	AC27	—
RA12N601	VR1020	—	—	—	8MR2009P	VR1036	AC28	AC27	—
RA12NON450 ..	VR1020	—	—	—	8MR2010P	VR1036	AC28	AC27	—
RA12NON451 ..	VR1020	—	—	—	8MR2012P	VR1036	AC28	AC27	—
RA12NWC451 ..	VR1020	—	—	—	8MR2026P	VR1036	—	—	—
RA24JD902	VR1032	—	—	—	8RF2014C	VR1021	—	—	—
RA24N900	VR1023	—	—	—	8SA2011R	VR1020	—	—	—
RA24N900D ...	VR1023	—	—	—	8TA2003B	VR1024	—	—	—

(continued on next column)

(continued on next page)

MOTOROLA (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
8TA2009E	VR1025	—	—	—
8TA2018D	VR1028	—	—	—
8TA2020C	VR1031	—	—	—
8TA2021E	VR1025	—	—	—
8TA2023D	VR1025	—	—	—
8TA2024D	VR1024	—	—	—
8TA2025C	VR1031	—	—	—
8TA2026E	VR1025	—	—	—
8TA2027D	VR1029	—	—	—
8TA2028E	VR1021	—	—	—
8TA2052C	VR1031	—	—	—
8TA3020C	VR1031	—	—	—
8TA3025C	VR1031	—	—	—
8TA3052C	VR1031	—	—	—
8V235085	VR1020	—	—	—
8V23508509	VR1020	—	—	—

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
8V235089	VR1020	—	—	—
8V235703	VR1020	—	—	—
10A29415	VR1020	—	—	—
10A29415D	VR1020	—	—	—
10A31126	VR1020	—	—	—
10B29800	VR1020	—	—	—
12N37A	VR1020	—	—	—
12N51	VR1020	—	—	—
12N51A	VR1020	—	—	—
12SA101A	VR1036	—	—	—
12SA102A	VR1036	—	—	—
12SA105	VR1036	—	—	—
12SA105A	VR1036	—	—	—
12SA106A	VR1036	—	—	—
12SA109A	VR1036	—	—	—

(continued on next column)

NISSAN-DATSUN

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
23100A4800	VR521	—	—	—
23100A5500	VR521	—	—	E487
23100A5501	VR521	—	—	—
23100B0800	VR521	—	—	—
23100B9802	VR603	—	—	—
23100B9805	VR603	—	—	—
23100D0201	VR603	—	—	—
23100D0800	VR603	—	—	—
23100D1700	VR603	—	—	—
23100D3300	VR603	—	—	—
23100D4405	VR619	—	—	E395
23100D4410	—	—	—	E480
23100D4415	—	—	—	E480
23100H7701	VR603	—	—	—
23100H7702	VR603	—	—	—
23100H7703	VR603	—	AC68	—
23100M0413	VR521	—	—	—
23100M0414	VR521	—	—	—
23100M5961	VR603	—	—	—
23100M6600	VR603	—	AC68	—
23100M6601	VR554	—	AC68	E615
23100N8500	VR603	—	—	—
23100P3006	VR603	—	—	—
23100U0100	VR521	—	—	—
23100U0113	VR521	—	—	—
23100U0114	VR521	—	—	—
23100V0101	VR603	—	AC44	—

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
23100V0102	VR603	—	AC44	—
23100V0106	VR603	—	AC44	—
23100V0107	VR603	—	AC44	—
23100V7310	VR597	—	—	E480
23100V7311	VR597	—	—	E480
23100W2501	VR642	—	—	—
23100W2502	VR642	—	—	—
23100W5801	VR603	—	—	—
23100W5803	VR603	—	AC68	—
23100W5805	VR603	—	—	—
23100W5806	VR603	—	—	—
23100W5807	VR603	—	AC44	—
23300AA000	VR554	—	—	E615
23700AA000	VR554	—	—	E615
23700AA020	VR554	—	—	E615
2231000H610	—	—	AC67	—
2309929W00	VR642	—	AC70	—
2309929W10	VR642	—	AC70	—
2309936W02	VR642	—	AC70	—
2309936W03	VR642	—	AC70	—
2309936W04	VR642	—	AC70	—
2309936W05	VR642	—	AC70	—
2310004F10	VR588	—	—	—
2310004F11	VR588	—	—	—
2310004Y10	VR629	—	—	—
2310005G05	VR603	—	—	E593
2310010G03	VR642	—	—	—

(continued on next column)

(continued on next page)

NISSAN-DATSUN (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
2310010W01 ...	VR603	—	AC68	—	2310064J10 ...	VR590	—	—	—
2310012C10 ...	VR597	—	—	E480	2310064J12 ...	VR590	—	—	—
2310012C11 ...	VR597	—	—	E480	2310065E10 ...	VR635	—	—	—
2310012G00 ...	VR603	—	—	—	2310077A00 ...	—	—	—	E395
2310012G01 ...	VR632	—	—	—	2310077A10 ...	VR629	—	—	—
2310012G02 ...	VR632	—	—	—	2310080G08 ...	VR632	—	—	—
2310015P01 ...	VR612	—	—	E615	2310080G09 ...	VR632	—	—	—
2310015P12 ...	VR578	—	—	E480	2310080W00 ...	VR603	—	—	—
2310015P13 ...	—	—	—	E480	2310081W00 ...	VR603	—	—	—
2310016E05 ...	VR612	—	—	E615	2310084W00 ...	VR603	—	—	—
2310017A01 ...	VR642	—	—	—	2310085E00 ...	VR612	—	—	E615
2310017C00 ...	VR603	—	—	—	2310088G00 ...	VR632	—	—	—
2310018A01 ...	VR642	—	—	—	2310088G08 ...	VR632	—	—	—
2310020P10 ...	—	—	—	E480	2310088G09 ...	VR632	—	—	—
2310020R00 ...	VR603	—	—	—	2330001Y00 ...	—	—	—	E512
2310020W01 ...	VR603	—	AC68	—	231001800 ...	VR521	—	—	—
2310026E10 ...	—	—	—	E480	231001801 ...	VR521	—	—	—
2310026E11 ...	—	—	—	E480	231001805 ...	VR521	—	—	—
2310028B11 ...	—	—	—	E480	2310014600 ...	VR521	—	—	—
2310029R00 ...	VR554	—	AC44	—	2310014601 ...	VR521	—	—	—
2310030P00 ...	—	—	—	E615	2310014602 ...	VR521	—	—	—
2310031P10 ...	VR635	—	—	—	2310014615 ...	VR521	—	—	—
2310034E00 ...	VR612	—	—	E615	2310014802 ...	VR521	—	—	—
2310034E01 ...	VR612	—	—	E615	2310016510 ...	VR521	—	—	—
2310035F10 ...	VR635	—	—	VR635	2310016512 ...	VR521	—	—	—
2310037M00 ...	VR603	—	—	—	2310016710 ...	VR521	—	—	—
2310042L71 ...	—	—	—	E480	2310016715 ...	VR521	—	—	—
2310042L72 ...	—	—	—	E480	2310017000 ...	VR554	—	—	—
2310050Y18 ...	VR629	—	—	—	2310020110 ...	VR521	—	—	—
2310050Y19 ...	VR629	—	—	—	2310020111 ...	VR521	—	—	—
2310051S10 ...	VR588	—	—	E480	2310020115 ...	VR521	—	—	—
2310051S11 ...	—	—	—	E480	2310021000 ...	VR521	—	—	E487
2310053A00 ...	VR620	—	—	E591	2310023000 ...	VR521	—	—	E487
2310053F00 ...	VR632	—	—	—	2310023005 ...	VR521	—	—	E487
2310054A01 ...	VR642	—	—	—	2310046090 ...	—	—	—	E591
2310054A02 ...	VR642	—	—	—	2310080215 ...	VR521	—	—	—
2310058S11 ...	—	—	—	E480					
2310064J00 ...	VR632	—	—	—					

(continued on next column)

PARIS-RHONE

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
A13N117	VR636	—	—	—	A14N63	VR571	—	—	A439
A13N18	VR571	—	—	A439	A14N65	VR571	—	—	A439
A13R243	VR571	—	—	A439	A14N77	VR571	—	—	A439
A14N51	VR571	—	—	A439					
A14N56	VR571	—	—	A439					

(continued on next column)

RENAULT

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
7700500295 ...	VR32	—	—	—
7700529484 ...	VR32	—	—	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
7700532831 ...	VR32	—	—	—

SAAB

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
8560054	VR243	—	—	—

SUBARU

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
23700AA090 ...	VR302	—	—	—
23815AA030 ...	VR247	—	—	—
23815AA040 ...	VR248	—	—	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
329918710	—	—	—	E481
495737601	VR245	—	—	—

SUZUKI

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
3140060B40 ...	VR633	—	—	—
3140086510 ...	VR633	—	—	—
3730021030 ...	VR579	AC99	—	—
3730032510 ...	VR578	—	—	E394

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
3730032520 ...	VR578	—	—	E394
3730032530 ...	VR578	—	—	E394

TOYOTA

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
270600A020 ...	—	—	—	E601
17052689	—	—	—	E480
2702013030 ...	VR610	—	—	—
2702013090 ...	VR558	—	—	—
2702015020 ...	VR610	—	—	—
2702015030 ...	VR563	—	—	—
2702015040 ...	VR534	—	—	—
2702015110 ...	VR610	—	—	—
2702015120 ...	VR610	—	—	—
2702021011 ...	VR528	—	—	E480
2702022010 ...	VR528	—	—	E480
2702022011 ...	VR528	—	—	E480
2702022012 ...	VR528	—	—	E480
2702022021 ...	VR528	—	—	E480
2702024010 ...	VR528	—	—	E480
2702025010 ...	VR528	—	—	E480
2702026102 ...	VR534	—	—	—

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
2702028030 ...	VR563	—	—	—
2702031031 ...	VR528	—	—	E480
2702031032 ...	VR528	—	—	E480
2702033010 ...	VR528	—	—	E480
2702033011 ...	VR528	—	—	E480
2702033030 ...	VR528	—	—	E480
2702035050 ...	VR559	—	—	—
2702035160 ...	VR572	—	—	E601
2702038014 ...	VR534	—	—	—
2702038111 ...	VR559	—	—	—
2702040060 ...	VR528	—	—	E480
2702040061 ...	VR528	—	—	E480
2702041011 ...	VR528	—	—	E480
2702041012 ...	VR528	—	—	E480
2702041013 ...	VR528	—	—	E480
2702041031 ...	VR528	—	—	E480
2702041032 ...	VR528	—	—	E480

(continued on next page)

TOYOTA (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set	Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
2702045010 ...	VR528	—	—	E480	2706042030 ...	VR572	—	—	—
2702054080 ...	VR623	—	—	—	2706043020 ...	VR563	—	—	—
2702054220 ...	VR623	—	—	—	2706043030 ...	VR563	—	—	—
2702056190 ...	VR623	—	—	—	2706043110 ...	VR572	—	—	—
2702056240 ...	VR623	—	—	—	2706046120 ...	—	—	—	E601
2702057071 ...	VR623	—	—	—	2706046190 ...	—	—	—	E601
2702060031 ...	VR528	—	—	E480	2706046200 ...	—	—	—	E601
2702060032 ...	VR528	—	—	E480	2706050010 ...	VR572	—	—	—
2702060033 ...	VR528	—	—	E480	2706061090 ...	VR624	—	—	—
2702061100 ...	VR558	—	—	—	2706061091 ...	VR624	—	—	E480
2702061110 ...	VR558	—	—	—	2706061100 ...	VR572	—	—	E480
2702061130 ...	VR558	—	—	—	2706062012 ...	VR572	—	—	E601
2702061150 ...	VR558	—	—	—	2706062040 ...	VR572	—	—	—
2702064080 ...	VR623	—	—	—	2706062070 ...	VR655	—	—	E601
2706002030 ...	VR572	—	—	E601	2706062090 ...	VR644	—	—	E601
2706003010 ...	VR655	—	—	E601	2706062110 ...	—	—	—	E601
2706003011 ...	VR655	—	—	E601	2706062160 ...	VR644	—	—	E601
2706003050 ...	VR644	—	—	E601	2706062190 ...	VR644	—	—	E601
2706010061 ...	—	—	—	E601	2706063020 ...	VR572	—	—	—
2706011100 ...	VR572	—	—	E601	2706063030 ...	VR572	—	—	—
2706011120 ...	—	—	—	E601	2706063080 ...	VR572	—	—	—
2706011220 ...	VR655	—	—	E601	2706063082 ...	VR572	—	—	E601
2706011250 ...	VR651	—	—	E601	2706063100 ...	VR572	—	—	—
2706011270 ...	VR652	—	—	E601	2706064080 ...	VR623	—	—	—
2706011281 ...	VR644	—	—	E601	2706064100 ...	VR623	—	—	—
2706011290 ...	VR652	—	—	E601	2706065020 ...	VR572	—	—	E601
2706011330 ...	VR652	—	—	E601	2706065040 ...	VR644	—	—	E601
2706011340 ...	VR644	—	—	E601	2706066070 ...	VR652	—	—	E601
2706015011 ...	VR563	—	—	—	2706072050 ...	VR572	—	—	—
2706015080 ...	VR644	—	—	E601	2706072060 ...	VR572	—	—	—
2706015100 ...	VR644	—	—	E601	2706072100 ...	VR572	—	—	—
2706015110 ...	VR644	—	—	E601	2706072171 ...	VR572	—	—	—
2706015140 ...	VR644	—	—	E601	2706074020 ...	VR572	—	—	E601
2706016030 ...	VR624	—	—	—	2706074130 ...	VR572	—	—	—
2706016050 ...	VR572	—	—	—	2706074150 ...	VR572	—	—	—
2706016080 ...	VR572	—	—	—	2706074160 ...	VR572	—	—	E601
2706016090 ...	VR572	—	—	—	2706074180 ...	VR655	—	—	E601
2706016170 ...	VR572	—	—	E601	2706074190 ...	—	—	—	E601
2706016230 ...	VR572	—	—	E601	2706074210 ...	VR655	—	—	E601
2706020010 ...	VR644	—	—	E601	2706074270 ...	VR655	—	—	E601
2706035020 ...	VR563	—	—	—	2706074290 ...	VR655	—	—	E601
2706035040 ...	VR563	—	—	—	2706074291 ...	VR655	—	—	—
2706035061 ...	VR572	—	—	E601	2706074300 ...	VR655	—	—	E601
2706035071 ...	VR572	—	—	—	2706074310 ...	VR655	—	—	E601
2706035120 ...	VR572	—	—	E601	2706074320 ...	VR655	—	—	E601
2706035130 ...	VR572	—	—	E601	2706074330 ...	VR655	—	—	E601
2706035150 ...	VR644	—	—	E601	2706074360 ...	VR644	—	—	E601
2706035160 ...	VR652	—	—	E601	2706074370 ...	VR644	—	—	E601

(continued on next column)

(continued on next page)

TOYOTA (Cont'd)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
2706074380 ...	VR644	—	—	E601
2706074390 ...	VR644	—	—	E601
2706074420 ...	VR644	—	—	E601
2706074430 ...	VR644	—	—	E601
2706074440 ...	VR644	—	—	E601
2706074450 ...	VR644	—	—	E601
2706074460 ...	VR644	—	—	E601
2706074500 ...	VR644	—	—	E601
2706075040 ...	VR652	—	—	E601
2706075150 ...	—	—	—	E601

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
2706075160 ...	VR644	—	—	E601
2706076010 ...	VR572	—	—	—
2706076030 ...	VR572	—	—	—
2706076040 ...	VR655	—	—	E601
2706076060 ...	VR644	—	—	E601
2706076080 ...	VR644	—	—	E601
2770062190 ...	VR644	—	—	E601
2770075150 ...	—	—	—	E601

VOLVO

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
269061	VR503	—	—	—
269629	VR503	—	—	—
1234977	VR503	—	—	—
1257294	VR503	—	—	E455
1258367	VR503	—	—	E455
1308766	VR503	—	—	E455
1323230	VR503	—	—	—
2415271	VR503	—	—	—
2417350	VR503	—	—	—
4424346	VR506	—	—	—
4628933	VR32	—	—	—
4639308	VR503	—	—	E455
4639316	VR503	—	—	—
12349775	VR503	—	—	E455
12359089	VR503	—	—	E455
13571997	—	—	—	M407

(continued on next column)

Unit No	Voltage Regulator	Diodes (P)/ Rectifier (P)	Diodes (N)/ Rectifier (N)	Brush Set
13634936	VR506	—	—	M407
13634977	VR506	—	—	M407
13635107	VR506	—	—	M407
13635115	VR506	—	—	M407
13635123	VR506	—	—	M407
35159300	VR506	—	—	M407
35444960	VR506	—	—	M407
35444975	VR506	—	—	M407
50027309	VR506	—	—	M407
50036433	VR506	—	—	M407
50036441	VR506	—	—	M407
50036987	VR506	—	—	M407
120400722	VR503	—	—	—
0120400545 ...	VR503	—	—	—
0120400716 ...	VR503	—	—	—

AMERICAN MOTORS

Unit No	Voltage Regulator	Brush Set	Bushing
925045	VR206	A434	—
3149528	—	SD707	—
3150323	—	R423	—
3150324	—	R423	—
3150325	VR126	R423	—
3155796	VR136	R423	—
3157206	—	A434	—
3157211	—	A434	—
3161479	—	R423	—
3161480	—	R423	—
3167664	—	R423	—
3200235	—	R423	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
3200236	—	R423	—
3200237	VR126	R423	—
3201811	—	A434	—
3201812	—	A434	—
3202796	—	R423	—
3202797	—	R423	—
3203564	—	R423	—
3203565	—	R423	—
3203578	VR208	A434	—
3203588	VR208	A434	—

AUTOLITE-PRESTOLITE

Unit No	Voltage Regulator	Brush Set	Bushing
GAG4127	CU2 ¹⁰	—	—
GAP4157	CU2 ¹⁰	—	—
GAR4601	—	A409	—
GAR4603	—	A409	4278
GAR4603A	—	A409	4278
GAR4605	—	A409	—
GAR4606	—	A409	—
GAR4607	CU2 ¹⁰	A409	—
GAR4608A	—	A409	4278
GAR4608B	—	A409	4278
GAR4608C	—	A409	4278
GAR4608D	—	A409	4278
GAR4608E	—	A409	4278
GAR4608F	—	A409	4278
GAR4608G	—	A409	4278
GAR4608H	—	A409	4278
GAR4609	—	A409	4278
GAR4609A	—	A409	4278
GAR4609B	—	A409	4278
GAR4610	—	A409	—
GAR4611	—	A409	4278
GAR4611A	—	A409	4278
GAR4612	—	A409	—
GAR4613	—	A409	—
GAR4614	—	A409	—
GAR4615	—	A409	—
GAR4616	—	A409	—
GAR4617	—	A409	—
GAR4618	—	A409	—
GAR4619	—	A409	4278
GAR4620	—	A409	4278

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
GAR4621	—	A409	—
GAR4622	CU2 ¹⁰	A409	—
GAR4623	—	A409	—
GAR4624	—	A409	4278
GAR4625	—	A409	4278
GAR4626	—	A409	—
GAR4627	—	A409	—
GAR4632	—	A409	—
GAR4633	—	A409	—
GAR4634	—	A409	—
GAR4635	—	A409	—
GAR4730	—	A409	4278
GAR4731	—	A409	4278
GAS4140	CU2 ¹⁰	—	—
GAS4175T	CU2 ¹⁰	—	—
GAS4177T	CU2 ¹⁰	—	—
GAS41941	CU2 ¹⁰	—	—
GBE4203	—	A409	—
GBE4204	—	A409	—
GBE4205	—	A409	—
GBE4206	—	A409	—
GBE4207	—	A409	—
GBE4208	—	A409	—
GBJ4201	—	A409	—
GBJ4202	—	A409	—
GBJ4203	—	A409	—
GBJ4204	—	A409	—
GBJ4205	—	A409	—
GBJ4601	—	A409	—
GBM460A	—	A409	4278
GBM460B	—	A409	4278

(continued on next page)

¹⁰ Physical comparison is necessary or check application guide

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
GBM4306A	—	A409	4278
GBM4306B	—	A409	4278
GBM4306C	—	A409	4278
GBM4306D	—	A409	4278
GBM4306E	—	A409	4278
GBM4306F	—	A409	4278
GBM4306G	—	A409	4278
GBM4306H	—	A409	4278
GBM4601	—	A409	4278
GBM4601C5	—	A409	4278
GBM4602	—	A409	4278
GBM4603	—	A409	4278
GBM4603A	—	A409	4278
GBM4603B	—	A409	4278
GBM4603C	—	A409	4278
GBM4603D	—	A409	4278
GBM4603E	—	A409	4278
GBM4603F	—	A409	4278
GBM4603G	—	A409	4278
GBM4603H	—	A409	4278
GBM4604	—	A409	4278
GBM4604A	—	A409	4278
GBM4604B	—	A409	4278
GBM4606	—	A409	4278
GBM4606A	—	A409	4278
GBM4606B	—	A409	4278
GBM4606C	—	A409	4278
GBM4607A	—	A409	4278
GBM4607B	—	A409	4278
GBM4608A	—	A409	4278
GBM4608B	—	A409	4278
GBM4608C	—	A409	4278
GBM4608D	—	A409	4278
GBM4609A	—	A409	4278
GBM4610A5	—	A409	4278
GBM4610B5	—	A409	4278
GBM4610C5	—	A409	4278
GBM4611A	—	A409	4278
GBM4612	—	—	4278
GBM4612A	—	A409	4278
GBM4613A1	—	A409	4278
GBM4614A	CU2 ¹⁰	A409	4278
GBM4615A	—	A409	4278
GBM4616A	—	A409	4278
GBM4617	—	A409	4278
GBM4619	CU2 ¹⁰	A409	4278
GBM4620A	—	A409	4278
GBM4622	—	A409	4278
GBM4622A5	—	A409	4278

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
GBM4802A5	—	A409	4278
GBM4802B5	—	A409	4278
GBM4802S	—	A409	4278
GBM4804A5	—	A409	4278
GBM4804B5	—	A409	4278
GBM4804C5	—	A409	4278
GBM4804D5	—	A409	4278
GBM4804E5	—	A409	4278
GBM4804F5	—	A409	4278
GBM4805	—	A409	4278
GBM4806A	—	A409	4278
GBM4807A1	—	A409	4278
GBM4808A	—	A409	4278
GBM4809A	—	A409	4278
GBM4809B	—	A409	4278
GBM4809B5	—	A409	4278
GBM4810A	—	A409	4278
GBM4811	CU2 ¹⁰	A409	—
GBM4812A	—	A409	4278
GBM4812A5	—	A409	4278
GBM4813A5	—	A409	4278
GBM4814A1	—	A409	4278
GBM4816A	—	A409	4278
GBM4818A1	—	A409	4278
GBM4818B1	—	A409	4278
GBM4819A	—	A409	4278
GBM4821A5	—	A409	4278
GBM4822A5	—	A409	4278
GBM4822BN5	—	A409	4278
GBM4823A5	CU2 ¹⁰	—	4278
GBM4901A	—	A409	4278
GBM46105S1	—	A409	4278
GBM46215	—	A409	4278
GBM46225	—	A409	4278
GBM48025	—	A409	4278
GBM48045	—	A409	4278
GBM48055	—	A409	4278
GBM48071	—	A409	4278
GBM48135	—	A409	4278
GBM48245	—	A409	4278
GBR4601	—	A409	4278
GBR4602	—	A409	—
GBR4603	—	A409	4278
GBR4604	—	A409	—
GBR4605	—	A409	4278
GBR4607	—	A409	—
GBR4608	—	A409	—
GBR4609	—	A409	—
GBR4611	—	A409	—

(continued on next page)

¹⁰ Physical comparison is necessary or check application guide

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
GBR4612	—	A409	—
GBS4605	—	A409	—
GBS4606	—	A409	—
GBS4611	—	A409	—
GBU4201	—	A409	4278
GBU4202	—	A409	4278
GBU4203	—	A409	4278
GBU4204	—	A409	4278
GBU4208	—	A409	4278
GBU4209	—	A409	4278
GBU4209A	—	A409	4278
GBU4210	—	A409	4278
GBU4211	—	A409	4278
GBU4212	—	A409	4278
GBU4213A	—	A409	4278
GBU4214	—	A409	4278
GBU4214A	—	A409	4278
GBU4216	—	A409	4278
GBU4216A	—	A409	4278
GBU4216B	—	A409	4278
GBU4801	—	A409	4278
GBU420104	—	A409	4278
GBW4602	—	A430	—
GBW4802	—	A430	—
GBW4804	—	A430	4278
GBW4804A	—	A430	4278
GBW4805	—	A430	—
GBW4805A	—	A430	—
GBW4808	—	A430	4278
GCJ4815	—	—	4278
GCK4805	—	A430	4278
GCK4805A	—	A430	4278
GCK4806	—	A430	4278
GCK4807	—	A430	4278
GCK48041	—	A430	4278
GCM4809A	—	—	4278
GCM4812	CU2 ¹⁰	—	—
GCM4815A4	VR25	—	—
GCM4816A4	VR25	—	—
GCO4801	—	—	4278
GCO4801C	—	—	4278
GCO4801D	—	—	4278
GCO4802	—	A430	—
GCO4802A	—	A430	—
GCO4802B	—	A430	—
GCO4802C	—	A430	—
GCO4803A	—	A430	4278
GCO4804A	—	A430	4278
GCO4805A	—	A430	4278

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
GCO4806A	—	A430	4278
GCO4807A	—	A430	4278
GCP4801	—	A430	4278
GCP4802	—	A430	4278
GCR4802	—	A430	—
GCR4802N	—	A430	—
GCS4807	—	—	4278
GCZ4803	—	—	4278
GCZ4805	—	—	4278
GDA(ALL)	—	A430	4278
GDB48062	—	—	4278
GDB48062N	—	—	4278
GDB48072	—	—	4278
GDB48072N	—	—	4278
GDF4813	—	—	4278
GDM48061	VR206	—	—
GDT4804A	—	SD707	—
GDZ4801A	VR25	A430	4278
GDZ4801B	VR25	A430	4278
GDZ4801C	VR25	A430	4278
GDZ4801D	VR25	A430	4278
GDZ4801E	VR25	A430	4278
GDZ4801F	VR25	A430	4278
GDZ4801G	VR25	A430	4278
GDZ4801H	VR25	A430	4278
GDZ4801J1	—	A430	4278
GDZ4801K	VR25 ¹⁹	A430	4278
GDZ4801L	VR25	A430	4278
GDZ4801LP	VR25	A430	4278
GDZ4801Q	VR25	A430	4278
GDZ4801R	VR25	A430	4278
GDZ4801S	—	A430	4278
GDZ4801S1	—	A430	4278
GDZ4801T	VR25	A430	4278
GDZ4801TV	VR25	A430	4278
GDZ4802A	VR25	A430	4278
GDZ4802B	VR25	A430	4278
GDZ4802S1	VR25	A430	4278
GDZ4803A	VR25	A430	—
GDZ4803B	VR25	A430	—
GDZ4804A	VR25	A430	4278
GDZ4805A	VR25	A430	4278
GDZ4805B	VR25	A430	4278
GDZ4806A	VR25	A430	—
GDZ4806B	VR25	A430	—
GDZ4807	VR25	A430	4278
GDZ4807A	VR25	A430	4278
GDZ4808	VR25	A430	—
GDZ4809	VR25	A430	—

(continued on next page)

¹⁰ Physical comparison is necessary or check application guide ¹⁹ Positive ground

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
GDZ4810A	VR25	A430	4278
GDZ4811A	VR25	A430	4278
GDZ4812A	VR25	A430	4278
GDZ4812B	VR25	A430	4278
GDZ4812S	VR25	A430	4278
GDZ4813A	—	A430	4278
GDZ4813B	VR25	A430	4278
GDZ4813C	VR25	A430	4278
GDZ4813D	VR25	A430	4278
GDZ4813E	VR25	A430	4278
GDZ4813F	VR25	A430	4278
GDZ4813G	—	A430	4278
GDZ4813S	VR25	A430	4278
GDZ4814AM ...	—	A430	4278
GDZ4814M	—	A430	4278
GDZ4816AM ...	—	A430	4278
GDZ4816M	—	A430	4278
GDZ4817A	VR22 ¹¹	A430	4278
GDZ4817A	VR27 ¹⁹	A430	4278
GDZ4818A	VR25	A430	4278
GDZ4818B	VR25	A430	4278
GDZ4819AM ...	—	A430	4278
GDZ4819BM ...	—	A430	4278
GDZ4819CM ...	—	A430	4278
GDZ4819M	—	A430	4278
GDZ4819MS ...	—	A430	4278
GDZ4820AM ...	—	A430	4278
GDZ4820BM ...	—	A430	4278
GDZ4820M	—	A430	4278
GDZ4821A	VR25	A430	4278
GDZ4821A1 ...	—	A430	4278
GDZ4821S1	—	A430	4278
GDZ4822A	—	A430	4278
GDZ4822A1 ...	—	A430	4278
GDZ4822B	—	A430	4278
GDZ4822S1	—	A430	4278
GDZ4823AM ...	—	A430	4278
GDZ6001A	VR25	—	4347
GDZ6001B	VR25	A430	4347
GDZ6001C	VR25	A430	4347
GDZ6001D	VR25	A430	4347
GDZ6001E	VR25	A430	4347
GDZ6001F	VR25	A430	4347
GDZ6001H	VR25	—	4347
GDZ6001HT ...	—	—	4347
GDZ6001S	—	A430	4347
GDZ6002A	VR25	A430	4347
GDZ6003	VR751	A430	4347
GEA4801	VR25	A430	4278

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
GEA4801A	VR25	A430	4278
GEA4802A	—	A430	4278
GEA4803A	VR25	A430	4278
GEA4803B	VR25	A430	4278
GEA4804A	VR25	A430	4278
GEB4801	VR25	—	—
GEB4801A	VR25	—	—
GEB4801B3 ...	VR25	—	—
GEB4802	VR25	—	—
GEB4802C	VR25	—	—
GEB4803A	VR25	—	—
GEB4803B	VR25	—	—
GEB4807	VR25	—	—
GEB4810	VR25	—	—
GEB4812	VR25	—	—
GEB4813	VR25	—	—
GEB4823	VR25	—	—
GEB4825A	VR25	—	—
GEB6001A	VR25	—	—
GEB6001B	VR25	—	—
GEB6001C	VR25	—	—
GEB6001D	VR25	—	—
GEB6001E	—	SD707	—
GEB6001F	—	SD707	—
GEB6001G	—	SD707	—
GEB6001H	VR25	—	—
GEB6001I	VR25	—	—
GEB6001J	VR25	—	—
GEB6001K	VR25	—	—
GEB6001L	VR25	—	—
GEB6001M	VR25	—	—
GEB6001N	VR25	—	—
GEB6001O	VR25	—	—
GEB6001P	VR25	—	—
GEB6001Q	VR25	—	—
GEB6001R	VR25	—	—
GEB6001S	VR25	—	—
GEB6001S1 ...	—	SD707	—
GEB48193	—	SD707	—
GEF4801A	—	A430	4278
GEF4801AT ...	—	A434	4278
GEF4801B	—	A430	4278
GEF4801C	—	A430	4278
GEF4801D	—	A430	4278
GEF4801E	—	A430	4278
GEF4803	—	A430	—
GEF4804	—	A430	4278
GEF4806	—	A430	4278
GEF4806A	—	A430	4278

(continued on next page)

¹¹ Negative ground ¹⁹ Positive ground

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing	Unit No	Voltage Regulator	Brush Set	Bushing
GEF4806B	—	A430	4278	GEG48122	—	SD707	—
GEF4809AM	—	A430	4278	GEG48171	—	SD707	—
GEF4809BM	—	A430	4278	GEH4821A2	—	SD707	—
GEF4809M	—	A430	4278	GEH4821B2	—	SD707	—
GEF4810AM	—	A430	4278	GEH4823A	—	SD707	—
GEF4810BM	—	A430	4278	GEH4823B	—	SD707	—
GEF4810M	—	A430	4278	GEH4827M1	—	SD707	—
GEF4811AM	—	A430	4278	GEH4828M1	—	SD707	—
GEF4813A	—	A430	4278	GEH4830B2	—	SD707	—
GEF4813AN	—	A430	4278	GEH4831A2	—	SD707	—
GEF4813B	—	A430	4278	GEH6001A	—	SD707	—
GEF4813C	—	A430	4278	GEH6001B	—	SD707	—
GEF4813D	—	A430	4278	GEH6001S	—	SD707	—
GEF4813S	—	A430	4278	GEH48292	—	SD707	—
GEF4814AM	—	A430	4278	GEH50022N	—	SD707	—
GEF4814BM	—	A430	4278	GEJ4801	—	A430	4278
GEF4815AM	—	A430	4278	GEJ4805	—	A430	4278
GEF4815BM	—	A430	4278	GEO4806	—	—	4278
GEF4815MA	—	A430	4278	GEO4807	—	—	4278
GEF4816	—	A430	4278	GEO4808	—	—	4278
GEF4817	—	A430	4278	GEO4816A	—	—	4278
GEF4819S	—	A430	4278	GEO4818A3	—	—	4278
GEF4901M	—	A430	4278	GEO48043	—	—	4278
GEF4902M	—	A430	4278	GEO48053	—	—	4278
GEF4903M	—	A430	4278	GEO48063	—	—	4278
GEF4904M	—	A430	4278	GEO48073	—	—	4278
GEF5001	—	A430	4347	GEO48093	—	—	4278
GEF5002	—	A430	4347	GEO48143	—	—	4278
GEF5003	—	—	4347	GEO48183	—	—	4278
GEF5003A	—	—	4347	GEWSeries	—	—	4278
GEF5004	—	—	4347	GEZ4802	—	SD707	—
GEF5004A	—	—	4347	GFA4819	—	—	4278
GEG4822 VR25	—	—	—	GFA48012	—	—	4278
GEG4829 VR25	—	—	—	GFA48082	—	—	4278
GEG4835M1	—	SD707	—	GFA48162	—	—	4278
GEG5002D	—	SD707	—	GFA48202	—	—	4278
GEG5002E	—	SD707	—	GFA48232	—	—	4278
GEG5002S	—	SD707	—	GFA48252	—	—	4278
GEG5101	—	—	4278	GFA48262	—	—	4278
GEG5101A	—	—	4278	GFA48332	—	—	4278
GEG5101B	—	—	4278	GFA48342	—	—	4278
GEG5101C	—	—	4278	GFA48352	—	—	4278
GEG5101D	—	—	4278	GFA48362	—	—	4278
GEG5101E	—	—	4278	GFA48372	—	—	4278
GEG5101F	—	—	4278	GFB4801	—	—	4278
GEG6001D	—	SD707	—	GFB48033	—	—	4278
GEG6001E	—	SD707	—	GFB48053	—	—	4278
GEG6001S	—	SD707	—	GFE ALL	—	A409	4278
GEG6001S1	—	SD707	—	GFESeries	—	A409	4278

(continued on next column)

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing	Unit No	Voltage Regulator	Brush Set	Bushing
GFJ4802	—	A409	—	GGA6001AO ...	VR204	—	—
GFM4801	—	A409	—	GGA6001AP ...	VR204	—	—
GFP4801A	—	A409	—	GGA6001AQ ...	VR204	—	—
GFP4801B	—	A409	—	GGA6001AR ...	VR204	—	—
GFP4804	—	A409	—	GGA6001AS ...	VR204	—	—
GFW4804	—	—	4278	GGA6001AT ...	VR204	—	—
GFW4805	—	—	4278	GGA6001AU ...	VR204	—	—
GFW4810	—	—	4278	GGA6001AV ...	VR204	—	—
GFW4815	—	—	4278	GGA6001B	—	SD707	—
GFW4824	—	—	4278	GGA6001C	VR204	—	—
GFW48201	—	—	4278	GGA6001D	—	SD707	—
GGA4802AM ...	VR204	—	—	GGA6001E	—	SD707	—
GGA4803	VR204	—	—	GGA6001EN ...	—	SD707	—
GGA4805A	—	SD707	—	GGA6001F	—	SD707	—
GGA4805B	—	SD707	—	GGA6001G	—	SD707	—
GGA4807	—	SD707	—	GGA6001H	VR204	—	—
GGA4808A	—	SD707	—	GGA6001J	VR204	—	—
GGA4809AM ...	VR204	—	—	GGA6001K	VR204	—	—
GGA4810	—	SD707	—	GGA6001L	VR204	—	—
GGA4812A	—	SD707	—	GGA6001M	VR204	—	—
GGA4813	—	SD707	—	GGA6001N	VR204	—	—
GGA4814A	VR204	—	—	GGA6001N1 ...	—	SD707	—
GGA4814B	—	SD707	—	GGA6001NS1 ..	VR204	—	—
GGA4814C	—	SD707	—	GGA6001P	VR204	—	—
GGA4814D	—	SD707	—	GGA6001R	VR204	—	—
GGA4814E	—	SD707	—	GGA6001S	VR1013	—	—
GGA4814F	VR204	—	—	GGA6001S1 ...	—	SD707	—
GGA4814G	VR204	—	—	GGA6001V	VR204	—	—
GGA4814H	VR204	—	—	GGA6001W	VR204	—	—
GGA4816	VR206	—	—	GGA6001X	VR204	—	—
GGA4817	VR206	—	—	GGA6001Y	VR204	—	—
GGA6001	VR204	—	—	GGA6001Z	VR412	—	—
GGA6001A	VR204	—	—	GGA6002A	VR204	—	—
GGA6001AB ...	VR412	—	—	GGA6002AA ...	VR204	—	—
GGA6001AC ...	VR204	—	—	GGA6002AGS ..	VR204	—	—
GGA6001AD ...	VR204	—	—	GGA6002B	VR204	—	—
GGA6001AE ...	VR204	—	—	GGA6002C	VR204	—	—
GGA6001AF ...	VR206	—	—	GGA6002D	VR204	—	—
GGA6001AG ...	VR204	—	—	GGA6002E	VR204	—	—
GGA6001AH ...	VR204	—	—	GGA6002F	VR204	—	—
GGA6001AH ...	VR412	—	—	GGA6002G	VR204	—	—
GGA6001AI ...	VR204	—	—	GGA6002GS ...	VR204	—	—
GGA6001AJ ...	VR204	—	—	GGA6002S	VR204	—	—
GGA6001AK ...	VR204	—	—	GGA6002S1 ...	VR204	—	—
GGA6001AL ...	VR204	—	—	GGA6003A	VR204	—	—
GGA6001AL ...	VR412	—	—	GGA6003B	VR204	—	—
GGA6001AM ...	VR204	—	—	GGA6003C	VR204	—	—
GGA6001AM ...	VR412	—	—	GGA6003D	VR204	—	—
GGA6001AN ...	VR204	—	—	GGA6003E	VR204	—	—

(continued on next column)

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing	Unit No	Voltage Regulator	Brush Set	Bushing
GGA6003F	VR204	—	—	GGA6009W	VR204	—	—
GGA6003G	VR204	—	—	GGA6009X	VR204	—	—
GGA6003S1 ...	VR204	—	—	GGA6009Y	VR204	—	—
GGA6004	VR204	—	—	GGA6010A	VR204	—	—
GGA6004A	VR204	—	—	GGA6010AA ...	VR204	—	—
GGA6004B	VR204	—	—	GGA6010B	VR204	—	—
GGA6004S1 ...	VR204	—	—	GGA6010BA ...	VR204	—	—
GGA6005A	VR204	—	—	GGA6010C	VR204	—	—
GGA6005B	VR204	—	—	GGA6010CGA ..	VR204	—	—
GGA6005BA ...	VR204	—	—	GGA6010CS1 ..	VR204	—	—
GGA6005S1 ...	VR204	—	—	GGA6010D	VR204	—	—
GGA6006A	VR204	—	—	GGA6010E	VR204	—	—
GGA6006B	VR204	—	—	GGA6010F	VR204	—	—
GGA6006C	VR204	—	—	GGA6010G	VR204	—	—
GGA6006D	VR204	—	—	GGC4802A	—	A430	4278
GGA6006E	VR204	—	—	GGC4802B	—	A430	4278
GGA6006F	VR204	—	—	GGC4802S	—	A430	4278
GGA6006G	VR204	—	—	GGE4801M	VR751	A430	4278
GGA6006H	VR204	—	—	GGE4803	—	A430	4278
GGA6006I	VR204	—	—	GGE4804M	—	A430	4278
GGA6006J	VR204	—	—	GGE4805M	—	A430	4278
GGA6006K	VR204	—	—	GGE4806A	—	A430	4278
GGA6006L	VR204	—	—	GGE4806B	—	A430	4278
GGA6006M	VR204	—	—	GGE4806C	—	A430	4278
GGA6006N	VR204	—	—	GGE4807M	—	A430	4278
GGA6006P	VR204	—	—	GGE4808M	—	A430	4278
GGA6006R	VR412	—	—	GGE4809B	VR751	A430	4278
GGA6006S	VR412	—	—	GGE4809S	VR751	A430	4278
GGA6006SERIES	VR204	—	—	GGF6101F	VR126	—	—
GGA6007	VR204	—	—	GGG4801M	—	A430	4278
GGA6007A	VR204	—	—	GGG4802M	—	A430	4278
GGA6007B	VR204	—	—	GGG4803	—	A430	4278
GGA6007C	VR204	—	—	GGH6002A	—	—	4347
GGA6007S1 ...	VR204	—	—	GGJ4801A	—	SD707	—
GGA6009AC ...	VR204	—	—	GGJ4802A	—	SD707	—
GGA6009AK ...	VR204	—	—	GGJ4802AX ...	—	SD707	—
GGA6009AL ...	VR204	—	—	GGJ4803A	—	SD707	—
GGA6009AM ...	VR204	—	—	GGJ4803B	—	SD707	—
GGA6009AN ...	VR204	—	—	GGJ4803C	—	SD707	—
GGA6009C	VR204	—	—	GGJ4804A	—	SD707	—
GGA6009K	VR204	—	—	GGJ4804B	—	SD707	—
GGA6009L	VR204	—	—	GGJ6001A	VR126	—	—
GGA6009M	VR204	—	—	GGJ6001B	VR126	—	—
GGA6009N	VR204	—	—	GGJ6001D	VR126	—	—
GGA6009NS1 ..	VR204	—	—	GGJ6001E	VR126	—	—
GGA6009P	VR204	—	—	GGJ6001F	VR126	—	—
GGA6009R	VR204	—	—	GGJ6001G	VR126	—	—
GGA6009S1 ...	VR204	—	—	GGJ6001J	VR126	—	—
GGA6009V	VR204	—	—	GGJ6001K	VR126	—	—

(continued on next column)

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing	Unit No	Voltage Regulator	Brush Set	Bushing
GGJ6001L	VR126	—	—	GGU6001C	—	A430	4347
GGJ6001S	VR126	—	—	GGU6001D	—	A430	4347
GGJ6001S1	VR126	—	—	GGU6001E	—	A430	4347
GGJ6002A	VR126	—	—	GGU6001F	—	A430	4347
GGJ6002B	VR126	—	—	GGU6001FF1	—	A430	4347
GGJ6002C	VR126	—	—	GGU6001G	—	A430	4347
GGJ6002E	VR126	—	—	GGU6001H	—	A430	4347
GGJ6002S	VR126	—	—	GGU6001I	—	A430	4347
GGJ6002S1	VR126	—	—	GGU6001J	—	A430	4347
GGJ6003A	VR126	—	—	GGU6001K	—	A430	4347
GGJ6003S1	VR126	—	—	GGU6001K1	VR126	A430	—
GGJ6004A	VR126	—	—	GGU6001KF	—	A430	4347
GGJ6004B	VR126	—	—	GGU6001L	—	A430	4347
GGJ6004C	VR126	—	—	GGU6001P	—	A430	4347
GGJ6004D	VR126	—	—	GGU6001R	—	A430	4347
GGJ6004E	VR126	—	—	GGU6001S	VR22 ¹¹	A430	4347
GGJ6004F	VR126	—	—	GGU6001S	VR27 ¹⁹	A430	4347
GGJ6004G	VR126	—	—	GGU6001S1	—	A430	4347
GGJ6004H	VR126	—	—	GGU6001T	—	A430	4347
GGJ6004S1	VR126	—	—	GGU6001U	—	A430	4347
GGJ6005A	VR126	—	—	GGU6001V	—	A430	4347
GGJ6005C	VR126	—	—	GGU6001W	—	A430	4347
GGJ6005D	VR126	—	—	GGU6002A	—	A430	4347
GGJ6008A	VR126	—	—	GGU6002B	—	A430	4347
GGJ6008B	VR126	—	—	GGU6002D	—	A430	4347
GGJ6101A	—	SD707	—	GGU6002S	—	A430	4347
GGJ6101C	—	SD707	—	GGU6002S1	—	A430	4347
GGJ6101S	—	SD707	—	GGU6004A	—	A430	—
GGJ6103A	VR126	—	—	GGU6004B	—	A430	—
GGM4801A	—	A409	4278	GGU6004C	—	A430	—
GGO4801	—	SD707	—	GGU6004D	—	A430	—
GGO4804	—	SD707	—	GGU6004S1	—	A430	—
GGO6001A	—	SD707	—	GGU6005A	—	A430	—
GGO6001S	VR126	A430	4347	GGU6005B	—	A430	—
GGO6001S1	VR126	A430	4347	GGU6005C	—	A430	—
GGO6001T	VR126	A430	4347	GGU6005S	—	A430	—
GGO6001U	VR126	A430	4347	GGU6005S1	—	A430	—
GGO6001V	VR126	A430	4347	GGU6006A	—	A430	—
GGO6001W	VR126	A430	4347	GGU6006AA	—	A430	—
GGP4801A	VR751	A430	4278	GGU6006B	—	A430	—
GGP4801B	VR751	A430	4278	GGU6006C	—	A430	—
GGP4801S	VR751	A430	4278	GGU6006D	—	A430	—
GGR4801A	—	A409	4278	GGU6006E	—	A430	—
GGS4801A	—	A430	4278	GGU6006F	—	A430	—
GGU4802S	—	A430	—	GGU6006G	—	A430	—
GGU5002	—	A430	4347	GGU6006GA	VR126	A430	—
GGU6001	VR126	—	—	GGU6006H	—	A430	—
GGU6001A	—	A430	4347	GGU6006J	—	A430	—
GGU6001B	—	A430	4347	GGU6006K	—	A430	—

(continued on next column)

(continued on next page)

¹¹ Negative ground ¹⁹ Positive ground

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
GGU6006S1 . . . —		A430	—
GGU6007A —		A430	—
GGU6007S —		A430	—
GGU6008A —		A430	4347
GGU6008B —		A430	4347
GGU6008C —		A430	4347
GGU6008D —		A430	4347
GGU6008S1 —		A430	4347
GGU6009A —		A430	4347
GGU6009B —		A430	4347
GGU6009C —		A430	4347
GGU6009D —		A430	4347
GGU6009S1 —		A430	4347
GGU6010B VR126		A430	—
GGU6012A —		A430	4347
GGU6012S1 —		A430	4347
GGU6013 VR126		—	—
GGU6013B —		A430	—
GGU6013C —		A430	—
GGU6013D —		A430	—
GGU6013E —		A430	—
GGU6013S1 —		A430	—
GGW60S1 VR27		A430	4347
GGW600S1 VR27		A430	—
GGW4801A VR27		—	4347
GGW4801B VR27		—	4347
GGW4801C VR27		—	4347
GGW4801D VR22 ¹¹		A430	4347
GGW4801D VR27 ¹⁹		A430	4347
GGW4801E VR22 ¹¹		—	4347
GGW4801E VR27 ¹⁹		—	4347
GGW4801EN . . . VR27 ¹⁹		A430	4347
GGW4801F VR22 ¹¹		—	4347
GGW4801F VR27 ¹⁹		—	4347
GGW4801S VR22 ¹¹		—	4347
GGW4801S VR27 ¹⁹		—	4347
GGW4802A VR25		—	4347
GGW4802B VR27		—	4347
GGW4802C VR27		—	4347
GGW4802S VR27		—	4347
GGW4803A VR27		—	4347
GGW6001A VR22 ¹¹		A430	4347
GGW6001A VR27 ¹⁹		A430	4347
GGW6001AB . . . VR22 ¹¹		A430	4347
GGW6001AB . . . VR27 ¹⁹		A430	4347
GGW6001AN . . . —		A430	4347
GGW6001AT . . . —		F404	4347
GGW6001AT1 . . . —		F404	4347
GGW6001B VR22 ¹¹		A430	4347

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
GGW6001B VR27 ¹⁹		A430	4347
GGW6001BF —		A430	4347
GGW6001C VR22 ¹¹		A430	4347
GGW6001C VR27 ¹⁹		A430	4347
GGW6001D VR27		A430	4347
GGW6001E VR25		A430	4347
GGW6001F VR25		A430	4347
GGW6001FFS1 . . . —		A430	4347
GGW6001G —		A430	4347
GGW6001H VR27		A430	4347
GGW6001HF —		A430	4347
GGW6001I VR27		A430	4347
GGW6001J VR27		A430	4347
GGW6001K VR27		A430	4347
GGW6001KF —		A430	4347
GGW6001L VR27		A430	4347
GGW6001P —		A430	4347
GGW6001P1 —		A430	4347
GGW6001Q VR22 ¹¹		A430	4347
GGW6001Q VR27 ¹⁹		A430	4347
GGW6001R VR22 ¹¹		A430	4347
GGW6001R VR27 ¹⁹		A430	4347
GGW6001S VR22 ¹¹		A430	4347
GGW6001S VR27 ¹⁹		A430	4347
GGW6001S1 —		F404	4347
GGW6001S1 . . . VR22 ¹¹		A430	4347
GGW6001S1 . . . VR27 ¹⁹		A430	4347
GGW6001S1N . . . —		A430	4347
GGW6001T —		F404	4347
GGW6001TS1 . . . —		—	4347
GGW6001V VR25		A430	4347
GGW6001W VR25		A430	4347
GGW6001W1 —		A430	4347
GGW6001X VR22 ¹¹		A430	4347
GGW6001X VR27 ¹⁹		A430	4347
GGW6001Y VR25		A430	4347
GGW6001Z VR27		A430	4347
GGW6002A VR27		A430	4347
GGW6002B VR27		A430	4347
GGW6002C VR27		A430	4347
GGW6002D VR27		A430	4347
GGW6002E VR27		A430	4347
GGW6002S VR27		A430	4347
GGW6002S1 . . . VR1071		A430	4347
GGW6003A VR25		A430	4347
GGW6003S VR25		A430	4347
GGW6007A VR27		A430	—
GGW6007B VR27		A430	—
GGW6007C VR27		A430	—

(continued on next page)

¹¹ Negative ground ¹⁹ Positive ground

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
GGW6007S1 ...	VR1071	A430	—
GGW6008B ...	VR27	A430	—
GGW6008BA ...	VR27	A430	—
GGW6008C ...	VR27	A430	—
GGW6008D ...	VR27	A430	—
GGW6008E ...	VR27	A430	—
GGW6008F ...	VR27	A430	—
GGW6008FA ...	VR27	A430	—
GGW6008G ...	VR27	A430	—
GGW6008H ...	VR27	A430	—
GGW6008J ...	VR27	A430	—
GGW6008K ...	VR27	A430	—
GGW6008L ...	VR27	A430	—
GGW6008P ...	VR27	A430	—
GGW6008S1 ...	VR27	A430	—
GGW6009A ...	VR27	A430	4347
GGW6009B ...	VR27	A430	4347
GGW6009S1 ...	VR27	A430	4347
GGW6010A ...	VR27	A430	4347
GGW6010B ...	VR27	A430	4347
GGW6010C ...	VR27	A430	4347
GGW6010S1 ...	VR27	A430	4347
GGW6011A ...	VR27	A430	—
GGW6011B ...	VR27	A430	—
GGW6011S1 ...	VR27	A430	—
GGW6012A ...	VR27	A430	4347
GGW6012B ...	VR27	A430	4347
GGW6012S1 ...	VR27	A430	4347
GGW6013A ...	VR27	A430	4347
GGW6013S1 ...	VR27	A430	4347
GGW6014A ...	VR27	A430	—
GGW6014A1 ...	VR22 ¹¹	A430	—
GGW6014A1 ...	VR27 ¹⁹	A430	—
GGW6014AA ...	VR27	A430	—
GGW6014AA1 ...	VR1071 ¹⁹	A430	—
GGW6014AA1 ...	VR126 ¹¹	A430	—
GGW6014B ...	VR27	A430	—
GGW6014E ...	VR27	A430	—
GGW6014S1 ...	VR22 ¹¹	A430	—
GGW6014S1 ...	VR27 ¹⁹	A430	—
GGW6016A ...	VR27	A430	—
GGW6016C ...	VR27	A430	—
GGW6016D ...	VR27	A430	—
GGW6016E ...	VR27	A430	—
GGW6016F ...	VR27	A430	—
GGW6016G ...	VR27	A430	—
GGW6016HA ...	VR27	A430	—
GGW6016S1 ...	VR27	A430	—
GGW6017A ...	VR27	A430	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
GGW6017B ...	VR27	A430	—
GGW6017S1 ...	VR27	A430	—
GGW6018A ...	—	A430	4347
GGW6019A ...	VR27	A430	4347
GGW6019S1 ...	VR27	A430	4347
GGW6020A ...	—	A430	—
GGW6022S ...	VR751	A430	—
GGW6601E ...	VR125	A430	—
GGW7102S ...	VR401	—	—
GGW7401A ...	VR27	A430	—
GGW7401S1 ...	VR27	A430	—
GGW7402A ...	VR22 ¹¹	—	—
GGW7402A ...	VR27 ¹⁹	—	—
GGW7402A1 ...	VR22 ¹¹	—	—
GGW7402A1 ...	VR27 ¹⁹	—	—
GGW7402B ...	VR27	A430	—
GGW7402C ...	VR27	A430	—
GGW7402S1 ...	VR22 ¹¹	—	—
GGW7402S1 ...	VR27 ¹⁹	—	—
GGW7403A ...	VR27	A430	—
GGW7403S1 ...	VR27	A430	—
GGW7404 ...	VR27	A430	—
GGW7404A ...	VR22 ¹¹	—	—
GGW7404A ...	VR27 ¹⁹	—	—
GGW7404AT ...	—	A430	—
GGW7404B ...	VR22 ¹¹	—	—
GGW7404B ...	VR27 ¹⁹	—	—
GGW7404BT ...	—	A430	—
GGW7404S ...	VR22 ¹¹	—	—
GGW7404S ...	VR27 ¹⁹	—	—
GGW7405S ...	VR22 ¹¹	—	—
GGW7405S ...	VR27 ¹⁹	—	—
GGW7406S ...	VR1071 ¹¹	—	—
GGW7406S ...	VR1071 ¹⁹	—	—
GGW7407A ...	—	A434	—
GGW7407S ...	—	A434	—
GGZ6001A ...	VR25	A430	4347
GGZ6001B ...	VR25	A430	4347
GGZ6001C ...	VR25	A430	4347
GGZ6001DM ...	—	A430	4347
GGZ6001M ...	—	A430	4347
GGZ6001S1 ...	VR25	A430	4347
GGZ6002A ...	VR126	A434	—
GGZ6003A ...	VR126	A430	4347
GGZ6004A ...	—	A430	—
GGZ7003A ...	—	A430	4347
GGZ7003S1 ...	—	A430	4347
GHB4801A ...	VR25	A430	4278
GHB4801B ...	VR25	A430	4278

(continued on next page)

¹¹ Negative ground ¹⁹ Positive ground

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
GHB4801C	VR25	A430	4278
GHB4801S1 ...	VR25	A430	4278
GHB4802A	VR750	A430	4278
GHB4802S1 ...	VR750	A430	4278
GHC6001AC ...	—	A409	4347
GHC6002A	—	A430	4347
GHC6002S1 ...	—	A430	4347
GHC6003A	—	—	4347
GHC6003B	—	A430	4347
GHC6003C	—	A430	4347
GHC6003S1 ...	—	—	4347
GHC6005A	—	A434	—
GHD6001A	—	A409	4347
GHD6001AA ...	—	A409	4347
GHD6001AB ...	—	A409	4347
GHD6001AB1 ..	—	A409	4347
GHD6001AC ...	—	A409	4347
GHD6001AC1 ..	—	A409	4347
GHD6001AD ...	—	A409	4347
GHD6001AF ...	—	A409	4347
GHD6001AG ...	—	A409	4347
GHD6001AH ...	—	A409	4347
GHD6001B	—	A409	4347
GHD6001B1 ...	—	A409	4347
GHD6001C	—	A409	4347
GHD6001D	—	A409	4347
GHD6001D1 ...	—	A409	4347
GHD6001E	—	A409	4347
GHD6001F	—	A409	4347
GHD6001G	—	A409	4347
GHD6001H	—	A409	4347
GHD6001I	—	A409	4347
GHD6001J	—	A409	4347
GHD6001K	—	A409	4347
GHD6001L1 ...	—	A409	4347
GHD6001O1 ...	—	A409	4347
GHD6001P	—	A409	4347
GHD6001Q	—	A409	4347
GHD6001Q1 ...	—	A409	4347
GHD6001R	—	A409	4347
GHD6001SS ...	—	A409	4347
GHD6001SSN ..	—	A409	4347
GHD6001V	—	A409	4347
GHD6001W	—	A409	4347
GHD6001X	—	A409	4347
GHD6001Y	—	A409	4347
GHD6001YH ...	—	A409	4347
GHD6001Z	—	A409	4347
GHD6002A	—	A409	4347

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
GHD6002B	—	A409	4347
GHD6002S	—	A409	4347
GHF6001AM ...	—	A430	4347
GHF6001BM ...	—	A430	4347
GHF6001MS1 ..	—	A430	4347
GHG6001AT ...	—	—	4347
GHG6001C	—	A430	4347
GHG6001CT ...	—	—	4347
GHG6001D	—	A430	4347
GHG6002AT ...	—	—	4347
GHG7001A	—	A434	—
GHG7001B	—	A434	—
GHH6001A	VR899	A409	4347
GHH6001B	—	A409	4347
GHH6001C	—	A409	4347
GHH6001D	VR899	A409	4347
GHH6001E	—	A409	4347
GHH6001E1 ...	VR899	A409	4347
GHH6001F	—	A409	4347
GHH6001F1 ...	VR899	A409	4347
GHH6001G	—	A409	4347
GHH6001H	—	A409	4347
GHH6001H1 ...	—	A409	4347
GHH6001J	—	A409	4347
GHH6001K	VR899	A409	4347
GHH6001L	—	A409	4347
GHH6001S	—	A409	4347
GHH6001SN ...	—	A409	4347
GHH6002A	—	A409	4347
GHH6002B	—	A409	4347
GHH6002C	—	A409	4347
GHH6002S	—	A409	4347
GHH6002SN ...	—	A409	4347
GHH6003A	—	A409	—
GHH6004	—	A409	4347
GHH6004A	—	A409	4347
GHH6004S	—	A409	4347
GHH6005A	—	—	4347
GHK6001A	VR25	A430	4347
GHK6002A	—	A430	—
GHM6001E	VR206	—	4347
GHM6001F	VR206	A430	—
GHM6001S1 ...	VR206	—	4347
GHM6002	—	A430	—
GHM6002A	VR206	—	—
GHM6002D	VR206	—	—
GHM6002E	VR206	—	—
GHM6002S1 ...	VR206	—	—
GHM6003A	VR126	A434	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
GHM6003B	VR206	—	—
GHM6003C	VR206	—	—
GHM6003D	VR206	—	—
GHM6003SN1 ..	VR206	—	—
GHM6004	VR206	A430	—
GHM6004A	VR206	—	—
GHM6004B	VR206	—	—
GHM6004C	VR206	—	—
GHM6004D	VR206	—	—
GHM6004E	VR206	—	—
GHM6004F	VR206	—	—
GHM6004G	VR206	—	—
GHM6004H	VR206	—	—
GHM6004K	VR206	—	—
GHM6004L	VR206	—	—
GHM6004NS ...	VR206	—	—
GHM6004P	VR206	—	—
GHM6004S	VR206	—	—
GHM6004S1 ...	VR206	—	—
GHM6004SN ...	VR206	—	—
GHM6007A	VR206	—	—
GHM6007B	VR206	—	—
GHM6007C	VR206	—	—
GHM6007S1 ...	VR206	—	—
GHM6008A	VR206	—	4347
GHM6008S1 ...	VR206	—	4347
GHM6009	VR206	A430	4347
GHM6009A	VR206	—	4347
GHM6009S1 ...	VR206	—	4347
GHM6010A	VR206	—	4347
GHM6010B	VR206	—	4347
GHM6010C	VR206	—	4347
GHM6010S1 ...	VR206	—	4347
GHM6011A	VR206	—	—
GHM6011S1 ...	VR206	—	—
GHM6012	VR206	—	—
GHM6012A	VR206	—	—
GHM6012B	VR206	—	—
GHM6012GA ...	VR206	—	—
GHM6012S1 ...	VR206	—	—
GHM6013	VR206	—	—
GHM6013A	VR206	—	—
GHM6013S1 ...	VR206	—	—
GHM6014AS1 ..	VR206	—	4347
GHM6015A	VR206	—	—
GHM6015B	VR206	—	—
GHM6015C	VR206	—	—
GHM6015D	VR206	—	—
GHM6015E	VR206	A434	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
GHM6015G	VR206	—	—
GHM6015S1 ...	VR206	—	—
GHM6016S	VR206	—	—
GHM6017A	VR206	—	—
GHM6018A	—	A434	—
GHM8001	VR206	—	—
GHM8001A	VR206	—	—
GHM8001B	VR206	—	—
GHM8001S1 ...	VR206	—	—
GHM8002A	VR206	—	—
GHM8002B	VR206	—	—
GHM8002S1 ...	VR206	—	—
GHM8004A	VR206	—	4347
GHM8004S1 ...	VR206	—	4347
GHM8005A	VR206	—	4347
GHM8005S1 ...	VR206	—	4347
GHM8006A	VR206	—	4347
GHM8006B	VR206	—	4347
GHM8006S1 ...	VR206	—	4347
GHP6002AT ...	—	—	4347
GHP6002AT1 ..	—	—	4347
GHP6002BT ...	—	—	4347
GHP6002CTN ...	—	—	4347
GHP6002TS1 ..	—	—	4347
GHP60021	—	—	4347
GHR4801M	—	A430	4347
GHR4801NM ...	—	A430	4347
GHR4802M	—	A430	4347
GHR4802NM ...	—	A430	4347
GHS6002AT ...	—	A439	—
GHS6002BT ...	—	A439	—
GHS6002CT ...	—	A439	—
GHS6002DT ...	—	A439	—
GHS6002ET ...	—	A439	—
GHS6002FT ...	—	A439	—
GHS6002GT ...	—	A439	—
GHS6002TS ...	—	A439	—
GHU4801M	—	A430	4347
GHU4801N	—	A430	4347
GHU4801NM ...	—	A430	4347
GHU4802M	—	A430	4347
GHU4802NM ...	—	A430	4347
GHW4801M	—	A430	4347
GHW4801NM ...	—	A430	4347
GHW4802M	—	A430	4347
GHW4802NM ...	—	A430	4347
GHW4803	—	A430	4347
GHW4804	—	A430	4347
GHW4805	—	A430	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
GHW4806	—	A430	—
GHW4807	—	A430	—
GHW4808	—	A430	—
GHW4809	—	—	4347
GHW4810	—	—	4347
GHX4801M	—	A430	4347
GHX4801NM	—	A430	4347
GHX4802M	—	A430	4347
GHX4802NM	—	A430	4347
GHX4803	—	—	4347
GHX4804	—	A430	4347
GJB6001A	VR25	—	—
GJC6001A	VR206	—	4347
GJC6002A	—	A430	4347
GJC6002S1	—	A430	4347
GJC6003S1	VR206	—	—
GJC7001A	VR206	—	—
GJC7001B	VR206	—	—
GJC7001C	VR206	—	—
GJC7001D	VR206	—	—
GJC7001E	VR206	—	—
GJC7001S1	VR206	—	—
GJC7002	VR206	—	—
GJC7002A	VR206	—	—
GJC7002B	VR206	—	—
GJC7002C	VR206	—	—
GJC7002D	VR206	—	—
GJC7002E	VR206	—	—
GJC7002F	VR206	—	—
GJC7002G	VR206	—	—
GJC7002H	VR206	—	—
GJC7002I	VR206	—	—
GJC7002J	VR206	—	—
GJC7002K	VR206	—	—
GJC7002L	VR206	—	—
GJC7002S	VR206	—	—
GJC7002S1	VR206	—	—
GJC7003A	VR206	A434	—
GJC7003AA	VR206	A434	—
GJC7003AS1	VR206	—	—
GJC7003B	VR206	A434	—
GJC7003BA	VR206	A434	—
GJC7003C	VR206	A434	—
GJC7003CA	VR206	A434	—
GJC7003D	VR206	A434	—
GJC7003E	VR206	A434	—
GJC7003EA	VR206	A434	—
GJC7003F	VR206	A434	—
GJC7003G	VR206	A434	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
GJC7003H	VR206	A434	—
GJC7003S1	VR206	A434	—
GJC7004	VR206	A434	—
GJC7004A	VR206	—	—
GJC7004S1	VR206	—	—
GJC7005	VR206	A434	—
GJC7005A	VR206	—	—
GJC7005B	VR206	—	—
GJC7005S1	VR206	—	—
GJC7006A	VR206	—	—
GJC7006B	VR206	—	—
GJC7006C	VR206	—	—
GJC7006S1	VR206	—	—
GJC7007A	VR206	—	—
GJC7007B	VR206	—	—
GJC7007S	VR206	—	—
GJC7008A	VR206	—	—
GJC7008B	VR206	—	—
GJC7009A	VR206	—	—
GJC7009B	VR206	—	—
GJC7009BA	VR206	—	—
GJC7009C	VR206	—	—
GJC7009CA	VR206	—	—
GJC7009S1	VR206	—	—
GJC7010	VR206	A434	—
GJC7010A	VR206	—	—
GJC7010S1	VR206	—	—
GJC7011A	VR206	—	—
GJC7011S	VR206	—	—
GJC7012	VR206	A434	—
GJC7012A	VR206	—	—
GJC7012B	VR206	—	—
GJC7012C	VR206	—	—
GJC7012D	VR206	—	—
GJC7012E	VR206	—	—
GJC7012F	VR206	—	—
GJC7012S1	VR206	—	—
GJC7013A	VR206	—	—
GJC7013B	VR206	—	—
GJC7013S1	VR206	—	—
GJC7014	VR206	A434	—
GJC7014A	VR206	A430	—
GJC7014B	VR206	A430	—
GJC7014S1	VR206	A430	—
GJC7016A	VR206	—	—
GJC7017A	—	A434	—
GJC7017B	—	A434	—
GJC7017C	—	A434	—
GJC7017D	—	A434	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
GJC7017E	—	A434	—
GJC7017S1	—	A434	—
GJC7018A	—	A434	—
GJC7019A	—	A434	—
GJC7101S	VR414	—	—
GJC7102S	VR414	—	—
GJC7401B	—	A434	—
GJC7401BT	—	A434	—
GJC7401S	VR206	—	—
GJC7401S1	—	A434	—
GJC7401TS1	—	A434	—
GJC7402S	VR126	A434	—
GJC7403S	VR122	—	—
GJC7404S	VR122	—	—
GJC7501A	—	A434	—
GJC7501S	—	A434	—
GJC8001A	VR206	—	—
GJC8001S1	VR206	—	—
GJD6001A	—	A430	—
GJF6001AM	—	A430	4347
GJF6001MS1	—	A430	4347
GJH6001A	—	—	4347
GJK7001A	—	A434	—
GJK7001AN	—	A430	—
GJK7001B	—	A434	—
GJK7001C	—	A434	—
GJK7001S	—	A434	—
GJK7001SN	—	A430	—
GJK7002A	—	A434	—
GJK7104GN	—	A434	—
GJL7001A	VR899	A434	—
GJL7001AN	VR899	A434	—
GJL7001B	VR899	A434	—
GJL7001C	—	A434	—
GJL7001EN	VR899	A434	—
GJL7001S	VR899	A434	—
GJL7001SN	VR899	A434	—
GJL7002A	VR899	A434	—
GJL7002B	VR899	A434	—
GJL7003A	—	A434	—
GJL7003BT	—	A434	—
GJM6004D	VR206	A434	—
GJM7001	VR206	—	—
GJM7001A	VR206	—	—
GJM7001B	VR206	—	—
GJM7001C	VR206	—	—
GJM7001D	VR206	—	—
GJM7001E	VR206	—	—
GJM7001F	VR206	A434	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
GJM7001S1	—	A434	—
GJM7002A	VR206	A430	—
GJM7002B	VR206	—	—
GJM7002C	VR206	—	—
GJM7002D	VR206	A430	—
GJM7002S1	VR206	A430	—
GJM7003A	VR206	—	—
GJM7003AA	VR206	—	—
GJM7003B	VR206	—	—
GJM7003BA	VR206	—	—
GJM7003C	VR206	—	—
GJM7003D	VR206	—	—
GJM7003DA	VR206	—	—
GJM7003S1	VR206	—	—
GJM7004S	VR206	—	—
GJM7004S1	VR206	—	—
GJM7005A	VR206	—	—
GJM7005S1	VR206	—	—
GJM7301S	—	A434	—
GJM7302S	—	A434	—
GJM7401A	VR206	A434	—
GJM7401B	VR206	A434	—
GJM7401C	VR206	A434	—
GJM7401D	VR206	A434	—
GJM7402A	VR206	A430	—
GJM7402B	VR206	A430	—
GJM7402C	VR206	A430	—
GJM7402S1	VR206	A430	—
GJM7403A	VR206	—	—
GJM7403B	VR206	—	—
GJM7403C	VR206	—	—
GJM7403D	VR206	—	—
GJM7403S1	VR206	—	—
GJM7404A	VR206	—	—
GJM7404S1	VR206	—	—
GJM8001A	VR206	—	—
GJM8001S1	VR206	—	—
GJM8002A	VR206	—	—
GJM8002S1	VR206	—	—
GJM8201A	VR206	—	—
GJM8201S1	VR206	—	—
GJM8202A	VR206	—	—
GJM8202S1	VR206	—	—
GJM8203A	VR206	A434	—
GJM8203S1	VR206	A434	—
GJO7101A	VR208	—	—
GJO7101S	VR208	—	—
GJO7102S	—	A434	—
GJO7105A	VR208	A430	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing	Unit No	Voltage Regulator	Brush Set	Bushing
GJO7301S	—	A434	—	GJT7101H	—	A430	—
GJO7302S	—	A434	—	GJT7101HT	—	A434	—
GJO7402A	—	A434	—	GJT7101N	—	A434	—
GJO7402S	—	A434	—	GJT7101S	—	A434	—
GJO7403A	—	A434	—	GJT7101SN	—	A434	—
GJO7501A	—	A434	—	GJT7103A	VR899	A434	—
GJO7501C	—	A434	—	GJT7103AN	VR899	A434	—
GJO7501D	—	A434	—	GJT7103B	—	A430	—
GJO7501S	—	A434	—	GJT7103C	—	A430	—
GJP7101A	VR208	—	—	GJT7103D	—	A430	—
GJP7101S	VR208	—	—	GJT7103F	—	A430	—
GJP7102C	VR208	A434	—	GJT7103FN	VR899	A434	—
GJP7102S	VR208	A434	—	GJT7103S	—	A430	—
GJP7103A	VR208	A434	—	GJT7103SN	—	A430	—
GJP7103B	VR208	A434	—	GJT7104	—	A430	—
GJP7103S	VR208	A434	—	GJT7104A	VR208	—	—
GJP7202A	VR206	—	—	GJT7104B	—	A430	—
GJP7202B	VR206	—	—	GJT7104S	—	A430	—
GJP7202D	VR122	—	—	GJT7104SN	—	A430	—
GJP7202S	—	A434	—	GJT7106A	—	A434	—
GJP7203A	VR208	A434	—	GJT7106B	—	A434	—
GJP7401A	VR206	—	—	GJT7106S	—	A434	—
GJP7402A	VR206	—	—	GJT7106SN	—	A434	—
GJP7402B	VR206	—	—	GJT7301A	—	A430	—
GJP7402C	—	A434	—	GJT7301B	—	A430	—
GJP7402D	VR206	—	—	GJT7301EN	—	A434	—
GJP7402E	VR122	—	—	GJT7301F	—	A434	—
GJP7402S	—	A434	—	GJT7301S	—	A434	—
GJP7403A	VR206	—	—	GJT7301SN	—	A434	—
GJP7404AT	—	A434	—	GJT7301SN1	VR208	—	—
GJP7405A	VR122	—	—	GJT7303C	—	A434	—
GJP7405S	VR122	—	—	GJT7303D	—	A434	—
GJS7002	—	A434	—	GJT7303E	—	A434	—
GJS7002N	—	A434	—	GJT7303J	—	A434	—
GJS7101B	—	A430	—	GJT7303S	—	A434	—
GJS7101BN	—	A430	—	GJT7303SN	—	A434	—
GJS7101DN	—	A430	—	GJT7304A	—	A434	—
GJS7101FN	—	A430	—	GJT7304B	—	A434	—
GJS7101H	—	A430	—	GJT7306SN	—	A434	—
GJS7103F	—	A430	—	GJT7403A	—	A434	—
GJS7103S	—	A430	—	GJT7403N	—	A434	—
GJS7106A	—	A430	—	GJT7403SN	—	A434	—
GJS7106B	—	A430	—	GJT7404A	—	A434	—
GJS7304A	—	A430	—	GJT7404B	—	A434	—
GJT7101C	VR208	—	—	GJT7404S	—	A434	—
GJT7101DN	VR208	A434	—	GJT7405A	VR899	A434	—
GJT7101E	—	A434	—	GJT7405AN	VR899	A434	—
GJT7101FN	VR208	A434	—	GJT7405BN	VR899	A434	—
GJT7101GN	VR208	A434	—	GJT7405S	VR899	A434	—

(continued on next column)

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing	Unit No	Voltage Regulator	Brush Set	Bushing
GJT71014B	—	A430	—	GJW7302S	—	A430	—
GJT71014BN . . .	—	A430	—	GJW7305A	—	A434	—
GJU7101B	—	A434	—	GJW7401A	—	A434	—
GJU7101S	—	A434	—	GJW7401S	—	A434	—
GJU7104A	—	A434	—	GJW7501A	—	A434	—
GJU7104B	—	A434	—	GJW7501S	—	A434	—
GJU7104S	—	A434	—	GJW7501SS	—	A434	—
GJU7202A	—	A434	—	GJY7401S	—	A434	—
GJU7203A	—	A434	—	GJY7401SN	—	A434	—
GJU7204S	—	A434	—	GJZ7501	—	A434	—
GJU7301A	—	A434	—	GJZ7502	—	A434	—
GJU7302A	—	A434	—	GKB7101S	VR401	A430	—
GJU7303A	—	A434	—	GKC7401S	VR122	—	—
GJU7303B	—	A430	—	GKC7402S	VR122	—	—
GJU7303S	—	A434	—	GKD7401S	VR1071	A430	—
GJU7501	—	A434	—	GKE7301	—	A434	—
GJU7502	—	A434	—	GKE7302	—	A434	—
GJU7503A	—	A434	—	GKH7101A	—	A434	—
GJU7503B	—	A434	—	GKH7101AT	—	A434	—
GJU7503S1	—	A434	—	GKJ7103AN	VR899	A434	—
GJU7505A	—	A434	—	GKJ7103F	VR899	A434	—
GJU7505B	—	A434	—	GKJ7103FN	VR899	A434	—
GJU7505S1	—	A434	—	GKJ7103SN	VR899	A434	—
GJU7506A	—	A434	—	GKJ7104A	VR899	A434	—
GJU7507A	—	A434	—	GKJ7104F	VR899	A434	—
GJW7101B	—	A434	—	GKJ7104FN	VR899	A434	—
GJW7101D	—	A434	—	GKJ7104SN	VR899	A434	—
GJW7101S	—	A434	—	GKJ7201A	VR899	A434	—
GJW7301A	—	A434	—	GKJ7201B	—	A430	—
GJW7301AN	VR204	A430	—	GKJ7201S	VR899	A434	—
GJW7301B	—	A430	—	GKJ7302S	—	A434	—
GJW7301C	—	A430	—	GKJ7303E	—	A434	—
GJW7301D	—	A430	—	GKJ7303J	—	A434	—
GJW7301DN	VR204	A430	—	GKJ7303L	—	A434	—
GJW7301E	—	A430	—	GKJ7303S	—	A434	—
GJW7301F	—	A430	—	GKJ7303SN	—	A434	—
GJW7301FH	VR204	A430	—	GKJ7303U	—	A430	—
GJW7301FN	VR204	A430	—	GKJ7305A	—	A434	—
GJW7301G	—	A430	—	GKJ7305B	—	A434	—
GJW7301HN	VR204	A430	—	GKJ7305S	—	A434	—
GJW7301J	VR204	A430	—	GKS7101S1	—	A434	—
GJW7301JN	VR204	A430	—	GKS7401S	—	A434	—
GJW7301KN	VR204	A430	—	GMC7402S	—	A434	—
GJW7301N	—	A434	—	GNZ6001H	VR25	—	—
GJW7301S	—	A434	—	INC10000	—	F404	4283
GJW7301SN	—	A434	—				
GJW7302A	—	A430	—				
GJW7302B	—	A430	—				

(continued on next column)

BOSCH

Unit No	Voltage Regulator	Brush Set	Bushing
0020600002 ...	—	E550	—
0101202022 ...	—	E450	—
0101202023 ...	—	E450	—
0101203008 ...	—	E450	—
0101206008 ...	—	E450	—
0101206009 ...	—	E450	—
0101206010 ...	—	E450	—
0101206011 ...	—	E450	—
0101206012 ...	—	E450	—
0101206030 ...	—	E450	—
0101206057 ...	—	E450	—
0101206058 ...	—	E450	—
0101206059 ...	VR502	E450	—
0101206060 ...	—	E450	—
0101206061 ...	—	E450	—
0101206062 ...	VR502	E450	—
0101206063 ...	—	E450	—
0101206067 ...	VR502	—	—
0101206076 ...	—	E450	—
0101206084 ...	—	E450	—
0101206087 ...	—	E450	—
0101206096 ...	—	E450	—
0101206099 ...	—	E450	—
0101206100 ...	—	E450	—
0101206102 ...	—	E450	—
0101206103 ...	—	E450	—
0101206113 ...	—	E450	—
0101206116 ...	VR502	E450	—
0101206120 ...	—	E450	—
0101206139 ...	—	E450	—
0101206140 ...	—	E450	—
0101206141 ...	—	E450	—
0101207005 ...	VR502	—	—
0101209031 ...	—	E450	—
0101209032 ...	—	E450	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
0101209036 ...	—	E450	—
0101209041 ...	—	E450	—
0101209060 ...	—	E450	—
0101209065 ...	—	E450	—
0101212001 ...	VR500	E450	—
0101212004 ...	VR500	E450	—
0101212006 ...	VR500	E450	—
0101212007 ...	—	E450	—
0101302022 ...	—	E451	—
0101302023 ...	—	E451	—
0101302029 ...	—	E451	—
0101302035 ...	—	E451	—
0101302067 ...	VR502	E452	—
0101302069 ...	VR502	—	—
0101302075 ...	VR502	E452	—
0101302083 ...	VR502	E452	—
0101302085 ...	VR502	E452	—
0101302089 ...	VR502	E451	—
0101302101 ...	VR502	E451	—
0101302102 ...	VR502	E451	—
0101302105 ...	—	E451	—
0101302111 ...	VR502	E452	—
0101302112 ...	VR502	E452	—
0101302113 ...	VR502	E451	—
0101302114 ...	VR502	E451	—
0101302117 ...	VR502	E452	—
0101304001 ...	—	E451	—
0101304007 ...	—	E451	—
0101304008 ...	—	E451	—
0101356005 ...	—	E451	—
0101356013 ...	—	E451	—
0101356014 ...	—	E451	—

CHRYSLER

Unit No	Voltage Regulator	Brush Set	Bushing
E71258M61M ..	—	A430	—
595316	—	A430	—
853770	VR25	A430	4264
1113853	VR27	A430	4347
1123538	—	A430	4264
1123539	—	A430	4264
1136923	VR25	A430	4264
1136930	—	—	4347
1136931	—	—	4347

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1136934	—	A430	4264
1138506	—	A430	—
1138509	—	A430	—
1194650	—	—	4264
1194652	—	—	4264
1257391	VR27	A430	4347
1257392	VR27	A430	4264
1262334	—	A430	4347
1263487	—	—	4347

(continued on next page)

CHRYSLER (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1263489	—	—	4347
1263554	—	—	4347
1263561	—	A430	4347
1263563	—	A430	4347
1263971	VR27	A430	4347
1263972	VR27	A430	4347
1263975	VR27	A430	4347
1264054	VR25	A430	4347
1264923	VR25	A430	4347
1264951	—	—	4347
1264965	VR27	A430	4347
1264985	—	A430	4347
1311468	VR27	A430	4347
1311471	—	A430	—
1321751	VR25	A430	4347
1321752	—	A430	4347
1323900	VR750	A430	4264
1323901	VR750	A430	—
1323917	—	A430	—
1323918	—	A430	—
1343230	—	A430	4347
1343231	VR27	A430	4347
1343232	—	—	4347
1343233	—	—	4347
1343235	—	A430	4347
1343236	VR27	A430	4347
1370319	—	—	4347
1383531	VR27	A430	4347
1390077	—	—	4347
1390456	VR25	A430	4347
1391185	—	—	4347
1391994	—	—	4347
1393795	VR27	A430	4347
1394998	VR27	A430	4347
1440393	—	—	4347
1440394	—	A430	4264
1440395	VR27	A430	4347
1473026	VR27	A430	4264
1473212	—	A430	4347
1479175	VR27	A430	4264
1479729	—	A430	4347
1479730	—	A430	4347
1495199	—	A430	4347
1502704	—	A430	4347
1504760	VR27	A430	4264
1504820	VR27	A430	4264
1505367	VR27	A430	4347
1505824	VR27	A430	4347
1505910	—	A430	4347

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1505917	—	A430	4347
1505918	—	—	4347
1505925	—	A430	4347
1505927	—	—	4347
1505929	VR25	A430	—
1505981	VR25	A430	—
1506279	VR25	A430	4347
1506281	VR25	A430	4347
1506302	VR25	A430	4347
1506324	VR25	A430	4347
1507515	VR27	A430	4347
1507928	—	A430	4347
1527328	VR27	A430	4347
1527330	VR27	A430	4347
1535579	—	A430	4347
1535591	—	A430	4347
1540596	VR27	A430	4264
1540597	VR27	A430	4264
1540640	—	A430	4347
1540817	VR27	A430	4347
1540820	VR27	A430	4264
1550576	VR27	A430	4347
1550577	VR27	A430	4347
1550609	—	A430	4347
1550610	—	A430	4347
1553022	—	A430	4347
1553023	—	A430	4347
1553025	—	A430	4347
1553026	—	A430	4347
1558152	—	A430	4278
1565784	VR27	A430	4347
1565786	VR27	A430	4347
1565787	VR27	A430	4347
1565820	—	A430	4347
1565827	—	A430	4347
1565879	VR27	A430	4264
1565880	—	A430	4347
1565882	—	A430	4347
1565884	—	A430	4347
1565885	—	—	4347
1565887	—	—	4347
1565889	—	—	4347
1565891	VR27	A430	4347
1565893	—	A430	4347
1565894	—	A430	4347
1566014	VR27	A430	4347
1566015	—	—	4347
1566016	—	—	4347
1566044	VR27	A430	4264

(continued on next page)

CHRYSLER (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1566045	VR27	A430	4347
1566355	VR206	—	—
1566356	VR206	—	—
1566365	—	A430	4264
1566367	VR27	A430	4264
1566368	VR27	A430	4264
1568355	VR206	—	4347
1568356	VR206	—	4347
1569175	VR206	—	4264
1569177	VR206	—	4264
1569179	VR206	A434	4264
1569180	VR206	—	4347
1569181	VR206	—	4347
1569182	VR206	—	—
1569186	VR206	—	4264
1569272	VR27	A430	4264
1569860	VR206	—	4264
1569861	VR206	—	4264
1569862	VR206	—	4264
1594518	—	—	4347
1594519	—	—	4347
1595104	—	—	4347
1595115	—	A430	4347
1604805	VR126	A430	—
1604825	—	A430	4347
1604826	VR27	A430	4264
1604829	VR27	A430	4264
1604830	VR27	A430	4264
1604831	VR27	A430	4264
1604834	VR27	A430	4347
1604839	—	A430	4264
1604840	—	A430	4264
1604843	VR27	—	4264
1604844	VR27	—	4264
1604849	VR27	—	4264
1604869	VR27	A430	4347
1604875	—	A430	4264
1605146	—	—	4347
1605400	VR27	A430	4264
1605401	VR27	A430	4264
1605402	VR27	A430	4264
1610364	—	A430	4347
1610366	—	A430	4347
1610368	—	A430	4347
1612703	—	A430	4347
1612704	—	A430	4347
1616642	—	A430	4347
1616643	—	A430	4347
1616644	—	A430	4347

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1616645	—	A430	4347
1642001	VR206	—	4264
1642002	VR206	—	4264
1642003	VR206	—	4264
1642004	VR206	—	4264
1642005	VR206	—	4264
1642006	VR206	—	4264
1642007	VR206	—	4264
1642008	VR206	—	4264
1642009	VR206	—	4264
1642010	VR206	—	4264
1642011	VR206	—	4264
1658858	VR204	—	4347
1658859	VR204	—	4347
1658860	VR204	—	—
1658861	VR206	—	4347
1658862	VR204	—	4347
1658863	VR204	—	4347
1658864	VR204	—	4347
1658865	VR204	—	4264
1658866	VR204	—	4264
1658867	VR204	—	4264
1658868	VR204	—	4264
1661773	VR204	—	4347
1662139	VR204	—	—
1662140	VR204	—	4347
1662141	VR204	—	4347
1662142	VR204	—	4347
1662143	VR204	—	4347
1662144	VR204	—	4347
1662145	VR206	—	4264
1662146	VR204	—	4264
1662147	VR204	—	4264
1662148	VR204	—	4264
1662149	VR204	—	4264
1662150	VR206	—	4264
1662151	VR206	—	4264
1662152	VR206	—	4264
1662153	VR206	—	4347
1662154	VR206	—	4347
1662155	VR204	—	4347
1663097	VR204	—	4347
1663184	VR204	—	4264
1665102	VR206	A430	4264
1665103	VR206	A430	4264
1665104	VR206	A430	4264
1665108	VR206	A430	4347
1665109	VR206	A430	4347
1665110	VR206	A430	4347

(continued on next page)

CHRYSLER (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1665111	VR206	A430	4347
1672790	—	A430	—
1672792	VR750	A430	—
1677529	VR27	A430	4347
1688652	VR206	—	4264
1689328	VR206	—	4264
1689329	VR206	—	4264
1704264	VR206	—	4264
1704265	VR206	—	4264
1704266	VR206	—	4264
1704267	VR206	A430	4264
1704268	VR206	A430	4264
1704269	VR206	A430	4264
1704272	VR206	A430	4264
1704273	VR206	A430	4264
1704279	VR206	A430	4264
1753624	VR206	A430	4264
1753625	VR206	A430	4347
1753670	VR204	—	4347
1770739	VR204	—	4347
1770740	VR204	—	4347
1770747	VR206	A430	4347
1770748	VR206	A430	4347
1770754	VR206	—	4264
1770755	VR206	—	4264
1779945	VR206	—	4264
1779946	VR206	—	4264
1779959	VR206	A430	4264
1779960	VR206	A430	4264
1779961	VR204	—	4347
1787869	VR206	A430	4264
1787870	VR206	—	4264
1787871	VR206	A430	4264
1787873	VR206	—	4264
1787874	VR206	—	—
1787875	VR206	—	4264
1787876	VR206	—	4264
1787929	VR206	—	4264
1787930	VR206	—	4264
1787931	VR206	—	4264
1787932	VR206	—	4264
1793795	VR206	A430	4264
1796326	VR206	—	4264
1796328	VR206	—	4264
1798590	VR206	A430	4264
1798591	VR204	—	4264
1798592	VR206	A430	4264
1798760	VR206	—	4264
1798766	VR206	—	4347

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1798767	VR206	—	4347
1799445	VR206	—	4264
1841509	VR204	—	4347
1842597	VR206	—	4347
1842598	VR206	—	4347
1842601	VR206	—	4264
1842603	VR204	—	—
1842606	VR204	—	—
1842608	VR750	A430	4347
1842609	VR750	A430	4347
1842770	VR206	—	4264
1842771	VR206	—	4264
1842772	VR206	—	4264
1842773	VR206	—	—
1842774	VR206	—	4264
1842775	VR206	—	4347
1842776	VR206	—	4347
1842778	VR206	—	4347
1842779	VR206	—	4264
1842780	VR206	—	4264
1842784	VR206	—	4264
1842785	VR206	—	4264
1842791	VR206	—	4264
1842794	VR206	—	4264
1842797	VR206	—	4264
1842800	VR206	—	4264
1842801	VR206	—	4264
1889400	VR206	—	4264
1889481	—	A430	4347
1889483	—	A430	4347
1889827	—	A430	4347
1889829	—	A430	4347
1889947	VR204	—	4264
1920845	VR206	—	4347
1920863	VR206	—	—
1920863C	VR206	A434	—
1920864	VR206	—	4264
1920866	VR206	—	4264
1920867	VR206	—	4264
1920876	VR206	—	4347
1920877	VR206	—	4347
1921887	VR206	—	4347
1941108	VR204	—	—
1941109	VR204	—	—
1941110	VR204	—	—
2095000	VR32	M400	—
2095060	VR32	M400	—
2095070	VR206	—	4264
2095072	VR206	—	4264

(continued on next page)

CHRYSLER (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
2095074	VR206	—	—
2095075	VR206	—	4264
2095100	VR32	M400	—
2095280	VR206	—	4347
2095286	VR206	—	4264
2095287	VR206	—	4264
2095290	VR206	—	—
2095293	VR206	—	—
2095294	VR206	—	—
2095295	VR206	—	—
2095300	VR32	M400	—
2095320	VR32	M400	—
2095325	VR206	—	4264
2095326	VR206	—	4264
2095348	VR206	—	4264
2095353	VR206	—	4264
2095355	VR206	—	4264
2095364	VR204	A430	—
2095365	VR204	A430	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
2095417	VR206	—	—
2095418	VR206	—	—
2095497	VR206	—	—
2095498	VR206	—	—
2095826	VR204	A430	4264
2095827	VR204	A430	4264
2098082	VR206	A434	—
2098794	VR204	A430	4264
2098907	VR206	A430	4264
2098908	VR206	A430	4264
2444930	VR27	A430	—
2444931	VR27	A430	—
2444932	VR27	A430	—
2444933	VR27	A430	—
2444953	VR206	—	—
2444956	VR206	—	—
2642688	—	A430	—
2642689	—	A430	—

DELCO REMY

Unit No	Voltage Regulator	Brush Set	Bushing
3U	VR122 ^{19,1}	R423	5242
3U	VR123 ^{11,1}	R423	5242
4U	VR1071 ¹¹	R413	—
4U	VR56 ¹¹	R413	—
5U	VR122	R423	5242
7U	VR56	R413	—
8U	VR1071 ^{11,6}	R413	5242
8U	VR56 ^{11,24}	R413	5242
9U	VR56	R413	—
10U	VR122	R423	5242
12U	VR122	R423	5242
13U	VR122	R423	5242
15U	VR126	R423	—
16U	VR122	R423	—
18U	VR1071 ¹¹	R423	5242
18U	VR1071 ¹⁹	R423	5242
21U	VR122	R423	5242
22U	VR128	R423	—
23U	VR128	R423	—
24U	VR126 ¹⁷	R423	—
24U	VR128 ⁶	R423	—
26U	VR128	R423	—
27U	VR122 ¹	R423	—
27U	VR128 ⁶	R423	—
28U	—	R423	5242

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
32U	VR122	R423	—
34U	VR122 ¹	R423	—
34U	VR126 ¹⁷	R423	—
35U	—	R423	—
36U	—	R423	—
37U	—	R423	—
38U	—	R423	—
39U	—	R423	—
40U	VR122 ¹	R423	—
40U	VR126 ¹⁷	R423	—
41U	—	R423	—
50D	—	R426	—
50DH	—	R419	—
50DT	—	R1001	5242
50UT	—	R423	—
51D	—	R426	—
51DT	VR146 ²²	R404	5242
51DT	VR850	R404	5242
51UT	—	R423	—
52D	VR140	R426	—
52D	VR142	R426	—
52DT	—	R404	5242
52U	—	R404	5242
52UT	—	R423	—
53D	VR142	R426	—

(continued on next page)

¹ 27-31 Amp ⁶ 42-46 Amp ¹¹ Negative ground ¹⁷ 32-36 Amp ¹⁹ Positive ground ²² 63 Amp ²⁴ 37-41 Amp

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
53DT	VR851	R404	5242
53UT	—	R423	—
54D	VR142	R429	—
54DT	VR899	R1001	5242
54UT	—	R423	—
55UT	—	R423	—
56UT	VR891 ²⁶	R423	—
57UT	—	R423	—
58UT	VR122	R423	5242
58UT	VR894 ¹¹	R423	5242
59UT	—	R423	—
60U	—	R404	5242
61U	—	R423	5242
62U	VR56 ¹¹	R413	5242
72U	VR56	R413	—
84U	VR1071 ^{11,6}	R423	5242
84U	VR56 ²⁴	R423	5242
85U	VR1071 ^{11,6}	R423	5242
85U	VR56 ^{19,24}	R423	5242
94U	VR1071 ^{19,6}	R423	5242
97U	VR122 ¹	R423	5242
97U	VR126 ¹⁷	R423	5242
434	CU2 ¹⁰	—	—
550	CU2 ¹⁰	—	—
551	CU2 ¹⁰	—	—
552	CU2 ¹⁰	—	—
603	VR123	—	—
605	VR123	—	—
901A	CU2 ¹⁰	R1001	—
902A	CU2 ¹⁰	R1001	—
903A	CU2 ¹⁰	R1001	—
904A	CU2 ¹⁰	R1001	—
905A	CU2 ¹⁰	R1001	—
906A	—	R1001	—
907A	CU2 ¹⁰	R1001	—
907B	CU2 ¹⁰	R1001	—
908B	CU2 ¹⁰	R1001	—
909B	CU2 ¹⁰	R1001	—
910B	CU2 ¹⁰	R1001	—
911B	CU2 ¹⁰	R1001	—
912B	CU2 ¹⁰	R1001	—
913C	CU2 ¹⁰	R1001	—
913D	—	R1001	—
913E	—	R1001	—
913F	CU2 ¹⁰	R1001	—
913G	CU2 ¹⁰	R1001	—
913H	—	R1001	—
914A	CU2 ¹⁰	R1001	—
914B	CU2 ¹⁰	R1001	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
915B	—	R1001	—
915C	—	R1001	—
915D	CU2 ¹⁰	R1001	—
916B	VR123	—	—
916C	VR123	—	—
916D	VR56	—	—
916E	VR123	—	—
916G	VR123	—	—
916H	VR56	—	—
916J	VR123	—	—
916K	VR56	—	—
917A	CU2 ¹⁰	R1001	—
917AD	CU2 ¹⁰	R1001	—
917B	CU2 ¹⁰	R1001	—
917C	CU2 ¹⁰	R1001	—
917D	CU2 ¹⁰	R1001	—
917E	—	R1001	—
917F	CU2 ¹⁰	R1001	—
917G	CU2 ¹⁰	R1001	—
917J	CU2 ¹⁰	R1001	—
917JL	CU2 ¹⁰	R1001	—
917K	CU2 ¹⁰	R1001	—
917L	CU2 ¹⁰	R1001	—
918A	—	R404	—
918B	—	R404	—
918C	—	R404	5242
918D	—	R404	5242
918E	—	R404	5242
918F	—	R404	5242
918G	—	R404	5242
918H	—	R404	5242
919A	CU2 ¹⁰	R1001	—
920A	—	R1001	—
920B	CU2 ¹⁰	R1001	—
921A	CU2 ¹⁰	R1001	—
921B	CU2 ¹⁰	R1001	—
922A	CU2 ¹⁰	R1001	—
923A	—	R1001	—
923C	CU2 ¹⁰	R1001	—
924A	CU2 ¹⁰	R1001	—
924B	CU2 ¹⁰	R1001	—
924C	CU2 ¹⁰	R1001	—
925B	CU2 ¹⁰	R1001	—
925C	CU2 ¹⁰	R1001	—
925D	CU2 ¹⁰	R1001	—
925E	CU2 ¹⁰	R1001	—
926A	CU2 ¹⁰	—	—
926B	CU2 ¹⁰	—	—
928A	—	R404	—

(continued on next page)

¹ 27-31 Amp ⁶ 42-46 Amp ¹⁰ Physical comparison is necessary or check application guide ¹¹ Negative ground ¹⁷ 32-36 Amp ¹⁹ Positive ground ²⁴ 37-41 Amp ²⁶ Tractor application

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
928B	VR123	—	—
929A	—	R404	—
929B	—	R404	—
930B	VR56	—	—
930C	VR123	—	—
930G	VR56	—	—
930H	VR56	—	—
931A	CU2 ¹⁰	R1001	—
931B	CU2 ¹⁰	R1001	—
931K	—	R1001	—
931M	—	R404	—
931MZ	—	R404	—
931N	—	R404	—
931O	—	R404	—
931P	—	R404	—
931Q	—	R404	—
931R	—	R404	—
931S	—	R404	—
931T	—	R404	—
931U	—	R404	—
931V	—	R404	—
931W	—	R404	—
931X	—	R404	—
931Y	—	R404	—
931Z	—	R404	—
932A	—	R404	—
932AD	—	R404	—
932B	—	R404	—
932C	—	R404	—
932D	—	R404	—
933B	—	R404	—
933C	—	R404	—
933D	—	R404	—
933F	VR56	R404	—
933G	VR56	R404	—
933H	VR56	R404	—
933J	VR56	R404	—
933K	VR56	R404	—
933L	VR56	R404	—
933M	VR56	R404	—
933N	VR56	R404	—
933P	VR56	R404	—
933R	—	R404	—
934A	VR56	—	—
934B	VR123	—	—
934C	VR56	—	—
934D	VR123 ¹⁹	—	—
934G	VR123 ¹⁹	—	—
934M	VR56 ¹¹	—	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
934M	VR56 ¹⁹	—	—
934N	VR123 ¹⁹	—	—
934P	VR56	—	—
934R	VR123	—	—
934S	VR56	—	—
934U	VR56 ¹¹	—	—
934U	VR56 ¹⁹	—	—
934V	VR123	—	—
934W	VR56	—	—
934X	VR123	—	—
935B	CU2 ¹⁰	R404	5242
935C	—	R404	5242
935D	—	R404	5242
935E	—	R404	5242
935F	CU2 ¹⁰	R404	5242
935G	CU2 ¹⁰	R404	5242
935H	—	R404	—
935J	—	R404	5242
935K	—	R404	5242
935L	—	R404	5242
935M	—	R404	5242
935N	—	R404	5242
935P	—	R404	—
935R	—	R404	5242
935S	—	R404	5242
935U	—	R404	5242
935V	CU2 ¹⁰	R404	5242
935W	—	R404	5242
935X	—	R404	5242
935Y	—	R404	—
935Z	CU2 ¹⁰	R404	—
936A	—	R404	5242
936B	—	R404	—
936C	—	R404	5242
936D	CU2 ¹⁰	R404	5242
936E	—	R404	5242
936F	—	R404	5242
936G	—	R404	5242
936H	—	R404	5242
936I	—	R404	5242
936J	—	R404	5242
936L	—	R404	—
936M	—	R404	5242
936N	—	R404	5242
936O	—	R404	5242
936P	—	R404	5242
936Q	—	R404	5242
936R	—	R404	5242
936S	—	R404	5242

(continued on next page)

¹⁰Physical comparison is necessary or check application guide ¹¹Negative ground ¹⁹Positive ground

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
936T	—	R404	5242
936U	—	R404	5242
936V	—	R404	5242
936W	—	R404	5242
936X	—	R404	—
936Y	—	R404	—
936Z	—	R404	—
937A	CU2 ¹⁰	R1001	5242
937B	CU2 ¹⁰	R1001	5242
937C	CU2 ¹⁰	—	5242
937D	—	—	5242
937E	CU2 ¹⁰	—	5242
937F	—	—	5242
937G	CU2 ¹⁰	—	5242
937H	CU2 ¹⁰	R404	5242
937J	—	R404	5242
937K	CU2 ¹⁰	R404	5242
937L	—	R404	5242
937M	—	—	5242
937N	CU2 ¹⁰	R404	5242
937P	—	R404	5242
937R	CU2 ¹⁰	R1001	5242
937S	CU2 ¹⁰	R1001	5242
937U	CU2 ¹⁰	R1001	5242
937V	CU2 ¹⁰	R1001	5242
937W	—	R1001	5242
937X	—	R1001	5242
937Y	CU2 ¹⁰	—	—
937Z	CU2 ¹⁰	—	5242
938A	CU2 ¹⁰	R1001	5242
938B	CU2 ¹⁰	R1001	5242
938C	CU2 ¹⁰	R1001	5242
938D	CU2 ¹⁰	R1001	5242
938E	CU2 ¹⁰	R1001	—
938F	CU2 ¹⁰	R1001	5242
938G	CU2 ¹⁰	R1001	—
939A	—	R1001	—
939B	—	R1001	—
939C	—	R1001	—
939D	—	R1001	—
939E	—	R1001	—
939F	—	R1001	—
939G	—	R1001	5242
939H	—	R1001	—
939K	—	R1001	—
939L	—	R1001	—
939M	—	R1001	5242
939N	—	R1001	—
939P	—	R1001	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
939R	—	R1001	—
939S	—	R1001	—
939T	—	R1001	—
939U	CU2 ¹⁰	R1001	5242
939V	—	R1001	5242
939X	CU2 ¹⁰	R1001	5242
939Y	—	R1001	—
940A	CU2 ¹⁰	R1001	—
940B	CU2 ¹⁰	R1001	5242
940C	CU2 ¹⁰	R1001	5242
940D	CU2 ¹⁰	—	—
940E	CU2 ¹⁰	R1001	5242
940F	CU2 ¹⁰	—	—
940G	CU2 ¹⁰	R1001	5242
940H	CU2 ¹⁰	R1001	—
940J	CU2 ¹⁰	R1001	5242
940K	CU2 ¹⁰	R1001	5242
940L	CU2 ¹⁰	R1001	5242
940M	CU2 ¹⁰	R1001	5242
940M1	CU2 ¹⁰	—	—
940M2	CU2 ¹⁰	—	—
940M3	CU2 ¹⁰	—	—
940M4	CU2 ¹⁰	—	—
940N	CU2 ¹⁰	R1001	5242
940O	CU2 ¹⁰	R1001	5242
940P	CU2 ¹⁰	R1001	5242
940Q	CU2 ¹⁰	R1001	5242
940R	CU2 ¹⁰	R1001	5242
940S	CU2 ¹⁰	R1001	5242
940T	CU2 ¹⁰	R1001	5242
940T1	CU2 ¹⁰	—	—
940T2	CU2 ¹⁰	—	—
940T3	CU2 ¹⁰	—	—
940U	CU2 ¹⁰	R1001	5242
940V	CU2 ¹⁰	R1001	5242
940W	CU2 ¹⁰	R1001	5242
940X	CU2 ¹⁰	R1001	5242
940Y	CU2 ¹⁰	R1001	5242
940Z	CU2 ¹⁰	R1001	5242
941A	CU2 ¹⁰	R1001	—
941B	CU2 ¹⁰	—	—
941C	CU2 ¹⁰	—	—
941D	CU2 ¹⁰	—	—
941E	CU2 ¹⁰	R1001	—
941F	CU2 ¹⁰	R1001	—
941G	CU2 ¹⁰	R1001	—
941H	CU2 ¹⁰	R1001	—
941H12	—	R1001	—
941J	CU2 ¹⁰	R1001	—

(continued on next page)

¹⁰Physical comparison is necessary or check application guide

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
941K	CU2 ¹⁰	R1001	—
941L	CU2 ¹⁰	R1001	—
941M	CU2 ¹⁰	R1001	—
941N	CU2 ¹⁰	R1001	—
941O	CU2 ¹⁰	R1001	—
941P	CU2 ¹⁰	R1001	—
941Q	CU2 ¹⁰	R1001	—
941R	CU2 ¹⁰	R1001	—
941S	CU2 ¹⁰	R1001	—
941T	CU2 ¹⁰	R1001	—
941U	CU2 ¹⁰	R1001	5242
941V	CU2 ¹⁰	R1001	—
941W	CU2 ¹⁰	R1001	—
941X	CU2 ¹⁰	—	—
941Y	CU2 ¹⁰	R1001	—
941Z	CU2 ¹⁰	R1001	—
941ZS	CU2 ¹⁰	R1001	—
942A	CU2 ¹⁰	R1001	5242
942B	CU2 ¹⁰	R1001	5242
942C	CU2 ¹⁰	R1001	5242
942D	CU2 ¹⁰	R1001	5242
942E	CU2 ¹⁰	R1001	5242
942F	CU2 ¹⁰	R1001	5242
942G	CU2 ¹⁰	R1001	5242
942H	CU2 ¹⁰	R1001	5242
942I	CU2 ¹⁰	R1001	5242
942J	CU2 ¹⁰	R1001	5242
943A	CU2 ¹⁰	R1001	—
943B	CU2 ¹⁰	R1001	5242
943C	CU2 ¹⁰	R1001	5242
943D	CU2 ¹⁰	R1001	5242
943E	CU2 ¹⁰	R1001	—
943F	CU2 ¹⁰	R1001	5242
943G	CU2 ¹⁰	R1001	—
943H	CU2 ¹⁰	R1001	5242
943I	CU2 ¹⁰	R1001	5242
943J	CU2 ¹⁰	R1001	5242
943K	CU2 ¹⁰	R1001	5242
943L	CU2 ¹⁰	R1001	5242
943M	CU2 ¹⁰	R1001	5242
943N	CU2 ¹⁰	R1001	5242
943O	CU2 ¹⁰	R1001	5242
943P	CU2 ¹⁰	R1001	5242
943Q	CU2 ¹⁰	R1001	5242
943R	CU2 ¹⁰	R1001	5242
943S	CU2 ¹⁰	R1001	5242
943T	CU2 ¹⁰	R1001	5242
943U	CU2 ¹⁰	R1001	5242
943V	CU2 ¹⁰	R1001	5242

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
943W	CU2 ¹⁰	R1001	5242
943X	CU2 ¹⁰	R1001	5242
943Y	CU2 ¹⁰	R1001	5242
943Z	CU2 ¹⁰	R1001	5242
944A	CU2 ¹⁰	R1001	—
944B	CU2 ¹⁰	R1001	5242
944C	CU2 ¹⁰	R1001	5242
944D	CU2 ¹⁰	R1001	—
944E	CU2 ¹⁰	R1001	—
944F	CU2 ¹⁰	R1001	—
944G	CU2 ¹⁰	R1001	5242
944N	CU2 ¹⁰	R1001	5242
944P	CU2 ¹⁰	R1001	5242
944X	—	R1001	5242
945A	—	R1001	—
945C	CU2 ¹⁰	R1001	—
945D	CU2 ¹⁰	R1001	—
945E	CU2 ¹⁰	R1001	—
945G	CU2 ¹⁰	R1001	—
945H	CU2 ¹⁰	R1001	5242
945L	CU2 ¹⁰	R1001	—
945N	CU2 ¹⁰	R1001	—
945P	CU2 ¹⁰	R1001	—
945Q	CU2 ¹⁰	R1001	5242
945R	—	R1001	—
945S	CU2 ¹⁰	R1001	—
945SV	—	R1001	—
945T	CU2 ¹⁰	R1001	—
945U	CU2 ¹⁰	R1001	—
945V	CU2 ¹⁰	R1001	—
945W	—	R1001	—
945X	CU2 ¹⁰	R1001	—
945Y	—	R1001	—
945Z	CU2 ¹⁰	R1001	5242
946A	CU2 ¹⁰	R1001	—
946B	CU2 ¹⁰	—	—
946C	CU2 ¹⁰	R1001	5242
946D	CU2 ¹⁰	R1001	5242
946E	CU2 ¹⁰	R1001	5242
946F	CU2 ¹⁰	R1001	—
946G	CU2 ¹⁰	—	—
946H	CU2 ¹⁰	—	—
946J	CU2 ¹⁰	R1001	5242
946K	—	R404	—
946L	—	R1001	5242
946M	—	R1001	5242
946N	CU2 ¹⁰	R1001	5242
946P	CU2 ¹⁰	R1001	5242
946R	CU2 ¹⁰	R1001	5242

(continued on next page)

¹⁰Physical comparison is necessary or check application guide

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
946S	CU2 ¹⁰	R1001	5242
947B	CU2 ¹⁰	R1001	—
947C	CU2 ¹⁰	R1001	—
947D	CU2 ¹⁰	R1001	—
947G	CU2 ¹⁰	R1001	—
948A	CU2 ¹⁰	R1001	5242
948B	CU2 ¹⁰	R1001	5242
948C	—	R404	5242
948D	—	R404	5242
948E	CU2 ¹⁰	R404	5242
948F	CU2 ¹⁰	—	—
948G	—	R404	5242
948H	—	R404	5242
948J	CU2 ¹⁰	R404	—
948K	CU2 ¹⁰	R404	—
948M	CU2 ¹⁰	—	—
948N	—	R404	5242
948P	—	R404	—
948R	CU2 ¹⁰	R404	5242
948S	—	R404	5242
948T	—	R404	5242
948U	—	R404	5242
948V	—	R404	—
948W	—	—	5242
948X	CU2 ¹⁰	R1001	5242
948Y	—	R404	5242
948Z	—	R404	5242
949D	CU2 ¹⁰	R1001	—
949E	CU2 ¹⁰	R1001	—
949F	CU2 ¹⁰	R1001	—
949G	CU2 ¹⁰	R1001	5242
949H	CU2 ¹⁰	R1001	—
949J	CU2 ¹⁰	R1001	5242
949L	CU2 ¹⁰	R1001	5242
949M	CU2 ¹⁰	R1001	5242
949N	CU2 ¹⁰	R1001	5242
949P	CU2 ¹⁰	R1001	—
949Q	CU2 ¹⁰	R1001	5242
949R	CU2 ¹⁰	R1001	5242
949S	CU2 ¹⁰	R1001	—
949T	CU2 ¹⁰	R1001	5242
949U	CU2 ¹⁰	R1001	5242
949V	CU2 ¹⁰	R1001	5242
949W	CU2 ¹⁰	R1001	5242
949X	CU2 ¹⁰	R1001	5242
949Y	CU2 ¹⁰	R1001	—
950	—	R1001	—
950A	CU2 ¹⁰	R1001	—
950B	CU2 ¹⁰	R1001	5242

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
950C	CU2 ¹⁰	R1001	5242
950D	CU2 ¹⁰	R1001	—
951A	CU2 ¹⁰	R1001	—
951B	CU2 ¹⁰	R1001	—
951D	CU2 ¹⁰	R1001	—
953D	CU2 ¹⁰	R1001	—
953E	CU2 ¹⁰	R1001	—
953G	CU2 ¹⁰	R1001	5242
953H	CU2 ¹⁰	R1001	—
953J	CU2 ¹⁰	R1001	5242
953K	—	R1001	—
953L	—	R1001	—
953M	CU2 ¹⁰	—	5242
953N	CU2 ¹⁰	R1001	5242
953P	—	R1001	—
953R	CU2 ¹⁰	R1001	—
953S	CU2 ¹⁰	R1001	5242
953T	CU2 ¹⁰	R404	5242
953U	CU2 ¹⁰	R1001	—
953V	CU2 ¹⁰	R1001	—
953W	CU2 ¹⁰	R1001	—
953X	—	R1001	—
953Y	CU2 ¹⁰	R1001	—
953Z	—	R1001	—
955A	—	R1001	—
955B	CU2 ¹⁰	R1001	—
955C	CU2 ¹⁰	R1001	—
955D	CU2 ¹⁰	R1001	5242
955E	CU2 ¹⁰	R1001	—
955F	CU2 ¹⁰	R1001	5242
955G	CU2 ¹⁰	R1001	5242
955H	CU2 ¹⁰	R1001	—
955J	CU2 ¹⁰	R1001	—
955K	CU2 ¹⁰	R1001	—
955L	CU2 ¹⁰	R1001	5242
955M	—	R1001	5242
955N	CU2 ¹⁰	R1001	—
955P	CU2 ¹⁰	R1001	—
955Q	CU2 ¹⁰	R1001	5242
955R	CU2 ¹⁰	R1001	5242
955S	CU2 ¹⁰	R1001	—
955T	CU2 ¹⁰	R1001	—
955U	CU2 ¹⁰	R1001	5242
955V	—	R1001	—
955W	—	R1001	—
955X	CU2 ¹⁰	R1001	—
955Y	CU2 ¹⁰	R1001	—
955Z	CU2 ¹⁰	R1001	—
956A	CU2 ¹⁰	R1001	5242

(continued on next page)

¹⁰Physical comparison is necessary or check application guide

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
956C	CU2 ¹⁰	R1001	5242
956D	CU2 ¹⁰	R1001	—
956E	CU2 ¹⁰	R1001	—
956F	CU2 ¹⁰	R1001	—
956G	CU2 ¹⁰	R1001	—
956H	CU2 ¹⁰	R1001	—
956I	CU2 ¹⁰	R1001	—
956J	CU2 ¹⁰	R1001	—
956K	CU2 ¹⁰	R1001	—
956M	CU2 ¹⁰	—	—
956P	—	R1001	—
957A	CU2 ¹⁰	R1001	5242
957B	CU2 ¹⁰	R1001	5242
957C	CU2 ¹⁰	R1001	5242
957D	—	R1001	—
957E	CU2 ¹⁰	R1001	—
957F	—	R1001	—
957J	CU2 ¹⁰	R1001	—
957K	—	R1001	—
957L	—	R1001	—
957M	—	R1001	—
957Q	CU2 ¹⁰	R1001	—
957R	CU2 ¹⁰	R1001	—
957T	CU2 ¹⁰	R1001	—
957U	CU2 ¹⁰	R1001	—
957V	CU2 ¹⁰	R1001	—
957W	CU2 ¹⁰	R1001	—
957X	—	R1001	—
957Z	CU2 ¹⁰	R1001	—
958A	—	R404	5242
958B	—	R1001	—
958C	—	R404	5242
958D	—	R404	5242
958E	—	R404	5242
958F	—	R1001	—
959A	CU2 ¹⁰	R1001	—
959B	—	R1001	—
959C	CU2 ¹⁰	R1001	5242
959D	CU2 ¹⁰	R1001	5242
959E	CU2 ¹⁰	R1001	—
959F	CU2 ¹⁰	R1001	—
959G	CU2 ¹⁰	—	5242
959J	CU2 ¹⁰	R1001	5242
959L	CU2 ¹⁰	R1001	—
959M	CU2 ¹⁰	R1001	—
959N	CU2 ¹⁰	R1001	—
959O	CU2 ¹⁰	R1001	—
959P	CU2 ¹⁰	R1001	—
959Q	CU2 ¹⁰	R1001	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
959R	CU2 ¹⁰	R1001	—
959S	CU2 ¹⁰	R1001	—
959T	CU2 ¹⁰	R1001	—
959U	CU2 ¹⁰	R1001	—
959V	CU2 ¹⁰	R1001	—
959W	CU2 ¹⁰	R1001	—
959X	CU2 ¹⁰	R1001	—
959Y	CU2 ¹⁰	R1001	—
959Z	CU2 ¹⁰	R1001	5242
960A	—	R404	5242
960B	—	R404	—
960C	—	R404	5242
960D	—	R404	—
960E	—	R404	5242
960F	CU2 ¹⁰	R1001	5242
960G	—	R404	5242
960H	—	R404	5242
960J	—	R404	5242
961A	CU2 ¹⁰	R1001	—
961C	—	R404	5242
961D	VR56	R404	5242
961E	—	R404	5242
961H	—	R404	—
961J	—	R404	5242
961K	—	R404	5242
961L	VR123	—	—
961M	—	R404	5242
961N	—	R404	5242
965A	—	R1001	—
965B	CU2 ¹⁰	R1001	—
965C	CU2 ¹⁰	R1001	—
965D	CU2 ¹⁰	R1001	—
965E	CU2 ¹⁰	R1001	—
965F	CU2 ¹⁰	R1001	—
965G	CU2 ¹⁰	R1001	—
965H	CU2 ¹⁰	R1001	—
965I	CU2 ¹⁰	R1001	—
965J	CU2 ¹⁰	R1001	—
965K	CU2 ¹⁰	R1001	—
965L	CU2 ¹⁰	R1001	—
965M	CU2 ¹⁰	R1001	5242
965P	CU2 ¹⁰	R1001	—
965S	CU2 ¹⁰	R1001	—
965T	CU2 ¹⁰	R1001	—
965U	CU2 ¹⁰	R1001	—
965V	CU2 ¹⁰	—	5242
965W	CU2 ¹⁰	R1001	5242
965X	CU2 ¹⁰	R1001	5242
965Y	CU2 ¹⁰	R1001	—

(continued on next page)

¹⁰Physical comparison is necessary or check application guide

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
965Z	—	R1001	—
967A	—	—	5242
967B	—	—	5242
967C	CU2 ¹⁰	—	5242
967D	CU2 ¹⁰	—	5242
967E	CU2 ¹⁰	—	5242
967G	CU2 ¹⁰	R1001	—
967J	CU2 ¹⁰	—	—
967L	—	R404	5242
967M	—	R404	5242
967N	—	R404	5242
967P	—	R404	5242
967S	—	R404	—
967T	CU2 ¹⁰	—	5242
967U	—	R404	—
967V	CU2 ¹⁰	R1001	—
967W	—	R1001	—
967X	—	R1001	—
967Y	CU2 ¹⁰	R1001	5242
967Z	—	R404	—
968A	—	R1001	—
968B	—	R404	—
968D	—	R404	5242
968E	—	R404	—
968F	—	R1001	5242
968G	—	R404	—
968H	—	R404	5242
968J	—	R404	5242
968K	—	R404	—
968L	—	R1001	5242
968M	—	R1001	—
968N	—	R404	—
968P	—	R404	5242
968R	—	R404	5242
968S	—	R404	—
968T	—	R404	5242
968U	—	R1001	—
968V	—	R1001	5242
968W	—	R1001	—
968X	—	R404	5242
968Y	—	R1001	—
973B	CU2 ¹⁰	—	—
973D	CU2 ¹⁰	—	—
973J	CU2 ¹⁰	—	—
975K	CU2 ¹⁰	—	—
975N	CU2 ¹⁰	—	—
110703	—	R1001	—
110704	—	R1001	—
1000326	VR122	R423	5242

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1100001	—	R404	5242
1100002	—	R404	5242
1100003	—	R404	5242
1100004	—	R404	5242
1100005	—	R404	5242
1100006	—	R404	5242
1100007	—	R404	5242
1100008	—	R404	5242
1100009	—	R404	5242
1100010	—	R404	5242
1100011	—	R404	5242
1100012	—	R404	5242
1100013	VR56 ¹¹	R423	5242
1100013	VR56 ¹⁹	R423	5242
1100016	—	R423	—
1100018	VR1071 ¹¹	R423	5242
1100018	VR1071 ¹⁹	R423	5242
1100019	VR56	R423	5242
1100020	—	R423	—
1100021	VR56	R423	5242
1100023	VR897	R423	—
1100024	—	R423	5242
1100025	—	R423	—
1100027	—	R423	—
1100028	VR1071 ¹¹	R423	5242
1100029	—	R423	—
1100030	—	R423	5242
1100031	VR56 ¹⁹	R423	—
1100032	—	R423	—
1100033	—	R423	—
1100034	—	R423	—
1100035	—	R423	—
1100036	—	R423	—
1100037	—	R423	—
1100038	VR850	R423	—
1100038	VR851	R423	—
1100039	VR850	R423	—
1100039	VR851	R423	—
1100040	VR851	R423	—
1100041	VR851	R423	—
1100042	VR56 ³⁷	R423	—
1100042	VR851 ²⁷	R423	—
1100043	VR850	R423	—
1100043	VR851	R423	—
1100044	—	R423	—
1100045	—	R423	—
1100046	—	R423	—
1100047	—	R423	—
1100048	—	R423	—

(continued on next page)

¹⁰Physical comparison is necessary or check application guide ¹¹Negative ground ¹⁹Positive ground ²⁷Two unit regulator ³⁷Three unit regulator

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1100051	VR56	R423	—
1100052	VR851	R423	—
1100053	—	R423	—
1100054	—	R423	—
1100055	—	R423	—
1100273	—	R423	—
1100292	VR894	R423	—
1100301	—	R423	5242
1100304	VR122 ¹¹	R423	5242
1100304	VR123 ¹⁹	R423	5242
1100305	VR898	R423	—
1100306	VR899	R423	—
1100307	VR899	R423	—
1100309	VR850	R423	—
1100309	VR897	R423	—
1100310	VR122	R423	5242
1100313	VR122 ¹¹	R423	5242
1100313	VR123 ¹⁹	R423	5242
1100314	VR899	R423	—
1100315	VR899	R423	—
1100316	VR899	R423	—
1100317	VR899	R423	—
1100318	VR122	R423	5242
1100319	VR893 ¹⁹	R423	5242
1100321	VR122	R423	5242
1100322	VR899	R423	—
1100323	VR122	R423	5242
1100324	VR122	R423	5242
1100326	VR122	R423	5242
1100327	VR899	R423	—
1100328	VR899	R423	—
1100332	—	R404	—
1100333	VR122	R423	—
1100334	VR899	R423	—
1100335	VR899	R423	—
1100336	—	R423	—
1100337	VR122	R423	—
1100338	VR898	R423	—
1100339	VR898	R423	—
1100341	VR899	R423	—
1100342	—	R423	—
1100344	VR897	R423	—
1100345	VR898	R423	—
1100346	—	R423	—
1100347	—	R423	—
1100348	VR899	R423	—
1100349	VR899	R423	—
1100350	VR899	R423	—
1100351	—	R423	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1100352	VR897	R423	—
1100353	VR896	R423	—
1100354	VR122	R423	—
1100355	VR899	R423	—
1100356	—	R423	—
1100357	VR122	R423	—
1100358	VR898	R423	—
1100359	VR896	R423	—
1100360	VR897	R423	—
1100361	VR891	R423	—
1100362	VR896	R423	—
1100363	VR896	R423	—
1100364	VR896	R423	—
1100365	VR898	R423	—
1100366	—	R423	—
1100367	VR898	R423	—
1100368	VR122	R423	—
1100369	VR897	R423	—
1100370	VR899	R423	—
1100371	VR123	R423	—
1100372	—	R423	—
1100373	—	R1001	—
1100374	—	R423	—
1100376	—	R423	—
1100377	—	R423	—
1100378	—	R423	—
1100379	VR899	R423	—
1100380	VR123	R423	—
1100381	VR897	R423	—
1100382	VR897	R423	—
1100383	VR896	R423	—
1100384	VR122	R423	—
1100385	VR123	R423	—
1100386	—	R423	—
1100387	VR898	R423	—
1100388	VR122	R423	—
1100389	VR126	R423	—
1100390	VR897	R423	—
1100391	VR122	R423	—
1100392	VR122	R423	—
1100393	VR122	—	—
1100394	VR122	R423	—
1100394	VR894 ¹¹	R423	—
1100394	VR898	R423	—
1100395	VR122	R423	—
1100395	VR894 ¹¹	R423	—
1100395	VR898	R423	—
1100396	VR122	R423	—
1100396	VR899	R423	—

(continued on next page)

¹¹ Negative ground ¹⁹ Positive ground

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing	Unit No	Voltage Regulator	Brush Set	Bushing
1100397	VR897	R423	—	1100449	—	R423	—
1100398	VR897	R423	—	1100450	VR897	R423	—
1100399	VR898	R423	—	1100451	—	R404	—
1100400	—	R423	—	1100452	—	R404	5242
1100401	VR898	R423	—	1100453	—	R404	5242
1100402	—	R423	—	1100454	—	R404	5242
1100403	VR894	R423	—	1100455	—	R404	5242
1100404	—	R423	—	1100456	—	R404	5242
1100407	VR897	R423	—	1100458	—	R404	—
1100408	VR122	R423	—	1100459	—	R404	5242
1100409	—	R423	—	1100460	—	R404	5242
1100410	VR122	R423	—	1100461	—	R404	5242
1100411	—	R423	—	1100462	—	R404	5242
1100412	VR122	R423	—	1100463	—	R404	—
1100413	VR123	R423	—	1100464	—	R404	5242
1100414	VR898	R423	—	1100465	—	R1001	—
1100415	VR122	R423	—	1100466	—	R404	5242
1100416	VR122	R423	—	1100467	—	R404	5242
1100417	VR897	R423	—	1100468	—	R404	5242
1100418	VR123 ¹⁹	R423	—	1100469	—	R404	5242
1100419	VR898	R423	—	1100470	VR851	R404	—
1100420	VR123	R423	—	1100471	VR122	—	—
1100421	VR122	R423	—	1100472	VR122	—	—
1100422	VR894	R423	—	1100495	—	R404	5242
1100423	—	R423	—	1100501	—	R404	5242
1100424	—	R423	—	1100502	VR851	R404	5242
1100425	VR898	R423	—	1100503	VR851	R404	5242
1100426	VR122	R423	—	1100504	—	R1001	5242
1100427	VR122	R423	—	1100505	—	R1001	5242
1100428	VR899	R423	—	1100506	—	R1001	5242
1100429	—	R423	—	1100507	—	R1001	5242
1100430	VR122	R423	—	1100508	—	R1001	5242
1100431	—	R423	—	1100509	VR851	R1001	5242
1100432	VR122	R423	—	1100511	—	R1001	5242
1100433	—	R423	—	1100512	—	R1001	5242
1100434	—	R423	—	1100513	—	R1001	5242
1100435	—	R423	—	1100516	—	R1001	5242
1100436	—	R423	—	1100517	—	R1001	5242
1100437	—	R423	—	1100518	VR851	R404	5242
1100438	—	R423	—	1100520	VR851	R404	5242
1100439	—	R423	—	1100522	VR851	R404	5242
1100440	—	R423	—	1100523	VR851	R1001	5242
1100441	—	R423	—	1100526	VR851	R404	5242
1100442	VR122	R423	—	1100527	—	R1001	5242
1100443	VR122	R423	—	1100528	VR851	R1001	5242
1100444	VR897	R423	—	1100529	VR851	R1001	5242
1100445	VR897	R423	—	1100530	VR851	R1001	5242
1100447	VR122	R423	—	1100531	VR851	R404	5242
1100448	—	R423	—	1100532	—	R404	5242

(continued on next column)

(continued on next page)

¹⁹ Positive ground

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1100534	VR851	R404	5242
1100535	—	R404	5242
1100536	—	R404	5242
1100537	—	R404	5242
1100538	—	R404	5242
1100539	VR851	R404	5242
1100540	VR852	R404	5242
1100541	VR851	R404	5242
1100605	VR142	R426	—
1100783	—	R429	—
1100789	VR142	R429	—
1100850	—	R429	—
1100952	—	R1001	5242
1100953	VR899	R1001	5242
1100954	—	R1001	5242
1100955	—	R1001	5242
1100956	VR898	R1001	5242
1100957	—	R1001	—
1100958	VR897	R1001	—
1100959	—	R404	5242
1100960	—	R404	5242
1100961	—	R404	5242
1100962	—	R404	5242
1100963	—	R404	5242
1100964	VR898 ¹⁹	R404	5242
1100965	—	R1001	5242
1100966	—	R1001	5242
1100968	VR899	R1001	5242
1100969	VR898	R1001	—
1100971	—	R1001	5242
1100972	—	R1001	5242
1100973	—	R404	5242
1100979	—	R404	5242
1100981	—	R1001	5242
1100983	—	R1001	5242
1100986	VR898 ¹⁹	R1001	5242
1100987	—	R1001	5242
1100988	—	R1001	—
1100990	VR898	R404	5242
1100991	VR898	R404	5242
1100992	VR899	R1001	5242
1100993	VR898	R404	5242
1100994	VR899	R404	5242
1100995	VR899	R404	5242
1100996	VR898	R404	5242
1100997	VR898	R404	5242
1100998	—	R1001	5242
1100999	VR899	R1001	5242
1101000	—	R404	5242

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1101001	VR898 ¹⁹	R404	5242
1101002	VR899	R404	5242
1101003	—	R1001	5242
1101004	VR898	R404	5242
1101005	VR896	R1001	5242
1101006	VR897	R404	5242
1101007	VR898	R404	—
1101009	—	R413	5242
1101010	VR898	R404	5242
1101011	—	R413	5242
1101012	VR896	R413	5242
1101013	VR898	R404	—
1101014	—	—	5242
1101051	—	R404	5242
1101052	—	R404	5242
1101053	—	R404	5242
1101054	—	R404	5242
1101055	—	R404	5242
1101056	—	R404	5242
1101057	—	R404	5242
1101351	—	R1001	5242
1101352	—	R1001	5242
1101353	—	R1001	5242
1101354	—	R1001	5242
1101355	—	R1001	5242
1101356	—	R1001	5242
1101357	—	R1001	5242
1101358	VR851	R1001	5242
1101359	—	R404	5242
1101360	—	R1001	5242
1101361	—	R404	5242
1101362	—	R404	5242
1101363	—	R1001	5242
1101364	—	R1001	5242
1101365	—	R1001	5242
1101366	—	R1001	5242
1101367	—	R1001	5242
1101368	—	R404	5242
1101369	—	R1001	5242
1101370	—	R1001	5242
1101371	—	R1001	5242
1101372	—	R1001	5242
1101373	—	R1001	5242
1101374	—	R1001	5242
1101375	—	R1001	—
1101376	—	R404	5242
1101377	VR851	R1001	5242
1101378	—	R1001	5242
1101379	—	R1001	5242

(continued on next page)

¹⁹ Positive ground

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing	Unit No	Voltage Regulator	Brush Set	Bushing
1101380	—	R1001	—	1101657	—	R1001	5242
1101381	—	R1001	5242	1101658	—	R1001	—
1101382	—	R1001	5242	1101659	—	R1001	5242
1101383	—	R1001	5242	1101660	—	R1001	—
1101384	—	R1001	5242	1101661	—	R1001	—
1101385	—	R1001	5242	1101662	—	R1001	5242
1101386	—	R1001	5242	1101663	—	R1001	—
1101387	—	R1001	5242	1101664	—	R1001	—
1101388	—	R1001	5242	1101665	—	R1001	—
1101390	—	R1001	5242	1101666	—	R1001	—
1101391	—	R1001	5242	1101667	—	R1001	—
1101392	—	R1001	5242	1101668	—	R1001	—
1101393	—	R1001	5242	1101669	—	R1001	—
1101397	—	R1001	5242	1101670	—	R1001	—
1101398	—	R1001	5242	1101671	—	R1001	—
1101399	—	R404	5242	1101672	—	R1001	—
1101400	—	R1001	5242	1101673	—	R1001	5242
1101401	—	R1001	5242	1101674	—	R1001	—
1101402	—	R1001	5242	1101675	—	R1001	—
1101403	—	R1001	5242	1101677	—	R1001	5242
1101404	VR851	R1001	5242	1101678	—	R1001	—
1101406	—	R1001	5242	1101679	—	R1001	—
1101408	—	R1001	5242	1101680	—	R1001	—
1101409	—	R404	5242	1101681	—	R1001	—
1101411	—	R1001	5242	1101682	—	R1001	—
1101413	—	R1001	5242	1101683	—	R1001	5242
1101414	—	R1001	5242	1101685	—	R1001	5242
1101415	—	R1001	5242	1101686	—	R1001	5242
1101416	—	R1001	5242	1101688	—	—	5242
1101417	—	R1001	5242	1101689	VR898	R430	—
1101418	—	R404	5242	1101690	—	R430	—
1101419	—	R1001	5242	1101691	—	R430	—
1101420	—	R404	5242	1101692	—	R430	—
1101421	—	R1001	5242	1101693	—	R430	—
1101422	—	R1001	5242	1101694	—	R430	—
1101423	—	R1001	5242	1101695	—	R430	—
1101425	—	R1001	5242	1101696	—	R430	—
1101426	—	R1001	5242	1101697	—	R430	—
1101429	—	R404	5242	1101698	—	R430	—
1101430	—	R1001	5242	1101699	VR896	R430	—
1101431	VR851	R1001	5242	1101701	—	R1001	—
1101432	—	R430	—	1101702	—	R404	—
1101433	VR896	R1001	5242	1101703	—	R1001	—
1101651	—	R1001	5242	1101704	—	R1001	—
1101652	—	R1001	5242	1101705	—	R1001	5242
1101653	—	R1001	—	1101706	—	R1001	5242
1101654	—	—	5242	1101707	VR1071 ¹⁹	R404	5242
1101655	—	R1001	—	1101708	—	R1001	—
1101656	—	R1001	5242	1101709	—	R1001	—

(continued on next column)

(continued on next page)

¹⁹ Positive ground

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1101710	—	R1001	5242
1101711	—	R1001	—
1101712	—	R1001	5242
1101713	—	R1001	—
1101714	—	R404	5242
1101715	—	R1001	5242
1101716	—	R404	5242
1101717	—	R1001	—
1101718	—	R1001	—
1101719	—	R1001	—
1101720	—	R1001	5242
1101721	—	R1001	—
1101722	—	R1001	—
1101723	—	R1001	5242
1101724	—	R1001	5242
1101725	—	R1001	5242
1101726	—	R1001	5242
1101727	—	R404	5242
1101728	—	R404	5242
1101729	—	R404	5242
1101730	—	R404	5242
1101731	—	R404	5242
1101732	—	R404	5242
1101733	—	R404	5242
1101734	—	R404	5242
1101735	—	R404	5242
1101736	—	R404	5242
1101737	—	R404	5242
1101738	—	R404	5242
1101739	—	R404	5242
1101740	—	R404	5242
1101741	—	R404	5242
1101742	—	R404	5242
1101743	—	R1001	—
1101744	—	R404	5242
1101745	—	R1001	—
1101746	—	R1001	5242
1101747	—	R1001	5242
1101748	—	R1001	5242
1101749	—	R404	5242
1101750	—	R404	5242
1101751	—	R404	5242
1101752	—	R404	5242
1101753	—	R404	5242
1101754	—	R1001	—
1101755	—	R1001	5242
1101756	—	R1001	5242
1101757	—	R1001	5242
1101758	—	R1001	5242

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1101759	—	R1001	—
1101760	—	R1001	—
1101762	—	R404	5242
1101766	—	R404	5242
1101767	—	R404	5242
1101768	—	R1001	—
1101769	—	R1001	5242
1101770	—	—	5242
1101771	—	R1001	5242
1101774	—	R404	5242
1101775	VR899	R1001	5242
1101776	—	R1001	—
1101777	VR899	R1001	5242
1101778	—	R1001	5242
1101779	—	R1001	5242
1101780	—	R1001	5242
1101781	—	R1001	—
1101782	—	R1001	5242
1101783	VR899	R1001	5242
1101784	VR899	R1001	5242
1101851	VR851	R1001	5242
1101852	VR851	R1001	5242
1101853	VR851	R1001	5242
1101854	VR851	R1001	5242
1101855	VR851	R1001	5242
1101856	VR851	R404	5242
1101857	VR851	R1001	5242
1101858	VR851	R1001	5242
1101859	VR851	R413	—
1101860	VR851	R1001	5242
1101862	—	R413	—
1101863	—	R430	—
1101864	—	R430	—
1101866	VR896	R413	5242
1101867	VR896	R413	5242
1101868	—	R430	—
1101869	VR896	R413	5242
1101870	—	R430	—
1101871	—	R430	—
1101872	—	R430	—
1101873	—	R430	—
1101874	—	R430	—
1101875	—	R430	—
1101876	—	R404	—
1101877	—	R404	—
1101878	—	R404	—
1101879	—	R404	—
1101880	—	R404	—
1101881	—	R404	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing	Unit No	Voltage Regulator	Brush Set	Bushing
1101882	—	R404	—	1101932	VR896	R430	—
1101883	—	R404	—	1101933	VR899	R430	—
1101884	VR128	R404	—	1101934	VR896	R430	—
1101885	VR128	R404	—	1101936	—	R430	—
1101886	VR128	R404	—	1101938	—	R430	—
1101887	VR128	R404	—	1101939	VR896	R430	—
1101888	VR128	R404	—	1101940	—	R430	—
1101889	VR128	R404	—	1101941	VR896	R430	—
1101890	VR128	R404	—	1101942	—	R430	—
1101891	VR128	R404	—	1101943	—	R430	—
1101892	VR128	R404	—	1101944	VR891	R430	—
1101893	VR128	R404	—	1101945	VR896 ¹¹	R430	—
1101894	VR128	R404	—	1101945	VR898 ¹⁹	R430	—
1101895	VR128	R404	—	1101947	VR896 ¹¹	R430	—
1101896	VR128	R404	—	1101947	VR898 ¹⁹	R430	—
1101897	VR128	R404	—	1101948	VR896 ¹¹	R430	—
1101898	VR128	R404	—	1101948	VR898 ¹⁹	R430	—
1101899	VR128	R404	—	1101949	VR896 ¹¹	R430	—
1101900	VR128	R404	—	1101949	VR898 ¹⁹	R430	—
1101901	VR128	R404	—	1101950	VR896 ¹¹	R430	—
1101902	VR128	R404	—	1101950	VR898 ¹⁹	R430	—
1101903	VR128	R404	—	1101951	VR898	R430	—
1101904	VR128	R404	—	1101952	VR891 ¹¹	R430	—
1101905	VR128	R404	—	1101953	VR896	R430	—
1101906	VR128	R404	—	1101954	VR122	R430	—
1101907	VR128	R404	—	1101955	—	R430	—
1101908	VR128	R404	—	1101956	VR896 ¹¹	R430	—
1101909	VR128	R404	—	1101957	VR896 ¹¹	R430	—
1101910	VR128	R404	—	1101957	VR898 ¹⁹	R430	—
1101911	VR128	R413	—	1101958	—	R430	—
1101912	VR128	R413	—	1101959	VR899	R430	—
1101913	VR128	R413	—	1101960	VR899	R430	—
1101914	VR128	R413	—	1101961	VR899	R430	—
1101915	VR128	R413	—	1101962	VR899	R430	—
1101916	VR128	R413	—	1101963	VR891	R430	—
1101917	VR128	R413	—	1101964	VR899	R430	—
1101918	VR128	R413	—	1101965	VR896 ¹¹	R430	—
1101919	VR128	R413	—	1101966	VR899	R430	—
1101920	VR128	R413	—	1101967	VR898	R430	—
1101921	VR128	R413	—	1101968	—	R430	—
1101922	VR128	R413	—	1101969	VR899	R430	—
1101923	—	R404	—	1101970	—	R430	—
1101926	—	R430	—	1101971	—	R430	—
1101927	VR899	R430	—	1101972	—	R430	—
1101928	VR899	R430	—	1101973	—	R430	—
1101929	VR899	R430	—	1101974	—	R430	—
1101930	VR896 ¹¹	R430	—	1101975	—	R430	—
1101930	VR898 ¹⁹	R430	—	1101976	—	R430	—
1101931	VR898	R430	—	1101977	—	R430	—

(continued on next column)

(continued on next page)

¹¹ Negative ground ¹⁹ Positive ground

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1101978	—	R430	—
1101979	—	R430	—
1101980	—	R430	—
1101981	—	R430	—
1101982	—	R430	—
1101983	—	R430	—
1101984	—	R430	—
1101985	—	R430	—
1101986	—	R430	—
1101987	VR899	R430	—
1101988	—	R430	—
1101989	—	R430	—
1101990	—	R430	—
1101991	—	R430	—
1101992	—	R430	—
1101993	—	R430	—
1101994	—	R430	—
1101995	—	R430	—
1101996	—	R430	—
1101997	VR898	R430	—
1101998	VR899	R430	—
1101999	—	R430	—
1102000	VR122	R423	—
1102002	VR122	R423	5242
1102003	VR122	R423	5242
1102005	—	R423	—
1102006	VR122	R423	—
1102007	VR122	R423	—
1102008	VR122	R423	5242
1102009	VR122	R423	5242
1102010	—	R423	5242
1102011	VR122	R423	5242
1102012	VR122	R423	5242
1102013	VR122	R423	5242
1102014	VR122	R423	5242
1102018	VR122	R423	5242
1102020	VR122	R423	—
1102021	VR122	R423	5242
1102022	VR122	R423	5242
1102023	VR123 ¹⁹	R423	5242
1102023	VR894 ¹¹	R423	5242
1102024	VR123	R423	—
1102025	VR122	R423	—
1102026	VR122	R423	—
1102027	VR126	R423	—
1102028	VR122	R423	5242
1102029	—	R423	5242
1102030	—	R423	—
1102031	VR126	R423	5242

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1102032	VR122	R423	5242
1102033	VR122	R423	5242
1102034	—	R423	—
1102038	—	R423	—
1102039	VR126	R423	5242
1102040	VR122 ¹¹	R423	—
1102040	VR56 ¹⁹	R423	—
1102041	VR122	R423	—
1102042	VR122	R423	5242
1102043	VR122	R423	—
1102044	—	R423	—
1102045	—	R423	5242
1102046	—	R423	—
1102049	VR122	R423	5242
1102050	—	R423	—
1102051	VR126	R423	5242
1102052	VR126	R423	—
1102053	VR126	R423	5242
1102054	VR126	R423	—
1102055	VR126	R423	—
1102056	VR122	R426	—
1102057	—	R423	5242
1102059	VR122	R423	—
1102060	VR128	R426	—
1102061	VR126	R423	—
1102062	VR891	R423	—
1102063	VR122	R423	5242
1102065	VR122	R423	5242
1102066	VR126	R423	—
1102067	VR126	R423	5242
1102068	VR122	R423	—
1102069	—	R423	—
1102070	—	R423	—
1102071	—	R423	—
1102072	—	R423	—
1102073	VR122 ¹	R423	—
1102073	VR126 ^{11,17}	R423	—
1102074	VR128	R423	—
1102075	VR891	R423	—
1102076	VR891	R423	—
1102077	VR128	R423	—
1102078	—	R423	—
1102079	VR126	R423	—
1102080	—	R423	—
1102081	VR126	R423	—
1102082	—	R423	—
1102083	VR126	R423	—
1102084	VR126	R423	—
1102085	VR122	R423	5242

(continued on next page)

¹ 27-31 Amp ¹¹ Negative ground ¹⁷ 32-36 Amp ¹⁹ Positive ground

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1102086	VR126	R423	—
1102087	VR126	R423	—
1102088	VR122	R423	—
1102091	VR128	R423	—
1102092	VR126	R423	—
1102093	VR128	R423	—
1102094	VR122	R423	—
1102096	VR122	R423	5242
1102097	VR122	R423	5242
1102099	VR126	R423	—
1102100	VR128	R423	—
1102101	VR128	R423	—
1102102	VR123	R404	—
1102103	VR128	R423	—
1102104	VR128	R423	—
1102105	VR128	R423	—
1102106	—	R423	—
1102107	VR122	R423	—
1102108	—	R423	—
1102109	VR126	R423	—
1102113	VR122	R423	—
1102114	VR126	R423	—
1102115	VR126	R423	—
1102116	—	R423	5242
1102117	—	R423	5242
1102118	—	R423	5242
1102119	VR894	R423	5242
1102120	VR122	R423	—
1102122	VR128	R423	—
1102123	VR128	R423	—
1102124	VR122	R423	—
1102125	VR126	R423	—
1102127	VR128	R423	—
1102128	VR122	R423	—
1102129	VR122	R423	—
1102132	VR128	R423	—
1102134	VR128	R423	—
1102135	—	R423	—
1102136	VR891	R404	—
1102138	VR128	R423	—
1102139	VR122	—	—
1102140	VR126	R423	—
1102141	VR128	R423	—
1102142	VR122	R423	—
1102143	VR128	R423	—
1102144	—	R423	—
1102145	—	R423	—
1102146	VR122	R423	—
1102147	VR126	R423	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1102148	VR122	R423	—
1102150	VR126	R423	—
1102152	VR891	R423	—
1102153	VR891	R423	—
1102158	VR122	R423	—
1102159	—	R423	—
1102163	VR122	R423	—
1102164	VR122	R423	—
1102165	VR126	R423	—
1102166	VR126	R423	—
1102167	VR122	R423	—
1102168	VR122 ¹	R426	—
1102168	VR126 ¹⁷	R426	—
1102169	—	R423	—
1102170	VR126	R423	—
1102171	VR206	R423	—
1102172	VR206	R423	—
1102173	VR126	R423	—
1102174	VR126	R423	—
1102175	VR126	R423	—
1102176	VR126	R423	—
1102177	VR126	R423	—
1102178	—	R423	—
1102179	—	R423	—
1102180	—	R423	—
1102181	VR126	R423	—
1102182	—	R423	—
1102183	VR126	R423	—
1102184	—	R423	—
1102186	—	R423	—
1102187	—	R423	—
1102188	—	R423	—
1102189	—	R423	—
1102190	—	R423	—
1102191	—	R423	—
1102192	—	R423	—
1102193	VR122	R423	—
1102194	—	R423	—
1102197	VR128	R423	—
1102198	VR128	R423	—
1102199	VR126	R423	—
1102200	VR126	R423	—
1102201	VR122	R423	—
1102202	VR126	R423	—
1102203	VR122	R423	—
1102204	—	R423	—
1102205	—	R423	—
1102206	—	R423	—
1102209	VR122	R423	—

(continued on next page)

¹ 27-31 Amp ¹⁷ 32-36 Amp

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1102210	VR122	R423	—
1102213	—	R423	—
1102214	—	R423	—
1102215	VR128	R423	—
1102216	VR891	R423	—
1102217	VR126	R423	—
1102219	—	R423	—
1102220	VR128	R423	—
1102222	VR122	R423	—
1102223	VR128	R423	—
1102224	VR122 ¹⁶	R423	—
1102224	VR128 ²⁰	R423	—
1102225	—	R423	—
1102226	VR122	R423	—
1102227	VR122	R423	5242
1102228	VR122	R423	—
1102229	—	R423	—
1102230	VR128	R423	—
1102231	VR128	R423	—
1102235	VR126	R423	—
1102236	VR126	R423	—
1102237	VR122	R423	—
1102239	—	R423	—
1102240	VR126	R423	—
1102241	—	R423	—
1102242	—	R423	—
1102243	—	R423	—
1102244	—	R423	—
1102245	—	R423	—
1102246	—	R423	—
1102248	VR122	R423	5242
1102249	—	R423	—
1102250	—	R423	—
1102251	—	R423	—
1102252	—	R423	—
1102253	—	R423	—
1102254	VR891	R423	—
1102255	VR122	R423	—
1102256	VR125 ¹⁹	R423	—
1102256	VR136 ¹¹	R423	—
1102257	VR126	R423	—
1102258	—	R423	—
1102259	—	R423	—
1102260	—	R423	—
1102261	VR128	R423	—
1102262	—	R423	—
1102263	VR122	R423	—
1102264	VR126	R423	—
1102265	VR126	R423	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1102266	VR122	R423	—
1102267	VR122	R423	—
1102268	VR126	R423	—
1102269	VR122	R423	—
1102270	—	R423	—
1102271	VR128	R423	—
1102272	—	R423	—
1102273	VR122	R423	—
1102274	VR126	R423	—
1102275	VR891	R423	—
1102276	—	R423	—
1102277	VR128	R423	—
1102279	VR128	R423	—
1102280	—	R423	—
1102281	VR891	R423	—
1102282	VR894	R423	—
1102287	—	R423	—
1102288	VR123	R423	—
1102293	—	R423	—
1102299	VR122	R423	—
1102300	VR126	R423	—
1102301	VR128	R423	—
1102302	VR126	R423	—
1102303	VR126	R423	—
1102304	VR126	R423	—
1102306	VR122	R423	—
1102307	VR126	R423	—
1102308	VR122	R423	—
1102309	VR128	R423	—
1102310	VR126	R423	—
1102311	VR122	R423	—
1102312	—	R423	—
1102313	VR126	R423	—
1102314	VR128	R423	—
1102315	VR126	R423	—
1102316	—	R423	—
1102317	VR126	R423	—
1102318	VR128	R423	—
1102319	VR126	R423	—
1102326	VR126	R423	—
1102327	VR126	R423	—
1102328	—	R423	—
1102329	VR122	R423	—
1102331	VR891	—	—
1102332	VR126	R423	—
1102333	VR122	R423	—
1102334	VR122	R423	—
1102335	VR894	R423	—
1102336	VR126	—	—

(continued on next page)

¹¹ Negative ground ¹⁶ 31 Amp ¹⁹ Positive ground ²⁰ 40 Amp

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1102337	VR122	R423	—
1102338	VR122	R423	—
1102339	VR891	R423	—
1102340	—	R423	—
1102341	—	R423	—
1102342	VR894	R423	—
1102343	VR891	R423	—
1102344	VR128	R423	—
1102345	VR128	R423	—
1102357	—	R423	—
1102401	—	R1001	—
1102402	—	R404	5242
1102403	—	R404	5242
1102404	—	R404	—
1102405	—	R1001	—
1102406	—	R1001	—
1102407	—	R404	5242
1102408	—	R404	5242
1102410	—	R1001	5242
1102411	—	R1001	—
1102412	—	R1001	—
1102413	—	R404	5242
1102414	—	R1001	—
1102415	—	R404	5242
1102416	—	R1001	—
1102417	—	R404	5242
1102418	—	R404	5242
1102419	—	R404	5242
1102420	—	R404	—
1102421	—	R404	—
1102422	—	R404	—
1102423	—	R404	—
1102424	—	R404	—
1102425	—	R404	—
1102426	—	R404	—
1102427	—	R404	—
1102428	—	R404	—
1102429	—	R404	—
1102430	—	R404	—
1102432	VR56	R404	5242
1102501	—	R1001	5242
1102502	—	R1001	—
1102503	—	R1001	—
1102504	—	R1001	—
1102505	—	R1001	—
1102506	—	R1001	—
1102507	—	R1001	—
1102508	—	R1001	—
1102509	—	R1001	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1102510	—	R1001	—
1102511	—	R1001	—
1102512	—	R1001	—
1102513	—	R1001	—
1102514	—	R1001	—
1102515	—	R1001	—
1102516	—	R1001	—
1102517	—	R1001	—
1102518	—	R1001	—
1102519	—	R1001	—
1102520	—	R1001	—
1102521	—	R1001	—
1102522	—	R1001	—
1102523	—	R1001	—
1102524	—	R1001	—
1102525	—	R1001	—
1102526	—	R1001	—
1102527	—	R1001	—
1102528	—	R404	—
1102529	—	R404	—
1102530	—	R1001	—
1102531	—	R1001	—
1102533	—	R404	—
1102534	—	R404	5242
1102535	—	R1001	—
1102536	—	R404	—
1102537	—	R404	—
1102538	—	R404	5242
1102539	—	R404	5242
1102540	—	R404	—
1102541	—	R404	—
1102546	—	R404	5242
1102567	VR56	R413	5242
1102575	—	R1001	—
1102651	VR56	R423	—
1102652	VR56	R423	—
1102653	VR56	R423	—
1102654	VR56	R423	—
1102655	VR56	R423	—
1102656	VR56	R423	—
1102657	VR56	R423	—
1102658	—	R404	—
1102659	—	R404	—
1102660	VR56	R423	5242
1102661	VR56	R413	5242
1102662	VR56	R413	5242
1102663	VR56	R413	5242
1102664	VR56	R413	5242
1102665	VR56	R413	5242

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1102666	VR56	R413	—
1102667	VR56 ¹¹	R413	5242
1102667	VR56 ¹⁹	R413	5242
1102668	VR56	R413	5242
1102669	VR56	R413	5242
1102670	VR56 ¹⁹	R413	5242
1102671	VR56	R413	5242
1102672	VR56	R413	5242
1102673	VR56 ¹¹	R413	5242
1102673	VR56 ¹⁹	R413	5242
1102674	VR56 ¹¹	R413	5242
1102674	VR56 ¹⁹	R413	5242
1102675	VR56 ¹¹	R413	5242
1102675	VR56 ¹⁹	R413	5242
1102676	VR56	R404	—
1102677	VR56 ¹¹	R413	5242
1102677	VR56 ¹⁹	R413	5242
1102678	VR56 ¹¹	R413	5242
1102678	VR56 ¹⁹	R413	5242
1102679	VR56	R413	5242
1102680	VR56	R413	5242
1102681	VR56	R413	5242
1102682	VR56	R413	5242
1102683	VR56	R413	5242
1102684	VR56	R413	—
1102685	—	R413	—
1102686	VR56	R413	5242
1102687	VR56	R404	5242
1102688	—	R413	5242
1102689	VR56	R413	—
1102690	VR56	R413	—
1102691	VR56	R413	5242
1102692	VR56	R413	5242
1102693	VR56 ¹¹	R413	5242
1102693	VR56 ¹⁹	R413	5242
1102694	VR56 ¹¹	R413	5242
1102694	VR56 ¹⁹	R413	5242
1102697	VR56	R413	5242
1102699	VR56	R413	—
1102700	VR1071 ¹¹	R413	—
1102700	VR56 ¹⁹	R413	—
1102701	VR56	R413	5242
1102702	VR56	R413	—
1102704	VR1071	R413	—
1102705	VR56	R413	—
1102706	VR1071	R413	—
1102707	VR1071	R413	—
1102708	VR1071	R413	5242
1102709	VR1071	R413	5242

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1102710	VR56 ¹¹	R413	—
1102710	VR56 ¹⁹	R413	—
1102711	VR56	R413	—
1102712	VR56	R413	5242
1102713	VR56 ¹¹	R413	5242
1102713	VR56 ¹⁹	R413	5242
1102714	VR56	R413	5242
1102715	VR56	R413	—
1102716	—	R413	5242
1102717	VR56 ¹⁹	R413	4347
1102718	—	R413	5242
1102719	VR56	R413	—
1102720	VR56	R413	—
1102721	VR56	R413	5242
1102722	VR56	R413	5242
1102723	VR56	R413	5242
1102724	VR56	R413	5242
1102725	VR56	R413	—
1102726	VR56	R423	5242
1102727	VR56	R404	5242
1102728	VR56	R413	5242
1102729	VR1071	R413	5242
1102730	VR56	R413	—
1102731	VR1071 ^{11,18}	R413	5242
1102731	VR1071 ^{19,18}	R413	5242
1102731	VR56 ^{11,23}	R413	5242
1102731	VR56 ^{19,23}	R413	5242
1102732	VR56	R413	5242
1102733	VR56	R413	5242
1102734	VR56	R413	—
1102735	VR56	R404	—
1102736	VR56	R413	5242
1102737	VR56	R413	—
1102738	—	R413	5242
1102739	—	R413	5242
1102740	VR56	R413	—
1102741	VR1071	R413	5242
1102742	VR56	R413	—
1102743	VR56	R413	5242
1102744	VR56	R413	—
1102745	VR56	R413	5242
1102746	VR56	R413	5242
1102747	VR56	R413	5242
1102748	VR56	R413	5242
1102749	VR56 ¹¹	R413	5242
1102749	VR56 ¹⁹	R413	5242
1102750	VR1071	R413	5242
1102751	VR56	R413	5242
1102752	VR56	R413	5242

(continued on next page)

¹¹ Negative ground ¹⁸ 37-42 Amp ¹⁹ Positive ground ²³ 38-42 Amp

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1102753	VR56	R413	5242
1102754	VR1071	R413	5242
1102757	VR1071	R413	5242
1102761	VR56 ¹¹	R413	5242
1102761	VR56 ¹⁹	R413	5242
1102766	—	R413	—
1102769	VR1071	R423	5242
1102770	VR1071	R413	—
1102771	VR1071	R413	5242
1102773	VR1071	R413	5242
1102774	VR1071	R413	5242
1102775	VR1071	R413	5242
1102776	VR56	R423	5242
1102777	VR1071	R423	5242
1102778	VR1071 ¹⁹	R423	5242
1102778	VR57 ¹⁸	R423	5242
1102779	VR1071	R423	5242
1102780	VR1071	R423	5242
1102781	VR1071	R423	5242
1102782	VR56	R423	5242
1102784	VR1071	R423	5242
1102785	VR1071 ¹¹	R423	5242
1102785	VR1071 ¹⁹	R423	5242
1102786	VR1071	R423	5242
1102787	VR1071	R423	5242
1102788	VR1071 ¹⁹	R423	—
1102788	VR56 ¹⁹	R423	—
1102789	VR56	R423	5242
1102793	VR1071 ¹¹	R423	5242
1102793	VR1071 ¹⁹	R423	5242
1102794	VR1071	R423	5242
1102797	VR1071	R423	5242
1102798	VR1071	R423	—
1102799	—	R413	5242
1102803	VR1071 ¹¹	R423	5242
1102803	VR1071 ¹⁹	R423	5242
1102804	VR1071	R413	—
1102805	VR1071	R423	5242
1102806	VR1071	R423	5242
1102807	—	R423	—
1102808	VR56 ¹⁹	R423	5242
1102808	VR851 ^{19,26}	R423	5242
1102810	—	R423	5242
1102811	VR1071 ¹¹	R423	5242
1102811	VR56 ¹⁹	R423	5242
1102812	VR1071	R423	5242
1102813	VR1071	R423	—
1102814	—	R423	—
1102815	VR1071	R423	5242

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1102816	VR56 ¹¹	R423	—
1102816	VR56 ¹⁹	R423	—
1102818	VR1071	R423	—
1102819	VR56	R423	5242
1102820	VR1071	R423	—
1102820	VR851 ^{19,26}	R423	—
1102821	—	R423	5242
1102822	—	R423	5242
1102823	VR56	R404	5242
1102824	VR1071	R423	—
1102825	VR1071	R423	—
1102827	VR56	R423	—
1102828	VR1071	—	—
1102830	—	R423	—
1102831	VR22	R423	—
1102832	—	R423	—
1102833	—	R423	—
1102834	—	R413	5242
1102835	—	R423	—
1102836	VR1071	R423	—
1102837	—	R423	—
1102838	VR56	R423	—
1102848	VR56	R423	—
1102950	VR123 ¹⁹	R404	5242
1102951	—	R404	5242
1102952	—	R404	5242
1102953	VR123	R413	5242
1102954	VR123	R413	5242
1102955	VR123 ¹⁹	R413	5242
1102956	VR123	R404	5242
1102957	VR123	R404	—
1102958	—	R404	—
1102959	VR123	R413	5242
1102960	VR123	R404	5242
1102961	VR123	R413	—
1102962	VR123	R413	5242
1102963	VR123	R413	5242
1102965	—	—	5242
1102966	VR123	R413	5242
1102967	VR123	R413	5242
1102968	VR123	R404	—
1102970	VR123	R404	5242
1102971	VR123	R404	5242
1102972	—	R404	5242
1102973	—	R404	5242
1102974	—	R413	—
1102975	VR896	R413	5242
1102976	VR123 ¹⁹	R413	5242
1102977	—	R413	5242

(continued on next page)

¹¹ Negative ground ¹⁸ 37-42 Amp ¹⁹ Positive ground ²⁶ Tractor application

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1102978	VR123	R413	—
1102979	VR123	R413	5242
1102980	VR123	R413	5242
1102981	VR123	R413	5242
1102982	—	R404	5242
1102983	—	R404	5242
1102984	VR123	R404	—
1102985	VR123 ¹⁹	R413	5242
1102987	VR123 ¹⁹	R413	5242
1102988	VR123	R404	5242
1102996	VR123	R413	5242
1102997	VR123	R404	5242
1103000	—	R413	5242
1103001	—	R1001	—
1103004	—	R404	5242
1103008	—	R404	5242
1103009	VR893	R423	—
1103010	—	R404	5242
1103011	VR122	R423	—
1103012	—	R404	5242
1103013	—	R404	5242
1103014	VR893	R404	5242
1103015	—	R423	—
1103016	VR893	R423	—
1103017	VR893	R423	—
1103018	—	R423	—
1103019	VR893	R423	—
1103021	VR893	R404	5242
1103023	—	R423	—
1103026	VR893	R423	—
1103027	—	R423	—
1103028	VR893	R423	—
1103029	VR893	R423	—
1103030	VR893	R423	—
1103031	VR893	R423	—
1103032	VR893	R423	—
1105001	VR123	R428	—
1105002	VR1071	R428	—
1105003	VR56	R428	—
1105004	VR56	R428	—
1105005	VR122	R428	—
1105006	—	R428	—
1105007	VR56 ¹⁹	R428	—
1105008	—	R428	—
1105009	VR1071 ¹¹	R428	—
1105009	VR56 ¹⁹	R428	4347
1105010	VR1071 ¹¹	R428	—
1105010	VR56 ¹⁹	R428	—
1105011	VR56 ¹⁹	R428	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1105013	VR56 ¹⁹	R428	—
1105014	—	R428	—
1105017	—	R428	—
1105018	VR56 ¹⁹	R423	—
1105019	VR123	R428	—
1105020	VR56	R423	—
1105021	VR56	R423	—
1105052	—	R428	—
1105053	—	R428	—
1105054	—	R428	—
1105055	—	R428	—
1105056	—	R428	—
1105057	—	R428	—
1105101	—	R428	—
1105102	—	R423	—
1105103	VR123	R428	—
1105105	VR126	R428	—
1105106	VR891 ¹⁹	R423	—
1105109	VR891 ¹⁹	R423	—
1105110	—	R428	—
1105111	—	R428	—
1105112	VR122	R428	—
1105113	VR126	R428	—
1105115	—	R428	—
1105116	VR126	R428	—
1105117	VR136	R428	—
1105118	VR126	R428	—
1105119	VR122	R423	—
1105120	VR126	R428	—
1105121	VR891 ¹⁹	R423	—
1105122	VR122	R423	—
1105123	VR128	R428	—
1105124	VR128	R428	—
1105125	VR128	R428	—
1105126	—	R423	—
1105127	VR126	R428	—
1105129	VR126	—	—
1105130	VR128	R428	—
1105131	VR126	R428	—
1105132	VR128	R428	—
1105134	—	R423	—
1105135	VR126	R428	—
1105136	—	R428	—
1105137	—	R423	—
1105138	—	R428	—
1105139	VR136	R428	—
1105140	—	R423	—
1105141	VR122	R423	—
1105142	VR122	R423	—

(continued on next page)

¹¹ Negative ground ¹⁹ Positive ground

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing	Unit No	Voltage Regulator	Brush Set	Bushing
1105143	VR122	R428	—	1105380	—	R404	—
1105144	—	R423	—	1105381	—	R404	—
1105145	VR126	R428	—	1105382	—	R404	—
1105146	VR128	R428	—	1105384	—	R404	—
1105147	—	R428	—	1105385	—	R404	—
1105148	VR126	R428	—	1105386	—	R404	—
1105150	—	R428	—	1105401	VR56	—	—
1105151	—	R428	—	1105526	—	R404	—
1105152	—	R428	—	1105527	—	R404	—
1105153	—	R428	—	1105528	—	R404	—
1105154	—	R428	—	1105529	—	R404	—
1105155	VR122	—	—	1105530	—	R404	—
1105156	VR122	R423	—	1105531	VR56 ¹⁹	R404	—
1105158	VR122	R423	—	1105532	VR56 ¹⁹	R404	—
1105201	VR123 ¹⁹	R404	—	1105726	VR123	R404	—
1105204	—	R423	—	1105727	VR123	R404	—
1105205	—	R423	—	1105728	VR123	R404	—
1105206	—	R428	—	1105729	—	R404	—
1105207	—	R423	—	1105730	VR123	R404	—
1105208	—	R423	—	1105731	VR123	R404	—
1105209	—	R423	—	1105732	VR123	R404	—
1105210	VR152	R423	—	1105733	VR123	R404	—
1105211	VR152	R423	—	1105734	VR123	R404	—
1105212	—	R428	—	1105735	VR123	R404	—
1105214	—	R428	—	1105736	VR123	R404	—
1105215	—	R428	—	1105738	VR123 ¹⁹	R404	—
1105216	VR152	R423	—	1105739	VR123	R404	—
1105217	—	R423	—	1105740	VR123	R404	—
1105218	—	R423	—	1105741	VR123	R404	—
1105219	—	R423	—	1105742	VR123	R404	—
1105220	—	R423	—	1105743	VR123	R404	—
1105221	—	R428	—	1105744	VR123	R404	—
1105222	VR152 ¹⁹	R423	—	1105745	VR123	R404	—
1105225	VR152 ¹⁹	R428	—	1105746	VR123	R404	—
1105226	—	R404	—	1105747	VR123	R404	—
1105227	—	R404	—	1105748	VR123	R404	—
1105228	—	R423	—	1105749	VR123	R404	—
1105232	VR152 ¹⁹	R428	—	1105750	VR123	R404	—
1105233	VR152 ¹⁹	R428	—	1105751	—	R404	—
1105235	VR152	—	—	1105752	—	R404	—
1105236	VR152	R423	—	1105753	—	R404	—
1105237	VR152	—	—	1105754	—	R404	—
1105241	VR152	—	—	1105755	—	R404	—
1105326	—	R404	—	1105756	—	R404	—
1105327	—	R1001	—	1105757	—	R404	—
1105376	—	R1001	—	1105758	—	R404	—
1105377	—	R404	—	1105759	—	R404	—
1105378	—	R404	—	1105760	—	R404	—
1105379	—	R1001	—	1105761	—	R404	—

(continued on next column)

(continued on next page)

¹⁹ Positive ground

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1105762	—	R404	—
1105763	—	R404	—
1105764	—	R404	—
1105765	—	R404	—
1105766	—	R404	—
1105767	—	R404	—
1105768	—	R404	—
1105769	—	R404	—
1105770	—	R404	—
1105776	—	R404	—
1105777	—	R404	—
1105778	—	R404	—
1105779	—	R404	—
1105780	—	R404	—
1105781	VR123	R404	—
1105782	VR56	R404	—
1105827	VR125	—	—
1105832	VR123	—	—
1105851	VR56	R413	5242
1105852	—	R413	5242
1105853	—	R413	5242
1105854	—	R413	5242
1105855	VR56	R413	5242
1105856	VR56	R413	5242
1105857	VR56	R413	5242
1105858	VR56	R413	5242
1105859	—	R413	—
1105860	—	R413	—
1105861	—	R413	—
1105862	—	R413	—
1105863	—	R413	—
1105864	—	R413	—
1105865	VR56	R413	—
1105866	—	R413	—
1105867	—	R413	—
1105868	VR56	R413	—
1105869	—	R413	—
1105870	—	R413	—
1105871	—	R413	5242
1105872	—	R413	5242
1105873	—	R413	5242
1105874	—	—	5242
1105875	VR56	R413	—
1105876	VR56	R413	—
1105877	—	R413	—
1105878	VR56	R413	—
1105879	VR56	R413	—
1105880	VR56	R413	—
1105881	VR56 ¹¹	R413	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1105881	VR56 ¹⁹	R413	—
1105882	—	R413	—
1105883	—	R413	—
1105884	VR56 ¹¹	R413	—
1105884	VR56 ¹⁹	R413	—
1105885	VR56 ¹¹	R413	—
1105885	VR56 ¹⁹	R413	—
1105886	VR56 ¹¹	R413	—
1105886	VR56 ¹⁹	R413	—
1105887	VR56 ¹¹	R413	—
1105887	VR56 ¹⁹	R413	—
1105889	VR56 ¹¹	R413	—
1105889	VR56 ¹⁹	R413	—
1105890	VR56	R413	—
1105891	VR56	R413	—
1105892	VR56	R428	5242
1105893	VR56	R428	—
1105894	VR56	R428	—
1105895	VR56	R428	—
1105896	VR56	R428	—
1105897	VR123	R428	—
1105898	—	R428	5242
1105899	VR123	R428	—
1105900	VR123	R428	—
1105902	—	R413	—
1105903	—	R413	—
1105904	—	R413	—
1105905	—	R413	—
1105906	—	R413	—
1105907	—	R413	—
1105909	VR123 ¹⁹	R413	—
1105909	VR894 ¹¹	R413	—
1105910	VR126	R413	—
1105912	VR123	R413	—
1105913	VR123	R413	—
1105914	VR123 ¹⁹	R413	—
1105915	VR123 ¹⁹	R413	—
1105915	VR894 ¹¹	R413	—
1105916	VR123	R413	—
1105917	VR123	R413	—
1105918	VR123	R413	—
1105919	VR123	R413	—
1105920	VR123	R413	—
1105921	—	R413	—
1105922	—	R413	—
1105923	VR123	R413	—
1105924	VR123	R413	—
1105925	VR123	R413	—
1105926	VR123 ¹⁹	R413	—

(continued on next page)

¹¹ Negative ground ¹⁹ Positive ground

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing	Unit No	Voltage Regulator	Brush Set	Bushing
1105930	VR123	R413	—	1106101	VR125 ¹⁹	R419	—
1105931	VR123	R413	—	1106101	VR136 ¹¹	R419	—
1105935	—	R428	—	1106102	VR125 ¹⁹	R419	—
1105936	VR126	R428	—	1106102	VR136 ¹¹	R419	—
1105937	—	R428	—	1106103	VR125 ¹⁹	R419	—
1105938	—	R428	—	1106103	VR136 ¹¹	R419	—
1105939	VR123 ¹⁹	R428	—	1106104	VR125 ¹⁹	R419	—
1105939	VR126 ¹¹	R428	—	1106104	VR136 ¹¹	R419	—
1105940	VR891	R428	—	1106105	—	R419	—
1105941	VR123 ¹⁹	R428	—	1106106	VR136	R419	—
1105942	VR891	R428	—	1106107	VR136	R419	—
1105943	VR123	R413	—	1106108	VR136	R419	—
1105944	VR126	R428	5242	1106109	VR136	R419	—
1105946	VR122	R428	—	1106110	VR136	R419	—
1105947	VR122	R428	—	1106111	VR125 ¹⁹	R419	—
1105949	VR123	R428	—	1106111	VR136 ¹¹	R419	—
1105950	—	R413	—	1106112	VR125 ¹⁹	R419	—
1105951	—	R413	—	1106112	VR136 ¹¹	R419	—
1105952	—	R413	—	1106403	VR56 ¹¹	—	—
1105953	—	R413	—	1106403	VR56 ¹⁹	—	—
1105954	—	R413	—	1106405	VR56	—	—
1105957	—	R428	—	1106406	VR56	—	—
1105958	VR893	R413	—	1106451	—	R413	—
1105963	VR893	R428	—	1106452	VR891	R404	—
1105967	—	R413	—	1106453	VR891	R404	—
1105969	VR893	R428	—	1106454	VR891	R404	—
1105970	—	R428	—	1106455	—	R413	—
1105971	—	R428	—	1106456	VR891	R404	—
1105972	—	R413	—	1106457	—	R413	—
1105976	VR152	R428	—	1106458	—	R413	—
1105977	—	R428	—	1106459	—	R413	—
1105979	—	R428	—	1106460	VR891	R404	—
1105981	—	R428	—	1106461	—	R413	—
1105982	VR152	R413	—	1106501	—	R404	—
1105983	—	R428	—	1106502	—	R404	—
1105984	—	R413	—	1106503	—	R404	—
1105985	—	R428	—	1106504	—	R404	—
1105988	VR152	R428	—	1106505	—	R404	—
1105990	—	R423	—	1106506	—	R404	—
1105991	—	R423	—	1106507	—	R404	—
1105992	—	R423	—	1106508	—	R404	—
1105994	—	R428	—	1106509	—	R404	—
1105995	—	R423	—	1106510	—	R404	—
1105997	—	R423	—	1106511	—	R404	—
1105998	—	R428	—	1106512	—	R404	—
1105999	VR152	R423	—	1106514	—	R404	—
1106052	VR123	—	—	1106515	—	R404	—
1106053	—	R419	—	1106516	—	R404	—
1106054	—	R419	—	1106517	—	R404	—

(continued on next column)

(continued on next page)

¹¹ Negative ground ¹⁹ Positive ground

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing	Unit No	Voltage Regulator	Brush Set	Bushing
1106518	—	R404	—	1106640	VR123	—	—
1106526	—	R404	—	1106641	VR123	—	—
1106527	—	R404	—	1106642	VR123	—	—
1106528	—	R404	—	1106643	VR123	—	—
1106529	—	R404	—	1106645	VR123	—	—
1106530	—	R404	—	1106651	VR123	—	—
1106531	—	R404	—	1106653	VR126	—	—
1106532	—	R404	—	1106660	VR123	—	—
1106533	—	R404	—	1106666	VR126	—	—
1106534	—	R404	—	1106676	VR136	—	—
1106535	—	R404	—	1106678	VR125 ¹⁹	—	—
1106536	—	R404	—	1106678	VR136 ¹¹	—	—
1106537	—	R404	—	1106680	VR125 ¹⁹	—	—
1106538	—	R404	—	1106680	VR136 ¹¹	—	—
1106539	—	R413	—	1106681	VR136 ¹¹	—	—
1106541	—	R404	—	1106744	VR56	R413	5242
1106542	—	R404	—	1106751	VR123 ¹¹	R419	—
1106544	—	R404	—	1106751	VR56 ¹⁹	R419	—
1106548	—	R404	—	1106752	—	R419	—
1106577	VR56	—	—	1106753	VR56	R419	—
1106578	VR56	—	—	1106754	VR56	R419	—
1106579	VR56	—	—	1106755	VR56	R419	—
1106580	VR56	—	—	1106756	VR1071	R419	—
1106581	VR56	—	—	1106757	—	R419	—
1106582	VR56	—	—	1106758	VR1071 ¹¹	R419	—
1106584	VR56	—	—	1106758	VR1071 ¹⁹	R419	—
1106585	VR56	—	—	1106759	VR56	R419	—
1106586	VR56	—	—	1106760	VR56	R419	—
1106587	VR56	—	—	1106761	VR56	R419	—
1106588	VR56	—	—	1106762	—	R419	—
1106589	VR56	—	—	1106763	VR56	R419	—
1106590	VR56	—	—	1106764	VR1071 ¹⁹	R419	—
1106592	VR123	—	—	1106764	VR123 ¹¹	R419	—
1106593	VR56	—	—	1106765	VR123	R419	—
1106626	VR123	—	—	1106766	VR56	R419	—
1106627	VR123	—	—	1106768	VR56	R419	—
1106628	VR123 ¹⁹	—	—	1106769	VR1071 ¹¹	R419	—
1106628	VR894 ¹¹	—	—	1106769	VR1071 ¹⁹	R419	—
1106629	VR123	—	—	1106772	VR56	R419	—
1106630	VR123	—	—	1106773	VR1071 ¹¹	R419	—
1106631	VR123	—	—	1106773	VR1071 ¹⁹	R419	—
1106632	VR123 ¹⁹	—	—	1106774	VR1071 ¹¹	R419	—
1106632	VR894 ¹¹	—	—	1106774	VR1071 ¹⁹	R419	—
1106633	VR122	R423	—	1106775	VR56 ¹¹	R419	—
1106635	VR123	—	—	1106775	VR56 ¹⁹	R419	—
1106636	VR123	—	—	1106776	VR1071	R419	—
1106637	VR123	—	—	1106777	VR56	R419	—
1106638	VR123	—	—	1106778	VR56	R419	—
1106639	VR123	—	—	1106779	—	R419	—

(continued on next column)

(continued on next page)

¹¹ Negative ground ¹⁹ Positive ground

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1106780	VR1071	R419	—
1106781	VR56	—	—
1106782	VR125	—	—
1106801	VR126	R419	—
1106802	VR125	R419	—
1106803	VR126	R419	—
1106804	—	R419	—
1106805	VR125	R419	—
1106806	VR126	R419	—
1106807	VR126	R419	—
1106808	VR125	R419	—
1106809	VR125	R419	—
1106810	VR125	R419	—
1106811	VR125	R419	—
1106812	VR126	R419	—
1106813	VR126	R419	—
1106814	VR126	R419	—
1106815	VR125	R419	—
1106816	VR126	R419	—
1106817	VR126	R419	—
1106818	—	R419	—
1106819	VR126	R419	—
1106820	VR126	R419	—
1106821	—	R419	—
1106822	—	R419	—
1106823	VR125	R419	—
1106824	—	R419	—
1106825	VR126	R419	—
1106826	VR125	R419	—
1106827	VR125	R419	—
1106828	VR126	R419	—
1106829	VR126	R419	—
1106830	VR125	R419	—
1106831	—	R419	—
1106832	VR126	R419	—
1106833	VR126	R419	—
1106834	VR126	R419	—
1106835	VR125	R419	—
1106836	VR125	R419	—
1106837	VR125	R419	—
1106838	VR125	R419	—
1106839	VR125	R419	—
1106840	VR125	R419	—
1106841	—	R419	—
1106842	VR125	R419	—
1106843	VR125	R419	—
1106844	VR125	R419	—
1106845	VR125	R419	—
1106846	VR125	R419	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1106847	VR126	R419	—
1106848	VR125	R419	—
1106849	VR125	R419	—
1106850	VR126	R419	—
1106851	VR152	R419	—
1106852	VR152	R419	—
1106853	VR152	R419	—
1106854	VR152	R419	—
1106855	VR152	R419	—
1106856	VR152	R419	—
1106857	VR152	R419	—
1106858	VR152	R419	—
1106859	VR152	R419	—
1106860	—	R419	—
1106861	VR893	R419	—
1106862	VR152	R419	—
1106863	—	R419	—
1106864	—	R419	—
1106865	VR893	R419	—
1106866	—	R419	—
1106867	VR152	R419	—
1106868	VR152	R419	—
1106869	VR56	R419	—
1106870	—	R419	—
1106871	VR152	R419	—
1106874	VR152	R419	—
1106875	VR893	R419	—
1106876	VR152	R419	—
1106882	VR125	R419	—
1106883	VR152	R419	—
1106884	VR152	R419	—
1106885	VR152	R419	—
1106886	VR152	R419	—
1106887	VR152	R419	—
1106888	VR152	R419	—
1106889	VR152	R419	—
1106890	VR152	R419	—
1106891	VR152	R419	—
1106892	VR152	R419	—
1106893	VR152	R419	—
1106894	VR152	R419	—
1106895	VR136	R419	—
1106896	—	R419	—
1106897	—	R419	—
1106898	—	R419	—
1106899	VR152	R419	—
1106904	VR125 ¹⁹	R419	—
1106907	VR125	R419	—
1106909	VR122 ¹	R419	—

(continued on next page)

¹ 27-31 Amp ¹⁹ Positive ground

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing	Unit No	Voltage Regulator	Brush Set	Bushing
1106909	VR125 ¹⁷	R419	—	1106968	—	R419	—
1106910	VR123	R419	—	1106969	—	R419	—
1106911	—	R419	—	1106970	VR152	R419	—
1106912	—	R419	—	1106972	VR152	R419	—
1106913	VR125	R419	—	1106975	—	R419	—
1106914	VR125	R419	—	1106976	VR56 ¹⁹	—	—
1106915	—	R419	—	1106977	VR56 ¹⁹	—	—
1106916	VR126	R419	—	1106978	VR125	—	—
1106917	VR123	R419	—	1106979	VR125	—	—
1106918	VR123	R419	—	1106981	VR126	—	—
1106919	VR126	R419	—	1106982	VR126	—	—
1106920	VR125 ²¹	R419	—	1106984	VR126 ¹¹	—	—
1106921	VR122	R419	—	1106986	VR125 ¹⁹	R419	—
1106922	VR123	R419	—	1106986	VR136 ¹¹	R419	—
1106923	VR123	R419	—	1106987	VR126	R419	—
1106924	VR125	R419	—	1106989	VR126	R419	—
1106926	—	R419	—	1106990	VR136 ¹¹	R419	—
1106927	—	R419	—	1106991	VR125	R419	—
1106928	VR125	R419	—	1106993	VR125 ¹⁹	R419	—
1106929	VR125	R419	—	1106993	VR136 ¹¹	R419	—
1106930	VR128	—	—	1106994	VR125 ¹⁹	R419	—
1106931	VR125	R419	—	1106994	VR136 ¹¹	R419	—
1106932	VR125	R419	—	1106995	VR125 ¹⁹	R419	—
1106934	VR125	R419	—	1106995	VR136 ¹¹	R419	—
1106935	VR125	R419	—	1106996	VR125 ¹⁹	R419	—
1106936	—	R419	—	1106996	VR136 ¹¹	R419	—
1106937	VR125	R419	—	1106997	VR125 ¹⁹	R419	—
1106940	VR125 ¹¹	R419	—	1106997	VR136 ¹¹	R419	—
1106940	VR125 ¹⁹	R419	—	1106998	VR125 ¹⁹	R419	—
1106941	VR136	—	—	1106998	VR136 ¹¹	R419	—
1106942	VR125	R419	—	1106999	—	R419	—
1106943	VR128	—	—	1110233	VR122	R423	—
1106944	—	R419	—	1112101	VR128	R423	—
1106945	VR125	R419	—	1112685	VR56	R413	—
1106946	VR136	—	—	1112686	VR56	R413	5242
1106948	VR125	R419	—	1112724	VR56	R413	5242
1106950	VR125	R419	—	1112737	VR56	R413	—
1106951	VR152	R419	—	1112770	VR1071	R413	—
1106952	—	R419	—	1112825	VR56	R423	—
1106953	—	R419	—	1117022	VR123 ¹⁹	—	—
1106954	VR152	R419	—	1117025	VR123 ¹⁹	—	—
1106955	VR152	R419	—	1117027	VR123 ¹⁹	—	—
1106956	—	R419	—	1117091	VR154	—	—
1106957	—	R419	—	1117092	VR154	—	—
1106958	—	R419	—	1117093	VR154	—	—
1106959	—	R419	—	1118838	VR125	—	—
1106960	—	R419	—	1118839	VR122	—	—
1106964	VR152	R419	—	1119156	VR125 ¹⁹	—	—
1106967	—	R419	—	1119604	VR126	—	—

(continued on next column)

(continued on next page)

¹⁷ Negative ground ¹⁷ 32-36 Amp ¹⁹ Positive ground ²¹ 50 Amp

DELCO REMY (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
1119619	VR136	—	—
1119672	VR125	—	—
1150327	—	R1001	—
1204088	—	E450	—
1204094	—	E450	—
1204163	—	E450	—
1204164	—	E450	—
1813399	—	R413	5242
1813400	—	R413	5242
1813401	—	R413	5242
1813458	—	R413	5242
1813481	—	R413	5242
1813611	—	R413	5242
1813612	—	R413	5242

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
1813624	—	R413	5242
1813663	—	R413	5242
1815860	VR126	R423	—
1816306	VR126	—	—
1816624	VR122	R423	—
1841209	CU2 ¹⁰	R1001	5242
1845551	CU2 ¹⁰	R1001	5242
1910966	VR804	—	—
1947579	VR896	R423	—
1947579	VR899	R423	—
1990270	—	R423	—

FORD-MOTORCRAFT

Unit No	Voltage Regulator	Brush Set	Bushing
B1A10002A	VR401	F404	—
B4C10002A	VR401	F404	—
B5C10002A	VR401	F404	—
B5S10002A	VR401	F404	—
B6A10002A	VR412	F404	4283
B6A10002B	—	F404	—
B6A10002E	VR204	—	—
B6A10002F	VR204	—	—
B6A10002H	VR412	F404	—
B6S10002A	VR412	F404	—
B7S10002A	VR412	F404	—
B8A10002A	VR414	F404	—
B8QH10002A ..	VR414	F404	—
B8S10002A	VR412	F404	—
B9A10002A	VR412	F404	—
B9FM10000A ..	VR414	F404	—
B9FM10002A ..	VR414	F404	—
B9FT10000A	VR412	—	—
B9FT10000B	VR412	—	—
B9FT10000C	VR412	—	—
B9FT10000D	VR412	—	—
B9LF10000B	VR136	R428	—
B9LF10002A	VR414	F404	—
B9NF10002A	VR953	F404	—
B9TF10000A	VR204	—	—
B9TF10000B	VR204	—	—
B9TF10000C	VR204	—	—
B9TF10000D	VR204	—	—
BEL10002B	—	F404	4283
BHJ10002A	—	F404	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
C0AF10000A ...	VR414	F404	—
C0AF10000B ...	VR412	F413	—
C0AF10000C ...	VR414	R428	—
C0AF10000D ...	VR414	F404	—
C0AF10000E ...	VR412	F413	—
C0AF10000F ...	VR412	F413	—
C0AF10000G ...	VR412	F413	—
C0AF10000K ...	VR414	F404	—
C0AF10002A ...	VR414	F404	—
C0AF10002B ...	—	R428	—
C0AZ10002C ...	VR414	F413	—
C0DF10000C ...	VR412	F404	—
C0DF10000D ...	VR412	F404	—
C0DF10002C ...	VR204	F404	—
C0MF10000A ...	VR414	F404	—
C0MF10002A ...	VR414	F404	—
C0NF10000A ...	VR953	F413	—
C0SF10000A ...	VR414	F404	—
C0TF10000C ...	VR412	F413	—
C0TF10000E ...	VR204	—	—
C0TF10000H ...	VR414	F413	—
C0TF10000J ...	VR412	F413	—
C0TF10002A ...	VR414	—	—
C0TF10002B ...	VR414	—	—
C0TF10002C ...	VR412	—	—
C1AF10000A ...	VR414	F404	—
C1AF10000B ...	VR414	F404	—
C1AF10000C ...	VR414	F404	—
C1AF10000D ...	VR414	F404	—
C1AF10000E ...	VR414	F404	—

(continued on next page)

¹⁰ Physical comparison is necessary or check application guide

FORD-MOTORCRAFT (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing
C1AF10000G ...	VR204	—	—
C1AF10000J ...	VR204	—	—
C1AF10000L ...	VR204	—	—
C1DF10000A ...	VR412	F413	—
C1DF10000B ...	VR412	F413	—
C1DF10000C ...	VR412	F413	—
C1DF10000D ...	VR412	F413	—
C1DF10002A ...	VR412	—	—
C1DF10002B ...	—	R428	—
C1DZ10002A ...	VR412	F413	—
C1SF10000A ...	VR414	—	—
C1SF10000B ...	—	F413	—
C1TF10000A ...	VR204	F508	—
C1TF10000AA ...	VR412	F413	—
C1TF10000AB ...	VR412	F413	—
C1TF10000AC ...	VR412	F413	—
C1TF10000AD ...	VR412	F413	—
C1TF10000AE ...	VR412	F413	—
C1TF10000AF ...	VR412	F404	—
C1TF10000AG ...	VR204	—	—
C1TF10000AH ...	VR412	F413	—
C1TF10000AJ ...	VR412	F413	—
C1TF10000AK ...	VR412	F413	—
C1TF10000BJ ...	VR412	F413	—
C1TF10000BK ...	VR412	F413	—
C1TF10000BL ...	VR412	F413	—
C1TF10000BM ...	VR412	F413	—
C1TF10000BN ...	VR412	F413	—
C1TF10000BO ...	VR412	F413	—
C1TF10000BP ...	VR412	F413	—
C1TF10000BQ ...	VR412	F413	—
C1TF10000BR ...	VR412	F413	—
C1TF10000BS ...	VR412	F413	—
C1TF10000BT ...	VR412	F413	—
C1TF10000BU ...	VR412	F413	—
C1TF10000BV ...	VR412	F413	—
C1TF10000BW ...	VR412	F413	—
C1TF10000BX ...	VR412	F413	—
C1TF10000BY ...	VR412	F413	—
C1TF10000BZ ...	VR412	F413	—
C1TF10000C ...	VR412	F404	—
C1TF10000CS ...	VR412	F413	—
C1TF10000CT ...	VR412	F413	—
C1TF10000CU ...	VR412	F413	—
C1TF10000CV ...	VR412	F413	—
C1TF10000CW ...	VR412	F413	—
C1TF10000CX ...	VR412	F413	—
C1TF10000CY ...	VR412	F413	—
C1TF10000CZ ...	VR412	F413	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
C1TF10000D ...	VR412	F404	—
C1TF10000DA ...	VR412	F413	—
C1TF10000E ...	VR204	—	—
C1TF10000F ...	VR204	—	—
C1TF10000G ...	VR412	F413	—
C1TF10000H ...	VR412	F413	—
C1TF10000J ...	VR412	F413	—
C1TF10000K ...	VR412	F413	—
C1TF10000L ...	VR412	F413	—
C1TF10000M ...	VR412	F413	—
C1TF10000N ...	VR412	F413	—
C1TF10000R ...	VR412	F413	—
C1TF10000S ...	VR412	F413	—
C1TF10000T ...	VR412	F413	—
C1TF10000U ...	VR412	F413	—
C1TF10000V ...	VR412	F413	—
C1TF10000W ...	VR412	F413	—
C1TF10000X ...	VR412	F413	—
C1TF10000Y ...	VR412	F413	—
C1TF10000Z ...	VR412	F413	—
C1TF10002A ...	VR412	F413	—
C1TZ10000A ...	VR412	F413	—
C1TZ10002A ...	VR412	F413	—
C1VF10000A ...	—	F413	—
C1VF10000B ...	VR414	F413	—
C1VF10002A ...	—	F404	—
C1VF10002B ...	VR414	F404	—
C1VF10002C ...	—	F413	—
C2AF10000B ...	VR412	F413	—
C2AF10000C ...	VR412	F413	—
C2AF10000D ...	VR412	F413	—
C2AF10000E ...	VR412	F413	—
C2AF10000F ...	VR412	F413	—
C2DF10000B ...	VR412	F413	—
C2DF10000C ...	VR412	F413	—
C2OF10000A ...	VR412	F413	—
C2OF10000B ...	VR412	F413	—
C2OF10000C ...	VR412	F413	—
C2OF10000D ...	VR412	F413	—
C2OF10000E ...	VR204	F508	—
C2OF10000F ...	VR412	F413	—
C2OF10000G ...	VR412	F413	—
C2OF10000H ...	VR412	F413	—
C2OF10000I ...	VR412	F413	—
C2OF10000J ...	VR412	F413	—
C2SF10000A ...	VR414	—	—
C2SZ10000A ...	VR414	F413	—
C2SZ10002A ...	VR414	F413	—
C2TF10000B ...	VR412	F413	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing	Unit No	Voltage Regulator	Brush Set	Bushing
C2TF10000H ...	VR412	F413	—	C4TF10000N ...	VR412	F413	—
C2TF10000J ...	VR412	F413	—	C4TZ10002A ...	VR412	F413	—
C2TF10000K ...	VR412	F413	—	C4TZ10002B ...	VR412	F413	—
C2TF10000L ...	VR414	F413	—	C8BA10002A ...	VR401	F404	4283
C2TF10000M ...	VR414	F413	—	C20F10000A ...	VR412	F413	—
C2TF10000N ...	VR412	F413	—	C20F10000B ...	VR412	F413	—
C2TF10000R ...	VR412	F413	—	C20F10000C ...	VR412	F413	—
C2TF10000S ...	VR414	F413	—	C20F10000D ...	VR412	F413	—
C2TF10000T ...	VR412	F413	—	C20F10000E ...	VR412	F413	—
C2TF10000U ...	VR412	F413	—	C20F10000F ...	VR412	F413	—
C2TF10000V ...	VR412	F413	—	C20F10000G ...	VR412	F413	—
C2TF10000Y ...	VR414	F413	—	C20F10000H ...	VR412	F413	—
C2TF10000Z ...	VR414	F413	—	C20F10000I ...	VR412	F413	—
C2TF10002F ...	—	F413	—	C20F10000J ...	VR412	F413	—
C3AF10000B ...	VR412	—	—	C30F10000B ...	VR412	F413	—
C3DF10000A ...	VR412	F413	—	FAA10000A ...	VR401	F404	4283
C3DF10000B ...	VR414	F413	—	FAA10000B ...	VR401	F404	4283
C3DF10000C ...	VR414	F413	—	FAA10000E ...	VR401	F404	—
C3DF10000D ...	VR412	F413	—	FAA10002A ...	VR401	F404	4283
C3NF10002A ...	VR953	F413	—	FAA10002B ...	VR401	F404	4283
C3OF10000B ...	VR412	F413	—	FAB10000C ...	VR401	F404	—
C3TF10000A ...	VR412	F413	—	FAB10000D ...	VR401	F404	—
C3TF10000B ...	VR412	F413	—	FAB10002A ...	VR401	F404	4283
C3TF10000C ...	VR412	F413	—	FAB10002B ...	VR401	F404	4283
C3TF10000D ...	VR412	F413	—	FAB10002C ...	VR401	F404	4283
C3TF10000E ...	VR412	F413	—	FAC10002A ...	VR951	F404	—
C3TF10000F ...	VR412	F413	—	FAD10002A ...	—	F404	—
C3TF10000G ...	VR412	F413	—	FAE10002A ...	—	F404	—
C3TF10000H ...	VR412	F413	—	FAF10000A ...	VR401	F404	4283
C3TF10000I ...	VR412	F413	—	FAF10000B ...	VR401	F404	4283
C3TF10000J ...	VR412	F413	—	FAF10002A ...	VR401	F404	4283
C3TF10000K ...	VR412	F413	—	FAF10002B ...	VR401	F404	4283
C3TF10000L ...	VR412	F413	—	FAK10000A ...	VR403	F404	—
C4DF10000A ...	VR412	F413	—	FAP10000A ...	VR403	F404	—
C4DF10000B ...	VR412	F413	—	FAR10000B ...	VR412	F413	—
C4DF10000C ...	VR412	F413	—	FAS10000B ...	VR412	F413	—
C4TF10000A ...	VR414	F413	—	FAS10000C ...	VR412	F413	—
C4TF10000B ...	VR412	F413	—	FAS10000E ...	VR412	F413	—
C4TF10000C ...	VR412	F413	—	FAS10000F ...	VR401	F404	—
C4TF10000D ...	VR412	F413	—	FAS10000G ...	VR412	F413	—
C4TF10000E ...	VR412	F413	—	FAT10000A ...	VR401	F404	—
C4TF10000F ...	VR412	F413	—	FAU10000A ...	VR204	—	—
C4TF10000G ...	VR414	F413	—	FAV10000A ...	VR204	—	—
C4TF10000H ...	VR412	F413	—	FAV10000B ...	VR204	—	—
C4TF10000I ...	VR412	F413	—	FAW10000A ...	VR412	—	—
C4TF10000J ...	VR412	F413	—	FAW10000F ...	VR204	—	—
C4TF10000K ...	VR412	F413	—	FBA10000A ...	VR401	F404	—
C4TF10000L ...	VR412	F413	—	FBA10000D ...	VR401	F404	—
C4TF10000M ...	VR412	F413	—	FBA10000E ...	VR401	F404	—

(continued on next column)

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Voltage Regulator	Brush Set	Bushing	Unit No	Voltage Regulator	Brush Set	Bushing
FBA10002A	VR401	F404	—	7HA10000B	VR401	F404	—
FBA10002D	VR401	F404	—	8BA10000A	VR401	F404	4283
FBA10002E	VR401	F404	—	8BA10000B	VR401	F404	4283
FBB10000A	VR403	F404	—	8BA10000C	VR401	F404	4283
FBB10000B	VR403	F404	—	8BA10000D	VR401	F404	4283
FBB10000C	VR403	F404	—	8BA10002A	VR401	F404	4283
FBB10000D	VR403	F404	—	8BA10002B	VR401	F404	4283
FBB10000F	VR403	F404	—	8BA10002C	—	F404	—
FBB10000H	VR403	F404	—	8BA10002D	VR401	F404	4283
FBB10002A	VR403	F404	—	8EL10000A	VR401	F404	4283
FBC10000A	VR401	F404	—	8EL10000B	VR401	F404	4283
FBC10000E	VR401	F404	—	8EL10002A	VR401	F404	4283
FBC10002A	VR401	F404	—	8EL10002B	VR401	F404	4283
FBD10002A	VR401	F404	—	8EL1001A	VR401	F404	4283
FBG10002A	VR401	F404	4283	8EL1001B	VR401	F404	4283
FBJ10000A	VR403	F404	—	8HA10000A	VR401	F404	4283
FBK10000A	VR403	F404	—	8HA10000B	VR401	F404	4283
FBL10000A	VR401	F404	—	8HJ10000A	VR401	F404	4283
FBM10000A	VR401	F404	4283	8HJ10000B	VR401	F404	4283
FBT10000B	VR412	F413	—	8HJ10002A	VR401	F404	—
FBT10000C	VR412	F413	—	8N10001	VR950	—	4283
FBT10000D	VR412	F413	—	01A10000A	—	F404	4283
FBU10000B	VR412	F413	—	91A10000	—	—	4283
FBU10000C	VR412	F413	—	2700004	VR412	F413	—
FBU10000D	VR412	F413	—	2900231	VR414	F404	—
FBV10000B	VR412	F413	—	2900232	VR414	F404	—
FBW10000B	VR412	F413	—	2900425	VR414	F404	—
FBW10000C	VR412	F413	—	2900430	VR414	F404	—
FCD10000A	VR204	—	—	2900450	VR953	—	—
FCE10000A	VR412	—	—	2900456	VR414	F404	—
FCT10000A	VR204	—	—	2900457	VR414	F404	—
FGB10002A	VR401	F404	—	2900458	VR414	F404	—
FGM10000B	VR204	—	—	2900459	VR414	F404	—
FGN10000A	VR412	—	—	2900460	VR414	F404	—
FGP10000A	—	F404	—	2900461	VR414	F404	—
FGP10000B	—	F404	—	2900462	VR414	F404	—
FGS10000A	—	F404	—	2900466	VR414	F404	—
FGS10000B	—	F404	—	2900639	VR412	F404	—
FGV10000A	VR414	F413	—	2900640	VR412	F404	—
FGV10002A	VR414	F404	—	2900641	VR412	F413	—
FGW10000A	VR204	F508	—	2900642	VR412	F413	—
FGZ10000A	VR412	F413	—	2900643	VR412	F413	—
FHA10000A	VR412	F413	—	2900644	VR412	F413	—
GGA6001SN	VR412	—	—	2900645	VR412	F413	—
OHA10000A	VR401	F404	4283	2900646	VR412	F413	—
OHA10000B	VR401	F404	4283	2900649	VR412	—	—
PB8M10002A	VR204	—	—	2900694	VR412	F413	—
PB8M10002B	VR412	F404	—				
ON10002	VR401	F404	4283				

(continued on next column)

LUCAS

Unit No	Voltage Regulator	Brush Set	Bushing
22700A	—	E403	—
22700J	—	E403	—
22703	—	E403	—
22704	—	E403	—
22713	—	E403	—
22715	—	E403	—
22716	—	E403	—
22725A	—	E403	—

(continued on next column)

Unit No	Voltage Regulator	Brush Set	Bushing
22725B	—	E403	—
22726	—	E403	—
22742A	—	E403	—
22742B	—	E403	—
22744	—	E403	—
22763	—	E403	—
22775	—	E403	—

AMERICAN MOTORS

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
JR775001	—	F508	—	5302
924885	ST51	A520	—	4258
925520	ST58	A514	—	4258
930405	—	A520	—	5289
948162	ST79	A520	—	5289
3156116	ST124	R503	—	5288
3157208	ST104	A520	—	5289
3157217	ST104	A520	—	5289
3157222	ST104	A520	—	5289
3161142	ST124	R503	—	5288
3162209	—	A520	—	5289
3162210	—	A520	—	5289
3168961	ST124	R503	—	5288
3169763	—	A519	—	5289
3173151	ST124	R503	—	5288
3173236	ST124	R503	—	5288
3174483	ST124	R503	—	5288
3174521	—	A519	—	5289
3174522	—	A519	—	5289
3178993	—	A519	—	5289
3179095	—	A519	—	5289
3181801	—	A519	—	5289

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
3182890	—	A519	—	5289
3182972	ST81	—	5339	5291
3184249	ST124	R503	—	5288
3184250	ST124	R503	—	5288
3188794	ST124	R503	—	5288
3191926	—	A519	—	5289
3193382	ST81	—	5339	5291
3208850	ST124	R503	—	5288
3209078	ST104	A519	—	5289
3212235	—	—	5339	5302
3229844	ST81	—	5339	5302
3231371	ST542	F508	—	5302
3231372	ST81	F508	—	5302
3236659	ST124	R507	—	5336
3242283	ST96	F509	—	5302
3250028	—	F508	—	5302
3250032	—	—	—	5302
5752791	—	F508	—	5302
8134193	ST128	R507	—	5336
8982775012	—	F509	—	5302

AUDI-VOLKSWAGEN

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
02A911023E	—	—	—	4204
003911023A	ST221	E552	—	—
003911023B	ST221	—	5313	—
003911023C	—	—	5313	—
003911023D	—	—	5313	—
003911023E	—	—	5313	—
020911023	—	—	—	4204
026911023	—	E702	5313	—
026911023F	ST225	—	—	—
027911023	ST226	—	—	5313
034911023	ST225	—	—	—
035911023	—	E552	5313	—
035911023D	ST226	—	—	—
035911023J	ST226	E552	—	—
035911023K	ST226	—	—	—
035911023L	—	E552	—	—
046911023	ST274	E552	5313	—
049911023D	ST226	—	5313	—
049911023G	ST226	E702	5313	—
049911023H	ST226	E702	5313	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
055911023A	ST226	—	5313	—
055911023B	—	—	5313	—
055911023D	ST249	—	5313	—
055911023G	—	—	—	4204
055911023J	—	—	5313	—
056911023A	—	—	5313	—
056911023B	—	—	5313	—
056911023C	—	—	5313	—
058977023A	—	E552	5313	—
068911023	ST249	E700	5313	—
068911023A	ST249	E700	—	—
068911023C	—	E510	5313	4671
068911023D	—	E510	5313	5321
068911023E	ST226	E510	5313	—
068911023F	—	E510	5313	4671
068911023G	ST249	—	—	—
068911023J	—	E510	5313	5321
077911023C	ST225	—	—	—
078911023	—	—	4204	—
084518400	ST212	E587	—	—

(continued on next page)

AUDI-VOLKSWAGEN (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
091911023	ST222	—	5313	—
091911023A ...	—	—	5313	—
091911023B ...	—	—	5313	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
176911023	—	—	4204	—
176911023A ...	—	—	5313	—
311911023D ...	ST222	—	—	—

AUTOLITE-PRESTOLITE

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
DN1298	ST63	—	—	—	—
DN1299	ST63	—	—	—	—
DN1389	ST63	—	—	—	—
MAB408A	—	A503	—	4258	4258
MAB408B	—	A503	—	4258	4258
MAB4003	ST6	—	—	4258	—
MAB4005	—	A503	—	4258	4258
MAB4007	—	—	—	4258	—
MAB4028	—	A503	—	4258	4258
MAB4030	—	—	—	4258	—
MAB4037	—	—	—	4258	—
MAB4040	—	A503	—	4258	—
MAB4040A	—	A503	—	4258	—
MAB4044	—	A503	—	4258	4258
MAB4044A	—	A503	—	4258	4258
MAB4045	—	A503	—	4258	4258
MAB4046	ST6	A503	—	4258	4258
MAB4046A	ST6	A503	—	4258	4258
MAB4054	—	A503	—	—	—
MAB4058	—	A503	—	4258	4258
MAB4060	ST63	—	—	—	—
MAB4061	ST63	—	—	—	—
MAB4063	—	A503	—	4258	4258
MAB4065	ST63	A503	—	—	—
MAB4066	ST63	A503	—	4258	4258
MAB4068	ST6	—	—	—	—
MAB4069	ST63	A503	—	4258	4258
MAB4069A	ST63	A503	—	4258	4258
MAB4069B	ST63	A503	—	4258	4258
MAB4071	—	A503	—	4258	4258
MAB4072	ST6	A503	—	4258	4258
MAB4072A	—	A503	—	4258	4258
MAB4073	ST63	A503	—	4258	4258
MAB4074	ST63	—	—	—	—
MAB4075	ST63	A503	—	4258	—
MAB4076	ST26	—	—	—	—
MAB4077	—	A503	—	—	—
MAB4078	ST6	A503	—	4258	4258
MAB4079	ST63	A503	—	4258	4258
MAB4080	—	A502	—	4264	4258

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MAB4081	—	A503	—	4264	4258
MAB4082	—	A503	—	4258	4258
MAB4083	ST63	A503	—	4258	4258
MAB4084	—	A503	—	4258	4258
MAB4085	—	A503	—	4258	4258
MAB4085A	—	A503	—	4258	4258
MAB4085B	—	A503	—	4258	4258
MAB4087	ST63	A503	—	4258	4258
MAB4088	ST63	A503	—	4258	4258
MAB4089	ST63	A503	—	4258	4258
MAB4090	ST63	A503	—	4258	4258
MAB4091	ST63	A503	—	4258	4258
MAB4092	ST63	A503	—	4258	4258
MAB4093	ST63	A503	—	4258	4258
MAB4094	ST63	A503	—	4258	4258
MAB4095	—	A503	—	4264	4258
MAB4098	ST63	A503	—	4258	4258
MAB4099	ST63	—	—	4258	—
MAB4100	ST63	A503	—	—	—
MAB4101	ST63	A503	—	4258	4258
MAB4101A	ST63	A503	—	4258	4258
MAB4103	—	A503	—	—	—
MAB4103A	—	A503	—	—	—
MAB4104	ST26	A503	—	—	—
MAB4105	—	A503	—	4258	—
MAB4105M	—	A503	—	4258	4264
MAB4106	ST63	A503	—	4258	4258
MAB4108	ST63	A503	—	4258	4258
MAB4109	ST63	A503	—	4258	4258
MAB4111	ST63	—	—	4258	4258
MAB4112	ST63	A503	—	4258	4258
MAB4114	—	—	—	4264	4258
MAB4115	ST63	A503	—	4258	4258
MAB4116	ST51	A503	—	4258	4258
MAB4117	ST51	A503	—	4258	4258
MAB4118	ST63	A503	—	4258	4258
MAB4118A	ST63	A503	—	4258	4258
MAB4119	ST63	A503	—	4258	4258
MAB4120	ST63	A503	—	4258	4258
MAB4121	—	A503	—	—	4258

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MAB4123	ST63	A503	—	4258	4258
MAB4124	ST63	A503	—	—	—
MAB4125	—	A503	—	4258	4258
MAD4106	—	A503	—	4264	—
MAD4112	ST6	—	—	4258	4258
MAH4015	—	—	—	4258	4258
MAJ4010	ST6	—	—	4258	4258
MAJ4011	ST6	A503	—	4258	4258
MAJ4016	ST6	A503	—	4258	4258
MAJ4017	ST6	A503	—	4258	4258
MAJ4018	ST6	A503	—	4258	4258
MAJ4020	—	A502	—	4258	4258
MAJ4021	—	A503	—	4258	4258
MAJ4024	—	A503	—	4258	4258
MAJ4033	—	A503	—	4258	4258
MAJ4034	—	A503	—	4258	4258
MAJ4035	—	A503	—	4258	4258
MAJ4038	ST6	A503	—	4264	4258
MAJ4040	—	A503	—	—	4258
MAJ4041	—	A503	—	4258	4258
MAJ4042	ST6	A503	—	4264	4258
MAJ4043	ST6	—	—	4264	4258
MAJ4044	—	A503	—	—	—
MAJ4045	—	—	4259	4264	4258
MAJ4046	—	A503	—	4258	4258
MAJ4047	—	A503	—	4258	4258
MAJ4048	—	A503	—	4258	4258
MAJ4049	—	A503	—	4258	4258
MAJ4050	—	A503	—	4258	4258
MAJ4053	—	A503	—	4258	4258
MAJ4054	ST63	A503	—	4264	4258
MAJ4055	ST63	—	—	4258	4258
MAJ4056	—	A503	—	4264	4258
MAJ4057	—	A503	—	—	—
MAJ4058	ST63	A503	—	4258	4258
MAJ4060	ST6	—	—	4258	4258
MAJ4061	—	A503	—	—	—
MAJ4062	ST63	A503	—	4258	4258
MAJ4063	—	A503	—	4258	4258
MAK4003	ST6	—	—	—	—
MAK4005	—	—	—	4258	—
MAK4009	ST6	—	—	—	—
MAK4011	ST63	—	—	—	—
MAK4012	ST63	—	—	—	—
MAK4013	ST6	—	—	4264	—
MAK4014	ST63	—	—	—	—
MAK4017	ST63	—	—	—	—
MAK4020	ST6	—	—	4264	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MAK4021	ST63	—	—	—	—
MAK4022	ST6	—	—	4264	—
MAK4026	ST63	—	—	—	—
MAK4028	—	—	—	4258	—
MAK4029	ST63	—	—	—	—
MAK4030	ST6	—	—	—	—
MAK4031	ST63	—	—	—	—
MAN4002	—	—	—	4264	—
MAN4005	—	—	—	4264	—
MAO4003B	ST63	—	—	—	—
MAS4001	ST6	—	—	4258	—
MAS4001B	—	—	—	4258	—
MAS4002	ST6	—	—	4258	—
MAS4003	ST6	—	—	4258	—
MAS4004	ST51	M400	—	4258	—
MAS4005	ST51	—	—	4258	—
MAS4006	ST51	—	—	4258	—
MAS4007	ST51	M400	—	4258	—
MAS4008	ST6	—	—	4258	—
MAS4009	ST6	—	—	4258	—
MAS4010	—	—	—	4258	—
MAS4011	ST51	M400	—	4258	—
MAS4012	ST79	—	—	4258	—
MAS4016	ST51	—	—	4258	—
MAS4102	—	—	—	4258	—
MAS4102A	—	—	—	4258	—
MAS4104	—	—	—	4258	—
MAS4105	—	—	—	4258	—
MAS4106	—	—	—	4258	—
MAS4107	—	—	—	4258	—
MAS4108	ST51	—	—	4258	—
MAS4109	ST51	—	—	4258	—
MAU4004	—	—	—	4258	—
MAU4005	—	—	—	4258	4258
MAU4006	—	—	—	4258	4258
MAU4007	ST51	—	—	4258	4258
MAU4008	ST51	—	—	4258	4258
MAU4010	ST79	A502	4259	4258	—
MAU4011	ST6	—	—	4264	4258
MAU4011A	—	—	—	4264	—
MAU4013	—	—	4259	4258	—
MAU4016	ST51	—	—	4258	4258
MAU4021	—	—	—	4258	—
MAU4022	ST6	A502	4259	4264	4258
MAU4023	ST63	—	—	—	—
MAU4025	—	—	—	4264	4258
MAU4026	ST51	—	—	4258	4258
MAU4027	ST79	—	—	4258	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MAU4031	—	A502	—	4258	—
MAU4034	ST51	—	—	4258	4258
MAU4035	ST51	—	—	4258	4258
MAU4036	ST79	A502	—	4258	—
MAU4038	—	A502	—	4264	—
MAU4040	—	—	—	4264	—
MAU4041	ST51	—	—	4258	—
MAU4042	ST51	—	—	4258	4258
MAU4043	ST51	—	—	4258	—
MAU4045	ST51	—	—	4258	—
MAU4046	ST51	—	—	4258	4258
MAU4047	ST51	—	—	4258	4258
MAW4001	ST6	A505	—	4258	4258
MAW4002	—	A505	—	4264	—
MAW4003	—	A505	—	4264	—
MAW4005	—	A505	—	4264	—
MAW4006	—	A505	—	4264	—
MAW4007	—	A505	—	4264	—
MAW4007A	—	A505	—	4264	—
MAW4007M	—	A505	—	4264	—
MAW4008	—	A505	—	4264	—
MAW4008A	—	A505	—	4264	—
MAW4008M	—	A505	—	4264	—
MAW4009	—	A505	—	4264	—
MAW4010	—	A505	—	4264	—
MAW4011	—	A505	—	4264	—
MAW4011A	—	A505	—	4264	—
MAW4013	—	A505	—	4264	—
MAW4013A	—	A505	—	4264	—
MAW4013B	—	A505	—	4264	—
MAW4015	—	A505	—	4264	—
MAW4016	—	A505	—	4264	—
MAW4016A	—	—	—	4264	—
MAW4018	ST63	A505	—	4258	4258
MAW4019	—	A505	—	4264	—
MAW4019A	—	A505	—	4264	—
MAW4020	ST27	A505	—	4264	—
MAW4020A	ST27	A505	—	4264	—
MAW4021	ST63	A505	—	4258	4258
MAW4022	—	A505	—	4264	—
MAW4022A	—	A505	—	4264	—
MAW4023	—	A505	—	4264	—
MAW4023A	—	A505	—	4264	—
MAW4024	ST63	A505	—	4258	—
MAW4025	—	A505	—	4264	—
MAW4026	—	A505	—	4264	—
MAW4027	—	A505	—	4258	—
MAW4028	ST6	A505	—	4264	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MAW4029	—	A505	—	4264	—
MAW4030	—	A505	—	4258	4258
MAW4031	—	A505	—	4258	4258
MAW4032	—	A505	—	4264	—
MAW4034	—	A505	—	4258	4258
MAW4035M	—	A505	—	4258	—
MAW4038	—	A505	—	4258	4258
MAW4039	ST63	A505	—	4264	4258
MAW4039M	—	A505	—	4264	4258
MAW4040	ST63	A505	—	4258	4258
MAW4041	ST62	A505	—	4258	—
MAW4042	ST6	A505	—	4264	4258
MAW4043	ST63	A505	—	4258	—
MAW4044	—	A505	—	4264	—
MAW4045M	—	A505	—	4264	4258
MAW4046M	—	A505	—	4264	4258
MAW4047	—	A505	—	4264	—
MAW4048	ST63	A505	—	4258	—
MAW4049	ST63	—	—	4258	4258
MAW4051	—	A505	—	4264	4258
MAW4052	—	A505	—	4264	—
MAW4054	—	A505	—	4258	—
MAW4054A	—	A505	—	4258	—
MAW4055	—	A505	—	4264	—
MAW4057	—	A505	—	4258	—
MAW4074	ST58	A505	—	4258	—
MAW4085	—	—	—	4264	—
MAX402M	—	A505	—	4264	4258
MAX4002	—	A505	—	4264	—
MAX4003	—	A505	—	4264	—
MAX4003A	—	A505	—	4264	—
MAX4004	—	A505	—	4264	—
MAX4006	ST63	A505	—	4258	4258
MAX4007	—	A505	—	4264	—
MAX4008	—	A505	—	4264	—
MAX4009	—	A505	—	4264	4258
MAX4010	ST63	A505	—	4264	4258
MAX4011	ST63	A505	—	4264	4258
MAX4013	ST63	A505	—	4264	—
MAX4014	ST63	A505	—	4264	4258
MAX4015	—	A505	—	4264	—
MAX4016	—	A505	—	4264	—
MAX4016A	—	A505	—	4264	—
MAX4017	—	A505	—	4264	—
MAX4018	—	A505	—	4264	—
MAX4019	—	A505	—	4264	—
MAX4020	—	A505	—	4264	—
MAX4020A	—	A505	—	4264	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MAX4021	—	A505	—	4258	4258
MAX4022	ST63	A505	—	4264	4258
MAX4023	ST63	A505	—	4264	4258
MAX4023M	—	A505	—	4264	4258
MAX4024	—	A505	—	4264	—
MAX4025	ST63	A505	—	4264	4258
MAX4026	ST63	A505	—	4264	4258
MAX4026M	—	A505	—	4264	4258
MAX4028	—	A505	—	4264	—
MAX4031	—	A505	—	4264	—
MAX4031A	—	A505	—	4264	—
MAX4031B	—	A505	—	4264	—
MAX4032	ST6	A505	—	4264	—
MAX4033	—	A505	—	4258	4258
MAX4034	—	A505	—	4264	4258
MAX4035	—	A505	—	4264	4258
MAX4037	—	A505	—	4264	—
MAX4038	—	A505	—	4264	—
MAX4039	—	A505	—	4264	—
MAX4040	—	A505	—	4264	—
MAX4041	—	A505	—	4264	4258
MAX4044	—	A505	—	4264	—
MAX4045	—	A505	—	4264	—
MAX4045A	—	A505	—	4264	—
MAX4046	ST63	A505	—	4258	—
MAX4048	ST63	A505	—	4258	—
MAX4050	—	A505	—	4264	—
MAX4051	—	A505	—	4264	—
MAX4052	—	A505	—	4264	4258
MAX4053	—	A505	—	4264	—
MAX4054	—	A505	—	4264	—
MAX4057	—	A505	—	4264	4258
MAX4058	ST63	A505	—	4258	—
MAX4059	—	A505	—	4264	—
MAX4060	—	A505	—	4264	—
MAX4062	—	A505	—	4264	—
MAX4063	ST63	A505	—	4258	4258
MAX4064	ST63	A505	—	4258	—
MAX4065	ST63	A505	—	4258	4258
MAX4066	ST63	A505	—	4258	4258
MAX4067	ST63	A505	—	4258	—
MAX4069M	—	A505	—	4264	—
MAX4070M	—	A505	—	4264	—
MAX4072	ST63	A505	—	4258	4258
MAX4073	ST63	A505	—	4258	—
MAX4074	ST63	A505	—	4258	4258
MAX4075	ST51	A505	—	4258	4258
MAX4076	—	A505	—	4264	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MAX4077	ST63	A505	—	4264	4258
MAX4078	—	A505	—	4258	4258
MAX4079	—	A505	—	4264	—
MAX4080	—	A505	—	4258	4258
MAX4081	—	A505	—	4258	4258
MAX4082	—	A505	—	4258	—
MAX4083	ST63	A505	—	4258	—
MAX4085	—	A505	—	4264	—
MAX4086	—	A505	—	4264	—
MAX4087	—	A505	—	4258	—
MAX4088	—	A505	—	4258	—
MAX4089	—	A505	—	—	—
MAX4090	—	A505	—	4264	—
MAX4091	ST63	A505	—	4258	4258
MAX4093	ST63	A505	—	—	—
MAX4094	—	A505	—	—	—
MAX4095	ST63	A505	—	4258	4258
MAY4014	—	—	—	4264	4258
MAY4017	—	—	—	4264	4258
MAY4019	—	—	—	4264	—
MAY4019A	—	—	—	4264	—
MAY4019B	—	—	—	4264	—
MAY4109A	—	A505	—	4264	—
MAY4109B	—	A505	—	4264	—
MAY4114	—	—	—	4264	—
MAY4114A	—	—	—	4264	—
MAY4114B	—	—	—	4264	—
MAY4127	ST79	—	—	4258	—
MAY4130	ST51	—	—	4264	—
MAY4130M	—	—	—	4264	—
MAY4131	ST51	—	—	4264	—
MAY4131M	—	—	—	4264	—
MAY4132	—	—	—	4264	—
MAY4134	ST79	—	—	4264	—
MAY4134M	—	—	—	4264	4258
MAY4135	ST79	—	—	4264	—
MAY4135M	—	—	—	4264	4258
MAY4138	—	—	—	4258	4258
MAY4139	ST82	—	—	4264	4258
MAY4145	ST51	—	—	4258	—
MAY4147	—	—	—	4264	—
MAY4148	—	—	—	4264	—
MAY4149M	—	—	—	4264	—
MAY4150M	—	—	—	4264	—
MAY4151	—	—	—	4264	—
MAY4152	ST51	—	—	4264	—
MAY4154	ST51	—	—	4264	—
MAY4202	ST79	—	—	—	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MBA4001	ST6	—	4259	4264	—
MBA4002	—	—	4259	4258	—
MBD4002	—	—	4278	—	—
MBD4003	—	—	4278	—	—
MBD4004	—	—	4278	—	—
MBD4005	—	—	4278	—	—
MBD4008A	—	—	4278	—	—
MBD4009	—	—	4278	—	—
MBD4011	—	—	4278	—	—
MBD4013T	—	—	4278	—	—
MBD4015	—	—	4278	—	—
MBD4016	—	—	4278	—	—
MBD4018	—	—	4278	—	—
MBD4024	—	—	4278	—	—
MBD4026	—	—	4278	—	—
MBD4028A	—	—	4278	—	—
MBD4031	—	—	4278	—	—
MBD4032	—	—	4278	—	—
MBD4033	—	—	4278	—	—
MBD4037	—	—	4278	—	—
MBD4038	—	—	4278	—	—
MBD4042	—	—	4278	—	—
MBD4043UT	—	—	4278	—	—
MBD4044UT	—	—	4278	—	—
MBE4003	ST6	—	—	4264	—
MBE4003A	ST6	—	—	4264	—
MBE4003AT	—	—	—	4264	—
MBE4004	ST6	—	—	—	—
MBE4007	ST51	—	—	—	—
MBG4003	ST51	—	—	—	—
MBG4003A	ST51	—	—	—	—
MBG4004	—	A502	—	—	—
MBG4006	ST51	—	—	4258	—
MBG4007	ST51	—	—	4258	—
MBG4008	ST51	—	—	4264	—
MBG4009	ST51	—	—	—	—
MBG4011	ST51	—	—	—	—
MBG4012	ST79	A502	—	4258	—
MBG4014	ST51	—	—	4264	—
MBG4015	—	—	—	4264	—
MBG4017	—	—	—	4264	4258
MBG4018	—	—	—	4264	4258
MBG4021	ST51	—	—	4264	4258
MBG4023	ST51	—	—	4264	4258
MBG4024	ST6	—	—	—	—
MBG4024T	—	A502	—	—	—
MBG4025	—	—	—	4264	—
MBG4026	—	—	—	4264	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MBG4101	—	—	—	4258	—
MBG4102	—	—	—	4258	—
MBG4103	—	—	—	5289	—
MBG4104	—	—	—	4258	—
MBG4104A	—	—	—	4258	—
MBG4105	—	—	—	4258	—
MBG4106	ST51	—	—	4264	—
MBG4107	ST51	A502	—	4258	—
MBG4107A	ST51	—	—	4258	—
MBG4107B	ST51	—	—	4258	—
MBG4108	ST51	—	—	4258	—
MBG4108A	ST51	—	—	4258	—
MBG4108AS	ST51	—	—	4258	—
MBG4109	—	A502	—	—	—
MBG4110	—	—	—	4258	—
MBG4111	—	A502	—	4258	—
MBG4112	ST51	—	—	4258	—
MBG4112A	ST51	—	—	4258	—
MBG4113	—	—	—	5289	—
MBG4114	ST51	—	—	4258	—
MBG4114A	ST51	—	—	4258	—
MBG4114AS	—	—	—	4258	—
MBG4115	ST51	—	—	4258	—
MBG4118	—	A502	—	—	—
MBG4119T	—	—	—	4258	—
MBG4122	ST51	—	—	4258	—
MBG4122A	ST51	—	—	4258	—
MBG4122AS	ST51	—	—	4258	—
MBG4123	ST51	—	—	—	—
MBG4124	—	A502	—	—	—
MBG4125	—	A502	—	—	—
MBG4125A	—	A502	—	—	—
MBG4125B	—	A502	—	—	—
MBG4127	ST51	—	—	4264	—
MBG4127A	ST51	—	—	4264	—
MBG4129	ST51	—	—	—	—
MBG4131	ST51	—	—	4258	—
MBG4132	ST51	A502	—	4258	—
MBG4133	—	—	—	4258	—
MBG4134	—	—	—	4258	—
MBG4134A	—	—	—	4258	—
MBG4134AT	—	—	—	4258	—
MBG4134B	—	—	—	4258	—
MBG4135	ST51	—	—	4258	—
MBG4135T	—	—	—	4258	—
MBG4137	ST51	—	—	—	—
MBG4138	—	A502	—	5289	—
MBG4139	—	A502	—	—	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MBG4140	—	A502	—	—	—
MBG4141	—	A502	—	—	—
MBG4142T	—	—	—	4258	—
MBG4143T	—	—	—	4258	—
MBG4144	—	—	—	4258	—
MBJ4101	ST51	—	—	4258	4258
MBJ4103	ST51	—	—	4258	4258
MBJ4104	—	—	—	4258	—
MBJ4105	ST51	—	—	4258	4258
MBJ4106	ST51	—	—	4258	4258
MBJ4107	ST51	—	—	4258	4258
MBJ4107A	ST51	—	—	4258	4258
MBJ4110	ST51	—	—	4258	—
MBJ4112	—	—	—	4258	—
MBJ4114	ST51	—	—	4258	4258
MBJ4115	—	—	—	4264	—
MBJ4116	ST51	—	—	4258	4258
MBJ4118	—	—	—	4337	—
MBJ4120	ST51	—	4278	4258	4258
MBJ4138	—	—	—	5285	—
MBJ4201	—	—	—	4337	—
MBJ4204	—	—	—	4337	—
MBJ4207	—	—	—	4337	—
MBJ4208	—	—	—	4337	—
MBJ4209	—	—	—	4337	—
MBJ4301	—	—	—	4337	—
MBJ4402	—	—	—	4337	—
MBJ4403	—	—	—	4337	—
MBJ4405	—	—	—	4337	—
MBJ4406	—	—	—	4337	—
MBJ4407	—	—	—	4337	—
MBJ4408	—	—	—	4337	—
MBJ4410	—	—	—	—	4258
MBJ6001	ST103	—	—	4264	—
MBM4001	—	A502	—	—	—
MBP4008T	—	—	—	4258	—
MBP4009T	—	—	—	4258	—
MBP4014T	—	—	—	4258	—
MBP4016T	—	—	—	4258	—
MBP4017T	—	—	—	4258	—
MBR4003	ST79	—	—	—	—
MBR4004	ST79	—	—	—	—
MBR4006	ST51	—	4278	4337	—
MBR4007	ST51	—	4278	4337	—
MBR4010	ST51	—	4278	—	—
MBR4012	ST51	—	4278	4337	—
MBR4013	—	—	4278	—	—
MBR4015	ST51	—	4278	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MBR4021	—	—	4278	—	—
MBR4022	ST51	—	4278	—	—
MBR4023	—	—	4278	—	—
MBR4024	—	—	4278	—	—
MBR4026	—	—	4278	—	—
MBR4029	—	—	4278	—	—
MBR4029A	—	—	4278	—	—
MBR4030	—	—	4278	—	—
MBY4003	—	—	—	4264	—
MBY4004AT	—	—	—	4258	—
MBY4010	—	—	—	4258	—
MBY4011T	—	—	—	4258	—
MCC4002T	—	—	4278	—	—
MCC4003	—	—	4278	—	—
MCC4004	—	—	4278	—	—
MCC4005	—	—	4278	—	—
MCH611A	—	A514	—	4264	—
MCH4001	ST27	A503	—	4264	—
MCH6001M	—	A503	—	4258	—
MCH6002M	—	—	—	4258	—
MCH6003	ST63	A503	—	4258	—
MCH6004	ST63	A503	—	4258	—
MCH6005	ST51	—	—	—	—
MCH6101	ST62	A514	—	4258	—
MCH6102	—	A514	—	4264	—
MCH6103	—	—	—	4264	—
MCH6105	—	A514	—	4264	—
MCH6106	—	A514	—	4264	—
MCH6106F	—	A514	—	4264	—
MCH6107	ST58	A514	—	4258	—
MCH6109	ST58	A514	—	4258	—
MCH6110	—	A514	—	4264	—
MCH6111	—	A514	—	4258	—
MCH6113	—	A514	—	4264	—
MCH6113A	—	A514	—	4264	—
MCH6116	ST58	A514	—	5289	—
MCH6117	—	A514	—	5289	—
MCH6201	ST62	A514	—	—	—
MCH6202	ST62	A514	—	—	—
MCH6203	ST63	A514	—	4258	—
MCH6204	—	A514	—	4258	—
MCH6205	—	A514	—	4258	—
MCH6206	—	A514	—	4258	—
MCH6207	—	A514	—	4258	—
MCH6208M	—	A514	—	4258	—
MCH6209M	—	A514	—	4258	—
MCH6210	—	A514	—	4258	—
MCH6211	—	A514	—	4258	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MCH6212	—	A514	—	4258	—
MCH6213	ST63	A514	—	4258	—
MCH6215	ST63	A514	—	4258	—
MCH6302	ST62	A514	—	4258	—
MCH6305	—	A514	—	4258	—
MCH6306	—	A514	—	4258	—
MCJ4001	—	—	—	4258	—
MCJ6001M	—	—	—	4258	—
MCJ6002M	—	—	—	4258	—
MCK4001	—	—	4278	—	—
MCK4002	—	—	4278	—	—
MCK4003	—	—	4278	—	—
MCK4004	—	—	4278	—	—
MCK4005	—	—	4278	—	—
MCK4006	—	—	4278	—	—
MCK4007	—	—	4278	—	—
MCK4008	—	—	4278	—	—
MCK4009	—	—	4278	—	—
MCK4010	—	—	4278	—	—
MCK4010S	—	—	4278	—	—
MCK4012	—	—	4278	—	—
MCK6001	—	—	4278	—	—
MCK6002	—	—	4278	—	—
MCL6001AM	—	A503	—	4258	—
MCL6001M	—	A503	—	4258	—
MCL6002AM	—	A503	—	4258	—
MCL6002M	—	A503	—	4258	—
MCL6003	ST63	A502	—	4258	—
MCL6004	ST63	A502	—	4258	—
MCL6004A	ST63	A502	—	4258	—
MCL6005	ST63	A502	—	4258	—
MCL6006	ST63	A502	—	—	—
MCL6007	—	A502	—	4258	—
MCL6008	—	A502	—	—	—
MCL6009	—	A502	—	4258	—
MCL6009A	—	A502	—	4258	—
MCL6009B	—	A502	—	4258	—
MCL6010M	—	A503	—	4258	—
MCL6011M	—	A503	—	4258	—
MCL6013	ST63	A502	—	4258	—
MCL6014	ST63	A502	—	4258	—
MCL6015	ST63	A502	—	4258	—
MCL6016	ST63	A502	—	4258	—
MCL6017	—	A502	—	—	—
MCL6101	—	A514	—	4264	—
MCL6102	—	A514	—	4264	—
MCL6103	—	A514	—	4264	—
MCL6104	—	A514	—	4258	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MCL6105	ST63	A514	—	4258	—
MCL6105M	—	A514	—	4258	—
MCL6106	ST63	A514	—	4258	—
MCL6107	—	A514	—	4264	—
MCL6108	—	A514	—	4264	—
MCL6109	—	A514	—	4264	—
MCL6110	—	A514	—	4264	—
MCL6110F	—	A514	—	4264	—
MCL6111	—	A514	—	4264	—
MCL6112	—	A514	—	4264	—
MCL6113	ST63	A514	—	4258	—
MCL6114	—	A514	—	4264	—
MCL6115	—	A514	—	4264	—
MCL6115T	—	—	—	4264	—
MCL6116	—	A514	—	4264	—
MCL6117	—	A514	—	4264	—
MCL6119	ST63	A514	—	4258	—
MCL6120	—	A514	—	4258	—
MCL6121	—	A514	—	4264	—
MCL6121A	—	A514	—	4264	—
MCL6122	ST63	A514	—	4258	—
MCL6124	—	A514	—	4264	—
MCL6126	—	A514	—	4264	—
MCL6126F	—	A514	—	4264	—
MCL6127M	—	A514	—	4264	—
MCL6128M	—	A514	—	4264	—
MCL6129	ST63	A514	—	—	—
MCL6130	—	A514	—	4264	—
MCL6131	ST63	A514	—	4258	—
MCL6132	—	A514	—	5289	—
MCL6133	—	A514	—	4264	—
MCL6134T	—	—	—	4258	—
MCL6135	—	A514	—	4264	—
MCL6137	ST63	A514	—	4258	—
MCL6138	—	A514	—	—	—
MCL6154	—	A514	—	—	—
MCL6155	—	A514	—	5289	—
MCL6159	—	A514	—	4258	—
MCL6160	—	A514	—	5289	—
MCL6201M	—	A514	—	4258	—
MCL6202	ST63	A514	—	4258	—
MCL6202M	—	A514	—	4258	—
MCL6203M	—	A514	—	4258	—
MCL6204	—	A514	—	4258	—
MCL6206	ST63	A514	—	4258	—
MCL6207	ST63	A514	—	4258	—
MCL6223	ST63	A514	—	4258	—
MCL6225	ST51	—	—	—	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MCL6225A	ST51	—	—	—	—
MCL6225T	ST51	—	—	—	—
MCL6226	—	A514	—	—	—
MCL6227	—	A514	—	—	—
MCL6228	ST51	—	—	—	—
MCL6304	—	A514	—	4264	—
MCL6308	—	A514	—	4264	—
MCL6309	—	A514	—	4264	—
MCL6401	—	A514	—	—	—
MCL6501	—	—	—	4337	—
MCL6502	ST51	—	—	—	—
MCL6505	—	—	—	5289	—
MCO4004	—	—	4278	—	—
MCO4005	—	—	4278	—	—
MCO4006	—	—	4278	—	—
MCO4007	—	—	4278	—	—
MCO4008	—	—	4278	—	—
MCO4009	—	—	4278	—	—
MCT6101	—	—	—	4264	—
MCT6103	—	—	—	4264	—
MCT6105M	—	—	—	4264	—
MCT6106M	—	—	—	4264	—
MCT6110	—	—	—	4264	—
MCT6202M	—	—	—	4258	—
MCT6301	—	—	—	4264	—
MCT6303M	—	—	—	4258	—
MCU4001	—	—	—	4337	—
MCU4002	—	—	—	4337	—
MCU4003	—	—	—	4337	—
MCU4004	—	—	—	4337	—
MCU6110	—	—	—	4264	4258
MCZ4001	—	—	—	4264	—
MCZ4001UT	—	—	—	4264	—
MCZ4002UT	—	—	—	4264	—
MCZ4004UT	—	—	—	4264	—
MCZ4007	—	—	—	4264	—
MCZ4007UT	—	—	—	4264	—
MCZ4008UT	—	—	—	4264	—
MCZ4103T	—	—	—	4264	—
MCZ4105T	—	—	—	4264	—
MCZ4106T	—	—	—	4264	—
MCZ4107T	—	—	—	4264	—
MCZ4109T	—	—	—	5289	—
MCZ4111T	—	—	—	4264	—
MDB6001A	—	—	—	4264	—
MDC6301	—	—	—	4264	—
MDC6302	—	—	—	4264	—
MDD6301	—	—	—	5289	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MDD6401	—	—	—	4264	—
MDE4001	—	—	—	4337	—
MDE4002	—	—	—	4337	—
MDF6001	ST103	—	—	4264	—
MDF6002	ST67	—	—	4258	—
MDF6003	—	—	—	4264	—
MDF6005	ST103	—	—	4264	—
MDF6006	ST103	—	—	4264	—
MDF6007	ST67	—	—	4258	—
MDF6008	ST103	—	—	5289	—
MDF6009	—	—	—	4258	—
MDF6010	ST79	—	—	—	—
MDF6011	—	—	—	4258	—
MDF6012	—	—	—	4258	—
MDF6013	ST103	—	—	4264	—
MDF6014	—	—	—	4258	—
MDF6015	—	—	—	4264	—
MDF6016	ST103	—	—	4264	—
MDF7010	—	A520	—	5289	5285
MDF7011	—	A520	—	5289	5285
MDG6001	—	—	—	4258	—
MDG6002	—	—	—	4258	—
MDG6003	—	—	—	4264	—
MDL6001	ST103	A519	—	5289	—
MDL6002	ST103	A519	—	—	—
MDL6003	ST66	A519	—	5289	5285
MDL6004	ST67	A519	—	5289	5285
MDL6005	ST103	A519	—	5289	—
MDL6006	—	A519	—	4258	—
MDL6007	—	A519	—	4258	—
MDL6008	—	A519	—	5289	—
MDL6009	ST51	A519	—	4258	—
MDL6010	ST51	A519	—	4258	—
MDL6011	ST51	A519	—	4258	—
MDL6012	ST51	A519	—	4258	—
MDL6013	ST103	A519	—	5289	—
MDL6014	ST103	A519	—	5289	—
MDL6015	ST51	A519	—	4258	—
MDL6016	—	A519	—	5289	—
MDL6017	ST51	A519	—	4258	—
MDL6018	ST51	A519	—	4258	—
MDL6019	—	A519	—	4258	—
MDL6020	—	A519	—	5289	—
MDL6021	—	A519	—	4258	—
MDL6022	—	A519	—	5289	—
MDL6023	—	A519	—	4258	—
MDL6024	ST51	A519	—	4258	—
MDL6025	—	A519	—	5289	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MDL6026	ST51	A519	—	4258	—
MDL6027	ST51	A519	—	4258	—
MDL6028	—	A519	—	4258	—
MDM6001	—	A519	—	5289	—
MDM6002	ST67	A519	—	5289	—
MDM6003	—	A519	—	—	—
MDM6004	—	A519	—	4258	—
MDM6005	ST51	A519	—	4258	—
MDM6006	—	A519	—	4258	—
MDM6007	ST81	A519	—	—	—
MDM6019	—	A519	—	4258	—
MDM6020	ST103	A519	—	5289	—
MDM6021	—	A519	—	4258	—
MDO4002M	—	A523	—	—	—
MDO4003M	—	A523	—	—	—
MDO4004M	—	A523	—	—	—
MDO4005M	—	A523	—	—	—
MDO4102M	—	A523	—	—	—
MDO4103M	—	A523	—	—	—
MDO4104M	—	A523	—	—	—
MDO4105M	—	A523	—	—	—
MDO4106M	—	A523	—	—	—
MDO4107M	—	A523	—	—	—
MDO4108A	—	A523	—	—	—
MDO4108AS	—	A523	—	—	—
MDO4108M	—	A523	—	—	—
MDO4108S	—	—	—	—	4258
MDO4109	—	A523	—	—	—
MDO4204M	—	A523	—	—	—
MDO4205M	—	A523	—	—	—
MDO4206M	—	A523	—	—	—
MDO4207M	—	A523	—	—	—
MDT6001	—	A519	—	5289	—
MDT6002	ST103	A519	—	5289	—
MDT6003	ST103	A519	—	5289	—
MDT6004	—	A519	—	5289	—
MDT6006M	—	A519	—	4258	—
MDT6007N	—	A519	—	4258	—
MDT6009	ST103	A519	—	5289	—
MDT6010	—	A519	—	4258	—
MDT6011	—	A519	—	4258	—
MDT6012	ST103	A519	—	4264	—
MDT6012BT	—	A519	—	4264	—
MDT6012C	ST103	A519	—	4264	—
MDT6012T	—	A519	—	4264	—
MDT6013	—	A519	—	4264	—
MDT6013A	—	A519	—	4264	—
MDT6014	—	A519	—	4264	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MDT6015	—	A519	—	4264	—
MDT6016	—	A519	—	4264	—
MDT6017	—	A519	—	—	—
MDT6018	ST103	A519	—	5289	—
MDT6020	—	A519	—	—	—
MDT6021	ST103	A519	—	4264	—
MDT6022	—	A519	—	—	—
MDT6023T	—	A519	—	4264	—
MDT6024	—	A519	—	—	—
MDT6025	—	A519	—	—	—
MDT6026	—	A519	—	—	—
MDT6027	—	A519	—	—	—
MDT7001	—	A520	—	5289	—
MDT7002	—	A520	—	—	—
MDT7004T	—	—	—	4258	—
MDT7005	—	A520	—	—	—
MDT7009	—	A520	—	—	—
MDT7009S	—	A520	—	—	—
MDT7010	—	A520	—	5289	—
MDT7011	—	A520	—	5289	—
MDT7012	—	A520	—	4258	—
MDT7012T	—	—	—	4258	—
MDT7013	—	A520	—	4258	—
MDT7014	—	A520	—	—	—
MDT7015	ST51	A520	—	—	—
MDT7016	—	A520	—	5289	—
MDT7017	ST51	A520	—	4258	—
MDT7018	—	A520	—	4258	—
MDT7019	—	A520	—	5289	—
MDT7020	ST51	A520	—	5289	—
MDT7021	—	A520	—	5289	—
MDT7022	—	A520	—	5289	—
MDT7023	—	A520	—	4258	—
MDT7024	—	A520	—	4258	—
MDT7025	—	A520	—	4258	—
MDT7030	—	A520	—	4258	—
MDT7101	ST109	A520	—	5289	—
MDU6001	—	A519	—	5289	—
MDU6002	—	A519	—	5289	—
MDU6003	—	A519	—	5289	—
MDU6006	ST51	A519	—	5289	—
MDU6007	ST51	A519	—	5289	—
MDU6008	ST51	A519	—	4258	—
MDU6009	ST51	A519	—	4258	—
MDU6010	—	A519	—	5289	—
MDU6011	—	A519	—	5289	—
MDU6012	—	A519	—	5289	—
MDU6013	—	A519	—	5289	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MDU6014	—	A519	—	5289	—
MDU6015	—	A519	—	—	—
MDU6016	—	A519	—	5289	—
MDU6017	—	A519	—	5289	—
MDU6019	ST103	A519	—	4264	—
MDU6020	—	A520	—	5289	—
MDU7001	—	A520	—	5289	—
MDU7002	—	A520	—	5289	—
MDU7003	—	A520	—	4258	—
MDU7003A	—	A520	—	4258	—
MDU7004	ST51	A520	—	4258	—
MDU7005	—	A520	—	5289	—
MDU7006	ST81	A520	—	5289	—
MDU7013	—	A520	—	5289	—
MDU7014	—	A520	—	5289	—
MDU7015	ST51	A520	—	5289	—
MDU7016	ST51	A520	—	5289	—
MDU7017	ST51	A520	—	4258	—
MDU7018	ST58	A520	—	5289	—
MDU7018A	ST58	A520	—	5289	—
MDU7019	ST58	A520	—	5289	—
MDU7019A	ST58	A520	—	5289	—
MDU7020	—	A520	—	—	—
MDU7022	ST51	A520	—	5289	—
MDU7023	ST51	A520	—	4258	—
MDU7024	—	A520	—	4258	—
MDU7025	—	A520	—	5289	—
MDU7026	—	A520	—	5289	—
MDU7028	—	A520	—	—	—
MDU7028S	—	A520	—	—	—
MDU7029	—	A520	—	—	—
MDU7029S	—	A520	—	—	—
MDU7030	—	A520	—	4258	—
MDU7031	ST51	A520	—	5289	—
MDU7032	—	A520	—	5289	—
MDU7033	—	A520	—	5289	—
MDU7034	—	A520	—	5289	—
MDU7035	—	A520	—	5289	—
MDU7036	—	A520	—	4258	—
MDU7037	ST51	A520	—	5289	—
MDU7101	ST104	A520	—	5289	—
MDU7102	ST51	A520	—	4258	—
MDU7102A	—	A520	—	4258	—
MDU7104	ST51	A520	—	4258	—
MDU7104A	—	A520	—	4258	—
MDU7105	ST51	A520	—	4258	—
MDU7106	ST104	A520	—	5289	—
MDU7107	ST104	A520	—	5289	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MDU7108	ST104	A520	—	5289	—
MDU7108S	ST104	A520	—	—	—
MDU7109	ST104	A520	—	5289	—
MDU7109S	ST104	A520	—	—	—
MDU7110HS	ST104	A520	—	—	—
MDU7110RH	ST104	A520	—	5289	—
MDU7111LH	ST104	A520	—	5289	—
MDU7111LHS	ST104	A520	—	—	—
MDU7112	ST104	A520	—	5289	—
MDU7115	—	A520	—	4258	—
MDU7116	—	A520	—	4258	—
MDU8007A	—	A520	—	5289	—
MDU8007AT	—	—	—	5289	—
MDW4001M	—	A523	—	—	—
MDW4002M	—	A523	—	—	—
MDW4003M	—	A523	—	—	—
MDW4004M	—	A523	—	—	—
MDW4005M	—	A523	—	—	—
MDW4006M	—	A523	—	—	—
MDW4007	—	A523	—	—	—
MDW4102M	—	A523	—	—	—
MDW4103M	—	A523	—	—	—
MDW4104M	—	A523	—	—	—
MDW4202M	—	A523	—	—	—
MDW4204M	—	A523	—	—	—
MDW4302M	—	A523	—	—	—
MDW4304M	—	A523	—	—	—
MDY6002	ST104	A520	—	5289	—
MDY6005	ST104	A520	—	5289	—
MDY6006	ST104	A520	—	5289	—
MDY6007	ST104	A520	—	5289	—
MDY6008	ST104	A520	—	5289	—
MDY6009	ST105	A520	—	5289	—
MDY6101	—	A519	—	—	—
MDY6102	—	A519	—	—	—
MDY6103	—	A519	—	—	—
MDY6104	—	A519	—	—	—
MDY6104XP	—	A519	—	—	—
MDY6105	—	A519	—	5289	—
MDY6106	—	A519	—	5289	—
MDY6107	ST51	A519	—	4258	—
MDY6108	—	A519	—	5289	—
MDY6109	—	A519	—	—	—
MDY6110	—	A519	—	5289	—
MDY6111	—	A519	—	5289	—
MDY6112	—	A519	—	5289	—
MDY6113	—	A519	—	5289	—
MDY6114	—	A519	—	5289	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MDY6116	—	A519	—	—	—
MDY6116S	—	A519	—	—	—
MDY6117	—	A519	—	—	—
MDY6118	—	A519	—	—	—
MDY6119	—	A519	—	—	—
MDY6120	—	A519	—	—	—
MDY6121	—	A519	—	—	—
MDY6122	—	A519	—	—	—
MDY6183	—	A519	—	—	—
MDY7002	—	A520	—	—	—
MDY7003	—	A520	—	—	—
MDY7004	ST51	A520	—	—	—
MDY7005	ST51	A520	—	4258	—
MDY7006	ST51	A520	—	4258	—
MDY7009	—	A520	—	4258	—
MDY7010	ST51	A520	—	4258	—
MDY7010A	ST51	A520	—	4258	—
MDY7011	—	A520	—	4258	—
MDY7012	ST51	A520	—	4258	—
MDY7013	—	A520	—	4258	—
MDY7014	—	A520	—	4258	—
MDY7017	—	A520	—	4258	—
MDY7018	—	A520	—	—	—
MDY7019	ST51	A520	—	4258	—
MDY7020	—	A520	—	—	—
MDY7020A	—	A520	—	—	—
MDY7021	—	A520	—	5289	—
MDY7023	—	A520	—	5289	—
MDY7024	—	A520	—	5289	—
MDY7027	—	A520	—	—	—
MDY7029	—	A520	—	—	—
MDY7030	—	A520	—	—	—
MDY7031	ST51	A520	—	—	—
MDY7032	—	A520	—	—	—
MDY7032A	ST51	A520	—	—	—
MDY7037	—	A520	—	—	—
MDY7037S	—	A520	—	—	—
MDY7038	ST51	A520	—	4258	—
MDY7039	—	A520	—	—	—
MDY7039S	—	A520	—	—	—
MDY7042	—	A520	—	—	—
MDY7042A	—	A520	—	—	—
MDY7044	—	A520	—	—	—
MDY7045	—	A520	—	5289	—
MDY7045A	—	A520	—	5289	—
MDY7046	—	A520	—	5289	—
MDY7046A	—	A520	—	5289	—
MDY7048	—	A520	—	5289	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MDY7049	—	A520	—	5289	—
MDY7051	—	A520	—	5289	—
MDY7053	—	A520	—	—	—
MDY7054	—	A520	—	5289	—
MDY7056	—	A520	—	5289	—
MDY7057	—	A520	—	—	—
MDY7058	—	A520	—	—	—
MDY7060	ST51	A520	—	4258	—
MDY7061	—	A520	—	—	—
MDY7062	ST51	A520	—	4258	—
MDY7063	—	A520	—	—	—
MDY8006A	—	A520	—	5289	—
MDY8101A	—	A520	—	5289	—
MDY8102A	—	A520	—	5289	—
MDZ4001UT	—	—	—	4264	—
MDZ6001UT	—	—	—	4264	—
MDZ6011	—	A519	—	4258	—
MEC4010	ST104	A520	—	—	4258
MEC6001	ST104	A520	—	5289	—
MEC6002	ST104	A520	—	5289	—
MEC6003	ST105	A520	—	5289	—
MEC6010	ST104	A520	—	—	—
MEC6101	ST104	A519	—	5289	—
MEC6102	—	A519	—	5289	—
MEC6103	—	A519	—	5289	—
MEC6401	—	A514	—	—	—
MEG6003	—	A520	—	4258	—
MEG6101	—	A519	—	—	—
MEG7001	ST51	A520	—	—	—
MEG7002	—	A520	—	—	—
MEJ6001	ST51	—	4278	4258	—
MEJ6003	—	—	4264	—	—
MEJ6101	—	—	4264	—	—
MEJ6102A	—	—	4264	—	—
MEJ6103	—	—	4264	—	—
MEJ8001B	—	—	4264	4264	—
MEJ8001C	—	—	4264	4264	—
MEK6001AT	—	—	—	5289	—
MEK6001T	—	—	—	5289	—
MEK6001UT	—	—	—	5289	—
MEK6004T	—	—	—	5289	—
MEO4001	—	A520	—	—	—
MEO4002	—	A520	—	—	—
MEO6001	ST103	—	—	4264	—
MEO6003	—	—	—	4264	—
MEO6003T	—	—	—	4264	—
MEO6004	ST103	—	—	4264	—
MEO6005	ST103	—	—	4264	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg	Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MEO6005A	ST103	—	—	4264	—	MFY8001B	—	—	4278	—	—
MEO6008	—	A520	—	—	—	MFY8001C	—	—	4278	—	—
MEO6009	—	—	—	4264	—	MFY8002AT	—	—	4278	—	—
MEO7003	—	—	—	5289	—	MGA4001	—	A523	—	—	—
MEO7004	—	A520	—	5289	—	MGB4001	—	—	—	5289	—
MEO7005	—	A520	—	5289	—	MGB4001T	—	—	—	5289	—
MER4001	—	—	4258	4258	—	MGB4002T	—	—	—	5289	—
MER4002	—	—	4258	4258	—	MHA6001	—	A519	—	—	—
MEU6001	—	—	4278	—	—	MHA6001S	—	A519	—	—	—
MEU8003A	—	—	4278	—	—	MHA6001T	—	A519	—	—	4258
MEU8003B	—	—	4278	—	—	MHA7002	—	A520	—	4258	—
MEU8003C	—	—	4278	—	—	MHA7004	ST51	A520	—	4258	—
MEW8001B	—	—	4278	—	—	MHA7005	—	A520	—	5289	—
MEX7002	—	—	—	5289	—	MHA7006	—	A520	—	5289	—
MEX7101T	—	—	—	4264	—	MHA7007	—	A520	—	—	—
MEX7102	—	—	—	4264	—	MHA7007A	—	A520	—	—	—
MEX7102T	—	—	—	4264	—	MHA7008	ST51	A520	—	5289	—
MEX7103	—	—	—	5289	—	MHA7009	—	A520	—	5289	—
MEX7103T	—	—	—	5289	—	MHA7010	—	A520	—	5289	—
MEY4001	—	—	—	4258	—	MHA7011	—	A520	—	—	—
MEY4002	—	—	—	4258	—	MHA7012	—	A520	—	5289	—
MEY4006	—	—	—	4258	—	MHA7013	—	A520	—	5289	—
MEZ6101	—	A519	—	—	—	MHA7014	—	A520	—	5289	—
MEZ7001	—	A520	—	—	—	MHA7014A	—	A520	—	5289	—
MEZ7002	—	A520	—	—	—	MHA7015	—	A520	—	5289	—
MFB6001	ST51	A520	—	—	—	MHA7016	—	—	—	5289	—
MFD6001T	—	—	—	4264	—	MHA7017	—	A520	—	—	—
MFD6002T	—	—	—	4264	—	MHA7018	—	A520	—	5289	—
MFE6001	—	A519	—	—	—	MHA7019	—	A520	—	4258	—
MFE6002	—	A519	—	—	—	MHA7020	—	—	—	5289	—
MFL4001	—	—	4258	4258	—	MHB4015	—	—	—	4258	—
MFY8001A	—	—	—	4264	—	MHB4015R	—	—	—	4258	—
MFY4001T	—	—	4278	—	—	MHJ4001UT	—	—	—	5289	—
MFY6101AUT	—	—	4278	—	—	MHJ4002	—	—	—	4337	—
MFY6101BUT	—	—	4278	—	—	MHJ4003	—	—	—	4337	—
MFY6101IUT	—	—	4278	—	—	MHJ4003S	—	—	—	4337	—
MFY6101KUT	—	—	4278	—	—	MHJ4004	—	A520	—	—	—
MFY6101UT	—	—	4278	—	—	MHJ4004R	—	A520	—	—	—
MFY6104CUT	—	—	4278	—	—	MHJ4005	—	A520	—	—	—
MFY6104DUT	—	—	4278	—	—	MHJ4005R	—	A520	—	—	—
MFY6104KUT	—	—	4278	—	—	MHJ7001	—	—	—	4258	—
MFY6301	—	—	4278	—	—	MHJ7002T	—	—	—	4258	—
MFY6501CUT	—	—	4278	—	—	MHJ7101	—	—	—	5289	—
MFY6501EUT	—	—	4278	—	—	MHJ7101T	—	—	—	5289	—
MFY8001AT	—	—	4278	—	—	MHJ7102T	—	—	—	5289	—
MFY8001ATB	—	—	4278	—	—	MHJ7103	—	A520	—	4264	—
MFY8001ATC	—	—	4278	—	—	MHJ7103T	—	A520	—	4264	—
MFY8001ATT	—	—	4278	—	—	MHL4001	—	—	4347	—	—

(continued on next column)

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MHN4001	—	A520	—	—	—
MHN4005	—	A520	—	—	—
MHN4006	—	A520	—	—	—
MHN4007	—	A520	—	—	—
MHP4101	—	—	—	4337	—
MHP7101T	—	—	—	4264	—
MHU7001T	—	—	—	4258	—
MHU7001TS	—	—	—	4258	—
MHU7103	—	—	—	4264	—
MHU7103T	—	—	—	4264	—
ML4122	ST6	—	—	—	—
ML4127	ST6	—	—	—	—
ML4130	ST51	—	—	—	4258
ML4130	ST6 ³⁶	—	—	—	—
ML4140	ST6	—	—	—	—
ML4145	ST51	—	—	—	4258
ML4145	ST6 ³⁶	—	—	—	4258
ML4154	ST6	—	—	4258	—
ML4156	ST6	—	—	4258	—
ML4157	ST6	—	—	4258	—
ML4159	—	M400	—	—	—
ML4162	—	—	—	4258	—
ML4163	—	—	—	4258	—
ML4164	ST6	—	—	—	—
ML4166	—	—	—	4258	—
ML4170	—	—	—	4258	—
ML4173	ST6	—	—	—	—
ML4175	—	—	—	4258	—
ML4176	ST63	—	—	4258	—
ML4176A	ST63	—	—	4258	—
ML4177	ST6	—	—	4337	—
ML4178	ST6	—	—	4337	—
ML4179	ST6	—	—	4258	—
ML4180	ST6	—	—	4258	—
ML4181	ST63	—	—	4258	—
ML4185	—	—	—	4337	—
ML4186	ST6	—	—	4258	—
ML4187	ST63	—	—	4258	—
ML4188	ST63	—	—	4258	—
ML4191	ST6	—	—	4258	—
ML4192	ST63	—	—	4258	—
ML4193	ST51	—	—	—	—
ML4196	ST51	—	—	4337	—
ML4197	ST63	—	—	4258	—
ML4199	ST63	—	—	4258	—
ML4200	ST63	—	—	4258	—
ML4201	ST51	—	—	4337	—
ML4202	ST63	—	—	4258	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
ML4203	ST79	—	—	—	—
ML4205	ST63	—	—	4258	—
ML4207	ST6	—	—	4258	—
ML4211	ST63	—	—	4258	—
ML4212	ST63	—	—	4258	—
ML4213	ST51	—	—	4337	—
ML4214	ST6	—	—	4258	—
ML4215	—	—	—	4258	—
ML4216	ST6	—	—	4258	—
ML4218	ST51	M400	—	—	—
ML4219	ST79	—	—	—	—
ML4220	ST63	—	—	—	—
ML4221	ST63	—	—	4258	—
ML4303	—	—	—	4258	—
ML4304	—	—	—	4258	—
ML4305	—	—	—	4258	—
ML4307	ST51	—	—	—	—
ML4308	ST51	—	—	4337	—
ML4309	—	—	—	4258	—
ML4310	ST63	—	—	4258	—
ML4310A	—	—	—	4258	—
ML4312	ST63	—	—	4258	—
ML4313	ST63	—	—	4258	—
ML4314	—	—	—	4337	—
ML4316	—	—	—	4337	—
ML4316A	—	—	—	4337	—
ML4318	—	—	—	4258	—
ML4319	ST51	—	—	4337	—
ML4320M	—	—	—	4337	—
ML4321M	—	—	—	4258	—
ML4322	ST51	—	—	4337	—
ML4324	ST63	—	—	4258	—
ML4325	ST63	—	—	4258	—
ML4327	—	—	—	4337	—
ML4329	—	—	—	4258	—
ML4330	—	—	—	4258	—
ML4331	ST63	—	—	4258	—
ML4332	ST63	—	—	4337	—
ML4334	ST6	—	—	4258	—
ML4343	ST51	—	—	4337	—
ML4345	ST63	—	—	4258	—
ML4346	ST63	—	—	4258	—
ML4352	ST51	—	—	4337	—
ML4352A	ST51	—	—	4337	—
ML4353	ST51	—	—	—	—
ML4356	ST51	—	—	—	—
ML4363	ST51	—	—	—	—
ML4372	ST51	—	—	—	—

(continued on next page)

³⁶ Mechanical switch

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MMD4001	—	—	—	4337	—
MMD4401	—	—	—	4337	—
MMG4002	—	A520	—	—	—
MMU4001	—	—	—	4258	—
MMU4001R	—	—	—	4258	—
MR4104	ST6	—	—	—	—
MR4108	ST6	—	—	4337	—
MR4111	ST51	—	—	4337	—
MR4113	ST6	—	—	—	—
MR4113A	ST6	—	—	—	—
MR4115	ST63	—	—	—	—
MR4116	ST79	—	—	—	—
MR4118	ST6	—	—	—	—
MR4119	ST51	—	—	4337	—
MR4122	ST6	—	—	4337	—
MZ4006	ST63	A502	—	4258	—
MZ4008	ST6	A502	—	4258	4258
MZ4019	ST6	A502	—	4258	4258
MZ4020	ST6	A502	—	4258	4258
MZ4022	ST6	A502	—	4258	4258
MZ4023	ST6	A502	—	4258	—
MZ4023A	ST6	A502	—	4258	4258
MZ4024	—	A502	—	—	—
MZ4025	—	A502	—	—	—
MZ4027	—	A502	—	4258	4258
MZ4027A	ST63	A502	—	4258	—
MZ4028	ST6	A502	—	—	—
MZ4031	ST6	A502	—	—	—
MZ4031A	ST6	A502	—	—	—
MZ4033	ST6	A502	—	—	4258
MZ4035	ST63	A502	—	—	—
MZ4036	—	A502	—	—	—
MZ4037	ST63	A502	—	—	—
MZ4038	—	A502	—	—	—
MZ4039	ST63	A502	—	—	—
MZ4040	ST63	A502	—	—	—
MZ4041	—	A502	—	4258	—
MZ4042	ST63	A502	—	4258	4258
MZ4044	ST6	A502	—	4258	4258
MZ4045	ST63	A502	—	—	—
MZ4046	—	A502	—	4264	4258
MZ4046T	—	—	—	4264	—
MZ4047	—	A502	—	4258	4258
MZ4048	ST51	A502	—	—	—
MZ4049	ST63	A502	—	—	4258
MZ4050	ST63	A502	—	—	—
MZ4051	ST63	A502	—	4264	4258
MZ4051A	ST63	A502	—	4264	4258

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MZ4051T	—	—	—	4264	—
MZ4052	ST63	A502	—	—	—
MZ4055	ST63	A502	—	—	—
MZ4056	—	A502	—	4264	—
MZ4057	—	A502	—	—	—
MZ4058	—	A502	—	4258	—
MZ4059	—	A502	—	4264	—
MZ4059A	—	A502	—	4264	—
MZ4060	—	A502	—	—	—
MZ4061	ST79	A502	—	—	—
MZ4062	—	A502	—	4264	—
MZ4062A	—	A502	—	4264	—
MZ4063	—	A502	—	—	—
MZ4064	—	A502	—	—	4258
MZ4065	ST58	A502	—	4264	4258
MZ4066	—	A502	—	—	—
MZ4067	ST6	A502	—	—	—
MZ4068	ST6	A502	—	4258	4258
MZ4069	ST6	A502	—	4264	4258
MZ4071	ST6	A502	—	4258	—
MZ4072	—	A502	—	—	—
MZ4073	—	A502	—	—	—
MZ4074	—	A502	—	—	—
MZ4075	—	A502	—	—	—
MZ4076	—	A502	—	4264	—
MZ4077	ST6	A502	—	—	—
MZ4078	ST63	A502	—	4264	—
MZ4079	—	A502	—	—	—
MZ4079A	—	A502	—	—	—
MZ4080	ST63	A502	—	4258	—
MZ4082	—	A502	—	—	4258
MZ4084	—	A502	—	—	—
MZ4085	ST63	A502	—	4258	4258
MZ4085T	—	—	—	4258	—
MZ4086	ST6	A502	—	4258	4258
MZ4087	ST63	A502	—	—	—
MZ4089	—	A502	—	4264	—
MZ4089A	—	A502	—	4264	—
MZ4090	ST6	A502	—	—	—
MZ4092	ST63	A502	—	—	—
MZ4092A	ST63	A502	—	—	—
MZ4093	—	A502	—	—	4258
MZ4094	ST63	A502	—	—	—
MZ4095	—	A502	—	4258	—
MZ4096	—	A502	—	—	—
MZ4098	—	A502	—	—	—
MZ4099	—	A502	—	—	4258
MZ4100	ST63	A502	—	—	4258

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MZ4101	—	A502	—	—	4258
MZ4102	—	A502	—	—	—
MZ4103	ST26	A502	—	—	—
MZ4104	ST6	A502	—	4264	4258
MZ4105	—	A502	—	4264	—
MZ4106	ST63	A502	—	4264	—
MZ4106A	ST63	A502	—	4264	—
MZ4107	—	A502	—	4264	—
MZ4107A	—	A502	—	4264	—
MZ4108	ST63	A502	—	—	4258
MZ4109	—	A502	—	—	4258
MZ4111	—	A502	—	—	—
MZ4112	—	A502	—	—	—
MZ4113	—	A502	—	—	4258
MZ4114	—	A502	—	—	—
MZ4115	—	A502	—	4264	—
MZ4118	—	A502	—	4264	4258
MZ4118M	ST6	A502	—	4264	4258
MZ4120M	—	A502	—	—	—
MZ4121	—	A502	—	4258	4258
MZ4123	—	A502	—	4264	4258
MZ4127	—	A502	—	4264	4258
MZ4128	—	A502	—	4258	—
MZ4129	ST63	A502	—	4258	—
MZ4130	ST63	A502	—	—	—
MZ4130A	ST63	A502	—	—	—
MZ4131	ST63	A502	—	—	—
MZ4133	ST62	A502	—	4258	—
MZ4134	—	A502	—	—	—
MZ4135	ST63	A502	—	4258	4258
MZ4136	ST27	A502	—	4258	—
MZ4137	—	A502	—	—	—
MZ4138	—	A502	—	4258	4258
MZ4138T	—	—	—	4258	—
MZ4139	ST63	A502	—	4258	—
MZ4140	—	A502	—	4264	—
MZ4141	—	A502	—	—	—
MZ4142	ST63	A502	—	4258	—
MZ4143	—	A502	—	4264	—
MZ4144	—	A502	—	4258	—
MZ4144M	—	A502	—	4258	—
MZ4145	—	A502	—	4258	4258
MZ4146	ST63	A502	—	4258	4258
MZ4146A	—	A502	—	4258	4258
MZ4147	—	A502	—	—	—
MZ4148	—	A502	—	4264	—
MZ4149	ST63	A502	—	4258	—
MZ4149A	ST63	A502	—	4258	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MZ4150	ST63	A502	—	4258	4258
MZ4151	ST27	A502	—	4258	—
MZ4152	ST27	A502	—	4258	—
MZ4153	ST63	A502	—	—	—
MZ4154	—	A502	—	4264	—
MZ4155	—	A502	—	—	—
MZ4156	ST63	A502	—	4258	—
MZ4157	—	A502	—	4258	—
MZ4159	ST63	A502	—	—	—
MZ4160	ST26	A502	—	—	—
MZ4161	ST63	A502	—	4258	—
MZ4162	—	A502	—	—	—
MZ4163	—	A502	—	—	—
MZ4164	ST58	A502	—	—	4258
MZ4165	—	A502	—	—	—
MZ4166	ST63	A502	—	4258	—
MZ4166S	ST63	A502	—	4258	—
MZ4166T	—	—	—	4258	—
MZ4167	ST58	A502	—	4258	—
MZ4170	ST63	A502	—	4258	—
MZ4171	ST63	A502	—	4258	—
MZ4172	—	A502	—	4258	—
MZ4174	—	A502	—	4258	—
MZ4174S	—	A502	—	4258	—
MZ4175	ST6	A502	—	4264	4258
MZ4176	—	A502	—	4258	—
MZ4178	—	A502	—	4258	—
MZ4179	ST63	A502	—	4258	—
MZ4180	—	A502	—	4258	—
MZ4181	—	A502	—	4258	—
MZ4181T	—	—	—	4258	—
MZ4183	ST63	A502	—	4264	4258
MZ4184	ST6	A502	—	—	—
MZ4185	—	A502	—	—	—
MZ4187	ST63	A502	—	4258	—
MZ4187T	—	—	—	4258	—
MZ4188	ST63	A502	—	4258	—
MZ4189	—	A502	—	4258	—
MZ4190	ST63	A502	—	4258	—
MZ4191T	—	—	—	4258	—
MZ4192	—	A502	—	4258	—
MZ4193	—	A502	—	4258	—
MZ4194	—	A502	—	4258	—
MZ4195	—	A502	—	4258	—
MZ4195T	—	—	—	4258	—
MZ4196	—	A502	—	4258	—
MZ4197	ST63	A502	—	4258	—
MZ4198	ST63	A502	—	4258	—

(continued on next page)

AUTOLITE-PRESTOLITE (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MZ4199	—	A502	—	4258	—
MZ4201	—	A502	—	—	—
MZ4202	—	A502	—	—	—
MZ4203	—	A502	—	—	—
MZ4204	—	A502	—	4258	—
MZ4204R	—	A502	—	4258	—
MZ4205	—	A502	—	—	—
MZ4205R	—	A502	—	—	—
MZ4206	—	A502	—	—	—
MZ4206R	—	A502	—	—	—
MZ4207	—	A502	—	—	—
MZ4207R	—	A502	—	—	—
MZ4208	—	A502	—	—	—
MZ4208R	—	A502	—	—	—
MZ4209	ST63	A502	—	—	—
MZ4210	—	A502	—	—	—
MZ4212	—	A502	—	—	—
MZ4213	—	A502	—	—	—
MZ4216	—	A502	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
MZ4216R	—	A502	—	—	—
MZ4217	—	A502	—	—	—
MZ4217R	—	A502	—	—	—
MZ4218	—	A502	—	—	—
MZ4218R	—	A502	—	—	—
MZ4219	—	A502	—	—	—
MZ4219R	—	A502	—	—	—
MZ4220	—	A502	—	—	—
MZ4220R	—	A502	—	—	—
MZ4221	—	A502	—	—	—
MZ4221R	—	A502	—	—	—
MZ4222	—	A502	—	—	—
MZ4222R	—	A502	—	—	—
MZ4223	—	A502	—	—	—
MZ4223R	—	A502	—	—	—
MZ4224	—	A502	—	—	—
MZ4224R	—	A502	—	—	—
MZ7076	—	A502	—	4264	—

BMW

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
0001108115 ...	ST340	—	—
0001110041 ...	ST340	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
0001314045 ...	ST340	—	—

BOSCH

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
001155003	—	E552	5314	—	—
001311023	—	—	—	5314	—
001311026	—	—	—	5314	—
001311039	—	—	—	5314	—
0001155003 ...	—	E552	5314	—	—
0001157001 ...	—	—	5313	—	—
0001157003 ...	—	—	5313	—	—
0001157004 ...	—	—	5313	—	—
0001157006 ...	—	—	5313	—	—
0001157007 ...	—	—	5313	—	—
0001157008 ...	—	—	5313	—	—
0001157009 ...	—	—	5313	—	—
0001160001 ...	—	—	5313	—	—
0001160002 ...	—	—	5313	—	—
0001160003 ...	—	—	5313	—	—
0001160007 ...	—	—	5313	—	—
0001160010 ...	—	—	5313	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
0001160012 ...	—	—	5313	—	—
0001160013 ...	—	—	5313	—	—
0001203008 ...	—	E550	5313	—	—
0001203009 ...	—	E550	5313	—	—
0001203016 ...	—	E550	5313	—	—
0001204004 ...	—	E550	5313	—	—
0001204005 ...	—	E550	5313	—	—
0001205003 ...	—	E550	5313	—	—
0001205005 ...	—	E550	5313	—	—
0001205012 ...	—	E550	5313	—	—
0001205015 ...	—	E550	5313	—	—
0001207001 ...	—	E551	5313	—	—
0001207002 ...	—	E551	5313	—	—
0001207013 ...	—	E551	5313	—	—
0001207015 ...	—	E551	5313	—	—
0001207018 ...	—	E551	5313	—	—
0001207019 ...	—	E551	5313	—	—

(continued on next page)

BOSCH (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
0001208001 ...	—	E552	5313	—	—
0001208002 ...	—	E552	5313	—	—
0001208003 ...	—	E552	5313	—	—
0001208006 ...	—	E552	5313	—	—
0001208007 ...	—	E552	5313	—	—
0001208009 ...	—	E552	5313	—	—
0001208014 ...	—	E552	5313	—	—
0001208023 ...	—	E552	5313	—	—
0001208024 ...	—	E552	5313	—	—
0001208025 ...	—	E552	5313	—	—
0001208026 ...	—	E552	5313	—	—
0001208029 ...	—	E552	5313	—	—
0001208032 ...	—	E552	5313	5314	—
0001208033 ...	—	E552	5313	—	—
0001208036 ...	—	E552	5313	—	—
0001208037 ...	—	E552	5313	—	—
0001208038 ...	—	E552	5313	—	—
0001208039 ...	—	E552	5313	—	—
0001208046 ...	—	E552	5313	—	—
0001208047 ...	—	E552	5313	—	—
0001208048 ...	—	E700	5313	—	—
0001208053 ...	—	E552	5313	—	—
0001208054 ...	—	—	5313	—	—
0001208056 ...	—	—	5313	—	—
0001208058 ...	—	E552	5313	—	—
0001208200 ...	—	E551	5313	—	—
0001208201 ...	—	E551	5313	—	—
0001208202 ...	—	E551	5313	—	—
0001208211 ...	—	E551	5313	—	—
0001208221 ...	—	E551	5313	—	—
0001208225 ...	—	E551	5313	—	—
0001208227 ...	—	—	5313	—	—
0001208403 ...	ST215	—	5313	—	—
0001208404 ...	—	E551	5313	—	—
0001208407 ...	ST216	—	5313	—	—
0001211001 ...	—	E552	5313	—	—
0001211002 ...	—	E552	5313	—	—
0001211004 ...	—	E552	5313	—	—
0001211005 ...	—	E552	5313	—	—
0001211012 ...	—	E552	5313	—	—
0001211013 ...	—	E552	5313	—	—
0001211016 ...	—	E552	5313	—	—
0001211017 ...	—	E552	5313	—	—
0001211023 ...	—	E552	5313	—	—
0001211025 ...	—	E552	5313	—	—
0001211209 ...	—	E551	5313	—	—
0001211210 ...	—	E551	5313	—	—
0001211218 ...	—	E551	5313	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
0001211221 ...	ST222	E551	5313	—	—
0001211222 ...	—	E551	5313	—	—
0001211223 ...	—	E551	5313	—	—
0001211227 ...	—	F517	—	—	—
0001211987 ...	—	E551	5313	—	—
0001211989 ...	—	E551	5313	—	—
0001211993 ...	ST222	E551	5313	—	—
0001211997 ...	ST222	E551	5313	—	—
0001211998 ...	ST222	E551	5313	—	—
0001212002 ...	—	E552	5313	4664	—
0001212005 ...	ST221	E552	5313	4664	—
0001212006 ...	ST221	E552	5313	4664	—
0001212007 ...	ST221	—	5313	—	—
0001212008 ...	—	—	5313	—	—
0001212011 ...	—	—	5313	4664	—
0001212012 ...	—	E552	5313	4664	—
0001212013 ...	—	E552	5313	4664	—
0001212204 ...	ST226	E551	5313	—	—
0001212206 ...	ST226	E551	5313	—	—
0001212207 ...	ST226	E551	5313	—	—
0001212208 ...	ST221	E551	5313	—	—
0001213003 ...	—	E551	5313	—	—
0001214001 ...	—	E552	5313	—	—
0001215001 ...	—	E700	5313	—	—
0001304016 ...	—	E550	—	—	—
0001304019 ...	—	E550	—	—	—
0001306004 ...	—	E550	—	—	—
0001307004 ...	—	E550	—	—	—
0001307007 ...	—	E550	—	—	—
0001307009 ...	—	E550	—	—	—
0001307010 ...	—	E550	—	—	—
0001307014 ...	—	E550	—	—	—
0001307018 ...	—	E550	—	—	—
0001307019 ...	—	E550	—	—	—
0001307021 ...	—	E550	—	—	—
0001307022 ...	—	E550	—	—	—
0001310000 ...	—	E551	5313	—	—
0001310005 ...	—	E551	5313	—	—
0001310007 ...	—	E551	5313	—	—
0001310010 ...	—	E551	5313	—	—
0001310013 ...	—	E551	5313	5321	—
0001310050 ...	—	E552	5313	—	—
0001310054 ...	—	E552	5313	—	—
0001311001 ...	—	E552	5313	5321	—
0001311007 ...	—	E552	5313	—	—
0001311016 ...	—	E552	5313	5321	—
0001311023 ...	—	E552	5313	—	—
0001311024 ...	—	—	5313	—	—

(continued on next page)

BOSCH (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
0001311026 ...	—	E552	5313	—	—
0001311027 ...	—	E552	5313	—	—
0001311032 ...	—	—	5313	—	—
0001311033 ...	—	E552	5313	—	—
0001311034 ...	—	E552	5313	—	—
0001311035 ...	—	—	5313	—	—
0001311038 ...	—	E552	5313	—	—
0001311039 ...	—	E552	5313	—	—
0001311040 ...	—	—	5313	—	—
0001311041 ...	—	—	5313	—	—
0001311042 ...	—	E552	5313	5321	—
0001311045 ...	—	E552	—	—	—
0001311046 ...	—	E552	5313	—	—
0001311100 ...	—	E700	5313	—	—
0001311103 ...	—	E700	5313	5314	—
0001311105 ...	—	E700	5313	5314	—
0001311108 ...	—	E700	5313	5314	—
0001311109 ...	—	E700	5313	5314	—
0001311110 ...	—	—	5313	—	—
0001311113 ...	—	E700	5313	—	—
0001311114 ...	—	E700	—	—	—
0001311116 ...	—	E552	5313	—	—
0001311120 ...	—	E552	5313	—	—
0001311122 ...	—	—	5313	—	—
0001311124 ...	—	E700	5313	—	—
0001311126 ...	—	E700	5313	—	—
0001311134 ...	—	E700	5313	—	—
0001312000 ...	—	E550	5313	4664	—
0001312100 ...	—	E550	5313	4664	—
0001312101 ...	—	—	5313	4664	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg
0001312102 ...	—	E700	5313	4664	—
0001312103 ...	—	—	5313	4664	—
0001312105 ...	—	E700	5313	4664	—
0001313001 ...	—	E552	5313	—	—
0001313003 ...	—	E552	5313	—	—
0001313005 ...	—	E552	5313	—	—
0001313007 ...	—	—	5313	—	—
0001314001 ...	—	E700	5313	—	—
0001314002 ...	—	—	5313	—	—
0001314003 ...	—	—	5313	—	—
0001314004 ...	—	—	5313	—	—
0001314005 ...	—	—	5313	—	—
0001314010 ...	—	E700	—	—	—
0001314012 ...	—	E552	5313	—	—
0001314013 ...	—	—	5313	—	—
0001314014 ...	—	E700	5313	—	—
0001314016 ...	—	E700	—	—	—
0001314018 ...	—	E551	5313	—	—
0001314025 ...	—	—	5313	—	—
0001315002 ...	—	—	5313	—	—
0001362047 ...	ST251	E701	—	—	—
0001362069 ...	ST251	E701	—	—	—
0031512801 ...	ST328	—	—	—	—
0031513801 ...	ST328	—	—	4671	—
0031515001 ...	ST328	—	—	—	—
0031517001 ...	ST251	—	—	—	—
0041513701 ...	ST286	—	—	—	—
0041514401 ...	ST328	—	—	—	—

CHRYSLER (ALSO SEE MITSUBISHI)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg	Solenoid Repair Kit
MD001333	ST213	—	—	—	—	—
MD001550	—	E587	—	—	—	—
MD001552	—	E587	—	—	—	—
MD001553	—	E587	—	—	—	—
MD001555	—	E587	—	—	—	—
MD003550	—	E587	—	—	—	—
MD003551	—	E587	—	—	—	—
MD021665	—	E587	—	—	—	—
MD021666	—	E587	—	—	—	—
MD021670	—	E587	—	—	—	—
MD021672	—	E587	—	—	—	—
MD021674	ST213	E587	—	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg	Solenoid Repair Kit
MD021676	—	E587	—	—	—	—
MD025235	—	E591	—	—	—	—
MD027382	ST300	—	—	—	—	—
MD027400	ST213	E587	—	—	—	—
MD027401	ST213	E587	—	—	—	—
MD034120	ST300	—	—	—	—	—
MD072585	ST300	—	—	—	—	—
MD085730	ST213	E481	—	—	—	—
MD180241	ST159	E512	—	—	—	—
MD306997	ST297	E512	—	—	—	—
MD306998	ST297	E512	—	—	—	—
MD602478	—	E587	—	—	—	—

(continued on next page)

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg	Solenoid Repair Kit
670662	ST63	A505	—	—	—	—
820400	—	A505	—	4264	—	—
868857	—	A505	—	4264	—	—
918151	—	A505	—	4264	—	—
920400	—	A505	—	4264	—	—
1070939	—	A505	—	4264	—	—
1075951	—	A505	—	4264	—	—
1126548	—	A514	—	4264	—	—
1194567	—	A505	—	4264	—	—
1261484	—	—	—	4264	—	—
1268125	—	A514	—	4264	—	—
1268126	—	A514	—	4264	—	—
1311459	—	A514	—	4264	—	—
1317790	—	A514	—	4264	—	—
1323911	—	A514	—	4264	—	—
1323915	—	—	—	4264	—	—
1326583	—	—	—	4264	—	—
1330243	—	—	—	4264	—	—
1330254	—	A514	—	4264	—	—
1343691	—	A514	—	4264	—	—
1343692	—	A514	—	4264	—	—
1343693	—	A514	—	4264	—	—
1383847	ST62	A514	—	4258	—	—
1392684	—	A514	—	4264	—	—
1405190	—	A514	—	4264	—	—
1405191	—	A514	—	4264	—	—
1440265	—	A514	—	4264	—	—
1473187	—	A514	—	4264	—	—
1473218	ST541	A514	—	4258	—	—
1473558	ST62	A514	—	4258	—	—
1484001	—	—	—	4264	—	—
1486137	—	—	—	4264	—	—
1486138	—	A514	—	4264	—	—
1488216	—	A514	—	4258	—	—
1503784	—	A514	—	4264	—	—
1508761	—	—	—	4264	—	—
1527689	—	A514	—	4264	—	—
1535557	—	A514	—	4258	—	—
1535558	—	A514	—	4258	—	—
1535559	—	A514	—	4258	—	—
1535560	—	A514	—	4258	—	—
1558150	—	—	—	4264	—	—
1558155	—	A514	—	4264	—	—
1569176	—	—	—	4264	—	—
1569178	—	—	—	4264	—	—
1569183	ST103	—	—	4264	—	—
1569185	—	—	—	4264	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg	Solenoid Repair Kit
1604035	ST541	—	—	4258	—	—
1604480	—	A514	—	4264	—	—
1605144	—	—	—	4264	—	—
1612205	—	E587	—	4258	—	—
1612706	—	—	—	4264	—	—
1616627	—	A514	—	4264	—	—
1627289	ST541	—	—	4258	—	—
1627290	ST541	—	—	4258	—	—
1630656	—	—	—	4264	—	—
1630683	ST63	A514	—	4258	—	—
1642140	—	—	—	4264	—	—
1642205	ST541	—	—	4258	—	—
1658033	ST541	—	—	4258	—	—
1660844	ST103	—	—	4264	—	—
1665053	ST103	—	—	4264	—	—
1665101	ST103	A519	—	5289	—	—
1677294	—	—	—	5289	—	—
1689338	ST66	A519	—	5289	—	—
1689339	ST541	A519	—	5289	—	—
1689340	ST541	A519	—	4258	—	—
1689341	ST541	A519	—	4258	—	—
1689342	ST103	A519	—	5289	—	—
1689343	ST103	A519	—	4264	—	—
1770712	ST103	A519	—	—	—	—
1779955	ST67	A519	—	5289	—	—
1793850	ST103	A519	—	5289	—	—
1842511	ST541	A519	—	—	—	—
1842520	—	A519	—	5289	—	—
1842562	ST103	A519	—	5289	—	—
1842563	ST103	A519	—	5289	—	—
1889100	ST106	M502	—	5289	—	STK12 ⁵
1889200	ST106	—	—	5289	—	STK12 ⁵
1889260	ST67	A519	—	5289	—	—
1889295	ST67	A519	—	5289	—	—
1889297	ST67	A519	—	5289	—	—
1889463	—	A519	—	—	—	—
1889770	—	A520	—	—	—	—
1889774	ST66	A519	—	5289	—	—
1889955	ST66	A520	—	4264	—	—
1922635	—	A519	—	4258	—	—
1922641	ST103	A519	—	5289	—	—
1941107	ST51	A519	—	4258	—	—
1941117	ST51	A519	—	4258	—	—
1941118	ST103	A519	—	4264	—	—
1941119	—	A519	—	4264	—	—
2038345	—	A520	—	5337	—	—
2065400	—	A519	—	5289	—	—

(continued on next page)

⁵ Starter repair kit

CHRYSLER (ALSO SEE MITSUBISHI) (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg	Solenoid Repair Kit	Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Bushing Center Brg	Solenoid Repair Kit
2095055	ST66	A520	—	5289	—	—	4091975	—	M503	—	5301	5300 ³²	STK48
2095150	—	M503	—	5289	—	—	4106114	—	M503	—	5301	5300 ³²	STK48
2095179	ST109	A520	—	5289	—	—	4106144	—	M503	4556	5301 ⁹	5300 ³²	—
2095254	ST67	A520	—	—	—	—	4111855	—	M503	—	5301	5300 ³²	STK48
2095296	—	A520	—	5289	—	—	4111860	—	M503	—	5301	5300 ³²	STK48
2095393	ST74	A520	—	—	—	—	4145359	—	M503	—	5301	5300 ³²	STK48
2095400	—	A519	—	—	—	—	4145360	—	M503	—	5301	5300 ³²	—
2095406	—	A519	—	5337	—	—	4240430	ST216	—	—	—	—	—
2095407	—	A519	—	5289	—	—	4339472	ST216	—	—	—	—	—
2095496	—	—	—	4258	—	—	4339474	ST216	—	—	—	—	—
2095500	—	M503	—	5289	—	—	4379143	ST160	—	—	—	—	—
2095509	ST66	A520	—	5289	—	—	4379144	ST160	—	—	—	—	—
2095753	ST106	M502	—	5289	—	STK12 ⁵	4379160	ST160	—	—	—	—	—
2095816	ST63	—	—	4258	—	—	4419308	ST216	F517	—	—	—	—
2095829	ST103	A519	—	5289	—	—	4557130	ST216	—	—	—	—	—
2098150	—	M503	—	—	—	—	4609150	ST159	E512	—	—	—	—
2098221	ST77	A519	—	5337	—	—	4672108	ST159	E512	—	—	—	—
2098345	ST66	A520	—	—	—	—	5206255	ST216	—	—	—	—	—
2098500	—	M503	—	5289	—	—	5206260	ST215	—	—	—	—	—
2098879	ST113	R504	—	—	—	STK26	5213045	ST216	—	—	—	—	—
2444071	—	R85	—	—	—	—	5213090	—	M504	—	—	—	—
2600098	—	M503	4556	5289	—	—	5213190	ST307	—	—	—	—	—
2642325	—	—	—	5289	—	—	5213395	ST216	—	—	—	—	—
2642444	ST106	M502	—	5289	—	—	5213450	ST216	—	—	—	—	—
2642445	ST106	M502	—	5289	—	STK12 ⁵	5226441	ST216	F517	5313	—	—	—
2642625	—	—	—	5289	—	—	5226442	ST216	F517	5313	—	—	—
2642692	ST106	M502	—	5289	—	STK12 ⁵	5226444	ST216	—	—	—	—	—
2642930	ST106	M502	—	5289	—	STK12 ⁵	5226742	ST307	M504	5313	—	—	—
2875022	ST51	A520	—	4258	—	—	5226844	—	E591	—	—	—	—
2875560	—	M503	—	5301	5300 ³²	STK48	5226948	ST216	—	—	—	—	—
2875660	—	M503	4556	5289	—	—	5227248	ST162	—	—	—	—	—
2875927	—	A520	—	5289	—	—	5227282	ST216	—	—	—	—	—
2875928	—	A520	—	5289	—	—	5233006	ST216	—	—	—	—	—
2958166	ST113	R504	—	—	—	—	5233007	ST216	—	—	—	—	—
3656575	—	M503	—	5301	5300 ³²	STK48	5233656	ST216	—	—	—	—	—
3656650	—	M503	—	5301	5300 ³²	STK48	30001695	ST247	—	—	—	—	—
3755250	—	M503	—	5301	5300 ³²	STK48	30005226	ST247	E508	—	—	—	—
3755900	—	M503	—	5301	5300 ³²	STK48	30005563	ST247	E508	—	—	—	—
4057937	ST215	—	—	—	—	—							
4091950	—	M503	—	5301	5300 ³²	STK48							

(continued on next column)

DELCO REMY

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit	Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
MAS4082	ST6	—	—	—	—	2M	ST11	R500	4200	4265	—
1M	ST110	R500	4200	4265	STK5	3M	ST110	R500	4200	4265	STK5

(continued on next column)

(continued on next page)

⁵ Starter repair kit ⁹ Two required ³² Gear Housing

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
4M	ST100	R503	4200	5288	STK2
5M	ST33	R503	4200	5288	—
6M	ST100	R503	4200	5288	STK2
7M	ST124	R503	—	5288	STK15
8M	ST124	R503	—	5288	STK15
9M	ST124	R503	4200	5288	STK15
10M	ST124	R503	4200	5288	STK15
11M	ST124	R503	—	5288	STK15
12M	ST124	R503	—	5288	STK15
13M	ST124	R503	4200	5288	STK15
14M	ST124	R503	4200	5288	STK15
15M	ST110	R500	4200	4265	STK5
16M	ST100	R503	4200	5288	STK2
17M	ST100	R503	4200	5288	STK2
18M	ST124	R503	4200	5288	STK15
19M	ST124	R503	4200	5288	STK15
20M	ST124	R503	4200	5288	STK15
21M	ST124	R503	—	5288	STK15
22M	ST124	R503	4200	5288	STK15
23M	ST100	R503	4200	5288	STK2
24M	ST124	R503	4200	5288	STK15
25M	ST124	R503	4200	—	STK15
26M	ST124	R503	4200	5288	STK15
27M	ST100	R503	4200	5288	STK2
28M	ST124	R503	4200	5288	STK15
29M	ST124	R503	4200	5288	STK15
30M	ST124	R503	4200	5288	STK15
31M	ST124	R503	4200	5288	STK15
32M	ST124	R503	4200	5288	STK15
33M	ST100	R503	4200	5288	STK2
34M	ST100	R503	4200	5288	STK2
35M	ST124	R503	4200	5288	STK15
36M	ST124	R503	4200	5288	STK15
37M	ST100	R503	4200	5288	STK2
38M	ST124	R503	4200	5288	STK15
39M	ST124	R503	4200	5288	STK15
40M	ST124	R503	4200	5288	STK15
41M	ST124	R503	4200	5288	STK15
42M	ST124	R503	4200	5288	STK15
43M	ST124	R503	4200	5288	STK15
44M	ST124	R503	4200	5288	STK15
45M	ST124	R503	4200	5288	STK15
46M	ST124	R503	4200	5288	STK15
47M	ST124	R503	4200	5288	STK15
48M	ST124	R503	4200	5288	STK15
49M	ST124	R503	4200	5288	STK15
50M	ST124	R503	4200	5288	STK15
51M	ST124	R503	4200	5288	STK15

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
52M	ST124	R503	4200	5288	STK15
53M	ST124	R503	4200	5288	—
54M	ST124	R503	4200	5288	STK15
55M	ST124	R503	4200	5288	STK15
56M	ST124	R503	4200	5288	STK15
57M	ST124	R503	4200	5288	STK15
58M	ST11	R500	—	4265	—
59M	ST11	R500	—	4310	—
60M	ST110	R500	4200	4265	STK5
61M	—	R500	—	4200	—
62M	ST63	R500	—	4200	—
63M	ST500	R500	4200	4200	—
64M	—	R500	4200	4200	—
65M	—	R503	4200	4200	—
66M	—	R500	4200	4200	—
330	—	R81	4265	—	—
336	—	R81	—	—	—
336X	—	R81	—	—	—
339	—	R81	4200	—	—
340	—	R81	4200	—	—
347	—	R81	4200	—	—
350	—	R81	—	—	—
355	—	R81	4200	—	—
368	—	R81	4200	—	—
369	—	R81	4200	—	—
371	—	R81	—	—	—
374	—	R81	—	—	—
378	—	R81	—	—	—
382	—	R81	4200	—	—
382X	—	R81	4200	—	—
385	—	R81	—	—	—
386	—	R81	4200	—	—
388	—	R81	4200	—	—
412	—	R81	—	—	—
413	—	R81	—	—	—
414	—	R81	—	—	—
420	—	R81	4200	—	—
421	—	R81	4286	—	—
422	—	R81	4265	—	—
423	—	R81	—	4286	—
424	—	R81	—	—	—
425	—	R81	—	—	—
426	—	R81	—	—	—
427	—	R81	—	—	—
429	—	R81	—	—	—
443	—	R81	—	4286	—
444	—	R81	4286	—	—
446	—	R81	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
447	—	R81	—	4286	—
448	—	R81	—	4286	—
449	—	R81	—	4286	—
450	—	R81	—	—	—
452	—	R81	—	4286	—
453	—	R81	—	4286	—
454	—	R81	—	4286	—
455	—	R81	4265	—	—
456	—	R81	—	4286	—
457	—	R81	4265	4265	—
458	—	R81	—	—	—
459	—	R81	—	—	—
470	—	R81	—	—	—
471	—	R81	—	—	—
473	—	R81	—	—	—
475	—	R81	—	—	—
477	—	R81	—	4286	—
479	—	R81	—	4286	—
482	—	R81	—	—	—
483	—	R81	—	—	—
484	—	R81	4265	—	—
485	—	R81	—	4286	—
486	—	R81	—	—	—
487	—	R81	—	—	—
488	—	R81	4286	—	—
489	—	R81	4200	—	—
491	—	R81	—	4286	—
492	—	R81	—	4286	—
493	—	R81	—	4286	—
494	—	R81	—	—	—
495	ST11	R81	4265	4265	—
496	—	R81	—	—	—
497	—	R81	—	—	—
498	—	R81	—	—	—
499	—	R81	—	4286	—
534	—	R81	—	—	—
540	—	R81	—	4286	—
541	—	R81	4265	—	—
542	—	R81	—	—	—
543	—	R81	4265	—	—
544	—	R81	—	—	—
545	—	R81	—	—	—
546	—	R81	4265	—	—
547	—	R81	—	4286	—
548	—	R81	4265	4286	—
549	—	R81	—	—	—
571	—	R81	—	—	—
572	—	R81	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
573	—	R81	4265	4286	—
574	—	R81	4265	4286	—
575	—	R81	—	4286	—
577	—	R81	—	4286	—
578	—	R81	—	4286	—
579	—	R81	—	4286	—
580	—	R81	4265	4265	—
581	—	R81	—	4286	—
582	—	R81	—	4286	—
583	—	R81	—	4286	—
584	—	R81	—	4286	—
585	—	R81	—	4286	—
586	—	R81	—	4286	—
587	—	R81	—	4286	—
588	—	R81	5284	—	—
589	—	R81	5284	—	—
590	—	R81	4265	—	—
591	—	R81	—	4286	—
592	—	R81	—	—	—
593	—	R81	—	—	—
594	—	R81	—	4286	—
595	—	R81	5284	—	—
596	—	R81	5284	—	—
598	—	R81	5284	—	—
599	—	R81	—	4286	—
640	—	R81	4265	—	—
641	—	R81	4265	—	—
642	—	R81	4265	—	—
643	—	R81	5284	—	—
644	—	R81	—	—	—
645	—	R81	5284	—	—
646	—	R81	5284	—	—
648	—	R81	5284	—	—
649	—	R81	4265	—	—
650	—	R81	5284	—	—
651	—	R81	—	4286	—
652	—	R81	5284	—	—
653	—	R81	5284	—	—
655	—	R81	—	4286	—
657	—	R81	5284	—	—
658	—	R81	5284	4286	—
659	—	R81	5284	—	—
660	—	R81	5284	4286	—
661	—	R81	4265	—	—
662	—	R81	5284	—	—
664	—	R81	4265	4265	—
665	—	R81	—	—	—
666	—	R81	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
667	—	R81	5284	4286	—
668	—	R81	5284	—	—
669	—	R81	5284	—	—
700	—	R81	4265	—	—
701	—	R81	5284	—	—
702	—	R81	5284	—	—
704	—	R81	4265	4286	—
705	—	R81	—	—	—
706	—	R81	—	4286	—
707	—	R81	5284	—	—
708	—	R81	5284	—	—
709	—	R81	5284	4286	—
710	—	R81	—	—	—
710E	—	R503	—	—	—
711	—	R81	5284	—	—
713	—	R81	4265	4286	—
713A	—	R500	—	—	—
713B	—	R500	—	—	—
713C	—	R500	—	—	—
713D	—	R500	—	—	—
713E	—	R500	—	—	—
713F	—	R500	—	—	—
713G	—	R500	—	—	—
713H	—	R500	—	—	—
713I	—	R500	—	—	—
713J	—	R500	—	—	—
713K	—	R500	—	—	—
714	—	R81	4265	4200	—
714A	—	R500	—	—	—
714AX	—	R500	—	—	—
714B	—	R500	—	4200	—
714C	—	R500	—	4200	—
714D	—	R500	—	4200	—
714E	—	R500	—	4200	—
714F	—	R500	—	4200	—
714G	—	R500	—	4200	—
714H	ST11	R500	—	4265	—
714J	—	R500	—	4200	—
714L	—	R500	—	4200	—
714N	ST11	R500	—	4265	—
714P	ST11	R500	—	4200	—
714Q	ST11	R500	—	4265	—
714R	ST11	R500	—	—	—
714S	ST11	R500	—	4265	—
714U	ST11	—	—	4200	—
714V	ST11	—	—	4265	—
714W	ST11	R500	—	4265	—
714X	—	R500	—	4200	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
714Z	—	R500	—	4200	—
715	—	R81	—	—	—
716A	—	R500	—	—	—
716B	—	R500	—	4200	—
716C	—	R500	—	—	—
716D	—	R500	—	—	—
716E	—	R500	—	—	—
716G	—	R500	—	—	—
717	—	R81	—	—	—
717A	—	R500	—	—	—
718	—	R81	5284	—	—
718A	—	R500	—	4200	—
718B	—	R500	—	4200	—
718C	—	R500	—	4200	—
718D	—	R500	—	4200	—
718E	—	R500	—	4200	—
718F	—	R500	—	4200	—
718G	—	R500	—	4200	—
718H	—	R500	—	4200	—
718I	—	R500	—	4200	—
718J	—	R500	—	4200	—
718K	—	R500	—	4200	—
718L	—	R500	—	4200	—
718M	—	R500	4200	—	—
718P	—	—	—	4200	—
718Q	—	R500	—	—	—
718R	—	R500	—	4200	—
718S	—	—	—	4200	—
718U	—	R500	—	4200	—
718V	—	R500	—	4200	—
718W	—	R500	—	—	—
718X	—	R500	—	—	—
718Y	—	R500	—	—	—
718Z	—	R500	—	4200	—
719	—	R81	5284	4286	—
720	—	R81	5284	—	—
720Q	—	R503	—	—	—
720QX	—	R503	—	—	—
720R	—	R503	—	—	—
720S	—	R503	—	—	—
720T	—	R503	—	—	—
720U	—	R503	—	—	—
720V	—	R503	—	—	—
720W	—	R503	—	—	—
720X	—	R503	—	—	—
720Y	—	R503	—	—	—
720YX	—	R503	—	—	—
720Z	—	R503	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
721	—	R81	5284	—	—
721A	—	R503	—	—	—
721B	—	R503	—	—	—
721C	—	R503	—	—	—
721D	—	R503	—	—	—
721E	—	R514	—	—	—
721F	—	R503	—	—	—
721G	—	R514	—	—	—
721H	—	R503	—	—	—
721I	—	R503	—	—	—
721J	—	R503	—	—	—
721K	—	R503	—	—	—
721L	—	R503	—	—	—
721M	—	R503	—	—	—
721N	—	R514	—	—	—
721P	—	R514	—	—	—
722	—	R81	5284	—	—
722A	—	R503	—	—	—
722B	—	R503	—	—	—
722C	—	R503	—	—	—
722D	—	R514	—	—	—
722E	—	R503	—	—	—
722F	—	R503	—	—	—
722G	—	R503	—	—	—
722H	—	R503	—	—	—
722I	—	R500	—	—	—
722J	—	R503	—	—	—
722K	—	R503	—	—	—
722L	—	R503	—	—	—
722M	—	R503	—	—	—
722N	—	R503	—	4286	—
722P	—	R503	—	—	—
722Q	—	R503	—	—	—
722R	—	R500	—	—	—
722S	—	R503	—	—	—
722T	—	R503	—	—	—
722U	—	R503	—	—	—
722V	—	R514	—	4286	—
722W	—	R503	—	4286	—
722X	—	R503	—	—	—
722Y	—	R514	—	4286	—
722Z	—	R503	—	4286	—
723	—	R81	5284	—	—
723A	—	R500	—	—	—
723B	—	R500	—	—	—
723C	—	R500	—	—	—
724	—	R81	4265	—	—
724A	—	R503	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
724B	—	R503	—	—	—
724C	—	R503	—	—	—
724D	—	R503	—	—	—
724E	—	R503	—	—	—
724F	—	R503	—	—	—
724G	—	R503	—	—	—
724H	—	R503	—	—	—
724J	—	R503	—	—	—
724K	—	R503	—	—	—
724L	—	R503	—	—	—
724M	—	R503	—	—	—
724N	—	R503	—	—	—
724P	—	R503	—	—	—
724Q	—	R503	—	—	—
724R	—	R503	—	—	—
724S	—	R503	—	—	—
724T	—	R503	—	—	—
724U	—	R503	—	—	—
724V	—	R503	—	—	—
724W	—	R503	—	—	—
724X	—	R503	—	—	—
724Y	—	R514	—	4286	—
724Z	—	R503	—	—	—
725	—	R81	—	5284	—
725A	—	R500	—	4200	—
725B	—	R500	—	4200	—
725C	—	R500	—	4200	—
725D	—	R500	—	4200	—
725E	—	R500	—	4200	—
725F	—	R500	—	4200	—
725G	—	R500	—	4200	—
725H	—	R500	—	4200	—
725I	—	R500	—	4200	—
725J	—	R500	—	4200	—
725K	—	R500	—	4200	—
725L	—	R500	—	4200	—
725M	ST11	R500	—	—	—
725N	ST11	R500	—	4265	—
725P	—	—	—	4200	—
725Q	ST11	R500	—	4265	—
725R	ST11	R500	—	4265	—
725S	ST11	R500	—	4200	—
725T	ST11	R500	—	4265	—
725U	ST11	—	—	4265	—
725V	—	R500	—	4265	—
725W	—	R500	—	4200	—
725X	—	R500	—	4265	—
725Y	ST11	R500	—	4265	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
725Z	—	R500	—	4265	—
726	—	R81	—	—	—
726A	—	R500	—	—	—
726B	—	R500	—	4200	—
726C	—	R500	—	4200	—
726E	—	R500	—	4200	—
726F	ST11	R500	—	4200	—
726G	ST11	R500	—	4200	—
726H	ST11	R500	—	—	—
726J	ST11	R500	—	—	—
726K	ST11	R500	—	—	—
727	—	R81	—	—	—
727A	—	R500	—	—	—
727B	—	R500	—	4265	—
727C	—	R500	—	4200	—
727D	—	—	—	4200	—
727E	—	R500	—	4200	—
727F	—	R500	—	4200	—
727G	—	R500	—	4265	—
727H	—	R500	—	4265	—
727J	—	R500	—	4265	—
727K	—	R500	—	4200	—
727L	—	R500	—	4265	—
727M	ST11	R500	—	4265	—
727N	—	R500	—	4265	—
727P	—	R500	—	4200	—
727R	—	R500	—	4265	—
727S	—	R500	—	4265	—
727T	ST11	R500	—	4265	—
727U	—	R500	—	4286	—
727V	—	R500	—	4200	—
727W	—	R500	—	4200	—
727X	—	—	—	4286	—
727Y	ST11	R500	—	4265	—
727Z	ST11	R500	—	4265	—
728	—	R81	—	—	—
728A	—	R503	—	—	—
728B	—	R503	—	—	—
728C	—	R503	—	—	—
728CV	—	R514	—	—	—
728D	—	R503	—	—	—
728E	—	R514	—	—	—
728F	—	R514	—	—	—
728H	—	R514	—	4265	—
728K	ST11	R503	—	4265	—
728L	—	R503	—	4265	—
728M	—	R503	—	4265	—
728N	—	R503	—	4265	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
728P	ST11	R503	—	4265	—
728R	—	R503	—	4265	—
728S	—	R503	—	4265	—
728T	—	R503	—	4265	—
728U	—	R503	—	4265	—
728V	—	R503	—	4265	—
728W	—	R503	—	4265	—
728X	—	R503	—	—	—
729	—	R81	—	4286	—
729B	—	R500	—	4200	—
729C	—	R500	—	4200	—
729D	—	R514	—	—	—
729E	ST11	R500	—	4265	—
729F	—	R500	—	4200	—
729G	—	R500	—	4200	—
729H	ST63	R500	—	4200	—
729J	ST11	R500	—	4265	—
729K	—	R514	—	—	—
729L	—	R500	4310	4286	—
730	—	R81	5284	4286	—
730A	—	—	4310	—	—
731	—	R81	4265	—	—
733	—	R81	5284	4286	—
734	—	R81	—	—	—
734A	ST11	R500	—	—	—
734B	ST11	R500	—	4265	—
734D	—	R500	—	4200	—
734E	ST11	R500	—	4265	—
734F	ST11	R500	—	4265	—
734G	ST85	R500	—	4200	—
734H	ST11	R500	—	4265	—
734I	ST11	R503	—	4265	—
734J	ST85	R500	—	4200	—
734K	ST11	R500	—	4265	—
734L	—	R500	—	4265	—
734N	ST11	R500	—	4265	—
734P	ST11	R500	—	4265	—
734R	—	R500	—	4265	—
734S	—	R500	—	4200	—
734T	—	R500	—	—	—
734U	—	R500	—	4265	—
734V	ST85	R500	—	4200	—
734W	ST85	R500	—	4200	—
734X	—	R500	—	—	—
734Y	ST85	R500	—	4200	—
734Z	—	R500	—	4265	—
735	—	R81	5284	—	—
735B	—	R500	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
735C	—	R500	—	—	—
736	—	R81	5284	4286	—
736B	—	R503	—	—	—
736C	ST500	R503	—	—	—
736D	—	R503	—	—	—
736E	—	R503	—	—	—
736F	—	R514	—	—	—
736G	—	R503	—	—	—
736H	—	R503	—	—	—
736J	—	R503	—	—	—
736K	—	R503	—	—	—
736L	—	R503	—	—	—
736M	—	R503	—	—	—
736N	—	R514	—	4286	—
736P	—	R514	—	—	—
736R	—	R503	—	4265	—
736S	—	R503	—	4265	—
736T	—	R514	—	—	—
736U	—	R514	—	—	—
736V	—	R503	—	—	—
736Y	—	R503	—	—	—
736Z	—	R514	—	—	—
737	—	R81	5284	—	—
737A	—	R514	—	—	—
737B	—	R503	—	—	—
737C	—	R503	—	—	—
737D	—	R503	—	—	—
737E	—	R503	—	—	—
737F	—	R514	—	—	—
737G	ST500	R503	—	—	—
737H	—	R514	—	—	—
737J	—	R503	—	—	—
737K	—	R503	—	—	—
737L	—	R503	—	—	—
737M	—	R503	—	—	—
737N	—	R503	—	—	—
737P	—	R514	—	—	—
737R	—	R503	—	—	—
737T	—	R503	—	—	—
737U	—	R514	—	—	—
737V	—	R503	—	—	—
737W	—	R514	—	—	—
737X	—	R503	—	—	—
737Y	—	R503	—	—	—
737Z	—	R503	—	—	—
738	—	R81	5284	—	—
738A	—	R503	—	4265	—
738B	—	R503	—	4265	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
738C	ST11	R503	—	4265	—
738D	ST11	R503	—	4265	—
738E	ST11	R503	—	4265	—
738G	—	R503	—	—	—
738H	—	R503	—	—	—
738J	ST11	R503	—	4265	—
738K	—	R503	—	—	—
738L	—	R503	—	—	—
738M	—	R503	—	—	—
738N	—	R503	—	—	—
738P	—	R500	—	4200	—
738Q	—	R500	—	4200	—
738R	—	R503	—	—	—
738S	ST11	R503	—	4265	—
738T	ST11	R503	—	4265	—
738U	—	R503	—	—	—
738V	ST11	R503	—	4265	—
738W	—	R514	—	—	—
738X	—	R503	—	4265	—
738Y	—	R503	—	—	—
738Z	—	R503	—	—	—
739	—	R81	5284	—	—
739A	—	R503	—	—	—
739B	—	R503	—	—	—
739C	—	R503	—	—	—
739D	—	R503	—	—	—
739E	—	R503	—	—	—
739F	—	R503	—	—	—
739G	ST11	R503	—	4265	—
739H	—	R503	—	—	—
739J	—	R503	—	—	—
739K	—	R503	—	—	—
739L	—	R503	—	4265	—
740	—	R81	5284	—	—
740A	—	R503	—	—	—
740B	—	R500	—	—	—
740C	—	R503	—	—	—
740D	—	R500	—	—	—
740E	—	R503	—	—	—
740F	—	R503	—	—	—
740G	—	R503	—	—	—
740H	—	R514	—	—	—
740J	—	R514	—	—	—
740K	—	R503	—	—	—
740L	—	R514	—	—	—
740M	—	R503	—	—	—
740N	—	R514	—	—	—
740P	—	R503	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
741	—	R81	5284	—	—
742	—	R81	5284	—	—
743	—	R81	5284	—	—
743A	—	—	4310	4286	—
744	—	R81	4265	—	—
745	—	R81	—	4286	—
746	—	R81	—	4286	—
747	—	R81	—	—	—
750	—	R81	—	4286	—
751	—	R81	5284	—	—
752	—	R81	5284	—	—
753	—	R81	—	4286	—
754	—	R81	5284	4286	—
755	—	R81	—	4286	—
756	—	R81	—	—	—
757	—	R81	—	4286	—
758	—	R81	4265	—	—
759	—	R81	—	4286	—
760	—	R81	—	—	—
761	—	R81	5284	4286	—
762	—	R81	5284	—	—
763	—	R81	5284	—	—
764	—	R81	4265	—	—
765	—	R81	—	4286	—
766	—	R81	5284	—	—
767	—	R81	5284	4286	—
768	—	R81	5284	—	—
769	—	R81	—	—	—
770	—	R81	4265	—	—
771	—	R81	4265	—	—
772	—	R81	5284	—	—
773	—	R81	5284	4286	—
774	—	R81	4265	4286	—
776	—	R81	—	4286	—
777	—	R81	5284	—	—
778	—	R81	—	4286	—
779	ST500	R81	4265	—	—
780	—	R81	5284	4286	—
781	—	R81	4265	—	—
782	—	R81	—	—	—
783	—	R81	4265	4200	—
784	—	R81	—	4286	—
785	—	R81	—	—	—
786	—	R81	5284	—	—
787	—	R81	—	4286	—
788	—	R81	4265	—	—
789	—	R81	4265	—	—
790	ST51	R81	4265	4286	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
791	—	R81	5284	—	—
793	—	R81	—	4286	—
794	—	R81	—	4286	—
795	—	R81	—	4286	—
796	—	R81	5284	—	—
798	—	R81	—	—	—
799	—	R81	5284	—	—
802	—	R81	—	—	—
803	—	R81	—	—	—
804	—	R81	—	—	—
805	—	R81	—	—	—
806	—	R81	—	—	—
807	—	R81	—	—	—
808	—	R81	—	—	—
809	—	R81	—	—	—
810	—	R81	—	—	—
813	—	R81	—	—	—
814	—	R81	—	—	—
815	—	R81	—	—	—
816	—	R81	—	—	—
817	—	R81	—	—	—
818	—	R81	—	—	—
819	—	R81	—	—	—
820	—	R81	—	—	—
821	—	R81	—	—	—
822	—	R81	—	—	—
823	—	R81	—	—	—
824	—	R81	—	—	—
825	—	R81	—	—	—
826	—	R81	—	—	—
827	—	R81	—	—	—
828	—	R81	—	—	—
829	—	R81	—	—	—
830	—	R81	—	—	—
831	—	R81	—	—	—
832	—	R81	—	—	—
833	—	R81	—	—	—
834	—	R81	—	—	—
835	—	R81	—	—	—
836	—	R81	—	—	—
838	—	R81	—	—	—
845	—	R81	—	—	—
847	—	R81	—	—	—
850	—	R81	—	—	—
852	—	R81	—	—	—
854	—	R81	—	—	—
855	—	R81	—	—	—
856	—	R81	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
857	—	R81	—	—	—
858	—	R81	—	—	—
859	—	R81	—	—	—
860	—	R81	—	—	—
861	—	R81	—	—	—
863	—	R81	—	—	—
866	—	R81	—	—	—
868	—	R81	—	—	—
870	—	R81	—	—	—
876	—	R81	—	—	—
880	—	R81	—	—	—
882	—	R81	—	—	—
883	—	R81	—	—	—
884	—	R81	—	—	—
886	—	R81	—	—	—
887	—	R81	—	—	—
888	—	R81	—	—	—
889	—	R81	—	—	—
890	—	R81	—	—	—
891	—	R81	—	—	—
892	—	R81	—	—	—
894	—	R81	—	—	—
1103862	ST124	R503	—	—	—
1104657	ST132	—	4286	—	STK21 ³⁰
1104657	ST132	—	4286	—	STK32 ³¹
1104851	—	R503	—	4286	—
1107001	ST11	R503	—	4265	—
1107002	—	R503	—	—	—
1107003	ST11	R503	—	4265	—
1107004	—	R514	—	—	—
1107005	—	R503	—	4265	—
1107006	—	R503	—	—	—
1107007	ST11	R503	—	4265	—
1107008	ST11	R503	—	4265	—
1107009	ST11	R503	—	4265	—
1107010	ST52	R503	—	—	—
1107012	—	R503	—	—	—
1107013	—	R503	—	4265	—
1107014	—	R503	—	—	—
1107015	—	R503	—	—	—
1107016	—	R503	—	—	—
1107017	—	R503	—	—	—
1107018	—	R503	—	4265	—
1107019	—	R503	—	4265	—
1107021	ST500	R503	—	—	—
1107022	ST11	R503	—	4265	—
1107023	ST11	R503	—	4265	—
1107024	ST11	R503	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107025	ST11	R503	—	—	—
1107026	ST11	R514	—	—	—
1107027	ST11	R503	—	—	—
1107028	ST11	R503	—	—	—
1107029	ST11	R503	—	—	—
1107030	ST63	R503	—	—	—
1107031	—	R503	—	4286	—
1107032	ST11	R503	—	4265	—
1107033	ST11	R503	—	4265	—
1107034	ST11	R503	—	4265	—
1107035	—	R503	—	—	—
1107036	ST500	R503	—	—	—
1107037	—	R503	—	—	—
1107038	—	R503	—	4265	—
1107039	ST11	R503	—	4265	—
1107040	—	R503	—	—	—
1107041	ST11	R503	—	4265	—
1107042	—	R503	—	—	—
1107043	—	R503	—	—	—
1107044	—	R503	—	—	—
1107045	—	R503	—	—	—
1107046	—	R503	—	—	—
1107047	ST11	R503	—	4265	—
1107048	—	R503	—	4286	—
1107049	—	R503	—	4265	—
1107050	—	R503	—	4265	—
1107051	—	R503	—	—	—
1107052	—	R503	—	—	—
1107053	—	R503	—	4265	—
1107054	ST11	R503	—	4265	—
1107055	ST11	R503	—	4265	—
1107056	—	R503	—	—	—
1107057	—	R503	—	4265	—
1107058	ST500	R503	—	—	—
1107059	—	R503	—	—	—
1107060	ST500	R503	—	—	—
1107061	ST11	R503	—	4265	—
1107063	—	R503	—	4265	—
1107064	ST500	R503	—	—	—
1107065	—	R503	—	—	—
1107066	ST11	R503	—	4265	—
1107067	ST500	R503	—	—	—
1107070	ST11	R503	—	4265	—
1107071	ST11	R503	—	4310	—
1107073	ST63	R503	—	—	—
1107074	ST63	R503	—	—	—
1107075	ST110	R503	—	4265	STK5
1107076	—	R503	—	4265	—

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107077	ST63	R503	—	—	—
1107078	—	R503	—	4265	—
1107079	ST110	R503	—	4265	STK5
1107080	ST110	R503	—	4265	STK5
1107081	—	R503	—	—	—
1107082	ST11	R503	—	4265	—
1107084	—	R503	—	—	—
1107086	ST52	R503	—	4286	—
1107087	—	R503	—	—	—
1107088	—	R503	—	—	—
1107089	—	R503	—	—	—
1107090	ST58	R503	—	4286	—
1107091	ST63	R503	—	—	—
1107092	ST63	R503	—	—	—
1107093	ST500	R503	—	—	—
1107094	ST63	R503	—	—	—
1107095	—	R503	—	—	—
1107096	ST500	R503	—	—	—
1107097	ST110	R503	—	4265	STK5
1107098	ST110	R503	—	4265	STK5
1107101	ST110	R503	—	4265	STK5
1107102	ST110	R503	—	4265	STK5
1107103	ST11	R503	—	4265	—
1107105	ST63	R503	—	—	—
1107107	ST110	R503	—	4265	STK5
1107108	ST11	R503	—	4265	—
1107109	ST110	R503	—	4265	STK5
1107110	ST110	R503	—	4265	STK5
1107114	ST110	R503	—	4265	STK5
1107115	—	R503	—	—	—
1107116	—	R503	—	—	—
1107117	ST110	R503	4310	5289	—
1107119	—	R503	—	—	—
1107120	ST63	R503	—	—	—
1107121	ST63	R503	—	—	—
1107125	—	R503	—	—	—
1107126	—	R503	—	—	—
1107127	ST500	R503	—	—	—
1107131	ST110	R503	—	4265	STK5
1107132	ST63	R503	—	—	—
1107133	—	R503	—	—	—
1107134	ST63	R503	—	—	—
1107135	ST110	R503	—	4265	STK5
1107136	ST63	R503	—	—	—
1107138	ST63	R503	—	—	—
1107139	—	R503	—	—	—
1107140	ST110	R503	—	4265	STK5
1107144	ST110	R503	—	4265	STK5

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107146	ST110	R503	—	4286	—
1107147	ST500	R503	—	—	—
1107148	ST63	R503	—	—	—
1107149	—	R503	—	—	—
1107150	ST33	R503	—	4265	—
1107154	ST63	R503	—	—	—
1107155	ST63	R503	—	—	—
1107156	ST110	R503	—	5288	STK5
1107157	—	R503	—	—	—
1107159	ST63	R503	—	—	—
1107162	ST63	R503	—	—	—
1107163	ST63	R503	—	—	—
1107165	ST500	R503	—	—	—
1107166	ST63	R503	—	—	—
1107168	ST110	R503	—	5288	STK5
1107169	ST63	R503	—	—	—
1107170	ST63	R503	—	—	—
1107173	ST63	R503	—	—	—
1107174	ST63	R503	—	—	—
1107175	ST63	R503	—	—	—
1107176	ST63	R503	—	—	—
1107177	—	R503	—	—	—
1107178	ST63	R503	—	—	—
1107179	—	R503	—	4265	—
1107180	—	R503	—	—	—
1107183	ST500	R503	—	—	—
1107184	—	R503	—	4286	—
1107185	—	R503	—	—	—
1107186	ST63	R503	—	—	—
1107187	ST11	R503	—	4265	—
1107188	ST33	R503	—	4265	—
1107189	—	R503	—	—	—
1107190	ST63	R503	—	—	—
1107191	ST63	R503	—	—	—
1107192	ST63	R503	—	—	—
1107193	ST11	R503	—	—	—
1107194	—	R503	—	—	—
1107195	ST63	R503	—	—	—
1107196	ST63	R503	—	—	—
1107197	ST63	R503	—	—	—
1107198	—	R503	—	—	—
1107199	ST63	R503	—	4286	—
1107200	ST500	R503	—	—	—
1107201	ST124	R503	—	5288	STK27
1107202	—	R503	—	—	—
1107203	ST124	R503	—	4265	STK27
1107204	ST124	R503	—	4265	STK27
1107205	ST124	R503	—	4265	STK27

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107206	ST124	R503	—	—	STK27
1107208	ST124	R503	—	5288	STK27
1107209	ST124	R503	—	4265	STK27
1107213	ST124	R503	—	—	STK15
1107214	ST124	R503	—	4265	STK27
1107215	ST124	R503	—	4265	STK27
1107217	ST51	R503	—	—	—
1107218	ST11	R503	—	5289	—
1107221	ST124	R503	—	5288	STK27
1107222	ST124	R503	—	5288	STK27
1107223	ST124	R503	—	5288	STK27
1107224	—	R503	—	4265	—
1107225	—	R503	—	4483	—
1107226	—	R503	—	—	—
1107227	ST51	R503	—	—	—
1107228	ST124	R503	—	4265	STK27
1107229	ST124	R503	—	4265	STK27
1107230	ST124	R503	—	5288	STK27
1107231	ST51	R503	—	—	—
1107233	ST124	R503	—	5336	STK27
1107234	ST124	R505	—	4265	STK27
1107235	—	R503	—	—	—
1107237	ST124	R503	—	5288	STK27
1107238	ST53	R503	—	—	—
1107239	ST53	R503	—	—	—
1107242	ST124	R503	—	5288	STK27
1107245	ST124	R503	—	4265	STK27
1107246	ST53	R503	—	—	—
1107247	ST124	R503	—	5288	STK27
1107248	ST124	R503	—	5288	STK27
1107249	ST124	R505	—	—	STK27
1107250	ST124	R503	—	5288	STK27
1107251	ST124	R503	—	4265	STK27
1107252	ST100	R505	—	4286	STK2
1107253	ST53	R503	—	—	—
1107254	—	R505	—	—	—
1107255	—	R505	—	—	—
1107256	—	R505	—	—	—
1107257	—	R503	—	4286	—
1107258	—	R503	—	—	—
1107259	ST124	R503	—	5288	STK27
1107260	ST124	R503	—	5288	STK27
1107261	—	R503	—	—	—
1107262	ST53	R503	—	—	—
1107263	—	R503	—	5288	—
1107265	ST53	R503	—	—	—
1107266	ST124	R503	—	5288	STK27
1107268	ST124	R503	—	—	STK27

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107270	ST124	R503	—	—	STK27
1107271	ST124	R503	—	—	STK27
1107272	ST124	R503	—	—	STK27
1107273	ST124	R503	—	—	STK27
1107274	ST124	R503	—	5336	STK27
1107275	ST124	R503	—	4265	STK27
1107276	—	R503	—	—	—
1107277	ST124	R503	—	—	STK27
1107279	ST124	R503	—	—	STK27
1107280	ST124	R503	—	—	STK27
1107282	ST124	R503	—	—	STK27
1107283	ST53	R505	—	—	—
1107284	ST124	R503	—	—	STK27
1107285	ST124	R503	—	—	STK27
1107286	ST124	R503	—	5336	STK27
1107289	ST124	R503	—	—	STK27
1107290	ST124	R503	—	5289	STK27
1107291	ST124	R503	—	4265	STK27
1107292	ST124	R503	—	4265	STK27
1107293	ST124	R503	—	—	STK27
1107294	ST124	R503	—	—	STK27
1107295	ST124	R503	—	4265	STK27
1107296	ST53	R503	—	—	—
1107297	ST124	R503	—	—	STK27
1107298	ST124	R503	—	—	STK27
1107299	ST124	R503	—	—	STK27
1107300	ST124	R503	—	4265	STK27
1107301	ST124	R503	—	5288	STK27
1107302	ST124	R503	—	5288	STK27
1107305	ST124	R503	4200	5288	—
1107306	ST124	R503	—	5288	STK27
1107307	ST124	R503	—	5288	STK27
1107308	ST124	R503	—	4265	STK27
1107309	ST100	R503	—	5288	STK2
1107310	ST124	R503	—	5288	STK27
1107311	ST124	R503	—	5288	STK27
1107312	ST124	R503	—	5336	STK27
1107313	ST124	R503	—	5288	STK27
1107314	ST124	R503	—	5336	STK27
1107315	ST124	R505	4310	—	STK27
1107316	ST124	R503	—	5288	STK27
1107317	ST124	R503	—	5288	STK27
1107320	ST124	R503	—	5288	STK27
1107321	ST124	R503	—	5336	STK27
1107322	—	R503	—	—	—
1107326	ST124	R503	—	4265	STK27
1107327	—	R503	—	—	—
1107328	—	R503	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit	Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107329	ST124	R503	—	5288	STK27	1107379	ST124	R503	4200	4265	STK15
1107330	ST124	R503	—	5288	STK27	1107380	ST124	R503	4200	5288	STK15
1107331	ST124	R503	—	5336	STK27	1107381	ST124	R503	4200	5288	STK15
1107332	ST124	R503	—	4265	STK27	1107382	ST124	R503	4200	4265	STK15
1107333	ST124	R503	—	5288	STK27	1107383	ST124	R503	4310	5288	STK15
1107334	ST124	R503	—	—	STK27	1107385	ST124	R503	4200	5288	STK15
1107335	ST124	R505	—	4265	STK27	1107386	ST124	R503	4200	—	STK15
1107336	ST124	R505	4310	—	STK27	1107387	ST124	R503	4200	5288	STK15
1107337	ST124	R503	—	5288	STK27	1107388	ST124	R503	4200	5288	STK15
1107338	—	R505	4200	4200	—	1107389	ST124	R503	4200	5288	STK15
1107339	ST124	R503	—	4265	STK27	1107390	ST124	R503	4200	—	STK15
1107340	ST124	R503	—	5288	STK27	1107391	ST124	R503	4200	5288	STK15
1107341	ST124	R503	—	4265	STK27	1107392	ST124	R503	4200	5288	STK15
1107342	ST124	R503	—	5336	STK27	1107393	ST124	R503	4200	4265	STK15
1107343	ST124	R503	—	4265	STK27	1107394	ST124	R503	4200	5288	STK15
1107344	ST124	R503	—	—	STK27	1107396	ST124	R503	4200	5288	STK15
1107345	ST124	R503	—	5288	STK27	1107397	ST124	R503	4200	5288	STK15
1107346	ST124	R503	—	5288	STK27	1107398	ST124	R503	4200	5288	STK15
1107347	ST124	R503	—	5288	STK27	1107399	ST124	R503	4200	5288	STK15
1107348	ST124	R503	—	5288	STK27	1107400	ST124	R503	4200	5288	STK15
1107349	ST124	R503	—	5288	STK27	1107401	—	R503	—	—	—
1107350	ST124	R503	—	—	STK27	1107402	—	R503	—	—	—
1107352	ST124	R503	—	5288	STK27	1107403	—	R503	—	—	—
1107353	ST124	R505	—	5288	STK27	1107404	ST500	R503	—	—	—
1107354	ST124	R503	—	5288	STK27	1107405	—	R503	—	—	—
1107355	ST124	R503	—	5288	STK27	1107406	—	R503	—	—	—
1107356	ST124	R505	—	—	STK27	1107407	ST500	R503	—	—	—
1107358	—	R503	—	—	—	1107408	ST500	R503	—	—	—
1107359	ST124	R505	—	—	STK27	1107409	—	R503	—	—	—
1107360	ST124	R503	—	5288	STK27	1107410	—	R503	—	—	—
1107361	ST124	R503	—	5288	STK27	1107411	—	R503	—	—	—
1107362	ST124	R503	—	—	STK27	1107412	ST500	R503	—	—	—
1107363	ST124	R503	—	5288	STK27	1107413	—	R503	—	—	—
1107364	ST124	R503	—	—	STK27	1107414	ST58	R503	—	—	—
1107365	ST124	R503	—	5336	STK27	1107416	ST58	R503	—	—	—
1107366	—	R503	—	—	—	1107417	ST58	R503	—	—	—
1107367	ST124	R503	—	5288	STK27	1107418	ST11	R503	—	—	—
1107368	ST124	R503	—	5336	STK27	1107419	—	R503	—	—	—
1107369	ST124	R503	—	—	STK27	1107420	ST11	R503	—	—	—
1107370	ST124	R505	—	—	STK27	1107421	—	R503	—	—	—
1107371	ST124	R505	—	—	STK27	1107422	ST63	R503	—	4286	—
1107372	ST124	R505	—	5336	STK27	1107423	—	R503	—	—	—
1107373	ST124	R503	—	5288	STK27	1107424	ST63	R503	—	—	—
1107374	ST124	R503	—	5288	STK27	1107425	—	R503	—	—	—
1107375	ST124	R503	—	5288	STK27	1107426	—	R503	—	—	—
1107376	ST124	R505	—	—	STK27	1107427	—	R503	—	—	—
1107377	ST124	R503	—	—	STK27	1107428	ST63	R503	—	—	—
1107378	ST124	R503	—	—	STK27	1107429	ST63	R503	—	—	—

(continued on next column)

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107430	—	R503	—	—	—
1107431	ST63	R503	—	—	—
1107432	ST63	R503	—	—	—
1107433	ST63	R503	—	—	—
1107434	—	R503	—	4286	—
1107435	ST500	R503	—	—	—
1107436	—	R503	—	—	—
1107437	—	R503	—	4286	—
1107438	ST63	R503	—	—	—
1107439	ST63	R503	—	—	—
1107440	ST63	R503	—	—	—
1107441	—	R503	—	—	—
1107442	—	R503	—	—	—
1107443	—	R503	—	4286	—
1107444	—	R503	—	—	—
1107445	ST500	R503	—	—	—
1107446	—	R503	—	—	—
1107447	ST63	R503	—	—	—
1107448	—	R503	—	—	—
1107449	—	R503	—	—	—
1107450	—	R503	—	—	—
1107452	—	R503	—	—	—
1107453	ST11	R503	—	—	—
1107454	—	R503	—	4286	—
1107455	—	R503	—	—	—
1107456	ST6	R503	—	—	—
1107458	ST63	R503	—	4286	—
1107459	—	R503	—	4286	—
1107462	ST63	R503	—	—	—
1107466	ST63	R503	—	—	—
1107467	ST63	R503	—	—	—
1107468	—	R503	—	4286	—
1107469	—	R503	—	—	—
1107470	ST63	R503	—	—	—
1107471	—	R503	—	4286	—
1107472	ST63	R503	—	—	—
1107473	ST63	R503	—	—	—
1107474	ST63	R503	—	—	—
1107475	ST63	R503	—	—	—
1107476	—	R503	—	—	—
1107477	—	R503	4310	4286	—
1107478	ST63	R503	—	—	—
1107479	—	R503	—	—	—
1107480	—	R503	—	4286	—
1107481	ST63	R503	—	—	—
1107482	ST500	R503	—	—	—
1107483	—	R503	—	—	—
1107484	—	R503	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107485	—	R503	—	—	—
1107486	—	R503	—	—	—
1107487	—	R503	—	—	—
1107488	ST63	R503	—	—	—
1107489	—	R503	—	—	—
1107490	ST63	R503	—	4265	—
1107491	ST63	R503	—	—	—
1107493	ST63	R503	—	—	—
1107494	ST63	R503	—	—	—
1107495	ST63	R503	—	—	—
1107496	ST124	R503	—	5288	STK27
1107497	ST124	R503	—	5336	STK27
1107498	—	R505	—	—	—
1107499	ST124	R503	—	5288	STK27
1107501	ST124	R514	4310	5289	STK15
1107502	ST51	R514	4310	4310	—
1107503	ST124	R514	4310	5289	STK15
1107504	ST124	R514	4310	5289	STK15
1107506	—	R504	—	4310	—
1107507	—	R514	4310	5289	—
1107508	—	R504	—	4286	—
1107509	—	R514	—	—	—
1107510	ST124	R504	—	4310	STK27
1107511	ST100	R504	—	5289	STK2
1107512	ST124	R504	—	4310	STK27
1107513	—	R504	—	4286	—
1107514	—	R514	—	5289	—
1107515	—	R522	—	5289	—
1107516	ST124	R504	—	4310	STK27
1107517	—	R504	—	—	—
1107518	ST100	R504	—	5289	STK2
1107519	ST51	R504	—	—	—
1107520	ST51	R504	—	—	—
1107521	—	R504	—	—	—
1107522	ST124	R504	—	4310	STK27
1107523	ST124	R504	—	4310	STK27
1107524	ST124	R504	—	4310	STK27
1107525	—	R504	—	—	—
1107526	—	R504	—	—	—
1107527	—	R504	—	5289	—
1107528	—	R504	—	4286	—
1107529	ST51	R504	—	—	—
1107531	—	R504	—	4286	—
1107532	ST100	R504	—	5289	STK2
1107533	ST124	R504	—	4310	STK27
1107534	—	R504	—	5289	—
1107535	ST100	R504	—	5289	STK2
1107536	ST51	R504	—	4286	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit	Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107537	ST11	R504	—	4286	—	1107590	—	R504	—	4310	—
1107538	ST100	R504	—	5289	STK2	1107591	ST124	R504	—	4310	STK27
1107539	ST124	R504	—	4310	STK27	1107592	ST124	R504	—	—	STK27
1107540	ST124	R504	—	4310	STK27	1107593	ST124	R504	—	4310	STK27
1107541	ST51	R504	—	—	—	1107594	ST124	R503	—	5288	STK27
1107542	—	R504	—	4310	—	1107596	ST124	R503	—	5288	STK27
1107543	ST124	R504	—	4310	STK27	1107598	ST124	R504	—	4310	STK27
1107544	ST124	R504	—	4310	STK27	1107599	ST124	R504	—	4310	STK27
1107545	ST100	R504	—	5289	STK2	1107600	ST124	R504	—	4310	STK27
1107546	ST124	R504	—	4310	STK27	1107601	—	R514	—	5288	STK5
1107547	ST124	R522	—	4310	STK27	1107602	—	R514	—	—	STK5
1107548	ST51	R504	—	—	—	1107603	—	R514	—	4265	—
1107549	ST124	R504	—	4310	STK27	1107605	ST51	R514	—	—	—
1107550	ST124	R504	—	4310	STK27	1107607	—	R514	—	4265	—
1107551	ST124	R504	—	4310	STK27	1107608	—	R503	4200	5288	—
1107553	—	R522	—	5289	—	1107609	ST100	R503	—	—	STK2
1107554	—	R504	—	—	—	1107610	ST100	R503	—	—	STK2
1107555	—	R522	—	4310	—	1107611	—	R503	—	—	—
1107556	ST124	R504	—	4310	STK27	1107612	—	R503	—	—	—
1107557	ST124	R504	—	4310	STK27	1107613	ST124	R503	—	—	STK27
1107558	ST124	R514	—	4310	STK27	1107615	ST11	R505	—	—	—
1107559	—	R514	—	4310	—	1107619	ST100	R503	—	—	STK2
1107561	ST124	R504	—	4310	STK27	1107620	ST100	R503	—	—	STK2
1107562	—	R504	—	—	—	1107621	ST100	R503	—	—	STK2
1107564	ST124	R504	—	4310	STK27	1107622	ST100	R503	—	—	STK2
1107565	ST51	R504	—	4310	—	1107623	ST100	R503	—	—	STK2
1107567	—	R504	—	4310	—	1107626	ST100	R503	—	—	STK2
1107568	—	R504	—	5289	—	1107627	ST100	R503	—	—	STK2
1107569	ST51	R504	—	4310	—	1107629	—	R503	—	—	—
1107570	—	R504	—	4286	—	1107630	—	R503	—	—	—
1107571	ST124	R504	—	4310	STK27	1107631	ST100	R503	—	—	STK2
1107572	—	R504	—	4310	—	1107632	ST100	R503	—	—	STK2
1107573	ST124	R504	—	4310	STK27	1107633	ST100	R503	—	—	STK2
1107574	ST124	R504	—	4310	STK27	1107634	ST33	R503	—	—	—
1107575	ST124	R504	—	4310	STK27	1107635	ST100	R503	—	—	STK2
1107576	ST124	R504	—	4310	STK27	1107638	ST100	R503	—	—	STK2
1107577	ST124	R504	—	4310	STK27	1107639	ST100	R503	—	5288	STK2
1107578	ST124	R504	—	4310	STK27	1107640	ST100	R503	—	—	STK2
1107580	ST124	R504	—	4310	STK27	1107641	ST124	R503	—	—	STK27
1107581	ST124	R504	—	4310	STK27	1107642	ST100	R503	—	—	STK2
1107582	ST124	R504	—	—	STK27	1107643	ST100	R503	—	—	STK2
1107583	ST124	R504	—	—	STK27	1107644	ST100	R503	—	—	STK2
1107584	ST124	R504	—	4310	STK27	1107645	ST100	R503	—	—	STK2
1107585	ST124	R504	—	4310	STK27	1107646	ST100	R503	—	—	STK2
1107586	ST124	R504	—	4310	STK27	1107647	ST100	R503	—	—	STK2
1107587	ST124	R504	—	4310	STK27	1107648	ST100	R503	—	—	STK2
1107588	ST124	R504	—	4310	STK27	1107649	ST100	R503	—	—	STK2
1107589	ST124	R504	—	4310	STK27	1107650	—	R503	—	—	—

(continued on next column)

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107651	—	R503	—	—	—
1107652	ST124	R503	—	—	STK27
1107653	ST124	R503	—	—	STK27
1107654	—	R503	—	—	—
1107655	ST124	R503	—	—	STK27
1107656	ST100	R503	—	—	STK2
1107657	ST124	R503	—	—	STK27
1107658	ST51	R503	—	—	—
1107659	ST51	R503	—	—	—
1107660	ST124	R503	—	—	STK27
1107661	ST124	R503	—	—	STK27
1107663	ST51	R503	—	—	—
1107664	ST124	R503	—	5288	STK27
1107665	ST124	R503	—	—	STK27
1107666	—	R503	—	5288	—
1107667	ST124	R503	—	—	STK27
1107668	ST124	R503	—	—	STK27
1107670	ST100	R503	4310	5288	STK2
1107671	—	R503	—	5288	—
1107672	ST100	R503	—	—	STK2
1107673	ST100	R503	—	—	STK2
1107674	ST100	R503	—	5288	STK2
1107675	ST100	R503	—	—	STK2
1107676	ST100	R503	4200	5288	STK2
1107677	ST100	R503	—	5288	STK2
1107678	ST124	R503	—	—	STK27
1107679	ST124	R503	—	5288	STK27
1107680	ST124	R503	—	4265	STK27
1107681	ST124	R503	—	5288	STK27
1107682	—	R503	—	—	—
1107683	ST124	R503	—	—	STK27
1107684	ST100	R503	—	—	STK2
1107685	ST51	R503	—	—	—
1107686	ST124	R503	—	—	STK27
1107687	ST124	R503	—	—	STK27
1107688	ST100	R503	—	—	STK2
1107689	ST124	R503	—	—	STK27
1107694	ST124	R503	—	—	STK27
1107695	—	R505	—	—	—
1107696	ST124	R503	—	5336	STK27
1107697	ST124	R503	—	—	STK27
1107698	ST51	R503	—	—	—
1107699	—	R503	—	—	—
1107700	ST124	R503	—	—	STK27
1107701	ST51	R503	—	—	—
1107702	ST51	R503	—	—	—
1107703	ST51	R503	—	—	—
1107704	ST124	R503	—	—	STK27

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107705	—	R505	—	—	—
1107706	ST124	R503	—	—	STK27
1107707	ST124	R503	—	—	STK27
1107708	—	R503	—	—	—
1107709	ST124	R503	—	—	STK27
1107710	ST124	R503	—	—	STK27
1107711	ST124	R503	—	5288	STK27
1107712	ST124	R503	—	5288	STK27
1107713	ST51	R503	—	—	—
1107714	ST100	R503	—	—	STK2
1107716	ST124	R503	—	5288	STK27
1107717	ST124	R503	—	5288	STK27
1107718	ST100	R503	—	5288	STK2
1107719	ST124	R503	—	5336	STK27
1107720	ST124	R503	—	—	STK27
1107721	—	R503	—	4265	—
1107722	ST124	R503	—	5288	STK27
1107723	ST124	R503	—	5288	STK27
1107724	ST124	R503	—	5288	STK27
1107725	ST100	R503	—	4286	STK2
1107728	—	R503	—	4265	—
1107729	—	R503	—	—	—
1107731	ST124	R503	—	5288	STK27
1107732	—	R503	—	—	—
1107733	—	R503	—	—	—
1107734	ST124	R503	—	—	STK27
1107735	ST124	R503	—	5288	STK27
1107736	—	R503	—	—	—
1107737	—	R503	—	—	—
1107738	ST100	R503	—	4265	STK2
1107739	ST124	R503	—	—	STK27
1107740	—	R503	—	—	—
1107741	—	R503	—	—	—
1107742	ST124	R505	—	5288	STK27
1107743	ST51	R503	—	—	—
1107744	ST124	R503	—	—	STK27
1107745	—	R503	—	—	—
1107746	ST51	R503	—	—	—
1107747	—	R503	—	—	—
1107748	—	R503	—	—	—
1107749	—	R503	—	5288	—
1107750	—	R503	—	5288	—
1107751	ST124	R503	—	5288	STK27
1107752	ST124	R505	—	—	STK27
1107753	—	R503	—	—	—
1107754	ST124	R503	—	5288	STK27
1107755	—	R503	—	—	—
1107756	—	R503	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107757	—	R503	—	—	—
1107758	—	R503	—	—	—
1107760	ST124	R503	—	5289	STK27
1107761	—	R503	—	—	—
1107762	—	R503	—	—	—
1107763	ST124	R503	—	5288	STK27
1107764	ST100	R503	—	4265	STK2
1107765	ST124	R503	—	5288	STK27
1107766	ST124	R503	—	5288	STK27
1107767	—	R503	—	4286	—
1107769	ST124	R503	—	5288	STK27
1107770	—	R503	—	—	—
1107771	ST124	R503	—	5289	STK27
1107772	ST100	R503	—	—	STK2
1107773	ST124	R503	—	5288	STK27
1107774	—	R503	—	—	—
1107776	ST124	R503	—	5288	STK27
1107777	ST124	R503	—	5288	STK27
1107778	—	R505	—	4286	—
1107779	ST100	R503	—	5289	STK2
1107780	—	R503	—	—	—
1107781	ST124	R503	—	5288	STK27
1107782	ST124	R503	—	—	STK27
1107783	ST124	R503	—	5288	STK27
1107784	ST124	R503	—	5288	STK27
1107785	ST124	R503	5242	5289	STK27
1107787	—	R503	—	—	—
1107788	—	R503	—	—	—
1107789	ST124	R503	—	5288	STK27
1107790	ST124	R503	—	5288	STK27
1107791	ST124	R503	—	5288	STK27
1107794	—	R503	—	4286	—
1107796	ST124	R503	—	5288	STK27
1107798	—	R505	—	—	—
1107799	ST124	R503	—	5288	STK27
1107800	ST124	R503	—	5288	STK27
1107801	—	R514	—	4286	—
1107802	—	R514	—	—	—
1107803	ST82	R514	—	—	—
1107804	—	R514	—	4265	—
1107805	—	R514	—	—	—
1107806	ST82	R514	—	4286	—
1107807	—	R514	—	—	—
1107808	ST82	R514	—	—	—
1107809	ST82	R514	—	4286	—
1107810	ST11	R514	—	4286	—
1107811	—	R514	—	4286	—
1107812	—	R514	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107813	—	R514	—	4286	—
1107814	ST82	R514	—	—	—
1107815	ST53	R514	—	—	—
1107816	—	R514	—	—	—
1107817	—	R514	—	—	—
1107818	ST63	R514	—	—	—
1107819	ST63	R514	—	—	—
1107820	—	R514	—	—	—
1107821	—	R514	—	4286	—
1107822	—	R514	—	—	—
1107823	ST500	R514	—	—	—
1107824	—	R514	—	—	—
1107825	—	R514	—	—	—
1107826	ST53	R514	—	—	—
1107827	—	R514	—	—	—
1107828	ST53	R514	—	4286	—
1107829	ST11	R514	—	—	—
1107830	ST53	R514	—	4286	—
1107831	ST51	R514	4310	4286	—
1107832	—	R514	—	—	—
1107833	ST51	R514	4310	4286	—
1107834	—	R514	4310	4286	—
1107835	—	R514	4310	4286	—
1107836	—	R514	4310	4286	—
1107837	—	R514	—	—	—
1107838	ST6	R514	—	4286	—
1107839	—	R514	4310	4286	—
1107841	ST51	R514	4310	4286	—
1107842	—	R514	4310	4286	—
1107843	ST100	R514	—	4265	—
1107844	—	R514	4310	4286	—
1107845	—	R514	4310	4286	—
1107846	—	R514	4310	4286	—
1107847	ST51	R503	—	—	—
1107848	ST51	R503	—	—	—
1107849	—	R503	—	4286	—
1107850	ST51	R503	—	4286	—
1107851	—	R503	4200	4286	—
1107852	ST51	R503	—	4286	—
1107853	ST124	R504	—	—	STK27
1107854	ST124	R504	—	—	STK27
1107855	ST124	R504	—	—	STK27
1107857	ST124	R504	—	—	STK27
1107859	ST124	R504	—	—	STK27
1107860	ST124	R504	—	—	STK27
1107863	ST124	R504	—	—	STK27
1107866	ST124	R504	—	—	STK27
1107867	ST124	R504	—	—	STK27

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107868	ST124	R504	—	—	STK27
1107869	ST124	R522	—	—	STK27
1107870	ST124	R504	—	—	STK27
1107871	—	R504	—	—	—
1107872	ST124	R504	—	—	STK27
1107873	ST124	R504	—	—	STK27
1107874	ST124	R504	—	4265	STK27
1107875	ST124	R504	—	4265	STK27
1107876	ST124	R503	—	—	STK27
1107877	ST124	R503	—	—	STK27
1107878	ST51	R503	—	—	—
1107879	ST124	R503	—	4265	STK27
1107880	ST51	R503	—	—	—
1107881	—	R503	—	—	—
1107882	ST124	R503	—	—	STK27
1107883	ST124	R503	—	—	STK27
1107884	ST124	R503	—	5289	STK27
1107885	ST124	R503	—	4265	STK27
1107886	—	R503	—	—	—
1107887	ST51	R503	—	4286	—
1107888	ST124	R503	—	—	STK27
1107889	ST124	R503	—	—	STK27
1107890	ST124	R503	—	—	STK27
1107891	ST124	R503	—	—	STK27
1107892	ST124	R503	—	—	STK27
1107893	—	R503	—	5288	—
1107894	—	R503	—	4286	—
1107895	ST124	R503	—	—	STK27
1107897	—	R505	—	4286	—
1107898	ST124	R503	—	5289	STK27
1107899	—	R503	—	5288	—
1107900	—	R503	—	5288	—
1107902	—	R503	—	5289	—
1107903	—	R503	—	—	—
1107904	—	R503	—	—	—
1107905	—	R503	—	—	—
1107906	ST11	R503	—	—	—
1107907	—	R503	—	4265	—
1107908	—	R503	—	—	—
1107909	—	R503	—	—	—
1107910	—	R503	—	—	—
1107911	—	R503	—	—	—
1107912	—	R503	—	—	—
1107913	—	R503	—	—	—
1107914	ST11	R503	—	4265	—
1107915	ST11	R503	—	—	—
1107916	—	R503	—	—	—
1107917	—	R503	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107918	—	R503	—	—	—
1107919	—	R503	—	5289	—
1107920	—	R503	—	4286	—
1107921	ST11	R503	—	4265	—
1107922	—	R503	—	4265	—
1107923	—	R503	—	—	—
1107924	—	R503	—	4265	—
1107925	—	R503	—	—	—
1107926	—	R503	—	—	—
1107927	—	R503	—	4286	—
1107928	—	R503	—	4286	—
1107929	—	R503	—	—	—
1107930	—	R503	—	4265	—
1107931	—	R503	—	—	—
1107932	—	R503	4310	4286	—
1107933	—	R503	—	—	—
1107934	—	R503	—	4265	—
1107935	—	R503	—	—	—
1107936	—	R503	—	—	—
1107937	—	R503	—	4286	—
1107939	—	R503	—	—	—
1107941	ST11	R503	—	4265	—
1107942	ST11	R503	—	—	—
1107943	—	R503	—	—	—
1107944	—	R503	—	—	—
1107945	—	R503	—	—	—
1107947	ST11	R503	—	4265	—
1107948	ST110	R503	—	—	—
1107949	—	R503	—	—	—
1107950	—	R503	—	—	—
1107951	ST500	R503	—	—	—
1107952	—	R503	—	—	—
1107953	—	R503	—	4265	—
1107955	ST110	R503	—	4265	—
1107956	ST110	R503	—	4265	—
1107957	ST110	R503	—	4265	STK5
1107958	—	R503	4310	4286	—
1107959	ST63	R503	—	—	—
1107960	ST110	R503	—	4265	STK5
1107962	—	R503	—	—	—
1107963	ST63	R503	—	—	—
1107964	ST63	R503	—	—	—
1107965	ST110	R503	—	4265	—
1107967	ST63	R503	—	—	—
1107969	ST110	R503	—	4265	STK5
1107970	ST63	R503	—	—	—
1107971	—	R503	4310	4286	—
1107972	ST63	R503	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1107973	ST110	R503	—	—	—
1107974	ST63	R503	4310	4286	—
1107976	ST63	R503	—	—	—
1107977	ST63	R503	—	—	—
1107981	ST110	R503	—	—	STK5
1107982	—	R503	—	4265	—
1107990	ST63	R503	—	—	—
1107994	ST110	R503	—	4265	STK5
1107996	ST63	R503	—	—	—
1107997	—	R503	—	4265	—
1107999	ST63	R503	—	—	—
1108001	ST110	R503	—	—	STK5
1108003	ST11	R503	—	—	—
1108006	ST63	R503	4310	4286	—
1108007	ST110	R503	—	4265	—
1108008	ST63	R503	—	—	—
1108009	ST63	R503	—	—	—
1108010	ST63	R503	—	—	—
1108012	ST500	R503	—	—	—
1108014	ST63	R503	—	—	—
1108016	ST500	R503	—	—	—
1108021	ST63	R503	—	—	—
1108023	ST63	R503	—	—	—
1108025	ST63	R503	—	—	—
1108026	ST110	R503	—	4265	STK5
1108027	ST110	R503	—	4265	—
1108029	ST63	R503	—	—	—
1108031	ST110	R503	—	4265	STK5
1108032	—	R503	—	—	—
1108033	ST110	R503	—	5289	—
1108035	ST110	R503	—	4265	STK5
1108036	ST63	R503	—	—	—
1108037	ST63	R503	—	—	—
1108038	ST63	R503	—	—	—
1108040	ST110	R503	—	4310	—
1108041	ST63	R503	—	—	—
1108042	ST110	R503	—	4265	STK5
1108043	ST63	R503	4310	4286	—
1108045	—	R503	4310	4286	—
1108046	—	R503	—	—	—
1108047	ST63	R503	—	—	—
1108048	—	R503	—	—	—
1108051	ST110	R503	—	5289	—
1108052	ST63	R503	—	—	—
1108053	ST110	R503	—	4265	—
1108055	ST63	R503	4310	4286	—
1108056	ST63	R503	—	—	—
1108057	—	R503	4310	4286	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1108058	ST110	R503	—	5289	STK5
1108059	ST500	R503	4310	—	—
1108060	ST63	R503	4310	4286	—
1108061	ST63	R503	—	—	—
1108062	—	R503	—	—	—
1108063	ST63	R503	—	—	—
1108064	—	R503	—	—	—
1108065	ST63	R503	—	—	—
1108066	ST63	R503	—	—	—
1108067	ST63	R503	—	—	—
1108068	—	R503	4310	4286	—
1108069	ST63	R503	4310	4286	—
1108070	ST110	R503	4310	5289	—
1108071	ST63	R503	—	—	—
1108072	ST500	R503	4310	—	—
1108073	ST63	R503	—	—	—
1108076	ST63	R503	4310	4286	—
1108077	ST63	R503	—	—	—
1108078	—	R503	—	—	—
1108080	ST63	R503	4310	—	—
1108081	—	R503	—	4286	—
1108082	ST110	R514	—	5289	—
1108083	ST63	R503	—	—	—
1108084	—	R514	4310	—	—
1108085	ST63	R503	—	—	—
1108086	ST63	R503	—	—	—
1108087	ST110	R514	4310	5289	—
1108089	—	R503	—	—	—
1108090	—	R503	—	—	—
1108091	—	R503	—	5288	—
1108092	ST63	R503	—	—	—
1108093	ST500	R503	—	—	—
1108094	ST63	R503	—	—	—
1108096	ST500	R503	—	—	—
1108097	ST63	R503	—	—	—
1108098	ST63	R503	—	—	—
1108099	ST500	R503	—	—	—
1108101	—	R514	—	—	—
1108102	—	R514	—	4286	—
1108103	—	R514	—	4286	—
1108104	ST11	R514	—	—	—
1108105	—	R514	—	5289	—
1108106	ST51	R514	—	—	—
1108107	ST11	R514	—	—	—
1108108	—	R514	—	4286	—
1108109	ST51	R514	—	—	—
1108110	—	R514	—	5289	—
1108111	ST51	R514	—	4286	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1108112	ST51	R514	—	4286	—
1108113	ST51	R514	—	4286	—
1108114	—	—	—	4200	—
1108115	—	R514	—	—	—
1108116	—	—	4310	4200	—
1108117	—	—	4310	4310	—
1108118	—	—	4310	4200	—
1108119	—	R514	—	4286	—
1108120	—	R514	—	—	—
1108121	—	R514	—	—	—
1108122	ST51	R514	—	—	—
1108123	—	R514	—	—	—
1108125	—	R514	—	—	—
1108126	ST51	R514	—	—	—
1108127	—	R514	—	—	—
1108128	—	R514	—	4265	—
1108129	ST51	R514	—	4286	—
1108130	ST51	R514	—	—	—
1108131	ST51	R514	—	—	—
1108132	—	R514	4310	4286	—
1108133	ST51	R514	—	—	—
1108135	—	R514	4310	—	—
1108142	ST51	R514	—	—	—
1108143	ST11	R514	—	—	—
1108144	ST11	R514	—	—	—
1108149	ST51	R514	4310	—	—
1108150	ST51	R514	—	—	—
1108151	—	R514	—	—	—
1108152	ST51	R514	—	—	—
1108153	—	R514	—	5289	—
1108154	ST51	R514	—	—	—
1108155	—	R514	—	—	—
1108156	—	R514	—	5288	—
1108157	ST110	R514	—	4265	STK5
1108158	—	R514	—	—	—
1108159	—	R514	4310	4286	—
1108161	—	R514	—	5289	—
1108162	ST500	R514	—	—	—
1108163	ST51	R514	—	—	—
1108164	ST112	R514	—	—	STK2
1108165	ST51	R514	4310	4286	—
1108166	—	R514	—	—	—
1108167	ST51	R514	—	—	—
1108168	ST51	R514	—	—	—
1108169	ST51	R514	—	—	—
1108170	ST51	R514	—	—	—
1108171	ST51	R514	—	—	—
1108173	—	R514	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1108174	—	R514	—	—	—
1108175	—	R514	—	4286	—
1108176	ST51	R514	4310	—	—
1108177	—	R514	—	4265	—
1108180	—	R503	—	—	—
1108181	—	R503	—	—	—
1108182	ST51	R503	—	—	—
1108183	—	R503	—	—	—
1108184	ST51	R503	—	4286	—
1108185	—	R503	—	—	—
1108186	ST51	R503	—	—	—
1108187	—	R505	—	—	—
1108188	ST51	R503	—	—	—
1108190	—	R503	—	—	—
1108191	—	R503	—	—	—
1108195	ST124	R503	—	5336	STK27
1108196	ST124	R503	—	—	STK27
1108197	ST124	R505	—	—	STK27
1108198	ST124	R503	—	—	STK15
1108199	ST51	R504	—	—	—
1108200	ST51	R504	—	—	—
1108201	—	R503	—	4286	—
1108202	—	R503	—	—	—
1108203	—	R503	—	4286	—
1108204	—	R503	—	—	—
1108205	—	R503	—	4286	—
1108206	—	R503	—	—	—
1108207	—	R503	—	—	—
1108208	—	R503	—	—	—
1108209	—	R503	—	—	—
1108210	—	R503	—	4286	—
1108211	—	R503	—	4286	—
1108212	—	R503	—	—	—
1108213	—	R503	—	—	—
1108214	—	R503	—	—	—
1108215	—	R503	—	—	—
1108217	ST63	R503	—	4286	—
1108219	ST63	R503	—	—	—
1108221	ST63	R503	—	—	—
1108222	ST63	R503	—	4286	—
1108223	—	R503	—	—	—
1108224	ST124	R503	—	5336	STK27
1108225	ST124	R503	—	—	STK27
1108226	—	R503	—	—	—
1108227	ST124	R503	—	—	STK27
1108229	ST124	R503	—	—	STK27
1108234	—	R514	—	—	—
1108239	—	R514	—	5289	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1108240	—	R514	—	5289	—
1108246	—	R505	—	—	—
1108249	—	R503	—	—	—
1108250	—	R514	—	5289	—
1108251	ST124	R514	—	—	STK15
1108258	—	R505	—	—	—
1108260	—	R505	—	5288	—
1108263	ST124	R503	4200	5288	STK15
1108267	—	R505	—	—	—
1108268	—	R503	—	—	—
1108273	—	R505	—	—	—
1108278	ST124	R503	—	—	STK27
1108280	—	R505	—	—	—
1108281	ST124	R503	—	—	STK27
1108282	ST124	R503	—	5336	STK27
1108283	ST124	R503	—	—	STK27
1108284	ST124	R503	—	—	STK27
1108285	ST124	R503	—	—	STK27
1108286	ST124	R503	—	5336	STK27
1108287	ST124	R503	—	—	STK27
1108289	ST124	R503	—	—	STK27
1108290	ST124	R503	—	—	STK27
1108291	ST124	R503	—	—	STK27
1108294	ST124	R503	—	—	STK27
1108295	ST124	R503	—	—	STK27
1108296	ST124	R503	—	4265	STK15
1108297	ST124	R503	—	5336	STK27
1108298	ST124	R503	—	—	STK27
1108299	ST124	R503	—	—	STK27
1108300	ST124	R503	—	—	STK27
1108301	ST124	R503	—	—	STK27
1108302	ST124	R503	—	—	STK27
1108303	ST124	R503	—	—	STK27
1108304	ST124	R503	—	—	STK27
1108305	ST124	R503	—	5288	STK15
1108306	ST124	R503	—	—	STK27
1108307	ST124	R503	—	—	STK27
1108308	—	R503	—	—	—
1108309	—	R505	—	—	—
1108310	—	R503	—	—	—
1108311	—	R503	—	—	—
1108312	—	R505	—	—	—
1108314	—	R505	—	—	—
1108315	—	R505	—	—	—
1108316	ST124	R503	—	—	STK27
1108317	ST124	R503	—	—	STK27
1108318	ST124	R503	—	—	STK27
1108319	ST124	R503	—	4265	STK27

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1108320	ST124	R503	—	5336	STK27
1108321	ST124	R503	—	—	STK27
1108322	ST124	R505	—	—	STK27
1108323	ST124	R503	—	4265	STK27
1108324	ST124	R503	—	—	STK27
1108325	ST124	R503	—	—	STK27
1108326	ST124	R503	—	5336	STK27
1108327	ST124	R503	—	5336	STK27
1108328	ST124	R503	—	—	STK27
1108329	ST124	R503	—	—	STK27
1108330	ST124	R503	—	—	STK27
1108331	ST124	R503	—	5288	STK27
1108332	ST124	R503	—	—	STK27
1108333	ST124	R503	—	5288	STK27
1108334	ST124	R503	—	4265	STK27
1108335	ST124	R503	—	5288	STK27
1108336	ST124	R503	—	—	STK27
1108338	ST124	R503	—	5336	STK27
1108340	ST124	R505	—	—	STK27
1108341	ST124	R503	—	4265	STK27
1108342	—	R505	—	—	—
1108343	ST124	R503	—	—	STK27
1108344	ST124	R503	—	4265	STK27
1108345	ST124	R505	4310	5288	STK27
1108347	ST124	R505	—	5288	STK27
1108348	ST124	R503	—	5288	STK27
1108349	ST124	R503	—	5288	STK27
1108350	ST124	R505	—	5336	STK27
1108351	ST124	R503	—	5288	STK27
1108352	ST124	R503	—	5336	STK27
1108353	—	R503	—	5288	—
1108354	ST124	R503	—	5288	STK27
1108355	ST124	R505	—	5336	STK27
1108356	ST124	R503	—	5336	STK27
1108357	ST124	R505	—	—	STK27
1108358	ST124	R503	—	—	STK27
1108359	—	R503	—	—	—
1108360	ST124	R503	—	5336	STK27
1108361	ST124	R503	—	5288	STK27
1108362	ST124	R503	—	5336	STK27
1108363	ST124	R505	—	—	STK27
1108364	ST124	R505	—	5336	STK27
1108365	ST124	R503	—	5336	STK27
1108366	ST124	R503	—	—	STK27
1108367	ST124	R503	—	—	STK27
1108368	ST124	R503	—	5336	STK27
1108369	ST124	R505	—	5336	STK27
1108370	ST124	R505	—	5336	STK27

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1108371	ST124	R503	—	5336	STK27
1108372	ST124	R505	—	5336	STK27
1108373	ST124	R503	—	—	STK27
1108374	ST124	R503	—	—	STK27
1108375	ST124	R503	—	—	STK27
1108376	ST124	R503	—	—	STK27
1108377	ST124	R503	—	—	STK27
1108378	ST124	R503	—	—	STK27
1108379	ST124	R503	—	—	STK27
1108380	ST124	R503	—	—	STK27
1108381	ST124	R503	—	5336	STK27
1108382	ST124	R503	—	5336	STK27
1108383	ST124	R503	—	—	STK27
1108384	ST124	R503	—	5336	STK27
1108385	ST124	R503	—	5336	STK27
1108386	ST124	R503	—	—	STK27
1108387	ST124	R503	—	—	STK27
1108388	ST124	R505	—	4265	STK27
1108389	ST124	R503	—	5336	STK27
1108390	ST124	R505	—	4265	STK27
1108391	ST124	R503	—	5336	STK27
1108392	ST124	R503	—	5336	STK27
1108393	ST124	R503	—	4265	STK27
1108394	ST124	R503	—	—	STK27
1108395	ST124	R503	—	—	STK27
1108396	ST124	R503	—	4265	STK27
1108397	ST124	R503	—	4265	STK27
1108400	ST124	R503	—	—	STK27
1108401	—	R514	—	—	—
1108402	—	R514	—	—	—
1108403	—	R514	—	—	—
1108404	—	R514	4310	4286	—
1108405	ST51	R514	—	4286	—
1108406	—	R514	—	4286	—
1108407	—	R514	—	—	—
1108408	—	R514	—	—	—
1108409	ST51	R514	—	—	—
1108410	—	R514	4310	4286	—
1108411	—	R514	4310	4286	—
1108412	ST51	R514	—	4286	—
1108415	ST124	R505	—	5336	STK27
1108416	ST124	R503	—	—	STK27
1108417	ST124	R503	—	—	STK27
1108418	ST124	R503	—	5336	STK27
1108419	ST124	R505	—	—	STK27
1108420	ST124	R503	—	—	STK27
1108421	ST124	R505	—	4265	STK27
1108422	ST124	R505	—	4265	STK27

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1108423	ST124	R505	—	4265	STK27
1108424	ST124	R505	—	—	STK27
1108425	ST124	R505	—	5336	STK27
1108426	ST124	R505	—	—	STK27
1108427	ST124	R503	—	5336	STK27
1108428	ST124	R503	—	5336	STK27
1108429	ST124	R503	—	5336	STK27
1108430	ST124	R503	—	5336	STK27
1108431	ST124	R503	—	—	STK27
1108432	ST124	R503	—	—	STK27
1108434	ST124	R503	—	5336	STK27
1108435	ST124	R503	—	5336	STK27
1108436	—	R503	—	—	—
1108438	—	R503	—	—	—
1108439	—	R503	—	—	—
1108440	—	R503	—	—	—
1108441	—	R503	—	—	—
1108442	—	R503	—	—	—
1108443	—	R505	—	4265	—
1108445	ST124	R503	—	—	STK27
1108446	ST124	R503	—	—	STK27
1108447	ST124	R505	—	—	STK27
1108448	ST124	R503	—	—	STK27
1108449	ST124	R503	—	—	STK27
1108450	ST124	R505	—	—	STK27
1108451	ST11	R503	—	5289	—
1108452	ST11	R503	—	5289	—
1108453	—	R503	—	5289	—
1108454	—	R503	—	5289	—
1108455	—	R503	—	—	—
1108456	—	R503	—	5289	—
1108457	—	R503	—	—	—
1108458	ST110	R503	—	5289	—
1108459	ST110	R503	—	5289	—
1108461	ST500	R503	—	—	—
1108464	ST500	R503	—	—	—
1108465	ST110	R503	—	5289	STK5
1108466	ST110	R503	—	5289	—
1108468	—	R503	—	—	—
1108469	ST53	R503	—	—	—
1108470	—	R503	—	—	—
1108475	ST124	R503	—	—	STK27
1108476	ST124	R503	—	—	STK27
1108477	ST124	R503	—	—	STK27
1108478	ST124	R503	—	5288	STK27
1108479	ST124	R503	—	—	STK27
1108480	ST124	R503	—	—	STK27
1108481	ST124	R503	—	5288	STK27

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1108482	ST124	R503	—	—	STK27
1108483	ST124	R503	—	—	STK27
1108484	ST124	R505	—	—	STK27
1108485	ST124	R505	—	—	STK27
1108486	ST124	R505	—	—	STK27
1108487	ST124	R505	—	—	STK27
1108488	ST124	R505	—	—	STK27
1108489	ST124	R503	—	5288	STK27
1108490	ST124	R503	—	—	STK27
1108491	ST124	R503	—	—	STK27
1108492	ST124	R503	4200	5336	—
1108493	ST124	R505	—	—	STK27
1108494	ST124	R503	—	—	STK27
1108495	ST124	R503	—	—	STK27
1108496	ST124	R503	—	—	STK27
1108497	ST124	R503	—	—	STK27
1108498	ST124	R503	—	—	STK27
1108499	ST124	R503	—	—	STK27
1108500	ST124	R503	—	—	STK27
1108501	ST124	R505	—	—	STK27
1108502	ST124	R503	—	5336	STK27
1108503	ST124	R503	—	5336	STK27
1108504	ST124	R503	—	5336	STK27
1108505	ST124	R505	—	—	STK27
1108506	ST124	R503	—	—	STK27
1108507	ST124	R503	—	—	STK27
1108508	ST124	R505	—	—	STK27
1108510	ST124	R503	—	—	STK27
1108511	ST124	R503	—	—	STK27
1108512	ST124	R503	—	5336	STK27
1108513	ST124	R503	—	5336	STK27
1108515	ST124	R503	—	5336	STK27
1108516	ST124	R503	—	5336	STK27
1108517	ST124	R503	—	5336	STK27
1108518	ST124	R503	—	5336	STK27
1108519	ST124	R503	—	—	STK27
1108520	ST124	R503	—	5336	STK27
1108521	ST124	R503	—	—	STK27
1108522	ST124	R503	—	5336	STK27
1108523	—	R503	—	5336	—
1108524	ST124	R503	—	—	STK27
1108525	ST124	R503	—	—	STK27
1108526	—	R514	—	—	—
1108527	—	R514	4310	5289	—
1108528	—	R514	—	5289	—
1108529	—	R514	—	4265	—
1108530	—	R514	—	4286	—
1108531	ST11	R514	4310	5289	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1108532	—	R514	4310	5289	—
1108533	ST51	R514	4310	4286	—
1108534	—	R514	4310	5289	—
1108535	ST51	R514	4310	4286	—
1108536	—	R514	—	4286	—
1108537	—	R514	—	5289	—
1108539	—	R514	4310	5289	—
1108542	—	R514	—	5289	—
1108543	—	R514	4310	5289	—
1108545	ST112	R514	4310	5289	STK2
1108546	ST112	R514	4310	5289	STK2
1108547	ST112	R514	4310	5289	STK2
1108551	—	R1001	5242	—	—
1108552	—	R514	—	—	—
1108553	—	R514	—	—	—
1108555	—	R503	—	—	—
1108556	—	R503	—	—	—
1108557	—	R514	4310	4310	—
1108558	—	R503	—	—	—
1108559	—	R514	—	4286	—
1108560	—	R514	4310	—	—
1108561	—	R503	—	—	—
1108562	ST51	R514	4310	—	—
1108563	—	R514	4310	4310	—
1108565	—	R503	—	—	—
1108566	—	R503	4310	4310	—
1108567	—	R503	4310	—	—
1108568	—	R503	4310	4310	—
1108569	—	R503	—	—	—
1108572	ST63	R514	—	—	—
1108574	—	R514	—	—	—
1108579	—	R503	—	—	—
1108580	—	R514	—	—	—
1108585	—	R514	—	—	—
1108588	ST63	R514	—	—	—
1108592	ST51	R514	—	—	—
1108602	—	R514	—	—	—
1108603	—	R514	—	—	—
1108604	—	R514	—	—	—
1108605	ST6	R514	—	4286	—
1108606	—	R514	—	—	—
1108607	ST51	R514	—	—	—
1108608	—	R514	—	—	—
1108609	ST6	R514	—	—	—
1108610	—	R514	—	4286	—
1108612	—	R514	—	4286	—
1108614	—	R514	—	—	—
1108615	—	R514	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1108616	—	R514	—	—	—
1108617	—	R514	—	—	—
1108618	ST53	R514	—	—	—
1108619	—	R514	—	—	—
1108620	—	R514	—	—	—
1108621	ST100	R514	—	5289	STK2
1108622	ST53	R514	—	—	—
1108624	—	R514	—	4286	—
1108625	—	R514	—	4286	—
1108626	ST53	R514	—	—	—
1108628	—	R514	—	—	—
1108629	—	R514	—	4286	—
1108631	ST11	R514	—	4286	—
1108632	ST112	R514	—	5289	STK2
1108633	—	R514	—	4286	—
1108634	ST112	R514	—	5289	STK2
1108635	—	R514	4310	4286	—
1108636	—	R514	4310	5289	—
1108637	ST51	R514	4310	4286	—
1108638	—	R514	4310	5289	—
1108639	—	R514	4310	—	—
1108640	—	R514	4310	5289	—
1108641	—	R514	4310	5289	—
1108642	ST124	R514	4310	5289	STK27
1108643	—	R514	4310	5289	—
1108644	—	R514	4310	5289	—
1108645	—	R514	4310	4286	—
1108646	ST112	R514	4310	5289	STK2
1108647	—	R514	4310	5289	—
1108648	—	R514	4310	5289	—
1108649	ST124	R514	4310	5289	STK27
1108650	ST51	R514	4310	—	—
1108651	—	—	—	4286	—
1108652	—	R514	4310	5289	—
1108653	—	R514	4310	5289	—
1108654	ST124	R514	4310	5289	STK27
1108656	ST124	R514	4310	5289	STK27
1108657	ST124	R514	4310	5289	STK27
1108658	—	R514	4310	5289	—
1108659	ST124	R514	4310	5289	STK27
1108660	—	R514	4310	—	—
1108661	—	R514	—	5289	—
1108662	ST124	R514	—	5289	STK27
1108663	ST124	R514	—	—	STK15
1108665	ST124	R514	—	5289	STK27
1108666	ST124	R514	—	5289	STK27
1108667	ST124	R514	—	5289	STK27
1108668	—	R514	—	5289	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1108669	—	R514	—	—	—
1108670	ST124	R514	—	5289	STK27
1108671	—	R514	—	5289	—
1108672	ST124	R514	—	5289	STK27
1108673	—	R514	—	5289	—
1108674	—	R514	—	—	—
1108675	ST124	R514	—	5289	STK27
1108676	ST11	R514	—	4310	—
1108677	—	R514	—	4310	—
1108678	—	R514	—	4310	—
1108688	ST124	R504	—	—	STK27
1108691	ST124	R504	—	—	STK27
1108692	ST124	R504	—	—	STK27
1108693	ST124	R504	—	—	STK27
1108694	ST124	R504	—	—	STK27
1108696	ST124	R504	—	—	STK27
1108697	ST124	R504	—	—	STK27
1108698	ST124	R504	—	—	STK27
1108700	ST124	R504	—	—	STK27
1108701	—	R84	5284	4286	—
1108702	—	R84	5284	4286	—
1108703	—	R84	5284	—	—
1108704	—	R84	5284	—	—
1108705	—	R84	5284	—	—
1108706	—	R84	5284	—	—
1108707	—	R84	5284	—	—
1108708	—	R84	5284	—	—
1108709	—	R84	5284	—	—
1108710	—	R84	5284	—	—
1108711	—	R84	5284	—	—
1108712	—	R84	5284	—	—
1108713	—	R84	5284	4286	—
1108714	—	R84	5284	—	—
1108715	—	R84	5284	—	—
1108716	—	R84	5284	—	—
1108717	—	R84	5284	—	—
1108718	—	R84	4286	—	—
1108719	—	R84	5284	—	—
1108721	—	R84	5284	—	—
1108722	—	R84	5284	—	—
1108723	—	R84	5284	—	—
1108724	—	R84	5284	4286	—
1108725	—	R84	5284	4286	—
1108726	—	R84	5284	—	—
1108727	—	R84	5284	4286	—
1108728	—	R84	5284	—	—
1108729	—	R84	4286	—	—
1108730	—	R84	5284	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit	Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1108731	—	—	5284	4286	—	1108785	ST124	R503	—	5336	STK27
1108732	—	—	5284	—	—	1108787	ST124	R505	—	5336	STK27
1108733	—	—	5284	—	—	1108788	ST124	R503	—	5336	STK27
1108734	—	R84	4286	—	—	1108789	ST124	R503	—	—	STK27
1108735	—	R84	5284	—	—	1108790	ST124	R503	—	—	STK27
1108736	—	R84	5284	—	—	1108791	ST124	R503	—	—	STK27
1108737	—	R84	5284	—	—	1108792	ST124	R505	—	5336	STK27
1108738	—	—	5284	—	—	1108793	ST124	R503	—	5288	STK27
1108739	—	R84	5284	—	—	1108794	ST124	R503	—	—	STK27
1108740	—	R84	5284	—	—	1108795	ST124	R503	—	5336	STK27
1108742	ST124	R503	—	5288	STK15	1108796	ST124	R503	—	—	STK27
1108743	ST124	R503	—	—	STK15	1108797	ST124	R503	—	—	STK27
1108744	ST124	R505	—	5288	STK27	1108798	ST124	R503	—	5336	STK27
1108745	ST124	R503	—	5336	STK27	1108799	ST124	R503	—	5336	STK27
1108746	ST124	R503	—	5336	STK27	1108801	—	R84	5284	—	—
1108747	ST124	R503	—	5336	STK27	1108802	—	R84	5284	—	—
1108748	ST124	R503	—	5336	STK27	1108803	—	R84	5284	—	—
1108751	—	R503	—	5288	—	1108804	—	R84	5284	—	—
1108752	ST124	R503	—	5336	STK27	1108805	—	R84	5284	—	—
1108753	ST124	R503	—	5336	STK27	1108806	—	R84	5284	—	—
1108754	ST124	R503	—	5336	STK27	1108807	—	R84	5284	—	—
1108755	ST124	R503	—	5336	STK27	1108808	—	R84	5284	—	—
1108756	ST124	R503	—	5336	STK27	1108809	—	R84	5284	4286	—
1108758	ST124	R503	—	—	STK27	1108810	—	R84	5284	4286	—
1108759	ST124	R503	—	—	STK27	1108811	—	R84	5284	—	—
1108760	ST124	R503	—	—	STK27	1108812	—	R84	5284	—	—
1108761	ST124	R503	—	5336	STK27	1108813	—	R84	5284	5288	—
1108762	ST124	R503	—	—	STK27	1108814	—	R84	5284	—	—
1108763	ST124	R503	—	—	STK27	1108815	—	R84	5284	—	—
1108765	ST124	R503	—	—	STK27	1108816	—	R84	5284	—	—
1108766	ST124	R503	—	—	STK27	1108817	—	R84	5284	—	—
1108767	ST124	R503	—	5336	STK27	1108818	—	R84	5284	5288	—
1108768	ST124	R503	—	—	STK27	1108819	—	R84	5284	—	—
1108769	ST124	R503	—	—	STK27	1108820	—	R84	5284	5288	—
1108770	ST124	R503	—	—	STK27	1108821	—	R84	5284	4286	—
1108771	ST124	R503	—	—	STK27	1108822	—	R84	5284	5288	—
1108772	ST124	R503	—	5288	STK27	1108823	—	R84	5284	—	—
1108773	—	R503	—	5336	—	1108826	—	R84	5284	—	—
1108774	ST124	R503	—	—	STK27	1108827	—	R84	5284	—	—
1108775	ST124	R503	—	5336	STK27	1108828	—	R84	5284	—	—
1108776	ST124	R503	—	—	STK27	1108831	—	R84	5284	5288	—
1108778	ST124	R503	—	5336	STK27	1108835	—	R84	5284	—	—
1108779	ST124	R503	—	—	STK27	1108836	—	R84	5284	—	—
1108780	ST124	R503	—	—	STK27	1108840	—	R84	5284	5288	—
1108781	ST124	R503	—	—	STK27	1108841	—	R84	5284	4286	—
1108782	ST124	R503	—	—	STK27	1108842	—	R84	5284	5288	—
1108783	ST124	R503	—	5336	STK27	1108846	—	R84	5284	—	—
1108784	ST124	R503	—	5336	STK27	1108849	—	R84	5284	—	—

(continued on next column)

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1108850	—	R84	4286	—	—
1108851	—	R84	5284	—	—
1108852	—	R84	5284	—	—
1108853	—	R84	5284	—	—
1108854	—	R84	5284	—	—
1108855	—	R84	5284	—	—
1108856	—	R84	5284	—	—
1108857	—	R84	5284	—	—
1108858	—	R84	5284	—	—
1108859	—	R84	5284	—	—
1108860	—	R84	5284	—	—
1108861	—	R84	5284	—	—
1108862	—	R84	5284	—	—
1108863	—	R84	5284	—	—
1108864	—	R84	5284	—	—
1108865	—	R84	5284	—	—
1108866	—	R84	5284	—	—
1108867	—	R84	5284	—	—
1108868	—	R84	5284	—	—
1108869	—	R84	5284	—	—
1108870	—	R84	5284	—	—
1108871	—	R84	5284	—	—
1108872	—	R84	5284	—	—
1108873	—	R84	5284	—	—
1108874	—	R84	5284	—	—
1108875	—	R84	5284	—	—
1108877	—	R84	5284	—	—
1108878	—	R84	5284	—	—
1108879	—	R84	5284	—	—
1108880	—	R84	5284	—	—
1108881	—	R84	5284	—	—
1108882	—	R84	5284	—	—
1108883	—	R84	5284	—	—
1108887	—	R84	5284	—	—
1108891	—	R84	5284	—	—
1108892	—	R84	5284	—	—
1108893	—	R84	5284	—	—
1108894	—	R84	5284	5288	—
1108895	—	R84	5284	5288	—
1108896	—	R84	5284	—	—
1108900	—	R81	—	4286	—
1108901	—	R81	5284	—	—
1108902	—	R81	5284	—	—
1108903	ST500	R81	4265	—	—
1108904	—	R81	4265	—	—
1108905	—	R81	4265	—	—
1108906	—	R81	4265	—	—
1108907	—	R81	4265	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1108908	ST500	R81	4265	—	—
1108909	—	R81	4265	—	—
1108910	—	R81	4265	—	—
1108911	—	R81	4265	—	—
1108912	—	R81	4265	—	—
1108913	—	R81	4265	—	—
1108914	ST11	R81	4265	—	—
1108915	—	R81	4265	—	—
1108916	—	R81	4265	—	—
1108917	—	R81	4265	—	—
1108918	—	R81	4265	—	—
1108919	ST11	R81	4265	—	—
1108920	ST500	R81	4265	—	—
1108921	—	R81	4265	—	—
1108922	—	R81	4265	—	—
1108923	—	R81	4265	—	—
1108924	—	R503	4265	4265	—
1108925	ST500	R81	4265	—	—
1108927	—	—	—	4286	—
1108928	—	—	—	4286	—
1108929	—	—	—	4286	—
1108930	—	—	—	4286	—
1108931	—	—	4265	—	—
1108932	—	—	4265	—	—
1108933	—	R81	4265	—	—
1108936	—	R81	4265	—	—
1108937	ST63	R81	4265	—	—
1108938	ST500	R81	4265	—	—
1108940	—	R81	4265	—	—
1108943	ST500	R81	4265	—	—
1108944	ST500	R81	4265	—	—
1108950	ST11	R84	—	—	—
1108951	ST6	R86	—	—	—
1108952	—	R86	—	—	—
1108953	—	R86	—	—	—
1108954	—	R84	—	—	—
1108955	—	R84	—	—	—
1108956	ST6	R84	—	—	—
1108957	—	R84	—	—	—
1108958	ST500	R86	—	—	—
1108959	ST51	R84	—	—	—
1108960	—	R84	—	—	—
1108961	—	R84	—	—	—
1108964	—	R84	—	—	—
1108965	—	R84	—	—	—
1108966	—	R86	—	—	—
1108968	ST51	R84	—	—	—
1108969	—	R86	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1108970	ST11	R84	—	—	—
1108973	ST51	R84	—	—	—
1108977	ST51	R84	—	—	—
1108980	—	R84	—	—	—
1108981	ST11	R86	—	—	—
1108982	ST11	R84	—	—	—
1108983	ST51	R84	—	—	—
1108984	ST63	R86	—	—	—
1108985	ST51	R84	—	—	—
1108987	—	R84	—	5288	—
1108988	ST51	R84	—	—	—
1108989	—	R84	—	—	—
1108990	—	R86	—	—	—
1108994	—	R86	—	5288	—
1108995	—	R84	—	—	—
1108996	—	R84	—	—	—
1108998	ST11	R86	—	—	—
1108999	—	R86	—	5288	—
1109000	ST63	R81	—	5288	—
1109001	—	R81	4265	4286	—
1109002	ST63	R81	4265	4286	—
1109003	—	R81	4265	4286	—
1109004	ST63	R81	4265	4286	—
1109005	ST51	R81	4265	4286	—
1109012	ST51	R81	4265	4286	—
1109014	—	R81	—	—	—
1109015	ST63	R81	4265	4286	—
1109016	ST63	R81	4265	4286	—
1109022	ST124	R503	—	—	STK27
1109023	ST124	R503	—	5336	STK27
1109024	ST124	R503	—	—	STK27
1109025	ST124	R503	—	5336	STK27
1109026	ST124	R503	—	5336	STK27
1109027	ST124	R503	—	5336	STK27
1109029	ST124	R503	—	5336	STK27
1109030	ST124	R503	—	5336	STK27
1109032	ST124	R505	—	5336	STK27
1109033	ST124	R503	—	5336	STK27
1109034	ST124	R503	—	5336	STK27
1109035	ST124	R503	—	5336	STK27
1109036	ST124	R503	—	5336	STK27
1109038	ST124	R503	—	—	STK27
1109039	ST124	R503	—	5336	STK27
1109040	—	R84	—	—	—
1109041	ST124	R503	—	—	STK27
1109042	ST124	R503	—	5336	STK27
1109045	—	R504	—	—	—
1109046	—	R504	—	5288	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109047	—	R504	—	5288	—
1109048	—	R504	—	5288	—
1109050	—	R504	—	5288	—
1109051	—	R522	—	—	—
1109052	ST124	R503	—	5336	STK27
1109053	ST124	R503	—	4265	STK27
1109054	ST124	R503	—	—	STK27
1109055	ST124	R503	—	—	STK27
1109056	ST124	R503	—	5336	STK27
1109057	ST124	R503	—	—	STK27
1109058	ST124	R503	—	5336	STK27
1109059	ST124	R503	—	5336	STK27
1109060	ST124	R505	—	5336	STK27
1109061	ST124	R503	—	—	STK27
1109062	ST124	R503	—	—	STK27
1109063	ST124	R503	—	—	STK27
1109064	ST124	R503	—	5336	STK27
1109065	ST124	R503	—	5336	STK27
1109066	ST124	R503	—	5336	STK27
1109067	ST124	R503	—	5336	STK27
1109068	ST124	R503	—	5336	STK27
1109069	ST124	R503	—	5336	STK27
1109070	ST124	R503	—	5336	STK27
1109072	ST124	R503	—	5336	STK27
1109074	ST124	R503	—	5336	STK27
1109075	ST124	R503	—	5336	STK27
1109076	ST124	R503	—	5336	STK27
1109077	ST124	R503	—	5336	STK27
1109078	ST124	R503	—	5336	STK27
1109079	ST124	R503	—	5336	STK27
1109080	ST124	R503	—	—	STK27
1109081	ST124	R503	—	—	STK27
1109082	ST124	R503	—	—	STK27
1109083	ST124	R503	—	5336	STK27
1109084	ST124	R503	—	—	STK27
1109085	ST124	R503	—	—	STK27
1109086	ST124	R503	—	—	STK27
1109087	ST124	R503	—	—	STK27
1109088	ST124	R503	—	—	STK27
1109089	ST124	R503	—	—	STK27
1109090	ST124	R503	—	—	STK27
1109091	ST124	R503	—	—	STK27
1109092	—	R503	—	—	—
1109093	ST124	R503	—	—	STK27
1109094	ST124	R503	—	—	STK27
1109095	ST124	R503	—	—	STK27
1109096	ST124	R503	—	—	STK27
1109097	ST124	R503	—	—	STK27

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109098	ST124	R503	—	—	STK27
1109099	ST124	R503	—	5336	STK27
1109100	—	R81	—	4286	—
1109101	—	R81	5284	—	—
1109102	—	R81	5284	—	—
1109103	—	R81	—	4286	—
1109104	—	R81	—	4286	—
1109105	—	R81	—	4286	—
1109106	—	R81	—	4286	—
1109107	—	R81	—	4286	—
1109108	—	R81	—	4286	—
1109109	—	R81	—	4286	—
1109110	—	R81	—	4286	—
1109111	—	R81	—	4286	—
1109112	—	R81	—	4286	—
1109113	—	R81	—	4286	—
1109114	—	R81	5284	—	—
1109115	—	R81	—	4286	—
1109116	—	R81	5284	—	—
1109117	—	R81	—	4286	—
1109118	—	R81	—	4286	—
1109119	—	R81	5284	—	—
1109120	—	R81	5284	—	—
1109121	—	R81	—	4286	—
1109122	—	R81	—	4286	—
1109123	—	R81	—	4286	—
1109129	—	—	—	4286	—
1109130	—	R81	—	5288	—
1109131	—	R81	—	5288	—
1109132	—	R81	—	5288	—
1109134	—	R81	5284	—	—
1109135	—	R81	—	4286	—
1109140	ST335	R522	—	—	—
1109141	ST124	R504	—	—	STK27
1109142	ST124	R504	—	—	STK27
1109143	ST124	R504	—	—	STK27
1109144	ST124	R504	—	—	STK27
1109145	ST124	R504	—	—	STK27
1109146	ST124	R504	—	—	STK27
1109147	ST124	R504	—	—	STK27
1109149	ST124	R504	—	—	STK27
1109150	—	R84	—	5288	—
1109151	—	R84	—	5288	—
1109152	—	R84	—	5288	—
1109153	—	R84	—	5288	—
1109154	—	R84	—	5288	—
1109155	—	R84	—	5288	—
1109156	—	R84	—	5288	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109158	—	R84	—	5288	—
1109163	—	R84	—	5288	—
1109164	—	R84	—	5288	—
1109169	—	R84	—	5288	—
1109170	—	R84	—	5288	—
1109172	—	R84	—	5288	—
1109173	—	R84	—	5288	—
1109176	—	R84	—	—	—
1109178	—	R84	—	5288	—
1109179	—	R84	—	5288	—
1109180	—	R84	—	5288	—
1109181	—	R84	—	5288	—
1109182	—	R84	—	5288	—
1109183	—	R84	—	5288	—
1109184	—	R84	—	5288	—
1109185	—	R84	—	5288	—
1109186	ST124	R504	—	—	STK27
1109187	ST124	R504	—	—	STK27
1109188	ST124	R504	—	—	STK27
1109189	ST124	R504	—	—	STK27
1109190	ST124	R504	—	—	STK27
1109191	ST124	R504	—	—	STK27
1109192	ST124	R504	—	—	STK27
1109193	ST124	R504	—	—	STK27
1109194	ST124	R504	—	—	STK27
1109196	ST124	R504	—	—	STK27
1109197	ST124	R504	—	—	STK27
1109198	ST124	R504	—	—	STK27
1109199	ST124	R504	—	—	STK27
1109200	—	R81	—	—	—
1109203	—	—	—	5284	—
1109204	—	R81	—	5284	—
1109205	—	R81	—	—	—
1109208	—	R504	—	—	—
1109209	ST124	R504	—	—	STK27
1109210	ST124	R504	—	—	STK27
1109212	ST124	R504	—	—	STK27
1109213	ST124	R504	—	—	STK27
1109214	ST124	R504	—	—	STK27
1109215	ST124	R504	—	—	STK27
1109216	ST124	R509	—	4265	STK27
1109217	—	R504	—	—	—
1109218	ST124	R509	—	4265	STK27
1109219	ST128	R509	—	4265	STK28
1109220	ST134	R519	—	—	—
1109221	ST137	R519	—	—	—
1109222	ST132	R519	—	—	STK21 ³⁰
1109222	ST132	R519	—	—	STK32 ³¹

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109224	ST134	R519	—	—	—
1109225	—	R84	—	5288	—
1109226	—	R84	—	5288	—
1109227	—	R84	—	5288	—
1109228	—	R84	—	5288	—
1109229	—	R84	—	5288	—
1109230	—	R84	—	5288	—
1109231	—	R84	—	5288	—
1109232	—	R84	—	5288	—
1109233	—	R84	—	5288	—
1109234	—	R84	—	5288	—
1109235	—	R84	—	—	—
1109236	—	R84	—	5288	—
1109237	—	R84	—	5288	—
1109238	—	R84	—	5288	—
1109240	—	R84	—	—	—
1109241	—	R84	4200	5288	—
1109242	—	R84	4200	5288	—
1109243	—	R84	4200	5288	—
1109244	—	R84	—	5288	—
1109245	—	R84	—	5288	—
1109246	—	R84	—	5288	—
1109247	—	R84	—	—	—
1109248	—	R84	—	5288	—
1109249	—	R84	—	5288	—
1109251	—	R504	—	—	—
1109252	—	R504	—	—	—
1109253	ST124	R504	—	—	STK27
1109255	—	R504	—	—	—
1109256	—	R504	—	—	—
1109257	ST124	R504	—	—	STK27
1109258	—	R504	—	—	—
1109259	—	R504	—	—	—
1109260	—	R504	—	—	—
1109261	ST124	R504	—	—	STK27
1109262	—	R504	—	—	—
1109263	ST124	R504	—	—	STK27
1109264	ST124	R504	—	—	STK27
1109265	—	—	4310	—	—
1109266	—	—	4310	—	—
1109267	—	—	4310	—	—
1109268	—	—	4310	—	—
1109269	—	—	4310	—	—
1109270	—	—	4310	—	—
1109271	—	—	4310	—	—
1109272	—	R504	—	—	—
1109274	ST134	R519	—	4498	—
1109275	ST134	R519	—	4498	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109276	ST134	R519	—	4498	—
1109277	ST134	R519	—	4498	—
1109278	ST134	R519	—	4498	—
1109279	ST134	R519	—	4498	—
1109280	ST138	R519	—	4498	—
1109281	ST137	R519	—	4498	—
1109282	ST134	R519	—	4498	—
1109283	—	R519	—	4498	—
1109284	ST138	R519	—	4498	—
1109285	ST132	R519	—	4498	STK21 ³⁰
1109285	ST132	R519	—	4498	STK32 ³¹
1109286	ST132	R519	—	4498	STK21 ³⁰
1109286	ST132	R519	—	4498	STK32 ³¹
1109287	ST132	R519	—	4498	STK21 ³⁰
1109287	ST132	R519	—	4498	STK32 ³¹
1109288	ST132	R519	—	4498	STK21 ³⁰
1109288	ST132	R519	—	4498	STK32 ³¹
1109289	ST132	R519	—	4498	STK21 ³⁰
1109289	ST132	R519	—	4498	STK32 ³¹
1109290	ST132	R519	—	4498	STK21 ³⁰
1109290	ST132	R519	—	4498	STK32 ³¹
1109291	ST132	R519	—	4498	STK21 ³⁰
1109291	ST132	R519	—	4498	STK32 ³¹
1109292	ST132	R519	—	4498	STK21 ³⁰
1109292	ST132	R519	—	4498	STK32 ³¹
1109293	ST132	—	—	—	—
1109294	ST132	R519	—	4498	STK21 ³⁰
1109294	ST132	R519	—	4498	STK32 ³¹
1109295	ST131	R519	—	4498	STK20 ³⁰
1109295	ST131	R519	—	4498	STK31 ³¹
1109296	ST132	R519	—	4498	STK21 ³⁰
1109296	ST132	R519	—	4498	STK32 ³¹
1109297	ST132	R519	—	4498	STK21 ³⁰
1109297	ST132	R519	—	4498	STK32 ³¹
1109298	ST132	R519	—	4498	STK21 ³⁰
1109298	ST132	R519	—	4498	STK32 ³¹
1109299	ST132	—	—	4498	STK21 ³⁰
1109299	ST132	—	—	4498	STK32 ³¹
1109300	—	R81	5284	—	—
1109301	—	R81	5284	—	—
1109302	—	R81	5284	—	—
1109303	—	R81	5284	—	—
1109304	—	R81	5284	4286	—
1109305	—	R81	5284	—	—
1109306	—	R81	5284	—	—
1109307	—	R81	5284	—	—
1109308	—	R81	5284	—	—
1109309	—	R81	4286	—	—

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109310	—	R81	5284	—	—
1109311	—	R81	5284	—	—
1109312	—	R81	5284	—	—
1109313	—	R81	5284	—	—
1109314	—	R81	5284	—	—
1109315	—	R81	5284	—	—
1109316	—	R81	—	—	—
1109317	—	R81	5284	—	—
1109318	—	R81	5284	—	—
1109319	—	R81	5284	—	—
1109320	—	R81	5284	—	—
1109321	—	R81	5284	—	—
1109322	—	R81	5284	—	—
1109323	—	R81	5284	—	—
1109324	—	R81	5284	4286	—
1109325	—	—	5284	—	—
1109326	—	—	5284	—	—
1109327	—	—	5284	4286	—
1109328	—	—	5284	—	—
1109329	—	—	5284	—	—
1109330	—	R81	4286	—	—
1109331	—	R81	5284	—	—
1109332	—	R81	5284	—	—
1109333	—	R81	5284	4286	—
1109334	—	R81	5284	—	—
1109335	—	R81	5284	4286	—
1109336	—	R81	5284	—	—
1109337	—	R81	5284	—	—
1109338	—	R81	5284	—	—
1109339	—	R81	5284	—	—
1109340	—	R81	5284	—	—
1109341	—	R81	5284	—	—
1109342	—	R81	5284	—	—
1109343	—	R81	5284	—	—
1109344	—	R81	5284	—	—
1109345	—	R81	5284	5288	—
1109346	—	R81	5284	—	—
1109349	—	R81	5284	—	—
1109351	—	R81	5284	5288	—
1109352	—	R503	—	—	—
1109353	—	R503	—	—	—
1109354	ST124	R503	—	—	STK27
1109355	ST124	R505	—	—	STK27
1109356	ST124	R503	—	—	STK27
1109357	ST124	R503	—	—	STK27
1109358	ST124	R503	—	—	STK27
1109359	ST124	R503	—	—	STK27
1109360	ST124	R503	—	—	STK27

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109361	ST124	R503	—	—	STK27
1109362	ST124	R503	—	—	STK27
1109363	ST124	R503	—	—	STK27
1109364	ST124	R503	—	—	STK27
1109365	ST124	R503	—	—	STK27
1109367	—	R503	—	—	—
1109368	ST124	R503	—	—	STK27
1109369	ST124	R503	—	—	STK27
1109371	—	R503	—	—	—
1109372	—	R503	—	—	—
1109373	—	R503	—	—	—
1109377	ST124	R503	—	—	STK27
1109379	—	R503	—	—	—
1109380	—	R503	—	—	—
1109381	—	R503	—	—	—
1109382	—	—	4265	—	—
1109383	ST11	R503	5288	—	—
1109384	—	R503	—	—	—
1109385	—	R503	—	—	—
1109386	—	R503	—	—	—
1109387	—	R503	—	—	—
1109388	—	R503	—	4200	—
1109389	—	R503	—	—	—
1109390	—	R503	—	—	—
1109391	—	R503	—	4286	—
1109392	—	R503	—	—	—
1109393	—	R503	—	—	—
1109394	—	R503	—	—	—
1109395	—	R503	—	—	—
1109396	—	R505	—	—	—
1109397	—	R503	—	—	—
1109398	ST124	R503	—	—	STK27
1109399	ST124	R503	—	5336	STK27
1109400	—	R84	5284	4286	—
1109402	—	R84	5284	4286	—
1109404	—	R84	5284	—	—
1109405	—	R84	5284	—	—
1109411	ST124	R503	—	5336	STK27
1109412	ST124	R503	—	5336	STK27
1109414	ST124	R503	—	5336	STK27
1109415	ST124	R503	—	—	STK27
1109416	ST124	R503	—	5336	STK27
1109417	ST124	R503	—	—	STK27
1109418	ST124	R503	—	—	STK27
1109419	ST124	R503	—	—	STK27
1109420	ST124	R503	—	—	STK27
1109421	ST124	R503	—	—	STK27
1109422	ST124	R503	—	—	STK27

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109423	ST124	R503	—	—	STK27
1109424	ST124	R503	—	—	STK27
1109425	ST124	R503	—	—	STK27
1109426	ST124	R503	—	—	STK27
1109427	ST124	R503	—	—	STK27
1109428	ST124	R503	—	—	STK27
1109429	ST124	R503	—	—	STK27
1109430	ST124	R503	—	—	STK27
1109431	ST124	R503	—	—	STK27
1109432	ST124	R503	—	—	STK27
1109433	ST124	R503	—	—	STK27
1109434	ST124	R503	—	—	STK27
1109435	ST124	R503	—	—	STK27
1109436	ST124	R503	—	—	STK27
1109437	ST124	R503	—	—	STK27
1109438	ST124	R503	—	—	STK27
1109439	ST124	R503	—	—	STK27
1109440	—	R84	—	5288	—
1109441	—	R84	—	5288	—
1109442	—	R84	—	5288	—
1109443	—	R84	—	5288	—
1109444	—	R84	—	5288	—
1109446	ST124	R503	—	—	STK27
1109447	ST124	R503	—	5336	STK27
1109448	ST124	R503	—	—	STK27
1109451	—	R501	4265	—	—
1109452	—	R501	4265	—	—
1109453	—	R501	4265	—	—
1109454	—	R501	4265	—	—
1109455	—	R501	4265	—	—
1109456	—	R501	4265	—	—
1109457	—	R501	4265	—	—
1109458	ST63	R501	4265	—	—
1109459	—	R501	4265	—	—
1109460	ST63	R501	4265	—	—
1109461	ST63	R501	4265	—	—
1109462	ST63	R501	4265	—	—
1109463	—	R501	4265	—	—
1109464	ST63	R501	4265	—	—
1109465	ST63	R501	4265	—	—
1109471	—	R501	4265	—	—
1109472	ST63	R501	4265	—	—
1109473	ST63	R501	4265	—	—
1109474	—	R501	4265	—	—
1109475	ST63	R501	4265	—	—
1109476	ST63	R501	4265	—	—
1109477	—	R501	4265	—	—
1109478	—	R501	4265	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109479	ST63	R501	4265	—	—
1109481	ST124	R503	—	5336	STK27
1109482	—	R503	—	5336	—
1109483	ST124	R503	—	5336	STK27
1109484	—	R503	—	—	—
1109485	—	R503	—	—	—
1109486	ST124	R503	—	5336	STK27
1109487	ST124	R503	—	5336	STK27
1109488	—	R503	—	5336	—
1109489	ST124	R503	—	5336	STK27
1109490	—	R503	—	5336	—
1109491	—	R503	—	—	—
1109492	—	R503	—	5336	—
1109493	ST132	R519	—	4498	STK21 ³⁰
1109493	ST132	R519	—	4498	STK32 ³¹
1109494	ST132	R519	—	4498	STK21 ³⁰
1109494	ST132	R519	—	4498	STK32 ³¹
1109495	ST128	R509	—	5336	STK28
1109496	ST124	R509	—	—	STK27
1109497	ST132	R519	—	4498	STK21 ³⁰
1109497	ST132	R519	—	4498	STK32 ³¹
1109498	—	R503	—	—	—
1109499	—	R504	—	—	—
1109500	—	R509	—	—	—
1109501	ST51	R501	4265	—	—
1109503	ST63	R501	4265	—	—
1109504	—	R501	—	—	—
1109505	—	R501	—	—	—
1109506	—	R501	—	—	—
1109507	ST51	R501	4265	—	—
1109508	ST51	R501	4265	—	—
1109509	—	R501	—	—	—
1109510	—	R501	—	—	—
1109511	—	R501	—	—	—
1109512	—	R501	—	—	—
1109513	—	R501	—	—	—
1109514	—	R501	4265	—	—
1109517	—	R501	—	—	—
1109518	—	R501	—	—	—
1109519	—	R501	—	—	—
1109521	ST124	R507	—	5288	STK15
1109522	ST124	R507	—	5288	STK27
1109523	ST124	R507	—	5288	STK15
1109524	ST124	R507	—	5288	STK15
1109526	ST124	R507	—	5288	STK15
1109527	—	R507	—	—	—
1109528	ST124	R507	—	5288	STK15
1109530	ST124	R507	—	5288	STK15

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit	Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109531	ST128	R507	—	5288	STK28	1109579	ST124	R503	—	—	STK27
1109532	ST128	R507	—	—	—	1109580	ST124	R503	—	5336	STK27
1109533	ST128	R507	—	5288	STK28	1109581	ST124	R503	—	—	STK27
1109534	ST128	R507	—	—	—	1109582	ST124	R503	—	5336	STK27
1109535	ST128	R507	—	5288	STK28	1109584	ST124	R503	—	—	STK27
1109537	ST128	R507	—	5288	—	1109585	ST124	R503	—	—	STK27
1109538	—	R507	—	—	—	1109586	ST124	R503	—	—	STK27
1109539	—	R504	—	—	—	1109587	ST124	R503	—	—	STK27
1109540	ST124	R504	—	—	STK27	1109588	ST124	R503	—	—	STK27
1109541	—	R504	—	—	—	1109589	ST124	R503	—	—	STK27
1109542	ST124	R504	—	—	STK27	1109591	ST124	R503	—	—	STK27
1109543	—	R504	—	—	—	1109592	ST124	R503	—	5336	STK27
1109544	ST128	R507	—	—	STK28	1109594	ST124	R503	—	—	STK27
1109545	ST131	R519	—	4498	STK20 ³⁰	1109595	ST124	R503	—	—	STK27
1109545	ST131	R519	—	4498	STK31 ³¹	1109596	ST124	R503	—	—	STK27
1109546	—	R507	—	—	—	1109597	ST124	R503	—	5336	STK27
1109547	—	R504	—	—	—	1109598	ST124	R503	—	—	STK27
1109548	—	R504	—	—	—	1109599	ST124	R503	—	—	STK27
1109550	—	R509	—	—	—	1109600	ST500	R501	—	—	—
1109551	ST128	R507	—	—	STK28	1109602	—	R501	4265	—	—
1109552	—	R503	—	—	—	1109603	ST500	R501	4265	—	—
1109553	ST132	R519	—	4498	STK21 ³⁰	1109604	ST500	R501	4265	—	—
1109553	ST132	R519	—	4498	STK32 ³¹	1109605	ST500	R501	4265	—	—
1109554	ST131	R519	—	4498	STK20 ³⁰	1109607	ST63	R501	4265	—	—
1109554	ST131	R519	—	4498	STK31 ³¹	1109608	—	R501	4265	—	—
1109555	ST132	R519	—	4498	STK21 ³⁰	1109609	ST63	R501	4265	—	—
1109555	ST132	R519	—	4498	STK32 ³¹	1109610	ST63	R501	4265	—	—
1109556	ST128	R507	—	—	STK28	1109611	ST500	R501	4265	—	—
1109559	—	R509	—	—	—	1109613	ST500	R501	4265	—	—
1109560	ST128	R507	—	—	STK28	1109614	ST500	R501	4265	—	—
1109561	ST128	R507	—	—	STK28	1109616	—	R501	4265	—	—
1109562	ST128	R507	—	5288	STK28	1109617	ST63	R501	4265	—	—
1109563	ST124	R509	—	4265	STK27	1109618	ST63	R501	4265	—	—
1109564	ST128	R507	—	5288	STK28	1109620	ST63	R501	4265	—	—
1109565	ST124	R509	—	5336	STK27	1109621	—	R501	4265	4265	—
1109566	ST124	R509	—	—	STK27	1109622	—	R501	4265	4265	—
1109567	ST124	R509	—	—	STK27	1109623	ST51	R501	4265	—	—
1109568	ST124	R503	—	—	STK27	1109624	ST132	R519	—	4498	STK21 ³⁰
1109569	ST124	R503	—	—	STK27	1109624	ST132	R519	—	4498	STK32 ³¹
1109570	ST124	R503	—	—	STK27	1109625	ST134	R519	—	4498	—
1109571	ST124	R503	—	—	STK27	1109626	ST134	R519	—	4498	—
1109572	ST124	R503	—	—	STK27	1109627	ST137	R519	—	4498	—
1109573	ST124	R503	—	—	STK27	1109628	ST132	R519	—	4498	STK21 ³⁰
1109574	ST124	R503	—	—	STK27	1109628	ST132	R519	—	4498	STK32 ³¹
1109575	ST124	R503	—	—	STK27	1109629	ST138	R519	—	4498	—
1109576	ST124	R503	—	—	STK27	1109630	ST132	R519	—	4498	STK21 ³⁰
1109577	ST124	R503	—	—	STK27	1109630	ST132	R519	—	4498	STK32 ³¹
1109578	ST124	R503	—	—	STK27	1109631	ST132	R519	—	4498	STK21 ³⁰

(continued on next column)

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109631	ST132	R519	—	4498	STK32 ³¹
1109632	ST132	R519	—	4498	STK21 ³⁰
1109632	ST132	R519	—	4498	STK32 ³¹
1109633	ST132	R519	—	4498	STK21 ³⁰
1109633	ST132	R519	—	4498	STK32 ³¹
1109635	ST132	R519	—	4498	STK21 ³⁰
1109635	ST132	R519	—	4498	STK32 ³¹
1109637	ST132	R519	—	4498	STK21 ³⁰
1109637	ST132	R519	—	4498	STK32 ³¹
1109638	ST132	R519	—	4498	STK21 ³⁰
1109638	ST132	R519	—	4498	STK32 ³¹
1109640	ST132	R519	—	4498	STK21 ³⁰
1109640	ST132	R519	—	4498	STK32 ³¹
1109641	ST132	R519	—	4498	STK21 ³⁰
1109641	ST132	R519	—	4498	STK32 ³¹
1109642	ST132	R519	—	4498	STK21 ³⁰
1109642	ST132	R519	—	4498	STK32 ³¹
1109643	ST132	R519	—	4498	STK21 ³⁰
1109643	ST132	R519	—	4498	STK32 ³¹
1109644	ST132	R519	—	4498	STK21 ³⁰
1109644	ST132	R519	—	4498	STK32 ³¹
1109645	ST132	R519	—	4498	STK21 ³⁰
1109645	ST132	R519	—	4498	STK32 ³¹
1109646	ST132	R519	—	4498	STK21 ³⁰
1109646	ST132	R519	—	4498	STK32 ³¹
1109647	ST132	R519	—	4498	STK21 ³⁰
1109647	ST132	R519	—	4498	STK32 ³¹
1109648	ST132	R519	—	4498	STK21 ³⁰
1109648	ST132	R519	—	4498	STK32 ³¹
1109649	ST132	R519	—	4498	STK21 ³⁰
1109649	ST132	R519	—	4498	STK32 ³¹
1109651	—	R501	—	—	—
1109652	—	R501	4265	—	—
1109654	—	R501	—	—	—
1109655	ST51	R501	4265	—	—
1109656	—	R501	4265	—	—
1109657	—	R501	4265	—	—
1109658	—	R501	4265	—	—
1109659	—	R501	—	—	—
1109660	—	R501	4265	—	—
1109661	ST11	R501	4265	4265	—
1109662	ST11	R501	4265	4265	—
1109664	—	R501	4265	—	—
1109665	—	R501	4265	—	—
1109667	—	R501	—	—	—
1109668	ST63	R501	4265	—	—
1109669	—	R501	4265	—	—
1109673	—	R501	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109674	—	R501	4265	—	—
1109675	—	R501	—	—	—
1109676	ST63	R501	4265	—	—
1109677	—	R501	4265	—	—
1109678	—	R501	4265	—	—
1109679	—	R501	—	—	—
1109680	—	R501	—	—	—
1109681	—	R501	4265	—	—
1109682	—	R501	4265	—	—
1109683	—	R501	—	—	—
1109684	—	R501	4265	—	—
1109685	—	R501	4265	—	—
1109686	—	R501	4265	—	—
1109687	—	R501	—	—	—
1109688	—	R501	—	—	—
1109689	—	R501	—	—	—
1109690	—	R501	—	—	—
1109691	—	R501	4265	—	—
1109692	ST63	R501	4265	—	—
1109694	—	R501	4265	—	—
1109695	—	R501	—	—	—
1109696	—	R501	—	—	—
1109697	—	R501	4265	—	—
1109699	—	R501	4265	—	—
1109700	—	R84	5284	—	—
1109703	—	R84	5284	—	—
1109706	—	R84	5284	—	—
1109708	—	R84	5284	—	—
1109710	—	R84	5284	—	—
1109712	—	R84	5284	—	—
1109714	—	R84	5284	—	—
1109715	—	R84	5284	—	—
1109717	—	R84	5284	—	—
1109718	—	R84	5284	—	—
1109726	—	R84	5284	—	—
1109728	ST134	—	—	—	—
1109729	—	R84	5284	—	—
1109731	—	R84	5284	5288	—
1109732	—	R84	5284	5288	—
1109733	—	R84	5284	5288	—
1109734	—	R84	5284	5288	—
1109739	—	R84	5284	5288	—
1109740	—	R84	5284	5288	—
1109743	—	R84	5284	—	—
1109753	—	R81	4265	—	—
1109755	ST132	R519	—	—	STK21 ³⁰
1109755	ST132	R519	—	—	STK32 ³¹
1109757	ST132	R519	—	—	STK21 ³⁰

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109757	ST132	R519	—	—	STK32 ³¹
1109758	—	R519	—	—	—
1109759	ST132	R519	—	—	STK21 ³⁰
1109759	ST132	R519	—	—	STK32 ³¹
1109762	—	R85	5284	5288	—
1109765	—	R86	5284	—	—
1109768	ST132	R519	—	—	STK21 ³⁰
1109768	ST132	R519	—	—	STK32 ³¹
1109769	ST134	R519	—	—	—
1109771	ST132	R519	—	4483	STK21 ³⁰
1109771	ST132	R519	—	4483	STK32 ³¹
1109772	ST132	R519	—	—	STK21 ³⁰
1109772	ST132	R519	—	—	STK32 ³¹
1109773	ST132	R519	—	—	—
1109774	ST132	R519	—	—	STK21 ³⁰
1109774	ST132	R519	—	—	STK32 ³¹
1109775	ST132	R519	—	—	STK21 ³⁰
1109775	ST132	R519	—	—	STK32 ³¹
1109776	ST132	R519	—	—	STK21 ³⁰
1109776	ST132	R519	—	—	STK32 ³¹
1109777	ST132	R519	—	4498	STK21 ³⁰
1109777	ST132	R519	—	4498	STK32 ³¹
1109779	—	R519	—	4498	—
1109780	ST132	R519	—	4498	—
1109781	ST132	R519	—	4498	STK21 ³⁰
1109781	ST132	R519	—	4498	STK32 ³¹
1109784	—	R81	—	—	—
1109785	—	R81	—	—	—
1109786	—	R81	—	—	—
1109788	ST132	R519	—	4498	STK21 ³⁰
1109788	ST132	R519	—	4498	STK32 ³¹
1109789	ST132	R519	—	4498	STK21 ³⁰
1109789	ST132	R519	—	4498	STK32 ³¹
1109790	ST131	R519	—	4498	STK20 ³⁰
1109790	ST131	R519	—	4498	STK31 ³¹
1109791	ST132	R519	—	—	STK21 ³⁰
1109791	ST132	R519	—	—	STK32 ³¹
1109792	ST132	R519	—	—	STK21 ³⁰
1109792	ST132	R519	—	—	STK32 ³¹
1109793	ST132	R519	—	—	STK21 ³⁰
1109793	ST132	R519	—	—	STK32 ³¹
1109794	ST132	R519	—	—	STK21 ³⁰
1109794	ST132	R519	—	—	STK32 ³¹
1109795	ST132	R519	—	—	STK21 ³⁰
1109795	ST132	R519	—	—	STK32 ³¹
1109796	ST134	R519	—	—	—
1109797	ST134	R519	—	—	—
1109798	ST132	R519	—	—	STK21 ³⁰

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109798	ST132	R519	—	—	STK32 ³¹
1109799	ST132	R519	—	—	STK21 ³⁰
1109799	ST132	R519	—	—	STK32 ³¹
1109800	—	R84	5284	—	—
1109801	—	R84	5284	5288	—
1109802	—	R84	5284	—	—
1109803	—	R84	5284	5288	—
1109804	—	R84	5284	5288	—
1109805	—	R84	5284	5288	—
1109807	—	R84	5284	—	—
1109808	—	R84	5284	—	—
1109809	—	R84	5284	5288	—
1109810	—	R84	5284	—	—
1109811	—	R86	5284	—	—
1109812	—	R84	5284	—	—
1109814	—	R84	5284	—	—
1109815	—	R84	5284	—	—
1109816	—	R84	5284	5288	—
1109817	—	R84	5284	—	—
1109819	—	R84	5284	—	—
1109820	—	R84	5284	—	—
1109822	—	R84	5284	—	—
1109823	—	R84	5284	5288	—
1109824	—	R84	5284	5288	—
1109827	—	R85	5284	—	—
1109828	ST134	R519	—	4498	—
1109829	ST134	R519	—	4498	—
1109830	ST132	R519	—	4498	STK21 ³⁰
1109830	ST132	R519	—	4498	STK32 ³¹
1109831	ST135	R519	—	4498	—
1109832	ST132	R519	—	4498	STK21 ³⁰
1109832	ST132	R519	—	4498	STK32 ³¹
1109833	ST132	R519	—	4498	STK21 ³⁰
1109833	ST132	R519	—	4498	STK32 ³¹
1109834	ST132	R519	—	4498	STK21 ³⁰
1109834	ST132	R519	—	4498	STK32 ³¹
1109835	ST132	R519	—	4498	STK21 ³⁰
1109835	ST132	R519	—	4498	STK32 ³¹
1109836	ST132	R519	—	4498	STK21 ³⁰
1109836	ST132	R519	—	4498	STK32 ³¹
1109837	ST132	R519	—	4498	STK21 ³⁰
1109837	ST132	R519	—	4498	STK32 ³¹
1109838	ST132	R519	—	4498	STK21 ³⁰
1109838	ST132	R519	—	4498	STK32 ³¹
1109839	ST132	R519	—	4498	STK21 ³⁰
1109839	ST132	R519	—	4498	STK32 ³¹
1109840	ST132	R519	—	4498	STK21 ³⁰
1109840	ST132	R519	—	4498	STK32 ³¹

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109841	ST132	R519	—	4498	STK21 ³⁰
1109841	ST132	R519	—	4498	STK32 ³¹
1109842	ST132	R519	—	4498	STK21 ³⁰
1109842	ST132	R519	—	4498	STK32 ³¹
1109844	ST132	R519	—	4498	STK21 ³⁰
1109844	ST132	R519	—	4498	STK32 ³¹
1109845	ST132	R519	—	4498	STK21 ³⁰
1109845	ST132	R519	—	4498	STK32 ³¹
1109846	ST132	R519	—	4498	STK21 ³⁰
1109846	ST132	R519	—	4498	STK32 ³¹
1109847	ST132	R519	—	4498	STK21 ³⁰
1109847	ST132	R519	—	4498	STK32 ³¹
1109848	ST132	R519	—	4498	STK21 ³⁰
1109848	ST132	R519	—	4498	STK32 ³¹
1109849	ST132	R519	—	4498	STK21 ³⁰
1109849	ST132	R519	—	4498	STK32 ³¹
1109852	—	R84	5284	—	—
1109853	—	R84	5284	—	—
1109854	—	R84	5284	—	—
1109861	—	R84	5284	—	—
1109862	—	R84	5284	—	—
1109865	—	R84	5284	—	—
1109866	—	R84	5284	—	—
1109867	—	R84	5284	—	—
1109869	—	R84	5284	—	—
1109872	—	R84	5284	—	—
1109873	—	R84	5284	—	—
1109874	—	R84	5284	5288	—
1109876	—	R84	5284	—	—
1109877	—	R84	5284	5288	—
1109881	—	R84	5284	—	—
1109883	—	R84	5284	—	—
1109885	—	R84	5284	5288	—
1109887	—	R84	5284	5288	—
1109891	—	R84	5284	5288	—
1109893	—	R84	5284	—	—
1109894	—	R84	5284	—	—
1109896	—	R84	5284	5288	—
1109897	—	R84	5284	—	—
1109898	—	R84	5284	—	—
1109899	—	R84	5284	—	—
1109902	—	R514	—	—	—
1109909	—	R514	—	—	—
1109910	—	R1001	5242	—	—
1109914	—	R514	—	—	—
1109915	—	R514	—	—	—
1109917	—	R514	—	—	—
1109918	—	R514	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109919	—	R514	—	—	—
1109923	—	R514	—	—	—
1109926	—	R503	—	—	—
1109930	—	R514	—	5288	—
1109934	—	R514	—	—	—
1109935	—	R503	—	5288	—
1109937	—	R503	—	—	—
1109938	—	R514	—	—	—
1109939	—	R503	—	—	—
1109940	—	R514	—	5289	—
1109943	—	R514	—	5289	—
1109945	—	R514	—	—	—
1109946	ST63	R503	—	—	—
1109948	—	R514	—	5289	—
1109950	—	R81	—	—	—
1109953	—	R81	—	—	—
1109954	—	R81	—	—	—
1109956	—	R81	—	—	—
1109958	—	R81	—	—	—
1109959	—	R81	—	—	—
1109960	—	R81	—	—	—
1109961	ST132	R519	—	4483	STK21 ³⁰
1109961	ST132	R519	—	4483	STK32 ³¹
1109962	ST132	R519	—	4483	STK21 ³⁰
1109962	ST132	R519	—	4483	STK32 ³¹
1109963	ST134	R519	—	4483	—
1109964	ST134	R519	—	4483	—
1109965	ST132	R519	—	4483	STK21 ³⁰
1109965	ST132	R519	—	4483	STK32 ³¹
1109966	ST132	R519	—	4483	STK21 ³⁰
1109966	ST132	R519	—	4483	STK32 ³¹
1109967	—	R81	—	—	—
1109968	ST132	R519	—	4483	STK21 ³⁰
1109968	ST132	R519	—	4483	STK32 ³¹
1109969	ST132	R519	—	4483	STK21 ³⁰
1109969	ST132	R519	—	4483	STK32 ³¹
1109970	ST134	R519	—	4483	—
1109971	ST132	R519	—	4483	STK21 ³⁰
1109971	ST132	R519	—	4483	STK32 ³¹
1109973	—	R519	—	4483	—
1109974	—	R519	—	4483	—
1109975	—	R519	—	4483	—
1109976	—	R81	—	—	—
1109977	ST132	R519	—	4483	STK21 ³⁰
1109977	ST132	R519	—	4483	STK32 ³¹
1109978	ST132	R519	—	4483	STK21 ³⁰
1109978	ST132	R519	—	4483	STK32 ³¹
1109979	ST132	R519	—	4483	STK21 ³⁰

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1109979	ST132	R519	—	4483	STK32 ³¹
1109980	ST134	R519	—	4483	—
1109982	—	R81	—	—	—
1109983	—	R519	—	4483	—
1109984	—	R519	—	4483	—
1109985	ST132	R519	—	4483	STK21 ³⁰
1109985	ST132	R519	—	4483	STK32 ³¹
1109986	ST132	R519	—	4483	STK21 ³⁰
1109986	ST132	R519	—	4483	STK32 ³¹
1109988	—	R519	—	4483	—
1109989	ST132	R519	—	4483	STK21 ³⁰
1109989	ST132	R519	—	4483	STK32 ³¹
1109996	—	R519	—	4483	—
1109998	ST132	R519	—	4483	STK21 ³⁰
1109998	ST132	R519	—	4483	STK32 ³¹
1109999	—	R519	—	4483	—
1111285	—	—	4200	5288	—
1113001	ST113	R504	—	5299	STK26
1113002	ST11	R504	—	—	—
1113003	ST11	R504	—	—	—
1113004	ST33	R504	—	—	—
1113005	ST33	R504	—	—	—
1113006	ST113	R504	—	5299	STK26
1113007	ST11	R504	—	5299	—
1113008	—	R504	—	—	—
1113009	ST500	R504	—	—	—
1113010	—	R504	—	5299	—
1113011	ST500	R504	—	—	—
1113012	ST500	R504	—	—	—
1113014	—	R504	—	—	—
1113015	—	R504	—	—	—
1113016	—	R504	—	—	—
1113017	—	R504	—	—	—
1113018	—	R504	—	—	—
1113019	—	R504	—	—	—
1113020	ST53	R504	—	—	—
1113021	—	R504	—	—	—
1113022	—	R504	—	—	—
1113024	—	R504	—	—	—
1113026	ST53	R504	—	—	—
1113027	ST53	R504	—	—	—
1113029	ST53	R504	—	—	—
1113030	ST63	R504	—	—	—
1113031	—	R504	5284	5284	—
1113034	ST113	R504	—	5299	STK26
1113035	ST11	R504	—	—	—
1113036	—	R504	—	5288	—
1113037	—	R504	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113038	ST113	R504	—	5299	STK26
1113039	—	R504	—	5299	—
1113040	ST113	R504	—	5299	STK26
1113041	ST33	R504	—	—	—
1113042	—	R504	—	—	—
1113044	ST63	R504	—	—	—
1113048	—	R504	—	5299	—
1113049	ST113	R504	—	—	STK26
1113050	ST113	R504	—	5299	STK26
1113051	—	R504	—	—	—
1113052	ST113	R504	—	5299	STK26
1113053	ST113	R504	—	5299	STK26
1113054	ST63	R504	—	—	—
1113055	ST6	R504	—	4498	—
1113056	ST113	R504	—	5299	STK26
1113057	—	R504	—	—	—
1113058	ST11	R504	—	5299	—
1113059	ST113	R504	—	5299	STK26
1113060	ST500	R504	—	—	—
1113061	ST500	R504	4310	—	—
1113062	—	R504	4310	—	—
1113065	—	R504	4310	—	—
1113066	ST113	R504	4310	4286	STK26
1113070	ST113	R504	4310	5299	STK26
1113071	ST11	R504	4310	—	—
1113072	ST51	R504	4310	—	—
1113075	ST113	R504	4310	5299	STK26
1113078	ST500	R504	4310	—	—
1113079	—	R504	—	—	—
1113080	ST500	R504	4310	4483	—
1113081	ST113	R504	4310	5299	STK26
1113082	ST113	R504	4310	5299	STK26
1113083	—	—	4310	—	—
1113084	—	—	4310	5299	—
1113087	ST113	—	4310	5299	STK26
1113088	ST113	R504	4310	5299	STK26
1113089	ST113	R504	—	5299	STK26
1113090	ST113	R504	—	5299	STK26
1113091	ST113	R504	4310	4286	STK26
1113092	ST113	R504	—	—	STK26
1113093	ST113	R504	—	5299	STK26
1113095	ST113	R504	4310	4286	STK26
1113096	—	—	4310	—	—
1113097	ST113	R504	4310	5299	STK26
1113098	ST113	R504	4310	5299	STK26
1113100	ST113	R504	—	5299	STK26
1113101	—	R522	—	5299	—
1113102	—	R504	—	4498	—

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113104	ST113	R504	—	5299	STK26
1113105	—	R522	—	5299	—
1113106	ST113	R504	—	5299	STK26
1113108	ST129	—	—	5299	—
1113109	ST129	—	—	5299	—
1113111	ST113	R504	—	5299	STK26
1113112	ST81	R504	4310	—	—
1113113	—	R522	—	5299	—
1113114	ST113	R504	—	5299	STK26
1113115	—	R522	—	5299	—
1113117	—	R522	—	5299	—
1113118	—	R522	—	5299	—
1113119	ST113	R504	—	5299	STK26
1113121	ST113	R504	—	5299	STK26
1113122	ST53	R504	—	4498	—
1113123	—	R522	—	5299	—
1113124	—	R522	—	5299	—
1113126	ST113	R504	—	5299	STK26
1113128	—	R504	—	5299	—
1113129	—	R504	—	—	—
1113130	ST113	R522	—	5299	STK26
1113131	ST113	R522	—	5299	STK26
1113132	ST113	R504	—	5299	STK26
1113133	—	R522	—	5299	—
1113135	ST115	R522	—	5299	—
1113136	ST113	R504	—	5299	STK26
1113137	—	R522	—	5299	—
1113138	ST113	R504	—	5299	STK26
1113139	ST113	R504	—	5299	STK26
1113142	—	R522	—	5299	—
1113148	ST115	R522	—	5299	—
1113149	ST113	R504	—	5299	STK26
1113150	ST113	R504	—	5299	STK26
1113152	—	R504	—	4483	—
1113153	ST113	R504	—	5299	STK26
1113154	ST113	R504	—	5299	STK26
1113155	ST113	R504	—	5299	STK26
1113156	—	R522	—	5299	—
1113157	—	R522	—	5299	—
1113159	ST113	R504	—	5299	STK26
1113160	ST113	R504	—	5299	STK26
1113161	—	R522	—	5299	—
1113162	—	R522	—	5299	—
1113163	—	R522	—	5299	—
1113164	ST113	R504	—	5299	STK26
1113165	ST113	—	—	5299	STK26
1113167	ST113	R504	—	5299	STK26
1113168	—	R522	—	5299	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113169	ST113	R504	—	5299	STK26
1113171	ST113	R504	—	5299	STK26
1113172	ST113	R504	—	5299	STK26
1113173	—	R522	—	5299	—
1113174	—	R522	—	5299	—
1113176	ST113	R504	—	5299	STK26
1113177	ST113	R504	—	5299	STK26
1113178	ST51	R504	—	4483	—
1113179	ST113	R504	—	5299	STK26
1113182	—	R504	—	5299	—
1113183	ST113	R504	—	5299	STK26
1113184	ST113	R504	—	5299	STK26
1113187	ST113	R504	—	5299	STK26
1113190	ST115	R522	—	5299	—
1113192	ST113	R504	—	5299	STK26
1113193	ST113	R504	—	5299	STK26
1113194	ST113	R504	—	5299	STK26
1113195	ST113	R504	—	5299	STK26
1113196	ST113	R504	—	5299	STK26
1113197	ST113	R504	—	5299	STK26
1113198	ST113	R504	—	5299	STK26
1113200	ST113	R504	—	5299	STK26
1113201	ST113	R504	—	5299	STK26
1113202	ST113	R504	—	5299	STK26
1113203	ST113	R504	—	5299	STK26
1113205	ST115	R522	—	5299	—
1113206	ST113	R504	—	5299	STK26
1113209	ST113	R504	—	5299	STK26
1113210	ST115	R522	—	5299	—
1113212	—	R522	—	5299	—
1113213	ST113	R504	—	5299	STK26
1113215	ST113	R504	—	5299	STK26
1113216	ST113	R504	—	5299	STK26
1113217	ST113	R504	—	5299	STK26
1113218	ST113	R504	—	5299	STK26
1113219	—	R522	—	5299	—
1113220	ST113	R504	—	5299	STK26
1113222	—	R522	—	5299	—
1113223	ST113	R504	—	5299	STK26
1113225	—	R522	—	5299	—
1113228	ST113	R504	—	5299	STK26
1113229	ST113	R504	—	5299	STK26
1113231	ST113	R504	—	5299	STK26
1113232	ST113	R504	—	5299	STK26
1113233	ST113	R504	—	5299	STK26
1113234	ST113	R504	—	5299	STK26
1113235	ST113	R504	—	5299	STK26
1113236	ST113	R504	—	5299	STK26

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113237	ST113	R504	—	5299	STK26
1113242	ST115	R522	—	5299	—
1113243	ST113	R504	—	5299	STK26
1113244	ST129	R522	—	5299	—
1113245	ST113	R504	—	5299	STK26
1113246	—	R522	—	5299	—
1113248	ST129	R522	—	5299	—
1113250	—	R522	—	5299	—
1113253	ST129	—	4310	—	—
1113254	ST129	R522	—	5299	—
1113256	ST129	R522	—	5299	—
1113257	ST129	R522	—	5299	—
1113258	ST129	R522	—	5299	—
1113259	ST129	R522	—	5299	—
1113261	ST129	R522	—	5299	—
1113262	ST129	R522	—	5299	—
1113263	ST129	R522	—	5299	—
1113267	ST151	R503	—	—	—
1113269	ST151	R523	—	5243	—
1113270	ST151	R523	—	5243	—
1113271	ST114	—	—	5243	—
1113272	—	R523	—	5243	—
1113274	ST149	R523	—	5243	—
1113275	ST149	R523	—	5243	—
1113276	ST149	—	—	5243	—
1113277	—	R523	—	5243	—
1113278	ST149	R523	—	5243	—
1113279	ST149	R523	—	5243	—
1113280	ST149	R523	—	5243	—
1113281	ST149	R523	—	5243	—
1113282	ST149	R523	—	5243	—
1113283	ST114	R523	—	5243	—
1113284	ST149	R523	—	—	—
1113285	ST114	R523	—	—	—
1113286	ST149	R523	—	—	—
1113287	ST149	R523	—	—	—
1113288	ST114	R523	—	—	—
1113289	ST149	R523	—	—	—
1113290	ST149	R523	—	—	—
1113292	ST149	R523	—	—	—
1113293	ST149	R523	—	5243	—
1113295	ST151	R523	—	—	—
1113296	ST151	R523	—	—	—
1113297	ST149	R523	—	—	—
1113301	—	R504	—	5288	—
1113302	ST113	R504	—	4286	STK26
1113303	ST113	R504	—	4286	STK26
1113304	ST33	R504	—	4286	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113305	—	R504	—	5288	—
1113306	—	R504	—	5288	—
1113307	—	R504	—	5288	—
1113308	—	R504	—	5288	—
1113309	—	R504	—	5288	—
1113310	—	R504	—	5288	—
1113311	—	R504	—	5288	—
1113312	—	R504	—	5288	—
1113313	—	—	—	5288	—
1113314	—	R504	—	4286	—
1113315	—	R504	—	4286	—
1113316	—	R504	—	5288	—
1113317	—	R504	—	5288	—
1113318	—	R504	—	5288	—
1113319	—	R504	—	5288	—
1113322	—	R504	—	5288	—
1113323	—	R504	—	5288	—
1113327	—	R504	—	5288	—
1113328	—	R504	—	5288	—
1113330	—	R504	—	4483	—
1113331	—	R504	—	5288	—
1113332	—	R504	—	5288	—
1113333	—	R504	—	5288	—
1113334	—	R504	—	—	—
1113335	—	R504	—	—	—
1113336	—	—	—	5288	—
1113338	—	R504	—	—	—
1113339	ST113	R504	—	—	STK26
1113340	—	R504	—	—	—
1113341	—	R504	—	—	—
1113342	—	—	—	5288	—
1113344	—	—	—	5288	—
1113345	ST113	R504	—	—	STK26
1113346	—	R504	—	—	—
1113348	—	—	—	5288	—
1113352	—	R504	—	—	—
1113353	ST132	R522	—	4483	STK21 ³⁰
1113353	ST132	R522	—	4483	STK32 ³¹
1113357	—	R504	—	5288	—
1113358	—	R504	—	5288	—
1113359	—	R504	—	5288	—
1113364	—	R504	—	5288	—
1113366	ST132	R522	—	4483	STK21 ³⁰
1113366	ST132	R522	—	4483	STK32 ³¹
1113367	ST113	R504	—	5299	STK26
1113368	ST113	R504	—	5299	STK26
1113369	—	—	4310	—	—
1113370	ST132	R522	—	4483	STK21 ³⁰

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113370	ST132	R522	—	4483	STK32 ³¹
1113371	—	R522	—	4483	—
1113372	—	R504	—	4483	—
1113373	ST113	R504	—	5299	STK26
1113374	—	—	4310	—	—
1113375	—	R522	—	4483	—
1113376	ST113	R504	—	5299	STK26
1113377	ST113	R504	—	5299	STK26
1113378	ST113	R504	—	4483	STK26
1113379	ST133	R504	—	4483	—
1113380	ST113	R504	—	5299	STK26
1113381	ST113	R504	—	5299	STK26
1113383	ST113	R504	—	5299	STK26
1113384	ST132	R522	—	4483	STK21 ³⁰
1113384	ST132	R522	—	4483	STK32 ³¹
1113385	ST132	R522	—	4483	—
1113386	ST132	R85	—	—	STK21 ³⁰
1113386	ST132	R85	—	—	STK32 ³¹
1113387	ST132	R522	—	4483	—
1113389	—	R86	—	—	—
1113391	ST130	—	—	5299	—
1113392	—	R86	—	—	—
1113393	—	R504	—	4483	—
1113398	—	R504	—	5299	—
1113400	ST130	R504	—	5299	—
1113402	ST113	—	—	5299	STK26
1113403	ST132	R522	—	4483	STK21 ³⁰
1113403	ST132	R522	—	4483	STK32 ³¹
1113405	ST130	R504	—	5299	—
1113406	ST131	R504	—	4483	STK20 ³⁰
1113406	ST131	R504	—	4483	STK31 ³¹
1113407	ST132	R522	—	4483	STK21 ³⁰
1113407	ST132	R522	—	4483	STK32 ³¹
1113408	ST131	—	—	—	STK20 ³⁰
1113408	ST131	—	—	—	STK31 ³¹
1113409	ST113	R504	—	5299	STK26
1113410	ST131	R86	—	4483	STK20 ³⁰
1113410	ST131	R86	—	4483	STK31 ³¹
1113411	ST131	R86	—	—	STK20 ³⁰
1113411	ST131	R86	—	—	STK31 ³¹
1113412	—	R86	—	—	—
1113413	—	R86	—	—	—
1113414	—	R504	—	5299	—
1113415	ST132	R522	—	4498	STK21 ³⁰
1113415	ST132	R522	—	4498	STK32 ³¹
1113416	ST130	R504	—	5299	—
1113417	ST130	R504	—	5299	—
1113418	ST130	R504	—	5299	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113419	—	R86	—	—	—
1113420	ST130	R504	—	5299	—
1113421	ST130	R504	—	5299	—
1113422	ST130	R504	—	5299	—
1113424	ST130	R504	—	5299	—
1113425	—	R86	—	—	—
1113426	ST130	R504	—	5299	—
1113428	ST130	R504	—	5299	—
1113430	—	R86	—	—	—
1113431	ST130	R504	—	5299	—
1113432	ST130	—	—	5299	—
1113433	ST130	R504	—	5299	—
1113434	—	R86	—	—	—
1113435	—	R86	—	—	—
1113436	ST130	R504	—	5299	—
1113437	—	R86	—	—	—
1113439	ST130	R504	—	5299	—
1113440	—	R86	—	—	—
1113441	ST130	R504	—	5299	—
1113442	ST130	R504	—	5299	—
1113443	—	R86	—	—	—
1113444	—	R504	—	5299	—
1113445	ST132	R522	—	4498	STK21 ³⁰
1113445	ST132	R522	—	4498	STK32 ³¹
1113446	ST130	R504	—	5299	—
1113447	—	R86	—	—	—
1113451	—	R504	—	—	—
1113452	—	R504	—	—	—
1113453	—	R504	—	—	—
1113454	ST53	R504	—	4286	—
1113456	ST53	R504	—	4286	—
1113457	—	R504	—	—	—
1113458	—	R504	—	4286	—
1113459	ST63	R504	—	4286	—
1113461	ST63	R504	—	4286	—
1113462	—	R504	—	4286	—
1113463	—	R504	—	4286	—
1113464	ST53	R504	—	4286	—
1113471	—	R504	—	—	—
1113472	—	R504	—	SD1109	—
1113473	ST130	—	—	4498	—
1113474	ST131	—	—	4483	—
1113475	ST131	R504	—	4498	STK20 ³⁰
1113475	ST131	R504	—	4498	STK31 ³¹
1113476	ST130	—	—	5299	—
1113477	—	—	—	4483	—
1113478	—	—	—	5299	—
1113479	ST132	—	—	4483	STK21 ³⁰

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113479	ST132	—	—	4483	STK32 ³¹
1113480	ST131	—	—	4483	—
1113481	ST132	—	—	4498	STK21 ³⁰
1113481	ST132	—	—	4498	STK32 ³¹
1113483	ST132	—	—	4498	—
1113484	—	—	—	5299	—
1113485	ST132	—	—	4498	—
1113486	ST132	—	—	4498	STK21 ³⁰
1113486	ST132	—	—	4498	STK32 ³¹
1113487	—	—	—	4498	—
1113488	—	—	—	5299	—
1113489	—	—	—	5299	—
1113490	—	—	—	5299	—
1113493	—	—	—	5299	—
1113494	ST130	R504	—	5299	—
1113495	—	R504	—	5299	—
1113496	—	R504	—	5299	—
1113497	—	—	—	5299	—
1113498	ST130	R504	—	5299	—
1113499	ST130	—	—	5299	—
1113500	ST131	R504	—	4498	STK20 ³⁰
1113500	ST131	R504	—	4498	STK31 ³¹
1113523	—	—	—	5288	—
1113532	ST131	R504	—	4498	STK20 ³⁰
1113532	ST131	R504	—	4498	STK31 ³¹
1113533	ST132	R522	—	4498	STK21 ³⁰
1113533	ST132	R522	—	4498	STK32 ³¹
1113534	ST132	R522	—	4498	STK21 ³⁰
1113534	ST132	R522	—	4498	STK32 ³¹
1113535	ST132	R522	—	4498	STK21 ³⁰
1113535	ST132	R522	—	4498	STK32 ³¹
1113536	ST132	R522	—	4498	STK21 ³⁰
1113536	ST132	R522	—	4498	STK32 ³¹
1113537	ST131	R86	—	—	STK20 ³⁰
1113537	ST131	R86	—	—	STK31 ³¹
1113538	ST131	R86	—	—	STK20 ³⁰
1113538	ST131	R86	—	—	STK31 ³¹
1113539	ST132	R85	—	—	STK21 ³⁰
1113539	ST132	R85	—	—	STK32 ³¹
1113540	ST132	R85	—	—	STK21 ³⁰
1113540	ST132	R85	—	—	STK32 ³¹
1113541	ST132	R522	—	4498	STK21 ³⁰
1113541	ST132	R522	—	4498	STK32 ³¹
1113542	ST132	R85	—	—	STK21 ³⁰
1113542	ST132	R85	—	—	STK32 ³¹
1113543	ST131	R504	—	4498	STK20 ³⁰
1113543	ST131	R504	—	4498	STK31 ³¹
1113544	ST132	R85	—	—	STK21 ³⁰

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113544	ST132	R85	—	—	STK32 ³¹
1113545	ST132	R522	—	4498	STK21 ³⁰
1113545	ST132	R522	—	4498	STK32 ³¹
1113546	ST135	R522	—	4498	—
1113547	ST131	R86	—	—	STK20 ³⁰
1113547	ST131	R86	—	—	STK31 ³¹
1113548	—	R86	—	—	—
1113582	—	R86	—	—	—
1113583	ST132	R85	—	—	STK21 ³⁰
1113583	ST132	R85	—	—	STK32 ³¹
1113584	ST132	R522	—	4498	STK21 ³⁰
1113584	ST132	R522	—	4498	STK32 ³¹
1113585	ST132	R85	—	—	STK21 ³⁰
1113585	ST132	R85	—	—	STK32 ³¹
1113586	—	—	—	5299	—
1113587	ST135	R522	—	4498	—
1113589	ST124	R509	—	4265	STK15
1113590	—	—	—	4265	—
1113591	ST335	—	—	4265	—
1113593	ST128	—	—	—	—
1113594	ST335	—	—	—	—
1113597	ST128	R509	—	—	—
1113598	—	R509	—	—	—
1113599	ST128	R509	—	—	—
1113600	ST335	—	—	—	—
1113601	—	R504	—	5288	—
1113602	—	R504	—	5288	—
1113603	—	R504	—	5288	—
1113604	—	R504	—	5284	—
1113605	—	R504	—	5288	—
1113606	—	R504	—	5288	—
1113607	—	R504	—	5288	—
1113608	—	R504	—	5288	—
1113609	—	R504	—	5288	—
1113610	—	R504	—	—	—
1113611	—	R504	—	—	—
1113612	—	R504	—	5288	—
1113613	—	R504	—	5284	—
1113614	—	R504	—	4286	—
1113615	—	R504	—	4286	—
1113616	—	R504	—	5288	—
1113617	—	R504	—	5288	—
1113618	—	R504	—	5288	—
1113619	—	R504	—	5288	—
1113620	—	R504	—	5288	—
1113621	—	R504	—	5288	—
1113622	—	R504	—	4286	—
1113623	—	R504	—	4286	—

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113624	—	R504	—	4286	—
1113625	—	R504	—	4286	—
1113626	ST113	R504	—	5299	STK26
1113628	—	R504	4310	5288	—
1113631	ST131	R504	—	4483	STK20 ³⁰
1113631	ST131	R504	—	4483	STK31 ³¹
1113633	ST113	R504	—	5299	STK26
1113634	ST113	R504	—	5299	STK26
1113635	ST113	R504	—	5299	STK26
1113636	ST113	R504	—	5299	STK26
1113637	ST113	R504	—	5299	STK26
1113638	ST131	R504	—	4483	STK20 ³⁰
1113638	ST131	R504	—	4483	STK31 ³¹
1113639	ST113	R504	—	5299	STK26
1113640	ST113	R504	—	5299	STK26
1113641	ST113	R504	—	5299	STK26
1113642	ST113	R504	—	5299	STK26
1113643	ST131	R504	—	4483	STK20 ³⁰
1113643	ST131	R504	—	4483	STK31 ³¹
1113644	ST113	R504	—	5299	STK26
1113645	ST131	R504	—	4483	STK20 ³⁰
1113645	ST131	R504	—	4483	STK31 ³¹
1113646	ST113	R504	—	5299	STK26
1113647	ST113	R504	—	5299	STK26
1113648	ST113	R504	—	5299	STK26
1113650	ST113	R504	—	5299	STK26
1113651	ST113	R504	—	5299	STK26
1113652	ST113	R504	—	5299	STK26
1113653	ST113	R504	—	5299	STK26
1113654	ST113	R504	—	5299	STK26
1113655	ST113	R504	—	5299	STK26
1113656	ST113	R504	—	5299	STK26
1113657	ST113	R504	—	5299	STK26
1113658	ST131	—	—	4483	STK20 ³⁰
1113658	ST131	—	—	4483	STK31 ³¹
1113659	ST113	—	—	5299	STK26
1113660	ST113	—	—	5299	STK26
1113661	ST113	R504	—	5299	STK26
1113662	ST113	—	—	5299	STK26
1113663	ST113	R504	—	5299	STK26
1113664	—	—	—	4483	—
1113665	ST113	R504	—	5299	STK26
1113667	ST113	—	—	5299	STK26
1113668	ST113	R504	—	—	STK26
1113669	—	—	—	4483	—
1113670	—	—	—	4483	—
1113672	ST113	—	—	5299	STK26
1113673	ST113	R504	—	—	STK26

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113674	ST131	R86	—	4483	STK20 ³⁰
1113674	ST131	R86	—	4483	STK31 ³¹
1113675	—	R86	—	5299	—
1113676	ST113	—	—	5299	STK26
1113678	ST131	R86	—	4483	STK20 ³⁰
1113678	ST131	R86	—	4483	STK31 ³¹
1113680	ST113	R504	—	5299	STK26
1113681	—	R86	—	5299	—
1113682	—	R86	—	5299	—
1113683	ST113	—	—	5299	STK26
1113684	—	R86	—	5299	—
1113685	ST113	R504	—	5299	STK26
1113686	ST116	R86	—	5299	—
1113687	—	R86	—	5299	—
1113688	ST113	R504	—	5299	STK26
1113689	—	R86	—	5299	—
1113690	ST113	R504	—	—	STK26
1113691	ST131	R86	—	4483	STK20 ³⁰
1113691	ST131	R86	—	4483	STK31 ³¹
1113693	ST131	R86	—	4483	STK20 ³⁰
1113693	ST131	R86	—	4483	STK31 ³¹
1113695	ST113	R504	—	5299	STK26
1113696	ST113	R504	—	5299	STK26
1113697	ST113	—	—	5299	STK26
1113698	—	R86	—	5299	—
1113699	—	R86	—	5299	—
1113700	—	R84	5284	—	—
1113702	—	R84	5284	—	—
1113703	—	R84	5284	—	—
1113704	—	R84	5284	—	—
1113705	—	R84	5284	—	—
1113706	—	R84	5284	—	—
1113707	—	R84	5284	—	—
1113708	—	R84	5284	—	—
1113709	—	R84	5284	—	—
1113710	—	R84	5284	—	—
1113711	—	R84	5284	5288	—
1113712	—	R84	5284	—	—
1113713	—	R84	5284	—	—
1113714	—	R84	5284	—	—
1113715	—	R84	5284	—	—
1113716	—	R84	5284	—	—
1113717	—	R84	5284	—	—
1113718	—	R84	5284	—	—
1113719	—	R84	5284	—	—
1113720	—	R84	5284	—	—
1113721	—	R84	5284	—	—
1113722	—	R84	5284	—	—

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113727	—	R84	5284	—	—
1113729	—	R84	5284	—	—
1113734	—	R84	—	—	—
1113735	—	R84	—	—	—
1113737	—	R84	—	—	—
1113739	—	R84	—	5288	—
1113741	—	R84	—	—	—
1113742	—	R84	—	5288	—
1113743	—	R84	—	—	—
1113745	—	R84	—	—	—
1113746	—	R84	—	—	—
1113747	—	—	—	5288	—
1113748	—	R84	—	—	—
1113749	—	R84	—	—	—
1113751	—	R84	—	5288	—
1113752	—	R84	—	—	—
1113753	—	R84	—	—	—
1113754	—	R84	—	—	—
1113755	—	R84	—	—	—
1113756	—	R84	—	—	—
1113758	—	R84	—	—	—
1113760	—	R84	—	—	—
1113761	—	R84	—	5288	—
1113762	—	R84	—	5288	—
1113763	—	R84	—	5288	—
1113765	—	R84	—	5288	—
1113766	—	R84	—	5288	—
1113767	—	R84	—	—	—
1113768	—	R84	—	—	—
1113769	—	R84	—	—	—
1113770	—	R84	—	5288	—
1113771	—	R84	—	—	—
1113772	—	R84	—	5288	—
1113773	—	R84	—	5288	—
1113774	—	R84	—	5288	—
1113775	—	R84	—	5288	—
1113776	—	R84	—	—	—
1113777	—	R84	—	—	—
1113778	—	R84	—	—	—
1113779	—	R84	—	—	—
1113780	—	R84	—	—	—
1113781	—	R84	—	—	—
1113782	—	R84	—	—	—
1113783	—	R84	—	5288	—
1113784	—	R84	—	5288	—
1113785	—	R84	—	5288	—
1113787	—	R84	—	—	—
1113788	—	R84	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113789	—	R84	—	—	—
1113797	—	R84	5284	5288	—
1113800	—	R84	5284	5288	—
1113801	—	R84	5284	—	—
1113803	—	R84	5284	—	—
1113804	—	R84	5284	—	—
1113806	—	R84	5284	—	—
1113807	—	R84	5284	—	—
1113808	—	R84	5284	—	—
1113810	—	R84	5284	5288	—
1113811	—	R84	5284	—	—
1113812	—	R84	5284	—	—
1113814	—	R84	5284	5288	—
1113815	—	R84	5284	—	—
1113817	—	R84	5284	—	—
1113818	ST132	R85	5284	4483	STK21 ³⁰
1113818	ST132	R85	5284	4483	STK32 ³¹
1113820	ST132	R85	5284	4483	STK21 ³⁰
1113820	ST132	R85	5284	4483	STK32 ³¹
1113823	—	R84	5284	5288	—
1113824	ST132	R85	5284	4483	STK21 ³⁰
1113824	ST132	R85	5284	4483	STK32 ³¹
1113825	ST132	R85	5284	4483	STK21 ³⁰
1113825	ST132	R85	5284	4483	STK32 ³¹
1113827	ST132	R85	5284	4483	STK21 ³⁰
1113827	ST132	R85	5284	4483	STK32 ³¹
1113828	—	R84	5284	5288	—
1113830	ST132	R85	5284	4483	STK21 ³⁰
1113830	ST132	R85	5284	4483	STK32 ³¹
1113831	ST132	R85	5284	4483	STK21 ³⁰
1113831	ST132	R85	5284	4483	STK32 ³¹
1113832	ST132	R85	5284	4483	STK21 ³⁰
1113832	ST132	R85	5284	4483	STK32 ³¹
1113834	—	R84	5284	5288	—
1113837	—	R84	5284	—	—
1113838	—	R84	5284	—	—
1113840	ST132	R85	5284	4483	STK21 ³⁰
1113840	ST132	R85	5284	4483	STK32 ³¹
1113842	ST132	R85	5284	4483	STK21 ³⁰
1113842	ST132	R85	5284	4483	STK32 ³¹
1113845	ST132	R85	5284	4483	STK21 ³⁰
1113845	ST132	R85	5284	4483	STK32 ³¹
1113846	ST132	R85	5284	4483	STK21 ³⁰
1113846	ST132	R85	5284	4483	STK32 ³¹
1113847	ST132	R85	—	—	STK21 ³⁰
1113847	ST132	R85	—	—	STK32 ³¹
1113849	ST132	R85	5284	4483	STK21 ³⁰
1113849	ST132	R85	5284	4483	STK32 ³¹

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113850	ST132	R85	5284	4483	STK21 ³⁰
1113850	ST132	R85	5284	4483	STK32 ³¹
1113851	ST132	R85	5284	4483	STK21 ³⁰
1113851	ST132	R85	5284	4483	STK32 ³¹
1113852	ST132	R85	5284	4483	STK21 ³⁰
1113852	ST132	R85	5284	4483	STK32 ³¹
1113853	ST132	R85	5284	4483	STK21 ³⁰
1113853	ST132	R85	5284	4483	STK32 ³¹
1113855	ST132	R85	5284	4483	STK21 ³⁰
1113855	ST132	R85	5284	4483	STK32 ³¹
1113856	ST132	R85	5284	4483	STK21 ³⁰
1113856	ST132	R85	5284	4483	STK32 ³¹
1113857	ST132	R85	5284	4483	STK21 ³⁰
1113857	ST132	R85	5284	4483	STK32 ³¹
1113858	ST132	R85	5284	4483	STK21 ³⁰
1113858	ST132	R85	5284	4483	STK32 ³¹
1113859	ST134	R85	5284	4483	—
1113864	ST132	R85	5284	4483	STK21 ³⁰
1113864	ST132	R85	5284	4483	STK32 ³¹
1113865	—	R85	5284	4483	—
1113866	—	R85	5284	4483	—
1113867	ST132	R85	5284	4483	STK21 ³⁰
1113867	ST132	R85	5284	4483	STK32 ³¹
1113870	—	R85	5284	4483	—
1113871	—	R85	5284	4483	—
1113872	ST132	R85	5284	4483	STK21 ³⁰
1113872	ST132	R85	5284	4483	STK32 ³¹
1113873	ST132	R85	5284	4483	STK21 ³⁰
1113873	ST132	R85	5284	4483	STK32 ³¹
1113874	ST132	R85	5284	4483	STK21 ³⁰
1113874	ST132	R85	5284	4483	STK32 ³¹
1113875	ST132	R85	5284	4483	STK21 ³⁰
1113875	ST132	R85	5284	4483	STK32 ³¹
1113876	ST132	R85	5284	4483	STK21 ³⁰
1113876	ST132	R85	5284	4483	STK32 ³¹
1113877	ST134	R85	5284	4483	—
1113878	—	R85	—	—	—
1113879	ST132	R85	5284	4483	STK21 ³⁰
1113879	ST132	R85	5284	4483	STK32 ³¹
1113880	ST132	R85	5284	4483	STK21 ³⁰
1113880	ST132	R85	5284	4483	STK32 ³¹
1113881	ST132	R85	5284	4483	STK21 ³⁰
1113881	ST132	R85	5284	4483	STK32 ³¹
1113882	ST132	R85	5284	4483	STK21 ³⁰
1113882	ST132	R85	5284	4483	STK32 ³¹
1113883	ST132	R85	5284	4483	STK21 ³⁰
1113883	ST132	R85	5284	4483	STK32 ³¹
1113884	—	R85	5284	4483	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113885	—	R84	5284	—	—
1113887	ST132	R85	5284	4483	STK21 ³⁰
1113887	ST132	R85	5284	4483	STK32 ³¹
1113888	ST132	R85	5284	4483	STK21 ³⁰
1113888	ST132	R85	5284	4483	STK32 ³¹
1113889	ST134	R85	5284	4483	—
1113892	ST132	R85	5284	4483	STK21 ³⁰
1113892	ST132	R85	5284	4483	STK32 ³¹
1113895	ST132	R85	5284	4483	STK21 ³⁰
1113895	ST132	R85	5284	4483	STK32 ³¹
1113898	ST132	R85	5284	4483	STK21 ³⁰
1113898	ST132	R85	5284	4483	STK32 ³¹
1113899	ST134	R85	5284	4483	—
1113900	ST132	R85	5284	4483	STK21 ³⁰
1113900	ST132	R85	5284	4483	STK32 ³¹
1113902	ST132	R85	5284	4483	STK21 ³⁰
1113902	ST132	R85	5284	4483	STK32 ³¹
1113905	ST132	R85	5284	4483	STK21 ³⁰
1113905	ST132	R85	5284	4483	STK32 ³¹
1113906	ST132	R85	5284	4483	STK21 ³⁰
1113906	ST132	R85	5284	4483	STK32 ³¹
1113907	ST132	R85	5284	4483	STK21 ³⁰
1113907	ST132	R85	5284	4483	STK32 ³¹
1113908	ST134	R85	5284	4483	—
1113909	—	R85	5284	4483	—
1113910	ST132	R85	5284	4483	STK21 ³⁰
1113910	ST132	R85	5284	4483	STK32 ³¹
1113911	ST134	R85	5284	4483	—
1113912	—	R84	5284	5288	—
1113913	—	R84	5284	5288	—
1113914	ST132	R85	5284	4483	STK21 ³⁰
1113914	ST132	R85	5284	4483	STK32 ³¹
1113915	ST132	R85	5284	4483	STK21 ³⁰
1113915	ST132	R85	5284	4483	STK32 ³¹
1113916	ST132	R85	5284	4483	STK21 ³⁰
1113916	ST132	R85	5284	4483	STK32 ³¹
1113917	ST132	R85	5284	4483	STK21 ³⁰
1113917	ST132	R85	5284	4483	STK32 ³¹
1113918	ST132	R85	5284	4483	STK21 ³⁰
1113918	ST132	R85	5284	4483	STK32 ³¹
1113920	ST132	R85	5284	4483	STK21 ³⁰
1113920	ST132	R85	5284	4483	STK32 ³¹
1113921	ST134	R85	5284	4483	—
1113923	ST132	R85	5284	4483	STK21 ³⁰
1113923	ST132	R85	5284	4483	STK32 ³¹
1113926	ST132	R85	5284	4483	STK21 ³⁰
1113926	ST132	R85	5284	4483	STK32 ³¹
1113927	ST134	R85	5284	4483	—

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113928	ST132	R85	5284	4483	STK21 ³⁰
1113928	ST132	R85	5284	4483	STK32 ³¹
1113931	ST131	R85	5284	4483	STK20 ³⁰
1113931	ST131	R85	5284	4483	STK31 ³¹
1113935	ST132	R85	5284	4483	STK21 ³⁰
1113935	ST132	R85	5284	4483	STK32 ³¹
1113936	ST132	R85	5284	4483	STK21 ³⁰
1113936	ST132	R85	5284	4483	STK32 ³¹
1113937	ST134	R85	5284	4483	—
1113938	ST132	R85	5284	4483	STK21 ³⁰
1113938	ST132	R85	5284	4483	STK32 ³¹
1113939	ST134	R85	5284	4483	—
1113941	ST132	R85	5284	4483	STK21 ³⁰
1113941	ST132	R85	5284	4483	STK32 ³¹
1113942	ST132	R85	5284	4483	STK21 ³⁰
1113942	ST132	R85	5284	4483	STK32 ³¹
1113945	ST134	R85	5284	4483	—
1113946	—	R84	5284	—	—
1113947	ST132	R85	5284	4483	STK21 ³⁰
1113947	ST132	R85	5284	4483	STK32 ³¹
1113948	ST132	R85	5284	4483	STK21 ³⁰
1113948	ST132	R85	5284	4483	STK32 ³¹
1113949	ST132	R85	5284	4483	STK21 ³⁰
1113949	ST132	R85	5284	4483	STK32 ³¹
1113950	ST132	R85	5284	4483	STK21 ³⁰
1113950	ST132	R85	5284	4483	STK32 ³¹
1113951	ST132	R85	5284	4483	STK21 ³⁰
1113951	ST132	R85	5284	4483	STK32 ³¹
1113952	ST132	R85	5284	4483	STK21 ³⁰
1113952	ST132	R85	5284	4483	STK32 ³¹
1113953	—	R85	5284	4483	—
1113954	ST134	R85	5284	4483	—
1113955	ST132	R85	5284	4483	STK21 ³⁰
1113955	ST132	R85	5284	4483	STK32 ³¹
1113956	ST132	R85	5284	4483	STK21 ³⁰
1113956	ST132	R85	5284	4483	STK32 ³¹
1113957	ST132	R85	5284	4483	STK21 ³⁰
1113957	ST132	R85	5284	4483	STK32 ³¹
1113958	ST132	R85	5284	4483	STK21 ³⁰
1113958	ST132	R85	5284	4483	STK32 ³¹
1113959	ST132	R85	5284	4483	STK21 ³⁰
1113959	ST132	R85	5284	4483	STK32 ³¹
1113960	ST132	R85	5284	4483	STK21 ³⁰
1113960	ST132	R85	5284	4483	STK32 ³¹
1113961	ST132	R85	5284	4483	STK21 ³⁰
1113961	ST132	R85	5284	4483	STK32 ³¹
1113962	ST132	R85	5284	4483	STK21 ³⁰
1113962	ST132	R85	5284	4483	STK32 ³¹

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113963	ST134	R85	5284	4483	—
1113964	ST134	R85	5284	4483	—
1113965	ST132	R85	5284	4483	STK21 ³⁰
1113965	ST132	R85	5284	4483	STK32 ³¹
1113966	ST132	R85	5284	4483	STK21 ³⁰
1113966	ST132	R85	5284	4483	STK32 ³¹
1113967	ST132	R85	5284	4483	STK21 ³⁰
1113967	ST132	R85	5284	4483	STK32 ³¹
1113968	ST132	R85	5284	4483	STK21 ³⁰
1113968	ST132	R85	5284	4483	STK32 ³¹
1113969	ST132	R85	5284	4483	STK21 ³⁰
1113969	ST132	R85	5284	4483	STK32 ³¹
1113970	ST132	R85	5284	4483	STK21 ³⁰
1113970	ST132	R85	5284	4483	STK32 ³¹
1113971	ST132	R85	5284	4483	STK21 ³⁰
1113971	ST132	R85	5284	4483	STK32 ³¹
1113972	ST132	R85	5284	4483	STK21 ³⁰
1113972	ST132	R85	5284	4483	STK32 ³¹
1113973	ST132	R85	5284	4483	STK21 ³⁰
1113973	ST132	R85	5284	4483	STK32 ³¹
1113974	ST132	R85	5284	4483	STK21 ³⁰
1113974	ST132	R85	5284	4483	STK32 ³¹
1113975	ST132	R85	5284	4483	STK21 ³⁰
1113975	ST132	R85	5284	4483	STK32 ³¹
1113976	ST132	R85	5284	4483	STK21 ³⁰
1113976	ST132	R85	5284	4483	STK32 ³¹
1113977	ST132	R85	5284	4483	STK21 ³⁰
1113977	ST132	R85	5284	4483	STK32 ³¹
1113978	ST132	R85	5284	4483	STK21 ³⁰
1113978	ST132	R85	5284	4483	STK32 ³¹
1113979	ST134	R85	5284	4483	—
1113980	ST132	R85	5284	4483	STK21 ³⁰
1113980	ST132	R85	5284	4483	STK32 ³¹
1113981	ST134	R85	5284	4483	—
1113982	ST134	R85	5284	4483	—
1113983	ST134	R85	5284	4483	—
1113984	—	R85	5284	4483	—
1113986	ST132	R85	5284	4483	STK21 ³⁰
1113986	ST132	R85	5284	4483	STK32 ³¹
1113988	ST132	R85	5284	4483	STK21 ³⁰
1113988	ST132	R85	5284	4483	STK32 ³¹
1113990	ST132	R85	5284	4483	STK21 ³⁰
1113990	ST132	R85	5284	4483	STK32 ³¹
1113991	ST132	R85	5284	4483	STK21 ³⁰
1113991	ST132	R85	5284	4483	STK32 ³¹
1113992	ST132	R85	5284	4483	STK21 ³⁰
1113992	ST132	R85	5284	4483	STK32 ³¹
1113993	ST132	R85	5284	4483	STK21 ³⁰

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1113993	ST132	R85	5284	4483	STK32 ³¹
1113994	ST132	R85	5284	4483	STK21 ³⁰
1113994	ST132	R85	5284	4483	STK32 ³¹
1113995	ST132	R85	5284	4483	STK21 ³⁰
1113995	ST132	R85	5284	4483	STK32 ³¹
1113997	ST132	R85	5284	4483	STK21 ³⁰
1113997	ST132	R85	5284	4483	STK32 ³¹
1113998	ST132	R85	—	4483	STK21 ³⁰
1113998	ST132	R85	—	4483	STK32 ³¹
1113999	ST132	R85	—	4483	STK21 ³⁰
1113999	ST132	R85	—	4483	STK32 ³¹
1114000	—	R86	5284	5288	—
1114001	—	R84	5284	4483	—
1114002	—	R84	5284	4483	—
1114003	—	R84	5284	4483	—
1114004	—	R84	5284	4483	—
1114005	—	R84	5284	4483	—
1114006	—	R84	5284	4483	—
1114007	—	R84	5284	4483	—
1114008	—	R84	5284	4483	—
1114009	—	R86	5284	4483	—
1114010	—	R84	5284	5288	—
1114011	—	R84	5284	4483	—
1114012	—	R84	5284	4483	—
1114013	—	R84	5284	4483	—
1114014	—	R84	5284	4483	—
1114015	—	R84	5284	4483	—
1114016	—	R84	5284	—	—
1114017	—	R84	5284	—	—
1114018	—	R84	5284	4483	—
1114019	—	R84	5284	4483	—
1114020	—	R84	5284	4483	—
1114021	—	R84	5284	4483	—
1114022	—	R84	5284	4483	—
1114023	—	R84	5284	5288	—
1114024	—	R84	5284	5288	—
1114025	—	R84	5284	4483	—
1114026	—	R84	5284	4483	—
1114027	—	R84	5284	4483	—
1114028	—	R84	5284	5288	—
1114029	—	R84	5284	4483	—
1114032	—	R84	5284	5288	—
1114033	—	R84	5284	5288	—
1114034	—	R84	5284	5288	—
1114035	—	R84	5284	5288	—
1114036	—	R84	5284	5288	—
1114040	—	R84	5284	—	—
1114041	—	R84	5284	5288	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114042	—	R84	5284	5288	—
1114043	—	R84	5284	5288	—
1114044	—	R84	5284	5288	—
1114045	—	R84	5284	5288	—
1114046	—	R84	5284	5288	—
1114047	—	R85	5284	4483	—
1114048	—	R84	5284	—	—
1114049	—	R84	5284	5288	—
1114051	ST131	R85	5284	4483	STK20 ³⁰
1114051	ST131	R85	5284	4483	STK31 ³¹
1114052	ST131	R85	5284	4483	STK20 ³⁰
1114052	ST131	R85	5284	4483	STK31 ³¹
1114053	—	R84	5284	—	—
1114054	ST131	R85	5284	4483	STK20 ³⁰
1114054	ST131	R85	5284	4483	STK31 ³¹
1114055	ST131	R86	5284	4483	STK20 ³⁰
1114055	ST131	R86	5284	4483	STK31 ³¹
1114056	ST131	R85	5284	4483	STK20 ³⁰
1114056	ST131	R85	5284	4483	STK31 ³¹
1114057	ST131	R85	5284	4483	STK20 ³⁰
1114057	ST131	R85	5284	4483	STK31 ³¹
1114058	ST131	R86	5284	4483	STK20 ³⁰
1114058	ST131	R86	5284	4483	STK31 ³¹
1114059	ST131	R86	5284	4483	STK20 ³⁰
1114059	ST131	R86	5284	4483	STK31 ³¹
1114060	—	R86	5284	—	—
1114061	ST131	R85	5284	4483	STK20 ³⁰
1114061	ST131	R85	5284	4483	STK31 ³¹
1114062	ST131	R86	5284	4483	STK20 ³⁰
1114062	ST131	R86	5284	4483	STK31 ³¹
1114063	ST131	R86	5284	4483	STK20 ³⁰
1114063	ST131	R86	5284	4483	STK31 ³¹
1114064	ST131	R86	5284	4483	STK20 ³⁰
1114064	ST131	R86	5284	4483	STK31 ³¹
1114065	ST131	R86	5284	4483	STK20 ³⁰
1114065	ST131	R86	5284	4483	STK31 ³¹
1114066	ST131	R86	5284	4483	STK20 ³⁰
1114066	ST131	R86	5284	4483	STK31 ³¹
1114067	ST131	R86	5284	4483	STK20 ³⁰
1114067	ST131	R86	5284	4483	STK31 ³¹
1114068	—	R86	5284	—	—
1114069	ST131	R85	5284	4483	STK20 ³⁰
1114069	ST131	R85	5284	4483	STK31 ³¹
1114070	ST131	—	5284	4483	STK20 ³⁰
1114070	ST131	—	5284	4483	STK31 ³¹
1114071	ST131	R85	5284	4483	STK20 ³⁰
1114071	ST131	R85	5284	4483	STK31 ³¹
1114072	ST131	R86	5284	4483	STK20 ³⁰

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114072	ST131	R86	5284	4483	STK31 ³¹
1114073	ST131	R85	5284	4483	STK20 ³⁰
1114073	ST131	R85	5284	4483	STK31 ³¹
1114074	ST131	R86	5284	4483	STK20 ³⁰
1114074	ST131	R86	5284	4483	STK31 ³¹
1114075	ST131	R86	5284	4483	STK20 ³⁰
1114075	ST131	R86	5284	4483	STK31 ³¹
1114076	ST131	R86	5284	4483	STK20 ³⁰
1114076	ST131	R86	5284	4483	STK31 ³¹
1114077	ST131	R85	5284	4483	STK20 ³⁰
1114077	ST131	R85	5284	4483	STK31 ³¹
1114078	ST131	R85	5284	4483	STK20 ³⁰
1114078	ST131	R85	5284	4483	STK31 ³¹
1114079	ST131	R85	5284	4483	STK20 ³⁰
1114079	ST131	R85	5284	4483	STK31 ³¹
1114080	ST131	R85	5284	4483	STK20 ³⁰
1114080	ST131	R85	5284	4483	STK31 ³¹
1114081	ST131	R85	5284	4483	STK20 ³⁰
1114081	ST131	R85	5284	4483	STK31 ³¹
1114082	ST131	R85	5284	4483	STK20 ³⁰
1114082	ST131	R85	5284	4483	STK31 ³¹
1114083	ST131	R85	5284	4483	STK20 ³⁰
1114083	ST131	R85	5284	4483	STK31 ³¹
1114084	ST131	R85	5284	4483	STK20 ³⁰
1114084	ST131	R85	5284	4483	STK31 ³¹
1114085	ST131	R85	5284	4483	STK20 ³⁰
1114085	ST131	R85	5284	4483	STK31 ³¹
1114086	ST131	R85	5284	4483	STK20 ³⁰
1114086	ST131	R85	5284	4483	STK31 ³¹
1114087	ST133	R86	5284	4483	—
1114088	ST131	R86	5284	4483	STK20 ³⁰
1114088	ST131	R86	5284	4483	STK31 ³¹
1114089	—	R84	5284	5288	—
1114090	ST131	R86	5284	4483	STK20 ³⁰
1114090	ST131	R86	5284	4483	STK31 ³¹
1114091	ST131	R86	5284	4483	STK20 ³⁰
1114091	ST131	R86	5284	4483	STK31 ³¹
1114092	ST131	R85	5284	4483	STK20 ³⁰
1114092	ST131	R85	5284	4483	STK31 ³¹
1114093	ST131	R86	5284	4483	STK20 ³⁰
1114093	ST131	R86	5284	4483	STK31 ³¹
1114094	ST131	R85	5284	4483	STK20 ³⁰
1114094	ST131	R85	5284	4483	STK31 ³¹
1114095	ST131	R85	5284	4483	STK20 ³⁰
1114095	ST131	R85	5284	4483	STK31 ³¹
1114096	ST131	R85	5284	4483	STK20 ³⁰
1114096	ST131	R85	5284	4483	STK31 ³¹
1114097	ST131	R85	5284	4483	STK20 ³⁰

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114097	ST131	R85	5284	4483	STK31 ³¹
1114098	ST131	R86	5284	4483	STK20 ³⁰
1114098	ST131	R86	5284	4483	STK31 ³¹
1114099	ST131	R85	5284	4483	STK20 ³⁰
1114099	ST131	R85	5284	4483	STK31 ³¹
1114100	—	R86	5284	4483	—
1114101	ST133	R85	5284	4483	—
1114102	ST133	R86	5284	4483	—
1114103	ST131	R86	5284	4483	STK20 ³⁰
1114103	ST131	R86	5284	4483	STK31 ³¹
1114104	ST131	R86	5284	4483	STK20 ³⁰
1114104	ST131	R86	5284	4483	STK31 ³¹
1114105	ST131	R85	5284	4483	STK20 ³⁰
1114105	ST131	R85	5284	4483	STK31 ³¹
1114106	ST131	R86	5284	4483	STK20 ³⁰
1114106	ST131	R86	5284	4483	STK31 ³¹
1114107	ST131	R85	5284	4483	STK20 ³⁰
1114107	ST131	R85	5284	4483	STK31 ³¹
1114109	ST131	R86	5284	4483	STK20 ³⁰
1114109	ST131	R86	5284	4483	STK31 ³¹
1114110	ST131	R86	5284	4483	STK20 ³⁰
1114110	ST131	R86	5284	4483	STK31 ³¹
1114111	ST131	R86	5284	4483	STK20 ³⁰
1114111	ST131	R86	5284	4483	STK31 ³¹
1114112	ST133	R85	5284	4483	—
1114113	ST133	R86	5284	4483	—
1114114	ST131	R85	5284	4483	STK20 ³⁰
1114114	ST131	R85	5284	4483	STK31 ³¹
1114115	ST131	R86	5284	4483	STK20 ³⁰
1114115	ST131	R86	5284	4483	STK31 ³¹
1114116	ST133	R85	5284	4483	—
1114117	ST131	R85	5284	4483	STK20 ³⁰
1114117	ST131	R85	5284	4483	STK31 ³¹
1114118	—	R86	5284	—	—
1114119	ST131	R86	5284	4483	STK20 ³⁰
1114119	ST131	R86	5284	4483	STK31 ³¹
1114120	ST133	R86	5284	4483	—
1114121	ST133	R85	5284	SD1109	—
1114122	ST131	R85	5284	SD1109	STK20 ³⁰
1114122	ST131	R85	5284	SD1109	STK31 ³¹
1114123	ST131	R86	5284	SD1109	STK20 ³⁰
1114123	ST131	R86	5284	SD1109	STK31 ³¹
1114124	—	R86	5284	SD1109	—
1114125	ST131	R86	5284	SD1109	STK20 ³⁰
1114125	ST131	R86	5284	SD1109	STK31 ³¹
1114126	ST131	R86	5284	SD1109	STK20 ³⁰
1114126	ST131	R86	5284	SD1109	STK31 ³¹
1114127	ST131	R86	5284	SD1109	STK20 ³⁰

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114127	ST131	R86	5284	SD1109	STK31 ³¹
1114128	ST131	R86	5284	SD1109	STK20 ³⁰
1114128	ST131	R86	5284	SD1109	STK31 ³¹
1114129	ST131	R86	5284	SD1109	STK20 ³⁰
1114129	ST131	R86	5284	SD1109	STK31 ³¹
1114130	ST131	R86	5284	SD1109	STK20 ³⁰
1114130	ST131	R86	5284	SD1109	STK31 ³¹
1114132	ST131	R86	5284	SD1109	STK20 ³⁰
1114132	ST131	R86	5284	SD1109	STK31 ³¹
1114133	ST131	R86	5284	SD1109	STK20 ³⁰
1114133	ST131	R86	5284	SD1109	STK31 ³¹
1114134	ST131	R86	5284	SD1109	STK20 ³⁰
1114134	ST131	R86	5284	SD1109	STK31 ³¹
1114135	ST131	R85	5284	SD1109	STK20 ³⁰
1114135	ST131	R85	5284	SD1109	STK31 ³¹
1114136	ST131	R86	5284	SD1109	STK20 ³⁰
1114136	ST131	R86	5284	SD1109	STK31 ³¹
1114137	ST131	R85	5284	SD1109	STK20 ³⁰
1114137	ST131	R85	5284	SD1109	STK31 ³¹
1114138	ST131	R86	5284	SD1109	STK20 ³⁰
1114138	ST131	R86	5284	SD1109	STK31 ³¹
1114139	ST131	R85	5284	SD1109	STK20 ³⁰
1114139	ST131	R85	5284	SD1109	STK31 ³¹
1114140	ST131	R86	5284	4483	STK20 ³⁰
1114140	ST131	R86	5284	4483	STK31 ³¹
1114141	ST131	R86	5284	4483	STK20 ³⁰
1114141	ST131	R86	5284	4483	STK31 ³¹
1114142	ST131	R85	5284	4483	STK20 ³⁰
1114142	ST131	R85	5284	4483	STK31 ³¹
1114143	ST131	R86	5284	4483	STK20 ³⁰
1114143	ST131	R86	5284	4483	STK31 ³¹
1114144	ST131	R86	5284	4483	STK20 ³⁰
1114144	ST131	R86	5284	4483	STK31 ³¹
1114145	ST131	R86	5284	4483	STK20 ³⁰
1114145	ST131	R86	5284	4483	STK31 ³¹
1114146	ST131	R85	5284	4483	STK20 ³⁰
1114146	ST131	R85	5284	4483	STK31 ³¹
1114147	ST131	R86	5284	4483	STK20 ³⁰
1114147	ST131	R86	5284	4483	STK31 ³¹
1114148	ST131	R86	5284	4483	STK20 ³⁰
1114148	ST131	R86	5284	4483	STK31 ³¹
1114149	ST131	R86	5284	4483	STK20 ³⁰
1114149	ST131	R86	5284	4483	STK31 ³¹
1114150	ST131	R86	5284	4483	STK20 ³⁰
1114150	ST131	R86	5284	4483	STK31 ³¹
1114151	ST131	R86	5284	4483	STK20 ³⁰
1114151	ST131	R86	5284	4483	STK31 ³¹
1114152	ST133	R86	5284	4483	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114153	ST131	R86	5284	4483	STK20 ³⁰
1114153	ST131	R86	5284	4483	STK31 ³¹
1114154	ST131	R85	5284	4483	STK20 ³⁰
1114154	ST131	R85	5284	4483	STK31 ³¹
1114155	ST131	R86	5284	4483	STK20 ³⁰
1114155	ST131	R86	5284	4483	STK31 ³¹
1114156	ST131	R86	5284	4483	STK20 ³⁰
1114156	ST131	R86	5284	4483	STK31 ³¹
1114157	ST131	R86	5284	4483	STK20 ³⁰
1114157	ST131	R86	5284	4483	STK31 ³¹
1114158	ST131	R86	5284	4483	STK20 ³⁰
1114158	ST131	R86	5284	4483	STK31 ³¹
1114159	ST131	R86	5284	4483	STK20 ³⁰
1114159	ST131	R86	5284	4483	STK31 ³¹
1114160	ST131	R86	5284	4483	STK20 ³⁰
1114160	ST131	R86	5284	4483	STK31 ³¹
1114161	ST131	R86	5284	4483	STK20 ³⁰
1114161	ST131	R86	5284	4483	STK31 ³¹
1114162	ST131	R86	5284	4483	STK20 ³⁰
1114162	ST131	R86	5284	4483	STK31 ³¹
1114163	ST131	R86	5284	4483	STK20 ³⁰
1114163	ST131	R86	5284	4483	STK31 ³¹
1114164	ST131	R86	5284	4483	STK20 ³⁰
1114164	ST131	R86	5284	4483	STK31 ³¹
1114165	ST131	R86	5284	4483	STK20 ³⁰
1114165	ST131	R86	5284	4483	STK31 ³¹
1114166	ST133	R86	5284	4483	—
1114167	ST131	R86	5284	4483	STK20 ³⁰
1114167	ST131	R86	5284	4483	STK31 ³¹
1114168	ST133	R85	5284	4483	—
1114169	ST131	R86	5284	4483	STK20 ³⁰
1114169	ST131	R86	5284	4483	STK31 ³¹
1114170	ST131	R86	5284	4483	STK20 ³⁰
1114170	ST131	R86	5284	4483	STK31 ³¹
1114171	ST133	R86	5284	4483	—
1114172	ST131	R86	5284	4483	STK20 ³⁰
1114172	ST131	R86	5284	4483	STK31 ³¹
1114173	ST133	R85	5284	4483	—
1114174	ST131	R86	5284	4483	STK20 ³⁰
1114174	ST131	R86	5284	4483	STK31 ³¹
1114175	ST131	R86	5284	4483	STK20 ³⁰
1114175	ST131	R86	5284	4483	STK31 ³¹
1114176	ST131	R86	5284	4483	STK20 ³⁰
1114176	ST131	R86	5284	4483	STK31 ³¹
1114177	ST131	R86	5284	4483	STK20 ³⁰
1114177	ST131	R86	5284	4483	STK31 ³¹
1114178	ST131	R85	5284	4483	STK20 ³⁰
1114178	ST131	R85	5284	4483	STK31 ³¹

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114179	ST131	R85	5284	4483	STK20 ³⁰
1114179	ST131	R85	5284	4483	STK31 ³¹
1114180	ST131	R85	5284	4483	STK20 ³⁰
1114180	ST131	R85	5284	4483	STK31 ³¹
1114181	ST131	R86	5284	4483	STK20 ³⁰
1114181	ST131	R86	5284	4483	STK31 ³¹
1114182	ST131	R85	5284	4483	STK20 ³⁰
1114182	ST131	R85	5284	4483	STK31 ³¹
1114183	—	R85	5284	4483	—
1114184	ST131	R86	5284	4483	STK20 ³⁰
1114184	ST131	R86	5284	4483	STK31 ³¹
1114185	ST131	R85	—	4483	STK20 ³⁰
1114185	ST131	R85	—	4483	STK31 ³¹
1114186	ST131	R85	—	4483	STK20 ³⁰
1114186	ST131	R85	—	4483	STK31 ³¹
1114187	ST131	R85	—	4483	STK20 ³⁰
1114187	ST131	R85	—	4483	STK31 ³¹
1114188	ST131	R86	—	4483	STK20 ³⁰
1114188	ST131	R86	—	4483	STK31 ³¹
1114189	ST133	R85	—	4483	—
1114190	ST131	R85	—	4483	STK20 ³⁰
1114190	ST131	R85	—	4483	STK31 ³¹
1114191	ST131	R86	—	4483	STK20 ³⁰
1114191	ST131	R86	—	4483	STK31 ³¹
1114192	ST133	R86	—	4483	—
1114193	ST131	R86	—	4483	STK20 ³⁰
1114193	ST131	R86	—	4483	STK31 ³¹
1114194	ST131	R86	—	4483	STK20 ³⁰
1114194	ST131	R86	—	4483	STK31 ³¹
1114195	ST131	R86	—	4483	STK20 ³⁰
1114195	ST131	R86	—	4483	STK31 ³¹
1114196	ST133	R85	—	4483	—
1114197	ST133	R86	—	4483	—
1114198	ST133	R86	—	4483	—
1114199	ST131	R86	—	4483	STK20 ³⁰
1114199	ST131	R86	—	4483	STK31 ³¹
1114400	ST133	R85	—	—	—
1114600	—	R514	—	—	—
1114601	—	R514	—	—	—
1114604	ST53	R1001	5242	—	—
1114605	—	R503	—	—	—
1114606	—	R514	—	—	—
1114607	—	R503	—	—	—
1114657	ST132	—	5284	4483	STK21 ³⁰
1114657	ST132	—	5284	4483	STK32 ³¹
1114660	ST132	—	5284	—	STK21 ³⁰
1114660	ST132	—	5284	—	STK32 ³¹
1114661	ST115	R522	4310	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114662	ST113	R504	4310	—	STK26
1114663	ST132	R519	—	—	STK21 ³⁰
1114663	ST132	R519	—	—	STK32 ³¹
1114664	ST132	R519	—	—	STK21 ³⁰
1114664	ST132	R519	—	—	STK32 ³¹
1114665	ST131	R86	5284	—	STK20 ³⁰
1114665	ST131	R86	5284	—	STK31 ³¹
1114666	ST132	R85	5284	—	STK21 ³⁰
1114666	ST132	R85	5284	—	STK32 ³¹
1114668	ST132	R85	5284	—	STK21 ³⁰
1114668	ST132	R85	5284	—	STK32 ³¹
1114669	ST132	R519	—	—	STK21 ³⁰
1114669	ST132	R519	—	—	STK32 ³¹
1114671	ST115	R522	—	—	—
1114672	ST115	R522	—	—	—
1114676	ST132	R85	5284	—	STK21 ³⁰
1114676	ST132	R85	5284	—	STK32 ³¹
1114677	ST132	—	—	—	STK21 ³⁰
1114677	ST132	—	—	—	STK32 ³¹
1114679	ST132	—	—	—	STK21 ³⁰
1114679	ST132	—	—	—	STK32 ³¹
1114680	ST132	—	—	—	STK21 ³⁰
1114680	ST132	—	—	—	STK32 ³¹
1114681	ST132	—	—	—	STK21 ³⁰
1114681	ST132	—	—	—	STK32 ³¹
1114682	ST132	—	—	—	STK21 ³⁰
1114682	ST132	—	—	—	STK32 ³¹
1114683	ST132	—	—	—	STK21 ³⁰
1114683	ST132	—	—	—	STK32 ³¹
1114684	ST132	—	—	—	STK21 ³⁰
1114684	ST132	—	—	—	STK32 ³¹
1114685	ST132	—	—	—	STK21 ³⁰
1114685	ST132	—	—	—	STK32 ³¹
1114686	ST132	—	—	—	STK21 ³⁰
1114686	ST132	—	—	—	STK32 ³¹
1114687	ST132	—	—	—	STK21 ³⁰
1114687	ST132	—	—	—	STK32 ³¹
1114688	ST132	—	—	—	STK21 ³⁰
1114688	ST132	—	—	—	STK32 ³¹
1114689	ST132	—	—	—	STK21 ³⁰
1114689	ST132	—	—	—	STK32 ³¹
1114700	ST131	R86	5284	4483	STK20 ³⁰
1114700	ST131	R86	5284	4483	STK31 ³¹
1114701	ST133	R85	5284	4483	—
1114702	ST131	R86	5284	4483	STK20 ³⁰
1114702	ST131	R86	5284	4483	STK31 ³¹
1114703	ST131	R86	5284	4483	STK20 ³⁰
1114703	ST131	R86	5284	4483	STK31 ³¹

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114704	ST131	R86	5284	4483	STK20 ³⁰
1114704	ST131	R86	5284	4483	STK31 ³¹
1114705	ST131	R86	5284	4483	STK20 ³⁰
1114705	ST131	R86	5284	4483	STK31 ³¹
1114706	ST132	R85	5284	4483	STK21 ³⁰
1114706	ST132	R85	5284	4483	STK32 ³¹
1114707	ST134	R85	5284	4483	—
1114708	ST131	R86	5284	4483	STK20 ³⁰
1114708	ST131	R86	5284	4483	STK31 ³¹
1114709	ST133	R86	5284	4483	—
1114710	—	R85	5284	4483	—
1114711	—	R85	5284	4483	—
1114712	—	R85	5284	4483	—
1114713	ST131	R86	5284	4483	STK20 ³⁰
1114713	ST131	R86	5284	4483	STK31 ³¹
1114714	ST131	R86	5284	4483	STK20 ³⁰
1114714	ST131	R86	5284	4483	STK31 ³¹
1114715	—	R85	5284	4483	—
1114716	ST131	R86	5284	4483	STK20 ³⁰
1114716	ST131	R86	5284	4483	STK31 ³¹
1114718	ST132	R85	5284	4483	STK21 ³⁰
1114718	ST132	R85	5284	4483	STK32 ³¹
1114719	ST134	R85	5284	4483	—
1114720	ST131	R86	5284	4483	STK20 ³⁰
1114720	ST131	R86	5284	4483	STK31 ³¹
1114721	ST131	R86	—	—	STK20 ³⁰
1114721	ST131	R86	—	—	STK31 ³¹
1114722	ST131	R86	—	—	STK20 ³⁰
1114722	ST131	R86	—	—	STK31 ³¹
1114723	ST131	R86	—	—	STK20 ³⁰
1114723	ST131	R86	—	—	STK31 ³¹
1114724	ST131	R86	—	—	STK20 ³⁰
1114724	ST131	R86	—	—	STK31 ³¹
1114725	ST131	R86	—	—	STK20 ³⁰
1114725	ST131	R86	—	—	STK31 ³¹
1114726	ST131	R86	—	—	STK20 ³⁰
1114726	ST131	R86	—	—	STK31 ³¹
1114727	ST132	R85	—	—	STK21 ³⁰
1114727	ST132	R85	—	—	STK32 ³¹
1114728	—	R85	—	—	—
1114729	—	R85	—	—	—
1114730	ST132	R85	—	—	STK21 ³⁰
1114730	ST132	R85	—	—	STK32 ³¹
1114731	ST131	R86	—	—	STK20 ³⁰
1114731	ST131	R86	—	—	STK31 ³¹
1114732	—	R85	—	—	—
1114733	ST133	R86	—	4483	—
1114734	ST131	R86	—	—	STK20 ³⁰

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114734	ST131	R86	—	—	STK31 ³¹
1114735	ST132	R85	—	—	STK21 ³⁰
1114735	ST132	R85	—	—	STK32 ³¹
1114736	—	R86	—	—	—
1114737	—	R85	—	—	—
1114738	ST132	R85	—	4483	STK21 ³⁰
1114738	ST132	R85	—	4483	STK32 ³¹
1114739	ST132	R85	—	—	STK21 ³⁰
1114739	ST132	R85	—	—	STK32 ³¹
1114740	—	R85	—	—	—
1114741	ST131	R85	—	—	STK20 ³⁰
1114741	ST131	R85	—	—	STK31 ³¹
1114742	ST132	R85	—	—	STK21 ³⁰
1114742	ST132	R85	—	—	STK32 ³¹
1114743	ST132	R85	—	—	STK21 ³⁰
1114743	ST132	R85	—	—	STK32 ³¹
1114744	ST133	R86	—	—	—
1114745	ST131	R86	—	4498	STK20 ³⁰
1114745	ST131	R86	—	4498	STK31 ³¹
1114746	ST133	R86	5284	4498	—
1114747	ST133	R86	5284	4498	—
1114748	ST131	R86	5284	4498	STK20 ³⁰
1114748	ST131	R86	5284	4498	STK31 ³¹
1114749	ST131	R85	5284	4498	STK20 ³⁰
1114749	ST131	R85	5284	4498	STK31 ³¹
1114750	ST131	R85	5284	4498	STK20 ³⁰
1114750	ST131	R85	5284	4498	STK31 ³¹
1114751	ST131	R86	5284	4498	STK20 ³⁰
1114751	ST131	R86	5284	4498	STK31 ³¹
1114752	ST131	R86	5284	4498	STK20 ³⁰
1114752	ST131	R86	5284	4498	STK31 ³¹
1114753	ST131	R86	5284	4498	STK20 ³⁰
1114753	ST131	R86	5284	4498	STK31 ³¹
1114754	ST131	R85	5284	4498	STK20 ³⁰
1114754	ST131	R85	5284	4498	STK31 ³¹
1114755	ST132	R85	5284	4498	STK21 ³⁰
1114755	ST132	R85	5284	4498	STK32 ³¹
1114756	ST132	R85	5284	4498	STK21 ³⁰
1114756	ST132	R85	5284	4498	STK32 ³¹
1114757	ST131	R86	5284	4498	STK20 ³⁰
1114757	ST131	R86	5284	4498	STK31 ³¹
1114758	ST131	R85	5284	4498	STK20 ³⁰
1114758	ST131	R85	5284	4498	STK31 ³¹
1114759	ST132	R85	5284	4498	STK21 ³⁰
1114759	ST132	R85	5284	4498	STK32 ³¹
1114760	ST135	R85	5284	4498	—
1114761	ST131	R86	5284	4498	STK20 ³⁰
1114761	ST131	R86	5284	4498	STK31 ³¹

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114762	ST132	R85	5284	4498	STK21 ³⁰
1114762	ST132	R85	5284	4498	STK32 ³¹
1114763	ST134	R85	5284	4498	—
1114765	ST131	R86	5284	4498	STK20 ³⁰
1114765	ST131	R86	5284	4498	STK31 ³¹
1114766	ST131	R86	—	—	STK20 ³⁰
1114766	ST131	R86	—	—	STK31 ³¹
1114767	ST132	R85	5284	4498	STK21 ³⁰
1114767	ST132	R85	5284	4498	STK32 ³¹
1114769	ST131	R85	—	—	STK20 ³⁰
1114769	ST131	R85	—	—	STK31 ³¹
1114770	ST131	R86	—	—	STK20 ³⁰
1114770	ST131	R86	—	—	STK31 ³¹
1114771	ST131	R86	—	—	STK20 ³⁰
1114771	ST131	R86	—	—	STK31 ³¹
1114772	ST132	R85	5284	4498	STK21 ³⁰
1114772	ST132	R85	5284	4498	STK32 ³¹
1114773	ST131	R86	5284	4498	STK20 ³⁰
1114773	ST131	R86	5284	4498	STK31 ³¹
1114774	ST132	R85	5284	—	STK21 ³⁰
1114774	ST132	R85	5284	—	STK32 ³¹
1114775	ST131	R86	5284	—	STK20 ³⁰
1114775	ST131	R86	5284	—	STK31 ³¹
1114776	ST132	R85	—	—	—
1114777	ST132	R85	5284	—	STK21 ³⁰
1114777	ST132	R85	5284	—	STK32 ³¹
1114778	ST132	R86	5284	—	STK21 ³⁰
1114778	ST132	R86	5284	—	STK32 ³¹
1114779	ST131	R85	5284	—	STK20 ³⁰
1114779	ST131	R85	5284	—	STK31 ³¹
1114780	ST131	R86	5284	—	STK20 ³⁰
1114780	ST131	R86	5284	—	STK31 ³¹
1114781	ST132	R85	5284	—	STK21 ³⁰
1114781	ST132	R85	5284	—	STK32 ³¹
1114782	ST132	R85	5284	—	STK21 ³⁰
1114782	ST132	R85	5284	—	STK32 ³¹
1114783	ST132	R85	5284	—	STK21 ³⁰
1114783	ST132	R85	5284	—	STK32 ³¹
1114784	ST132	R85	5284	—	STK21 ³⁰
1114784	ST132	R85	5284	—	STK32 ³¹
1114785	ST132	R85	5284	—	STK21 ³⁰
1114785	ST132	R85	5284	—	STK32 ³¹
1114786	—	R85	5284	—	—
1114787	ST131	R86	5284	—	STK20 ³⁰
1114787	ST131	R86	5284	—	STK31 ³¹
1114788	ST131	R86	5284	—	STK20 ³⁰
1114788	ST131	R86	5284	—	STK31 ³¹
1114789	ST131	R85	5284	—	STK20 ³⁰

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114789	ST131	R85	5284	—	STK31 ³¹
1114790	—	R85	5284	—	—
1114791	ST131	R86	5284	—	STK20 ³⁰
1114791	ST131	R86	5284	—	STK31 ³¹
1114792	ST132	R85	5284	—	STK21 ³⁰
1114792	ST132	R85	5284	—	STK32 ³¹
1114793	ST132	R85	5284	—	STK21 ³⁰
1114793	ST132	R85	5284	—	STK32 ³¹
1114796	ST131	R86	5284	—	STK20 ³⁰
1114796	ST131	R86	5284	—	STK31 ³¹
1114797	ST131	R86	—	4498	STK20 ³⁰
1114797	ST131	R86	—	4498	STK31 ³¹
1114798	ST131	R86	—	4498	STK20 ³⁰
1114798	ST131	R86	—	4498	STK31 ³¹
1114799	—	R86	—	4498	—
1114800	ST131	R518	—	4498	STK20 ³⁰
1114800	ST131	R518	—	4498	STK31 ³¹
1114801	ST131	R518	—	4498	STK20 ³⁰
1114801	ST131	R518	—	4498	STK31 ³¹
1114802	ST131	R518	—	—	STK20 ³⁰
1114802	ST131	R518	—	—	STK31 ³¹
1114803	ST131	R518	—	4498	STK20 ³⁰
1114803	ST131	R518	—	4498	STK31 ³¹
1114804	ST131	R518	—	4498	STK20 ³⁰
1114804	ST131	R518	—	4498	STK31 ³¹
1114805	ST132	—	—	—	STK21 ³⁰
1114805	ST132	—	—	—	STK32 ³¹
1114806	ST131	R518	—	4498	STK20 ³⁰
1114806	ST131	R518	—	4498	STK31 ³¹
1114807	ST131	R518	—	—	STK20 ³⁰
1114807	ST131	R518	—	—	STK31 ³¹
1114808	ST131	R518	—	—	STK20 ³⁰
1114808	ST131	R518	—	—	STK31 ³¹
1114809	ST131	R518	—	—	STK20 ³⁰
1114809	ST131	R518	—	—	STK31 ³¹
1114810	ST131	R518	—	—	STK20 ³⁰
1114810	ST131	R518	—	—	STK31 ³¹
1114811	ST131	R518	—	—	STK20 ³⁰
1114811	ST131	R518	—	—	STK31 ³¹
1114812	ST131	R518	—	—	STK20 ³⁰
1114812	ST131	R518	—	—	STK31 ³¹
1114813	ST132	R518	—	—	STK21 ³⁰
1114813	ST132	R518	—	—	STK32 ³¹
1114814	ST131	R518	—	—	STK20 ³⁰
1114814	ST131	R518	—	—	STK31 ³¹
1114815	ST131	R518	—	—	STK20 ³⁰
1114815	ST131	R518	—	—	STK31 ³¹
1114816	ST140	—	—	—	—

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114817	ST131	R518	—	—	STK20 ³⁰
1114817	ST131	R518	—	—	STK31 ³¹
1114818	ST131	R518	—	—	STK20 ³⁰
1114818	ST131	R518	—	—	STK31 ³¹
1114819	ST131	R518	—	—	STK20 ³⁰
1114819	ST131	R518	—	—	STK31 ³¹
1114820	ST133	R518	—	—	—
1114821	ST131	R518	—	—	STK20 ³⁰
1114821	ST131	R518	—	—	STK31 ³¹
1114822	ST131	R518	—	—	STK20 ³⁰
1114822	ST131	R518	—	—	STK31 ³¹
1114823	ST131	R518	—	—	STK20 ³⁰
1114823	ST131	R518	—	—	STK31 ³¹
1114824	ST140	R518	—	—	—
1114825	ST131	R518	—	—	STK20 ³⁰
1114825	ST131	R518	—	—	STK31 ³¹
1114826	ST133	R518	—	—	—
1114827	ST131	R518	—	—	STK20 ³⁰
1114827	ST131	R518	—	—	STK31 ³¹
1114828	ST131	R518	—	—	STK20 ³⁰
1114828	ST131	R518	—	—	STK31 ³¹
1114829	ST133	R518	—	—	—
1114830	ST133	—	—	—	—
1114831	ST133	R518	—	—	—
1114832	ST131	R518	—	—	STK20 ³⁰
1114832	ST131	R518	—	—	STK31 ³¹
1114833	ST133	R518	—	—	—
1114834	ST131	R518	—	—	STK20 ³⁰
1114834	ST131	R518	—	—	STK31 ³¹
1114835	ST131	R518	—	—	STK20 ³⁰
1114835	ST131	R518	—	—	STK31 ³¹
1114836	ST131	R518	—	—	STK20 ³⁰
1114836	ST131	R518	—	—	STK31 ³¹
1114839	ST131	—	—	—	STK20 ³⁰
1114839	ST131	—	—	—	STK31 ³¹
1114840	ST132	—	—	—	STK21 ³⁰
1114840	ST132	—	—	—	STK32 ³¹
1114841	ST135	—	—	—	—
1114842	ST132	—	—	—	STK21 ³⁰
1114842	ST132	—	—	—	STK32 ³¹
1114843	ST132	—	—	—	STK21 ³⁰
1114843	ST132	—	—	—	STK32 ³¹
1114844	ST132	—	—	—	STK21 ³⁰
1114844	ST132	—	—	—	STK32 ³¹
1114845	ST132	—	—	—	STK21 ³⁰
1114845	ST132	—	—	—	STK32 ³¹
1114846	ST132	—	—	—	STK21 ³⁰
1114846	ST132	—	—	—	STK32 ³¹

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114847	ST135	—	—	—	—
1114848	ST132	—	—	—	STK21 ³⁰
1114848	ST132	—	—	—	STK32 ³¹
1114849	ST132	—	—	—	STK21 ³⁰
1114849	ST132	—	—	—	STK32 ³¹
1114850	ST132	—	—	—	STK21 ³⁰
1114850	ST132	—	—	—	STK32 ³¹
1114851	ST132	—	—	—	STK21 ³⁰
1114851	ST132	—	—	—	STK32 ³¹
1114852	ST132	—	—	—	STK21 ³⁰
1114852	ST132	—	—	—	STK32 ³¹
1114853	ST132	—	—	—	STK21 ³⁰
1114853	ST132	—	—	—	STK32 ³¹
1114854	ST132	—	—	—	STK21 ³⁰
1114854	ST132	—	—	—	STK32 ³¹
1114855	ST132	—	—	—	STK21 ³⁰
1114855	ST132	—	—	—	STK32 ³¹
1114856	ST132	—	—	—	STK21 ³⁰
1114856	ST132	—	—	—	STK32 ³¹
1114857	ST132	—	—	—	STK21 ³⁰
1114857	ST132	—	—	—	STK32 ³¹
1114858	ST132	—	—	—	STK21 ³⁰
1114858	ST132	—	—	—	STK32 ³¹
1114859	ST132	—	—	—	STK21 ³⁰
1114859	ST132	—	—	—	STK32 ³¹
1114860	ST135	—	—	—	—
1114861	ST132	—	—	—	STK21 ³⁰
1114861	ST132	—	—	—	STK32 ³¹
1114862	ST132	—	—	—	STK21 ³⁰
1114862	ST132	—	—	—	STK32 ³¹
1114863	ST132	—	—	—	STK21 ³⁰
1114863	ST132	—	—	—	STK32 ³¹
1114864	ST132	—	—	—	STK21 ³⁰
1114864	ST132	—	—	—	STK32 ³¹
1114865	ST132	—	—	—	STK21 ³⁰
1114865	ST132	—	—	—	STK32 ³¹
1114866	ST134	—	—	—	—
1114867	ST134	—	—	—	—
1114868	ST134	—	—	—	—
1114869	ST134	—	—	—	—
1114870	ST134	—	—	—	—
1114871	ST132	—	—	—	STK21 ³⁰
1114871	ST132	—	—	—	STK32 ³¹
1114872	ST132	—	—	—	STK21 ³⁰
1114872	ST132	—	—	—	STK32 ³¹
1114873	ST132	—	—	—	STK21 ³⁰
1114873	ST132	—	—	—	STK32 ³¹
1114874	ST132	—	—	—	STK21 ³⁰

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114874	ST132	—	—	—	STK32 ³¹
1114875	ST132	—	—	—	STK21 ³⁰
1114875	ST132	—	—	—	STK32 ³¹
1114876	ST132	—	—	—	STK21 ³⁰
1114876	ST132	—	—	—	STK32 ³¹
1114877	ST132	—	—	—	STK21 ³⁰
1114877	ST132	—	—	—	STK32 ³¹
1114878	ST132	—	—	—	STK21 ³⁰
1114878	ST132	—	—	—	STK32 ³¹
1114879	ST132	—	—	—	STK21 ³⁰
1114879	ST132	—	—	—	STK32 ³¹
1114880	ST132	R518	—	—	STK21 ³⁰
1114880	ST132	R518	—	—	STK32 ³¹
1114881	ST133	R518	—	—	—
1114882	ST131	R518	—	—	STK20 ³⁰
1114882	ST131	R518	—	—	STK31 ³¹
1114883	ST131	R518	—	—	STK20 ³⁰
1114883	ST131	R518	—	—	STK31 ³¹
1114884	ST131	R518	—	—	STK20 ³⁰
1114884	ST131	R518	—	—	STK31 ³¹
1114885	ST131	R518	—	—	STK20 ³⁰
1114885	ST131	R518	—	—	STK31 ³¹
1114886	ST131	R518	—	—	STK20 ³⁰
1114886	ST131	R518	—	—	STK31 ³¹
1114887	ST133	R518	—	—	—
1114888	ST131	R518	—	—	STK20 ³⁰
1114888	ST131	R518	—	—	STK31 ³¹
1114889	ST131	R518	—	—	STK20 ³⁰
1114889	ST131	R518	—	—	STK31 ³¹
1114890	ST131	R518	—	—	STK20 ³⁰
1114890	ST131	R518	—	—	STK31 ³¹
1114891	ST131	R518	—	—	STK20 ³⁰
1114891	ST131	R518	—	—	STK31 ³¹
1114892	ST131	—	—	—	STK20 ³⁰
1114892	ST131	—	—	—	STK31 ³¹
1114893	ST131	R518	—	—	STK20 ³⁰
1114893	ST131	R518	—	—	STK31 ³¹
1114894	ST131	R518	—	—	STK20 ³⁰
1114894	ST131	R518	—	—	STK31 ³¹
1114895	ST131	R518	5284	4498	STK20 ³⁰
1114895	ST131	R518	5284	4498	STK31 ³¹
1114896	ST131	R518	5284	4498	STK20 ³⁰
1114896	ST131	R518	5284	4498	STK31 ³¹
1114897	ST131	R518	5284	4498	STK20 ³⁰
1114897	ST131	R518	5284	4498	STK31 ³¹
1114898	ST131	R518	5284	4498	STK20 ³⁰
1114898	ST131	R518	5284	4498	STK31 ³¹
1114899	ST131	R518	5284	4498	STK20 ³⁰

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114899	ST131	R518	5284	4498	STK31 ³¹
1114900	ST131	R518	5284	4498	STK20 ³⁰
1114900	ST131	R518	5284	4498	STK31 ³¹
1114901	ST131	—	5284	4498	STK20 ³⁰
1114901	ST131	—	5284	4498	STK31 ³¹
1114902	ST133	R518	5284	4498	—
1114903	ST132	—	5284	4498	STK21 ³⁰
1114903	ST132	—	5284	4498	STK32 ³¹
1114904	ST131	—	5284	4498	STK20 ³⁰
1114904	ST131	—	5284	4498	STK31 ³¹
1114905	ST132	—	5284	4498	STK21 ³⁰
1114905	ST132	—	5284	4498	STK32 ³¹
1114906	ST131	R518	5284	4498	STK20 ³⁰
1114906	ST131	R518	5284	4498	STK31 ³¹
1114907	ST135	—	5284	4498	—
1114908	ST131	R518	5284	4498	STK20 ³⁰
1114908	ST131	R518	5284	4498	STK31 ³¹
1114909	ST132	—	5284	4498	STK21 ³⁰
1114909	ST132	—	5284	4498	STK32 ³¹
1114910	ST132	—	5284	4498	STK21 ³⁰
1114910	ST132	—	5284	4498	STK32 ³¹
1114911	ST131	R518	5284	4498	STK20 ³⁰
1114911	ST131	R518	5284	4498	STK31 ³¹
1114912	ST131	R86	5284	4498	STK20 ³⁰
1114912	ST131	R86	5284	4498	STK31 ³¹
1114913	ST131	—	5284	4498	STK20 ³⁰
1114913	ST131	—	5284	4498	STK31 ³¹
1114914	ST132	—	5284	4498	STK21 ³⁰
1114914	ST132	—	5284	4498	STK32 ³¹
1114915	ST132	—	5284	4498	STK21 ³⁰
1114915	ST132	—	5284	4498	STK32 ³¹
1114916	ST132	—	5284	4498	STK21 ³⁰
1114916	ST132	—	5284	4498	STK32 ³¹
1114917	ST132	R85	5284	4498	STK21 ³⁰
1114917	ST132	R85	5284	4498	STK32 ³¹
1114918	ST133	R86	5284	4498	—
1114919	ST131	R86	5284	4498	STK20 ³⁰
1114919	ST131	R86	5284	4498	STK31 ³¹
1114920	ST140	R518	5284	4498	—
1114921	ST132	—	5284	4498	STK21 ³⁰
1114921	ST132	—	5284	4498	STK32 ³¹
1114922	ST132	—	5284	4498	STK21 ³⁰
1114922	ST132	—	5284	4498	STK32 ³¹
1114923	ST132	—	5284	4498	STK21 ³⁰
1114923	ST132	—	5284	4498	STK32 ³¹
1114924	ST134	—	—	—	—
1114925	ST134	—	—	—	—
1114926	ST132	—	—	—	STK21 ³⁰

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114926	ST132	—	—	—	STK32 ³¹
1114927	ST131	—	—	—	STK20 ³⁰
1114927	ST131	—	—	—	STK31 ³¹
1114928	ST131	—	—	—	STK20 ³⁰
1114928	ST131	—	—	—	STK31 ³¹
1114929	ST131	—	—	—	STK20 ³⁰
1114929	ST131	—	—	—	STK31 ³¹
1114930	ST131	—	—	—	STK20 ³⁰
1114930	ST131	—	—	—	STK31 ³¹
1114931	ST131	—	—	—	STK20 ³⁰
1114931	ST131	—	—	—	STK31 ³¹
1114932	ST131	—	—	—	STK20 ³⁰
1114932	ST131	—	—	—	STK31 ³¹
1114933	ST131	—	—	—	STK20 ³⁰
1114933	ST131	—	—	—	STK31 ³¹
1114934	ST131	R518	—	—	STK20 ³⁰
1114934	ST131	R518	—	—	STK31 ³¹
1114935	ST132	—	—	—	STK21 ³⁰
1114935	ST132	—	—	—	STK32 ³¹
1114936	ST133	—	—	—	—
1114937	ST133	R518	—	—	—
1114938	ST131	R518	—	—	STK20 ³⁰
1114938	ST131	R518	—	—	STK31 ³¹
1114939	ST133	R518	—	—	—
1114940	ST133	R518	—	—	—
1114941	ST133	—	—	—	—
1114942	ST131	R86	—	—	STK20 ³⁰
1114942	ST131	R86	—	—	STK31 ³¹
1114943	ST131	R518	—	—	STK20 ³⁰
1114943	ST131	R518	—	—	STK31 ³¹
1114944	ST133	R518	—	—	—
1114945	ST132	—	—	—	STK21 ³⁰
1114945	ST132	—	—	—	STK32 ³¹
1114947	ST132	—	—	—	STK21 ³⁰
1114947	ST132	—	—	—	STK32 ³¹
1114948	ST132	—	—	—	STK21 ³⁰
1114948	ST132	—	—	—	STK32 ³¹
1114949	ST132	—	—	—	STK21 ³⁰
1114949	ST132	—	—	—	STK32 ³¹
1114950	ST132	—	—	—	STK21 ³⁰
1114950	ST132	—	—	—	STK32 ³¹
1114951	ST132	—	5284	4498	STK21 ³⁰
1114951	ST132	—	5284	4498	STK32 ³¹
1114952	ST132	—	5284	4498	STK21 ³⁰
1114952	ST132	—	5284	4498	STK32 ³¹
1114953	ST132	—	5284	4498	STK21 ³⁰
1114953	ST132	—	5284	4498	STK32 ³¹
1114955	ST131	R518	5284	4498	STK20 ³⁰

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114955	ST131	R518	5284	4498	STK31 ³¹
1114956	ST131	R518	5284	4498	STK20 ³⁰
1114956	ST131	R518	5284	4498	STK31 ³¹
1114957	ST135	R518	5284	4498	—
1114958	ST132	—	5284	4498	STK21 ³⁰
1114958	ST132	—	5284	4498	STK32 ³¹
1114959	ST132	—	5284	4498	STK21 ³⁰
1114959	ST132	—	5284	4498	STK32 ³¹
1114960	ST131	—	5284	4498	STK20 ³⁰
1114960	ST131	—	5284	4498	STK31 ³¹
1114961	ST131	—	5284	4498	STK20 ³⁰
1114961	ST131	—	5284	4498	STK31 ³¹
1114962	ST134	—	5284	4498	—
1114963	ST132	—	5284	4498	STK21 ³⁰
1114963	ST132	—	5284	4498	STK32 ³¹
1114964	ST132	—	5284	4498	STK21 ³⁰
1114964	ST132	—	5284	4498	STK32 ³¹
1114965	ST133	R518	5284	4498	—
1114966	ST134	R518	5284	4498	—
1114967	ST131	R518	5284	4498	STK20 ³⁰
1114967	ST131	R518	5284	4498	STK31 ³¹
1114968	ST132	—	5284	4498	STK21 ³⁰
1114968	ST132	—	5284	4498	STK32 ³¹
1114969	ST131	R518	5284	4498	STK20 ³⁰
1114969	ST131	R518	5284	4498	STK31 ³¹
1114970	ST132	—	5284	4498	STK21 ³⁰
1114970	ST132	—	5284	4498	STK32 ³¹
1114971	ST132	—	5284	4498	STK21 ³⁰
1114971	ST132	—	5284	4498	STK32 ³¹
1114972	ST132	—	5284	4498	STK21 ³⁰
1114972	ST132	—	5284	4498	STK32 ³¹
1114973	ST132	—	5284	4498	STK21 ³⁰
1114973	ST132	—	5284	4498	STK32 ³¹
1114974	ST132	—	5284	4498	STK21 ³⁰
1114974	ST132	—	5284	4498	STK32 ³¹
1114975	ST131	R518	5284	4498	STK20 ³⁰
1114975	ST131	R518	5284	4498	STK31 ³¹
1114976	ST131	R518	5284	4498	STK20 ³⁰
1114976	ST131	R518	5284	4498	STK31 ³¹
1114977	ST131	R518	5284	4498	STK20 ³⁰
1114977	ST131	R518	5284	4498	STK31 ³¹
1114978	ST133	R518	5284	4498	—
1114979	ST132	—	5284	4498	STK21 ³⁰
1114979	ST132	—	5284	4498	STK32 ³¹
1114982	ST132	—	5284	4498	STK21 ³⁰
1114982	ST132	—	5284	4498	STK32 ³¹
1114984	ST133	R518	5284	4498	—
1114985	ST131	R86	—	—	STK20 ³⁰

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1114985	ST131	R86	—	—	STK31 ³¹
1114986	ST131	R86	—	—	STK20 ³⁰
1114986	ST131	R86	—	—	STK31 ³¹
1114987	ST132	R85	—	—	STK21 ³⁰
1114987	ST132	R85	—	—	STK32 ³¹
1114988	ST131	R85	—	—	STK20 ³⁰
1114988	ST131	R85	—	—	STK31 ³¹
1114989	ST132	R85	—	—	STK21 ³⁰
1114989	ST132	R85	—	—	STK32 ³¹
1114990	ST131	R86	—	—	STK20 ³⁰
1114990	ST131	R86	—	—	STK31 ³¹
1114991	ST131	R86	5284	4498	STK20 ³⁰
1114991	ST131	R86	5284	4498	STK31 ³¹
1114992	ST131	R86	5284	4498	STK20 ³⁰
1114992	ST131	R86	5284	4498	STK31 ³¹
1114993	ST131	—	5284	4498	STK20 ³⁰
1114993	ST131	—	5284	4498	STK31 ³¹
1114994	ST131	R518	5284	4498	STK20 ³⁰
1114994	ST131	R518	5284	4498	STK31 ³¹
1114995	ST132	—	5284	4498	STK21 ³⁰
1114995	ST132	—	5284	4498	STK32 ³¹
1114996	ST132	—	5284	4498	STK21 ³⁰
1114996	ST132	—	5284	4498	STK32 ³¹
1114997	ST131	R518	5284	4498	STK20 ³⁰
1114997	ST131	R518	5284	4498	STK31 ³¹
1114999	ST140	—	5284	4498	—
1117542	ST124	—	—	—	—
1117543	ST124	—	—	—	—
1117544	ST124	—	—	—	—
1117608	—	R503	—	—	—
1117963	—	—	—	4200	—
1118207	—	R503	—	—	—
1118877	—	R84	4286	—	—
1118878	—	R84	4286	—	—
1330315	ST172	R512	5299	5299	—
1813397	ST63	R503	—	—	—
1814169	—	R503	—	4265	—
1814231	ST11	R503	—	4265	—
1814232	—	R503	—	4265	—
1814233	—	R503	—	4265	—
1814422	—	R503	—	4265	—
1814510	ST100	R503	—	—	STK2
1814520	ST100	R503	—	—	STK2
1814560	—	—	—	5288	—
1845521	—	R503	—	4200	—
1845549	—	R503	—	—	—
1845591	—	R503	—	—	—
1861181	ST6	R503	—	4200	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1862523	—	R503	—	—	—
1878002	ST58	R503	—	—	—
1878077	ST58	R503	—	—	—
1882547	—	R501	—	—	—
1909330	—	—	5284	—	—
1910938	ST58	R503	—	—	—
1911763	—	R503	—	—	—
1911832	—	R503	—	—	—
1915056	—	R501	—	—	—
1917855	—	R503	—	—	—
1917857	—	R503	—	—	—
1917882	—	R501	—	—	—
1937444	ST146	R513	5299	5299	STK46
1984427	ST128	R507	—	—	STK28
1984450	ST128	R507	—	—	STK28
1990200	ST140	R518	5284	4498	—
1990201	ST140	R518	5284	4498	—
1990202	ST132	R85	5284	4498	STK21 ³⁰
1990202	ST132	R85	5284	4498	STK32 ³¹
1990205	ST133	R85	5284	4498	—
1990206	ST131	R518	5284	4498	STK20 ³⁰
1990206	ST131	R518	5284	4498	STK31 ³¹
1990208	ST131	R518	5284	4498	STK20 ³⁰
1990208	ST131	R518	5284	4498	STK31 ³¹
1990209	ST131	R518	5284	4498	STK20 ³⁰
1990209	ST131	R518	5284	4498	STK31 ³¹
1990210	ST132	R85	—	—	STK21 ³⁰
1990210	ST132	R85	—	—	STK32 ³¹
1990211	ST131	R86	—	—	STK20 ³⁰
1990211	ST131	R86	—	—	STK31 ³¹
1990212	ST131	R86	—	—	STK20 ³⁰
1990212	ST131	R86	—	—	STK31 ³¹
1990213	ST135	R85	—	—	—
1990214	ST131	R85	—	—	STK20 ³⁰
1990214	ST131	R85	—	—	STK31 ³¹
1990215	ST131	R86	—	—	STK20 ³⁰
1990215	ST131	R86	—	—	STK31 ³¹
1990216	ST134	R85	—	—	—
1990217	ST134	—	5284	4498	—
1990218	ST131	R518	5284	4498	STK20 ³⁰
1990218	ST131	R518	5284	4498	STK31 ³¹
1990219	ST131	—	5284	4498	STK20 ³⁰
1990219	ST131	—	5284	4498	STK31 ³¹
1990220	ST133	R86	—	—	—
1990221	ST131	R518	5284	4498	STK20 ³⁰
1990221	ST131	R518	5284	4498	STK31 ³¹
1990222	ST132	—	5284	4498	STK21 ³⁰
1990222	ST132	—	5284	4498	STK32 ³¹

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1990223	ST131	—	5284	4498	STK20 ³⁰
1990223	ST131	—	5284	4498	STK31 ³¹
1990224	ST131	—	5284	4498	STK20 ³⁰
1990224	ST131	—	5284	4498	STK31 ³¹
1990225	ST134	R520	—	4498	—
1990226	ST137	R520	—	4498	—
1990227	ST132	R520	—	4498	STK21 ³⁰
1990227	ST132	R520	—	4498	STK32 ³¹
1990228	ST132	R520	—	4498	STK21 ³⁰
1990228	ST132	R520	—	4498	STK32 ³¹
1990229	ST132	R520	—	4498	STK21 ³⁰
1990229	ST132	R520	—	4498	STK32 ³¹
1990230	ST134	R520	—	4498	—
1990231	ST132	R520	—	4498	STK21 ³⁰
1990231	ST132	R520	—	4498	STK32 ³¹
1990232	ST132	R520	—	4498	STK21 ³⁰
1990232	ST132	R520	—	4498	STK32 ³¹
1990233	ST132	R520	—	4498	STK21 ³⁰
1990233	ST132	R520	—	4498	STK32 ³¹
1990234	ST132	R520	—	4498	STK21 ³⁰
1990234	ST132	R520	—	4498	STK32 ³¹
1990235	ST132	R520	—	4498	STK21 ³⁰
1990235	ST132	R520	—	4498	STK32 ³¹
1990236	ST132	R520	—	4498	STK21 ³⁰
1990236	ST132	R520	—	4498	STK32 ³¹
1990237	ST132	R520	—	4498	STK21 ³⁰
1990237	ST132	R520	—	4498	STK32 ³¹
1990238	ST132	R520	—	4498	STK21 ³⁰
1990238	ST132	R520	—	4498	STK32 ³¹
1990239	ST132	R520	—	4498	STK21 ³⁰
1990239	ST132	R520	—	4498	STK32 ³¹
1990240	ST132	R520	—	4498	STK21 ³⁰
1990240	ST132	R520	—	4498	STK32 ³¹
1990241	ST132	R520	—	4498	STK21 ³⁰
1990241	ST132	R520	—	4498	STK32 ³¹
1990242	ST134	R520	—	4498	—
1990243	ST132	R520	—	4498	STK21 ³⁰
1990243	ST132	R520	—	4498	STK32 ³¹
1990244	ST132	R520	—	4498	STK21 ³⁰
1990244	ST132	R520	—	4498	STK32 ³¹
1990245	ST137	R520	—	4498	—
1990246	ST134	R520	—	4498	—
1990247	ST132	R520	—	4498	STK21 ³⁰
1990247	ST132	R520	—	4498	STK32 ³¹
1990248	ST132	R520	—	4498	STK21 ³⁰
1990248	ST132	R520	—	4498	STK32 ³¹
1990249	ST132	R520	—	4498	STK21 ³⁰
1990249	ST132	R520	—	4498	STK32 ³¹

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1990250	ST132	R520	—	4498	STK21 ³⁰
1990250	ST132	R520	—	4498	STK32 ³¹
1990251	ST132	R520	—	4498	STK21 ³⁰
1990251	ST132	R520	—	4498	STK32 ³¹
1990252	ST134	R520	—	4498	—
1990253	ST134	R520	—	4498	—
1990254	ST134	R520	—	4498	—
1990255	ST134	R520	—	4498	—
1990256	ST138	R520	—	4498	—
1990257	—	R520	—	4498	—
1990258	ST138	R520	—	4498	—
1990259	ST132	R520	—	4498	STK21 ³⁰
1990259	ST132	R520	—	4498	STK32 ³¹
1990260	ST132	R520	—	4498	STK21 ³⁰
1990260	ST132	R520	—	4498	STK32 ³¹
1990261	ST131	R520	—	4498	STK20 ³⁰
1990261	ST131	R520	—	4498	STK31 ³¹
1990262	ST132	R520	—	4498	STK21 ³⁰
1990262	ST132	R520	—	4498	STK32 ³¹
1990263	ST132	R520	—	4498	STK21 ³⁰
1990263	ST132	R520	—	4498	STK32 ³¹
1990264	ST132	R520	—	4498	STK21 ³⁰
1990264	ST132	R520	—	4498	STK32 ³¹
1990265	ST132	R520	—	4498	STK21 ³⁰
1990265	ST132	R520	—	4498	STK32 ³¹
1990266	ST135	R520	—	4498	—
1990267	ST132	R520	—	4498	STK21 ³⁰
1990267	ST132	R520	—	4498	STK32 ³¹
1990268	ST132	R520	—	4498	STK21 ³⁰
1990268	ST132	R520	—	4498	STK32 ³¹
1990269	ST132	R520	—	4498	STK21 ³⁰
1990269	ST132	R520	—	4498	STK32 ³¹
1990270	ST132	R520	—	4498	STK21 ³⁰
1990270	ST132	R520	—	4498	STK32 ³¹
1990271	ST132	R520	—	4498	STK21 ³⁰
1990271	ST132	R520	—	4498	STK32 ³¹
1990272	ST135	R520	—	4498	—
1990273	ST132	R520	—	4498	STK21 ³⁰
1990273	ST132	R520	—	4498	STK32 ³¹
1990274	ST132	R520	—	4498	STK21 ³⁰
1990274	ST132	R520	—	4498	STK32 ³¹
1990275	ST134	R520	—	4498	—
1990276	ST132	R520	—	4498	STK21 ³⁰
1990276	ST132	R520	—	4498	STK32 ³¹
1990277	ST131	R520	—	4498	STK20 ³⁰
1990277	ST131	R520	—	4498	STK31 ³¹
1990278	ST132	R520	—	4498	STK21 ³⁰
1990278	ST132	R520	—	4498	STK32 ³¹

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1990279	ST132	—	5284	4498	STK21 ³⁰
1990279	ST132	—	5284	4498	STK32 ³¹
1990280	ST131	R518	5284	4498	STK20 ³⁰
1990280	ST131	R518	5284	4498	STK31 ³¹
1990291	ST132	R520	—	4498	STK21 ³⁰
1990291	ST132	R520	—	4498	STK32 ³¹
1990296	ST131	R518	5284	4498	STK20 ³⁰
1990296	ST131	R518	5284	4498	STK31 ³¹
1990297	ST132	—	5284	4498	STK21 ³⁰
1990297	ST132	—	5284	4498	STK32 ³¹
1990298	ST140	R520	—	4498	—
1990299	ST131	R518	5284	4498	STK20 ³⁰
1990299	ST131	R518	5284	4498	STK31 ³¹
1990300	ST133	R518	5284	4498	—
1990302	ST133	R518	5284	4498	—
1990303	ST131	R518	5284	4498	STK20 ³⁰
1990303	ST131	R518	5284	4498	STK31 ³¹
1990304	ST133	R518	5284	4498	—
1990307	ST135	—	5284	4498	—
1990308	ST144	R512	5299	5299	STK44
1990309	ST172	R512	5299	5299	—
1990310	ST172	R512	5299	5299	—
1990311	—	R512	5299	5299	—
1990312	—	R512	5299	5299	—
1990313	ST172	R512	5299	5299	—
1990316	ST172	R512	5299	5299	—
1990317	ST172	R512	5299	5299	—
1990318	—	R512	5299	5299	—
1990319	ST144	R512	5299	5299	STK44
1990320	ST172	R512	5299	5299	—
1990321	—	R512	5299	5299	—
1990322	—	R512	5299	5299	—
1990324	ST132	—	5284	4498	STK21 ³⁰
1990324	ST132	—	5284	4498	STK32 ³¹
1990325	ST131	R518	5284	4498	STK20 ³⁰
1990325	ST131	R518	5284	4498	STK31 ³¹
1990326	—	R512	5299	5299	—
1990327	—	R512	5299	5299	—
1990328	ST132	—	5284	4498	STK21 ³⁰
1990328	ST132	—	5284	4498	STK32 ³¹
1990329	ST131	R518	—	4498	STK20 ³⁰
1990329	ST131	R518	—	4498	STK31 ³¹
1990330	ST146	R513	5299	5299	STK46
1990331	ST146	R513	5299	5299	STK46
1990332	ST146	R513	5299	5299	STK46
1990333	ST138	—	5284	4498	—
1990335	ST133	R518	5284	4498	—
1990336	—	R512	5299	5299	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1990337	ST145	R510	5299	4498	STK45
1990339	ST133	R518	5284	4498	—
1990340	ST132	—	5284	4498	STK21 ³⁰
1990340	ST132	—	5284	4498	STK32 ³¹
1990341	ST144	R512	5299	5299	STK44
1990342	ST133	R518	5284	4498	—
1990343	ST132	—	5284	4498	STK21 ³⁰
1990343	ST132	—	5284	4498	STK32 ³¹
1990344	ST147	R511	5299	4498	STK46
1990346	ST132	—	5284	4498	STK21 ³⁰
1990346	ST132	—	5284	4498	STK32 ³¹
1990347	—	R512	5299	5299	—
1990348	ST145	R510	5299	4498	STK45
1990349	ST145	R510	5299	4498	STK45
1990350	ST147	R511	5299	4498	STK46
1990352	ST145	R510	5299	4498	STK45
1990353	ST145	R510	5299	4498	STK45
1990354	ST145	R510	5299	4498	STK45
1990355	ST145	R510	5299	4498	STK45
1990356	ST145	R510	5299	4498	STK45
1990357	ST147	R511	5299	4498	STK46
1990358	ST145	R510	5299	4498	STK45
1990359	ST147	R511	5299	4498	STK46
1990360	ST147	R511	5299	4498	STK46
1990361	ST147	R511	5299	4498	STK46
1990362	ST145	R510	5299	4498	STK45
1990363	ST145	R510	5299	4498	STK45
1990364	ST147	R511	5299	4498	STK46
1990365	ST145	R510	5299	4498	STK45
1990366	ST147	R511	5299	4498	STK46
1990367	ST147	R511	5299	4498	STK46
1990368	ST147	R511	5299	4498	STK46
1990369	ST164	R510	5299	4498	—
1990370	ST145	R510	5299	4498	STK45
1990371	ST147	R511	5299	4498	STK46
1990372	ST145	R510	5299	4498	STK45
1990373	ST147	R511	5299	4498	STK46
1990374	ST164	R510	5299	4498	—
1990375	ST145	R510	5299	4498	STK45
1990376	ST145	R510	5299	4498	STK45
1990377	ST145	R510	5299	4498	STK45
1990378	ST147	R511	5299	4498	STK46
1990379	ST145	R510	5299	4498	STK45
1990380	ST164	R510	5299	4498	—
1990381	ST184	R511	5299	4498	—
1990382	ST147	R511	5299	4498	STK46
1990383	ST147	—	5299	4498	STK46
1990384	ST147	—	—	—	STK46

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1990385	ST145	—	5299	4498	STK45
1990386	ST145	—	5299	4498	STK45
1990387	ST145	—	5299	4498	STK45
1990388	ST147	R511	5299	4498	STK46
1990389	ST147	R511	5299	4498	STK46
1990391	ST145	R510	5299	4498	STK45
1990392	ST145	—	—	—	—
1990393	ST145	R510	5299	4498	STK45
1990394	ST145	R510	5299	4498	STK45
1990395	ST145	R510	5299	4498	STK45
1990396	ST164	R510	5299	4498	—
1990397	ST145	R510	5299	4498	STK45
1990398	ST145	R510	5299	4498	STK45
1990400	ST145	R510	5299	4498	STK45
1990401	ST164	R510	5299	4498	—
1990402	ST164	R510	5299	4498	—
1990403	ST132	R511	5299	4498	STK21 ³⁰
1990403	ST132	R511	5299	4498	STK32 ³¹
1990404	ST145	R510	5299	4498	STK45
1990405	ST145	R510	5299	4498	STK45
1990406	ST145	R510	5299	4498	STK45
1990407	ST164	R510	5299	4498	—
1990408	ST145	R510	5299	4498	STK45
1990411	ST184	R511	5299	4498	—
1990413	ST147	R511	5299	4498	STK46
1990414	ST184	R511	5299	4498	—
1990415	—	R511	5299	4498	—
1990416	ST184	R511	5299	4498	—
1990417	ST145	R510	5299	4498	STK45
1990418	ST147	R511	5299	4498	STK46
1990419	ST164	R510	5299	4498	—
1990420	ST145	R510	5299	4498	STK45
1990421	ST145	R510	5299	4498	STK45
1990422	—	R511	5299	4498	—
1990423	ST182	R510	5299	4498	—
1990424	ST182	R510	5299	4498	—
1990427	ST182	R510	5299	4498	—
1990428	ST182	R510	5299	4498	—
1990429	ST182	R510	5299	4498	—
1990430	ST145	R510	5299	4498	STK45
1990431	ST145	R510	5299	4498	STK45
1990432	—	R511	5299	4498	—
1990434	ST147	R511	5299	4498	STK46
1990435	ST147	R511	5299	4498	STK46
1990436	ST147	R511	5299	4498	STK46
1990437	ST147	R511	5299	4498	STK46
1990438	ST145	R510	5299	4498	STK45
1990439	ST145	R510	5299	4498	STK45

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1990440	ST145	R510	5299	4498	STK45
1990441	ST145	R510	5299	4498	STK45
1990442	ST145	R510	5299	4498	STK45
1990446	ST145	R510	5299	4498	STK45
1990447	ST147	R511	5299	4498	STK46
1990448	ST164	R510	5299	4498	—
1990449	ST145	R510	5299	4498	STK45
1990450	ST164	R510	5299	4498	—
1990451	ST164	R510	5299	4498	—
1990452	ST164	R510	5299	4498	—
1990453	ST147	R511	5299	4498	STK46
1990454	ST147	R511	5299	4498	STK46
1990455	ST147	R511	5299	4498	STK46
1990456	ST147	R511	5299	4498	STK46
1990457	ST147	R511	5299	4498	STK46
1990458	ST164	R510	5299	4498	—
1990459	ST147	R511	5299	4498	STK46
1990460	ST147	R511	5299	4498	STK46
1990462	ST147	R511	5299	4498	STK46
1990463	ST147	R511	5299	4498	STK46
1990464	ST147	R511	5299	4498	STK46
1990466	ST164	R510	5299	4498	—
1990467	ST145	R510	5299	4498	STK45
1990468	ST145	R510	5299	4498	STK45
1990469	ST145	R510	5299	4498	STK45
1990470	ST145	R510	5299	4498	STK45
1990471	ST145	R510	5299	4498	STK45
1990473	ST164	R510	5299	4498	—
1990474	ST147	R511	5299	4498	STK46
1990475	ST145	R510	5299	4498	STK45
1990477	ST145	R510	5299	4498	STK45
1990478	ST145	R510	5299	4498	STK45
1990481	ST131	R518	5284	4498	STK20 ³⁰
1990481	ST131	R518	5284	4498	STK31 ³¹
1990482	ST135	—	5284	4498	—
1990483	ST145	R510	5299	4498	STK45
1990484	ST145	R510	5299	4498	STK45
1990485	—	R511	5299	4498	—
1990486	ST145	R510	5299	4498	STK45
1990487	ST145	R510	5299	4498	STK45
1990489	ST145	R510	5299	4498	STK45
1990490	ST145	R510	5299	4498	STK45
1990491	ST147	R511	5299	4498	STK46
1990492	ST145	R510	5299	4498	STK45
1990493	—	R511	5299	4498	—
1990494	ST145	R510	5299	4498	STK45
1990495	ST145	R510	5299	4498	STK45
1990496	ST145	R510	5299	4498	STK45

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1990497	ST147	R511	5299	4498	STK46
1990498	ST172	R512	5299	5299	—
1990499	ST146	R512	5299	5299	STK46
1990925	ST131	R518	—	—	—
1993700	ST132	—	5284	4498	STK21 ³⁰
1993700	ST132	—	5284	4498	STK32 ³¹
1993701	ST146	R513	5299	5299	STK46
1993702	ST146	R513	5299	5299	STK46
1993703	ST131	R518	5284	4498	STK20 ³⁰
1993703	ST131	R518	5284	4498	STK31 ³¹
1993704	ST132	—	5284	4498	STK21 ³⁰
1993704	ST132	—	5284	4498	STK32 ³¹
1993705	ST172	R512	5299	5299	—
1993707	ST146	R513	5299	5299	STK46
1993708	ST134	R520	—	4498	—
1993709	—	R512	5299	5299	—
1993711	—	R513	5299	5299	—
1993712	—	R512	5299	5299	—
1993713	ST172	R512	5299	5299	—
1993719	—	R512	5299	5299	—
1993723	—	R513	5299	5299	—
1993726	—	R512	5299	5299	—
1993728	—	R512	5299	5299	—
1993729	ST146	R513	5299	5299	STK46
1993732	ST146	R513	5299	5299	STK46
1993736	ST172	R512	5299	5299	—
1993737	ST172	R512	5299	5299	—
1993738	ST172	R512	5299	5299	—
1993739	ST132	R520	—	4498	STK21 ³⁰
1993739	ST132	R520	—	4498	STK32 ³¹
1993740	ST138	—	—	4498	—
1993741	ST146	R513	5299	5299	STK46
1993742	ST146	R513	5299	5299	STK46
1993743	—	—	—	4498	—
1993745	ST146	R513	5299	5299	STK46
1993746	—	R512	5299	5299	—
1993753	ST132	R520	—	4498	STK21 ³⁰
1993753	ST132	R520	—	4498	STK32 ³¹
1993754	—	R512	5299	5299	—
1993755	ST172	R512	5299	5299	—
1993756	ST172	R512	5299	5299	—
1993759	ST172	R512	5299	5299	—
1993761	ST172	R512	5299	5299	—
1993762	ST172	R512	5299	5299	—
1993763	ST172	R512	5299	5299	—
1993764	ST172	R512	5299	5299	—
1993765	ST172	R512	5299	5299	—
1993767	—	R512	5299	5299	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1993768	ST172	R512	5299	5299	—
1993769	ST172	R512	5299	5299	—
1993770	ST172	R512	5299	5299	—
1993771	ST146	R513	5299	5299	STK46
1993772	ST145	R510	5299	4498	STK45
1993773	ST146	R513	5299	5299	STK46
1993774	ST145	R510	5299	4498	STK45
1993775	ST145	R510	5299	4498	STK45
1993776	ST145	R510	5299	4498	STK45
1993778	ST146	R512	5299	5299	STK46
1993781	ST132	R520	—	4498	STK21 ³⁰
1993781	ST132	R520	—	4498	STK32 ³¹
1993782	ST164	R510	5299	4498	—
1993783	ST145	R510	5299	4498	STK45
1993784	ST147	R511	5299	4498	STK46
1993785	ST145	R510	5299	4498	STK45
1993786	ST147	R511	5299	4498	STK46
1993787	ST146	R512	5299	5299	STK46
1993788	ST147	R511	5299	4498	STK46
1993789	ST146	R512	5299	5299	STK46
1993790	—	R512	5299	5299	—
1993791	—	R512	5299	5299	—
1993792	—	R512	5299	5299	—
1993793	—	R512	5299	5299	—
1993794	ST172	R512	5299	5299	—
1993795	ST145	R510	5299	4498	STK45
1993796	ST147	R511	5299	4498	STK46
1993797	ST147	R511	5299	4498	STK46
1993798	ST138	R520	—	4498	—
1993799	—	R512	5299	5299	—
1993800	—	R512	5299	5299	—
1993801	ST147	R511	5299	4498	STK46
1993802	ST147	R511	5299	4498	STK46
1993803	ST145	R510	5299	4498	STK45
1993804	ST147	R511	5299	4498	STK46
1993805	ST147	R511	5299	4498	STK46
1993806	ST145	R510	5299	4498	STK45
1993807	ST145	R510	5299	4498	STK45
1993808	ST147	R511	5299	4498	STK46
1993810	ST147	R511	5299	4498	STK46
1993811	ST164	R510	5299	4498	—
1993812	ST147	R511	5299	4498	STK46
1993813	ST145	R510	5299	4498	STK45
1993814	ST147	R511	5299	4498	STK46
1993815	ST147	R511	5299	4498	STK46
1993816	ST145	R510	5299	4498	STK45
1993817	ST172	R512	5299	5299	—
1993818	—	R512	5299	5299	—

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1993819	ST172	R512	5299	5299	—
1993820	ST145	R510	5299	5299	STK45
1993822	ST184	R511	5299	4498	—
1993823	ST145	R510	5299	4498	STK45
1993824	ST164	R510	5299	4498	—
1993825	ST132	R520	—	4498	STK21 ³⁰
1993825	ST132	R520	—	4498	STK32 ³¹
1993826	ST147	R511	5299	4498	STK46
1993827	ST184	R511	5299	4498	—
1993828	ST147	R511	5299	4498	STK46
1993829	ST146	R513	5299	5299	STK46
1993831	ST146	R513	5299	5299	STK46
1993832	ST172	R512	5299	5299	—
1993833	ST147	R511	5299	4498	STK46
1993835	ST147	R511	5299	4498	STK46
1993838	—	R513	5299	5299	—
1993839	ST132	R520	—	4498	STK21 ³⁰
1993839	ST132	R520	—	4498	STK32 ³¹
1993840	ST132	R520	—	4498	STK21 ³⁰
1993840	ST132	R520	—	4498	STK32 ³¹
1993841	ST132	R520	—	4498	STK21 ³⁰
1993841	ST132	R520	—	4498	STK32 ³¹
1993842	ST147	R511	5299	4498	STK46
1993847	ST132	R520	—	4498	STK21 ³⁰
1993847	ST132	R520	—	4498	STK32 ³¹
1993849	ST145	R510	5299	4498	STK45
1993850	ST172	R512	5299	5299	—
1993851	ST143	R512	5299	5299	—
1993852	ST132	R520	—	4498	STK21 ³⁰
1993852	ST132	R520	—	4498	STK32 ³¹
1993853	ST172	R520	5299	5299	—
1993854	STH404	R520	5299	5299	—
1993855	ST172	R520	5299	5299	—
1993856	ST145	R510	5299	4498	STK45
1993859	ST131	R520	—	4498	STK20 ³⁰
1993859	ST131	R520	—	4498	STK31 ³¹
1993860	ST132	R520	—	4498	STK21 ³⁰
1993860	ST132	R520	—	4498	STK32 ³¹
1993861	ST146	R513	5299	5299	STK46
1993862	ST146	R513	5299	5299	STK46
1993863	ST145	R510	5299	4498	STK45
1993864	ST131	R520	—	4498	STK20 ³⁰
1993864	ST131	R520	—	4498	STK31 ³¹
1993865	ST172	R512	5299	5299	—
1993866	—	R512	5299	5299	—
1993869	ST172	R512	5299	5299	—
1993871	ST172	R512	5299	5299	—
1993873	ST172	R512	5299	5299	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1993874	ST172	R512	5299	5299	—
1993878	ST172	R512	5299	5299	—
1993879	ST172	R512	5299	5299	—
1993880	ST172	R512	5299	5299	—
1993881	ST172	R512	5299	5299	—
1993883	ST172	R512	5299	5299	—
1993884	ST172	R512	5299	5299	—
1993885	ST172	R512	5299	5299	—
1993886	ST172	R512	5299	5299	—
1993887	ST172	R512	5299	5299	—
1993891	—	R512	5299	5299	—
1993893	—	R512	5299	5299	—
1993894	ST143	R512	5299	5299	—
1993898	ST172	R512	5299	5299	—
1993901	ST101	R513	5299	5299	—
1993902	ST101	R513	5299	5299	—
1993903	ST101	R513	5299	5299	—
1993905	ST101	R513	5299	5299	—
1993909	ST101	R513	5299	5299	—
1993910	—	R513	5299	5299	—
1993911	—	R513	5299	5299	—
1993914	—	R513	5299	5299	—
1993917	ST102	R513	5299	5299	—
1993918	ST102	R513	5299	5299	—
1993919	—	R513	5299	5299	—
1993920	ST102	R513	5299	5299	—
1993921	ST102	R513	5299	5299	—
1993922	ST135	R520	—	4498	—
1993923	—	R511	5299	4498	—
1993924	—	R511	5299	4498	—
1993925	ST145	R510	5299	4498	STK45
1993926	—	R513	5299	5299	—
1993928	ST172	R512	5299	5299	—
1993930	ST102	R513	5299	5299	—
1993931	ST172	R512	5299	5299	—
1993932	—	R510	5299	4498	—
1993933	ST162	R511	5299	4498	—
1993934	—	R510	5299	4498	—
1993935	—	R510	5299	4498	—
1993936	ST162	R511	5299	4498	—
1993937	—	R510	5299	4498	—
1993938	—	R510	5299	4498	—
1993939	—	R510	5299	4498	—
1993940	ST162	R511	5299	4498	—
1993941	ST162	R511	5299	4498	—
1993942	—	R510	5299	4498	—
1993943	—	R510	5299	4498	—
1993944	ST162	R511	5299	4498	—

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1993945	ST162	R511	5299	4498	—
1993947	ST183	R512	5299	5299	—
1993950	ST172	R512	5299	5299	—
1993951	ST172	R512	5299	5299	—
1993953	ST102	R513	5299	5299	—
1993954	ST102	R513	5299	5299	—
1993955	ST102	R513	5299	5299	—
1993956	ST143	R512	5299	5299	—
1993957	ST143	R512	5299	5299	—
1993958	ST143	R512	5299	5299	—
1993959	—	R520	—	4498	—
1993960	—	R520	—	4498	—
1993961	ST145	R510	5299	4498	STK45
1993963	ST172	R512	5299	5299	—
1993964	ST172	R512	5299	5299	—
1993965	ST174	R512	5299	5299	—
1993966	ST173	R513	5299	5299	—
1993967	ST143	R512	5299	5299	—
1993968	ST131	R520	—	4498	STK20 ³⁰
1993968	ST131	R520	—	4498	STK31 ³¹
1993969	ST183	R512	5299	5299	—
1993970	ST183	R512	5299	5299	—
1993971	ST183	R512	5299	5299	—
1993972	ST101	R513	5299	5299	—
1993973	ST145	R510	5299	4498	STK45
1993974	ST183	R512	5299	5299	—
1993975	ST182	R510	5299	4498	—
1993977	—	R510	5299	4498	—
1993979	ST172	R512	5299	5299	—
1993980	ST162	R511	5299	4498	—
1993981	ST143	R512	5299	5299	—
1993982	—	R510	5299	4498	—
1993983	—	R510	5299	4498	—
1993984	—	R510	5299	4498	—
1993986	ST102	R513	5299	5299	—
1993987	ST147	R511	5299	4498	STK46
1993988	ST143	R512	5299	5299	—
1993989	ST132	R520	—	4498	STK21 ³⁰
1993989	ST132	R520	—	4498	STK32 ³¹
1993991	—	R511	5299	4498	—
1993992	ST143	R512	5299	5299	—
1993993	ST147	R511	5299	4498	STK46
1993994	ST172	R512	5299	5299	—
1993995	ST175	R513	5299	—	—
1993996	ST184	R511	5299	4498	—
1993997	ST183	R512	5299	5299	—
1993998	ST184	R511	5299	4498	—
1993999	ST184	R511	5299	4498	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1998201	—	R503	—	—	—
1998202	—	R503	—	—	—
1998203	—	R503	—	—	—
1998204	ST124	R503	—	5336	STK27
1998205	ST124	R503	—	5336	STK27
1998206	ST124	R503	—	5336	STK27
1998207	ST124	R503	—	—	STK27
1998208	ST124	R503	—	—	STK27
1998209	ST124	R503	—	—	STK27
1998210	ST124	R503	—	—	STK27
1998211	ST124	R503	—	—	STK27
1998212	—	R503	—	—	STK27
1998213	ST124	R503	—	—	STK27
1998214	ST124	R503	—	—	STK27
1998215	ST124	R503	—	—	STK27
1998216	ST124	R503	—	—	STK27
1998217	ST124	R503	—	—	STK27
1998218	ST124	R503	—	—	STK27
1998219	—	R503	—	—	STK27
1998220	ST124	R503	—	—	STK27
1998221	ST124	R503	—	—	STK27
1998222	ST124	R503	—	—	STK27
1998223	ST124	R503	—	5336	STK27
1998224	ST124	R503	—	5336	STK27
1998225	ST124	R503	—	5336	STK27
1998226	ST124	R503	—	5336	STK27
1998227	ST124	R503	—	—	STK27
1998228	ST124	R503	—	5336	STK27
1998229	ST124	R503	—	5336	STK27
1998230	ST124	R503	—	5336	STK27
1998231	ST124	R503	—	5336	STK27
1998232	—	R503	—	—	—
1998233	ST128	R503	—	5336	STK28
1998234	ST128	R503	—	5336	STK28
1998235	ST128	R503	—	5336	STK28
1998236	ST128	R503	—	5336	STK28
1998237	ST128	R503	—	5336	STK28
1998238	ST128	R503	—	—	STK28
1998239	ST128	R503	—	—	STK28
1998240	ST128	R503	—	5336	STK28
1998241	ST128	R503	—	—	STK28
1998242	ST128	R503	—	—	STK28
1998243	ST128	R503	—	—	STK28
1998244	ST128	R503	—	—	STK28
1998245	ST128	R503	—	5336	STK28
1998247	ST128	R503	—	5336	STK28
1998248	ST124	R503	—	5336	STK15
1998249	ST124	R503	—	5336	STK15

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1998250	ST124	R503	—	5336	STK15
1998251	ST128	R503	—	—	—
1998252	ST128	R503	—	—	—
1998253	ST128	R503	—	5336	STK28
1998256	ST124	R503	—	5336	STK15
1998257	ST124	R503	—	5336	STK15
1998258	ST128	R503	—	5288	STK28
1998259	ST128	R503	—	—	—
1998260	ST128	R503	—	5288	—
1998261	ST128	R503	—	5288	—
1998262	ST128	R503	—	—	—
1998263	ST128	R503	—	—	—
1998264	ST128	R503	—	—	STK28
1998265	ST128	R503	—	—	STK28
1998266	ST128	R503	—	—	—
1998267	ST128	R503	—	—	—
1998269	ST128	R503	—	—	—
1998270	ST128	R503	—	—	—
1998271	ST128	R503	—	—	—
1998272	ST128	R503	—	5288	—
1998273	ST128	R503	—	—	—
1998274	ST128	R503	—	—	—
1998275	ST128	R503	—	—	STK28
1998276	ST128	R509	—	—	—
1998279	ST128	R505	—	5288	STK28
1998280	ST128	R503	—	5288	—
1998281	ST128	R503	—	—	—
1998282	ST128	R503	—	—	—
1998283	ST128	R503	—	—	—
1998284	ST128	R503	—	—	—
1998285	ST128	R503	—	5288	STK28
1998286	ST128	R503	—	5336	STK28
1998287	ST128	R509	—	—	—
1998288	ST128	—	—	5288	—
1998289	ST128	—	—	5288	STK28
1998290	ST128	R503	—	—	STK28
1998292	ST128	R503	—	—	—
1998293	ST128	R503	—	—	—
1998294	ST128	R503	—	—	—
1998295	ST128	R503	—	—	—
1998296	ST128	—	4200	—	—
1998297	ST128	R503	—	—	—
1998298	ST128	R503	—	—	—
1998299	ST128	R503	—	—	—
1998300	ST128	R503	—	—	—
1998301	ST128	R503	—	—	STK28
1998302	ST128	R503	—	—	STK28
1998303	ST128	R503	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1998304	ST128	R503	—	—	—
1998305	ST128	R503	—	—	—
1998306	ST128	R503	—	—	—
1998307	ST128	R503	—	—	STK28
1998308	ST128	R503	—	—	—
1998309	ST128	R503	—	—	STK28
1998310	ST128	R503	—	—	—
1998311	ST128	R503	—	—	—
1998313	ST128	R503	—	—	STK28
1998314	—	R503	—	5336	—
1998315	ST128	R503	—	—	STK28
1998316	ST128	R503	—	—	STK28
1998317	—	R503	—	5336	—
1998318	—	R503	—	5336	—
1998320	—	R503	—	—	—
1998321	—	R503	—	5336	—
1998323	ST128	R503	—	—	—
1998324	ST128	R503	—	5288	—
1998325	ST128	R503	—	—	—
1998326	ST128	R503	—	—	STK28
1998327	ST128	R503	—	—	—
1998328	ST128	R503	—	—	STK28
1998329	ST128	R503	—	—	—
1998330	ST128	R509	—	—	—
1998331	ST128	R509	—	—	—
1998332	ST128	R509	—	—	—
1998333	ST128	R509	—	—	—
1998334	ST128	R509	—	—	—
1998335	ST128	R509	—	—	—
1998336	ST128	R509	—	—	—
1998337	ST128	R509	—	—	—
1998338	ST128	R509	—	—	—
1998339	ST128	R509	—	—	—
1998340	ST128	R509	—	—	—
1998341	ST128	R509	—	—	—
1998342	ST128	R509	—	—	—
1998343	ST128	R509	—	—	—
1998344	ST128	R509	—	—	—
1998345	ST128	R509	—	—	—
1998346	ST128	R509	—	—	—
1998347	ST128	R509	—	—	—
1998348	ST128	R509	—	—	—
1998349	ST128	R509	—	—	—
1998350	ST128	R509	—	—	—
1998351	ST335	—	—	—	—
1998352	ST128	R509	—	—	—
1998353	ST128	R509	—	—	—
1998354	ST128	R509	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1998355	ST128	R509	—	—	—
1998356	ST128	R509	—	—	—
1998357	ST128	R509	—	—	—
1998358	ST128	R509	—	—	—
1998359	ST128	R509	—	—	—
1998360	ST128	R509	—	—	—
1998361	ST128	R509	—	—	—
1998362	ST128	R509	—	—	—
1998363	ST128	R509	—	—	—
1998364	ST128	R509	—	—	—
1998365	ST128	R509	—	—	—
1998366	ST128	R509	—	—	—
1998367	ST128	R509	—	—	—
1998368	ST128	R509	—	—	—
1998370	ST128	R509	—	—	—
1998371	ST128	R509	—	—	—
1998373	ST128	R509	—	—	—
1998374	ST128	R509	—	—	—
1998375	ST128	R509	—	—	—
1998376	ST128	R509	—	—	—
1998377	ST128	R509	—	—	—
1998378	ST128	R509	—	—	—
1998379	ST128	R509	—	—	—
1998380	—	R509	—	—	—
1998381	ST128	R509	—	—	—
1998382	ST128	—	—	—	—
1998383	ST128	R509	—	—	—
1998384	ST128	R509	—	—	—
1998385	ST128	R509	—	—	—
1998386	ST128	R509	—	—	—
1998387	ST128	R509	—	—	—
1998388	ST128	R509	—	—	—
1998389	ST128	R509	—	—	—
1998390	ST128	R509	—	—	—
1998391	ST128	R503	—	—	—
1998392	ST128	R503	—	—	—
1998393	ST128	R503	—	—	STK28
1998394	ST128	R509	—	—	—
1998395	ST128	R503	—	—	—
1998396	ST128	R503	—	—	—
1998397	ST128	R503	—	—	—
1998398	ST128	R503	—	—	—
1998399	ST128	R503	—	—	—
1998400	ST128	R503	—	—	STK28
1998401	—	R509	—	4265	—
1998402	ST128	R504	—	—	—
1998403	ST128	R504	—	—	—
1998404	ST124	R503	—	5288	STK27

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1998405	—	R503	—	5288	—
1998408	ST128	R509	—	—	—
1998409	ST335	—	—	4265	—
1998410	ST128	R503	—	—	—
1998411	ST128	R503	—	—	—
1998412	ST128	R503	—	—	—
1998413	ST128	R503	—	—	—
1998414	ST128	R503	—	5288	—
1998415	ST128	R505	—	5288	STK28
1998416	ST128	R503	—	5288	—
1998418	ST128	R509	—	—	STK28
1998419	ST128	R503	—	—	—
1998421	ST124	R503	—	5288	STK27
1998422	ST128	R507	—	—	STK28
1998423	ST128	R509	—	—	—
1998424	ST128	R503	—	—	—
1998426	ST335	—	—	—	—
1998427	ST128	R507	—	—	STK28
1998428	ST128	R507	—	—	STK28
1998429	ST128	R507	—	—	STK28
1998430	ST128	R507	—	—	STK28
1998431	ST128	R507	—	—	STK28
1998434	ST128	R507	—	—	STK28
1998435	ST128	R503	—	—	STK28
1998436	ST128	R503	—	5336	STK28
1998437	ST128	R503	—	—	STK28
1998438	ST128	R503	—	—	—
1998439	ST128	R503	—	—	STK28
1998440	ST124	R503	—	—	STK27
1998441	ST128	R503	—	—	STK28
1998442	ST124	R509	—	4265	STK27
1998443	ST128	R503	—	—	—
1998444	ST128	R503	—	4292	STK28
1998445	ST128	R507	—	5336	STK28
1998446	—	R504	—	—	—
1998447	ST128	R507	—	4497	STK28
1998448	ST128	R507	—	—	STK28
1998449	ST128	R507	—	—	STK28
1998450	ST128	R507	—	—	STK28
1998451	ST128	R507	—	—	STK28
1998452	ST128	R503	—	—	STK28
1998453	ST128	R507	—	—	STK28
1998454	ST335	—	—	—	—
1998455	ST128	R509	—	—	—
1998456	ST128	R509	—	—	—
1998457	ST128	R509	—	—	—
1998459	ST335	—	—	—	—
1998460	—	R503	—	4292	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1998461	ST128	R503	—	5336	STK28
1998464	ST128	R509	—	—	—
1998465	ST128	R509	—	—	—
1998466	ST128	R507	4200	5336	STK28
1998467	ST128	R503	—	—	STK28
1998468	ST128	R509	—	—	—
1998469	ST124	R503	—	—	STK27
1998470	ST124	R503	—	5336	STK27
1998471	ST124	R503	—	5336	STK27
1998472	ST124	R503	—	5336	STK27
1998473	ST124	R503	—	4292	STK27
1998474	ST124	R503	—	5336	STK27
1998476	ST128	R507	—	—	—
1998477	ST128	R507	—	—	STK28
1998479	ST128	R509	—	—	—
1998480	ST128	R509	—	—	—
1998481	ST128	R509	—	—	—
1998482	ST128	R507	—	4497	STK28
1998483	ST128	R503	—	—	STK28
1998484	ST128	R509	—	—	—
1998485	ST128	R503	—	—	—
1998486	ST128	R509	—	—	—
1998488	ST335	—	—	—	—
1998489	ST128	R509	—	—	—
1998490	—	R509	—	—	—
1998491	ST128	R503	—	—	—
1998496	ST128	R509	—	—	—
1998498	—	R509	—	—	—
1998499	ST124	R503	—	5336	STK27
1998500	ST124	R503	—	5336	STK27
1998501	ST124	R503	—	5336	STK27
1998502	ST128	R507	—	—	—
1998503	ST128	R507	—	—	—
1998504	ST128	R507	—	—	—
1998505	ST128	R509	—	—	—
1998506	ST128	R509	—	—	—
1998507	ST128	R509	—	—	—
1998508	ST128	R509	—	—	—
1998509	ST128	R507	—	—	—
1998511	ST128	R507	—	—	STK28
1998512	ST128	R507	—	—	—
1998513	—	R503	—	5336	—
1998514	ST128	R507	—	—	STK28
1998515	ST128	R507	—	—	STK28
1998516	ST128	R503	—	5336	STK28
1998517	ST128	R503	—	5336	STK28
1998518	ST163	—	—	—	—
1998519	ST335	—	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1998521	ST128	R507	—	—	STK28
1998522	ST128	R509	—	—	—
1998523	ST128	R507	—	—	STK28
1998524	ST128	R507	—	—	STK28
1998525	ST128	R507	—	—	STK28
1998526	ST128	R507	—	5336	STK28
1998527	ST128	R507	—	—	STK28
1998528	ST128	R507	—	—	STK28
1998529	ST128	R507	—	4497	STK28
1998530	ST128	R507	—	—	STK28
1998531	ST128	R507	—	5336	STK28
1998532	ST128	R507	—	4497	STK28
1998533	ST128	R507	—	—	—
1998534	ST128	R507	—	—	—
1998535	ST128	R507	—	—	STK28
1998536	ST128	R507	—	—	STK28
1998542	ST128	R507	—	—	—
1998544	ST128	R507	—	5336	STK28
1998545	ST163	—	—	—	—
1998546	ST128	R507	—	—	STK28
1998547	ST128	R507	—	4497	—
1998548	ST128	R507	—	5336	STK28
1998550	ST128	R507	—	—	—
1998552	ST128	—	—	—	STK28
1998553	ST128	—	—	—	STK28
1998554	ST128	—	—	—	STK28
1998555	ST128	—	—	—	STK28
1998556	ST128	—	—	—	STK28
1998557	ST128	R503	—	5336	STK28
1998558	ST128	R503	—	—	STK28
1998559	ST128	R503	—	—	—
1998560	ST128	R503	—	—	STK28
1998561	ST128	R503	—	—	STK28
1998562	ST128	R503	—	—	STK28
1998563	ST128	R503	—	4292	STK28
1998564	ST128	R503	—	5336	STK28
1998565	ST128	R503	—	—	—
1998566	—	R503	—	5336	—
1998568	—	R503	—	5336	—
1998569	—	R503	—	5336	—
1998570	—	R503	—	5336	—
1998571	—	R503	—	5336	—
1998572	ST128	R503	—	5336	STK28
1998574	ST128	R503	—	—	STK28
1998575	ST128	R503	—	—	—
1998576	ST128	R503	—	—	—
1998577	ST128	R503	—	—	STK28
1998579	ST128	R503	—	—	STK28

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
1998580	ST128	R503	—	—	STK28
1998583	ST128	R503	—	5336	STK28
1998584	ST128	R503	—	5336	STK28
1998588	ST128	R503	—	5336	—
1998589	ST128	R503	—	5336	—
1998590	ST128	R503	—	5336	STK28
1998591	ST128	R503	—	5336	STK28
1998594	ST124	R503	—	5336	STK27
1998595	ST124	R503	—	5336	STK27
1998596	ST124	R503	—	5336	STK27
1998597	ST128	R503	—	—	STK28
1998598	ST128	R503	—	4292	STK28
1998599	—	R503	—	4292	—
9000719	ST128	R525	—	—	—
9000735	ST203	R525	—	—	—
9000762	—	R525	—	—	—
9000763	—	R525	—	—	—
9000768	—	R525	—	—	—
9000773	ST152	R525	—	—	—
9000775	—	R525	—	—	—
9000776	—	R525	—	—	—
9000789	—	R525	—	—	—
9000796	—	R525	—	—	—
9000797	—	R525	—	—	—
10455001	ST128	R507	—	—	STK28
10455004	ST128	R507	—	—	STK28
10455006	ST128	R507	—	—	STK28
10455007	ST128	R507	—	—	STK28
10455008	ST128	R507	—	—	—
10455009	ST128	R507	—	—	—
10455010	ST152	—	—	—	—
10455011	ST152	—	—	—	—
10455012	ST152	—	—	—	—
10455013	ST152	R503	—	—	—
10455015	ST128	R507	—	—	STK28
10455016	ST128	R507	—	—	STK28
10455017	ST128	R507	—	4497	STK28
10455018	ST128	R507	—	—	STK28
10455019	ST128	R507	—	—	STK28
10455020	ST128	R507	—	—	STK28
10455021	ST128	R507	—	—	STK28
10455022	ST128	R507	—	—	STK28
10455023	ST128	R507	—	—	—
10455024	ST128	R507	—	—	STK28
10455025	ST152	—	—	—	—
10455026	ST152	—	—	—	—
10455042	ST152	—	—	—	—
10455044	ST128	R507	—	—	STK28

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
10455045	ST128	R507	—	—	—
10455046	ST128	R507	—	—	—
10455047	ST152	—	—	—	—
10455048	ST152	—	—	—	—
10455049	ST128	R507	—	5336	—
10455050	ST152	—	—	—	—
10455051	ST152	—	—	—	—
10455052	ST128	R507	—	—	STK28
10455053	ST152	R507	—	—	—
10455054	ST152	—	—	—	—
10455055	ST128	R507	—	—	STK28
10455058	ST128	R507	—	—	—
10455060	ST152	—	—	—	—
10455061	ST152	—	—	—	—
10455064	ST171	—	—	—	—
10455065	ST171	—	—	—	—
10455066	ST171	—	—	—	—
10455067	ST171	—	—	—	—
10455069	ST171	—	—	—	—
10455070	ST152	—	—	—	—
10455072	ST171	—	—	—	—
10455073	ST171	—	—	—	—
10455074	ST171	—	—	—	—
10455076	ST152	—	—	—	—
10455081	ST171	—	—	—	—
10455300	ST128	R503	—	—	STK28
10455301	ST128	R503	—	—	STK28
10455305	ST128	R503	—	—	STK28
10455306	ST128	R503	—	—	—
10455308	ST124	R503	—	—	STK27
10455309	ST124	R503	—	5336	STK27
10455310	ST124	R503	—	5336	STK27
10455311	ST124	R503	—	5336	STK27
10455312	ST128	R503	—	—	—
10455314	ST128	R503	—	4292	—
10455315	ST128	R503	—	4292	STK28
10455316	ST128	R503	—	—	—
10455317	ST128	R503	—	—	—
10455318	ST128	R503	—	—	—
10455319	ST128	R503	—	—	STK28
10455320	ST128	R503	—	—	STK28
10455321	ST128	R503	—	—	—
10455322	—	R503	—	—	—
10455323	ST128	R503	—	—	—
10455324	ST128	R503	—	—	—
10455325	ST128	R503	—	—	—
10455326	ST128	R503	—	—	—
10455327	ST128	R503	—	—	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
10455328	ST128	R503	—	—	—
10455329	ST128	R503	—	—	—
10455330	ST128	R503	—	—	—
10455331	ST128	R503	—	—	—
10455332	ST128	R503	—	—	—
10455333	ST128	R503	—	—	—
10455334	ST128	R503	—	—	STK28
10455335	ST124	R503	—	—	STK27
10455336	ST128	R503	—	—	—
10455337	ST128	R503	—	—	—
10455338	ST128	R503	—	—	—
10455339	ST128	R503	—	—	—
10455340	ST128	R503	—	—	—
10455341	ST128	R503	—	—	STK28
10455343	ST124	R503	—	—	—
10455344	ST124	R505	—	5336	—
10455345	ST124	R505	—	5336	—
10455346	ST128	R505	—	5336	—
10455347	ST128	R503	—	—	—
10455348	ST128	R503	—	—	—
10455349	ST128	R503	—	—	—
10455350	ST128	R503	—	—	—
10455351	ST128	R503	—	—	—
10455352	ST128	R503	—	—	—
10455353	ST128	R503	—	—	—
10455354	ST128	R503	—	—	—
10455355	ST128	R503	—	—	—
10455356	ST128	R503	—	—	—
10455357	ST128	R503	—	4292	STK28
10455494	ST171	—	—	—	—
10455600	—	R503	—	4292	—
10455601	—	R503	—	4292	—
10455602	—	R503	—	4292	—
10455603	—	R503	—	5336	—
10455604	ST128	R503	—	5336	STK28
10461041	ST131	—	5284	4498	STK20 ³⁰
10461041	ST131	—	5284	4498	STK31 ³¹
10461045	ST131	—	5284	4498	STK20 ³⁰
10461045	ST131	—	5284	4498	STK31 ³¹
10461046	ST131	—	5284	4498	STK20 ³⁰
10461046	ST131	—	5284	4498	STK31 ³¹
10461047	ST132	—	5284	4498	STK21 ³⁰
10461047	ST132	—	5284	4498	STK32 ³¹
10461048	ST131	—	5284	4498	STK20 ³⁰
10461048	ST131	—	5284	4498	STK31 ³¹
10461059	ST131	—	5284	4498	STK20 ³⁰
10461059	ST131	—	5284	4498	STK31 ³¹
10461060	ST131	—	5284	4498	STK20 ³⁰

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
10461060	ST131	—	5284	4498	STK31 ³¹
10461061	ST131	—	5284	4498	STK20 ³⁰
10461061	ST131	—	5284	4498	STK31 ³¹
10464594	ST171	—	—	—	—
10465001	ST128	R503	—	—	—
10465036	ST128	R507	—	—	—
10465321	ST124	R503	—	—	—
10478800	—	R520	—	4498	—
10478801	ST145	R510	5299	4498	STK45
10478802	ST145	R510	5299	4498	STK45
10478803	ST145	R510	5299	4498	STK45
10478804	ST145	R510	5299	4498	STK45
10478805	ST143	R512	5299	5299	—
10478806	ST172	R512	5299	5299	—
10478807	ST138	R520	—	4498	—
10478808	ST138	R520	—	4498	—
10478809	—	R510	5299	4498	—
10478810	ST145	R510	5299	4498	STK45
10478811	ST102	R513	5299	5299	—
10478812	ST176	R512	5299	—	—
10478813	ST131	R520	—	4498	STK20 ³⁰
10478813	ST131	R520	—	4498	STK31 ³¹
10478814	—	R513	5299	5299	—
10478815	ST175	R513	5299	—	—
10478816	ST145	R510	5299	4498	STK45
10478817	ST177	R513	5299	—	—
10478818	ST176	R512	5299	—	—
10478819	ST102	R513	5299	5299	—
10478820	—	R511	5299	4498	—
10478824	—	R510	5299	4498	—
10478825	ST174	R512	5299	5299	—
10478826	ST173	R513	5299	5299	—
10478827	ST138	R519	5299	4498	—
10478828	ST138	—	5299	4498	—
10478829	ST138	—	5299	4498	—
10478830	—	—	—	4498	—
10478831	ST172	R512	5299	5299	—
10478832	—	R510	5299	4498	—
10478833	—	R510	5299	4498	—
10478836	ST184	R511	5299	4498	—
10478839	ST147	R511	5299	4498	STK46
10478843	ST134	R520	5299	4498	—
10478844	—	R520	5299	4498	—
10478845	—	R520	5299	4498	—
10478846	ST132	R520	5299	4498	STK21 ³⁰
10478846	ST132	R520	5299	4498	STK32 ³¹
10478848	—	R520	5299	4498	—
10478849	ST134	R520	5299	4498	—

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
10478850	—	R520	5299	4498	—
10478851	—	R520	5299	4498	—
10478852	—	R520	5299	4498	—
10478853	ST132	R520	5299	4498	STK21 ³⁰
10478853	ST132	R520	5299	4498	STK32 ³¹
10478854	—	R520	5299	4498	—
10478855	ST132	R520	5299	4498	STK21 ³⁰
10478855	ST132	R520	5299	4498	STK32 ³¹
10478856	ST132	R520	5299	4498	STK21 ³⁰
10478856	ST132	R520	5299	4498	STK32 ³¹
10478857	ST137	R520	5299	4498	—
10478858	—	R520	5299	4498	—
10478859	ST132	R520	—	4498	STK21 ³⁰
10478859	ST132	R520	—	4498	STK32 ³¹
10478860	ST132	R520	—	4498	STK21 ³⁰
10478860	ST132	R520	—	4498	STK32 ³¹
10478861	—	R520	—	4498	—
10478862	ST132	R520	—	4498	STK21 ³⁰
10478862	ST132	R520	—	4498	STK32 ³¹
10478863	ST132	R520	—	4498	STK21 ³⁰
10478863	ST132	R520	—	4498	STK32 ³¹
10478864	ST132	R520	—	4498	STK21 ³⁰
10478864	ST132	R520	—	4498	STK32 ³¹
10478865	ST132	R520	—	4498	STK21 ³⁰
10478865	ST132	R520	—	4498	STK32 ³¹
10478866	ST132	R520	—	4498	STK21 ³⁰
10478866	ST132	R520	—	4498	STK32 ³¹
10478867	—	R520	—	4498	—
10478868	—	R520	—	4498	—
10478869	ST132	R520	—	4498	STK21 ³⁰
10478869	ST132	R520	—	4498	STK32 ³¹
10478870	ST138	R520	—	4498	—
10478871	ST138	R520	—	4498	—
10478872	ST132	R520	—	4498	STK21 ³⁰
10478872	ST132	R520	—	4498	STK32 ³¹
10478873	ST132	R520	—	4498	STK21 ³⁰
10478873	ST132	R520	—	4498	STK32 ³¹
10478874	ST132	R520	—	4498	STK21 ³⁰
10478874	ST132	R520	—	4498	STK32 ³¹
10478875	ST138	R520	5299	4498	—
10478876	ST134	R520	—	4498	—
10478877	ST131	R520	—	4498	STK20 ³⁰
10478877	ST131	R520	—	4498	STK31 ³¹
10478878	ST132	R520	—	4498	STK21 ³⁰
10478878	ST132	R520	—	4498	STK32 ³¹
10478879	ST132	R520	—	4498	STK21 ³⁰
10478879	ST132	R520	—	4498	STK32 ³¹
10478880	ST132	R520	—	4498	STK21 ³⁰

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
10478880	ST132	R520	—	4498	STK32 ³¹
10478881	ST131	R520	—	4498	STK20 ³⁰
10478881	ST131	R520	—	4498	STK31 ³¹
10478882	ST132	R520	—	4498	STK21 ³⁰
10478882	ST132	R520	—	4498	STK32 ³¹
10478883	ST132	R520	—	4498	STK21 ³⁰
10478883	ST132	R520	—	4498	STK32 ³¹
10478884	ST132	R520	5299	4498	STK21 ³⁰
10478884	ST132	R520	5299	4498	STK32 ³¹
10478885	ST134	R520	—	4498	—
10478887	ST132	R520	—	4498	STK21 ³⁰
10478887	ST132	R520	—	4498	STK32 ³¹
10478888	ST132	R520	—	4498	STK21 ³⁰
10478888	ST132	R520	—	4498	STK32 ³¹
10478889	—	R520	—	4498	—
10478890	—	R512	5299	5299	—
10478892	ST184	R511	5299	—	—
10478893	ST182	R511	5299	—	—
10478894	ST145	R510	5299	—	STK45
10478895	ST145	R510	5299	4498	STK45
10478897	—	R512	5299	—	—
10478898	—	R513	5299	—	—
10478903	ST132	R520	5299	4498	STK21 ³⁰
10478903	ST132	R520	5299	4498	STK32 ³¹
10478905	ST132	R520	5299	4498	STK21 ³⁰
10478905	ST132	R520	5299	4498	STK32 ³¹
10478906	ST132	R520	5299	4498	STK21 ³⁰
10478906	ST132	R520	5299	4498	STK32 ³¹
10478907	ST132	R520	5299	4498	STK21 ³⁰
10478907	ST132	R520	5299	4498	STK32 ³¹
10478908	ST132	R520	5299	4498	STK21 ³⁰
10478908	ST132	R520	5299	4498	STK32 ³¹
10478909	ST132	R520	5299	4498	STK21 ³⁰
10478909	ST132	R520	5299	4498	STK32 ³¹
10478910	ST131	R520	5299	4498	STK20 ³⁰
10478910	ST131	R520	5299	4498	STK31 ³¹
10478911	ST132	R520	5299	4498	STK21 ³⁰
10478911	ST132	R520	5299	4498	STK32 ³¹
10478912	ST132	R520	5299	4498	STK21 ³⁰
10478912	ST132	R520	5299	4498	STK32 ³¹
10478915	ST134	R520	5299	4498	—
10478916	ST138	R520	5299	4498	—
10478917	ST131	R520	5299	4498	STK20 ³⁰
10478917	ST131	R520	5299	4498	STK31 ³¹
10478918	ST164	R510	5299	4498	—
10478919	ST138	—	5299	4498	—
10478921	—	R512	5299	5299	—
10478925	ST177	R513	5299	—	—

(continued on next page)

³⁰ Oval face unit ³¹ Square face unit

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
10478926	ST177	R512	5299	—	—
10478927	ST143	R512	5299	5299	—
10478928	ST143	R512	5299	5299	—
10478929	ST143	R512	5299	5299	—
10478930	ST143	R512	5299	5299	—
10478931	—	R510	5299	—	—
10478932	—	R510	5299	—	—
10478933	—	R510	5299	—	—
10478934	—	R510	5299	—	—
10478935	—	R510	5299	—	—
10478936	—	R510	5299	—	—
10478937	ST162	R511	5299	—	—
10478938	ST162	R511	5299	—	—
10478939	ST162	R511	5299	—	—
10478940	ST162	R511	5299	—	—
10478941	ST145	R510	5299	4498	STK45
10478942	ST145	R510	5299	4498	STK45
10478943	ST145	R510	5299	4498	STK45
10478944	ST145	R510	5299	4498	STK45
10478946	ST145	R510	5299	4498	STK45
10478947	ST145	R510	5299	4498	STK45
10478948	ST145	R510	5299	4498	STK45
10478949	ST174	R512	5299	5299	—
10478951	—	R510	5299	4498	—
10478952	ST162	R511	5299	4498	—
10478953	ST183	R512	5299	5299	—
10478957	ST143	R512	5299	5299	—
10478960	ST102	R513	5299	5299	—
10478961	ST175	R513	5299	—	—
10478962	ST145	R510	5299	5299	STK45
10478964	ST145	R510	5299	5299	STK45
10478965	ST164	R510	5299	5299	—
10478966	ST145	R510	5299	5299	STK45
10478967	ST145	R510	5299	5299	STK45
10478968	ST178	R510	5299	4498	—
10478971	ST178	R510	5299	4498	—
10478976	ST102	R513	5299	5299	—
10478977	ST164	R510	5299	4498	—
10478978	ST145	R510	5299	4498	STK45
10478979	ST184	R511	5299	4498	—
10478980	ST147	R511	5299	4498	STK46
10478981	ST147	R511	5299	4498	STK46
10478983	ST145	R510	5299	4498	STK45
10478984	ST164	R510	5299	4498	—
10478985	ST164	R510	5299	4498	—
10478986	ST147	R511	5299	4498	STK46
10478987	—	R511	5299	4498	—
10478988	ST162	R511	5299	4498	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
10478989	ST147	R511	5299	4498	STK46
10478990	ST147	R511	5299	4498	—
10478991	ST164	R510	5299	4498	—
10478992	ST145	R510	5299	4498	STK45
10478996	ST147	R511	5299	4498	STK46
10478997	ST145	R510	5299	4498	STK45
10478998	ST164	R511	5299	4498	—
10478999	—	R512	5299	—	—
10479000	ST145	R510	5299	4498	STK45
10479001	—	R520	—	4498	—
10479002	—	R520	—	4498	—
10479003	ST164	R510	5299	4498	—
10479004	—	R510	5299	4498	—
10479005	—	R510	5299	4498	—
10479006	—	R510	5299	4498	—
10479007	—	R510	5299	4498	—
10479008	ST162	R511	5299	4498	—
10479009	ST162	R511	5299	4498	—
10479010	ST162	R511	5299	4498	—
10479011	ST162	R511	5299	4498	—
10479012	ST147	R511	5299	4498	STK46
10479013	ST175	R513	5299	—	—
10479014	ST143	R513	5299	—	—
10479015	ST143	R513	5299	—	—
10479016	ST143	R513	5299	—	—
10479017	—	R510	5299	4498	—
10479018	ST145	R510	5299	4498	STK45
10479019	ST145	R510	5299	4498	STK45
10479020	ST102	R513	5299	—	—
10479021	ST145	R510	5299	4498	STK45
10479022	ST147	R511	5299	4498	STK46
10479023	—	R512	5299	—	—
10479024	—	R513	5299	—	—
10479026	—	R510	5299	4498	—
10479027	—	R510	5299	4498	—
10479028	—	R510	5299	4498	—
10479030	—	R510	5299	4498	—
10479034	ST143	R512	5299	5299	—
10479035	ST183	R512	5299	5299	—
10479036	ST172	R512	5299	5299	—
10479037	ST145	R510	5299	4498	STK45
10479038	ST145	R510	5299	4498	STK45
10479040	—	R510	5299	4498	—
10479041	—	R510	5299	4498	—
10479043	—	R513	5299	—	—
10479047	ST183	R526	—	—	—
10479050	ST138	R520	—	4498	—
10479052	—	R511	5299	4498	—

(continued on next page)

DELCO REMY (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
10479053	ST162	R511	5299	—	—
10479054	ST143	R512	5299	5299	—
10479060	—	R512	5299	—	—
10479061	—	R512	5299	—	—
10479062	ST145	R510	5299	4498	STK45
10479063	ST145	R510	5299	4498	STK45
10479064	ST145	R510	5299	4498	STK45
10479065	ST145	R510	5299	4498	STK45
10479067	ST147	R511	5299	4498	STK46
10479068	ST172	R512	5299	5299	—
10479069	ST183	—	5299	5299	—
10479071	—	R512	5299	—	—
10479072	ST182	R511	5299	4498	—
10479078	ST145	R511	5299	4498	STK45
10479080	ST145	R510	5299	4498	STK45
10479081	ST145	R510	5299	4498	STK45
10479082	ST145	R510	5299	4498	STK45
10479090	ST145	R510	5299	4498	STK45
10479091	—	R510	5299	4498	—
10479092	—	R510	5299	4498	—
10479099	ST145	R510	5299	4498	STK45
10479600	—	—	—	5243	—
10479604	ST149	R523	—	5243	—
10479605	—	—	—	5243	—
10479606	ST114	R523	—	5243	—
10479607	ST114	R523	—	5243	—
10479608	—	—	—	5243	—
10479611	—	—	—	5243	—
10479612	—	—	—	5243	—
10479613	ST114	R523	—	5243	—
10479614	—	R523	—	5243	—
10479615	—	R523	—	5243	—
10479616	—	—	—	5243	—
10479617	ST114	R523	—	5243	—
10479618	ST114	R523	—	5243	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End	Solenoid Repair Kit
10479619	—	R523	—	—	—
10479620	ST114	R523	—	5243	—
10479628	ST114	R523	—	5243	—
10479629	—	—	—	5243	—
10479630	ST114	R523	—	5243	—
10496873	ST171	—	—	—	—
11076334	ST33	R503	4200	5288	—
11109212	—	—	—	4200	—
11113184	ST113	R504	—	—	—
30001696	ST153	—	—	—	—
30005925	ST153	—	—	—	—
91172280	ST247	E512	—	—	—
91174247	ST153	—	—	—	—
91175987	ST294	—	—	4600	—
94022494	ST214	E582	—	—	—
94141664	ST241	—	—	—	—
94204438	ST203	E592	—	—	—
94338799	ST241	—	—	—	—
94480791	ST294	—	—	—	—
94857220	ST591	—	—	—	—
96051950	ST241	E704	—	4600	—
96054321	—	E591	—	—	—
96058456	ST241	E512	—	—	—
96058457	ST241	—	—	—	—
96062498	ST241	E704	—	4600	—
96062790	ST294	—	—	—	—
96064782	ST241	E512	—	—	—
96064783	ST241	—	—	—	—
96065247	ST247	—	—	—	—
96065611	ST247	E512	—	—	—
96067876	ST247	E512	—	—	—
104550023	ST128	R507	—	—	—

FORD-MOTORCRAFT

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
B6S818400	ST247	—	—	—
B7T11002A	ST81	R503	—	5288
B7TZ11002A	ST81	—	—	—
B7TZ11002B	ST81	—	—	5302
B8C11002A	ST81	F502	4264	5297
B8C11002C	ST81	—	4264	—
B8QH11002A	ST81	—	—	—
B9S11002A	ST81	F502	5339	5287

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
B9TF11001A	ST81	R504	—	—
B9TF11002A	ST81	R504	—	—
C0DF11001A	ST81	—	5339	5291
C0DF11001D	ST81	—	5339	5291
CONF11002A	ST542	F502	—	5297
CONN11001A	ST113	—	—	—
C1TF11001C	ST81	R85 ¹²	4286	—
C1VF11001D	ST81	—	5339	5291

(continued on next page)

¹² Packaged in bulk. Use as required.

FORD-MOTORCRAFT (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
C2AF11001A ...	ST81	F502	—	5297
C2AF11001B ...	ST81	F502	—	5297
C2AF11001C ...	ST81	F502	—	5297
C2AF11002A ...	ST81	F502	5339	5297
C2AZ110002A ...	ST81	F502	—	—
C2AZ11002A ...	ST81	F502	—	5297
C2DF11001A ...	ST81	F505	5295	5296
C2DF11001B ...	ST81	F505	5295	5296
C2DF11001C ...	ST81	F505	5295	5296
C2DF11001D ...	ST81	F505	5295	5296
C2DF11001E ...	ST81	F505	5295	5296
C2DF11001F ...	ST81	F505	5295	5296
C2DF11001G ...	ST81	F505	5295	5296
C2DF11001H ...	ST81	F505	5295	5296
C2DZ11002A ...	ST81	F505	5295	5296
C2OF11001A ...	ST81	—	5339	5291
C2OF11001B ...	ST81	—	5339	5291
C2OF11001C ...	ST81	—	5339	5291
C2OF11001D ...	ST81	—	5339	5291
C2OF11001E ...	ST81	—	5339	5291
C2OZ11002A ...	ST81	—	—	5291
C2OZ11002B ...	ST82	—	—	—
C2SF11001A ...	ST81	F502	5339	5297
C2SF11001B ...	ST81	F502	5339	5297
C2SF11001C ...	ST81	F502	5339	5297
C2TA11001B ...	ST81	—	—	—
C2TF11001B ...	ST81	F502	—	—
C2TZ11002B ...	ST81	F502	—	—
C2TZ11002C ...	ST81	—	—	—
C2TZ11002D ...	ST81	F502	—	—
C2VF11001C ...	ST81	—	5339	5291
C2VY11002A ...	ST81	—	5339	5291
C3A11001A ...	ST81	F502	—	5297
C3AF11001A ...	ST81	F502	5339	5297
C3DF11001A ...	ST81	F505	5295	5296
C3DF11001B ...	ST81	F505	5295	5296
C3DF11001D ...	ST81	F505	5295	5296
C3NF11001A ...	—	F502	—	—
C3NF11001B ...	—	F502	—	5297
C3NF11001C ...	ST542	—	—	—
C3NF11002A ...	ST541	F502	—	5287
C3NF11002B ...	ST542	F502	—	5297
C3NF11002C ...	ST542	—	—	5297
C3NF11002D ...	ST53	F502	—	5297
C3NF11002E ...	ST542	F502	—	5297
C3NF11002H ...	ST542	F502	—	5297
C3OF11001A ...	ST81	—	5289	5291
C3OF11001B ...	ST81	—	5339	5291

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
C3OZ11002B ...	ST81	—	5339	5291
C3OZ11002C ...	ST81	—	—	—
C3SF11001A ...	ST81	F502	5339	5297
C3TF11000A ...	—	—	4200	5288
C3TF11001A ...	ST81	R85 ¹²	4286	—
C3TF11001B ...	ST81	—	—	—
C3TZ11002A ...	ST81	R85 ¹²	4286	—
C3VF11001A ...	ST81	—	5339	5291
C4DF11001A ...	ST81	F505	5295	5296
C4DF11001B ...	ST81	F505	5295	5296
C4OF11001A ...	ST81	—	—	5291
C4OF11001B ...	ST81	—	5339	5291
C4OZ11001A ...	ST81	—	5339	5291
C4OZ11001B ...	ST81	—	5339	5291
C4TF11000A ...	ST81	R85 ¹²	4286	—
C4TF11001A ...	ST81	—	—	—
C4TF11001B ...	ST81	—	—	—
C4TF11001C ...	ST81	F502	—	—
C4TZ11002A ...	ST81	R85 ¹²	4286	—
C4TZ11002B ...	ST81	—	5295	—
C4VY11002A ...	—	—	5339	5291
C4ZF11001A ...	ST81	—	—	5291
C5AF11001A ...	ST81	—	—	5291
C5DF11001A ...	ST81	F505	5295	5296
C5DF11001B ...	ST81	F505	5295	5296
C5NF11001A ...	ST81	—	—	5291
C5NF11001B ...	ST81	—	—	5291
C5TF11000A ...	ST81	R85 ¹²	4286	—
C5TF11000B ...	ST81	R504	—	—
C5TF11001A ...	ST81	—	—	5291
C5TF11001B ...	ST81	—	—	5291
C5TZ11002A ...	ST81	—	—	5291
C5TZ11002D ...	ST82	—	5295	—
C6AF11001A ...	ST81	—	—	—
C6AF11001B ...	ST81	F505	5295	5296
C6AZ11002A ...	ST81	—	—	—
C6OF11001A ...	ST81	—	—	5291
C6OZ11002A ...	ST81	—	—	—
C6TA11001A ...	ST81	—	—	—
C6TF11000A ...	ST81	R85 ¹²	4286	—
C6TF11000B ...	ST81	R504	—	—
C6TF11000C ...	ST81	R85 ¹²	4286	—
C6TF11001B ...	ST113	—	—	—
C6TF11001C ...	—	R85	—	—
C6TZ11002A ...	ST81	R504	—	—
C6TZ11002B ...	ST81	—	—	—
C6TZ11002C ...	ST81	R504	—	—
C6TZ11002D ...	ST81	R85 ¹²	4286	—

(continued on next page)

¹² Packaged in bulk. Use as required.

FORD-MOTORCRAFT (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
C6TZ11002E ...	ST81	R85 ¹²	4286	—
C6VF11001A ...	ST81	—	—	—
C6VY11001A ...	ST81	—	—	—
C6VY11002A ...	ST81	—	—	—
C7AF11001 ...	ST81	—	—	—
C7AF11001A ...	ST81	—	—	5291
C7AF11001B ...	ST81	—	—	5291
C7AF11001C ...	ST81	—	—	5291
C7AF11001D ...	ST81	—	5295	5296
C7AF11001E ...	ST81	—	5339	—
C7AF11001F ...	ST81	—	—	5291
C7DF11001A ...	ST81	F505	5295	5296
C7DF11001F ...	ST81	F505	5339	5296
C7NF11001B ...	—	—	—	5291
C7NF11001C ...	—	—	—	5291
C7OF11001A ...	ST81	—	—	5291
C7TF11000A ...	ST81	R504	—	—
C7TF11000B ...	ST81	R85 ¹²	4286	—
C7TF11000C ...	ST81	R504	—	—
C7TF11001A ...	ST81	—	—	—
C7TF11001B ...	ST81	—	—	5291
C7TZ11002A ...	ST81	R504	—	—
C7TZ11002B ...	ST81	R85 ¹²	4286	—
C7TZ11002C ...	ST81	R504	—	—
C7VF11001A ...	ST81	—	5339	5291
C7ZF11001A ...	ST81	—	—	5291
C7ZF11001B ...	ST81	—	—	5291
C8AF11001A ...	ST81	—	—	—
C8AZ11002A ...	ST81	—	—	—
C8HF11001A ...	ST81	—	—	—
C8TF11000B ...	ST81	R85 ¹²	4286	—
C8TF11000C ...	ST81	R85 ¹²	4286	—
C8TF11001B ...	—	R85	—	—
C8TF11001C ...	—	R85	—	—
C8TZ11002A ...	ST81	R85 ¹²	4286	—
C8TZ11002B ...	ST81	R85 ¹²	4286	—
C8VF11000A ...	ST81	—	—	—
C8VF11001A ...	ST81	—	—	—
C8VY11002A ...	ST81	—	—	—
C8VY11002B ...	ST81	—	—	—
C8VY11002C ...	ST82	—	—	—
C9AF11001A ...	ST81	—	—	—
C9AF11001B ...	ST81	—	—	5291
C9HS11000C ...	ST131	R85 ¹²	4286	—
C9HS11001C ...	—	R85	—	—
C9ZF11001A ...	ST81	—	—	5291
D0AF11001A ...	ST81	—	—	5302
D0AF11001B ...	ST81	—	—	5302

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
D0AF11001C ...	ST81	—	—	5302
D0AF11001E ...	ST81	—	—	5302
D0DF11001A ...	ST81	F505	5295	5302
D0HS11000AA ...	—	R85 ¹²	4286	—
D0HZ11002A ...	ST131	R85	—	—
D0NF11001A ...	—	F504	—	—
D0OF11001A ...	ST81	—	—	5302
D0TF11001A ...	ST81	—	—	5302
D0VF11000A ...	ST117	—	—	—
D0VF11000AA ...	ST131	R85	—	—
D0VF11001A ...	ST117	—	5339	5339
D0VF11002A ...	ST117	—	—	—
D0VY11002A ...	ST117	—	—	—
D0ZF11001A ...	ST81	—	—	5302
D0ZF11001B ...	ST81	—	—	5302
D1AF11001AA ...	ST81	—	—	5302
D1AZ11002A ...	ST82	—	—	5302
D1FF11001AA ...	—	—	—	5302
D1FZ11002A ...	ST81	F505	—	5302
D1PF11001AA ...	—	F508	—	5302
D2AF11001AA ...	ST82	—	—	5302
D2AF11001BA ...	ST81	—	—	—
D2AF11001CA ...	ST82	—	—	5302
D2AF11001DA ...	ST82	—	—	5302
D2AF11001EA ...	ST82	—	—	—
D2AF11001HA ...	ST82	—	—	5302
D2AF11001JA ...	ST82	—	—	5302
D2FZ11002A ...	ST81	F505	—	5302
D2OF11001AA ...	ST81	—	—	5302
D2OF11001BA ...	ST82	—	—	5302
D2TF11001AA ...	—	—	—	5302
D2TF11001BA ...	—	—	—	5302
D2VF11000AA ...	ST117	—	—	—
D2VF11001A ...	ST117	—	5339	—
D2VF11001AA ...	ST117	—	5339	—
D2ZF11001AA ...	ST81	—	—	5302
D2ZF11001BA ...	ST81	—	—	5302
D2ZF11001CA ...	ST82	—	—	5302
D3HF11000AA ...	ST81	R85 ¹²	4286	—
D3HF11000BA ...	—	R85 ¹²	4286	—
D3OZ11002A ...	ST82	—	—	—
D3TF11000AA ...	—	R85 ¹²	4286	—
D3TF11000BA ...	—	R85 ¹²	4286	—
D3TF11000CA ...	—	R85 ¹²	4286	—
D3TF11000DA ...	—	F504	—	—
D3TF11001CA ...	ST81	—	—	—
D3TF11001DA ...	ST81	—	—	—
D3TZ11002C ...	ST81	—	—	—

(continued on next page)

¹² Packaged in bulk. Use as required.

FORD-MOTORCRAFT (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
D4AF11000AA .	—	—	—	5302
D4AF11000BA .	—	—	—	5302
D4AF11001AA .	ST82	—	—	—
D4AF11001BA .	ST82	—	—	—
D4AZ11002A . . .	ST82	—	—	—
D4FZ11002B . . .	ST82	F505	5295	5302
D4HF11000BA .	ST81	R504	—	—
D4HF11000CA .	ST81	—	—	—
D4HF11001AA .	ST81	—	—	—
D4HZ11002C . . .	ST81	—	—	—
D4NN11000A . .	ST81	—	—	—
D4OF11001AA .	ST82	—	—	—
D4OF11001BA .	ST82	—	—	—
D4OZ11002A . .	ST82	—	—	5302
D4TF11000CA .	ST82	R85	—	—
D4TF11001AA .	ST117	—	5339	5339
D4TF11001BA .	ST117	—	5339	5339
D4TZ11002A . . .	—	R85 ¹²	—	—
D4TZ11002B . . .	—	R85 ¹²	—	—
D4TZ11002C . . .	—	R85 ¹²	4286	—
D4TZ11002D . . .	ST82	—	—	—
D4TZ11002E . . .	—	R85 ¹²	4286	—
D4VF11000A . . .	ST81	—	5339	—
D4VF11000AA .	ST117	—	—	—
D4VF11000BA .	ST117	—	—	—
D4VF11001AA .	—	F504	—	—
D4VF11001BA .	—	F504	—	—
D4VY11002A . . .	ST117	—	—	—
D4VY11002B . . .	—	—	SD1114	—
D4ZF11001AA .	ST82	—	—	5302
D4ZF11001AB .	ST82	—	—	5302
D4ZF11001BA .	ST82	—	—	5302
D4ZZ11002A . . .	ST82	—	—	5302
D5AF11001AA .	ST117	—	5339	—
D5AF11001AB .	ST82	—	—	—
D5AF11001BA .	ST117	—	—	5302
D5AF11001BB .	ST82	—	—	5302
D5AF11001EA .	ST82	—	—	5302
D5AZ11002A . . .	ST82	—	—	—
D5AZ11002B . . .	ST82	—	—	5302
D5AZ11002C . . .	ST82	—	—	5302
D5OF11001AA .	ST82	—	—	5302
D5OF11001BA .	ST82	—	—	5302
D5TF11001AA .	ST81	—	—	5302
D5TF11001BA .	ST81	—	—	5302
D5TF11001DA .	ST82	—	—	—
D5TZ11002A . . .	ST81	—	—	5302
D5VF11000AA .	—	F504	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
D5VF11000AB .	ST117	—	5339	—
D5VF11001AB .	—	F504	—	—
D6AF11001AA .	ST82	—	—	—
D6AZ11002A . . .	ST82	—	—	—
D6BF11001AA .	ST82	—	—	5302
D6BF11001BA .	ST81	—	—	5302
D6DZ11002A . . .	ST82	—	—	5302
D6DZ11002B . . .	ST81	—	—	5302
D6EF11001AA .	ST82	—	—	5302
D6EF11001BA .	—	F505	—	5302
D6FZ11002A . . .	ST82	—	—	5302
D6FZ11002B . . .	ST82	F505	5295	5302
D6OF11001AA .	ST82	—	—	5302
D6OZ11002A . .	ST82	—	—	5302
D6TF11001AA .	ST81	—	—	5302
D6TF11001BA .	ST81	—	—	5302
D6TF11001CA .	ST81	—	—	—
D6TF11001DA .	ST81	—	—	5302
D6TZ11002A . . .	ST81	—	—	5302
D6TZ11002B . . .	ST81	—	—	5302
D6TZ11002C . . .	ST81	—	—	—
D6TZ11002D . . .	ST81	—	—	5302
D7AZ11002A . . .	—	—	—	5302
D7AZ11002B . . .	ST81	—	5339	—
D7DZ11002A . . .	ST82	—	—	5302
D7DZ11002B . . .	ST81	—	—	5302
D7HF11001AA .	ST81	—	—	4483
D7HF11001BA .	ST81	—	—	4483
D7HT11001BA .	STH404	—	—	—
D7HZ11002A . . .	ST81	—	—	5302
D7NN11001A . .	ST81	—	—	—
D7NN11001B . .	ST81	—	—	—
D7OZ11002A . . .	—	—	—	5302
D7TZ11002A . . .	—	—	—	5302
D7ZZ11002A . . .	ST82	—	—	5302
D8AF11001AA .	—	F508	—	5302
D8AF11001BA .	—	F508	—	—
D8BF11001AA .	ST82	F508	—	5302
D8BF11001BA .	ST81	F508	—	5302
D8BF11001CA .	ST82	F508	—	5302
D8BZ11002A . . .	ST82	—	—	5302
D8EF11001AA .	ST82	F508	—	5302
D8EF11001CA .	ST81	F508	5339	5302
D8EF11001HA .	ST81	F508	—	5302
D8FF11001HA .	—	F508	5339	5302
D8FZ11002A . . .	ST82	F505	5295	5302
D8FZ11002B . . .	ST82	—	—	5302
D8HF11001AA .	ST81	F508	—	5302

(continued on next page)

¹² Packaged in bulk. Use as required.

FORD-MOTORCRAFT (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
D8HT11001AA .	ST81	—	—	—
D8HZ11002C . . .	ST82	—	—	—
D8HZ11002E . . .	ST81	—	—	—
D8LF11001AA .	—	—	5339	—
D8OF11001AA .	—	F508	—	5302
D8TF11001AA .	—	F508	—	5302
D8ZF11001AA .	ST82	F508	—	5302
D9HT11001AA .	STH404	F508	—	—
D9HZ11002A . . .	STH404	—	—	—
D12F11001AA . .	ST81	F505	—	5302
D12F11001AB . .	ST81	F505	—	5302
D12F11001BA . .	ST81	F505	5339	5302
D22F11001AA . .	ST81	F505	—	5302
D22F11001AB . .	ST81	F505	5295	5302
D22F11001BA . .	ST81	F505	5295	5302
D27Z11002A . . .	ST200	—	—	4600
D32F11001AA . .	—	F505	—	5302
D42F11001AA . .	ST81	F505	5295	5302
D42F11001AB . .	ST81	F505	5295	5302
D42F11001BA . .	ST82	F505	5295	5302
D77Z11002A . . .	—	—	—	4600
D77Z11002B . . .	—	—	—	4600
D97Z11002A . . .	ST200	—	—	4600
D37311002A . . .	ST200	—	—	4600
E0HT11000AA .	STH404	R85 ¹²	—	—
E0HT11000AB .	STH404	R85 ¹²	—	—
E0HZ11002A . . .	—	R85 ¹²	—	—
E0HZ11002B . . .	STH404	—	4286	—
E1AF11001BA .	—	F508	—	5302
E1AZ11002B . . .	—	—	—	5302
E1BF11001AA .	—	F508	—	5302
E1BF11001BA .	—	F508	—	5302
E1BZ11002A . . .	—	—	—	5302
E1BZ11002B . . .	ST82	—	—	5302
E1EF11001AC .	—	F508	—	5302
E1EF11001AD .	—	F508	—	5302
E1FZ11002A . . .	—	—	—	5302
E1FZ11002B . . .	ST82	—	—	5302
E1HF11001AA .	STH404	F508	5289	—
E1HT11001AA .	ST82	—	—	4483
E1HT11001AB .	STH404	—	—	—
E1HT11001BA .	ST82	—	—	4483
E1HT11001BB .	STH404	—	—	—
E1HT11001CA .	ST82	—	—	4483
E1HT11001CB .	STH404	—	—	—
E1HT11001DA .	ST82	—	—	4483
E1HT11001DB .	STH404	—	—	—
E1HT11001EA .	ST82	—	—	4483

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
E1HT11001EB .	STH404	—	—	—
E1HT11001FA . .	ST82	—	—	4483
E1HT11001FB . .	STH404	—	—	—
E1HZ11002A . . .	STH404	—	5289	—
E1PZ11002A . . .	—	—	—	5302
E1TF11001AA . .	—	F508	—	5302
E1TF11001BA . .	—	F508	—	5302
E1TF11001CA . .	STH404	F508	—	—
E1TZ11002A . . .	—	—	—	5302
E1TZ11002B . . .	—	—	—	5302
E1TZ11002C . . .	STH404	—	—	—
E1ZF11001AA . .	—	F508	—	5302
E1ZF11001AB . .	—	F508	—	5302
E1ZZ11002A . . .	—	—	—	5302
E1ZZ11002B . . .	—	—	—	5302
E2BF11001AA .	—	—	—	5302
E2BZ11002A . . .	—	—	—	5302
E2EF11001AA .	—	F508	—	5302
E2FZ11002A . . .	ST82	—	—	5302
E2HT11001AA .	STH404	—	4286	—
E2HT11001BA .	—	—	—	4483
E2HT11001CA .	—	R520	—	4483
E2HZ11002A . . .	STH404	—	4286	—
E2PF11001BA .	—	F508	—	5302
E2PF11001CA .	—	F508	—	5302
E2SF11001AA .	ST82	F508	—	5302
E2SZ11002A . . .	—	—	—	5302
E2TF11001AA . .	ST82	F508	—	5302
E2TZ11002A . . .	ST82	—	—	5302
E3AF11001AA .	—	—	—	5302
E3AZ11002A . . .	—	—	—	5302
E3EF11001AA .	—	F509	—	5302
E3FZ11002A . . .	—	—	—	5302
E3TF11000AA . .	—	R509	—	—
E3TF11001AA . .	—	F509	—	5302
E3TZ11002D . . .	ST82	—	—	5302
E4AF11001AA .	—	F509	—	5339
E4DF11001AA .	—	F509	—	5339
E4DF11001BA .	—	F509	—	—
E4EF11001AA .	—	F509	—	—
E4EF11001BA .	—	F509	—	5302
E4FZ11002A . . .	ST126	—	—	—
E4LF11001AB . .	—	F509	—	—
E4SF11001AA .	—	F509	—	—
E4TF11001A . . .	—	F509	—	5302
E4TF11001AA . .	—	F509	—	5339
E4TZ11002B . . .	STH404	—	—	—
E5TF11000AA . .	ST82	—	—	—

(continued on next page)

¹² Packaged in bulk. Use as required.

FORD-MOTORCRAFT (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
E6DF11001AA . . .	—	F509	—	—
E6DF11001BA . . .	—	F509	—	—
E6DZ11002A . . .	STH404	—	—	—
E6DZ11002B . . .	STH404	—	—	—
E6EF11001AA . . .	—	F509	—	—
E6EF11001BA . . .	—	—	SD1114	5302
E6HT11001AA . . .	—	—	—	4483
E7DF11001AA . . .	ST406	F509	—	—
E7ZF11001AA . . .	—	F509	—	—
E8DF11001AA . . .	—	F509	—	—
E8TF11001AA . . .	STH404	—	—	—
E9OF11000AA . . .	ST406	—	—	5302
E9OF11000BA . . .	ST406	—	—	5302
E9SF11000AA . . .	ST406	—	—	5302
E9SF11000BA . . .	ST406	—	—	5302
E17Z11002A . . .	—	—	—	4600
E17Z11002B . . .	—	—	—	4600
E17Z11002C . . .	—	—	—	4600
E25F11001AA . . .	ST82	—	—	5302
E25Y11002A . . .	—	—	—	5302
E25Z11002A . . .	ST126	—	—	5302
E37F11001AA . . .	—	F509	—	5302
E37F11001BA . . .	ST82	—	—	—
E43F11001AA . . .	—	F509	—	—
E43Z11002A . . .	STH404	—	—	—
E47F11001AA . . .	—	F509	5339	—
E47F11001BA . . .	—	F509	—	—
E57F11000AA . . .	STH404	E511	—	—
E69F11001AA . . .	STH404	F509	5302	5339
F0CU11000AA . . .	ST406	—	—	5302
F0CU11000AB . . .	ST406	—	—	—
F0CU11000BA . . .	ST406	—	—	5302
F0OU11001AA . . .	ST406	—	—	—
F1VU11000AA . . .	ST203	—	—	—
F2DU11000AA . . .	ST406	—	—	—
F2DU11000BA . . .	ST406	—	—	—
F2HT11000AA . . .	ST406	—	—	—
F2HT11000BA . . .	ST406	—	—	—
F2VU11000AC . . .	ST406	—	—	—
F2VU11000AD . . .	ST406	—	—	—
F02U11000AA . . .	—	—	—	5302
F07F11001BA . . .	STH404	—	—	—
F07U11000AA . . .	—	—	—	5302
F07U11000BA . . .	—	—	—	5302
F13U11000AA . . .	ST406	—	—	—
F17U11000AB . . .	—	—	—	5302
FAC11001B	ST53	F502	5339	5287
FAC11001E	ST53	F502	5339	5287

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
FAC11001H	—	F502	—	—
FAC11001P	ST58	F502	5339	5287
FAC11001S	ST53	F502	5339	5287
FAC11002B	ST58	F502	5339	5287
FAC11002G	ST58	F502	5339	5287
FAC11002N	ST541	F502	5339	5287
FAD11002A	ST53	F502	5339	—
FAE11002A	ST58	F502	5339	—
FAF11001A	ST58	F502	5339	—
FAG11000A	ST81	—	4264	—
FAG11001B	ST58	F502	5339	5287
FAG11001D	ST58	F502	5339	5287
FAH11000A	ST81	—	4264	—
FAH11001A	—	F502	—	—
FAH11002A	—	F502	5339	—
FAJ11002A	ST58	F502	5339	—
FAM11001A	ST58	—	5339	—
FAM11001B	ST58	F502	5339	—
FAR11001A	ST81	F502	5339	5297
FAR11001B	ST58	F502	5339	—
FAY11001A	ST81	F502	5339	5297
FAY11002A	ST81	F502	5339	5287
IA11002A	ST53	F502	5339	—
IBA11001A	ST58	F502	5339	—
ICM11001C	ST58	F502	5339	—
ICM11002A	ST53	F502	5339	—
MB35918400A . . .	ST416	—	—	—
MB35918400C . . .	ST416	—	—	—
ML4358	STH404	—	—	—
PB6M11002	ST81	F502	5339	5287
SFD016903	ST131	—	—	—
1BA11001A	—	F502	—	—
1CM11001C	—	F502	—	—
3T66074	—	E511	—	—
7EH11001B	—	F502	5339	—
7EH11002B	ST53	F502	5339	—
7RA11001	—	F502	—	—
7RA11001A	ST58	F502	5339	5339
7RA11002	ST53	F502	5339	—
8AL11002A	ST53	F502	5339	—
8AL11002B	ST53	F502	5339	—
8AQ11002A	ST53	F502	5339	—
8EL11001B	—	F502	—	—
8EQ11001A	—	F502	—	—
8N11001	ST540	F502	5339	—
74EB11000BA . . .	—	E552	—	—
76EB11000BA . . .	—	E552	—	—
76EB11000CA . . .	—	E552	—	—

(continued on next page)

FORD-MOTORCRAFT (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
1311033	—	E552	—	—
1311046	—	E552	—	—
1311049	—	E552	—	—
1311107	—	E552	—	—
1311120	—	E552	—	—
1311121	—	E552	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
1811001	—	F502	—	—
2900550	ST81	F502	5339	5297
2900557	ST81	F502	5339	5297
2900726	—	F502	—	5297
2900804	ST542	F502	—	—

HITACHI

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
S1345B	ST248	—	—
S114170E	ST205	E582	—
S114180G	ST205	E582	—
S114229F	ST205	E582	—
S114254B	ST208	E593	—
S114295	ST304	E582	—
S114305	ST244	—	—
S114348	ST281	E582	—
S114348B	ST281	E582	—
S114393	—	E593	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
S114396	—	E704	—
S114396D	—	E704	—
S114461	ST288	E582	—
S114528	ST269	—	—
S114607	ST282	—	—
50020460	—	E700	—
50036177	—	E700	—

HONDA

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
31200P01005 ..	ST322	—	—
31200P03005 ..	ST322	—	—
31200P03902 ..	ST322	—	—
31200P30902 ..	ST322	—	—
31200PB1934 ..	ST256	E704	—
31200PB1935 ..	ST244	—	—
31200PC0004 ..	ST256	E704	—
31200PC0891 ..	—	E591	—
31200PC1004 ..	ST256	E704	—
31200PC2014 ..	—	E591	—
31200PC2661 ..	—	E591	—
31200PE0013 ..	ST256	E704	—
31200PE0015 ..	—	E704	—
31200PE0661 ..	—	E591	—
31200PE0901 ..	ST256	E704	—
31200PE0902 ..	—	E704	—
31200PM3003 ..	—	E591	—
31200PM5L01 ..	—	E704	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
31200PT0906 ..	ST322	—	—
3110060A11 ...	ST247	E512	—
3110060A12 ...	ST247	E512	—
3110060A22 ...	ST247	E512	—
3110060B51 ...	ST294	—	—
3110064B12 ...	ST247	E512	—
31100826D2 ...	ST247	—	—
31100860D2 ...	ST247	E512	—
3110082612 ...	ST241	—	—
3110083031 ...	ST247	—	—
3110086032 ...	ST247	E512	—
31200657016 ..	—	E591	—
31200657025 ..	ST244	—	—
31200657671 ..	—	E591	—
31200671671 ..	—	E591	—
31200689661 ..	—	E591	—
31200689662 ..	—	E591	—

I.H.C.

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
67928C91	ST113	R85	—	—
70954C91	ST124	—	—	—
107365C91	ST113	R504	—	—
107369C91	ST113	R504	—	—
107581C91	ST113	R504	—	—
387036R91	—	R503	—	4200
396459R93	—	—	4310	4310
400121R92	ST113	R504	4310	4310

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
403298R91	ST113	R504	4310	4310
403299R91	ST124	R503	—	—
403300R92	ST124	—	—	—
445079C91	ST124	R503	—	5336
528012R91	ST113	R504	—	—
1014321C91 ...	—	—	4600	—

ISUZU

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
8104550160 ...	ST128	—	—
8104550230 ...	ST128	—	—
8104550250 ...	ST152	—	—
8941155670 ...	ST301	—	—
8941305600 ...	ST203	—	—
8941416642 ...	ST241	E704	—
8941416643 ...	ST241	E704	—
8941566710 ...	—	E591	—
8941723260 ...	—	E591	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
8942226880 ...	ST203	—	—
8942340650 ...	ST203	—	—
8942363471 ...	ST301	—	—
8942510882 ...	ST241	—	—
8943387981 ...	—	E591	—
8944393150 ...	ST241	E704	—
8944497820 ...	ST241	—	—

LUCAS

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
25022	ST81	—	—
25022M	—	E501	—
25022N	—	E501	—
25022Q	—	E501	—
25022R	—	E501	—
25022T	—	E501	—
25038	—	E501	—
25061	—	E501	—
25063	—	E501	—
25065	—	E501	—
25071	—	E501	—
25075	—	E501	—
25075A	—	E501	—
25075D	—	E501	—
25076	—	E501	—
25076E	—	E501	—
25076H	—	E501	—
25079E	—	E501	—
25079H	—	E501	—
25083A	—	E501	—
25083E	—	E501	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
25083F	—	E501	—
25085A	—	E501	—
25085B	—	E501	—
25087	—	E501	—
25088	—	E501	—
25096	—	E501	—
25105	—	E501	—
25112	—	E501	—
25118	—	E501	—
25122	—	E501	—
25129	—	E501	—
25132	—	E501	—
25142	—	E501	—
25147	—	E502	—
25149	—	E502	—
25181	—	E501	—
25300A	—	E501	—
25300H	—	E501	—
25301A	—	E501	—
25301D	—	E501	—
25304A	—	E501	—

(continued on next page)

LUCAS (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
25307A	—	E501	—
25307B	—	E501	—
25659	—	E502	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
25674	—	E503	—
25707	—	E503	—

MAZDA

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
AM1518400 ...	ST268	—	—	5343
B5C11002A ...	ST58	F502	5339	5287
B6A11002A ...	ST81	F502	5339	5287
B6C11002A ...	ST81	—	4264	—
B6DK18400 ...	—	—	AD1245	—
B6S818400A ...	—	E508	5342	—
B61P18400 ...	ST247	—	5342	5343
B61R18400A ...	—	—	5342	—
B30118400B ...	—	—	—	5343
B30118400C ...	—	E508	5342	5343
B31518400B ...	—	E508	5342	5343
B35918400 ...	—	—	—	5343
B35918400A ...	—	—	—	5343
B50518400 ...	—	—	5342	5343
B59318400 ...	—	E508	5342	5343
B63018400 ...	—	—	—	5343
B63018400A ...	ST247	—	—	5343
B65818400A ...	ST247	E508	—	—
B67618400A ...	ST247	—	—	5343
B67618400B ...	ST247	—	5342	5343
BPD418400A ...	—	—	—	5343
BPE918400 ...	ST247	E512	—	—
D50518400A ...	ST246	E508	—	5344
D50518400B ...	—	E508	5342	5343
D53018400 ...	—	E508	5342	5343
E35618400B ...	—	E508	5342	5343
F2D418400 ...	ST247	—	—	5343
F2D418400A ...	—	—	—	5343
F8B118400C ...	—	E508	5342	5343
F21418400B ...	ST247	—	—	5343
F21418400C ...	—	—	—	5343
F22518400A ...	—	—	—	5343
F24018400 ...	—	E508	—	—
F24018400B ...	—	E508	5342	—
F27018400B ...	ST247	E508	—	—
F27118400A ...	ST247	—	—	—
F80218400B ...	—	E508	—	5344
F85018400E ...	—	E508	5342	5343
FE1H18400 ...	ST247	—	—	5343
FE1J18400A ...	—	E508	5342	5343

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
FE5A18400A ...	—	E508	5342	—
FE5018400E ...	—	E508	5342	—
FP1318400 ...	—	—	—	5343
FS0518400 ...	—	—	—	5343
FS1118400 ...	—	—	—	5343
G60218400A ...	ST212	E580	—	—
G60218400B ...	ST212	E580	—	—
JE0118400A ...	—	—	—	5343
JE0118400B ...	—	—	—	5343
JE1618400 ...	—	—	—	5343
JE1618400A ...	—	—	—	5343
JE2618400 ...	—	—	—	5343
JE2618400A ...	ST246	—	—	5343
JE2718400D ...	ST579	—	—	—
JE4818400 ...	ST579	—	—	—
JE4918400 ...	ST579	—	—	—
JF0118400B ...	—	—	—	5343
JF0118400C ...	—	—	—	5343
JF2718400B ...	ST246	—	—	5343
K80518400 ...	—	—	—	5343
KL0618400B ...	ST310	—	—	—
KL0618400F ...	ST287	—	—	—
KL1118400 ...	—	—	—	5343
KL3618400 ...	—	E512	—	—
KL3618400B ...	—	—	AD1245	5343
KL4718400 ...	ST287	—	—	—
KL7018400 ...	ST287	—	—	—
KL8618400 ...	ST582	—	—	—
KLO618400F ...	ST213	—	—	—
N3A118400 ...	—	—	—	5343
N22118400A ...	—	E508	—	5344
N31818400 ...	—	—	—	5343
N31818400A ...	—	E512	—	5343
N31818400B ...	—	—	—	5343
N32618400 ...	—	—	—	5343
N32618400B ...	—	E512	—	—
N32718400 ...	—	—	—	5343
N32718400A ...	—	—	—	5343
PN2318400B ...	—	E511	—	—
R20118400B ...	ST263	E511	—	—

(continued on next page)

MAZDA (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
R20118400C ...	ST263	—	—	—
S21118400 ...	ST257	E511	—	—
VS0118400A ...	ST257	—	—	—
ZZL018400 ...	ST406	—	—	—
ZZL118400 ...	ST406	—	—	—
ZZM018400 ...	ST406	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
ZZM118400 ...	ST406	—	—	—
175718400C ...	ST212	E587	—	—
175818400B ...	ST212	E587	—	—
188318400 ...	ST212	E587	—	—
190718400A ...	ST212	E587	—	—

MITSUBA

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
SM30213	ST322	—	—
SM30244	ST322	—	—
SM30245	ST322	—	—
SM30246	ST322	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
SM30248	ST322	—	—
SM40203	ST283	—	—
SM40215	ST322	—	—

MITSUBISHI

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
M3T38882	—	—	—	5343
M000T70281 ...	—	—	—	5343
M000T70381 ...	—	—	—	5343
M000T70481 ...	—	—	—	5343
M000T70681 ...	—	—	—	5343
M000T70781 ...	—	—	—	5343
M000T70881 ...	—	—	—	5343
M000T70981 ...	—	—	—	5343
M000T71181 ...	—	—	—	5343
M000T71381 ...	—	—	—	5343
M000T71581 ...	—	—	—	5343
M000T71681 ...	—	—	—	5343
M001M70685 ...	ST247	E512	—	5343
M001M70981 ...	—	E512	—	5343
M001M71481 ...	—	E512	—	5343
M001M72086 ...	—	E512	—	5343
M001M72181 ...	—	E512	—	5343
M001M72182 ...	—	E512	—	5343
M001M72281 ...	—	—	—	5343
M001M72981 ...	—	E512	—	5343
M001M73481 ...	ST246	—	—	—
M001M74781 ...	ST292	—	—	—
M001M75381 ...	ST246	—	—	—
M001Q71281 ...	ST247	—	—	—
M001T60081 ...	—	E512	—	—
M001T60181 ...	—	E512	—	—
M001T60581 ...	—	E512	—	—
M001T70481 ...	ST159	E512	—	5343

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
M001T70483 ...	—	E512	—	5343
M001T70687 ...	—	E512	—	5343
M001T70881 ...	—	E512	—	—
M001T70981 ...	—	E512	—	5343
M001T71281 ...	ST247	—	—	—
M001T71381 ...	ST287	E512	—	5343
M001T71481 ...	—	E512	—	5343
M001T71881 ...	ST247	—	—	—
M001T72086 ...	—	E512	—	5343
M001T72088 ...	—	E512	—	5343
M001T72181 ...	—	E512	—	5343
M001T72182 ...	—	E512	—	5343
M001T72281 ...	—	—	—	5343
M001T72581 ...	ST287	E512	—	5343
M001T72583 ...	—	E512	—	5343
M001T72981 ...	—	E512	—	5343
M001T73281 ...	ST287	E512	—	5343
M001T73381 ...	ST159	E512	—	5343
M001T73383 ...	—	E512	—	5343
M001T73681 ...	—	E512	—	—
M001T74781 ...	ST292	—	—	—
M001T77681 ...	—	E512	—	5343
M002M92071 ...	ST263	—	—	—
M002T23685 ...	ST311	E580	—	5344
M002T25481 ...	ST311	—	—	—
M002T31081 ...	—	—	—	5343
M002T37081 ...	ST247	—	—	5343
M002T41181 ...	—	E508	5342	—

(continued on next page)

MITSUBISHI (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
M002T41182 ...	—	E508	5342	—
M002T42481 ...	—	E508	5342	—
M002T42781 ...	—	—	—	5343
M002T42881 ...	—	—	—	5343
M002T42981 ...	—	—	—	5343
M002T44081 ...	—	E508	5342	5343
M002T48081 ...	—	E508	5342	5343
M002T49781 ...	—	E508	5342	—
M002T49881 ...	—	E508	5342	5343
M002T50181 ...	ST311	—	—	—
M002T53181 ...	ST300	E580	—	5343
M002T56182 ...	ST263	—	—	—
M002T58581 ...	—	E580	—	—
M002T58781 ...	—	E580	—	—
M002T58881 ...	—	E580	—	—
M002T60072 ...	ST257	E511	—	—
M002T60171 ...	ST263	E511	—	—
M002T60172 ...	—	E511	—	—
M002T60185 ...	ST263	E511	—	—
M002T60671 ...	—	E511	—	—
M002T61171 ...	ST263	—	—	—
M002T62871 ...	ST257	—	—	—
M002T74171 ...	ST263	—	—	—
M002T92071 ...	ST263	E511	—	—
M002T92172 ...	—	E511	—	—
M003M32782 ...	—	E508	5342	5343
M003Q38882 ...	ST247	—	5342	5343
M003T20681 ...	—	E580	—	5344
M003T26781 ...	—	E580	—	5344
M003T30583 ...	ST247	—	—	—
M003T30681 ...	ST247	—	—	—
M003T30881 ...	—	E508	5342	5343
M003T32588 ...	—	E508	5342	5343
M003T32592 ...	ST159	E508	5342	5343
M003T32593 ...	—	E508	5342	5343
M003T32681 ...	—	E508	—	5344
M003T32782 ...	ST246	E508	—	5343
M003T33081 ...	—	E508	5342	5343
M003T36081 ...	—	E508	—	5343
M003T37781 ...	—	—	—	5343
M003T38081 ...	—	E508	5342	—
M003T38082 ...	—	E508	5342	—
M003T38181 ...	ST247	—	—	5343
M003T38481 ...	—	—	—	5343
M003T38885 ...	—	E508	5342	5343
M003T39385 ...	—	E508	5342	5343
M003T39481 ...	—	E508	5342	5343
M003T39981 ...	ST247	—	5342	5343

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
M003T41083 ...	—	E508	5342	5343
M003T41088 ...	—	E508	5342	5343
M003T41185 ...	ST247	—	—	5343
M003T41186 ...	—	—	—	5343
M003T41381 ...	ST247	—	—	5343
M003T41481 ...	ST247	—	—	5343
M003T41581 ...	ST247	—	—	5343
M003T42281 ...	ST247	—	—	—
M003T42781 ...	—	E508	5342	5343
M003T42881 ...	—	E508	5342	5343
M003T43381 ...	—	E508	5342	5343
M003T43481 ...	—	E508	5342	5343
M003T43581 ...	—	E508	5342	5343
M003T48181 ...	—	—	5342	5343
M003T49381 ...	—	E508	5342	5343
M003T49585 ...	—	E508	5342	5343
M003T49781 ...	—	E508	5342	5343
M003T70081 ...	—	E508	5342	5343
M003T80571 ...	—	E580	—	—
M003V38881 ...	—	E508	5342	5343
M003V38882 ...	—	—	5342	5343
M003Y24482 ...	—	E508	5342	5343
MD066761 ...	ST159	—	5342	5343
MD072654 ...	ST263	E511	—	—
MD079461 ...	—	E508	5342	—
MD081567 ...	ST159	E508	5342	5343
MD081568 ...	—	E580	—	—
MD085731 ...	ST300	E580	—	—
MD087531 ...	ST265	E580	—	—
MD087532 ...	ST300	E580	—	—
MD095188 ...	—	E511	—	—
MD095865 ...	—	E511	—	—
MD099667 ...	ST159	E512	—	5343
MD099673 ...	ST300	E580	—	5343
MD100431 ...	ST159	E508	5342	5343
MD101219 ...	ST271	E508	—	—
MD105042 ...	—	E508	5342	—
MD107614 ...	—	E508	5342	5343
MD107615 ...	—	E508	5342	5343
MD112625 ...	ST287	E512	—	5343
MD121581 ...	ST263	E511	—	—
MD125926 ...	ST159	—	—	—
MD136933 ...	—	E512	—	—
MD161437 ...	—	E508 ³⁴	5342	5343
MD162387 ...	ST159	E508	—	—
MD162836 ...	—	E508 ³⁴	5342	5343
MD162837 ...	—	E508 ³⁴	5342	5343
MD162838 ...	—	E508 ³⁴	5342	5343

(continued on next page)

³⁴ Some units may require soldering or spot welding the brushes lead to the brush holder plate or yoke assembly

MITSUBISHI (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
MD162839	ST159	E512 ³⁴	—	5343
MD162840	ST159	E512 ³⁴	—	5343
MD162841	ST159	—	—	—
MD162842	ST287	E512 ³⁴	—	5343
MD162843	ST287	E512 ³⁴	—	5343
MD162860	—	E512 ³⁴	—	5343
MD163188	—	—	—	5343
MD163837	ST159	E508	—	—
MD164865	—	E508 ³⁴	5342	—
MD164866	—	E508 ³⁴	5342	—
MD164975	ST263	—	—	—
MD164976	ST263	—	—	—
MD164978	ST263	—	—	—
MD170049	—	—	—	5343
MD170803	—	E508 ³⁴	5342	—
MD171228	—	E580 ³⁴	—	—
MD171502	—	E580 ³⁴	—	—
MD172860	ST159	—	—	—
MD172861	—	E512	—	5343
MD172862	ST159	—	—	—
MD172863	—	E512	—	5343
MD172864	ST287	E512	—	—
MD174482	—	—	—	5343
MD174483	—	—	—	5343
MD178511	ST159	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
MD180238	—	E508 ³⁴	5342	5343
MD180239	—	E508 ³⁴	5342	5343
MD180937	—	—	—	5343
MD181470	—	E508 ³⁴	5342	—
MD182488	—	E512 ³⁴	—	5343
MD182836	ST159	E508	—	—
MD188720	—	—	—	5343
MD188721	—	—	—	5343
MD189054	—	E508 ³⁴	5342	5343
MD192227	—	E508 ³⁴	5342	5343
MD192228	—	E508 ³⁴	5342	5343
MD192277	ST159	E508	—	—
MD301350	—	—	5342	5343
MD306472	ST298	E512	—	—
MD309471	—	E512	—	—
MD309472	—	E512	—	—
MD360368	ST287	E508	—	—
MD611223	ST159	E512	—	—
MD611625	ST287	—	—	5343
MM115517	—	E508 ³⁴	—	5344
MM115518	—	E580 ³⁴	—	—
MO4672108	ST159	E512	—	—
MR5L1914	ST159	E508	—	—

NIPPONDENSO

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
DF4EH	ST256	E704 ³⁴	—
DFDE6	ST256	E704 ³⁴	—
DFKEE	ST256	E704 ³⁴	—
DR4FM	—	E591 ³⁴	—
DR4R6	—	E591 ³⁴	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
DRDFE	—	E591 ³⁴	—
0280005091	ST168	M504	—
0280005130	ST168	M504	—

NISSAN-DATSUN

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
M1T72085	ST326	E512	—	—
M2T53882	ST375	—	—	—
M1772281	ST270	—	—	—
2330M8100	ST218	E582	—	—
2330M8300	ST218	E581	—	—
23300AA020	—	E591	—	—
23300AA280	ST247	E512	—	—
23300AA300	ST247	E512	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
23300AA390	—	E512	—	—
23300D0213	ST247	—	—	5343
23300D0214	ST247	—	—	—
23300D0301	ST208	E593 ³⁴	—	—
23300D0511	—	E512 ³⁴	—	5343
23300D0513	—	E512 ³⁴	—	5343
23300D1700	ST218	E593 ³⁴	—	—
23300F6610	ST293	—	—	—

(continued on next page)

³⁴ Some units may require soldering or spot welding the brushes lead to the brush holder plate or yoke assembly

NISSAN-DATSUN (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
23300H5014 ...	—	—	—	5343
23300H5015 ...	—	—	—	5343
23300KA220 ...	ST247	E508	—	—
23300KA221 ...	ST247	E508	—	—
23300M8000 ...	ST218	—	—	—
23300M8011 ...	ST247	—	—	5343
23300M8100 ...	ST218	—	—	—
23300M8111 ...	ST311	E580 ³⁴	—	5344
23300M8200 ...	ST218	—	—	—
23300M8211 ...	—	—	—	5343
23300M8300 ...	ST218	E581 ³⁴	—	—
23300N5911 ...	ST311	—	—	—
23300T5072 ...	ST247	—	—	5343
23300U0114 ...	—	E580 ³⁴	—	5344
23300U6000 ...	ST202	E582	—	—
23300U6003 ...	ST205	E582	—	—
23300U6004 ...	ST304	—	—	4634
23300V0706 ...	ST306	—	—	—
23300V4171 ...	—	E580 ³⁴	—	—
23300V5301 ...	ST306	E593	—	—
23300V5302 ...	ST208	E593 ³⁴	—	—
23300W0402 ...	—	—	—	4634
23300W0417 ...	—	—	—	5343
23300W2500 ...	ST305	—	—	—
23300W9810 ...	—	E512 ³⁴	—	—
233000C010 ...	ST311	—	—	—
233000M200 ...	ST331	—	—	—
233000M201 ...	ST331	—	—	—
233000M210 ...	—	—	—	5343
233000M211 ...	—	—	—	5343
233000W010 ...	ST365	—	—	—
233000W011 ...	ST365	—	—	—
233001E400 ...	ST332	—	—	—
233001S715 ...	ST270	—	—	—
233009E010 ...	ST376	—	—	—
2330001E12 ...	ST247	—	—	5343
2330001E13 ...	ST247	—	—	—
2330001Y10 ...	—	E512 ³⁴	—	5343
2330003E11 ...	ST247	—	—	5343
2330004E00 ...	—	E593 ³⁴	—	—
2330004E01 ...	ST279	E593 ³⁴	—	—
2330006W61 ...	ST306	E593 ³⁴	—	—
2330007G00 ...	ST306	E593 ³⁴	—	—
2330008U10 ...	—	—	—	5343
2330011M01 ...	ST302	E593 ³⁴	—	—
2330012G02 ...	ST272	—	—	—
2330012G03 ...	ST272	—	—	—
2330016E01 ...	ST269	—	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
2330016E02 ...	ST269	—	—	—
2330016E03 ...	ST269	—	—	—
2330016E04 ...	ST269	—	—	—
2330017C00 ...	ST282	E582 ³⁴	—	—
2330017C05 ...	ST285	E582	—	—
2330017C06 ...	ST285	E582 ³⁴	—	4634
2330017C07 ...	ST285	E593	—	—
2330017C60 ...	ST284	E593 ³⁴	—	—
2330018C00 ...	ST282	—	—	—
2330018C02 ...	ST282	E593	—	—
2330018C05 ...	ST285	E582	—	—
2330018C06 ...	ST285	—	—	4634
2330018C07 ...	ST285	—	—	4634
2330018C09 ...	ST285	E593	—	—
2330018C60 ...	ST284	E593 ³⁴	—	—
2330018V10 ...	ST247	—	—	—
2330020P11 ...	ST247	E512 ³⁴	—	5343
2330020R11 ...	ST247	E512 ³⁴	—	5343
2330021P00 ...	ST285	E593 ³⁴	—	—
2330022P00 ...	ST285	E593 ³⁴	—	—
2330022P71 ...	—	E512 ³⁴	—	5343
2330030F10 ...	—	E512 ³⁴	—	5343
2330030F11 ...	—	E512 ³⁴	—	5343
2330030P10 ...	ST343	—	—	—
2330030P16 ...	ST343	—	—	—
2330030R12 ...	—	—	—	5343
2330030R13 ...	—	—	—	5343
2330032F10 ...	ST311	—	—	—
2330036A00 ...	—	E593 ³⁴	—	—
2330036A10 ...	ST311	—	—	—
2330037A10 ...	ST311	E580 ³⁴	—	5344
2330041B10 ...	—	—	—	5343
2330041B16 ...	—	—	—	5343
2330041B70 ...	—	—	—	5343
2330041B76 ...	—	—	—	5343
2330042L14 ...	—	—	—	5343
2330043L16 ...	—	E580 ³⁴	—	5344
2330044R10 ...	—	E512 ³⁴	—	5343
2330044R11 ...	—	E512 ³⁴	—	5343
2330048L10 ...	—	E512 ³⁴	—	—
2330050Y10 ...	—	E512 ³⁴	—	5343
2330050Y11 ...	—	E512 ³⁴	—	5343
2330050Y12 ...	—	—	—	5343
2330051E10 ...	—	E512 ³⁴	—	5343
2330051E11 ...	—	E512 ³⁴	—	5343
2330052F10 ...	—	E512 ³⁴	—	—
2330053F10 ...	ST270	E512	—	—
2330053F11 ...	ST270	E512	—	—

(continued on next page)

³⁴ Some units may require soldering or spot welding the brushes lead to the brush holder plate or yoke assembly

NISSAN-DATSUN (Cont'd)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
2330053J11 ...	—	E512 ³⁴	—	5343
2330053J12 ...	—	E512 ³⁴	—	5343
2330057M70 ...	ST275	E512 ³⁴	—	5343
2330060S10 ...	ST247	—	—	5343
2330060U10 ...	ST292	—	—	—
2330060U11 ...	ST292	—	—	—
2330065Y01 ...	ST331	—	—	—
2330065Y10 ...	—	E512 ³⁴	—	5343
2330074Y00 ...	—	E582	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
2330079E10 ...	—	E512 ³⁴	—	—
2330080W00 ...	ST277	E582 ³⁴	—	—
2330081W00 ...	ST304	E582 ³⁴	—	4634
2330084A11 ...	ST311	—	—	—
2330084A17 ...	ST311	—	—	—
2330085A01 ...	ST288	E582	—	—
2330086G10 ...	ST278	E512	—	—
2330086G11 ...	ST278	—	—	—

OMC (OUTBOARD MARINE CORP.)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
382138	ST124	—	—	—
384118	ST124	R503 ³⁴	—	—
384198	ST124	R503 ³⁴	—	—
384242	ST124	R503 ³⁴	—	—
384243	ST124	R503 ³⁴	—	—
980803	ST81	—	—	—
980820	ST124	R503 ³⁴	—	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame	Bushing Drive End
980821	ST124	R503 ³⁴	—	—
981078	ST124	R503 ³⁴	—	—
981288	ST124	R503 ³⁴	—	—
981289	ST124	R503 ³⁴	—	—
981821	—	F508 ³⁴	—	5302
982200	ST124	R503 ³⁴	—	—

SAAB

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
4443776	ST599	—	—

SUBARU

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
23300AA010 ...	—	E591	—
23300AA040 ...	ST247	E512	—
23300AA050 ...	ST247	—	—
329918710 ...	ST200	E481	—
429917000 ...	ST241	E704	—
429917130 ...	ST241	E704	—
429917200 ...	ST200	E591	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
429917210	—	E591	—
429917220	—	E591	—
429917300	—	E591	—
429917310	—	E591	—
829918600	ST200	—	—

SUZUKI

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
3110060A10 ...	ST153	—	—
3110060A20 ...	ST153	—	—
3110083021 ...	ST153	E508	—
3110083030 ...	ST153	E508	—

(continued on next column)

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
3610011150 ...	ST159	—	—
3610021740 ...	ST159	—	—

³⁴ Some units may require soldering or spot welding the brushes lead to the brush holder plate or yoke assembly

TOYOTA

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
2810010030 ...	ST241	E704	—
2810015070 ...	—	E591	—
2810015180 ...	—	E591	—
2810016080 ...	—	E591	—
2810016110 ...	—	E591	—
2810016240 ...	ST156	E591	—
2810034052 ...	—	E591	—
2810034070 ...	ST200	E587	—
2810034080 ...	—	E591	—
2810035030 ...	—	E591	—
2810046090 ...	—	E591	—

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
2810046140 ...	—	E591	—
2810060070 ...	—	E591	—
2810063020 ...	—	E591	—
2810063050 ...	—	E591	—
2810065020 ...	—	E591	—
2810066020 ...	—	E591	—
2810066040 ...	—	E591	—
2810075070 ...	—	E591	—
2810075090 ...	—	E591	—
2810076070 ...	—	E591	—

(continued on next column)

VOLVO

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
240360	—	E552	5313
870977	—	E552	—
1311034	—	E700	—
1311038	—	—	5321
1323230	—	E455	—
2386209	—	E550	—
2416154	—	E552	5301
4638565	ST264	—	5313
4643169	ST264	—	5313
4643177	ST264	—	5313
13571997	ST323	—	—
13634514	ST249	—	—
13639125	ST249	—	—
13987029	ST264	—	5321
35233014	ST323	—	—
35233022	—	—	5321
50016005	ST264	—	5321

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
50020460	—	—	5321
50035641	ST323	—	—
50036177	—	—	5321
50036920	ST323	—	—
50037415	ST249	—	—
50038108	ST249	—	—
50039189	ST249	—	—
91284216	ST249	—	—
0001362047 ...	—	—	5321
0021517101 ...	ST274	—	5321
0021519701 ...	ST274	—	5321
0031510701 ...	ST274	—	5321
0031513801 ...	—	—	5321
0031517001 ...	—	—	5321
0041515201 ...	—	—	5321
0041515601 ...	—	—	5321

(continued on next column)

YUGO

Unit No	Solenoid Switch	Brush Set	Bushing C.E. Frame
1616404	ST249	—	—



ECHLIN®

Unit Parts Guide

For Electrical Systems

**Distributor Parts: Electronic Ignition & Contact Controlled Ignition
Alternator Parts, Generator Parts & Starter Parts**