# 4500/4600 Exit Device Dogging Installation Instructions

1. Remove the two screws which hold the push bar to the cover tube and set aside.

2. Slide the push bar out of the tube.

3. Set the push bar upside down on the table and remove the two screws that hold the dogging mechanism in place. Thread locker was used on these screws when they were originally applied. Be sure to press down firmly upon the screws or use an impact driver while unscrewing them in order to prevent stripping the heads.

4. Attach the new dogging mechanism with the same screws.

5. Slide the push bar back into the cover tube.

6. Reattach the push bar to the cover tube by installing the two screws.

Install these two screws