

SERVICE BULLETIN

BRIGGS & STRATTON TECHNOLOGIES

Automotive Systems Group

TO CENTRAL SERVICE DISTRIBUTORS
AUTHORIZED AUTOMOTIVE SERVICE DISTRIBUTORS
AS-1975 MANUAL OWNERS
SUBJECT Ford Pin Tumblers

No. AS-1093
DATE 12-15-85
FILE IN Bulletin
Binder

Effective this notice we will begin phasing out Stainless Steel Pins and replacing with Brass Pins.

This change is required because of the reduction in production requirements and the design change in Ford Locks.

Because of current inventory both at the Factory and in the field, it will be a running change over a considerable length of time.

The change-over will be on a part by part basis, thus you could find the following conditions when receiving parts.

Example: 83245 - Brass Pins
83246 - Stainless Steel Pins
83249 - Brass Pins

Parts effective are:

83245
83246
83247
83248
83249

BRIGGS & STRATTON CORPORATION
L. B. White
Service Sales Manager
Automotive Lock Division

LBW: bjo