

SERVICE BULLETIN

BRIGGS & STRATTON TECHNOLOGIES

Automotive Systems Group

TO Central Service Distributors
Authorized Automotive Service Distributors
AS-1975 Manual Holders


No. AS-1112
DATE 1/16/90
FILE IN Position

SUBJECT Honda Ignition Change – Effecting Key Blanks

HONDA Corp. has incorporated a "Push To Lock" feature on their 1989 vehicles. This will require the key blank to be 4mm longer to function.

Do NOT use the 1988 key blank in a 1989 VEHICLE.

The key will become lodged in the ignition.



As always, please contact your local Briggs & Stratton Distributor for details.

Scot T. Hooper
Service Director
Briggs & Stratton Technologies