




NOTES:

1. FOR BOTH SIDES OF CABLE, INNER & OUTER SHIELDS SHOULD NOT TOUCH EACH OTHER. LEAVE ABOUT .25" OF THE INSULATOR TAPE & APPLY A PIECE OF HEAT SHRINK ABOVE IT.
2. ON CONNECTOR SIDE, CUT OUT INNER SHIELDS & LEADS NOT USED. CONNECT OUTER SHIELD AS PER PROCESS SPECIFIED ON DRAWING LD5302.
3. AT FLYING LEAD END, TWIST & TIN THE END OF EACH LEAD.
4. LABEL WITH PART NUMBER & CURRENT REVISION LETTER AS SHOWN WITH .12" HIGH CHARACTERS USING BLACK PERMANENT INK.

REV. DESC: NEW, TO REPLACE LD5140	VERSION: 00	TDR: 000000402086
FILE: \AAA\00138\520	REVISED: 08:02:09 07/21/2006	BY: ENLEFDO
MTL: -		

BALDOR ELECTRIC CO.

RESOLVER FEEDBACK CABLE ASSEMBLY, 'CE'