



### Application Software upgrade (iMap)

Model: iKeyboard 3/iKeyboard 4/iKeyboard 5/iKeyboard 6  
Release date: 6th July, 2016  
Version: V1.09 (Windows)  
Who need to upgrade: All user  
Upgrade fix: Fixed “Firmware Upgrade” issue on Windows 10

### Update footprint

<i>Version</i>	<i>Release date</i>	<i>Feature added or bug fix</i>
V1.01(Windows)	9 <sup>th</sup> Jan., 2014	Refined the GUI
V1.02 (Windows)	30 <sup>th</sup> Mar., 2014	Solved the hardware connection on some version of Windows.
V1.02 (Mac)	23 <sup>rd</sup> Jan., 2014	Improve the firmware upgrade process software
V1.03 (Windows)	15 <sup>th</sup> Feb., 2014	Added an reverse function on sustain
V1.03 (Mac)	15 <sup>th</sup> Feb., 2014	Added an reverse function on sustain
V1.05 (Windows)	27 <sup>th</sup> Feb., 2015	Improved the “Firmware upgrade” software
V1.05 (Mac)	27 <sup>th</sup> Feb., 2015	Improved the “Firmware upgrade” software
V1.06 (Windows)	29 <sup>th</sup> May., 2015	Uninstall the previous iMap during installing the current iMap process.
V1.07 (Windows)	24 <sup>th</sup> Feb., 2016	Added iKeyboard 8
V1.08 (Windows)	6 <sup>th</sup> June, 2016	Added function to modulation and Pitch allows user to select as below:
- Modulation-	Return to “0” when release or Stay at the value at the released point	
- Pitch:	Return to “Center” when release or stay at the value at the released point	

Remark: