



Firmware upgrade note

Model: Platform M+
 Release date: 23rd Aug., 2018
 Version: V2.02
 Who need to upgrade: All users. Especially user who wanted to use Platform B+ with Platform M+

**Note: Please make sure iMap V2.00 or above is being used for the firmware V2.00 or above.
 Platform M+ firmware must be upgraded to V2.00 or above if Platform B+ is intended to use together.**



Upgrade fix/Feature added:

1. Eliminated ticking noise and chatter on faders in idle position when a session is open.
2. Corrected rotary controls being too “notched” and skipping when adjusting parameters.
3. In Protocols, the volume dB readout was added to the top line of the Platform D2 display.

Update footprint

Version	Release date	Feature added or bug fix
V1.06	7 th July, 2017	First release.
V1.07	10th Feb., 2018	Improved the USB driver
V2.00	1 st June, 2018	Equipped with Mackie Control and HUI Emulation for universal DAW (Except LogicPro mode is equipped for LogicPro) and User define mode.

Notice: “Mixer” button function will be vary according to the DAW. Please refer to the below list for the its function on each DAW.

- 1.Nuendo/Cubase: Left
- 2.Logic Pro: Marker
- 3.Samplitude: Marker Mode
- 4.Live: <Locator
- 5.Reaper: Marker
- 6.Studio One: Marker Mode
- 7.Reason: To Left Locator
- 8.Bitwig Studio: Marker
- 9.Sonar: 
- 10.Audition: 
- 11.FL Studio: Shift
- 12.DP: RTZ

V2.01 1st June, 2018

1. Improved fader calibration process
2. Fixed Platform D/D2 display refresh issue when using with Logic Pro
3. Added function - Touch sensitive for displaying channel volume dB value

Remark: