

Update notes for the Platform M+/X+ iMap:

2020

5-21, V2.11 Beta:

- Fixed the unavailable MIDI message box (error from last update)

5-18, (V2.10 Beta):

- Fixed the firmware upgrade problem on macOS Catalina
- Fixed a typo of setup package on Windows

5-15, V2.09 Beta:

- Possibly fixed the firmware upgrade problem on Catalina

5-15, V2.08:

- Fixed the jog-wheel issue

4-9, V2.07:

- Step 3 shows warning when user not select the unit called "iCON firmware upgrade"

2-15, (V2.06):

- Allow users to upgrade firmware on macOS Catalina

2019

V2.05:

- Forbid users to upgrade firmware on macOS Catalina

10-16, V2.03:

- Add a null MIDI Type for fader touch part to be silent
- Add Rotation Pattern for knobs and jog wheel
- Cancel the JUCE logo
- In order to compatible for website: Platform_M+_and_X+_iMap --> PlatformMPlus_and_XPlus_iMap

2018

11-16, V2.01:

- Add Control Protocol dropdown options: MCP, HUI
- Add customizable HUI mode

5-21, V2.00:

- Change to 4 common control modes
- JUCE edition
- Fix the MIDI value of Mixer function in Mackie mode

2017

8-22, V1.04:

- Fix "Load File" bug

(TO BE APPENDED ...)