

Update notes for the Platform M/X iMap:

2020

5-21, V2.11 Beta:

- Fixed the unavailable MIDI message box (error from last update)

5-18, V2.10 Beta:

- Fixed the firmware upgrade problem on macOS Catalina

5-15, V2.08:

- Fixed the jog-wheel issue

4-9, V2.07:

- Step 3 shows warning when user not select the unit called "iCON firmware upgrade"

4-11, V2.06:

- Fixed an issue with the MacOS iMap installation package

2-15, V2.06 Beta:

- Allow users to upgrade firmware on macOS Catalina

2019

12-10, V2.05:

- Forbid users to upgrade firmware on macOS Catalina

5-11, V2.01:

- Add customizable HUI mode

2018

8-8, V2.00:

- JUCE edition
- Change to 4 common control modes

3-6, V1.07:

- Fix the problem of not recognizing Platform X in Step 1 of Firmware Upgrade

(TO BE APPENDED ...)